

# Title List of Documents Made Publicly Available

Docket 50 Documents from October through December 1978

### U.S. Nuclear Regulatory Commission

Office of Administration



#### Available from

6PO Sales Program

Division of Technical Information and Deciment Control

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Printed copy price: \$8.00

and

National Technical Information Service Springfield, VA 22161

## Title List of Documents Made Publicly Available

Docket 50 Documents from October through December 1978

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



#### CONTENTS

Preface	١
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Itoms by Facility Name	χi
Domestic Licensing of Production and Utilization Facilities - Docket 50	1
Personal Author Index	45
Corporate Source Index	85
Report Number Index	19
Cross Reference of Enclosures to Principal Documents	21
Appendix - Definitions of Docket 50 Categories	

		•	


#### **PREFACE**

This special edition of the *Title List* contains Docket 50 material from 1978 that has not appeared in previous issues of the *Title List*. The documents in this supplement are indexed by personal author, corporate source, and report number. The listings of this material on the domestic licensing of production and utilization facilities, divided into the categories used for filing and searching in the NRC Public Document Room, are as follows:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

The Appendix sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



- 1. NRC/PDR Document category (see Appendix).
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to microfiche files.
- 9. This three digit portion of this entry is the number of the microfiche frame on which this document starts.
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO." See NOTES on this page for information about ordering publications.

The Docketed Items list is arranged sequentially by category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this publication may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

	*	i în		
·				

#### ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Name	Page	Docket	Name	Page
Univ. of Michigan Research Reactor	1	50-99	Babcock & Wilcox Test Reactor	16
Indian Point Station, Unit 1	i	50-106	Oregon State Univ.	17
Battelle Memorial Inst. Research Reactor	3	50-112	Univ. of Oklahoma Research Reactor	17
Dresden Nuclear Power Station, Unit 1	3	50-113	Univ. of Arizona Research Reactor	18
Babcock & Wilcox Co. Critical Facility	6	50-116	Iowa State Univ. Research Reactor	18
Enrico Fermi Atomic Power Plant, Unit 1	6	50-123	Univ. of Missouri Research Reactor	18
Valiccitos Boiling Water Reactor	6	50-128	Texas A&M Univ. Research Reactor	18
Massachusetts Institute of Technology Research Reactor	6	50-131	Omaha Veterans Administration Hospital Research Reactor	18
Westinghouse Test Reactor	7	50-133	Humboldt Bay Power Plant, Unit 3	18
Washington State Univ. Research Reactor	7	50-134	Worcester Polytech Institute Research	19
Yankee-Rowe Nuclear Power Station	7	50.142	Reactor	10
Plum Brook Research Reactor Facility	10	50-142	UCLA Training Reactor	19
Union Carbide Research Reactor	10	50-146	Saxton Nuclear Experimental Facility	19
State Univ. of New York Research Reactor	10	50-147	Rockwell International Corp. Critical Facility	20
Texas A&M Univ. Research Reactor	11	50-148	Univ. of Kansas Research Reactor	20
Univ. of Virginia Research Reactor	11	50-155	Big Rock Point Nuclear Plant	20
General Electric Test Reactor	11	50-157	Cornell Univ. Research Reactor	23
Univ. of Utah Research Reactor	15	50-160	Georgia Institute of Technology Research Reactor	23
General Electric Nuclear Test Reactor	15	60.163		24
Catholic Univ. of America Research Reactor	15	50-163	General Atomic Company	24
Unly, of Florida Training Reactor	15	50-170	National Naval Medical Center	24
Westinghouse Critical Experiment	16	50-171	Peach Bottom Atomic Power Station, Unit 1	24
General Atomic Co.	16	50-182	Purdue Univ. Research Reactor	24
Rockwell International Research Reactor	16	50-183	Vallecitos Experimental Superheat Reactor	24
Cornell Univ. Zero Power Reactor	16	50-184	National Bureau of Standards Reactor	24
Univ. of Delaware Research Reactor	16	50-186	Univ. of Missourl Research Reactor	25

Do	ket	Name	Page	Docket	Nate	Page
	50-187	Space Radiation Research Reactor	25	50-269	Oconee Nuclear Station, Unit I	97
	50-188	Kansas State Univ. Research Reactor	25	50-270	Oconee Nuclear Station, Unit 2	101
	50-193	Rhode Island & Providence Plantations AEC	25	50-271	Vermont Yankee Nuclear Power Station	104
	50-200	B&W Test Reactor	25	50-272	Salem Nuclear Generating Station, Unit 1	106
	50-201	West Valley Reprocessing Plant	25	50-274	U.S. Geological Survey Research Reactor	110
	50-206	San Onofre Nuclear Station, Unit 1	26	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	110
	50-213	Haddam Neck Plant	30	50-276	Georgia Technology Research Reactor	116
	50-219	Oyster Creek Nuclear Power Plant	33	50-277	Peach Bottom Atomic Power Station, Unit 2	116
	50-220	Nine Mile Point Nuclear Station, Unit 1	37	50-278	Peach Bottom Atomic Power Station, Unit 3	119
	50-223	Univ. of Lowell Research Reactor	40	50-279	Santa Maria De Garona Nuclear Power Plant	121
	50-224	Univ. of California Research Reactor	40	50-280	Surry Power Station, Unit 1	122
	50-225	RPI Critical Experiment	40	50-281	Surry Power Station, Unit 2 .	126
	50-227	TRIGA Thermionic Prototype Reactor	40	50-282	Prairie Island Nuclear Station, Unit 1	130
	50-236	Lockheed Aircraft Corp.	40	50-284	Idaho State Univ. Research Reactor	132
	50-237	Dresden Nuclear Power Station, Unit 2	40	50-285	Fort Calhoun Station, Unit 1	132
	50-243	Oregon State Univ. Research Reactor	45	50-286	Indian Point Station, Unit 3	135
	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	45	50-287	Oconee Nuclear Station, Unit 3	139
	50-245	Milistone Nuclear Power Station, Unit 1	.48	50-288	Reed College Research Reactor	142
	50-247	Indian Point Station, Unit 2	52	50-289	Three Mile Island Nuclear Station, Unit 1	142
	50-249	Dresden Nuclear Power Station, Unit 3	55	50-290	Proof Test Facility	144
	50-250	Turkey Point Plant, Unit 3	59	50-293	Pilgrim Nuclear Power Station, Unit 1	144
	50-251	Turkey Point Plant, Unit 4	64	50-295	Zion Nuclear Power Station, Unit 1	146
	50-252	Univ. of New Mexico Research Reactor	69	50-296	Browns Perry Nuclear Power Station, Unit 3	150
	50-254	Quad-Cities Station, Unit 1	69	50-297	North Carolina State Univ. Pulstar Reactor	154
	50-255	Palisades Nuclear Plant	72	50-298	Cooper Nuclear Station	154
	50-259	Browns Ferry Nuclear Power Station, Unit 1	75	50-301	Point Beach Nuclear Plant, Unit 2	157
	50-260	Browns Ferry Nuclear Power Station, Unit 2	79	50-302	Crystal River Nuclear Plant, Unit 3	159
	50-261	H.B. Robinson Plant, Unit 2	82	50-304	Zion Nuclear Power Station, Unit 2	i63
	50-263	Monticello Nuclear Generating Plant	85	50-305	Kewaunee Nuclear Power Plant	166
	50-264	Dow Chemical Co.	88	50-306	Prairie Island Nuclear Station, Unit 2	169
	50-265	Quad-Cities Station, Unit 2	88	50-309	Maine Yankee Atomic Power Plant	171
	50-266	Point Beach Nuclear Plant, Unit 1	91	50-311	Salem Nuclear Generating Station, Unit 2	173
	50-267	Fort St. Vrain Nuclear Generating Station	94	50-312	Rancho Seco Nuclear Generating Station	176

Name	Page	Docket	Name	Page
Arkansas Nuclear One, Unit 1	179	50-325	Brunswick Steam Electric Plant, Unit 1	213
Donald C. Cook Nuclear Power Plant, Unit 1	182	50-326	Univ. of California at Irvine Research Reactor	216
Donald C. Cook Nuclear Power Plant, Unit 2	185	50-237	Sequoyah Nuclear Plant, Unit 1	216
Calvert Ciiffs Nuclear Power Plant, Unit 1	190	50-328	Sequoyah Nuclear Plant, Unit 2	220
Calvert Cliffs Nuclear Power Plant, Unit 2	192	50-329	Midland Plant, Unit 1	223
Three Mile Island Nuclear Station, Unit 2	195	50-330	Midland Plant, Unit 2	229
Edwin I. Hatch Nuclear Plant, Unit 1	199	50-331	Duane Arnold Energy Center	234
Shoreham Nuclear Power Station	202	50-332	Barnwell Reprocessing Plant	238
Diablo Canyon Nuclear Power Plant, Unit 2	205	50-333	James A. Fitzpatrick Nuclear Power Plant	238
Brunswick Steam Electric Plant, Unit 2	210	50-334	Beaver Valley Power Station, Unit 1	241

-313 -315 -316 -317 -318 -320 -321 -322 -323 -324

#### ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket
Arkansas Nuclear One, Unit 1	50-313	179	Dresden Nuclear Power Station, Unit 2	50-237
Duane Arnold Energy Center	50-331	234	Dresden Nuclear Power Station, Unit 3	50-249
Babcock & Wilcox Co. Critical Facility	50-13	6	James A. Fitzpatrick Nuclear Power	50-333
Babcock & Wilcox Co. Test Reactor	50-99	16	Plant	
Beaver Valley Power Station, Unit 1	50-334	241	Fort Calhoun Station, Unit 1	50-285
Big Rock Point Nuclear Power Plant	50-155	20	Fort St. Vrain Nuclear Generating Station	50-267
Browns Ferry Nuclear Power Station,	50-259	75	General Atomic Co.	50-89
Unit 1			General Atomic Co.	50-163
Browns Ferry Nuclear Power Station, Unit 2	50-260	79	General Electric Nuclear Test Reactor	50-73
Browns Ferry Nuclear Power Station,	50-296	150	General Electric Test Reactor	50-70
Unit 3			Georgia Institute of Technology Research Reactor	50-160
Brunswick Steam Electric Plant, Unit 1	50-325	213	Georgia Tech Research Reactor	50-276
Brunswick Steam Electric Plant, Unit 2	50-324	210		
Caivert Cliffs Nuclear Power Plant, Unit 1	50-317	190	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244
Calvert Cliffs Nuclear Power Plant,	50-318	192	Haddam Neck Plant	50-213
Unit 2	20-219	192	Edwin I. Hatch Nuclear Plant, Unit 1	50-321
Catholic Univ. of America Research Reactor	50-77	15	Humboldt Bay Power Plant, Unit 3	50-133
Donald C. Cook Nuclear Power Plant, Unit	1 50-315	182	Idaho State Univ. Research Reactor	50-284
•	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Indian Point Station, Unit 1	50-3
Donald C. Cook Nuclear Power Plant, Unit	2 50-316	185	Indian Point Station, Unit 2	50-247
Cooper Nuclear Station	50-298	154	Indian Point Station, Unit 3	50-286
Crystal River Nuclear Plant, Unit 3	50-302	159	·	
Diablo Canyon Nuclear Power Plant,	50-275	110	Iowa State Univ. Research Reactor	50-116
	50.000		Kansas State Univ. Research Reactor	50-188
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	205	Kewaunee Nuclear Power Plant	\$0-305
Dow Chemical Co.	50-264	88	Maine Yankee Atomic Power Plant	50-309
Dresden Nuclear Power Station, Unit 1	50-10	3	Massachusetts Institute of Technology Research Reactor	50-20

6	Docket	Page	Name	Docket	Page
and Plant, Unit 1	50-329	223	Quad-Cities Station, Unit 2	50-265	88
and Plant, Unit 2	50-330	229	Rancho Seco Nuclear Generating Station	50-312	176
tone Nuclear Power Station, nit 1	50-245	48	Reed College Research Reactor	50-288	142
ticello Nuclear Generating Plant	50-263	85	Rhode Island & Providence Plantations AEC	50-193	25
onal Bureau of Standards Reactor	50-184	24	H.B. Robinson Plant, Unit 2	50-261	82
onal Naval Medical Center	50-170	24	Rockwell International Research Reactor	50-94	16
Mile Point Nuclear Station, nit 1	50-220	37	RPI Critical Experiment	50-225	40
h Carolina State Univ. PULSTAR	50-297	154	Salem Nuclear Generating Station, Unit 1	50-272	106
eactor			Salem Nuclear Generating Station, Unit 2	50-311	173
nee Nuclear Station, Unit 1	50-269	97	San Onofre Nuclear Station, Unit 1	50-206	26
nee Nuclear Station, Unit 2	50-270	101	Sequoyah Nuclear Plant, Unit 1	50-327	216
nee Nuclear Station, Unit 3	50-287	139	Sequoyah Nuclear Plant, Unit 2	50-328	220
ha Veterans Administration Hospital esearch Reactor	50-131	18	Shoreham Nuclear Power Station	50-322	202
on State Univ.	50-106	17	Space Radiation Research Reactor	50-187	25
on State Univ. Research Reactor	50-243	45	State Univ. of New York Research Reactor	50-57	10
er Creek Nuclear Power Plant	50-219	33	Surry Power Station, Unit 1	50-280	122
ades Nuclear Plant	50-255	72	Surry Power Station, Unit 2	50-281	126
h Bottom Atomic Power Station, Juit 1	50-171	24	Texas A&M Univ. Research Reactor	50-59	11
h Bottom Atomic Power Station,	50-277	116	Texas A&M Univ. Research Reactor	50-128	18
Init 2	30 277		Three Mile Island Nuclear Station, Unit 1	50-289	142
h Bottom Atomic Power Station, Init 3	50-278	119	Three Mile Island Nuclear Station, Unit 2	50-320	195
			Turkey Point Plant, Unit 3	50-250	59
im Nuclear Power Station, Unit 1	50-293	144	Turkey Point Plant, Unit 4	50-251	64
Brook Research Reactor Facility	50-30	10	UCLA Training Reactor	50-142	19
t Beach Nuclear Plant, Unit 1	50-266	91	Union Carbide Research Reactor	50-54	10
t Beach Nuclear Plant, Unit 2	50-301	157	Univ. of Arizona Research Reactor	50-113	18
rie Island Nuclear Station, Unit 1	50-282	130	Univ. of California at Irvine Research Reactor	50-326	21 <b>6</b>
rie Island Nuclear Station, Unit 2	50-306	169	Univ. of California Research Reactor	50-224	40
lue Univ. Research Reactor	50-182	24	Univ. of Florida Training Reactor	50-83	15
d-Cities Station, Unit 1	50-254	69	Univ. of Kansas Research Reactor	50-148	20

Name	Docket	Page	Name	Docket
Univ. of Lowell Research Reactor	50-223	40	Vallecitos Boiling Water Reactor	50-18
Univ. of Michigan Research Reactor	50-2	1	Vallecitos Experimental Superheat Reactor	50-183
Univ. of Missouri Research Reactor	50-123	18	Vermont Yankee Nuclear Power Station	50-271
Univ. of Missourl Research Reactor	50-186	25	Washington State Univ. Research Reactor	50-27
Univ. of New Mexico Research Reactor	50-252	69	Westinghouse Critical Experiment	50-87
Univ. of Oklahoma Research Reactor	50-112	17	West Valley Reprocessing Plant	50-201
Univ. of Utah Research Reactor	50-72	15	Yankee-Rowe Nuclear Power Station	50-29
Univ. of Virginia Research Reactor	50-62	11	Zion Nuclear Power Station, Unit 1	50-295
U.S. Geological Survey Research Reactor	50-274	110	Zion Nuclear Power Station, Unit 2	50-304

#### DOCKETED ITEMS

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plane

7810230163 Changes to Sacurity Plan for subj facil have been avalues submitted, in lite dat 780712 780825. Changes do not decrease affectivenese of plan & are acceptable. Submittels contain proprietary info & are w/held from pub disclosure. REID.R M Operating Reactors Branch 4 (Pre 790625). 78/10/06 ip. 94170.142.

#### P. Operating license stage documents & correspondence

- 7811020140 Forwards Amend#25 to Fecil Oper LiceR-28 revising tech space as requested in 780913 itr w/Refety Evaluation Rept. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/12. 2pp. 94334:287.
- --7811020146 Amend#25 to Fecil Oper LiceR-28 revising tech specs re auth of intermetallic Uranium Aluminida (UAIX) & Uranium Oxida (UAIX) & Uranium Telega (UAIX) & Uranium Oxida (UAIX) & Uranium Oxida (UAIX) Cerest Fuels in addition to uranium-aluminum alloug fuel & delation of cold sump alerm.

  REID-R.W. Operating Reactors Branch 4 (Pre 790625), 78/10/12, 299 94354: 289.
- --7811020150 Safety Evaluation Rept Supporting Amend#25 to Facil Oper LiceR-28 concluding that UAIX & U308 fuels are acceptable elementatives in this FM.

  a Office of Nuclear Reactor Regulation, Director, 78/10/12. 7pp. 94334:276.
- 7811060013 Forwards Amand@26 to Facil Oper LiceR-28 revising tech space 4s requested in 780928 ltr w/safety Evaluation.
  REID.R.W. Operating Reactors Branch 4 (Pra 790620), 78/10/13. 2pp. 94422:223.
- --7811060015 Amend826 to Fec11 Open LiceR-28 revising Tech Spece to auth pwr Isval far Ford Nuc Reactor when 10-plate fusl assembliss from PSU Res Reactor are utilized in E.W. & 8 frings locations of reactor core. REID/R.W. Opensting Reactors Branch 4 (Prs 790625). 78/10/13. 789. 94422:227.
- --78:1060019 Baisty Evaluation Rapt supporting Amend#26 to Facil Oper Lic9R-28 concluding that an increase from 6 Mw to 2 Mw in Assisum allowed pur of FNR w/10-pileta Puel assemblies in E/N & B core positions is acceptable. a Office of Nuclear Reactor Regulation, Director. 78/10/13, 3pp. 9462:234.
- Q. Inspection reports. IE Bulletine & correspondence
- 7811090037 Porwards IE Inspec Rept#50-002 on 780905-08 & w/o Notice of Violation, DAVIS.A.B. Repien 1. Philodelphia. Reactor Construction & Engineering Support Branch. 78/10/03. 2pp. 02732:317.
- --7811090040 IE Inspec Rept#50~002/78-03 on 780906~08 during which i itsm of noncompliance was noted: inedequate documentation of surveillance requirements.

  OMEOER, L. R., PIBHER, W. L. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 78/09/28. 9pp. 02732:319.
- --78:1090041 Notics of Violation from inspec on 780906-08.
   Region 3. Chicago, Fuel Facility & Materiels Safety Brench.
  78/09/28. ip. 02732:328.

- 7B110B0135 Responds to 7B1003 NRC ltr re noncompliance noted in losps on 7B0906-08. Corrective actions cellbr of gemma spectrometry equip to preparation of health physics procedure requesterly cellbr of gemma spectrometry squip by 7B1201.

  KERS, W. Michigen, Univ. of. 7B/10/24. pp. 94398:007.
- 7811200052 Ack receipt of 781024 itr Informing NRC of steps taken to correct violations noted during inspec.
  DAVIS.A B. Region 3. Chicago. Foel Facility & Materials Safety
  Branch. 78/11/08. 1p. 94215-344.

OOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F. Bscurity, medical, smargency & fire protection plane
- 7811200181 Forwards revs to Mod Amend Security Plan of subj facil & requests withholding from public disclosure IAW Section 2.790(d).
  CARILLUI J. Consolidated Edison Co. of New York. 78/11/09. (p. 94292-907

#### Q. Adjudicatory correspondence

- 781109018B Forwards recent NRC memos re problems w/plps support base plate design Staff will inform 2d of conclusions after study of add info from licenses. (See AND: 7811020332, 7811020338, & 7811020343.)

  SMITH-B-H Office of the Executive Legal Director. 78/10/24, 2pp. 94031-028
- J. Insurance & Indomnity information
- 7811220076 Porwards Endorsements#99 to ANI Policy#NF-100 & #86 to MAEI Policy#NF-29. which reflect return premium dus to subject) shutdown from 780214-0522. CAHILL-N J. Consolidated Edispn Co. of New York, 78/11/15. 1p. 94071:276.
- --7811220078 Endorsement#98 to ANI Policy#NF-100.

  Nuclear Energy Liebility Insurance Association, 78/08/30. 1g. 94071:277.
- --7811220081 Endorssment#86 to MAELU Policy#MF-29.

  \* Nuclear Energy Liability Insurance Association. 78/09/05. ip. 94071:278.
- P. Operating license stage documents & correspondence
- 7812050004 Porwards Licenses Performance Eval Questions for subj fact in response to 771123 request. Fisis it is gossible that dev of statistical methodology for such eval may not justify the affort. Quelitative eval may be se good. Urges 1-quer test. ORIEN. 8. Region i. Philadelphia. Qffics of the Director. 77/12/13. 12pp. 94200:114.
- ---7812050013 Requests views of Regional Directors on Licenses performed and of sub; facils. Forwards questions to be enswered by 771209.
  THORNBURG, H. Division of Reactor Construction Inspection, 77/11/23, 2pp. 94200;126.
- 7810240108 Forwards data specified in Section 401 Certification for Sept Includes species code list, grass size output, circulating water tempuriver water discharge, cham discharges & daily fish counts.

  MONTI-M. A. Consolidated Edison Co. of New York. 78/10/13. 17pp.

- 7811070120 Informs NRC 1AN Tech Bpet that Btrawtown Dairy has ceased open & therefore milk sample is unobtainable Samples of leafy green vegetables & milk from Shenandoah Farm will be taken.

  CAMILL.W J Consolidated Edison Co of New York 78/10/30. 2pp 74033: 290
- 7811170160 Forwards data specified in Section 401 Certification for the conth of October-1978
  MONTI.W A Consolidated Edison Co of New York 78/11/10 16pp. 94048; 031
- 7812150088 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attenders to facilitate sending out hat! Hyenci Registration Form & List of Locations. HILLER\_JR Assistant Director for Bite & Bafeguerds (Pre 791030). 78/11/15 5pp 94211.343
- 7812190016 Forwards Rev#1 "Braft Radiblogical Effluent Tech Specs" for PHR (4(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) ORIMES B K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15 6pp 94214:286.
- 7812070153 Notice of seminar on 781208 on new Hodel Radiological Effluent Tach Space for nuc pur plants Requests advance submission of seminar specific questions W/encl Seminar info Sheet.Proposed Agenda & maps GRIER. 8. H Region 1, Philadelphia. Office of the Director 78/11/21. Bpp. 94373 192
- 7812150026 Discusses possible dangers of LOCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing H/enci ANON 7812080207 SCHNENCER, A. Operating Reactors Granch ( Pre 790525) 78/11/28. 5pp. 94210-001
- 7812150321 Responds to 781121 memo requesting mod to Environ Tech Specs to req continuous monitoring & recording of effluents from detergent Waste Collector tanks. Memo has been forwarded to DSE.
  EIBENHUT. D. Q. Assistant Director for Systems Engineering (Pre 791030), 78/12/04 p. 94022:014.
- 7812070180 Forwards application for amend to OLs ZARMAS-P Consolidated Edison Co of New York 78/12/05. 1p. 94375:030
- --7812070182 Application for amend to DLs Certificate of Svc encl CAMILL W J Consolidated Edison Co of New York 78/12/05 12pp. 94375 03t.
- 7812280126 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantisted by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J. O. Office of Inspection & Enforcement. Office of the Director 78/12/06 2pp 94310.262.
- 7812030013 Requests views of Regional Directors on Licensee performance eval of subj facils. Forwards questions to be enswered by 771209.
  THORNBURG. H. Division of Reactor Construction Inspection. 77/11/23. 2pp
- 7812190174 Forwards copies of "App1 for Amend to Oper Lic" which request amends to section 4 1 2a of Environ Tech 8pec Requirements for subj facils. Amends would restructure present Aquatic Environ Monitoring Prog. Cert of 8vc encl. CAHILL.M. J. Consolidated Edison Co. of New York. 78/12/14. 3pp. 94340:002.
- --7812190180 Appl for emend to Licensee DPR-3, DPR-26 & DPR-64 requesting rev to Environ Tech Specs Rev Tech Specs & praposed mode are designed to provide a monitoring prog for continuous assessment of Hudson River fish population. CAHILL.H.J., EARLY.P.J. Consolidated Edison Co. of New York. 78/12/14. 46pp. 94340:003.
- G. Inspection reports, IE Bulletins & correspondence
- 7810160246 Forwards IE Bulletin#78-12: "Atypical Welf Material in Reactor Pressure Vessel Walds" requesting action w/n 60 days & list of IE Bulletin Issued in 1978 (8ee AND # 7810040283) ORIER, B. H. Region I, Philadelphia, Office of the Director. 78/09/29. App. 94003:308

- 7811060201 Forwards 1E Circular#78-17 (See AND.7810230221.Docket #50-133.781013)
  ORIER.8. H Region i, Philadelphia, Office of the Director.
  78/10/13 lp 94889 200
- 7811060224 Act receipt of 780818 itr informing NRC of Steps teten to correct violations noted during inspect50-003/78-06 & #30-247/78-19 GRIER-8 H Region 1. Philadelphia. Office of the Director. 78/10/20 2pp 94488.141
- --7811060238 Responds to 780712 NRC itr re Violations noted in Inspec Repts#50-003/78-06 & #50-247778-19. Corrective ections Quality Assurance checklists mode environ audit procedures & related environ procedures revised ZARAKAS.P Consolidated Edison Co of New York 78/08/18 4pp 94488.143
- --7811050239 Forwards IE inspec Repts#30-003/78-05 & #50-247/78-16 on 780316-18 & 780322-23 & Notice of Violation.
  GRIER.B. H. Region 1. Philadelphia. Defice of the Director 78/07/12. 3pp 94488:147
- ~~7811060244 Notice of Violation from Inspec on 780516-18 & 780522-23 BTOHR, J. P. Region 1, Philadelphie, Defice of the Director 78/07/12 3pp 94488:150
- --7811060247 IE Inspec Repts#30-003/78-06 & #50-247/78-19 on 780516-18 during which 5 items of noncompliance were noted failure to monitor cooling water systems & approve procedural changes in accord u/EBTR/failure to submit timely measurement repts BCRES. J. Region 1. Philadelphia. Defice of the Director 78/07/07. 24pp. 74488 153
- 7812010345 Forwards licensee performance avaluation for Region 1 No operating reactor in Region 1 is considered to have either abnormal or unusual safety concern. GRIER, B.H. Region 1, Philadelphia, Office of the Director 78/11/01. 4pp. 94418:254.
- 7811140252 Ack receipt of 781018 ltr informing NRC of steps taken to correct violations noted during inspecM50-003/78-11 & W50-247/78-29.

  BM17H.O H. Region 1. Philadelphia. Fuel Facility & Materials Sefety Branch. 78/11/03. lp. 94400.106
- --7811140255 Responds to 780926 NRC ltr re violation noted in inspec Repts#50-003/78-11 & #50-247/78-29. Corrective actions. malfunctioning pen linkage mechanism in recorder of monitor CT-1014 repaired & monitor fluehed CAHILL. H. J. Consolidated Edison Co. of New York 78/10/18 2pp
- --7811140256 Forwards 1E Inspec Repts#50-003/78-11 & #50-247/78-29 on 780905-00 & Notice of Violation. CROCKER.H.H. Region 1. Philadelphia, Fuel Facility & Meterials Safety Branch. 78/09/26 2pp. 94400 109
- --7811140299 Notice of Violation from Inspec on 780905-08 CROCKER.H.W. Region 1. Philadelphia, Office of the Director. 78/09/26 1p. 94400:111
- --7811140262 IE Inspec Repts#50-D03/78-11 & #50-247/78-29 on 780905-08 during which 1 item of noncompliance was noted; failure to continuously monitor & record liquid effluent discharges. THONUS.L. Region 1. Philadelphia. Diffice of the Director 78/09/24. 6pp 94400 i12.
- 7812180037 Forwards 1E inspec Repts#50-003/78-12 & 50-247/78-33 on 781011-12 during which no items of nancompliance were noted. SMITH 0. H. Region 1. Philadelphiae Fuel Facility & Materials Sefety Branch. 78/11/03. 2pp. 94133:092.
- --7812180038 IE Inspec Repts#50-003/78-12 & #50-247/78-33 on 781011-12 during which no items of noncompliance were noted Major arees inspected incl-observation of licensus conducted emergency drill & circulating cooling water temp monitor. BURES,R J., 810HR.J.P. Repion I. Philadelphia, Fuel Facility & Meterials Bafaty Branch. 78/11/02. App. 94133-094
- 7811290214 Forwards JE Circular #78-18, "UL Fire Test, "W/enc1 ANO: 7811150002.

  ORIER.B.N. Region 1, Philadelphie, Office of the Director. 78/11/06 1p. 94237, 329.
- 7812150133 Forwards 1E Bulletin#78-12A, suppl to 1E Bulletin#78-12. W/encl AND:7811300055. ORIER:8.H. Region 1. Philadelphia, Office of the Director. 78/11/24. 19. 94212:174.

ept 1978 including breakdown & total weight AHILL-W J. Consolidated Edison Co. of New York 78/10/13 Spp. 4412:171

1210340 Forwards Monthly Oper Rept for Oct 1978 AMTLL-W J Consolidated Edison Co. of New York 78/11/15. ip 4484-328

811210344 Monthly Oper Rept for Oct 1978 KANULA, L., MAKEREACE, J. Consolidated Edison Co. of New York. 78/11/08. 9pp 94484 299

2010206 Forwards corrected copy of Chem Discharges sheet in Section iO1 Cert Rept for Oct 1978. IONTI, H. A. Consolidated Edison Co. of New York. 78/11/15. 2pp. 14409 265

.1220153 Forwards tabulation of daily record of fish collections for lct 1978 w/dsily species breakdown & total weight: AHILLIH J. Consolidated Edison Co. of New York 78/11/16. 4pg. 74074: 277

12180132 Forwards data epacified in Section 401 Certification for Commonwealth Edison Co. 78/12/10. 17pp. 94366:056

12270188 Forwards rept of fish impingement & corrective action for Nov 1978 CAHILLIN J. Consolidated Edison Co. of New York. 78/12/14. 5pp 94018.037.

12210207 Forwards Monthly Open Rept for Nov 1978, CAMILL.W. J. Consolidated Edison Co. of New York 78/12/15. 1p 94279, 163,

7812210211 Monthly Open Rept for Nov 1978 KANULA, L. Consolidated Edison Co. of New York. 78/12/05. 7pp. 94279 104.

CHET 50-6 BATTELLE MEMORIAL INST. REBEARCH REACTOR Inspection reports. IE Bulleting & correspondence

ill170316 Forwards 1E Inapec Repts 0-0008/78-04.430-05728/78-03 & #50-006/78-01 on 780911-15 during which no ltems of noncompliance were noted DAVIB.A B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch. 78/10/10. 2pp. 02763:322.

-7811170319 IE Inspec Repts 70-0008/78-04.30-05728/78-03 & 50-006/78-01 on 7B0911-15 during which no items of noncompliance were noted. Areas inspecirediet protec progredioactive waste mgt. tech spec requirements for retired res reactor.

MILLER, D. E. Region 3. Chicego, Fuel Facility & Meteriels Safety
Branch. 78/10/10. 7pp. 02763:324.

SCHET 50-10 DREEDEN NUCLEAR POWER STATION, UNIT I Adjudicatory correspondence

812270230 Proposed stipulation rs NRDC & CBE's representation of unnared members in Dresden-Guad Cities transshipment is not acceptable to RRC.NRC position on NRDC's petition to lotervene remeins as stated in 781103 pleading OCODARD.R: J. Office of the Executive Legal Director. 78/12/06. ip. 94017.138.

. Deneral correspondence

810310024 Informs that for SEP normal channel of oral communication will be followed, but to expedite reviews direct arel communication between subj fecil steff & members of SEP brench is encouraged. Z TEMANN, D. L Operating Reactors Branch 2 (Prs 790625). 78/10/10. 2pp. 94094: 345

#### 1. Insurance & indemnity information

'812180210 Forwards copies of insurence policies WNELIA, NF-43 & MAELU, OBTER, J. Commonwealth Edison Co. 78/12/12. 2pp. 94365:062.

7812190109 Requests refund of 66 per mut in excess indemity for paid for LicHDPR-2, MDPR-19, MDPR-25, MDPR-29, MDPR-30, MDPR-37,

#DPR-4R

POOLE, R.D. Commonwealth Edison Co. 78/12/13 1p. 94376.323

P. Operating license stage documents & correspondence

Y4167, U64.

7812080025 FOIA request for ell recorde incl.quentity of radioactive met! disposed of from former Menhantten proj in IL known as Chicago Piles#1.2 & 3. Matl disposed of in IL by Lindsay Cos et Morrie facil & Dresden facil MANGELL.D. 111inois. Stete of 78/11/06 2pp

7812050013 Requests views of Regional Directors on Licensee performance eval of subj facils Forwarde questions to be answered by 771209 THORNSURG, H. Division of Reector Construction Inspection. 77/11/23.

94200 126 200

78:11:30059 Forwards initial sval of 8 complete SEP topics & response to request for clerification of SEP documentation procedures made et 780531 meeting. Requests response re facts used to define plents by NRC staff. EleBhWT.D G Assistent Director for Systems Engineering (Pre 791000). 78/08/17 2pp 94010-275.

--781i130337 NRC rasponse to the SEP owners group suggestions for documentation procedures for the NRC Systemetic Evaluation Prog Forwards conclusions re individual areas of concern at nuc power plents

\* Assistent Director for Systems Engineering (Pre 791030) 78/09/17. 23pp 94010:293

7810190148 Reports on use of Type B ATCOR cesk#BC-48-220 BTEPHENBON. B. B. Commonwealth Edison Co 78/10/03. ip 94414:058.

7811080275 Notification of 781023-24 eite visit to observe, discuse & identify sits specific salamic design features & info.
Agende-liet of partinent info required for review by senior selamic review team & description of BEP review encl ZIEMANN.D. L Operating Reactors Branch 2 (Pre 790625) 800.

7810200084 Analytic work re testing of core spray distribution et facility in progress Work must be finished before conclusions cen be drawn from test program Rept will be submitted by mid-Osc 1978
TURBAN,M.S. Commonwealth Edison Co. 78/10/13. 1p. 94367:094.

78:0240158 Forwards evaluation of surveillance requirements on BWR recirculation pumps & discharge valves in operation w/less then ail loops in svc.BHR jet pump operating indications & upper plenum injection w/DBEs affectd in LOCA TURBAK-M. B. Commonwealth Edison Co. 78/10/18. 19pp

7811100105 Forwards copy of NUREG-0485, "Status Summery Rept-Systemetic Evel Pres. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 78/10/19.

--7811100109 "Btetus Bummary Rept. Systematic Evaluation Program " . Office of Management and Program Analysis. NUREO-0485 VO: 78/09/22, 205pp.

78:0260153 Requests 45-day extension to allow time to provide addl inf re eccuracy of environ quelification of sefety-related electrical equipment.

TURBAK: M. S. Commonwealth Editon Co. 78/10/23 ip 94095.338.

7811020322 Withdraus request to emend Tech Space re reporting requirements for reactivity enomelies as Reg Guids "Interpretetion" by NRC on 780701 does not require rept for reactivity increase of less then 5 eecs. REED C. Commonwealth Edison Co. 78/10/26 2pp. 94255; 223

7811030161 Forwards proposed Amend changing Tech Space w/regard to updating station organizational charts. Changes have received onsite & offsite approval. REED, C. Commanweelth Edison Co. 78/10/26. 9pp. 02724: 009.

- 7811140014 Requests add) into on FRF switchover from injection to recirculation made, isolation of reactor protecting from non-tarfety may. ERF may logic b design & specific drawings of elect sys. & complete plant elect drawing indices ITEMANN.D L. Operating Reactors Branch 2 (Pre 790525) 78/10/26 Jpp. 74423-340
- 7811140002 Notifies applicant of 781128 NRC-sponsored seminar re-Model Radiological Effluent Tach Specs for Nuc Pur Plants w/encl Saminar Info Sheetito be completed & returned by 781117) & Proposed Agenda.
  KEPPLER.J. G. Region J. Chicago. Defics of the Director 78/11/07.
  App. 94426:022
- 7811270071 Forwards Amend#27 to Facil Oper LickDPR-2 & essociated Safety Eval & Notice of Issuance CIEMANN.D. L. Operating Reactors Branch 2 (Prs 790625) 78/11/09 2pp. 94246-303.
- --7811270073 Amend#27 to Facil LicMDPR-2.permitting open of subj facil for low pur physics test. ZIEMANN, D L. Opensting Reactors Branch 2 (Pre 790625) 78/11/09. 4pp 94246:305
- --7811270078 Bafety Eval Supporting Arendw27 to Fecil Oper LickDPR-2.
  Concludes there is no increased risk from its
  Implementation

  Office of Nuclear Resector Regulation, Director. 78/11/09 4pp.
  94246-309
- --7811270081 Natice of lesusnes of Amend #27 to Facil Oper LickDPR-2 permitting oper of subj facil for low pur physice test ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/09. 28p. 94246:313.
- 78:1280430 Forwards draft Bys Evel Prog Safety Inputs re Tapic VIII-3 A. Station Dettary Text Req Requests they be transmitted to licensees. DAVIS.O.K. Systematic Evaluation Programs Granch (Pre 790625). 78/11/14. 23pp. 94381:119.
- 7812150071 Notification of workshops in Jan-Hay 1979 in Regions 1-5 to siplain techniques of job analysis & performence testing to how to relate such testing to qualification plan development & training. Designed for working level personnel HILLER.J.R. Assistant Director for Site & Sefeguerde (Pre 791030). 78/11/15. 5pp. 94210:213
- 7812180248 Forwards RevM1 "Oraft Radiological Effluent Tech Space" for BMR's(NuREO-0423) & "Preparation of Radiological Effluent Tech Space for Nuc Pur Plants" (NuREO-0133). GRIMESIO. M. Assistant Director for Engineers & Projects (Pre 790425), 78/12/13. 49p 94364-123
- 7812030107 Forwards rev page to Topical Rept CE-1-A: "Gual Assurance Prog. Rev 6." Rev reflects Reg Guidel. 28 & 1 33 rev. TURBAK: M. G. Commonwesth Edison Co. 78/11/17 2pp. 94335; 354.
- 7811280213 Forwards current lic status list for subj facils. REED C. Commonwealth Edison Co. 78/11/20, 9pp. 94012:130.
- 7812040194 Rept on 780927 visit to facil for familiarization 4 eddl info. Industrial & tranep facils & control room area were observed. FBAR aubjects were discussed W/list of perticipants.
  FONTECILA.H M. Bystematic Evaluation Programs Branch (Pre 790625).
  78/11/20. opp. 94457:122.
- 7812060303 Notification of 781207 meeting w/8EP Owner's Group in Bethesde. MD to discuss plane to address esismic input for use in BEP seismic review.
  LEVIN.H.A. Systematic Evaluation Programs Branch (Pra 790625), 78/11/24. 2pp.
- 7812080114 Proposes Tach Spec change is min reactor vassel head stud teneigning temp. Changing it from 130 F to 70 F Change is req because 130 F temp is difficult to meintain when solvent is in primary sys. Wistress fracture analysis.

  REED. C. Commonwealth Edison Co. 78/12/01. opp. 94104:354.
- 78:2110055 Forwards safety evaluation to used for feedwater pump trip on reactor high water level. Trip determined unnecessary to ensure safe operation of facility.
  71EPANN D. L. Operating Reactors Branch 2 (Pro 790625), 78/12/01.
  4pg. 94408:282.
- 78:2120:35 Forwards revised lists w/environ qualification of safety-related electrical squipment in response to NRC 780906 ltr. Includes SEP by equipment type. SEP submittal ref. location time required & type of environ.

  TURBAN, M.S. Commonwealth Edison Co. 78/12/01. 31pg. 94276.297.

- 7812280129 Emphasizes importance of submitting accurate & completo NRC by licensees & applicants Info submitted must be substantiated by date & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J 0 Office of inspection & Enforcement. Office of the Director 78/12/06. 2pp. 94311:336
- 78:2140361 Requests eval of systems designed to accomplate effective pipe breaks inside containment at subj facil in order for NRC to complete SEP review ILEMANN.D L. Operating Reactors Branch 2 (Prs. 790625). 78/1: 3pp 03557 235
- 7812150099 Requests add1 info from SEP licensess re slet penetr of reactor containments in order to complete eval. ILEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/14pp 94212 032
- 7812210078 Forwards NUREG-0485,Vol 1.Number 2. "Status Bummary 8EP." W/o enc! TIEMAKN.D.L. Operating Reactors Granch 1 (Pre 790625) 78/1 2pp. 94269 360.
- 7812190097 Accepts topical rept#CE-1-A Rev#6, "Comm Edison Co Qu Assurance Prog for Nuc Generating Stations." Requests submittel of 36 copise HAASS.H.P Quality Assurance Branch. 78/12/13 ip. 94376:
- 7812270375 Responds to 781120 request for temporary waiver of R Prog for Cic Operators & Benior Operators(Limited). Betton 3. paragraph B Requests proposed determination of amend class-state the basis & submit fee of \$1200 D1GOS-R.M License Fee Management Branch. 78/12/19. 1p. 94227:224.
- 78:2270327 Describes and plans to lines to make them comply w/A local lesk rate test requirement Mpd will be completed during chemical cleaning.
  TURBAK.M.S. Commonwealth Edison Co 78/12/20. 3pp. 94232.
- O. Inspection reports, IE Bulletins & correspondence
- 7810110052 Forwards IE lnsp Repts 50-010/78-23.50-237/78-21 & 5 78-23 on 780807-10 & 16-18 & notice of deviation. DAVIS.A.S. Region 3. Chicago. Office of the Director. 78/09 2pp. 74080:049.
- --7810110054 Notics of Deviation from inspec on 780807-10 & 780
  \*\* Region 3. Chicago, Fuel Facility & Materials Bafety Bran 78/09/08 1p. 94063: 226
- --7810110062 is Inspec Repts#50-010/78-23.#50-237/78-21 & #50-2 on 780807-10 & 16-18 during which I item of deviation was noted Failure to meet FSAR commitment for manitoring unit 2/3 liquid rad waste sefluents.

  OREGER.L.R. FIBHER,H L. Repian 3. Chicago. Office of the Director. 78/09/06 11pp. 94063:227
- 78:1010018 Forwards IE Inspec Repts#50-10/78-25, #50-237/78-22 & 78-24 on 780705-06.11-12, 19-20, 780817, 23-25, 29-31 & 780901, during which no items of noncompliance were noted. FIGRELIT. 9. Region 3. Chicago. Reactor Operations Nuclear Su Branch. 78/09/20. 2pp. 94290-141.
- --781010022 IE Inspsc Repts#50-10/78-25,#50-237/78-22 & #50-24
  780705-06,11-12,19-20,780817,23-25,29-31,780901.during which no items of noncompliance were noted Hajor areas inspect followup of noncompliance & review of plant open.
  BANKER, J. L. Region 3, Chicago, Office of the Director. XN
  Region 3, Chicago, Reactor Openations Nuclear Support Brance 78/09/20. 7pp.
- --7811010022 IE Inspec Rept#50-10/78-25, #50-237/78-22 & #50-245 780703-06, ii-12, i9-20, 7808[7, 23-25, 29-31, 780901, during which no items of noncomplience were noted Major areas inspec: followup of noncompliences & review of plant open. BARKER, J. L. Region 3, Chicago, Reactor Openations Nuclear Brench. 78/09/20. 7pp.
- 7810110277 Responds to 780908 NRC itr re deviation noted in Int Rapts 50-010/78-23, 50-237/78-21, 50-249/78-23. Corrective actions: liquid radwasts dischargs monitor will be returned to eve 4 starm will be made operable. REED.C. Commonwealth Edison Co. 78/09/22. 3pp. 94079: 148.
- 7811010009 Response to 780921 NRC ltr re deviation noted in IE Rept#50-10/78-27. Corrective actions: lubricating oil pressure readings were w/in ranges recommended by vendor. Procedures will be revised by 781006.
  REED.C. Commonwealth Edison Co. 78/10/06. 2pp. 94290:244.

- 1p 94290 248.
- --7811010027 IE Inepsc Rept#50-10/78-27 on 780816-17 during which i item of noncompliance was notedifations to adhere to approved procedures white testing record of temporary diseal generator.acceptable criteria values had not been met. SMITH.U.D. Region 3. Chicago. Office of the Director NEVES.L.A. SUPPERTER.U.F. Region 3. Chicago. Neactor Operations Nuclear Support Branch 78/09/19 4pp 94290-247.
- 7810200203 Ack receipt of 780922 ltr informing NRC of steps taken to correct item of noncompliance identified in ltr of 700900 DAVIS.A D. Region 3. Chicago, Fusi Facility & Materials Bafety Branch. 78/10/12. 1p. 94367:009
- 7810300030 Forwards IE Circular878-17 (See AND 7810230221)
  KEPPLER, J. G. Region 3. Chicago, Office of the Director 78/10/13
- 7810310093 Forwards review of weid portion of inservice insp program.
  New tables show total number of walds or components
  requiring insp over plant ideatime for each code catagory
  TURBAK-M B. Commonwealth Edison Co. 78/10/19 120pp 94091.170.
- 7811300261 Forwards IE Inspec Repts#50-010/78-26:50-23/78-23 & 50-249/78-25 on 780905-08:12-14:20-22: & 26-28 & Notice of Violation FIDELLI.9. Region 3: Chicago: Reactor Operations Nuclear Support Scance. 78/10/25. 2pp. 94075:233.
- --7811300264 Notice of Violation from inspec on 780905-00.12-14.30-22 & 26-28.

  Region 3. Chicago. Reactor Operations Nuclear Support Branch 78/10/25. 1p. 94075:061.
- --7811300268 IE Inapet Rapte#30-010/78-26.50-237/78-23 & 50-249/786-25 on 780905-08.12-14.20-22 & 26-28 during which I itam of noncompliance was noted: fatiure to rapt a 30 day reportable event in 30 days.

  BARKER J. L. CHRISBOTIMOS N. HUOHES J. Region D. Chicago. Reactor Operations Nuclear Support Branch 78/10/25. 15pp 94075.237
- 78:1020335 Ack receipt of 78:1006 itr informing NRC of staps taken to correct violations noted during inspecs50-010. FIDRELIA G. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78:10725. ip. 94241:016.
- 7812050011 Forwards IE Inspec ReptsM50-010/78-29, 50-237, -294, -295, -304/78-25, 50-249/78-27 t 50-265/78-26 on 781002 during which no items of noncompilance were noted.

  KEPPLER, J. Q. Region 3. Chicago. Dffice of the Director. 78/10/30.
  2pp. 74200:183
- --7812050027 IE Inspec Repts for subj facile on 781002 during which no items of noncompliance were noted. Major areas inspected inclidiscussion of actions being taken by util to improve its rag performance & tour of Zion station.

  KNDP:R C., FIORELLI.O. Region 3, Chicago, Reactor Operations Noclear Support Granth KEPPLER.J.O. Region 3, Chicago, Dffice of the Director. 78/10/30. 3pp. 94200:185
- 7811150063 Forwards IE Circular 78-18, "Underwriters Lab Fire Test " KEPPLER.J Q. Region 3, Chicago. Office of the Director. 78/11/06 Jp. 9412:240.
- 7811280486 Unresolved items noted in IE Inspec ReptsM50~010/77-28, 850-237/77-25 & #50-249/77-25 have been reviewed & recommendations made, Documentation of unresolved items withold per 10CFR2.790(d).

  HIND.J.A. Region 3. Chicago, Bafeguarda Branch. 78/11/16. 1p. 94381:358.
- 7812050297 Forwards IE Builatin 78-12A, "Atypical Waid Mat) in Reactor Pressure Vessei Walds."
  KEPPLER J. O. Region 3. Chicago, Defice of the Director 78/11/24.
- 78121400B1 Forwards IE Inapec Reptem50-010/78-2B. 850-237/78-24 & 850-249/78-26 on 781010-13,781016-19 & Notice of Violation. Reptem, J. O. Region 3. Chicago, Défice of the Director 78/12/01. 2pp. 9412B: 227.

- 7812290026 Forwards IE Builotin 70-14. "Deterioration of Buna-N Components in ABCO Balenoids." KEPPLER, J. O Region 3. Chicago, Office of the Director 711/12/19 ip. 94208 009
- R Periodic uperating reports & related correspondence
- 7810100078 Monthly Progress Rapt required for scheduled ECCS/1ECE-279 & fire protec mode TURBAK.M S Commonwealth Edison Co. 78/10/04 2pp 94032:236
- 7810100101 Forwards monthly operating mept for Bapt 1970 GTEPHENSON, B B Communicalth Edizon Co. 70/10/12 ip 94066 200
- --7010180104 Monthly aparating rept for Bept 1970 PIELAN J F. Communication Edition Co. 78/10/10 63pp 94366-289
- 7811140099 Monthly rapt for Oct 1978 on progress re completion of sche ECCB.IEEE-179 & fire protec mode All work is still underway. TURBAK-M 8 — Commonwealth Edison Co — 70/11/08 — 2pp — 94425, 100
- 7011140119 Forwards monthly operating mept for Oct 1970 BTEPHENSON.B B Commonwealth Edison Co 70/41/00 ip 94485 104
- --7811140169 Manthly operating rept for Oct 1978. PIELANJF Communweith Edison Co. 78/11/00 Spp. 94425 185.
- 7812130184 Forwards monthly operating rapt for Nev 1978 BYEFHENSON, B. B. Commonwealth Ediator Co. 78/12/08 ip 94304-001
- --7012130106 Honthly Open Rept for Nov 1770 PIELAN, J. F. Commonwealth Edison Co. 78/13/05 6pp. 94306-002
- 9. Reportable incorrences, tells & related correspondence
- 7010170204 Forwards LER 78-030703L-0 BTEPHENSION B. D. Communicatiti Edison Co 78/10/03 to 94236:361.
- --7010170216 LER 70-030/001.-0 on 200914, white performing DDB 1600-1, amergency condenser nutlet valve MOIOL failed to close remotely from control room. Caused by valve operator needing tubrication Valve exercised & closed manually MOIR-1 Commonwealth Edison Co. 78/10/03 1p. 94236-362.
- 781024014B Forwards LER 70-029/03L-0 STEPHENSON, 8 B Commonwealth Edition Co 78/10/12 1p
- --7810240150 i.ER 78-027/03L-0: on 780914 ieak found in retirculation if C4446-3" GI-RI at wald approx i ft above collector tank where pipe reduces from 3 to Q inches, cousing continuous funding of reduces bidg morth sump pump Caused by erosion. TRAXLER, D.V. Commonwealth Edison Co. 78/10/12 ip
- 7811090113 Forwards LER 78-031/03L-0 BYEPHENBON.B B Commonwealth Edison Co 78/10/30 ip 94042 293.
- --7811090124 LER 78-031/031-0. on 781007, insplot turbing pipeway locate two lasks in Electron bypass line (2705-4"-FB). Caused by pipe erosion. One hole repaired w/welfed patch & other w/ clamp-on patch. Line echeduled to be replaced during outngo TRAXLER, D. V. Commonwealth Edison Co. 78/10/27 ip. 94042 294.
- 7811210388 Forwards LER 78-032/017-0.
  BTEPHENSON.B.B. Commonwealth Edison Co 78/11/13 1p 94406 200
- --7811210392 LER 78-032/01T-0 on 781031. following spurious reactor screening normal shutdown.cooldown rate discovered to be 35 F greater than Tach Space limits. Caused by failure of operator to isolate SUAE in time to greent cooldown.

  ALLEN.R Commonwealth Edison Co 78/11/13 2pp 94486-281
- 7812180174 Forwards LER 78-034/03L-0 8TEPHENSON, B. B. Commonwealth Edison Co. 78/18/08, 2pp. 94339.330
- --7812180177 LER 78-034/DDL-0:on 781201.channeled fuel assembly drappe from grapple while being transferred to spent fuel pool Caused by assembly not being properly istined to grapple FARRALD. Commonwealth Edison Co. 70/12/01 3pp 94339:332

- V. Operator Examinations
- 7811270138 Requests temporary wasver from Section III-Paragraph 8.00 "Requalification Program for Licensed Operators. Senior Operators & Senior Operators thimsted)." Current program of lectures eases & mod training to continue during shutdown. TURSAK-M. B. Commonwealth Edieon Co. 78/11/20. 2pp. 94233:393.

DOGKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY
J. Insurance & Indemnity inforestion

- 7809130339 Signed Amendmi8 to Indomnity Agreement#8-8.adding new Article VIII re: payment of assessed deferred premiums for subj facile.

  GALIZHAN.J. Antitrust & Indomnity Group. 78/09/01. 2pp.
- P. Operating license stage documents & correspondence
- 7811000166 Forwards corrected copy of 781016 ltr to recipient, which should have referenced Doctat#50-10 in addition to #50-99. REID. R. H. Dpereting Reactors Brench 4 (Prs 790625). 78/10/24. 1p. 02724: 025.
- 7812180060 Forwards AmendWi0 to Oper LicMCX-10 & Sefety Eval rept in response to 780626 request. REID.R.H. Operating Reactors Branch 4 (Fra 790625). 78/11/29. 1p. 94133: 102.
- --7812180064 Bafety Evel Rept in support of Amend WiO to Oper Lic MCX-10. REID.R. W. Operating Resectors Brench 4 (Pre 790625). 78/11/29. 2pp. 94133:106
- G. Inspection reports, 1E Bulletins & correspondence
- 7810270103 Forwards 1E Inspec Repts#50-99/77-4 & #50-13/77-4 on 771129-771201 during which no items of noncompliance were noted. KENNA.H.B. Region Q. Atlenta, Sefeguerds Branch. 77/12/27. 2pp. 94059:287.
- --7810270113 IE Inapst Repts#50-13/77-4 & #50-99/77-4 on 771129-771201 during which no items of noncomplience were noted. Hejor eres taspected included; physical security prag. Security plan. Security organization. Burvaillance. Access controls. JUNNER. J. N. Repton 2. Atlante, Defice of the Director. 77/12/22. ip. 94055; 288.
- 7812030001 Forwards IE Inspec Repts#50-99/78-2.#50-13/78-2 & #70-624/78-10 on 780911-15 & Notice of Violation.

  8UTHERLAND.J. T. Region 2. Atlents. Fuel Fecility & Metarials Sefety Branch. 78/10/27. 2pp. 94200:001.
- --7812050002 Notice of Violation from inep on 780911-18.
  \* Region 2, Atlanta: Fuel Facility & Materials Sefety Branch, 78/10/27. 1p. 94200:003.
- ---7812050005 1E Inspec Repts #50-99/78-2,#50-13/78-2 & 470-824/78-10 on 780911-15 during which 1 litem of noncompliance was noted; storage of flammable liquids in containers that ere not safety approved cans.
  PERROTTI.D. J. Region 2. Atlante. Office of the Director. 78/10/27. 17pp. 94200:004.
- 78:2080215 Forwards Inepac Rept#50-099/78-03 & Inspec Rept#50-013/78-03 on 78:0918-22 during which no items of noncomplience were noted.

  8UTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/10/30. 299, 94137:074.
- --7812080219 IE Inspec Rept#50-099/78-03 & IE Inspec Rept #50-013/78-03 on 780918-22 during which no items of noncompliance were nated. Major ereas inspec inclinadiat protec procedures & posting & labeling. DAVIB, J. H. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/10/30. 7pp.
- 7812200156 Concurs that inspac rept contains no proprietory info & agrees to placing it in NRC PDR. ENGELDER, T. C. Babcack & Wilsox Co. 78/12/08. ip. 94136:334.
- ~~7812200158 Forwards Inspec Repts#50-13/78-4 & #50-99/78-4 on 781115-17 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Spanch. 78/12/01. 2pp. 94154:355.

--7812200161 IE Inspec Repts #50-013/78-04 & #50-099/78-04 on 781115-8 during which no items of noncompliance were noted Major areas inspected inclides & records reviews & audits: esperiments refueling procedures & IE Circular review. HINCKLEY.D.Q., MCHENRY.T.J., DANCE.H.C. Region 2, Atlante, Office of the Director. 78/12/08. Dep. 94156:337

DOCKET 30-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

J. Insurence & indemnity information

١

- 7810120021 Forwards endorsement#90 to Nuc Energy Liability Insurence Policy NF-92 requested in 780922 NRC ltr.
  MATERS.B.R. Detroit Edison Co. 78/10/05. 3pp. 94330:170.
- P. Operating license stege documents & correspondence
- 7810310025 Ack ltr & mpt meeting w/ NRC et util on 780823. WHIDDON,D. Detroit Edison Co. 78/10/03. 1p. 94094:362.
- DOCKET 30-18 VALLECITOS BUILING WATER REACTOR
- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 7812060002 Comments on size of Trenches A, B, L E at facility. Final eval must be besed on evidence indicating whether thrusts near reactor ere due to landstiding as tectonic processes & whather there are other feuits commected withrusts.

  THOMPSON, G. Affiliation Unknown. 78/10/24, 2pp. 94328:060.
- P. Operating license stage documents & correspondence
- 7811080345 Supports a parmanent shutdown of the Vallecitos plant in G because of tritium sessegs into underground water. PLANCK.C. Affiliation Unknown. 76/10/16. Ip. 94406:317.
- 7811130177 Forwards preliminery trench logs for facil site.
  DARMITZEL.R.W. General Electric Co. 78/11/02. 73pp. 94087:050.
- 7812260096 Summary of 781205-06 site visit to observe tranches & discuss seismic implications of derived data.

  JACKBON.R. E., GREEVEB. J. T. Geosciances Stench. 78/12/13. App. 94349: 330.
- DOCKET 50-20 MASSACHUSETTS INST. OF TECH. REB. REACTOR
  P. Operating license stage documents & correspondence
- 7812140095 Forwards Amend#15 to fecil liceR-37 which identifies currently approved security plan & incorp this plan as a condition of the license. Becurity plan w/held pursuent to 2.790.
  REID.R.U. Operating Reactors Stanch 4 (Pre 790625), 78/11/28.
- ~~7812140098 Amend#15 to Facil Open Lic#R-37 re incorp of security p into a condition of the lic.
  REID.R.H. Opereting Reactors Branch 4 (Pra 790625). 78/11/28.
  29p. 94126:353.
- 7812080093 Requests that Tach Space for subj facil be amended by adding definition for the term "Frequency." Lack of such a definition has resulted in veryling interpretations of time intervals. Suggested definition preferred. CLARK.L. Massechusetts instituts of Tachnology. 78/12/04. 2pp. 74108.032.
- G. Inspection reports, IE Sulletine & correspondence
- 7810180178 Forwards IE Inspec Repts#50-020/78-04,70-0089/78-02, 70-0194/78-02,70-0095/78-02 & 70-0938/78-02 on 780809-18 during which no items of noncompliance were noted. MARTIN.M.O. Region 1, Philadelphia, Befeguards Branch. 78/09/Od 2pp. 94317; 146.
- --7810180181 IR Inspec Repts#50-020/78-04:70-00899/78-02:70-0194/71
  70-0095/78-02 & 70-0938/78-02 on 780809-11 during which no items of nancompliance were noted. Area inspected; not matl control & accounting prog. inventory & records.
  HQLQDY,D.J., B188E17,P.H. Region i. Philadelphia, Bafeguards Brench. 78/08/20. 7pp. 94317:148.

- 7811300355 Forwards IE Inspec Rept#05000020/78-05 & Notice of Violation.
  BMIM.O.H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 78/10/18. 2pp 94116:303
- --7811300377 Notice of Violation from inspec on 780913-15 • Region 1, Philadelphia. Fuel Facility & Materials Bafety Branch 78/10/18 ip. 94116:305
- --7813300380 lE Inspec Rept#50-020/78-05 on 780913-15 during which I item of noncompliance was noted. Pailure to submit a timely notice to NRC & Pailure to have a copy of a shipping container certificate.

  BERABIAN. J. A., PLUMLEE, K. E., KNAPP, P. J. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch. 78/10/05. 11pp 94116-306.
- 7812180078 Forwards IE Inspec Rept#50-020/78-07 on 781004 during which no items of noncompliance were noted. CARLEON, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/03 2pp 94131:342
- --7812180082 IE inspec Rept#50-020/78-07 on 781004 during which no items of noncompliance were noted Hajor areas Inspected incl. fabrication & installation of new addl stainless steel heat sichanger in reactor coolant water sys.

  SANDERS.W F., EBNETER.B D Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 78/10/30. 3pp 94131 344.
- 7812060180 Ack receipt of 781107 ltr informing NRC of steps taken to correct violations noted during inspect90-020/78-06.
  BRUNNER.E. J. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/11/24. 1p. 94382:105
- --78120601B3 Responds to 781016 NRC ltr re deviations in inspec Rept #50-020/78-06 MIT will apply for amend of tech specs to define frequency-permitting an extension of time interval between surveillence test & other functions by 25%. CLARK.L. Massachusetts institute of Tochnology. 78/11/07. 2pp. 94382.106.
- --7812060194 Forwards 1E Inspec Rept #50-020/78-06 & Notice of Violation. BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78/10/16 2pp. 94392:108.
- --7812060203 Notice of violation from inspec on 780927-29.

   Region i, Philadolphia, Dffice of the Director. 78/10/16 lp 94382-110
- --7812060219 lE Inspec#50-020/78-06 on 780927-29 during which i item of noncompliance was noted Reactor Bafeguards Comm neetings were too infraquent.

  9TETA.T., GREENMAN.E. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/10/16. 7pp. 94382:111.

#### DOCKET 50-22 WESTINGHOUSE TEST REACTOR

- G inspection reports. 1E Bulletins & correspondence
- 7811030146 Forwards Addendum to Annual Inspec Rept For Lic#TR-2 Anewere questions re isotopic composition & source of radioactivity in MTR canal water.
  DIPIAZZA: R.P. Wastinghouse Electric Corp. 78/10/31. 3pp. 02723: 2A1
- BOCKET 50-27 WABHINGTON STATE UNIV. RESEARCH REACTOR
  F. Gecurity, medical, emergency & fire protection plans
- 7811030014 Amend submitted in 780823 ltr is an admin mod of security plan & does not affect Facility security. Finds amend acceptable.
  REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/17. ip. 02720: 282.

### DOCKET 50-29 YANKEE-ROME NUCLEAR POWER STATION F. Security, medical, emergency & fire protection plans

781020005: Comments on fire protec eval safe shutdown methods &

- 7811020012 Forwards subj fecil Fire Protec Review describing summary of staff positions, licensee response & status of corrective actions taken to satisfy staff concerns LAINAB.Q Plant Systems Branch (Pre 791030) 78/10/24. 38pp. 94351-193
- 7811070300 Notice of 781109 meeting w/util to discuss fire protection program including fire brigade staffing & interim fire protection mode BURGER. A Operating Reactors Branch 2 (Pre 790623) 78/11/01 2pp 07893-053
- 78:11:30321 Forwards staff positions to aval of subj facil fire protecting on 78:0925-20 Identifies areas of concern in the program at adequately addressed by YAE 21EMANN.O.L. Operating Reactors Branch 2 (Pro 790625) 78/11/01 53pp 94087 069
- 7812050128 Forwards latest rev of mod amend security plan(MASP) to meet 780609 NRC comments. Encl w/held from put disclosure pursuant to 2 790.

  QROCE,R H. Vankee Atomic Electric Co. 78/11/29 ip 94335 049
- 7812030210 Informs NRC of util's positions on outstanding fire protectissues. H/encl 761019 MA Fireflighting Academy 1tr to util retraining prog MODDY. DE Yenhee Atomic Electric Co 78/12/01 14pp. 94331.216
- 7812190087 Describes util reviru interim fire brigade sile YAE has agreed to an interim fire brigade of 5 trained firefighters on each operating shift & to an hourly fire watch patrol util util alea contract for firefighting course HDDDY.D E Yankey Atomic Electric Co. 78/12/13 292 94343.028

#### H General correspondence

7010310159 Informs that for SER normal channel of oral communication will be followed, but to expedite revious direct oral communication between subj facil staff & members of SEP branch is oncouraged ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 70/10/10 Zpp. 74090.216.

#### J insurance & indemnity information

- 7811240044 Forwards copy of York 780927 ltr re endorsements to the ANI & MAELU policies. PARADIBO.P. J. Harsh & McLennan, Inc. . H & M Nuclear Consultants, Inc. Div. 78/10/10. ip. 94459:267.
- --781124004B Forwards certified copies of a number of enforcements to ANI & MAELU policies. Copies of endorspeents are encl along widates they were originally sent to J Belzaman YORKAR N. New England Power Co. 78/09/27. 23pp. 94455:268
- P. Operating license stage documents & correspondence
- 7811130100 Forwards Initial eval of 8 complete SEP topics & response to request for clarification of SEP documentation procedures made at 780331 meeting. Requests response re facts used to define plants by NRC staff. (See AND87811130337 ) EISENHUI.D. (L. Assistant Director for Systems Engineering (Pre 791030). 78/08/17 2pp 94010:291
- 7810110177 Re meeting of 780900 subj facil. Will undertake evaluation of assymetric LOCA loads. Evaluation will include atody of megnitude of loads on reactor vessel supports dev of models. A preparation of seismic assessments. VANCENBURGH. D. Yankee Atomic Electric Co. 78/10/00 2pp. 94069-102.
- 78:01:0163 Forwards addl info requested 780908 re reduction of incore neutron detector symbols. Tech Epocs changes t commitment to constr core map from video tape of es-loaded core JDHNBON, N. P. Yenkse Atomic Electric Co. 78/10/04. 7pp. 94069:260
- 7810130127 Util will submit tabulated info requested in 780906 1tr 49 days later than requested.

  ORDCE,R.H. Yankes Atomic Electric Co. 78/10/06. 19 94003:059.
- 7Bi0190138 Forwards Amend 91 to License #DPR-9 revising Tech Specs as requested in 7B0713 itr w/safety evaluation & notice of issuance.

ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/06.

- --7810190169 Amend 51 to License DPR-3 revising Tech Specs re limitation of crone travel over spent fuel pit & surveillance requirements for travel of giver 900 lb loads ever spent fuel pit.
  ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625). 78/10/06 4pp. 94414:070
- --TBi0190:75 Safety evaluation supporting Amend 31 to DPR-3 concluding that rearrangement in pit of spent fuel & racte. & installing new roof hatch over pit. & temporary gete support brackets in pit are acceptable of Office of Nuclear Reactor Regulation. Director. 78/10/06. Spp. 94446:074
- --7810190182 Notice of Issuance of Amend #51 to Facil Oper LIC MDPR-3 on 781006 ZIEMANN, D L. Operating Reactors Branch 2 (Pre 790625). 78/10/06. Job. 94414.082.
- 7810260160 Objects to continuous NRC demands that util meet addition titeria me overpressuritation events, while NRC review process is unjustifiably lengthy bresults only in requests for add1 info. Believes \$4000 fee request is unauthorized VANCENBURGHID. Maine Yantee Atomic Power Co. 78/10/16. Spp. 94059: 342.
- 78102400B5 Presents results of grout investigation described in 780925 ltr to NRC. Concludes that heavy metals are present which will affect pool water chemistry.

  JOHNGON-W P. Yankes Atomic Electric Co. 78/10/18. ip. 07893:046.
- 7811020247 Repte on review of 8 Systematic Evel Prop topic assessments.

  Confirms that 4 are applicable to subj facil & that it is
  essential that assessments be generalized enough to apply
  to all plants

  VANDENBURGH.D Yantee Atomic Electric Co. 78/10/20. 2pp.
  94247:112.
- 7811030011 Forwards Bafety Eval of Proposed Mode to ECCB Recirculation Bye (TAC7667). LAIRAS.O. Assistant Director for Plant Byetems. 78/10/26. 2pp. 02720:226.
- 78iii00027 Requests addi info on ESF switchover from injection to recirculation mode, isolation of reactor protec eys from non-safety eys.ESF eye logic & deeign. & specific drawinge of elec eys & complete plant elec drawing indices.

  ZIEMANN.D. L. Operating Reactors Granch 2 (Fra 790625). 78/10/26.
  3pp. 94178.284
- 7811020246 Proposes mode to Append A of Oper LiceDPR-3. Would change Table 3 6-1 to reflect addition of 4 manual isolation valves which become containment isolation boundaries & are subj to type C tests
  MINNICK.E. Yankes Atomic Electric Co. 78/10/30 Spp. 94247:107.
- 7811240090 Returns 7 copies of Proprietary Orawing#001-33679. "N"-Pump. L.P.B. 1. by Ingersoll-Rand Co which was submitted as enci to 7800222 tr but was not req for review completion. Only B copies were received & 1 was destroyed. TIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/06. 2pp. 94436, 350
- 7811210223 Responds to 780908 appl for lic amend to permit facil oper w/planned loading pattern for Core 14 & requests add1 info re fuel design.accident analysis & LOCA analysis.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/11/08.
  3pp. 94486:333
- 7811140190 Describes 2 supporting analysis re-core boron concentration following unlikely event of LOCA occuring during reactor vessel hydrostatic test on zero power physics test. VANDENBURGH, D. Yankee Atomic Electric Co. 78/11/10. 2pp. 94384: 278.
- 78:1170201 Responds to 780711 NRC itr requesting util to submit lic amend appl to incorp applicable Space of Model Tech Spac.

  Util is having difficulty meeting response sched outlined in 78071: Itr due to sched refueling.

  GROCE.R.H. Yankee Atomic Electric Co. 78/11/13. ip. 94047:339.
- 7811280080 Forwards Amend 52 to License DPR-3, safety evaluation & notice of issuance & availability.
  218MANN,D.L. Deprating Reactors Branch 2 (Pre 790625), 78/11/14.
  2pp. 02728:145.
- --7811280082 Amend 52 to License DPR-3, changing Tech Specs to permit operation w/mod to ECCB recirculation cooling subsystem. ZIEMANN. D. L. Operating Reactors Branch 2 (Pre 770625). 78/11/14. 27pp. 02728:147.

- ~7811280083 Bafety evaluation supporting Amend 32 to License DPR-3 \* Diffice of Nuclear Reactor Regulation. Director. 78/11/14. App 02/28, 173.
- --78112E0084 Notice of issuance & availability of Amend 32 to License DPR-3 MAMBACH, T. V. Operating Reactors Branch 2 (Pre 790625). 78/11/14 28p. 02728:179.
- 7811280430 Forwards draft Bys Eval Prog Safety inputs re Topic VIII-3 A. Station Battery Test Req. Requests they be transmitted to Licensess. DAVIS. D. K. Gustematic Evaluation Programs Branch (Prog 790425)
- DAVIB. D.K. Bystematic Evaluation Programs Branch (Pre 790625) 78/11/14. 23pp. 94381:119.
- 78:R150092 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requeste pre-workshop registration of ettendees to facilitate sending out mail. M/encl Registration Form & List of Locations MILLER. J. R. Assistant Director for Site & Safeguards (Pre 791030) 78/11/15. 5pp. 94212:001.
- 7812190063 Forwards RevNi "Draft Radiological Effluent Tech Specs" for PMR 's INURES-04731 & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NURES-0133). W/o and AND-7811270173 & 781127018.

  QRIFES.B.K. Assistant Director for Engineers & Projects (Pre 790623). 78/11/15. 6pp. 94215:107.
- 7811240167 Requests auth to change Tech Spec by adding add1 limit on Allowable Paak Rod Linear Heat Generation Rate for recycled fuel from Core XIII.aeeuring plant oper w/in limite defined by LDCA analyses for referenced fuel.
  VANDENBURGH, D. Yankes Atomic Electric Co. 78/11/21. 4pp. 94458:28B.
- 78:1240238 Forwards response to NRC questions requesting add1 info on core performance enalysis rept YAEC-1162. NRC questions have necessitated a Tech Base change, which will be submitted shortly.

  VANCENBURGH, D. Yenkes Atomic Electric Co. 78/11/21. 15pp.
- 7811280221 Submits design & safety cleek info applicable to parts of alternate shutdown methods mod.Entire new eye piping designed per util Engineering Dept QA Menuel & componente purchased & installed per Operational QA Menuel YOQAP~i-A QROCE.R.H. Yankee Atomic Electric Co. 78/11/21. ip. 94012:090
- 7812070158 Notification of 781208 seminar in King of Prussie.PA to discuss new model radiological affluent Tech Specs. Seminar info sheet & proposed agenda enci.

  ORIEP.S.H. Region 1. Philadelphia. Office of the Director.
  78/11/21. Spp. 94375: 184.
- 7811290255 Proposes emend to Tech Specs for facil lic.Proposed changes consist of wording changes & ciarifications.None of the changes will alter scope or bests for any Tech Bpacs.
  Proposed emend attached w/check for \$1200.
  VANDENBURGH.D. Yankes Atomic Electric Co. 78/11/24. 18pp. 94237:06A
- 7812060297 Requests comments on draft eval of Systematic Eval Prog topic 8-3.A re Station Sattery Test Requirements ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 78/11/24. 4pp. 94382: 225.
- 78:2110133 Forwards Amend 53 to License DPR-3. sefety evaluation be notice of issuence & availability.
  ZIEPMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/24.
  2pp. 94393:213.
- --7812110139 Amend 53 to License DPR-3, changing Tech Spece by reducing neutron detector thimbles required to be operable from 17 to 12 ZIEMANN D. L. Operating Reactore Stench 2 (Pre 790625). 78/11/24. 13pp. 94393;215.
- --7812110143 Safety evaluation supporting Amend 53 to License DPR-3. \* Office of Nuclear Reactor Regulation, Director. 78/11/24. 9pp. 7439:228.
- --7812110145 Notice of Issuance & availability of Amend 53 to License DR-3.

  8/LVER.R.O. Operating Reactors Branch 2 (Pre 790625). 78/11/24.
  2pp. 94093:235.

- Ouring current refueling shutdown ECCS Sys was mod resulting in deletion of number of items from original list. QROCE.R.H. Vankee Atomic Electric Co. 78/11/27. 55pp. 94456:173.
- 7812040234 Responds to 760924 NRC itr request by forwarding Specs 3.4.10 % 4.4 10 to Append A to smend current Oper Lic. Also forwards results of Nov 1978 Eddy Current Inspecs. VANCENBURGH. D. Yankse Atomic Electric Co. 78/11/27. 14pp.
- 7812140040 Finds Yankee Pur Bpike Model(YAEC-1140)acceptable. Forwards aval & suppl.
  REID.R.W. Operating Reactors Branch 4 (Pre 790525). 78/11/27. 2pp
- --7812140042 Safety Eval Rapt for Yankas Pur Spike Model. Finds model acceptable Wencl BER Supplied dtd Aug 1978.

  • Operating Resctors Branch 4 (Pre 790625). 78/11/27. 15pp. 94126: 31 5.
- 7812110004 Discusses possible dangers of LDCA in continuant purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. M/encl ANO: e7812080207.
  ZIEMANN D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Operating Reactors Branch 2 (Pre 790625). 78/11/29. ZIEMANN, D. L. 8pp. 94339: 157.
- 7812080116 Transmits current sched for mach struc work prog for SEP/Asymmetric LOCA loads re sub, facil Activities involve dev of analytic models, seismic assessments & piping ansluses. VANDENBURGH. D. Yankes Atomic Electric Co. 78/12/04. 2pp. 94104: 361.
- 78:2140340 Authorizes refund of \$4.000 Class III amend fee submitted in 781030 ltr. NRC has determined that weiver of fee is appropriat s. DIOOS.R.M. License Fee Management Branch. 78/12/05. 1p. 03557: 164.
- 7812210295 Forwards Amend 64 to License DPR-3. safety evaluation & notice of issuance & availability. 21EMNN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/06. 2pp. 94167:323.
- --7812210301 Amend 54 to License DPR-3, revising Tech Space re facility operation w/refueled Core 14, performance of subsequent steam generator inap IAH Section 3/4.4.10 % inclusion of four containment isolation values in Table 3.6-1.

  INCHANN. D.L. Operating Resolves Brench 2 (Pre 790625). 78/12/06. 11EMANN, D. L. Ope 40pp. 94168: 001.
- --781221030B Safety evaluation supporting Amend 54 to License DPR-3. Office of Nuclear Reactor Regulation, Director, 78/12/06. 14pp. 94168: 004.
- --7812210312 Notice of isauthors & availability of Amend 54 to License ZIEHANN, D. L. Operating Reactors Branch 2 (Pre 790625), 78/12/06. 2pp. 94168:018
- 7819280117 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info aubmitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result.

  DAVIB.J.O. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94310:211.
- 7812150115 Requests addl info from SEP licensees re alec penetrations of reactor containments in order to complete eval.
  21EMANN.O.L. Operating Reactors Branch 2 (Pre 770625). 78/12/08,
  4pp. 94212:149.
- 7812210034 Forwards NUREG-0485, Vol 1. No 2 "Status Summary Rept-Sys Eval Prog. "M/a encl.
  IIEMANN.D. L. Operating Reactors Branch 2 (Prs 790625). 78/12/08.
  2pp. 94267:352.
- 7812140145 Responds to 781026 & 1124 NRC requests for add1 info re Systematic Eval Prog topics Provides info on automatic ECCS realignment, qual of isolation devices, anged safety features k station battery test requirements.

  9ROCE, R. H. Yankee Atomic Electric Co. 78/12/12. 2pp. 94133:342.
- 7812200230 Forwards drawings to several SEP elec topics, as requested in 781026 NRC ltr. Drawings available in Central Files.
  9RDCE.R.H. Yankee Atomic Electric Co. 78/12/13. ip. 94288:359.

plent geotech design

- Q. Inspection reports, 1E Bulletins & correspondence
- 78:0160236 Forwards IE Bullatin 78-12. "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days & list of IE Bulletins issued in 1978 (sas ANDM7810040233) QRIER, B. H. Region 1. Philadalphia, Defice of the Director 78/09/29. 6pp. 94004:331.

LEVIN.H A Systematic Evaluation Programs Granch (Pre 790625) 78/12/13 App 94020 337

- 7812010277 Forwards IE Insp Rept 50-029/78-14 on 780926-28.No noncompliance noted. BRUNNER.E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/10 2pp. 94417 225
- --7812010278 1E inep Rept 50-029/78-14 on 780926-28 No noncompliance noted. Major areas inspected: preparations for refueling. ECCB proceduras & in-office raview of monthly operating rapts. Inspector assisted fire protection survey team. LAZARUS.H.J. Region i, Philadelphia, Defice of the Director 78/10/06. App. 94417:227
- 7811060181 Forwards 1E Circular#78-17 (See AND. 7810230221. Docket #50-133,781013. ) ORIER 8 H. Region i, Philadelphia, Dffice of the Director 78/10/13. ip. 94489:134.
- 7812010108 Forward# IE Insp Rept 50-029/78-15 pn 780925-28 No noncompliance noted. CARLSON.R. T. Region 1. Philedelphia. Reactor Construction & Engineering Support Branch. 78/10/18. 2pp 94418:00l
- --7812010111 1E Inep Rept 50-029/78-15 on 780925-28 No nancompliance noted, Major areas inspected; arrangement of sefety-related aquipment, fire hazards, fire protection equipment & administrative controls.

  PAOLING, R. J. Asgion i. Philadelphia, Office of the Director.

  ESNETER, B. D. Region i. Philadelphia, Resctor Construction &

  Englisering Support Branch. 78/10/17. 4pp. 94418:003
- 7811290151 Forwards 1E Circular #78-18. "UL Fire Test. "W/enc1 ANO: 78:1150002. GRIER, B. H. Region 1, Philadelphia: Office of the Director 78/11/06. 1p. 94239:344.
- 7812010146 Responds to 1E Bulletin 78-12. Requests time extension unt 790131 to provide record exerches requested. ORDCE,R.H. Yankse Atomic Electric Co. 78/11/13. 1p. 94418: 088.
- 78:2:80026 Forwards IE Bulletin878-:2A. Suppl to IE Bulletin 78:12. W/ancl ANO:78::300055. GRIER.8.H. Region I. Philadeiphia, Office of the Director. 78/11/24. 1p. 94:30:335.
- R. Periodic operating reports & related correspondence
- 7810170176 Forwards Monthly Statistical Rapt for Sept 1978
  MDDDY, O.E., Yankas Atomic Electric Co., 78/10/10. ip. 94270: 093
- --7810170178 Monthly Statistical Rapt 78-9 for Sept 1970. BUDGREN.R.M. Yanksa Atomic Electric Co. 78/10/06. Spp. 94270 OR4
- 7811140120 Forwards Monthly Statistical Rept for Oct 1978
  MODDY, D. E. Yankes Atomic Electric Co. 78/11/10, 1p. 94425: 205.
- --7811140122 Monthly Statistical Rept 78-10 for Oct 1978. SJOREN, R. H. Yankaa Atomic Electric Co. 78/11/10.
- 7812150286 Forwards Monthly Statistical Rept for Nov 1978 MODDY, D. E. Yankas Atomic Electric Co. 78/12/11. ip 94409: 185
- --7812150288 Monthly Statistical Rept 78-11 for Nov 1978. SJOOREN, R. M. Yankse Atomic Electric Co. 78/12/11. 94409: 184
- B. Reportable occurrences. LERs & related correspondence
- 7810180008 Forwards LER#78-023/03L-0.
  AUTIO.H.A. Yankes Atomic Electric Co. 78/10/13. ip. 94422:007

- --7810180009 LER 78-023/03L-0 on 780913. during 5-h shutdown dose equivalent i-131 concentration of primary coolant sys exceeded i 0 rC1/g dose equivalent of 1-131 Caused by cladding defect in single fuel rod DDINELL.R L Yantes Atomic Electric Co 78/10/13 4pp. 94422 000
- 7810180015 Forwards LER#78-024/03L-0 AUTIO.H A Yantes Atomic Electric Co 78/10/13 1p 94422 004
- --7810180017 LER#78-024/031-0 on 780913 during unscheduled shutdown steam generator bloudoun chloride concentration exceeded 0 3ppm Caused by phenomenon of hideout of inpurities in steam MAY.E L. Yankee Atomic Electric Co. 78/09/13 2pp. 94422:003
- 7810240152 Forwards LER 78-025/03L-0 AUTID:H A Yankee Atomic Electric Co 78/10/18 tp 07893 047.
- --78:0240154 LERM78-025/03L-0 on 780918 during normal oper source check failed to give proper response while performing surveillance on Mein Coolant Bys Leskage Air Particlete Monitor Caused by end of life of photomultiplier & electron tubes a Yankee Atomic Electric Co 78/10/18 2pp 07893 048
- 7810240156 Forwards LER 78-026/03L-0 AUTID, H. A Yankee Atomic Electric Co 78/10/18 ip 07893.090
- --7810240163 LER 78-026/03L-0 on 780918 while checking primary vent steck monitoring equipment during Mode I operation, plastic container used to collect condensation from primary vant stack monitor air dryer was found leaking. • Yankee Atomic Electric Co. 78/10/18 2pp 07893 051
- 78i1090145 RQ 50-029/78-29, during Mode & refueling shutdown w/#23 guide tube removal being initiated, load increased above normal base load & anticipated guide tube weight abserved Ceused by incorrectly set load cell.

  AUTIO.HA Yankes Atomic Electric Co. 78/i1/06. 2pp. 94042-360.
- 78i1280473 Reportable Occurrence#50-29/78-29 during Mode 6 refueling shutdown, guide tube weight fluctuated 100-300 ibs above base load Caused by manipulator load cell set incorrectly.

  ANTID. H.A. Yanke Atamic Electric Co. 78/11/06. 2pp. 94379:356
- 78iii70200 RO 50-29/78-30 on 78ii09, epprox 100% eddy current exam of steem generators 1 & 4 reveeled that 15 tubes in steem generator 6 12 tubes in steem generator 4 have degraded tubes of more than 40% well thickness.

  AUTIO. H A Yankee Atomic Electric Co 78/11/09. 1p 94136:082.
- 7811170211 RO 50-29/78-31: on 781113, abnormal degradation found in fuel cledding In fallowing through on cause for ROs 77-55, 78-03, 78-19 & 78-23, sipping of spent fuel from Core 8 completed & three suspect fuel essemblies identified AUTIO, H.A. Yankee Atomic Electric Co. 78/11/13 ip. 94136:112.
- 7811300378 Reportable Documence 50-29/78-31 Abnormal degredation discovered in fuel cladding while following through on other reportable accumences. Complete report of follow with 2 wits.

  AUTIO:H A. Yankee Atomic Electric Co. 78/11/13. 1p. 94136-251.
- 7811210317 Forwards LER#78~029/01T-0 AUTIO: H A. Yankee Atomic Electric Co 78/(1/15 ip. 94468:035
- --7811210325 LER 78-027/017-0. on 781101, during refueling white removing guide tubes, en euxiliary set of latches closed on #23 control rod drive sheft Henigulator hendling tool loeds cell controller wes reed justed.

  ARON. R. Yentee Atomic Electric Co. 78/11/15. 20s. 94488-036
- 7811280290 LERM78-027/OOL-0 on 781021: during shutdown, steam generator's chloride concentration exceeded 0.5ppm Caused by steam generator's chem hidsout.

  BDUTHELL,R.L. Yankee Atomic Electric Co 78/11/20. 1p. 94395:235
- 7811280284 Forwards LER 78-027/03L-0 AUTIO.H.A. Yenhee Atomic Electric Co. 78/11/20. ip 94393.234.
- 7811280328 Forwards LER#78-028/03L-0. AUTIO.H. A. Yenkee Atonic Electric Co. 78/11/20. ip. 94395:348.
- --7811280332 LERN78-028/03L-0 on 781021: during test OP-4502, two safety valves, Type HD36 Btgle HC65 & Type BD33 Style HC65 mfg by Crosby Valve & Oage Cl.had low setpoints. Setpoint drift was caused by spring characteristic changes HAY.E L. Yankes Atomic Electric Co. 78/11/20. 2pp. 94395:349.

- 7811280323 LER#78-030/01T-0 on 781109 during eddy current tes tubes in M1 & 12 tubes in M4 steam generators had greater than 40% wall degradation. Degradation of one tube caused by mfg defectiother causes unknown. MAYLE L Yantee Atomic Electric Co 78/11/22 Jpp. 9439
- 78:1280314 Forwards LERW78-030/01T-0.
  AUT10.H A Yankes Atomic Electric Co 78/11/22 1p 943
- 7811290198 Forwards LER#78-031/01T-0 AUT10, H A Yankee Atomic Electric Co 78/11/25. ip 942
- --7811290203 LER#78-031/017-0 on 781111 during Core X117-XIV shutdown Puel sipping revealed degradation of fuel claddi in assemblies#A4926.88026.04906 & B4826.Cause is under investigation by Exzon.
  BOUTHELL.R L. Yankee Atomic Electric Co. 78/11/25 ip 9423-300
- 78:2010224 LERN78-028/03L-1 on 78:1021 during test CP-4502.2 s valves mfg by Crosby Valve & Oage.were found to have setpoints lower than Tech Specs limits Cause is unknown. Valves reset & uill be retested before startup. MAY:EL Yantee Atomic Electric Co. 78/11/27. 2pp.
- DOCKET 50-30 PLUM BRODM RESEARCH REACTOR FACILITY
  P. Operating license stage documents & correspondence
- 7812180435 Submite conformed copies of seismic analysis & con info re subj facil IAW 771107 request. Believes seismic analysis gives essurence that facil can be Oper safely w/in present tech specs.

  DARMITZEL, R W General Electric Co 77/11/29. 42pp. 943
- DOCKET 30-54 UNION CARBIDE REBEARCH REACTOR

  F Security, nedical, emergency & fire protection plans
- 7812270164 Forwards Physical Security Plan changes Revisions from pub disclosure pursuant to 2 790
  PARAD180.J W Union Carbide Corp. 78/12/20 ip 94018.0
- J. Insurance & indomnity information
- 7B12290157 Requests explenation es to why UCC is esked to edd to Indemnity Agreement B-14 re assessment of deferred premiums when it has no relevance to the five megawatt thermal res reector owned by UCC.

  VOTILM H Union Cerbide Corp. 78/12/21. 1p. 94190:291.
- P. Operating license stage documents & correspondence
- 7811160147 Forwards ltrs re eppl of 10CFR73.50 requirements to site whenever total U-235 in unirrediated fuel elements & irrediated & unirrediated target sell secess 5.000 & notes inapplicability to facil.Proprietery info w/held VOTH M H. Union Carbide Corp. 78/11/10. 1p. 94135:263.
- 781219009: Forwards final draft of Yech Specs & recommends so compliance w/new specs. QEOROE, K.D. Union Cerbids Corp. 78/12/15. 2pp. 94341:01
- DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR
  H. General correspondence
- 7810300187 Notifies NRC of respondent's appointment as Acting of Nuc Science & Tech Facil at SUNY/Buffalo, & other appointments.
  CHDN H.Y. New York, State Univ. of, Buffalo 78/07/25.
  94034.003
- P. Operating license stage documents & correspondence
- 7811280092 Reminder that subj facil lic expires on 780915 & 1 requires timely appl. W/encl "Lic Renewal Review Items." REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/11 02726:328.

- O Inspection reports. IE Bulletins & correspondence
- 7810190104 Ack receipt of 780919 itr informing NRC of steps taken to correct violations noted during Inspect50-057/78-04 MARTIN-M.Q. Region I. Philadelphia, Bafeguards Branch 78/09/29 1p 94413.280.
- --7610190107 Forwards 1E Inspec Rept#50-057/78-04 & Notice of Violation. MARTIN. U O Region i, Philadelphia, Bafeguards Branch. 78/08/30 2pp 94413.279
- --7810190116 IE Inspec Rept#50-097/78-0A on 780726-28 during which 2 items of noncompliance were noted. Security Drganization-quarterly audit not performed first quarter 1978. & Surveillance-detes clock checks not conducted by police BALEV,R J. SMITH.R. Region 1. Philadelphia, Bafeguards Branch. 78/08/14 ip. 94413-281.

#### DUCKET 90-59 TEXAB A&M UNIV REBEARCH REACTOR

- 7811020277 Value/Impact Assessment of Ouidance to Applicants relative to Emergency Planning Requirements for Research Reactors Recommends Reg Ouide.

  REID. R. U. Operating Reactors Branch 4 (Pre 790625) 78/10/12 4pp. 94260 272.
- F. Security, medical, emergency & fire protection plans
- 7811030222 Forwards copies of Reg Guide 2 XX and Final draft ANS 15 16 to assist in formulation of emergency plan for subj facil. W/O enci. REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/12 ip 02/24 251.
- 7812220079 Forwards "Emergency Plan for TXAM Univ AGN-201M Reactor." MillER.J Teres A & M Univ. 78/12/18 1p. 94343:300
- --7812220080 "Emergency Plan for TXAM Univ AGN-201M Reactor (Serial 106) as Mod to incl ANBIS 16 & Reg Oulde 2. XX Guidence " Teres A & M Univ. 78/12/12. 24pp 94343.301.
- P. Operating license stage documents & correspondence
- 7811020272 Forwards proposed Reg Quide 2.XX w/ Value/Impact Assessment & Finel draft ANS 15.16 re emergency planning as assistance for rev Memphis Stete Univ Tach Spec rev REIO.R.W Operating Reactors Dranch 4 (Pre 790625). 78/10/12. 1p. 94260:241.
- --7811020274 Proposed NRC Rag Guide 2, XX, "Emergency Planning for Research Reactors". REID.R.W. Operating Reactors Branch 4 (Prø 790629). 78/10/12 44pp. 94260:242.
- --7811020298 Draft "Std for Emergency Planning for Research Reactors."

  Identifies elements & procedures of emergency plan re coping

  W/ emergencies & minimizing consequences of research reactor
  accidents.
  RICHARDS.M. American Nuclear Society 77/12/30 14pp.
  94260.276
- 781215025B Responds to 781012 NRC 1tr & Porwards mods to Tech Specs as rev Append A to lic(R-23)renewal appl of 770531. Tech Specs rev to incl ANSI N378-1974 & Reg Guide 2.2 guidence.
  MILLER, J. E. Texas A & M Univ. 78/12/11. 30pp. 94213.126.

#### G. Inspection reports, IE Bulletine & correspondence

- 7812180421 Forwards Inspec Rept#50-059/78-01 on 781107-08 during which no Items of noncompliance were noted.

  MADSEN.O L. Region 4, Delles, Reactor Operations Nuclear Support Branch. 78/12/01. 2pp. 94398:342.
- --7812180424 Inspect Rept#50-059/78-01 on 781107-08 during which no items of noncomplience were noted Heyor areas inspected incl: implementation of Physical Security Plan relative to SNM protection addess control.alarm sys.locks.keys & hardware. HARD.J.J. EVANS.C.A., MADSEN.G.L. Region 4, Dallas, Resctor Operations Nuclear Support Branch. 78/12/01 ip. 94358:344

- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

  P Operating license stage documents & correspondence
- 7812200222 Requests arend of Tech Spec Sec 4.1 C re visual inspec of boron-stainless steel 4afety rods for LicHR-66 Amend also requested for change in Tech Spec Sec 1 12d for LicHR-66 & Spec 15D for LicHR-123/wording is unnecessarily vegue WILLIAMSON, T. O Virginia, Univ of 70/07/14. 2pp 94162-303.
- 7811010102 Responds to IE Bulletin 78-08 Bulletin does not apply to subj facility as reactor has no such tuber IE Bulletin 78-07, does not apply.

  WILLIAMSON, TO Virginia, Univ. of 78/08/31 ip. 74381-344
- 7811030063 Responds to 770309 appl for renewal of Facil Oper LiceR-UVA Res Reactor Requests add1 into re financial considerations & emergency planning w/in 60 days REID.R.W. Operating Reactors Grench 4 (Pre 790625) 78/10/16 02723 310
- 7811080179 Offers comments on NRC regs for self protecting SNM in r reactor fuel element. Asserts that weakness in spec is that dose rate is not connected w/specific quantity of SNM Supporting documentation from med treatises encl WILLIAMSQN, T.O. Virginia. Univ of 78/10/30 21pp
- 7812200232 Requests emend for Facil Oper Lic\*R-66, to rev sections 3 4 6 of Tech Specs to allow oper of reactor when Emergency Exit Menhale Hatch is closed in order to enhance reactor security WILLIAMSDN.T. Q Virginia, Univ of 78/12/11 2pp 94162: 319.
- 7812200221 Requests approval of amend to Facil Open Lic#R-66 allow
- Univ to receive passess & use Np237. Mat1 will be used for neutron dosimetry in an irradiat test of pressure vasse) steels
  WILLIAMSON, T. Q. Virginia. Univ. of 78/12/18 1p. 94162.302
- 7812260144 Provides info requested in NRC 781016 itr re lic renewel items. Info incl financial & environ considerations. & gen info concerning Univ HILLIAMSON.T.O Virginia. Univ of 78/12/18. 28pp 94161/197
- 7812290007 Forwards Amend#12 to Fec11 Lic#R-66 & Bafety Evel REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/19. 94207:321
- --7812290008 Amend #12 to Facil LickR-66-changing Tech Spec re surveillance of safety rods REID.R.W. Operating Reactors Branch 4 (Pre 790623). 78/12/19 4pp. 94207:323
- --78:2290010 Safety Evel supporting Amend#12 to Facil LickR-66 Concissuence of amend will not be inimical to public or national interests

  \* Office of Nuclear Reactor Regulation. Director 78/12/19, 94207:327.

#### DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- 7809260236 Response to 771219 ltr.Hevakewe to Former Chairman M. Rome NRC ellowing interim open by Gen Elec Go of its GETR facil pending completion of pub hearings. Decision to allow interim open rests with ABLB.

  DIRCKB. W. J. Office of the Executive Director for Openetione.
  78/02/07. 2pp. 01384:088
- · A Application/construction stage documents & correspondence
- 7810230144 Ack receipt of 780818 proposed site fault investigation Expects that NRC sefety eval could be issued by Jen 1979 REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/09/27. 94164:083.
- 7811200089 Responds to 781013 ltr to J Hendrie re subj fecils. Rept eval of both fecils continues & that discharges of trittum have been small fraction of reg limits of 10CFR Part 20. W/out encl NRC eval of site. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 78/11/13. 2pp. 94218:344.

FOX: A Affiliation Unknown. 78/11/06 19. 94252 296.

#### G. Adjudicatory correspondence

- 7810230026 Forwards "Gen Elec Co Establishment of ASLB to Rule on Petitions", to be pub in Fed Register 771116 Hat1 to be charged to requisition #0-149
  CHILK-B J. Office of the Becretary of the Commission 77/11/11.
  19. 94169, 265
- --7810230030 Notice of "Establishment of ABLB to Rule on Petition" to be pub in 771116 Fed Register YCRE-J. R. Atomic Bafety end Licensing Board Penel. 77/10/21. 2pp. 94169:247.
- 7810110268 "Intervenors' Answers to Licenses's Interrogetories dtd 780626" gave reseans why certain info cannot be provided & agrees that nuc reactors should not be located near aerthquake feults. DELLUMB.R.V. House of Rep. 78/09/18 3pp. 94068:001
- 7810110271 "Intervenors' Discovery Status Rept" listing all documents received & sent out since 780816 in QETR Show Couse proceedings
  DELLUMS.R.V. House of Rep. 78/09/22. 3pp. 94068:041.
- 7810300062 Intervenor's Interrogs to the Cen Elec Co re piping in subj facil. Wienci Cort of sec BALDHIN W A. Baldwin W. A. 78/09/25. 3pp. 94034:283.
- 7810190193 Intervenor's Discovery Stetus Rept. Lists what FOE hes received to date
  BALDHIN. A. Friends of the Earth, 78/09/27, 3pp. 94270:017.
- 7810140100 Believes that reopening subj facil would pose a severe threat to his health & sefety. Requests limited eppearance at public hearings.

  TRAMPLEABURE. Affiliation Unknown. 78/09/28. ip. 94002:242.
- 7810120019 Responds to 780929 request for copy of Steff dreft rept on sarthquake potential. W/encl 780817 rept "Show Gauss Proceeding Sefety Evaluation Rept Input, OS Test Reactor Bits //eliscitos Nuc Center".

  18889.5 A. Office of the Executive Legal Director. 78/09/29. 38pp. 94300: 133
- 78:0140:13 Denies request of N Snow, ecting on behalf of intervenor R.
  Dellums that USOS provide estimates of meximum etrong ground
  motion & surfece offset at site of sub; fecil.
  LUTON.E. Atomic Sefety end Licensing Spare Panel. 78/10/02. 2pp.
- 78:01:40:30 8d has yet to receive opinione re subj facil thet were to be transmitted via Congressmen Deliums by the US Attorney General & House Select Committee on Ethics.

  \* Atomic Sefety and Licensing Board Panel. 78/10/03. Ip. 94466: 350.
- 7810130188 Order re intervenore' motion for order suspending preperation of SER pending results of hearing.NRC will show neither the SER nor eny contributing staff member wee bissed by exparts communications
  LUTON.E. Atomic Sefety and Licensing Sourd Penel. 78/10/05. 3pp. 94003.116.
- 78i0300PR3 NRC Steff's Answer to intervenor's Motion for Reference of Questions. Intervenore are Friends of the Earth & Congresseman Ranald Deliuse. NRC Steff opposes their motion dtd 7809;3. Certificate of Svc encl.

  CHANDLER, L. ... Office of the Elecutive Legal Director. 78/10/05. opp. 74034:089.
- 7810230084 Intervenor's Response to Licenses's Cross-Motion for Imposition of Senctions. Licenses had filed request for imposition of Senctions against intervenors for not answering interrogs. Requests GE 780928 motion be denied. BALCHIN, M.A. Frisnds of the Earth. DELLUMB, R.V. House of Rep. 796/10/06, 12pp. 94170:146.
- 7810250009 NRC Staff Response to Licensee's Cross Motion for Imposition of Sanctions, Staff Recommends that in lieu of such action, the 8d direct Intervenors, Congressmen Ronald Dellums & Friends of the Earth, to state their intentions re 8d's order. BHANGON, D. T. Office of the Executive Legal Director. 78/10/10.

- 78:1200044 Responds to 78:013 itr requesting that Test Reactor be shutdown permanently because of tritium separage. Facil is shut down because of potential for surface faulting.not seepaga.uhich is w/in reg limits.H/o Show Cause Order encl. DENTON.H R. Office of Nuclear Reactor Regulation. Director. 78/10/13. 1p. 94215:325.
- 781107036) Requests Gen Elec Nuc Test Reactor remein closed until proper seismic & geological tests are concluded. Also expresses concern over tritium which may be seeping into ground water from facil. Requests info re hearings on facil. DELFIND, J. B. Affiliation Unknown. 78/10/15. ip. 94043:200
- 78:1130246 Intervenor R Dellums'discovery status rept.listing documents received & sent re-proc re-subj facil since 780922. Cert of Bvc encl.

  DELLUMB.R.V. House of Rep. 78/10/23 3pp 94011-279.
- 781102024) Danies licenses GE's cross-motion for imposition of senttions upon intervenors Dellums & Burton for feilure to respond to GE's discovery request. Danies intervenors' request for referral of 780814 ruling to NRC.

  LUTON. & Atomic Sefety and Licensing Board Penel. 78/10/24. 13pp. 94247-090.
- 7Bi1290297 Ack 7Bi003 ltr perticipation as intervenor in QETR Vallecitos Nuc Center proc. States legal counsel approves representation at proc. DELLUMS, R. V. House of Rep. 7B/10/26. 2pp. 94239: 260.
- --7811290304 States informel views re-perticipation as intervenor. Member of Congress are parmitted to furnish representational sector private parties in proc before Fed agency if no compensation is received. M/Cert of Bvc.

  KEUCH, R. L. Justice-Dept. of. Attornsy General's Office. 78/06/R6.
  4pp. 94239:262.
- 7811200064 Btates that since the last status rept.steff has neither received nor issued any new discovery requests re subjecti.

  8MANBON.D.T. Diffice of the Executive Legal Director. 78/11/02. ip. 94215:351.
- 78:1270049 Requests to be informed of ell hearings re subj facil. Absolutely opposes ell fecil oper until completion of adequate seismic studias, pub hearings & consideration of all syldence. QETR & Pu labs must be shut down & lic revoked. LEWIB, A. B. Affiliation Unknown. 78/11/05. ip. 94260:361.
- 781204034B Intervenor's Discovery Status Rept. Lists correspondence eant & received since last Status Rept. BARLOW 9. Friends of the Earth. 78/11/07. 3pp. 94489:308.
- 7812040360 Forwards 780929 memo from ofc of Nuc Resctor Rag to Comm re results of recent fire protec res test by Underwriters lab. W/encl ANO.7810050359.

  BNANBON,D.T. Dffice of the Executive Legal Director. 78/11/07. 1488. 94127:149.
- 78ii2i0451 Licenese GEVN's discovery status rept.interroge were submitted by Rep R Dellume on 780808 b 7808i8: licenese responded on 780821 b 780830 respectively. Cert of svc encl. EDGAR. G. L. Horgen, Lewis & Bockius. 78/11/08. 8pp. 94480:344.
- 7811300393 Requests that subj facil be kept closed because of the unepeakable threst its operation would pose for the pub. HAWK C. Affiliation Unknown. 78/11/10. 1p. 94136:300.
- 7812010323 Strongly supports keeping subg facil closed, Believes it is an unspeakably great denger to present & future generations. HAWK.C. Affiliation Unknown. 78/11/10, ip. 94417:324.
- 7811220133 Orente Intervenore' 780818 motion for order compelling responses to their 780803 interrogs by licanese Gen Elec. Denies licenses's cross-motion for protective order re this discovery.

  LUTON-E. Atomic Befety and Licensing Board Panel. 78/11/13. 1p. 94074:259.
- 781;220:37 Denies Motion of intervenore Deliume; J Surton & P Surton for licenses Den Elec to make photographs in verification of grimary & escondary cooling pipe & support locations. GEVN Motion for protective order is grented.

  LUTON, E. Atomic Sefety and Licensing Roard Penel. 78/11/13. ip. 94074:253.

Friends of the Earth. 78/11/13 Epp. 44203 230

tes apposition to subj facil Requests order halting tritium into groundwater. Affiliation Unknown 78/11/15. 1p 94306/323.

ervenors Response to NABLB Memorandum & Order dtd 781024. rePuse to reveal names of any persons Aiding unless intervenors intend to call these persons . Cert of Bvc encl. House of Rep. 78/11/15 2pp. 94278:272.

ensee GEVN's Response to ASLB Memorandum & Order of ting intervenors Friends of the Earth & Dellums o GEVN interrogs Responsee are nonresponsive. s imposing of earctions Cert of Svc ahol. Morgan. Lewis & Backius. 78/11/17. 3pp. 94071-304.

usets subj facil remain closed until it can be shown that h & sefety are completely assured. #fillation Uninown. 78/11/20 1p. 94306:327.

tervenore' Response to Discovery Requests." Intervenore, he Earth, do not believe production of Btolzman in response to any discovery requests preliminary rept. Cart of Svc encl.
Friends of the Earth 78/11/27, 6PP, 94407: 311.

Staff's Answer to intervenore FOIE's & R Dellums'request 'refusal to enswer itensee OENN's interroge be Comm Staff urgae that request be denied & that ad from discovery. W/Cart of Svc. Office of the Executive Lagai Director. 78/11/29 310.

gness QE's Answers to intervenor R Dellum's interrogetions concern feel flooding sys-containment upon relief sys & other topics re wafety of subjusts & Cent of Svc encl., OILLILAND, D. L., DARMITZEL, D H. General Electric Co. pp. 94347:334.

recte error in "NRC Btaff answer to Intervenors' Request & Licensee's Motion for imposition of dtd 781129. (In p2 "dented" should read "granted." to Licensee's request to impose senctions.

Diffice of the Executive Legal Director 78/12/05 ip.

#### respondence

usets appearance at all showcause hearings re subj psymment & complete closing of subj facil due ion on a capable fault on Unknown. 78/09/10. ip. 94088:203.

oses restart of subj facil. Affiliation Unknown. 78/09/30. ip. 94412:925.

resses concern re permanent & complete closing of subj ted weete & earthquaste hazards. Requeste notice te of any NRC hearing related to the status of

Filiation Uninown. 78/11/04 2pp. 94273:299.

ponds to 781015 itr opposing respening of subj facil. lic process Recipient is incl in Svc list of sive notice ofhearings on subj (See: ANC

Office of Nuclear Reactor Regulation, Director, pp. 94449:196.

ponds to 781020 referral ltr re 781019 ltr of H Wolch by Lafety-related design repts explaining safety if 21 reactors w/GE Hark I containment H/encl tr to Wolth & congressional correspondence. Office of the Executive Director for Operations. 13pp. 03588-090.

Irges subj fecil ehutdoun decision by made permanent by NRC. nfo re etatus of 150kg of plutonium stored at subj

Affiliation Unknown, 78/10/15. ip. 03558:108.

- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 78ii010220 Comments on 780824 meeting at facility Believes that if Verona Fault exists no threat to facility exists Strong earthquake is possible PAGE-B.M. Stanford Univ. 78/08/25 ip. 94392:021.
- 78:1020313 Calleves no finel conclusions run be drawn from 780824 meeting at subj facil re aglemic studies of subj site THOMPSON C. A Stanford Univ. 78/08/25. ip 94256:025
- P. Operating license stage documents & correspondence
- 7812180404 Forwards form reply sent in response to pub inquiries repending lic renswal apple. Forwards mailing list for notices to be issued on renewal apple.

  BURGER.A. Operating Reactors Branch 1 (Pre 790625) 77/05/06. 4pp. 94337.087.
- 7812180408 Forwards draft ltr outlining NRC review process as background info for QETR review Requests comments HANCHETT.J.Q Region 3, San Francisco, Office of the Director. 77/05/06. App 94337:101.
- 7812150069 Requests submitted of addl site-related info w/in 30 days. 8CHWENCER.A. Operating Resttors Branch i (Pre 790625). 77/05/20 2pp 94210:190
- 7812180355 Reports on briefing by D Hard re detailed field mapping that has identified a number of faults w/relatively young gablogical movement near subj facil.

  8TEPP.J.C. Gaosciences Branch. 77/09/12 2pp. 94356.073
- 7812180357 Summerizes 770803 meeting re discussion of seienic resval of subj facil. Concluded that addi info re site seismic & gaologic info is needed from Gen Elec BURGER. A. Operating Reactors Brench i (Pre 790625). 77/09/15 4pp. 94356:075
- 7812180414 Summerizes 770831 briefing on Gen Elec's Phase I Osological investigation which presented a new map of Livermore Valley & interpreted the geology & selemology of eres around Oreanville & Lee Posites Faults. BURGER: A Operating Reactore Branch i (Pre 790625). 77/09/15. 4pp. 94357:148.
- 7812180411 Discusses rereview re ability to cool core assuming cooling water absence of Full estemic design capability. Socials of various assumptions, steff must have reasonable assumance of items withstanding salemic forces.

  8CHNENCER. A. Operating Resctors Branch 4 (Pre 790625). 77/10/04 iipp. 94357:112.
- 7812210127 Requests that Ocology & Beismology Branch provide tech assistance to Div of Operating Reactors in the goology & esiamology review of the subj facil as discussed in enclosed TAC#7062 U/o encl.
  BTELLO.V. Division of Operating Reactors. 77/10/04. Ip. 94267.318.
- 7612200053 "Review of Severe Weather Meteorology at Gen Elec Co Veilecttoe, CA." Provides calculations & info for determining characteristics of design-basis storm. FUJITA.T.T. Argonna National Laboratory. 77/05/31. 25pp. 74159:083.
- 7812190225 Summerizee 771024 conversation w/GE & consultants to determine CE's plans for further investigations of faulting man Vallection facil & status of investigations.

  BTEPP.J. C. Qeosciences Branch 77/10/25. 2pp. 94381: 250.
- 7810130107 Notice of meeting w/GE on 771029 to provide into to justify resuming oper of GETR.

  OULLER.K.R. Division of Operating Reactors. 77/10/27. ip. 94003;167.

Ţ

1

7812180330 Forwards rept on status of assessment of geology & spismology at OETR site, dtd 771025.

OAMMILL. W. P. Assistant Director for Bite Technology. 77/10/28.

App. 94357:338

- 7812190231 Discusses status of trench closing at Vellecitos & eramination of trenches by NRC & other agencies. Recommends that 0E be allowed to backfill trenches 1.2 & 3 & the large bareholes now dug. w/encl comments for 771202 GEIR meeting DENTON.H R. Dffice of Nuclear Reactor Regulation. Director. 77711/30 5pp 94381.265.
- 7812210331 Forwards info re facil fuel element decay heat as of 771130 HOOGATT.O.D General Electric Co 77/12/07. 7pp. 94014.279
- 7810260037 Forwards for review "Beismic & Dasis for Struc Analysis of Reactor Bldg by EDAC" dtd 771216 for review Encl already on file in PDR & Central Files
  BAGCHI-Q Engineering Branch (Pre 791030). AT-42-24-0116
  77712/23 3pp. 01791 037.
- 7809270023 Outlines proposed action plan on Gen Elec's 771216 response to NRC's 771024 Order to Show Causa. SCHWENCER.A Operating Reactors Brench 1 (Pre 790625) 78/01/05.
- 7912180428 identifies sys which are req to assure adequate core cooling. & epecifies operability conditions that must be met by each sys.

  BAER.R.L. Reactor Bafety Branch (Pre 791030). 78/01/09. 3pp. 94358:029.
- 7812180431 Provides results of 771216 site visit to observe topography & geology exposed in trenches Further study is needed to determine certain absence of feulting et site. KURKJIAN, T. G. Interior, Dept of, Occiogical Survey. 78/01/30. 2pp 94364-252.
- 7812100429 Forwards 780201 USOB review of potential faulting at subj site Feels staff should not take firm position until after its review. W/encl AND 7809200047 QAMMILL. H. P. Assistant Director for Site Technology. 78/02/03 2pp. 94358:020
- 7812190198 Summary of 780125 meeting to discuss effect of possible earthquekes generated by Calvarnas & Verona faults at site.

  JACKSON R. E Division of Site Safety & Environmental Analysis.
  78/02/03 ip 94076-112
- 7812180401 Forwards info on all GETR scrams which have occurred since plant was initially started in 1938 DARMHITGEL, R. W. General Electric Co. 78/02/14. 2pp.
- 7810110200 Responds to 780911 request for info on status of OEIR. OE is conducting a fault investigation.will take 2 months before NRC can produce safety evaluation & another month before show cause issues go before ASLB DIRCKS.H.J. Office of the Executive Director for Operations. 78/10/04. 3pp 94069:001.
- --7810110203 In 780209 ltr.author was informed that US Geological Survey & an independent consulting firm were advising NRC on matters re subj facil geology & selsmology. Requests a rept on status of proceedings.
  TOWER, J. Senate. 78/09/11. 2pp. 94069:004.
- --78:01:0205 Expresses concern about OETR shutdown besuse it may disrupt the supply of radioisotopes, some of which are only meds cornercially at the subplecti, Requests restart oper to begin as soon as possibls. TOWER, J. Benate. 77/12/20 2pp. 94069:006.
- --7810:10207 In response to 771220 ltr. forwards info on status & Issues relevant to subj facil, Pub hearings are being held & the ARLB will make the final decision re-restart.

  DIRCKS.W J. Office of the Executive Director for Operations. 78/02/09. 2pp. 9405:00B.
- 7810110165 Responds to 780406 request for add1 info re resumption of open of GETR.

  DARMITZEL.R. M. General Electric Co. 78/10/06 39pp 94069:279.
- 7810270110 Requests that subj facils rameln closed, inesmuch as Celsvers fault is only a few hundred feet from plant.
  F18CHER. B. Affiliation Unknown. 78/10/08. ip. 94059:302.
- 781024020A Notification of 781013 meeting in Pleasanton, CA to inspect trenches completed in site fault investigation. NELBON-C. C. Operating Reactors Branch 4 (Pre 790625). 78/10/10.
- 7811020033 Opposes reopening of subj facil because it is built on a gaologically unstable site. VANTHICH, M. Affiliation Uninoum 78/10/20. 19. 94355:198.

- 7811080039 Requests rept of attached 781018 constituent ltr re attempts by Hendris of NRC to suppress potential damaging into re nuc pur safety as reported by Union of Concerned Scientists HAYAKAVA, 8 I Senate 78/10/20 Ip. 94398-113
- --7811080056 Contends NRC shut-down order for Gen Elec Test Reactor be made permanent since safety against merimum selemic activity can not be guarantsed Also requests discharges of trittum cease & info on hearings be provided MUCH, H. Apriliation Unknown. 78/10/15. 1p. 94398-115.
- 7811070331 Responds to 781006 ltr to J Schlesinger re facil in Livernore Valley Region DOE is collecting the requested infore LLL Questions re Vallecitos facil are being forwarded to NRC.

  BRATTON, J. K. Defense, Dept. of. 78/10/24. 1p. 94043.179.
- --7811070355 Requests info on seismic & geologic testing in the Liverage Valley Region & what effect faulting in the area has had on the Vallecitos Atomic Leb & Livermore Leb. Questions whether facil siting meets UBOS & NRC criteria. RYAN.L J House of Rep. 78/10/05 ip. 94043 178.
- 7812190169 Notification of 771028 meeting in Bathesda w/OE to allow 9E to give NRC its assessment of all NRC-lic activities at Vallecites as req by 771024 Show Causs Order.
  OALLER.K R Division of Operating Reactors. 77/10/26. 1p. 94381:161
- 7811030259 Rept on 781017 site visit to make preliminary observations of Oen Elec-proposed site investigation. Believes that until main scarp & assoc rupture surface are located for mapped landslide complex the stability ensigns is questionable. GREEVES, J. T. JACKSON, R. E. Oeosciences Branch. 78/10/27. 7pp. 94272:059.
- 78i1070i13 Responds to 78i002 NRC request for addl info re appl for addition to Tech Specs.Forwards clarification of term "Cold Shutdown".
  CUNNINOHAM, 0 E. General Electric Co. 78/1i/Oi. 4pp. 94043:301.
- 7812190178 Requests DOR provide proposed Fed Register Notice repting shutdown of QCIT as abnormal occurrence. Wenci copy of previous FRN for Abnormal Occurrence for info.
- enutous of very as apporant occurrence for the copy of previous FRN for Abnormal Occurrence for the CEIBENHUT.D.Q. Division of Operating Reactors. 77/11/10. App. 94381:108.
- 7811270169 Forwards comments from 781017 site visit to view trenching excavations of current GETR seismic investigation. For and see ANO 7811030259.

  REID.R. W Operating Reactors Branch 4 (Pre 7906251. 78/11/11. 4pp. 94272:055.
- 7812180293 Notice of 781209 visit to facil in order to inspect tranches completed in the QETR site fault investigation.
  NELBON.C.C. Operating Reactors Branch 4 (Pre 790625). 78/11/27.
  3pp. 94265:219.
- 7812080131 Forwards info considered reportable under Section D2 of Lic TR-1. During 781101 Calibr of primary coolant ecrem & emergency cooling trip instru, trip points indicated switches out of epsc.

  DARNITZEL.R.W. General Electric Co. 78/11/29. 2pp. 94106:351.
- 7812140121 Forwards logs of the tranches at & near subj facil.Logs svaliable in Central Files. DARMITZEL, R.W. General Electric Co. 78/11/29. 150pp. 94480:001.
- 7812180329 Forusrds status rept of DBE review of geology as it relates to potential for surface faulting of GETR sits. Deta is incomplete & does not allow finel conclusions. Encl request for addl info.

  DENIBN.H.R. Division of Site Safety & Environmental Analysis.
  78/12/13. 9p. 94337:329.
- 7812190020 Forwards NRC Order to Show Cause, which req that Gen Elec Test Reactor be placed & maintained sefely in cold shutdown condition pending further order. GASE-E. O Office of Nuclear Reactor Regulation, Director.
- 7812280297 Forwards rept re 781205-6 subj facil site visit re tranches & selamic snelysis. REID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/12/18. 2pp. 74349:348.

- 7810230070 Forwards IE Inspec Rept#50-70/78-07 on 780907-08 during which np itsms of noncompliance wars noted. CREWS.J.L. Region 5. Ban Francisco. Reactor Operations Nuclear Busport Branch. 78/09/20. 2pp. 94169:181.
- --7810230092 IE Inspec ReptH50-70/78-07 on 780907-08 during which no items of noncompliance were noted. Major areas inspected included: logs & recorderryview & audit: experiments: LER followin: & independent inspec efforts.

  CANTER-H. L., HILLER, L. E., CREWS, J. L. Region 5, Ben Francisco, Resctor Operations Nuclear Support Brench. 78/09/20. 400. 0449-187.
- 7811270121 Forwards IE Inspec Rept#50-70/78-08 on 780926-28 during which no items of noncompliance were noted.

  BPENCER, Q. B. Region 5. Ben Francisco. Reector Construction & Engineering Support Brench. 78/10/19. 2pp. 94271:272.
- --7811270126 IE inepec Rept#50-70/78-08 on 780926-28 during which no items of noncompliance were noted Major eress inepsc incl: mass of primary heet exchanger, esiamic restreints, QA records & followup on previous inspec items.

  BISHOP, Y. M., HAIST, D. P., HAYNEB, R. C. Region 5. San Frencisco, Resctor Construction & Engineering Support Drench 78/10/18 Spp 94271; 274.
- 7812140070 Forwards 1E Inspec Rept#50-070/78-09 on 781004-05 during which no items of noncompliance were noted.
  800K-H.E. Region 5. Ban Francisco. Fuel Facility & Materials Bafety Branch. 78/10/31. 2pp. 94127:356.
- --7812140072 iE Inspec Rept#80-070/78-09 on 781004-08 during which no items of noncompliancs were noted Major areas inspected: ratiet asfety organization changes in rediat safety procedures personnel exposures survey instru & tour of fecil. FiBM.R.F., RIEDLINGER, B.A., BOOK.H.E. Region 5. Ben Frencisco, Fuel Fecility & Materials Bafety Branch. 78/10/27. App. 94107-138
- U. Congressions1/Executive Correspondence
- 7811210065 Responds to 781006 itr to Dept of Energy re present status of only facile. Based on selemology & site geology evaluation continued NTR oper & activities authorized by LickWhM-960 were found to be acceptable.

  DIRCKB.H.J. Office of the Executive Director for Operations.
  78/11/13. 3pp. 94488:319.
- --7813210096 Responds to 781006 htm to Mr Schlesinger re siting of subj facils. Requested info is being collected & will be sent se soon as dete is available. Copy of 781006 ltm has been forwarded to the NRC. BRATTON. J. M. Energy, Dept. of. 78/10/18. ip. 94488; 323.
- 78:1240091 Responds to 78:1017 itr by forwarding a copy of NRC's reply to Mrs DelFino's 78:1015 ltr to Chairman Hendrie.
  DIRCMS-W.J. Office of the Executive Director for Operations.
  78/11/15. 1p. 94468:077.
- --7811940094 Forwards 781015 DelFino ltr to NRC & requests e complete report in duplicate re sub; facil hazards to safety & health Requests to be informed of ell related hearings. HAYAKAHA, B. I. Senate, 78/10/17. ip. 94458:081.
- --7811240096 Recommends that both subj facils remain closed until further into the health & safety(especially the discharge of tritium into the groundwater)& geotech data is made available to the pub.

  DELFING. J. B. Affiliation Unknown. 78/10/15. 2pp. 94458:083

DOCKET BO-72 UNIV. OF UTAN RESEARCH REACTOR
P. Operating license stage documents & correspondence

7810240006 Reply to 780725 ltr re Memphis State Univ Tech Spec re ANS 15.18 Admin controls. RSID.R.W. Operating Reactors Branch 4 (Pre 770625). 78/10/10. 4pp. P Operating license stage documents & correspondence

7811210002 Reminder that LiceR-33 for subj facil will expire on 790721. & remewal appling timely filing Consideration will be revelued as port of evaluation. W/encl Lic Renewal Review Itams. REID R.W. Operating Reactors Branch 4 (Pre 790623). 78/11/06. 7pp. 94622:001.

- 7812270401 Forwards Amend#13 to LickR-33 & Safety Eval.Changing Specs in response to 760811 request REID.R.W. Dperating Reactors Branch 4 (Pre 790625) 78/12/14 2pp 9422:321.
- --7812270409 Amend Hi3 to Lic HR-33. Chenging 1sch Apec re-cellbr survelllance of all instru & deleting Tech Apec requirement for respiratory protec. Updates NRC organizational titles. REID.R.M. Operating Reactore Branch 4 (Pre 790623). 78/12/14 Spp. 94232:323.
- --7812270416 Batsty Eval supporting Amend #13 to Lic#R-33 Concludes amend will not be inimical to common defense & security or to pub health & sefety.

  \*\*\* Office of Nuclear Resctor Regulation, Director. 78/12/14. 3pp. 94232:328.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA REBEARCH REACTOR
P. Operating license stegs documents & correspondence

7810170185 In response to 780927 NRC ltr.Dreft tech space for AGN-201 resetor have been reviewed & ere acceptable JORDANLE.D. Cetholic Univ. 78/10/10. ip. 94270 046

DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

F. Security, medical, emergency & fire protection plans

- 7811070376 Accepts Arognaut rep reactor security plan & rev Requeste that the besic plan & revisions be consolidated into one document for inclusion in the renewal lic.
  REID.R.H. Operating Resctors Branch 4 (Pre 770625). 78/10/12. Ip 94043:282.
- P. Operating literes stage documents & correspondence
- 7810180081 Describes preparation of info for renewal of Facil Oper Lic #R-36. New BAR & Tech Spac are being prepared re change of fuel. Final submission to NRC will be in June: 1977.
  DIAZ.N.J. Floride, Univ. of, Gainseville. 78/10/10. Spp. 94412: 292.
- 78:2060149 Informs NRC effective 780901 MJ Chemien returned to UF Chairmenship of Dept of Nuc Engr Sciences.

  OHANIAN.M.J. Florids, Univ. of, Geinesville. 78/11/30. 1p.
- G. Inspection reports. IE Bulletine & correspondence
- 78:01:01:07 Ack receipt of 7809:5 ltr informing NRC of steps taken to correct violations noted during inspect50-083/78-05.
  KENNA, M. B. Region Q. Atlenta, Bafeguards Branth. 78/10/02. ip. 03:55:244.
- --78101(0194 Responds to Notice of Violation from 780814 Physical Bacurity Inspec which found that a reactor key was inserted w/o operator present Daily checkout & reactor shutdown procedures will be corrected. DIALIN.J., OHANIAN.H.J. Florida, Univ. of, Geinseville, 78/09/15. 2pp. 94089:133.
- --7B1011019B Forwards IE Inspec Rept#50-083/78-05 & Notice of Violation. KENNA, M. B. Region 3, Chicago, Sefeguards Brench. 78/09/07. Epp. 94069:135.
- --7B10110R01 Notice of Violation from inspec on 7B0817.

  \* Region 3. Chicego. Safeguerde Branch. 78/08/17. 1p.
- --7810110204 IE Inspec Rept#50-083/78-05 on 780817 during which 1 item of noncompliance was noted.

  \*\*Region 3, Chicago: Befeguards Branch: 78/08/17. 4pp. 9408/138.

- DOCKET 30-87 WESTINGHOUSE CRITICAL EXPERIMENT

  F. Security, medical, emergency & fire protection plans
- 7810230141 Act receipt of 770919 & 771229 changes to Security Plan. Finds changes acceptable & containing proprietary Info. REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/09/29 ip. 94164-085.
- G Inspection reports, ig Builetine & correspondence
- 7810190248 Responds to request for reply to 1E Dulletin#78-08. Bulletin is not applicable to subj facil & none of actions suggested were instituted.

  ROTH J.M. Westinghouse Ejectric Corp. 78/10/05. ip. 94413:342.
- 78:1090043 Forwards IE inspec Rept#50-087/78-06 on 780920-22 Inspec rept details w/held from pub disclosure pursuant to 2.790 HiND, J.A. Region 3, Chicago, Office of the Director. 78/10/31. 2pp. 94040 062
- --7Bi1090044 IE Insper Rapt#30-087/78-06 on 7B0920-22 during which no items of noncompliance were noted. Areas inspected included. security plan to organization; access controlialarm tys: surveillance; radiological sabotage protec. CHRISTOFFER. G. M. MADEDA. T. J., MIND. J. A. Region 3, Chicago, Office of the Director, 78/10/30 p. 94040.064

DOCKET 50-B9 GENERAL ATOMIC CO.

- F. Security, medical. emergency & fire protection plane
- 7812190145 Forwards current physical security plan in compliance U/regs.classified as "Nati Sacurity Info" pursuant to certain DOE requirements. Requests that earlier copies be destroyed, and new copies be withheld.

  MONRY.M.R. General Atomic Co. (subs. of Quif Dil Co.). 78/12/15.
  19. 94340-070.
- P. Operating items9 stage documents & correspondence
- 7812040243 Forwards Fed Register Notice containing Oan Atomic Co applior facil export lic.

  DPLINOER.O.O. Optice of International Programs, Director. 78/11/17
  10. 94413:334.
- --7812040249 Qen Atomic Co Appl for Facii Export Lic to auth export TRIGA Mark i ree reactor u/thermei pur level of 100 Kilowatte to Morocco.

  DPLINGR.0 9 0ffice of international Programs. Director. 78/11/17. 2pp. 94413:335.
- V Operator Examinations
- 7810300284 Finds proposed changes to reactor open requal prog acceptable. Changes do not substantially decrease the frequency, duration, or scope of the prog. COLLINS.P.F. Operator Licensing Branch, 78/10/25, 1p. 94185:308.

DOCKET 50-94 ROCKHELL INTERNATIONAL REBEARCH REACTOR

- J. Insurance & indemnity information
- 7810270197 Forwards copies of Policy NF-12: Endorsements#75-83, 85-89 & 94(Advanced Premium & Standard & Reserve Premium for CY1978) & Policy NF-93 Endorsements 75-79 and 83(Advanced Premium, Standard & Reserve Premium for CY1978.
  PIERCE-J. W. Rockweil International Corp. 78/10/19. 30pp 94094:043

DDCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR
F. Sacurity, medical, emergency & fire protection plane

7810260021 Forwards NRC Reg Ouide 2.XX "Emergency Planning for Res Restors". Request these documents be used in preparing emergency plan in appl for lic renewal. REID.R.W. Operating Resctors Branch 4 (Pre 790625). 78/10/17. 49pp. 94372:160.

- G Adjudicatory correspondence
- 7812210517 Petition by NY St Energy Office for leave to participate as an interested state in proc re Cornell Univ Zero Pur Reactor St is acting to protec health-safety & environ of NY citiens Cert of Svc enc!
  8HAPIROL N
- P Operating license stage documents & correspondence
- 7810120038 Requests 20 year renewal of LickR-89. Complete appl will be forwarded at a later date.

  COOME.W D. Cornell Univ. 78/10/06. ip 94332:314.
- 7812140065 Forwards Notice of Proposed Renewal of Facil Lic.Prasent lic expires 781221. REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/27, 2pp. 94126:337
- --7812140069 Notice of Proposed Renewal of Facil Lic#R-89 until 981121. REID.R.W Operating Reactors Branch 4 (Pre 790623). 78/10/28. 4pp. 94126-339.
- G. Inspection reports, IS Bullstins & correspondence
- 7812050286 Ack receipt of 781030 ltr informing NRC of steps taken to correct violations noted during inapac#30-97/78-02, #50-157/78-02 & #70-211/78-01.

  MARTIN.H.Q. Region 1, Philadalphia, Safeguarda Branch. 78/11/07 is. 94202-321
- --7812050290 Responds to 781004 NRC ltr re deviation noted in Inspec Rep #50-97/78-02.#50-157/78-02 & #70-211/78-01 Corrective actions: complete physical inventory & documentation finished 781023. CLARK.D.D. Cornell Univ 78/10/30. Ip. 94202 322.
- --7812050295 Forwards IE Inspec Repts#50-97/78-02, #50-157/78-01 & Notice of Violation.

  MARTIN.W.Q. Region I. Philadelphia: Bafeguards Branch 78/10/04
  2pp. 44202:323.
- --7812030298 Notice of Violation from inspec on 780907-08

  \* Region i. Philadeiphia. Bafeguards Branch. 78/i0/04. ip.
  94202:325.
- --7812050304 IE Inspec RepteM50-97/78-02, #50-157/78-02, #70-211/78-01 on 780907-08 during which i item of noncompilance was noted: failure to perform complete physical inventory w/in required iz months.

  8tMMERB, R. J. Region i, Philadelphia, Befeguards Branch. 78/10/04. 6pp. 74202.326
- --7812050304 iE inspec Repts#50-97/78-02.#50-157/78-02.#70-211/78-01 on 780907-08 during which I item of noncompliance was noted: failure to perform complate physical inventory w/in required 12 months.

  BUMMERS.R.J. Region I. Philadelphia. Bafeguards Brench 78/10/04.

DOCKET 50-98 UNIV. OF DELAWARE RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 7810230145 On 780826.DELU removed all components of its AON-201 nuc reactor. Surveys of reactor room & reactor components show no removable containination levels in excess of background. DELU requests fine1 inspec per termination of fecil.
  RUSSELL-T-M. Delaware, Univ. of 78/10/12. 3pp. 94164:200.

OCCKET 50-99 BABCOCK & WILCOX TEST REACTOR

F. Swcurity, medical, emergency & fire protection plans

7810230147 States that NRC raview of physical security plan & revs is complete. Finds plan acceptable. Requests that vendor resubmit plan as single document for inclusion into lic by 790531 in loose-leaf format.

REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/06, 2pp. 94194:343.

#### O. Inspection reports. IE Bulletins & correspondence

- 7812080215 Forwards Inspec Rept#50-099/78-03 & Inspec Rept#50-013/78-03 on 780918-22 during which no items of noncompliance were noted.

  SUT-ERLAND. J. T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch, 78/10/30 2pp. 94137.074.
- --7812080219 IE Inspec Rept#50-099/78-03 & IE Inspec Rept #30-013/78-03 on 780918-22 during which no items of noncompliance were noted. Major areas inspec incl radiat protec procedures & posting & labeling DAVIS.J.H Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/10/30 7pp.
- 7812200156 Concurs that inspec rapt contains no proprietary info & agrees to placing it in NRC PDR.
  ENGELDER-T.C. Babcock & Wilcox Co. 78/12/08 Ip. 94156:354.
- 7810270103 Forwards IE Inspac RepteM50-99/77-4 & M50-13/77-4 on 771129-771201 during which no items of noncompliance were noted. MENNA, M.B. Region 2. Atlanta. Safeguards Branch. 77/12/27. 2pp. 94099: 297.
- --7810270113 IE inspec Repts#50-13/77-4 & #50-99/77-4 on 771129-771201 furing which no items of noncompliance were noted Major area inspected included physical security prog. Security plan. Security organization. Survaillance, Access controls. JOYNER, J. H. Region 2, Atlanta, Office of the Director. 77/12/22. 15. 94059 288
- 7812050001 Forwards IE Inspac Repts#50-99/78-2.#50-13/78-2 & #70-824/78-10 on 780911-15 & Notice of Violation.

  8UTHERLAND.J.T. Region 2. Atlanta, fuel Facility & Materials Safety Branch. 78/10/27. 2pp 94200:001.
- --7812050002 Notice of Violation from inep on 780911-15.
  4 Region 2, Atlanta, Fuel Facility & Materials Bafaty Branch.
  78/10/27. 1p. 94200:003.
- --7812030005 IE Inspec Rapts M30-99/78-2, M30-13/78-2 & M70-824/78-10 on 780911-15 during which i item of noncompliance was noted: storage of flarmable liquids in containers that are not eafety approved cans.
  PERROTTI, D. J. Ragion 2, Atlanta, Office of the Director. 76/10/27. 17pp. 94200:004.
- 7812200158 Forwards Inspec Repts#50-13/78-4 & #50-99/78-4 on 781115-17 during which no litms of noncompliance were noted LCNO.F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/12/01. 2pp. 94156:355.
- ~-7812200161 IE Inspec Repts #50-013/78-04 & #50-099/78-04 on 761115-17 during which no items of noncompliance were noted Hajor areas inspected incl. loge & records reviews & audite; esperiments refusling procedures & IE Circular review HINCKLEY, D. Q., MCHENRY, T. J., DANCE, H. C. Region Q. Atlanta, Office of the Diractor. 78/12/08. Spp. 94136:357.

#### DOCKET 50-106 DREGON STATE UNIV.

- A. Application/construction stage documents & correspondence
- 7811200009 Forwards FR notice of proposed issuence of orders authorizing dismantling of facil disposition of component parts & termination of facil lic.per 780913 appl. (w/encl ANGW7811150247.)
  REID.R.W. Operating Reactors Branch 4 (Pre 790628). 78/10/31. 1p. 94218:286.
- a. Operating license stage documents & correspondence
- 7812270193 Forwards Diemantling & Disposal Plan For AGN-201 training reactor oper under LicMR-51. Reactor is to be transferred to Northwestern Univ. WAND C. H. PDPGVICH, M. Oregon State Univ. 78/12/18. 2pp. 74018:059.

- G. Inspection reports. IE Bullatins & correspondence
- 7812070041 Forwards Inspec Rept#30-106/78-02 on 781024-26 during wh no items of noncompliance were noted CREMB.J L. Region 5. San Francisco. Reactor Operations Nuclear Busport Branch. 78/10/31. 2pp. 94134.069
- --7812070043 IE Inspec Regt#30-106/78-02 on 781024-26 during which restants of noncompliance were noted Major areas inspec incl: operation.logs & records, procedures, training & survefilance. MORRILL, P. J., CARLSON, J. D., STERNBERG, D. M. Region 5. Sen Francisco, Reactor Operations Nuclear Support Branch. 78/10/31 22p. 94134-071.
- 7811150247 Notice of proposed issuance of orders authorizing dismentling of facil at Oragon St Univ.disposition of component part of facil & termination of facil LickR-51. REID.R.M. Operating Reactors Branch 4 (Pre 790625) 78/10/31. 94273:064.
- DOCKET 50-112 UNIV. OF OKLAHDHA RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- 7810110167 Requests 20-year extension/renewal of NRC Lic#R-53. Wiil furnish documentation by mid-Nov 1978. UPTHEGROVE, W.R. Oblahome, Univ. of. 78/10/06 ip 94069 090.
- 7810310297 Responds to itr re renewal of A0N-231 Lic 6R-53.Forwards new guidalines re emergancy planning for res reactors day since 780528 NRC itr whenci dreft Reg Guida 2 XX & ANS Draft Standard for Emergancy Planning for Res Reactors. REID R.H. Operating Reactors Branch 4 (Pre 790625) 78/10/06. 479pp 94089.005.
- 7811210212 Notice of proposed renewal of Facil LicHR-53 for operation AON-211 Reactor located at UDK Renewal would extend expiration data to 981299 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/02 94407:142.
- 7811290310 Forwards "Notice of Proposed Renewal of Facil LiceR-53 P AON-211 Reactor". Although expiration date for lic is 781229, existing lic will not be considered expirad until appl has been finally determined. REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/11/02. 94193: 247.
- --7811290315 "Notice of Proposed Renewal of Fecil Lic" for Lic#R-53 oper of AQN-211. Renewal would extend expiration data to 781229.

  REID.R.W. Operating Reactors Brench 4 (Prf 790625). 78/11/02.4pp. 94193.249.
- 7811090082 informs NRC of reaseignment to Martin Jischks of responsibilities re univ reactor & nuc mati activities carried out under Lic SNM-1397.

  UPTHEOROVE.W.R. Oklahoma: Univ. of. 78/11/03 ip. 94041-291.
- G. Inspection reporte, 1E Bullatine & correspondence
- 7810130245 Forwarde copy of IE Inspec RaptsM50-112/78-02 & 70-1430/78-02 on 780821 & 22 during which no iteme of noncompliance were found.

  HIND J.A. Ragion 3: Chicago- Safeguards Branch. 78/10/05. 2pp. 94072:176
- --7810130247 IE Inspec Repts#30-112/78-02 & 70-1430/78-02 on 780823 during which no items of noncompliance were noted. Areas inepscted incl:nuc mati control & accounting, inventory, shipping, receiving, storage & controls. W/o rept. 4 Region 3. Chicago, Bafaguarde Branch. 78/10/04. Ip. 94079:178.

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR P. Operating license stage documents & correspondence

7811D30224 Forwards Amend#13 to Facil Oper Lic#R-52 revising Tech Spece as requested in 770714 ltr w/sefety Evaluation REID.R W Deprating Reactors Branch 4 (Pre 790625). 78/10/12. 2pp. 02724-252

~-781:030228 Amend#13 to Facil Oper Lic#R-52 revising Tech Space re editorial changes to incorporate currently used terminology. Onsite org & position titles, increase of maximum insertion

reactivity & mod of instru oper requirements Operating Reactors Branch 4 (Pre 790625). 78/10/12. REID. R. W.

17pp. 02724. 254.

--781030232 Seraty evaluation supporting Amend 13 to License R-52 concluding that proposed Tech Spec changes are acceptable and do not reduce any of the safety margine.

\*\*\*Office of Nuclear Resolver Regulation, Director 78/10/12 bpp. 02724-271

DOCKET 50-116 10WA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

7812180303 Notifies licenses of expiration of Oper Licen-59 for Argonaut-Type Model UTR-10 on 791012 & forwards specific items that must be addressed in renewel appl REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/07. Bpp. 94363:353 REID. R. W

8. Reportable occurrences, LERs & related correspondence

7811050073 Gurmarizes File documentation re alimination of inspac of Shim-Safety Rod Position Potentiomater Resears: success of hardware mod is proven inspec procedure was harmful, elimination of procedure supported by Radiat Bafety Comm HENDRICKSON, R I lowa State Univ. 78/10/28. 2pp 94423 94423: 355. HENDRICKSON, R

--7811060074 Reportable Occurrence on 780914:UTR-10 Shim-Bafaty Rod failed to insert during menual acrem.dua to loose position potentioneter mounting nut. Mod: lock washer added to potentioneter mounting hardware.

HENDRICKSON.R iowa State Univ. 73/09/27. 3pp 94423:357.

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR P Operating licenes stage documents & correspondence

78:1280210 Forwards specific requirements reviewed in appl for lic renewal. Renewal of liceR~79 req submission of an appl that demonstrates that reactor can continue to be operated safely thru the term of the renewel. REID-R.W Operating Reactors Granch 4 (Pre 790623), 78/11/14, -6pp. 94013:201.

Q inspection reports, IE Bulletins & correspondence

78:1290393 Perwards IE Inspec Rapt#50-123/78-04 on 780921-22 during which no items of noncompilance were noted.
DAVIS, A.B. Region 3. Chicago, Fuel Facility & Materials Safety
Branch 78/10/23 2pp 94181:182.

--781 1270377 IE Inspec Rept#50~123/78-04 on 780921-22 during which no itsms of noncompliance were noted. Major areas inspected incl: amergency planning activities, coordination w/support agencies, training & internal audits. AXELSON.W L. Region 3, Chicago, Fuel Fecility & Meteriels Bafety Branch. 78/10/20 4pp. 74181,184.

DOCKET 50-128 TEXAB ALM UNIV. RESEARCH REACTOR Q. Inspection reports, IE Bulletine & correspondence

78ii170ii1 Forwards IE Inspec Rept#50-128/78-02 & Notice of Violation. HADERN-0.L. Region 4: Dallate, Reactor Operations Nuclear Support Branch. 78/10/06. 2pp 94047:131.

--7811170114 Notice of Violation from inspec on 780911-15.Ltr of 710623 from AEC to TXAM also encl.

MADBEN.G.L. Region 4, Dalles, Reactor Operations Nuclear Support

Branch. 78/10/06. 3pp. 94047:133.

--7811170119 1E Inspec Rept#50-128/78-02 on 780911-15 during which 2 items of noncompliance were noted failure to post High Radiation Area & failure to post notice to workers MURRAY.B., MADBEN.G.L. Region 4, Dalles, Resctor Operations Nuclear Support Branch, 78/10/04, 9pp. 94047-136

7812070001 Forwards 18 Inspec Rept+30-128/78-03 on 781107-09.

MADEEN.G. L. Region 4. Dallas. Reactor Operations Nuclear Support
Brench. 78/11/20. 1p. 94134:073.

--7812070002 IE Inapsc Rept#50-128/78-03 on 781107-09 during which no items of noncompliance were noted Major ereas insper incl: implementation of approved physical security plan re protection of ShM security organization & access control.

HARDLJ J. Region 4. Dellas. Reactor Operations Nuclear Support

Branch EVANS, C. A. MADSEN, O. L. Region 4. Dellas. Office of the

Director. 78/11/20 1p. 94134-076

DOCKET 50-131 DMAHA VET. ADMIN HOSP. RESEARCH REACTOR P. Operating license stage documents & correspondence

781218037: Forwards specific items that must be addressed in renewal of Oper Lican-37 which expires 790824. Gen requirements are given in 10CPRSO. 31. 55 & 73. Operating Reactors Branch 4 (Pre 790625). 78/12/07. REID, R. W 10pp. 94338 188

DOCKET 50-133 HUMBOLDT BAY POWER PLANT. UNIT 3 H General correspondence

7812130054 Forwards updated svc list pursuant to agreement to discuss discovery procedures at 781114 meeting.
HATTB.M.J. McCutchen.Doyle.Brown & Emersen 78/11/21. App. 94211:025.

J. Insurance & Indomnity information

7812130002 Forwards Amend#20 to Indemnity Agreement#8-21. CRANE.P.A. Pacific Oas & Electric Co. 78/12/05. ip. 94307:254.

--78:2130008 Amend#20 to Indemnity Agreement#8-21, adding new Article VIII.covering deferred premiums & submission of finencial statements.

8ALTZMAN.J. Antitrust & Indomnity Group.

& Electric Co. 78/12/05. 2pp 94307:255. BONNER, J. F. Pacific Gas

P. Operating license stage documents & correspondence

7812060276 Requests registration as user of shipping packages, Cart#6059 & 6144 Quality Assurance Prog will be exactted accordingly.
CRANE, P. A. Pacific Gas & Electric Co. 78/08/10. ip. 94372:282.

7810240111 Forwards copies of appl for amend to DPR-7 open lic re miner change in frequency requirement for not safeguerd sys-testing & other minor admin changes. As a Class 2 amenda fee is \$1200 & is forwarded. CRANE, P. A. Pacific Gas & Electric Co. 78/10/20. 1p.

--7810240113 Requests Facil Oper Lic DPR-7 be amended by making edmin changes to Tach Blace appended to lic Changes set forth incl changes in frequency of performing Nuc Bafeguard Bys Testing & adding Quelity Control to Plant Staff Rev Comm. SHACKLEFORD.B., CRANE, P. A., HORRISBEY, J. C. Pacific Qas & Electric Co. 78/10/12, 17pp.

7810310207 Forwards"Guarterly Status Rept of Investigations & Mode. 780701-780930.Rept#19". Topics incl geologic & seismologic investigations seismic design review.purchase b installations of seismic mods. GROVE, P. A. Pacific Qes & Electric Co. 78/10/27. 2pp. 94090:326.

7811280439 Confirms 781024 conversation w/J Carroll re the PQEE decision to suspend until spring the present cycle of drilling oper because of high winter drilling costs & lack of sermisation from land owner to dig a trench.

ROONEY,V.L. Operating Reactors Brench 3 (Pre 790625). 78/10/30. 1p. 94380:135.

7812150134 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendes to fecilitate sending out mett. W/encl Registration Form & List of Locations.

MILLER-J.R. Assistant Director for Site & Safeguards (Pre 791030).
78/11/13. Spp. 2180250 Forwards Rev#1 "Draft Radiological Effluent Tech Space" for R's(NVREG-0473) & "Preparation of Radiological Effluent the Speed for Nuc Pur Plants" (NUREG-0133)

IPES-B.K Assistant Director for Englabbrs & Projects (Pre10625) 78/11/15 6pp 94366-119.

2070314 Notification of 78)113 meeting w/Dutch & POSE & w/Dutch on 11117 to provide technical info re unit & ref plant for tch 54 MWE natural circulation Dadewaard W/list of tendess & question encl IDMEY,V L. Operating Reactors Branch 3 (Pre 790625) 70/11/20

PP. 94084: 325

REBOOTS Emphasizes importance of submitting accurate & complete info by NIC by licensess & applicants Info submitted must be obstantiated by data & calculations Licenses must notify in complete or enforcement ection will result WIB.J.O Office of Inspection & Enforcement, Office of the crector 78/12/06. 2pp. 03555:3[1]

inspection reports. IE Bulletins & correspondence

1240092 Forwards IE Inspec Rept#30-133/78-11 on 780828-31 during lich no items of noncomplience were noted. IEHG.J.L. Region 5. Ben Frencisco. Reactor Operations Nuclear Japont Brench 78/09/18. Zpp.

310240094 IE Inspec Rept#50-133/78-11 on 780828-31 during which no items of noncompliance were noted Major areas inspected included, outage activities, records mgt eys followup & followup on Builetine & Circulars.

MCESHMER, J.D., JOHNSTON, G.W., CREMB, J.L. Region 5, San Frencisco, Res

0200255 Forwards IE Inspec Rept#50-133/78-12 on 780821-24 during nich no items of noncomplience were noted Encl conteins 790 info & Is wheld from public disclosure. BROERHAUG.L.R. Region 5. Ban Frencisco. Bafeguarde Branch 9/10/11. 2pp. 03555:204.

0230221 IE Circular#78-17-Inedequate Guard Training/Gualification & #181fled Records.Discusses incidents of qualification scords falsification & recommends action to prevent EUFFERCE.

Office of Inspection & Enforcement, Office of the Director 3/10/13. 6pp. 94181:356

0230316 Forwards IE Circuler#78-17. (800 AND: 7810230221. Docket DESCRIPTION OF THE CITCUISTW/8-17. (See AND: 7810230221.DOCKET D-313,781013) NOELMEN.R.M. Region 5. Ban Francisco. Office of the Director B/10/13. 1p. 94166:347.

ii50007 Forwards IE Circular 78-18. NGELKEN,R H. Region 5. Ban Francisco. Office of the Director. 9/11/06. lp. 94112:301.

2190194 Forwards IE Inpact Rept#30-133/78-13 on 781023-26 during hich no itams of noncompliance were noted. DOK.H.E. Region 5. San Francisco, Fusi Fecility & Materials Sefety ranch. 78/11/17. 2pp. 94381:040.

812190197 IE Inspec Rept#50-133/78-13 on 781023-26 during which no items of noncompliance were noted. Major areas inspected incl:emargency plenning redipl anviron procedures & radiat protec training.

FISH.R.F. Region 5. San Francisco. Office of the Director. 78/11/17. 9pp. 94381:042.

2270450 Forwards IE Inspec Rept#50-133/78-14 on 781113-15 during hith no itsms of noncompliance were noted REWGJL. Region 5, Sen Francisco. Resetor Operations Nuclear upport Branch. 78/11/22. 2pp. 94015:351.

812270456 IE Inspec Rept#50-133/78-14 on 781113-15 during which no items of noncompliance were noted. Mejor areas inspected inclications activities, pipe support surveillance, calibr & followup on IE Bulletine & LERB.

CANTER. H. L. , MORRILL, P. J. , MORBENER, J. D. Region 5, San Francisco, Reactor Operations Nuclear Support Branch. 78/11/22. 5pp.

94015: 353.

1300063 Forwerds 1E Bulletin478-12A. suppl to IE Bulletin 78-12. NGELKEN.R.H. Region 5. Ban Frencisco. Office of the Director 8/11/24. ip.

Bii300055 IE Bulletin#78-12A.suppl to IE Bull=tin 78-12 modifying requirements to IE Bull=tin 78-12 re-info on weld matls used shall be submitted w/In 120 days & correlation of specific heat to weldments is not req. 

• Office of Inspection & Enforcement, Office of the Director. 78/11/24. App. 94127:100.

7612290030 Forwards 1E Bulletin 70-14. ENOELKEN.R H Region 5. San Francisco. Office of the Director 78/12/19 ip 06911 001

R Periodic operating reports & related correspondence

7810180123 Forwards Monthly Open Rept for Sept 1978.
RAYHOND, W. A. Pacific Gas & Electric Co. 78/10/09 1p 94140 297

-7810180125 Monthly Oper Rept for Sept 1978 BIERBAUM. O A Pacific Gas & Electric Co 78/10/04 4pp 94140 258

7911150146 Forwards Monthly Oper Rept for Oct 1978 RAYMOND. W A Pacific Gas & Electric Co. 78/11/10 1p 94272 267

--7811130149 Montly Oper Rept for Oct 1978 BIERBAUH, G A Pecific Gee & Electric Co 78/11/01 4pp. 94272 268

78:2130310 Forwards Monthly Oper Rept for Nov 1978
RAYMOND, M. A Pacific Oas & Electric Co 78/12/08 1p 94021 340

--7812130311 Monthly Oper Rept for Nov 1978 OETTY, B C Pacific Gas & Electric Co 78/12/01 4pp

B Reportable occurrences. LERs & related correspondence

7810180028 Forwards LER#78-003/017-0 CRANE. P A Pacific Cas & Electric Co 78/10/11 1p 94195 193

--7810180035 LERM78-003/01T on 780912 during cold shutdown.#3 fire/low pressure pump was operated but would not reseat rendering it inoperable Caused by valve which was installed horizontally instead of vertically.
REDEKER, S. J. Pacific Oas & Electric Co. 70/10/11 lp 94195 194

DOCKET 50-134 HORCESTER POLYTECH INST. REBEARCH REACTOR V Operator Examinations

7811240038 Requests sched of operator examination in Jan 1979 for 3 persons Formal appl & Pacil epproval will be forwarded upon completion of treining prop MILBURYLL Worcester Polytechnic Inst. 78/11/10 1p. 94497:247

DOCKET 50-142 UCLA TRAINING REACTOR P. Operating license stage documents & correspondence

7812080099 Forwards itr from Director of UCLA Los Angeles Nuc Energy Leb re items in 780922 NRC ltr.Wo ltr. EVRACES J C California. Univ of Los Angeles 78/12/01. 1p 94109:008

O Inspection reports. IE Bulletine & correspondence

7812270421 Forwards Inspec Rept#30-142/78-03 on 781030-31 & Notice of Violetion W/o enci. NORDERHAUG.L.R Region 5. Ban Francisco. Befeguards Dranch 78/12/18. 2pp. 94312:328.

DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY J. Insurance & Indomnity information

7812010127 Forwards Endorssment#60 & 69 to Bezon NELIA Policy NF-107. States Endorsement#60 amended: advance premium \$425 & standerd premium & reserve premium \$284, 75. Endorsement #66 amended: stendard premium & reserve premium \$227. 80 M/smcl. MQNTOQMERY.C R. General Public Utilities 78/11/27. 19 94418:058

DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY
J. Insurance & Indeenity Information

7810270197 Forwards copies of Policy NF-12 Endorsements#75-83.83-89 k 94(Advanced Premium & Stendard & Reserve Premium for CY1978) k Policy NF-93 Endorsements 75-79 and 83(Advanced Premium. Standard & Reserve Premium for CY1978.
PIERCE.J. W Rockwell International Corp. 78/10/19 30pp 94054.041

DOCKET 50-148 UNIV. OF MANSAS REBEARCH REACTOR
P. Operating license etage documents & correspondence

- 7812040071 Forwards Ameni#12 to Facil LitHR-78 for res reactor changing Tech Spec re surveillance of rod megnets. REID-R.M. Operating Reactors Branch 4 (Pre 790625) 78/11/16 2pp. 94455 075.
- --7812040074 Amend#12 to Fecil Lic#R-78.changing Tech Spec resurveillance of rod magnets.
  REID.R.W. Operating Resctors Branch 4 (Pre 790625). 78/11/16.
  Spp. 94455:077.
- --7812040079 Sefety Eval supporting Amend#12 to Facil Lic#R-78.Concludes ###n6 would not be inimical to pub interests.

  \*\*Operating Reactors Branch 4 (Pre 790525). 78/11/16 2pp. 94455:082
- Q. Inspection reports, iE Builetins & correspondence
- 7812060324 Forwards IE Inegec Rept#30-148/78-0) & Notice of Violation MADSEN.Q L Region 4. Delias. Reactor Operations Nuclear Support Branch. 78/10/13. 2pp 94029:344.
- --7812060326 Natice of Vialation from Inspec on 781004-06.

  # Region 4. Delies, Reactor Operations Nuclear Support Brench.
  78/10/13 ip. 94329.346
- --7812050332 IE Inspec Rept#50-148/78-01 on 781004-06 during which 1 item of noncompliance was noted: Push elements were removed from core out of order
  DICKERBON.H M. Region 4. Delias, Rector Operations Nuclser
  Support Branch. 78/10/13. App. 94329:347
- 78:11:70289 Ack receipt of 78:026 itr informing NRC of steps taken to correct deviations noted in Inspec Rept#50-148-78-01.Finds that add1 info is req. MADEEN, O. U. Region 4. Dalles. Reactor Operations Nuclear Support Brench. 78/11/02. ip. 94044:235.
- --7811170293 Responds to 781018 NRC ltr re violation noted in Inspec Rept#50-148/78-01.01d fuel unloading procedure has been superseded. KRAFT.D.C. Kansas. Univ. of. 78/10/26. ip. 94046:236.
- 7812060311 Act receipt of 781026 & 781113 ltrs informing NRC of steps taken to correct violations noted during inspec #50-148/78-01.

  MADSEN.Q.L. Region 4. Delies. Reactor Operations Nuclear Support Branch. 78/11/20. 1p. 94332:012.
- --7812060319 Supple info contained in 781026 ltr. There has been a check of procedures to see that all superssded procedures ere clearly merked Merking superceded procedures should evold repetition of generic prob of oper w/old procedures. KRAFT, D. C. Kenses, Univ. of. 78/11/13. ip. 94332:013.

DOCKET 50-155 BIQ ROCK POINT NUCLEAR PLANT F. Security, medical, emergency & fire protection plana

- 7812130161 Forwards rev security plans for subj facils as requested by NRC.Plans withheld (ref 10CFR2.790).

  \*\*HOFFMAN.D.P.\*\* Consumers Power Co. 78/12/08. 1p. 94305:120.
- P. Operating license stage documents & correspondence
- 78:01:01:64 Forwards fire protection plan describing fire protection administration controls & fire barrier tasts.
  HOFFMAN, D. P. Consumers Power Co. 78/10/06. Ip. 94069:267.

- 7810190218 Forwards ejectric diagrams omitted from 780808 package. Set of aperture cards advanced directly to R Silver HDFFMAN, D.P. Consumers Power Co. 78/10/10. 1p. 94415.191.
- 7810310027 informs that for SEP normal channel of oral communication will be followed, but to expedits reviews direct oral communication between subj facil staff & members of SEP branch is encouraged.

  ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/10/10.

  Zpp. 94094 347.
- 7810160097 Informs of dalay in providing NRC w/info re environ qualification of safety-related equip due to slow review of tebles presented.

  BIXELD A Consumers Power Co. 78/10/11. lp. 94004:221.
- 7810250065 Discusses use of continuous control rod drive feature during power operation. Concludes that ability to reliably verify coupling integrity is important. Change does not superseds or replace 741101 Tech Specs change request.

  81XEL-0 A. Consumers Power Co. 78/10/19. 2pp. 07587-001.
- 7811090039 Forwards AmendW21 to Facil Oper LicMDPR-6 for subj facil. Amend changes Tech Bpecs as requested in 780517 ltr by incorporating requirements of 10CFERSO Append J for periodic tast schedule & formula for reduced pressure leak rates. ZIEMANN,D L. Operating Reactors Branch 2 (Pre 790425). 78/10/20. 2pp. 94040 048
- --7B11070071 AmendW21 to Facil Oper LicMDPR-6 changes Yech Spece to incl periodic test schedule & formula for reduced pressure lask rates. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/20. 4pp 94040:050
- --7811090079 Sefsty Evai by Ofc of Nuc Reactor Reg Supporting Amend#21 to Lic#DPR-6 of subj facil. Amend changes Tech Specs reperiodic test schedule & formule for reduced prassure leak rate. Concludes issuance of amend is sacurity & health safe.

  ### Uffice of Nuclear Reactor Regulation, Director. 78/10/20. 3pp. 94040:034.
- --7811090088 Natice of Issuence of Amend#21 to Facil Oper Lic#DPR-6 ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625). 78/10/20. 2pp.
- 7811210172 Eval of cable splices in reactor containment as referenced in 780224 submittal has been completed Splicing math may be inadequate to preclude failure of LOCA. Plant is shut-down & splices are being repaired. FD00-H.C. Consumers Power Co. 78/10/23. ip. 01791:057.
- 7810270075 Responds to 780817 NRC itr requesting review of initial evel of 8 SEP topics, No errors were identified during review.

  Ravisw rept entl.

  HOFFNAN, D. P. Consumers Power Co. 78/10/24. 23pp. 94059:169.
- 7811010165 Forwards add1 \$2,800 fee for consideration of license amend request dtd 780517.

  BIXE, D.A. Consumers Power Co. 78/10/26. 1p. 94391:237.
- 7811130047 Requests add1 info re ESP switchover from injection to recirculation mode.isolation of reactor safety protec sys from non-safety sys B engr safety features.(ESF) sys logic & design.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.
  3ps. 40010:231.
- 7811030277 Forwards requests for add1 info re fire protection per 781010-13 site visit Response desired by 781113. LAINAB.e. Plant Systems Branch (Pre 791030). 78/10/27. 9pp. 02719:346.
- 7811020212 Forwards add1 description of Reactor Physics Methodology of subj fac11 for discussions leading to issuence of Amend#15 to DPR=0.

  BIXE.D. A. Consumers Power Co. 78/10/30. 1p. 94257;137.
- --7811020219 Describes methode used in physics model dev by CPC included descriptions of techniques used in generation of input & modeling of core & comparisons of plant data to results generated by physics model.

  4 Consumers Power Co. 78/08/25, 61pp. 94257:138.
- 7811060084 Notifies NRC of possible deficiency found in analysis for very small breek LOCA, but which le not considered reportable occurance under tech space.

  81XE.D.A. Consumers Power Co. 78/10/31. 2pp. 94422; 120.

# DOCKETED ITEMS

- 7811130167 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plants Encl w/Seminar Info Sheet(to be completed & returned by 781117) & Proposed Agenda KEPPLER, J O Re Region 3. Chicago. Office of the Director 78/11/07 6pp 03553: 215.
- 7811150198 Forwards proposed change to Teth Specs for License BPR-6. incorporating requirements implementing 10CFR50 App 1 per NRC 780711 1tr BIXEL. D. A. Consumers Power Co 78/11/13 18pp 94242:216.
- 7811280430 Forwards draft Sys Eval Prog Safety inpute re Topic VIII-3 A. Station Battery Test Req Requests they be transmitted to DAVIS.D.K. Systematic Evaluation Programs Branch (Pre 790625) 78/11/14. 23pp 94381 119
- 7811270140 Forwards names of attenders at meeting on 781116 re site geologic & geotech features at subj facil.W/att agenda & items to be reviewed ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790623) 78/11/15 3pp. 94271:327
- 7812150173 Notice of workshops re implementation of training & quel requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out mall W/enci Registration Form & List of Locations.
  MILLER.J.R. Assistant Director for Site & Bafeguards (Pre 791030).
  78/11/15. Spp.
- 7812180264 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for BWR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Pients" (NUREO-0133) W/o encl AND: 7811280104 & 7811270180.

  ORITES B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp
- 7812060377 Ack receipt of 780714 tech info. Forwards request for eddi info based on review & site visit. Response requested by Operating Reactors Dranch 2 (Pra 790625). 78/11/20. ZIEMANN. D. L 10pp. 94331:318
- 7811270094 Forwards req ECCB ring spray sys design eval"Big Rock Point Core Spray Byranger & Bisam Baffle Design Rept."
  BIXE.D.A. Consumers Power Co. 78/11/21. 1p. 94437:119.
- --7811270099 Forwards "Big Rock Point Core Spray Sparger & Steem Deffie Design Rept" & append 364. Rept describes improved flow distrib characterisics. Recommends confirmation test be serformed prior to inetallation. LEDATE.R.E. General Electric Co NEDC-21974, 78/11/27. 300pp. 94437: 120.
- 7812040220 Responds to 780322 NRC 1tr requesting add1 info relating to engineered sefety features evellable to mitigate consequences of postulated fuel handling accident inside containment at subj fecility. Related correspondence. BIXEL, D. A. Consumers Power Co. 78/11/29, 12pp 94452: 295.
- 7812070215 Forwards technical justification for next proposed containment integrated leek rate test (iLRT) in 1980-1981. As a result of excessive leak rate encountered ILRT considered to be first ILRT failure. BIXEL, D. A. Consumers Power Co. 78/11/29, 3pp. 03555; 101.
- 78:21:0011 Discusses possible dengers of LOCA in conteinment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANO: #7812090207.
  ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29.
  Epp. 94339: 237.
- 7812050224 Responds to 780906 request for info re sefety-related elected equip quel using NRC stenderd date format. Equip addressed is that which will ensure safe shutdown during LOCA & main steam line break or is subj to hostile environ due to these. BIXEL, D. A. Consumers Power Co. 78/11/30. 46pp. 94201:152.
- 7812130281 Reviews 780307 submittal & concludes feedwater trip on high reactor level is not necessary to assure safe oper of subj Pacil. ZIEMANN. D. L. Operating Reactors Branch 2 (Pre 790525). 78/12/01. 2pp. 94291: 338.
- --7812130286 Safety Eval of the proposed actions re BMR feedwater pump trip on reactor high level. Concludes that util decision not

- 78:2280118 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIS-J O Defice of inspection & Enforcement, Office of the Director 78/12/06 2pp 94310-213
- 7812120182 Informs 188C of Pilter testing condition in respiratory protec equip which is different from regulation in Reg Ouide 8.15, but which meets the regulatory requirements. BIXEL D A Consumers Power Ca 78/12/08 ip 94277.082.
- 7812130133 Forwards responses to 781120 NRC request for addl info re Fire Heierde Analysis & to NRC staff positions derived from 781010-13 fire protec site visit Hod implementation sched will be submitted by 790115 HOFFM
- 7812150085 Requests eddi info from SEP licensess re siectrical penetrations of restor conteinments to complete evaluation ZIEMANN.D L. Operating Resetors Branch 2 (Pre 790625) 78/12/08 ZIEMANN.D L. 0 4pp 94211 339
- 7812210091 Forwards NUREG-0485, Vol 1. No 2 "Status Summery Rept-Bys Eval Prog " W/o enc) Ziemann, O. L. Op 2pp. 94269.154 Operating Reactors Branch 2 (Pre 790625) 78/12/08.
- 7812270039 Requests addi into to complete review of "Big Rock Point LOCA Aneigete Using Erron Nuc Co Non-Jet Pump BUR Evel Model Large Breek Example Problem" XN-NF-78-25 Revi Info incl. emergency condenser reactor water lavel & choked flow.
  21EMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/12/14 6pp. 94160 211
- 7812260045 Burmary of 781116 meeting w/util to discuss SEP review of site geology & geotechnical data List of attendess encl CHENG.T.M. Systematic Evaluation Programs Branch (Pre 790625) CHENO, T.M. Systemetic Eval 78/12/15 4pp. 94021:040
- 7812260212 Forwards rev tables describing environ qual of subj facil equip. Corrected tables represent Attach 2 of 781130 itr. BIXEL, D. A. Consumers Power Co. 78/12/20 6pp. 94160:177
- 7812280134 Responds to 781208 request for addl info re SEP Topic Vili-"Electrical Penatrations of Reactor Containmente" Requires tabulation of info selected by NRC in docket search by early Jan to prepere reply within schedule BIXEL, D.A. Consumers Power Co. 78/12/22 ip. 94310:339.
- Q. Inspection reports, IE Bulistins & correspondence
- 7810260179 Forwards 1E Inep Rept 50-155/78-05 on 780829-0901 & notice of violation DAVIS. A. B. Region G. Chicago: Fuel Facility & Materials Safety Brench. 78/09/18. 2pp. 94057:284.
- --7810260180 Notice of violation from inep on 780829-0901.

  Region 3, Chicego, Fuel Fectitity & Meteriele Sefety Branch. 78/09/18. 1p. 94057: 286.
- --7810260183 IE lnep Rept 30-153/78-05 on 780829-0901 Noncompliance noted:licenese disposal of licenesd metle. SCHUMACHER.M.C. Region 3. Chicago. Fuel Fecility & Materials Brench. 78/09/18. 8pp. 94057; 287.
- 7811240170 Responds to 780918 NRC ltr re devietion noted in Inspec rep 50-155/78-05 Corrective action: procedures re transfer or release of industrial-commercial items have been ray & ell

items leaving control areas will be surveyed.
BIXEL, D.A. Consumers Power Co. 78/10/06. ip. 94458:262.

- 7810190234 Forwards 16 Insp Rept 50-155/78-08 on 780912-22 & notice of violation. HIND.J.A. Region 3. Chicago, Safeguerds Branch 78/10/10. 2pp. 94414:214
- --7810190236 Notice of violation from insp on 780919-22. \*\* Region 3, Chicago, Bafeguards Branch. 78/10/05. lp. 94052 063.
- --7810190247 1E Inspec Rept#50-155/78-08 on 780919-22 during which I item of noncompliance was noted: failure to prapare corrected Form NRC-741. Proprietary info deleted. HIND, J. A. Region 3. Chicago, Safeguarde Branch. 78/10/05. Spp. 94052:064.

- 7810230334 Forwards 1E Circular#78-17 (800 AND 781023022).Docket 50-313.781013)
  KEPPLER, J O Region 3. Chicago, Office of the Director 78/10/13. 1p 94194-305
- 7811300135 Forwards IE Insp Rept 50-155/78-07 on 780911-15 & notice of violation.
  FIORELLI.G. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/26 2pp. 94073:223.
- --78i1300138 Notice of violation from insp on 780911-15 \* Region 3, Chicago, Office of the Director: 78/10/26. ip 94073.198
- --7811300141 iE inep Rept 30-155/78-07 on 780911-15. Noncompilance noted: failure to follow procedures for all structures.eys. conjoinents & safety actions defined in facility quality isst.
  HUNTER.D.R., RIDOMAY.M.R., MARNICK.R.F. Region 3, Chicago: Office of the Director. 78/10/26. 22pp. 94073:199.
- 7811150051 Forwards IE Circular 78-10. KEPPLER.J. 9. Ragion 3- Chicego, Office of the Director. 78/11/06. 1p. 94112:163
- 7811280052 Responds to NRC 781010 ltr re violations noted in Insp. Rept 50-155/78-08. Corrective actions corrected forms NRC-741 were prepared for two instances cites & will be issued by 781115. Proceedural changes initiated BIXEL-D.A Consumers Power Co. 78/11/09. 2pp. 03554:176.
- 7812020192 Responds to NRC 781026 ltr re violetions noted in Insp Rept 50-155/78-07. Corrective actions: startup checklist & BOP-1 procedure will be revised, time required for stable reactor period defined & blocking of screm capability documents BIXEL. D.A. Consumers Power Co. 70/11/20 Rep. 94109:341.
- 7812030314 Forwards 1E Bulletin878-12A, suppl to 1E Bulletin 78-12. W/enc! ANO.7611300035. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 78/11/24. 1p. 94393-195
- 7812060371 Ack receipt of 781006 ltr informing NRC of steps telen to correct violations noted in Insp Rept 30-135/78-12.

  DAVIS, A.B. Region D. Chicago, Fuel Fecility & Materials Sefety Branch. 78/11/28 lp. 94331:309.
- 78120E0217 Ack receipt of 781109 itr informing NRC of steps teken to correct violations noted in NRC 781010 ltr.
  HIND J.A. Region D. Chicago, Safeguards Branch. 78/11/28. lp. 94137:084.
- 7812260302 Ack receipt of 781120 ltr Informing NRC of steps taken to correct violations noted in NRC 781026 ltr. FIGRELLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/12/14. 1p. 94160:071.
- 7812280056 Forwards IE Bullstin 78-14. KEPPLER. J. G. Region 3. Chicago. Office of the Director. 78/12/19. 1P. 03554:344.
- 7812270180 Forwards description of inservice insp program for subj facility & requests relief from specific requirements of Section X1 of Boiler & Pressure Vessel Code. Notes that issuance of ement to 10CFR30. 55a will modify requests.
  BIXEL.D.A. Consumers Power Co. 78/12/22. 76pp. 94163:001.
- A. Periodic operating reports & related correspondence
- 7812120109 Forwards Monthly Open Rept for Nov 1978.
  HARTMAN.C. J. Consumers Power Co. 78/12/05. 1p. 94275;315.
- -~7812120112 Monthly Oper Rept for Nov 1978. HIMEBAUCH-N. Consumers Power Co. 78/12/05. 7pp. 94275:316.
- 7812270198 Corrected copy of Monthly Open Rapt for Nov 1978, H1MEBAUCH, N. Consumers Power Co. 78/12/05. 2pp. 74017:208.
- S. Reportable occurrences, LERs & related correspondence
- 7811210350 While using fuel trensfer cask to move core internals for 780922 maint activities, cable which controls cask sling brake went slack which could prevent timely tripping of cask brake mechanism.

  HARTMAN.C.J. Consumers Power Co. 78/09/25. ip. 94484:357.

- 7810170217 Forwards LER#78-032/03L-0.
  81XEL-D A Consumers Power Co. 78/09/27. 1p. 94236.193.
- 7810110104 Farwards LER#78-036/01L-0.
  81XEL-D.A Consumers Power Co 78/10/05. 1p. 94066:345.
- --78:01:01:06 LERN78-035/01L-0 on 78:0703 condensate storage tank level fell below 65% limit due to oper error caused by operator oversight incident to be rev to minimize potential for recurrence.

  \*\*Consumers Power Co. 78:/10/03. 1p. 94066.346.
- 7811240231 Forwards LER#78-041/01T-0.

  BIXEL-0 A. Consumers Power Co. 78/10/06. 1p. 94458:208.
- --7811240235 LER#78-041/017-0 on 780922: while relaing transfer cask to move core components, trip line controlling cask safety sling trip device went slack. Caused by sxcessive wear on gear driving chain takeup for trip line to safety sling brake.

  \*\* Consumers Power Co. 78/10/06. 1p. 94438: 209
- 7810130171 Forwards LER#78-038/03L-0, #78-039/03L-0 & #78-040/03L-0. BIXEL.D.A. Consumers Power Co. 78/10/09. ip. 94003:055.
- --78:0130175 LER#78-038/03L-0 on 780909: during pient startup control rod drive temps were excessive due to drive cooling weter leeks at small control rod drive bolted flenge "O-ring" seals. Seel rings repieced. & seal specers edded.

  \*\* Consumers Power Co. 78/10/09. 7pp. 94003:056.
- --7810130179 LERM78-039/03L-0 on 780911: during shutdown conditions, a control rod drive was removed for meint w/o reactor mode switch being placed in shutdown position. Repeirmen felled to notify control room as required a Consumars Power Co. 78/10/09. ip. 94003:057.
- --7810130183 LERM78-040/03L-0 on 780910: visuel inspec showed a blown ful in e per supply inverter. Hypothesis is that lightly loaded inverter should have a dummy load to practude transisht supply voitegs problems. Fuse replaced et once. « Consumers Power Co. 78/10/09. ip. 94003:058.
- 7811210369 Reportable Occurrence: on 781018.e routine inspec for isekage revseled minor leekage at nonisoletable wild where a 3/4" stub lins is connected to 3" reactor clean-up sys return line.

  BIXEL.D.A. Consumers Power Co. 78/10/19. 1p. 94485:133.
- 7810250096 Responds to 780906 NRC itr questioning control rod drive performance. During 1977-78, fecility had no cess of fellure of control rod to insert during control rod testing & reactor acrees.

  81XEL.D.A. Consumers Power Co. 78/10/20. 1p. 07587:001.
- 7810310190 Forwards LERW78-042/03L-0.
  81XEL-D. A. Consumers Power Co. 78/10/26, 1p. 94090:154.
- --7810310133 LERW78/042/03L-O on 780929: control rod coupling integrity tests performed in the jog mode white at pur oper(since July 1974) may not heve been valid tests. In jog mode the withdrew pressure timing signal is not of sufficient duration.

  \* Consumers Power Co. 78/10/26. ip. 94090: 155.
- 7811090203 Forwards LER#78-037/01T-1, LER#78-031/01T-1, LER#78-037/03X-1, LER#78-035/01T-1 & LER#78-036/03L-1, Update of previous rapt on 780912.
  - # Consumers Power Co. 78/10/26, 1p. 94038;268.
- --7811090205 LERM78-037/01T-1 on 780906:mein steam isolation valve MO-7050 failed to close during routine tests. Caused by herdaned valve stem pecking. Velve operated property after pecking lubricated.

  \* Consumers Power Co. 78/10/26. 2pp. 94038:269.
- --781090223 LERM78-031/01T-1 on 780810: rejectable weld identified in weld made in 1972. Defect based on relience on 1972 rediggr techniques, Defect area being observed. Repairs will be made during future outage.

  \*\* Consumers Power Co. 78/10/26. 2pp. 94038: 270.
- --7811090226 LERM78-032/03X-i on 780819: failurs of check valva providin containment integrity in 2" deminaralized water line: R5 gailuns of contaminated water removed from plant. Caused by velve defects water removal dus to inadequate survey.

  \* Consumers Power Co. 78/10/26. 2pp. 94038: 272.

- -7811090229 LERM78-035/01T-1 on 780904: supply valve CV/4097 leaked in excess of Tech Spec limits. Caused by maladjustment on 24" butterfly valve seel. Adjustment procedures & valve design will be reviewed.

  \* Consumers Power Co. 78/10/26 2pp. 94038: 274
- -7811090234 LER#78-036/03L-1 on 780909 during transfer of water to
  - primary sys during hot shutdown condensate storage tank level fell below 65 percent level. Caused by operator oversight • Cansumers Power Co. 78/10/26. 1p. 94038:276
- 911030136 Forwards LERW78-044/017-0. 91XEL.D. A Consumers Power Co. 78/10/31. 1p. 02723: 299.
- -7811030139 LERM7B-044/01T-0 on 781018: during primary sys startup.minor leak at 3/4"vent sips weld attachment seen on 3" return line from cleanup sys to 2 reactor recirculating loop. Caused by fatigue cracking from inside to outside coupling weld.

   Consumers Power Co. 78/10/31. 3pp. 02723.300.
- B11070217 Forwards LERR78-045/01T-0. HOFFMAN, D. P. Consumers Power Co. 78/11/02. Ip. 94039:183.
- -7811070224 LERM78-045/01T-0 on 781020: during Systematic Eval Progreviews, splice matl used in control & Instrictionist for equip req to oper during LOCA was of marginal moisture resistance. due to the quality of the matl itself.

   Consumers Power Co. 78/11/02. 2pp. 94039: 124.
- 911140146 Forwards LERN78-043/03L-0 & #78-046/03L-0. 81XEL-D. A. Consumers Power Co. 78/11/10. 1p. 94383: 266.
- -7811140150 LER#78-046/03L-0 on 781025: Drive A-2 scrammad in 6.0 seconds, exceeding Tach Spec meximum. Caused by broken Buna-N disc on moving core of one of two screm pilot sciencids, resulting in slow venting ection.

   Consumers Power Co. 78/11/10. ip. 94383: 267.
- -7811140191 LER#78-043/03L-0 on 781014. Drive C-4 scrammed in 4.4 seconds, exceeding Tech Spec meximum Caused by broken Buna-N diec on moving core of one of two ecram pilot sciencids, resulting in slow venting action.

   Consumers Power Co. 78/11/10. 1p. 94383:868.
- 812040237 Forwards LER#78-027/03X-1 & #78-047/03L-0. 81XEL.D.A. Consumers Power Co. 78/11/29. 1p. 94328:03B.
- ~7812040239 LER#7B-027/03X-i on 78060i:control Rod Drive E-4 could not be w/drawn beyond Position 20 due to unknown cause Drive was reinstalled in reactor & has operated satisfactorily.

   Consumers Power Co. 78/11/29, ip. 94328:039.
- -7812040241 LERM78-047/03L-0 on 781031: control rod drive temp on Drive E-2 was above 350F degrees & excessive leakage was observed at E-2 drive flange connection due to "O-Ring" seal failure. Newseal ring installed & tested satisfactorily. 
   Consumers Power Co. 78/11/29. 1p.
- B1211017: Forwards LER#78-048/03L-0. B1XBL.D.A. Consumers Power Go. 78/12/06. ip. 94337:095.
- -7812110174 LER078-048/03L-0 on 781108: during steady state pur oper, the emergancy condenser shall side temp noted to be at 205 degrees F. Coused by leakegs thru M07053 veive.

   Consumers Power Co. 78/12/06. 1p.
- B12220074 Forwards LER#78-049/03L-0. B1XEL.O.A. Consumers Power Co. 78/12/14. Ip. 94342:331.
- -7812220075 LER#78-049/03L-0 on 781115: reactor water low level test circultry did not provide req test response. Caused by test trip level potentiometer drift.

  4 Consumers Power Co. 78/12/14. 1p. 94342: 032.
- OCKET 50-157 CORNELL UNIV. RESEARCH REACTOR
  I. General correspondence
- 811060082 Notifies NRC that subj facil is no longer pert of the School of Applied & Engineering Physics. Correspondence should be addressed to Dean Paul McIssac.

  OBMALD.P. I. Cornell Univ. 78/10/31. ip.

- P. Operating license stage documents & correspondence
- 7811080013 Forwards Amenda? to Licke-80 for Cornell Univ TRIGA react REID.R U Operating Reactors Branch 4 (Pre 790625). 78/10/24. 1 943/8:020.
- --7811060018 AmandW7 to LicHR-80 for Cornell Univ TRIOA reactor char Tech Specs re receipt, possession & use of special nuc ratio. REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/24. 200. 94198-022
- --7811080024 Rev pages to Lic Amende7.

   Operating Reactors Branch 4 (Pre 790625). 78/10/24 9pp. 94398 024.
- O. Inspection reports. IE Bulletins & correspondence
- 7812030286 Ack receipt of 781030 ltr informing NRC of steps taken to correct violations noted during inepec#30-97/78-02.
  #30-157/78-02 & #70-211/78-01.
  NARTIN.H.O. Region 1. Philadelphia. Befeguards Brench. 78/11/07.
  ip 94202:321
- --7812050290 Responds to 781004 NRC ltr re deviation nated in Inspec #50-97/78-02, #50-157/78-02 & #70-211/70-01 Corrective actions: complete physical inventory & documentation finished 781023 CLARK, D. D. Cornell Univ. 78/10/30. 1p. 94202:322.
- --7812050295 Forward\* IE Inspec Rept#850-97/78-02, #50-157/78-02, #70-211/78-01 & Notice of Violation.
  MARTIN.W.o. Region 1, Philadeiphia: Bafeguard\* Branch. 78/10/0 28p. 94202:323.
- --781205029B Notice of Violation from inepec on 780907-08.

  \* Region 1: Philadelphia: Bafeguards Branch 78/10/04. 1p. 9402:325.
- --7812050304 if Inepec Repts#50-97/78-02.#50-137/78-02.#70-211/78-01 780907-08 during which i item of noncompliance was noted: failure to perform complete physical inventory U/in required 12 months.

  SUMMERS. R. J. Region 1. Philadelphia. Safeguards Branch. 78/10/6pp. 94202:326.
- DOCKET 90-140 GEORGIA INST. OF TECH. REBEARCH REACTOR

  E. NRC Sefety Evaluation Report (SER), supple & correspondence
- 7812180386 Grants exemption for GIT from add1 security provisions of 10CFR73.50 & 73.60 until 791130. Forwards concurrence meno & BER STELLD.V. Division of Operating Reactors, 78/11/30, 4pp. 94357:256.
- --7812180389 SER supporting exemption from 10CFR73.30 \$ 73.60 in ord for licensee to properly store PuBe neutron source in reactor bidg w/o providing addl security measures for one year. # Office of Nuclear Reactor Regulation, Director. 28/11/30, 3
- G. Inspection reports, IE Bulletins & carrespondence
- 7812010175 Forwards 18 Inspec RepteM50-160/78-04, M50-276/78-02, M70-277/78-04 & M70-386/78-04 on 780925-27 during which no items of noncomplience were noted.

  KENNA M, B. Region 2, Atlante, Bafeguards Branch. 78/10/20: 2pp. 94409: 221.
- --7812010182 IE Inspec Repte#50-160/78-04, #50-276/78-02, #50-277/78-0
  #70-0386/78-04 on 780928-27 during which no itema of noncompliance were noted. Major erese inspec incl:nuc metl control & accounting procedures review.
  TODO.4.A., HILLIAMS.4.H. Region 2. Atlente. Safeguarde Branch. 78/10/20. 3pp. 74409: 223.
- 7811020440 Forwards IE Inspec Rept#50-160/78-02 on 780717-27 & notic of violation.

  8UTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materiels Safe Branch. 78/09/15. 2pp. 94351:178.

- DOCKET 50-163 GENERAL ATOMIC COMPANY
- A Application/construction stage documents & correspondence
- 7810270107 Reportable occurrence on 780831.at full power (1500 tw).reg control rod continued to withdraw even when operator was not depressing "up" control. Faulty up switch replaced & tested
- MORRY. W R. General Atomic Co (subs of Quif Dil Co ) 78/09/15. 2pp 94059 290
- F. Becurity, medical, emergency & fire protection plans
- 7812190145 Forwards current physical escurity plan in compilance w/reps.ciansified as "Natl Security Info" pursuant to certain DDE requirements Requests that series copies be destroyed and now copies be withheid General Atomic Co. (subs. of Quit Oil Co.) 78/12/15. MOWRY, W R.
- B Reportable occurrences. LERs & related correspondence
- 7810270104 Forwards reportable occurances on 780831 MOURY, W.R. 0s n 1p. 94039.289. Osneral Atomic Co (subs. of Gulf Oil Corp.) 78/09/15
- V Operator Examinations

1p. 94340 070

- 7810300284 Finds proposed changes to reactor open requal prog acceptable. Changes do not substantially decrease the frequency, duration or scope of the prog COLLINS.P. F Operator Licensing Branch 78/10/25 ip. 94183.308
- DOCKET 50-170 NATIONAL MAVAL MEDICAL CENTER P Operating license stage documents & correspondence
- 7810130227 Forwards AFRR1-TRIGACR-084 YAE)Annual Rept dtd 781031 HC1NDOE D. W Defense Dept of Defense Nuclear Agency. 78/10/06. 94079-324.
- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1 G. Inspection reports, iE Bulietins & correspondence
- 7812010345 Forwards licensee performance evaluation for Region i.No operating reactor in Region i is considered to have either abnormal or unusual safety concern ORIEFA B H. Region i. Philadelphia. Défice of the Director. 78/11/01 4pp. 94418: 234.
- 7812050004 Forwards Licenses Performance Eval Questions for subj facils in response to 771123 request. Feels it is possible that day of statistical mathodology for such sval may not justify the effort dualitative eval may be as good. Urges 1-year tast. ORIER. B.H. Region i. Philadelphia. Office of the Director. 77/12/13. 12pp 94200 114.
- --78:2050013 Requests views of Regional Directors on Licenses performance eval of subj facits. Forwards questions to be answered by THORNBURG.H. Division of Reactor Construction inspection. 77/11/23, 2pp. 94200.126.
- 7811150116 Forwards copies of Decommissioning Plan ALDEN: W. M. Philadelphia Electric Co. 78/11/06. 19. 94481:082.
- --7811150119 Decomm plan will progress in 4 phases. Phase i incl loading unloading & transfering fuel to spent fuel pool. Phase Il incl shipping fuel to reprocessing plant in ID, & Phase iII initiated after fusl is accepted. Philadelphia Electric Co. 78/07/31 118pp, 94481:083.
- 7811270298 Responds to 781106 request for info concerning licensee reg performance eval for Region 1 plants by NRC Provides details. ORIGR, B. M. Region 1, Philadeiphia, Office of the Director. 78/11/09, 9pp. 94239:230.

7812180268 Forwards RevM1 "Draft Radiological Effluent Tech Specs" for SWR's (NUREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREG-0123).

ORINES, B. K. Assistant Director for Engineers & Projects (Pre

- 70:12280035 Emphasizes importance of submmitting accurate & complete infeto NRC by licensees & applicants Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J C Office of Inspection & Enforcement. Office of the Director 78/12/06 2pp 94:33-214
- DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR
- P Operating license stage documents & correspondence
- --7812180079 Amend#3 to open lic#R-87. Changing Tech Specs to provide concise & definitive statement of limits of reactor oper parameters & surveillance measures req to assure that limits are not exceeded Operating Reactors Branch 4 (Pre 790625) 78/11/28

7812180076 Forwards Amend#3 to subj Pacif 11c#R-07 & Safety Evel REID.R.W Operating Reactors Branch 4 (Pre 790625) 78/11/28 2pp 94131 282

- --7812180086 Safety Eval Rept supporting Amend#3 to Oper LicHR-87. Concludes smand does not involve significant helards consideration, safety of pub not andangered & activities conducted in compliance will not be iminical to defense.

  Operating Reactors Branch 4 (Pra 790625) 78/11/28 3pp. 94131.328
- Q inspection reports. IE Bulletins & correspondence

44pp. 94131-284

- 7810310029 Forwards Inspec Rapt #50~182/78-02 on 780816-18 & Notice of FIDELLI-9. Region 3. Chicago-Reactor Operations Nuclear Support Branch. 78/09/21 2pp. 94094:349.
- --7810310033 Notice of Violation from inspec on 780816-18 Region 3. Chicago, Reactor Operations Nuclear Support Branch 78/09/21. 1p 94094:351.
- --7810310168 IE Inspac Rept#50-182/78-02 on 780816-18 Noncompliance nated operator w/expired licenes operated reactor. BROWN.C., LITTLE.W.S. Region 3, Chicago, Defice of the Director 78/09/21 4pp 94094:352.
- DOCKET 50-183 VALLECITOB EXPERIMENTAL SUPERHEAT REACTOR P Operating license stage documents & correspondence
- 78:2190020 Forwards NRC Order to Show Cause, which req that Gsn Elec Tast Reactor be placed & meinteined safely in cold shutdown condition pending further order. QASE.E.O Office of Nuclser Reactor Regulation, Director. 77/10/21.
- DOCKET 30-184 NATIONAL BUREAU OF STANDARDS REACTOR O. Inspection reports, 1E Bulletine & correspondence
- 7811300361 Forwards 1E Inspec Rept#50-184/78-05 on 780822-24 & Notice of Violation. BRUNNER,E.J. Region i, Philadelphia, Reactor Operations Nuclear Support Brench. 78/09/13 2pp 94116:290.
- ~-7811300362 Notice of Violation from inspec on 780822-24.

  \*\* Region i, Philadslphia, Reactor Operations Nuclear Support Branch. 78/09/13 ip. 94116:292.
- ~~7811300363 IE Image: Rept#50-184/78-05 on 780822-24 during which I i of noncompliance was noted; using outdated survaillance test ARCHITZEL.R.E., MCCABE.E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/12. App. 94116:293.
- 7812060275 Assponds to NBS 780923 ltr. Fells to find basis for withholding inspec rept IAW 10CFR2, 790, but will forward to Headquarters for action. ORIEM B.H. Region is Philadelphia. Office of the Director. 78/10/13. ip. 94372:258.
- ~-7812060286 Forwards pages of 16 Inspec Rept#50-184/78-04 & requests that noted portions be withheld from pub disclosurs. CATER.R. B. Commerce. Dept. of. National Bureau of Standards.

#### JOUNE LED IT EIMID

- 7812050300 Forwards 1E Inepet Rept#50-184/78-04 on 780706, 780711; & 780713 & Notice of Violation. CROCKER.H W. Region 1. Philadelphia. Fuel Facility & Materials Safety Brench 78/08/07. 2pp 94372 266
- --7Bi20a030B Notice of Violation from inspec on 780706,780711 & 780713 
   Region 1, Philadelphia, Fuel Facility & Materials Safety Granch 78/09/07. 1p. 94372-268
- --7812060316 IE Inepec ReptM50-184/78-04 on 780706,-11 & -13, during which 1 item of noncomplience was noted air flow rate in fume boods MC001-2 was too long PLUMLEE, K. E., KNAPP, P. J. Region 1. Philadelphia, Fuel Facility & Meterial's Bafety Branch. 78/08/07 13pp 94372 269
- 7812080041 Danies request to withhold from pub disclosure 780823 NBS ltr & portions of 1E Rept#50-184/78-Q4. Comm does not withhold memaly because info relates to reactor fuel gower, or C Executive Officer for Operations Support 79/11/08 2pp 94104 028
- 8 Reportable occurrences. LERs & related correspondence
- 7811210320 On 781102 during routine test, shim arm Wi had drop time in excess of acceptable range caused by slightly longer clutch release. Assembly removed & snap ring on armature hub replaced in favor of a more uniform support CARTER/R 8 Commerce. Dept. of 78/11/07 8pp 94488 073.

# OOCKET 30-186 UNIV. OF MISSOURI RESEARCH REACTOR

- J Insurance & indemnity information
- 7810110079 Responds to 780922 ltr & forwards copy of Advence Premium & Stendard Premium Endorsement to nuc liebility policy for 1978 w/Amend #10 to Indemnity Agreement E-45.
  BLANSTY.V. Missouri, Univ. of Rolls. 78/09/25. 4pp. 94063 344.
- P. Operating license stage documents & correspondence
- 78122900B0 Repts on failure of Regulating Blade Position Rod run-in on 781127; due to loosened set ecrew on position indication drive gear Corrective action: reactor shutdown blade position indication repaired. Set ecrew will be obsolved. BRUGGER.R.M., MCKIBBEN.J C Missouri, Univ. of Rolle. 78/12/21 2pp. 94190.087
- S. Reportable occurrences, LERs & related correspondence
- 7811050076 Reportable Occurence on 781022: Control Blade"B"unexpectedly dropped from drive magnet & hung up shout 7 inches above full insertion probably caused by broken outer race of 1 of 8 vertical guide bearings.
  MCKIBBEN, J. C. Missouri, Univ. of, Rolla. 78/10/31. 3pp 94484: COL

## DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

- H. General correspondence
- 7811140149 Notifies NRC of personnel changes at Northrop Reactor Fecil. CHALMERS.W. J. Northrop Corp. 78/10/05. 1p. 94383.274.
- P. Operating license stage documents & correspondence
- 7811020248 Forwards "Natural Environ Radioactivity Survey for 8\*pt 1977 thru Aug 1978\*for reactor LiceR-90.

  CRANDALL, M. E. Northrop Corp. 78/10/17. ip. 94247:114.
- --781102025: "Natural Environ Radioactivity Survey for the Pariod of Sept 1977 Through Aug 1978". ADAMS.J., COZENS.O., WODDS.J. Northrop Corp. 78/10/17. 10pp. 94247:115.
- O. Inspection reports. IE Bulletins & correspondence
- 78:2120331 Ack receipt of 78:114 ltr informing NRC of steps taken to correct deviations noted in Inepec Rept#30-1877/78-03. GREMB.J.L. Region 5, San Francisco. Reactor Operations Nuclear Support Branch. 78/12/01. ip. 94207:342.

- --7812130342 Responds to 781030 NRC ltr re deviation noted in Inapec Re #30-187/78-03 Corrective actions establishes calendar of periodic maint.reinstates prog of periodic b systematic performance eval of lic individuals.smerg procedure review CRANDALL.w E Northrop Corp 78/11/14 2pp. 94307 343
- --7812130346 Forwards Inspec Rept#50-187/78-03 on 781012-1013 & assoc Notice of Violation CREMS.J L. Region 5. San Prancisco. Resector Operations Nuclear Support Branch 78/10/30 2pp 94307 345
- --7812130347 Notice of Violation from Inspec on 781012-1013 CREWB.J L. Region S. Ban Francisco, Reactor Operations Nuclear Support Branch 78/10/30 to 94307 347
- --7812130350 IE inspec ReptM50-187/78-03 on 781012-1013 during which 2 items of noncompliance were noted in the following areas: periodic raint on pulse rod drive cylinder & periodic iic operator avals

  JOHNSON: P. H., CARLSON: J. D., STERNBERG: D. M. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 78/10/30 4pp 94307-348
- DUCKET 50-188 HANBAS STATE UNIV. RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- 78:01:0029 Forwards changes in procedures for Aug 1977-June 1978 btenniel control rod Insp.fuel element insp.& reactor Startup w/period acram bypassed.
  FANAR.E. Kaness State Univ. 78/09/25 9pp. 94063.141
- 7811130127 Responde to 781026 ltr re Dr Eckoff's training & authorizes him to perform licensed duties COLLINB, P. F. Operator Licensing Branch. 78/10/31 lp. 94076:120
- DOGKET 50-193 RHODE IBLAND & PROVIDENCE PLANTATIONS AEC
  P. Operating license stage documents & correspondence
- 7810200017 Forwards Amend#6 to Fecil Oper Lit#R-95-changing Tech Specre U-235 fuel weight limitation REID.R.H Operating Reactors Branch 4 (Pra 790625), 78/10/02. 2pp. 94195/215
- --7810200021 AmendM6 to Fecil LickR-95.chenging Tech Bpec re U-205 fuel weight limitation. REID.R W. Operating Reactors Brench 4 (Pre 790625). 78/10/02. 4pp. 94195-217
- --7810200024 Safety Evaluation Supporting Amend#6 to Fecil Lic#R-95. Concludes that hererds will not increase. • Operating Reactors Branch 4 (Pre 790625). 78/10/02. 3pp. 94195-221.

# DOCKET 50-200 BEN TEST REACTOR

- J. Insurence & indemnity information
- 7809130539 Bigned Amend#18 to Indernity Agreement#B-6. adding new Article VIII re: payment of assessed deferred premiume for subj facils BALTZMAN, J. Antitruet & Indemnity Group. 78/09/01. 2pp.
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT
  D. NRC Dreft/Finel Environmental Statements, supple & correspondence
- 781:100125 Advises that NFS will submit its eval on items addressed in 780627 NRC itr prior to 781016 rether than 780930 ee originally estimated in NF ltr of 780814. CLARK-J R. Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.). 78/09/22. Ip. 94246:337.

#### H. General correspondence

7811280118 NF plans to submit apple for Senoir Operating Lice for D Ploets & C Ross. The addl training will be completed in Feb 1979 & appropriate NRC examinations are requested for March 1979. PIERCE.A.C. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.). 78/10/30. ip. 94013:008.

- 7810170056 Forwards changed papers for incorporation into West Valley Site Rept ROCERS.V C Ford Decom & Davis Utah. inc NRC-02-77-197 78/09/27 10 94214 391
- 7811200219 Presents ARC persenctive & conclusions re specific criterial for decommissioning level waste tanks at subj. facti DSE should lead in dev of disposal option to safely isolate waste should have in-tank solidification scheme HARTIN.J 8 Assistant Director for Fuel Cycle Safety & Licensing 78/10/10 2pp. 94232-099
- --7811200221 "Compilation of the Radioactive Waste Disposal Classification Sys Data Base." Task Rept-analysis of West Valley Site Analyses low-level radioactive caste burial area & high level waste storage tanks using RNDCB methodology of Ford Bacon & Davis Utah. Inc FBDU-247-01 78/09/30 110pp 94752 101
- 7011170233 Responds to 780627 NRC request for review & eval of actions recommended by DuPont re Waste Tank Safety Plans to augment procedure for transfer of waste from insvc tank#8D-2 to spare tank#8D-1 in the interest of greater conservation CLARM.J R Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 78/10/12 9pc. 94048 315
- 7811170045 Notice of 781029 visit to subj facil to observe struc characteristics of plant w/respect to tornado resistance & to acquire info necessary to complete status rept on NRC plant mod review PERSON.L B Fuel Reprocess & Recycle Branch (Pre 790727) 78/10/23 pp. 94048.263
- 7811170037 Summary of 781005 meeting w/Nuc Fuel Svc re dev of info for decome Next rewiing will be 781108 W/encl reference index for Meth Process Plant area HAUGHNEY, C. J. Fuel Reprocess & Recycle Granch (Pre 790727), 78/10/27, 32pp. 94048.212
- 7811280370 Notification of reating w/Nwc Fuel Svc on 701115 in 911ver Spring to discuss prograss of NFS efforts to process aveilable tech info. Needed as basis for future decontamination & decomp of West Valley facil HAUGHEY. U Fuel Reprocess & Recycle Branch (Pre 790727) 78/11/01. 2pp. 94397: 229
- 7811280411 Discusses site visit to subj fecil to obtain head end ventilation sys info for CRNL analysts Detelled flow diegrem of sys was composed by NRC & CRNL analysts & will be used for constructing model for computer analysis CLARKA, 7 Fyel Reprocess & Recycle Branch (Pre 790727). 78/11/01 2pp 94397 326.
- 7B12150058 "W NY Nuc Svc Center Study Final Repl for Pub Comment "
  Presents potentially viable options for dealing w/sub; shut
  down feciltNuc Fuel Svc fuel reprocessing plant) decomm &
  waste disposal-continued nuc use of non-nuc use of facil.

   Energy, Dept. of, 78/11/30, 33pp. 94210.262.
- 7812180114 Notice of 790109 meeting in Silver Byring MD U/Nut Fuel Bycs re info needed to provide basis for Future decontamination & decommissioning of subj Facil.
  HAUGHNEY, C. J. Fuel Reprocess. & Recycle Branch (Pre 790727).
  78/12/04. 3pp. 94130: 323.
- G. Inspection reports, IE Bulletins & correspondence
- 7810300334 Forwards 2 memos & 3 ltrs re Inspec Rept #50-201/72-03 conducted 720919-23 & 720926-29 PAULUS.R C Office of Inspection & Enforcement. Office of the Director 78/10/23 1p. 94270.205
- --7810300338 Responds to 730203 AEC ltr re violetions noted in inspec Rept #30-201/72-03 w/detailed objections to metlers in reptrequests that rept & present ltr be withhled from PDR, since it conteins errors & is not a finel document. MILLER,R N Nuclear Fuel Services, Inc (subs. of Getty Oil Co.). 73/03/12. 9pp. 94270:206.
- --7810300343 Act receipt of 730126 itr informing NRC of steps taken to correct deviations noted in inspec Rept #50-201/72-03. NPLSON,P.R. Region t. Philadelphia. Office of the Director 73/02/05 ip. 94270:215.

- --7810300354 Buggests surprise inspec of subj facil w/subsequent news release to local newspaper or writing a ltr to the local newspaper citing the encl anonymous ltr Bubj facil has been a running sore re plant conditions releases etc HENDRIE. J H Atomic Energy Commission. 72/09/12 3pp 94270 236
- --7810300398 Recommends investigation of subj facil re-working condition careless exposure & working condition of the core.

   Affiliation Unknown 72/09/03 2pp 94270:237.
- --7810300362 Suggests making copy of inspec rept available to local press
  & possibly levying civil penalties
  O'LEARY, J.F. Assistant Director for Licensing 72/09/19 ip
- 7812290076 Forwards IE inspec Rept#50-201/78-08 on 781024-26 during which no items of noncompliance were noted. SMITH.0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 78/11/13 2pp. 94190 076
- --7812290078 JE [naper Rept#50-201/78-08 on 781024-26 during which no liters of noncompliance were noted Areas inspected environ monitoring progret & implementation.
  KOTTAN, J. J. ACKSON, T. J. 8TORR, J.P. Region i. Philadelphia. Fuel Facility & Materials Safety Branch 78/11/13 4pp 94190.078.
- R Periodic operating reports & related correspondence
- 7811270257 Quarterly Rep1 for period Jul 1-9ept 30, 1978 OLDHAM,W A Nuclear Fuel Bervices, Inc. (subs. of Getty Oil Co.). 78/10/30 12pp 94252:352.
- 7812150036 Forwards results & flow measurements for Oct 1978 DEDHAM.H.A Nuclear Fuel Bervices. Inc. (subs. of Octty Oil Co.). 78/11/08 4pp 94210:054.
- DOCKET 50-206 SAN UNDERE NUCLEAR STATION. UNIT 1
- A. Application/construction stage documents & correspondence
- 7810200375 Believes that there is a potential problem w/Class iE battery racks supplied to sub; facil Additionaltion bar for seismic protec util be available for retrofit w/in 60 days. MCMANUB.C.K. ESB, Inc. 78/10/11 ip. 94271:184.
- F. Security, medical, emergency & fire protection plans
- 7810180218 Summary of 780829 meeting re fire protec prog for subj fac11 w/list of attenders & steff positions identifying open items. "Fire Protec Prog. NRC Positions-SCEC Responses encl. BURGER.A Operating Reactors Brench 2 (Pre 790625). 78/09/30 24pp 94421 271
- 7810250142 Following site visit & evaluation of Fire Protec Prog. there are 2 Fire areas critical to shutdown capacity which need add1 fire protec: 4160 volt switchgear room & turbins oil reservoir area.

  DUNNING.T. Plant Systems Branch (Pre 791030). 78/10/12. 10pp.
- 7810230155 Review of fire protec prog for provisional oper lic#DPR-13 re mod to 4160-volt ewitchgeer room (Fire Zone 8) & mod to 10be oil reservoir & conditioner eree (Fire Zone 9A).
  BASHIN.R.P. Southern California Edison Co. 78/10/18 29pp.
- 7810300ili Bummarizes 780915 mesting re fire protec prog for subj fecil. Discussed plans & schedules for facil mods for fire protec. Handout: "Casuelty Procedures to be implemented Following Total Loss of 416)v Buitchgeer." encl. BURGER.A. Operating Reactors Brench 2 (Pre 790625). 78/10/18. 11pp. 74033.219.
- 7811030205 Discusses fire protec plans re subj facils. Before startup, interim mods.casualty procedure for sefe shutdown & improved fire fighting & detection capability will be req. LAINAB.O. Plant Systems Brench (Pre 791030). 78/10/26 2pp. 02/25:317.

- 781 10&0104 Advises that "Casualty procedure're air supply for Lube 0:1 Reservoir & Conditioner Area & "station wall-thru"will be performed in response to 781018 NRC request re fire protec HAYNES. J D Sauthern California Edison Co 78/10/30 2pp 94424; 300
- 781:11:30:297 Review of 78:10:18 submittal relating to fire protects found acceptable cending completion & review of final fire protectmod Conclusions based on util's connitrent to verying that alternate supply of compressed air will be available ZIEMAN-0.0 L. Operating Reactors Branch 2 (Pre 790625) 78/10/31 3pp 94068.131
- 7811250060 Forwards summary of open items on subj facil fire protection as projection to project and Licensee response to encl staff position to required LAINAS.0 Plant Systems Branch (Pre 791030) 78/11/07 9pp 94498:312
- 78110B0105 Informs NRC that rev of physical security plans will be Fubmitted by 781120 due to additine requirement HAYNES.J 0 Southern California Edison Co 78/11/08 ip 74399: 137
- 7812050059 Forwards surmary of open items in NRC review of fire protecting for subj facilizes staff position PF-27A re concern W/Cable Spreading Area" & add1 staff position PF-51
  "Containment" Requests response to staff position by 781127
  2 IEMANN.D.L. Southern Celifornia Edison Co. 78/11/17 5pp
  94-272:227
- 7812010142 informs NRC that SCE has established liaison w/US Marshall Svc & US Marine Corps in order to repei criminal attivity or sabotage should its own security forces be unable to contain such acts Encl 780814 Itr is w/held from pub disclosure PIODYT.O R Chickering & Gregory 78/11/22 ip 94418.084
- 7812050186 States util is unable to submit response to Fire Protec Review questions by 781128 Will submit by 781201 MAYNES. J 0 Southern California Edison Co 78/11/28 ip 94335 175
- 7812050219 Notifies NRC that submission of revisecurity plans will be delayed until 781215 to allow time to incorporate agreements reached u/outside law enforcement agencies. & the methods of protecting against sabotage by the insider HAYES-J 0 Southern Colifernia Edison Co 78/11/29 2pp 943181332
- 7812120101 Responds to NRC staff positions forwarded in 781117 NRC ltr re Fire Protec Prog Review Btaff positions responded to incl: PF-27A. "Cable Spreading Area" to PF-51. "Contactament "BASKIN-R P Southern California Edison Co. 78/12/01 4pp. 94273:020
- 7812220082 Requests review of enclosed and physical security plans and issuance of Socurity Plan Evel Repts Indicating NRC approval. Enclosed sacurity plan documents are proprietary & are w/held IAW 2.790
  MEAD. J T Southern California Edison Co 78/12/19 2pp. 94343.329
- 9 Adjudicatory correspondence
- 7811100047 Forwards Notice of Appearance for C Kocher as counsel for BCE in proceedings re subj facil Cert of BVC encl BEOLETTO, J. A. Bouthern California Edison Co. 78/10/17 3PP. 94178-394
- 7811100048 Forwards Notice of Withdrawal of R Woodbury & D Barry as counsels for SCE in proceedings re subj facil Cert of Svc BEDLETTO.J A Bouthern California Edison Co 78/10/17 3PP. 94178.337
- H Opneral correspondence
- 7811010051 Informs that for SER normal channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged.

  21EMANNO. L. Operating Reactors Branch 2 (Pre 790625). 78/10/10 2pp. 74290 134
- 7812130093 Ack receipt of 781107 natification of change of address CASEY.8 8. Chickering & Gregory 78/31/13. 1p 94294.310

- 7812190150 For all future correspondence w/SCE to sub, facils.RE Woodburg is to be deleted from sec list & replaced by CR Kocher HAYKES.J C Southern California Edison Co 78/12/13 ip 94340 143
- J Insurance & indemnity information
- 7810250037 Forwards Endorsements #66.67.68 to Policy NF-146 & #58.59.60 to Policy NF-146 & #58.59.60 to Policy NF-146 & #58.59.60 to Policy NF-146 & #58.59.60
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 7812060086 Comments on Yera Corp rept "Simulation of Earthquake Ground Motions" Rept is a breakthrough in understanding seismic wave propogation & ground motion characteristics Bhould not be used to provide basic plant design criteria SEED.H B. Affiliation Unknown 78/10/05 2pp 94328 350
- P Operating license stage documents & correspondence
- 7810130236 Natice of Issuance of America'36 to Provisional Oper Lic #DPR-13 on 780925 ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/09/25 2pp 94031 038
- 7810200026 Forwards Amend to License DPR-13, changing Tech Specs by adding requirement for min water level above spent fuel pool max weight to be carried over spent fuel assemblies ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 78/09/25 2pp 94402 020
- --7810200029 Amend 36 to License DPR-13 changing Tech Spec requirement for min water level above spent fuel pool & max weight to be carried over spent fuel assemblies ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/09/25 7pp 94402 022
- --78102C0031 Bafety Evaluation Supporting Amend#36 to 1.1c#DPR-b3.
  Concludes that there is no increased hazard to the country
  or the population
  # Operating Reactors Branch 2 (Pre 790623) 78/09/23 7pp.
  74402 029
- 7810110096 Atk receipt of 780817 NRC ltr requesting comments on staff evaluation of Bystematic Evaluation Program for subj facil Comments incl HAYNES, J.O. Southern California Edison Co. 78/10/03. 4pp 94065-356
- 7810250012 Requests add1 info on deviations in proposed change # 75 to Tech Specs re insectinspec for steam generators & proposed Tech Spec for eddy current tests or gaging to monitor generator tube dents
  ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/10/10
  4pp
- 7810230105 Info sought by N9C itr of 780906 re environ qual of safety-related elec equip will be provided by 781127 HAYNES.J G Southern Colifornia Edison Co. 78/10/13. Ip 94165:148
- 7810300068 Burmary of 781006 meeting w/util to discuss SEE program Bummary of util/TERA presentation & attendee list and 1 DAVIS.D K Systematic Evaluation Programs Granth (Pre 790625) 78/10/16 33p 94034-241
- 78:1020053 Forwards BER supporting acceptance of postponement of certain permanent ECCB single failure fire at subj facil Mod incl installation of redundant undervoltage relays. Installation of a redundant valve.& redundant control pur 21EFANN.D. Deparating Reactors Branch 4 (Pre 790625) 78/10/14 3pp. 94335 229.
- --7811020059 SER supporting Amend #25 % acceptance of postponement of cartain permanent ECCB Single Failure Fires at subj facil Postponement of installation of redundant undervoltage relay is not acceptable as discussed

  \*\*Office of Nuclear Reactor Regulation, Director 78/10/16.
  10pp 94353.222
- 781023026B Forwards list of add1 studies re Site Specific Earthquake prop of sub; facil w/understanding that Site Specific earthquake response spectra dev by TERA will be the basis of seismic reevaluation of sub; facil.

  BASKIN.K P Southern California Edison Co 78/10/18 4pp. 94271-142

- 781030009B Un 78091B sched retraival of settling plates round both primary & bath-up plates damaged. Problem has been regettive over 3 years & is attributed to marins studies. Proposes request to delate studies READ. J T Southern Celifornia Edison Co 78/10/18 2pp 94035 070.
- 7810310132 Forwards proposed Tech Spec which has been med to provide add1 info requested in 781010 NRC ltr. Add1 info pertains to images to monitor tube denting & imperfections at antivibration bar intersections.

  BARKIN.K.P. Bouthern California Edison Co. 78/10/24 10pp. 74090: 144
- 7810250056 Forwards results of BCE examination of facts defining subj fact) in each topic assessment for 3 BEP topics so requested in 780911 NRC ltr.
  HAYNEG.J.G. Southern California Edison Co. 78/10/25. 3pp.
- 7811100141 Requests add1 info on ESF Buitchover from Injection to recirculation mode: solation of reactor protectes from non-safety sys. ESF sys togic & design, specific drawing of size typ. & complete plant elec frawing indicas w/antl. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625) 78/10/26 3pp.
- 7811070243 Responds to NRC request to justify changes in the following physics startup tests:HZP Critical Boron Concentration.HZP Control Bank Worth Acceptance Criterie.Low Pur Core map. Fowar Coefficient & Pur Defect test.
  HAYNES.J.O Bouthern Csiifornia Edison Co. 78/10/27. 3pp.
- 78:11:7005: Forwards draft aval of 2 8EP topics.radiological consequences of steam generator tube failure & of main line failure outside containment. Concludes that subj facil 1s safe re both possibilities.
  21EMANN.D.L. Operating Reactore Branch 2 (Pre 790625). 78/10/29. 10pp. 94046.23B.
- 7811060086 Repts insertion of a Containment Spray Sys notice Inspected requirement in Section 4.2 of Tech Space. "Bafety Injection & Containment Spray Sys Periodic Testing."

  BABKIN-K.P. Southern California Edison Co. 78/10/30. 2pp 94424: 080.
- 7811140053 Forwards Amend#37 to Provisional Oper Lic#DPR-13-changing Tech Spac re Cycle 7. 21EMANN-D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/31. 3pp. 94420-223.
- --7811140055 Amend#37 to Provisionsi Oper Lic#DPR-13.changing Tech Spec re Cycle 7 oper. ZIEMANN, D. L. Operating Reactors Brench 2 (Pre 790625). 78/10/31. 20pp. 94420.22b.
- --7811140057 Safety eval supporting Amend 37 to Licensa DPR-13. Amend dose increase safety risk.
  ZIEMANN, D.L. Dparating Reactors Granch 2 (Pre 790625). 78/10/31.
  16pp. 94420:251.
- --7811140063 Notice of Isauance of Amend#37 to Provisional Oper Lic #EPR-13, changing Tech Spacedeletes Lic Conditions 3.E.3F(1) 3.F(2):re steam generator inspec & cycle 7 core.
  ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790623). 78/10/31.
  Zpp. 94420:268.
- 78i1280007 Initial study mapt for constr & open of a single circuit 230 KV transmission line from subj facil to Encine Generating Btation in San Diago County, CA. Wichnel Environ Data Btatsment & Addendum&1 to EOS re cultural resources.

  a Ban Diago Gas & Electric Co. 78/11/08. 237pp. 02726:003.
- 7811210316 Forwards corrected part(f) of 770922 sd61 info re control room operator doses.
  HAYNES-U.G. Southern Celifornia Edison Co. 78/11/14. 2pp.

94488: 053.

- 78i1210377 Based on review of subj model Tech Spec submitted by 780711 NRC ltr.3 NRC computers would be needed to calculate model parameters. Since computers are not now available, lic amend tequested w/in 120 days of 780711 ltr will not be submitted. HAYNES.J. 9, Southern Celifornia Edison Co. 78/11/14. 2pp. 94485; 147.
- 7811320146 Responds to 780718 NRC ltr requesting comments on rept re 780524-25 sits visit. Finds five incorrect tech details in rept & re-syc water reservoir & sawell constr. MAYNEB, J. O. Southern Celifornia Edison Co. 78/11/14, 2pp. 74074:337.

A. Station Sattery Test Req. Requests they be transmitted to licensess. DAVIS.D.K. Bystematic Evaluation Programs Branch (Pre 790623), 78/11/14 23pp

ABITEDOADO LOLMELOR

- 7812150197 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attandess to facilitate sending out mail Wisnel Registration Form & List of Locations.
  MILLERUJR. Assistant Director for Site & Befaguards (Pre 791030). 78/11/15. 5pp.
- 7812190057 Forwards Ray#1 "Draft Radiological Effluent Tech Space" for PHR's(NUREO-0473) & "Preparation of Radiological Effluent Tach Space for Nuc Pur Plants" (NUREO-0133).

  GRIMES:B.K. Assistant Director for Engineers & Projects (Pra 790&25) 78/11/15. App. 94215/083
- 7812040007 Forwards Amend #38 to License DPR-13. safety evaluation & notice of issuance.
  71EFANN, D. L. Operating Reactors Branch 2 (Pre 790623). 78/11/17.
- --78:2040012 Amend#38 to Licenss DPR-i3, changing Tech Space of combined heat up. cooldown & pressure limitations, reactor coolent sys, radioactive gasebus waste release, fire protec sys surveillance & radio environ monitoring.

  ZIEMANN. D L. Operating Reactors Branch 2 (Pre 790625). 78/11/17. 170p.
- --7812040017 Safety evaluation Supporting Amend#38 to Oper Lic#DPR-i3.

  Supports issuance of amend which would reduce maximum allowable rates for preseurizer heatup.

  \*\*Office of Nuclear Reactor Regulation, Director. 78/ii/17. 4pp. 74323.342.
- --7812040020 Notice of Issuance of Amend#38 to Lic#DPR-13 Rev Tech Epect to reduce maximum allowable rate for presentizer hashup: to increase maximum ellowable rate for presentizer cooldown & to daleta provisione of Respiratory Protec Prog. WAMBACH.T.V. Operating Reactors Brench 2 (Pre 790625). 78/11/17. Zpp. 94325:346.
- 7811280219 Responds to 770926 request for evel of potential boron dilution accident at subj facii, Concludes sys in subj facii has no potential for return to criticality & that except for Chem & Volume Control Bys-no 1 event can cause such failure. BASKIN.K.P. Bouthern Cailfornia Edison Co. 78/11/20. 2pp. 94012:088.
- 7811280245 Follows up 761116 rept re failed thermal shiald flaxures in 4 of 6 supports 1978 inspec found 5 of 6 flaxures cracked. Believes situation does not affect continued oper & plans no corrective action. HEAD, J. T. Bouthern Celifornia Edison Co. 78/11/21, 2pp. 94012:160.
- 78;1280212 NRC's staff snviron qual tables for SEP Topic III-12, Environ qual of Bassty Related Elec Equip will not be available for submitted until 78:1218.

  HAYNEB: J. 9. Bouthern California Edison Co. 78/11/22. ip. 94012: 129.
- 7811280229 Submits proposed mods to air supply sys of subj facil. Mods will ensure evaluability of air supply to req equip after loss of main air header due to fire in lube oil reservoir & conditioner area.

  3ABKIN.K.P. Southern California Edison Co. 78/11/22. 2pp. 94395:001.
- 7812130136 Forwards for raview draft NRC avais (BEP), "Thermal-Overload Protec for Motors of Motor-operated Valves & & SEP Battery Capacity Tasts." ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/11/24. 7pp. 94305:108.
- 7812110056 Discusses possible dengers of LDCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.W/encl ANC: w7612080007.
  21EPANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Gpp. 74408:256.
- 7812140292 Forwards AmendW39 to Provisional Open LicWDPR-13, revising Tack Space as requested in 780717 ltr. ZIEMANN.D.L. Operating Reactors Stanch 2 (Pre 790625), 78/11/30. 3pp. 03958:017.

- --7812140304 Amend#39 to Provisional Uper Licemper 13. Tev ista aper re certain provisions in Sections & & 5 (Admin Controls) of Append A&B. respectively, to reflect new corp & station org struc. & to increase ensite review come members 2 (Pre 790625). 78/11/30. 16pp. 03558.020
- --7812140308 Notice of issuance of Amend#39 to Provisional Oper Lic#DPR-13 on 781130 71EHANN, D. L. Operating Reactors Branch 2 (Pre 790625) 78/11/30. 200 03558: 038.
- 78:228007: Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants info submitted must be substantiated by data & calculations Licensee must notify NRC of any ineccuracies or enforcement action will result.

  DAVIS.J O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp 03999: IBB
- 78:2140299 Requests addi info re pips breats inside containment. Forwards itr summarizing current criterie re pips breaks for BEP Plents Operating Reactors Branch 2 (Pre 790625) 78/12/07 21EMANN. D. L. 0
- --7812140311 Forwards "Sys Evel Prog for Assessment of the Effects of Postulated Breaks in Fluid Sys Piping Inside Containment" which provides guidence for selecting design locations & orientations of postulated breaks.

  DAVIS.D.K. Systematic Evaluation Programs Branch (Pre 790625). DAVIS D. K. Systematic Evalu 78/07/20. 13pp. 03556:285.
- 7B12200132 Forwards results of SCE examination of facts defining sub; facil in NRC topic assessments
  HAYNEB.J Q Southern California Edison Co. 78/12/07 3pp. 94156.299
- 7812210018 Forwards NUREG-0485. Vol 1. No 2 "Status Bummary Rept-Sys Eval Prog " W/o enci. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94249: 335.
- 7812270046 Requests addi info to complete review of Topic Vill-4 "Elec Penetrations of Reactor containments." Info inci-circuit & sisc penetration info ZIEMANN, D. L. Environmental Projects Branch 2. 78/12/08. 4pp. 94160: 251
- 7812270196 Forwards Summary of Physics Startup Tests conducted from 781031 to 781111. Comparison of measured values W/pradicted values were w/in limits of Raviau & Acceptance Criteria egreed upon w/NRC staff. OTTOSON.H.L. Southern California Edison Co. 78/12/15. ip
- --7812270199 Bummary of Physics Startup Tasta conducted from 781031 to 78111, Parformed Rod Drop Time Test. Hot Zero Per Physics Test & tast of Per Escalation. Companison of massured & predicted values w/n limits of Ravise & Acceptance Criterie Southern California Edison Co. 78/12/11. 3pp. 94017:205
- 7812270165 Equip snviron qual tables forwarded 780906.will be completed & forwarded by 790122 Dalay caused by sfforts to meet NRC schaf requirements on other projects incl subj facil Physical Sacurity & Fire Protec Progs. RAYNES, J. O. Southern California Edison Co. 78/12/18 Ip. 94018: 087

#### O inspection reports. IE Bullatins & correspondence

- 7810300018 Forwards IE Inspec Rept#50-206/78-11 on 780814-15 during which no items of noncompliance were noted. BOOKUH.E. Region 5. Ban Francisco, Fuel Facility & Materials Befaty Branch. 78/09/07. 2pp. 94034:347.
- --7810300020 IE Inspec Rept#50-206/78-11 on 780814-19 during which no tems of noncomplience were noted. Major arest inspecially intensive tems of noncomplience were noted. Major arest inspecially included insutron monitoring prog. refueling outage planning & training & post emergency exercise activity.

  BOOK.H.E., CURTIS.J.R. Region 5. Ben Francisco. Fuel Facility & Heteriels Befety Brench. 78/09/07. 3pp. 94034:349.
- 7810230320 Forwards 1E Circuler#78-17. (See AND: 7810230221. Docket 50-313, 781013) ENGLKEN, R. M. Region 3. San Francisco, Office of the Director. 78/10/13. 1p.

.. KEPOICE DE STEAM GEMEN COM VII Refueling Outage" Results support request for lic amend to delete req to bring facil to a cold shutdown condition to perform inspec MAYNES, J G Southern California Edison Co 78/10/25. 200 94053, 137

AGIOS/OSIA LOLMALO?

--7810270216 "Results of Steam Generator Inspec Prog for Cycle VII Refuzling Outage" Presents results of completed overall inspec prog-corrective actions taken & conclusions based on

. . . . . .

7810190135 Fowerds IE Inspet ReptsH50-206/78-12, 780906-08 during without of noncompliance were noted IE rept withheld subj to 2 790.

\* Bouthern California Edison Co. 78/10/23 90pp 94033:139.

NORDERHAUG, L. R. Region 5, Ben Francisco, Befsguarde Branch 78/10/04. 2pp 94414:043.

results re continued plant oper

- 78:2150180 Forwards IE inspec Repts#90-206/78-16 on 78:1016-19 durin uhich no items of noncompliance were noted BOOK.H.E. Region 5. Sen Francisco. Fuel Facility & Materials Gaf-Branch. 78/11/03. 2pp. 94212-201
- --7812150185 IE Inspsc Repts#50-206/78-15 on 781016-19 during which itsms of noncompliance were noted. Major areas inspected inclinadiat protec prog during refueling outage & followup activity CURTIS,J.R. Region B. San Francisco, Office of the Director 78/11/03. Spp. 94212:283
- 7811130019 Forwards 1E Circular 78-18 ENGELKEN.R.H. Region 5. San Francisco. Offics of the Director. 78/11/06 ip. 94111:221
- 7812070283 Forwards IE Inspec Rept#50-206/78-13 on 780921-28.1012-1 1016-18 during which no items of noncompliance were noted. CREWB.J.L. Region 5. Ban Francisco. Office of the Director. 78/11/08. 2pp. 94085-215.
- --7812070296 iE inspec Rept#50-204/78-13 on 780921-28,1012-13 & 101 during which no items of noncompliance were noted Major areas inspected incl:local last rate tests refueling preparations & oper.maintenance activities & LER's.
  WCESONER.J., CANTER.H., HDRN.A Region 5. Ban Francisco, Offic
  the Otractor. 78/11/07. 6pp 94080:217.
- 78:2210376 Notice of Violetion from inspec on 781010-13 & 1024-27. a Region 5. San Francisco, Reactor Construction & Engineering Bupport Branch, 78/11/13. 2pp. 94015:040.
- --7812210380 IE Inspec ReptsW50-206/78-14 on 781010-13 & 1024-27 du which i item of noncompliance was noted feilure to perform nondestructive siam of vessel closure stude & nuts IAU requirements of ABME Code. PATE R. J. . HAIBT D. P. Region 3. Ben Francisco. Reactor Construction & Engineering Support Branch. 78/11/13 94015.042.
- --7812210388 Responds to 781115 NRC itr re violations noted in Insp Rept#50-206/78-14 Corrective actions: a calibr block equipped w/refisctors has been obtained & prog to eval equivalence of technique initiated.
  MODRE, J. B. Southern Celifornie Edison Co. 78/12/06. 2pp. 94015:050.
- --7812210399 Ack receipt of 781206 itr informing NRC of steps takes correct violations noted during inspec 850-206/78-14. BPENCER, Q.B. Region 5. San Francisco. Reactor Construction & Engineering Support Brench. 78/12/14. 1p. 94015:053.
- 7812210370 Forwards iE inspsc Rspt#50-206/78-14 on 781010-13 & 1024 & Notice of Violation. SPENCER.O. S. Region 5. Ban Francisco. Reactor Construction & Engineering Support Brench. 78/11/15. 2pp 94015:038.
- 7811300097 Forwards IE Builetin #78-12A. suppl to IE Bulletin 78-12. W/encl ANG 7811300055. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 78/11/24. 19. 94073:035.
- 7812290098 Forwards 1E Bulletin 78-14 ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director. 78/12/19. ip. 03695:192.
- R. Periodic operating reports & related correspondence
- 7810130159 Forwards Monthly Open Rept for Bept 1978. CURRAN. J. M. Bouthern California Edison Co. 78/10/02. 1p. 94002: 348.

94002: 349.

- 7811160000 Forwards Monthly Open Rept for Oct 1978 CURRANIJ M. Southern California Edison Co 78/11/06 ip. 74130:177
- --78iii60082 Monthly Oper Rept for Oct 1978 QON.D.M. R. Bouthern California Edison Co. 78/11/02. Spp. 94132:176.
- 7812190157 Forwards Monthly Open Rept for Nov 1978. CUBRAN-J. M. Southern California Edison Co. 78/12/06. 1p. 94340: 161.
- --7812190159 Monthly Oper Rept for Nov 1978.
  GCULD, W. Southern California Edison Co. 78/12/05. Spp.
- B. Reportable occurrences, LERs & related correspondence
- 7810180089 Data from bottom & midwater temp sentors desmed irretrieveble due to instru malfonctions Instrus replaced & personnel admonished re importance of deta retrieval No environ impact caused by loss of date. HEAD.J.T. Gouthern California Edison Co. 78/10/13 2pp. 74400: 239.
- 7010180197 Details reportable occurrence at subj facil. During heat treatment on 780913.2(89) lbs of fish impinged-80% of which were apoctin croakers. Occurrence not deemed to have effect on local soptfin croaker population. HEAD.J.T. Southern Californie Edison Co. 78/10/13. 2pp. 94317:015.
- 7810250123 Repts occurrence per Section 5.6 3.4(3) of Append 8 to Provisional Oper Lic DPR-13. During retrieval of settling plates, both primary & backup settling plate racks were found to be severely demaged in Zone OA. Has no environ impect, HEAD. J. T. Southern Celifornia Edison Co. 78/10/18. 2pp. 74368: 312.
- 7812130280 During Insvc Inspec Teet of these support 4 snubbers, two weld indications were found which rsq repair 8 during snubber surveillance two snubbers feiled. LER will be forwarded. CURRAN, J. M. Southern Celifornia Edison Co. 78/10/24. 2pp. 94279: 395.
- 7811140177 Forwards LER#78-011/01T-0. MODRE.J.B. Southern California Edison Co. 78/11/06. 3pp. 94398: 240.
- --7811140181 LERN78-011/01T-0 on 781023: during shock & sway test: 9 shubbers were found to be inoperable & during insyr test: 4 had cracked weids. Shubber fellures & cracked attachment walds are attributed to operating transients. CURRAN-J.M. Southern California Edison Co. 78/11/06. 2pp. 94384:251.
- 7811280277 Forwards LER#78-012/03L-0. MEAD J.T. Southern California Edison Co. 78/11/2:. 2pg. 94395:216.
- --78:128028: LERN78-0:2/03L-O on 78:023: seal water return line(#2014) & the discharge line(#2002) of the charging pumps dev through well cracks due to chloride etrese corrosion. Affectsd areas replaced w/new pipe & fittings.
  CURRAN. J. M. Bouthern California Edison Co. 78/11/09. 1p. 74393: 218.

#### V. Operator Examinations

7811130132 Responds to 781011 & 24 ltrs describing training Cyrus K Anderson received in order to qualify for resumption of likensed duties. Authorities resumption. COLLING, P. F. Operator Licensing Branch. 78/10/31. ip. 94076:149.

### DDCKET 60-213 HADDAM NECK PLANT H. General correspondence

7810310021 Informe that for BEP normel channel of drai communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of BEP branch is encouraged.

21EMANN,D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/10.

2pp. 94094:241.

- 7812180142 Forwards copies of insurance Endorsement#57 which amends the site description at subj facil affective 781117.
  8E0GR.R. Connecticut Yankee Atomic Power Co. 78/12/13. Ip. 94365:274.
- --7812180151 Insurance Endorsement#57 of Policy#WF-151 Forwards new site description of subj fecil BARDES,C.R. Nuclear Energy Liebility Insurance Association. 78/11/17. 2pp 94365:275.
- P. Operating license etage documents & correspondence
- 78iii30064 Forwards initial eval of 8 complete SEP topics & response to request for clarification of SEP documentation procedures made at 780531 meeting Requeste response re facts used to define plants by NRC staff. (See ANGW78iii30037.)
  EIBENRUT, D. 0. Assistant Director for Systems Engineering (Pre 791000). 78/00/17. 2pp. 94076:227.
- 7810270404 Forwards Amend #2B to Facil Open Lic #DPR-61, changing Tech Spec re fire protec sys.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/03.
  3pp.
- --7810270410 Amend#28 Lic#DPR-61, chenging Tech Spec re fire protec sys is subj fecil.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/03.
  iipp
- --7810270413 Safety eval supporting Amend 28 to License DPR 61. Amend dor not increase safety risk b Operating Reactors Brench 2 (Pre 790625). 78/10/03. 49pp.
- --7810270417 Reviews fire protec in operating nuc pur station.
  Re-evaluation of fire protec prog resulted in identifying areas of pient in which fire could have undesirable effects on safe shutdown of reactor.
  HALLR.E. Brookhayen National Leboratory. 78/05/10. 3pp.
- --7BiO270422 Notice of issuence of Amend#28 for Lic#DPR-61, changing Tech Bpec re fire protec sys. 21EMANN.D.L. Operating Reactors Branch 2 (Pre 770625). 78/10/03. 2pp.
- 7810260182 Bubmits rept re subjutil test prog on the containment of elec penetrations et subj facil. Sefety related elec penetrations endified by Reychem heat-shrink tubing would qualify for the next 2 years.

  COUNSIL. W. O. Connecticut Yankes Atomic Power Co. 78/10/10. 9pp. 94057-298
- 7810260171 Forwards addl info re main eteam line break to support request for emend to Tech Spece. Concludes that charging pump flow is not required for remainder of the present cycle.

  COUNGIL, N. O., FEE. M. F. Connecticut Yankee Atomic Power Co. 78/10/20. Spp. 94037:273.
- 7810300125 Notice of 781026 meeting w/CT Yankee & other util using Carborundum-supplied boron-carbide. Carborundum to present statue of their test prog for poison plates.

  HAMBACH.T.V. Operating Reactors Branch 2 (Pre 790625), 78/10/24.

  2pp. 94035:145.
- 7811070302 Forwards Amend#29 to Fact Oper Lic#DPR-61.delsting lic condition C(3)issued in Amend#26 dtd 780526. & rev Tech Spec re main steam line brack reanalysis.

  ILEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/24.

  2pp. 94041:001.
- --7811070307 Amend#29 to Fecil Oper Lic#DPR-61, changing Tech Bpecs remain steam line break reanalysis.
  ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/24.
  10pp./. 94041:003.
- --7811070311 Bafety eval supporting Amend 29 to License DPR-61. Amend do not increase safety risk.

  \* Operating Reactors Branch 2 (Pre 790625). 78/10/24. 5pp. 7404t:013.
- --7811070313 Notice of Issuance of Amend#29 to Facil Oper Lic#DPR-61.
  deleting Lic Condition C(3) of Amend#26 & rsv Tech Spec re
  main steam line break reanalysis.
  ZIEMANN.D.L. Operating Reactore Branch 2 (Pre 790625). 78/10/24.
  20p. 94041018.

- 7811030097 Forwards index of elec schematic drawings for subj facil. Also forwards accompanying aperature cards index & cards of supplemental frawings submitted on 780929 & safety-related drawings re subj facil evailable in CF. COUNDIL H.O. Connecticut Vankes Atomic Power Co. 78/10/27 3pp. 02721:370.
- 78iii30i93 Forwards "Boron Carbida" rept prepared by Carborundum Codescribing requal prog teets & results re sub; facile
  Answers to NRC queries & other analyses are also encises is
  non-proprietary version of Carborundum rept.
  COUNSIL-M. Q. Northeast Utilities. 78/11/03. 14pp.
- 7811140193 Diacussas Progress of NUSCO Nuc Records Prog for CN Yankee Atomic Pur & NE Nuc Energy Co Microfilming may not be completed by 790731, but hard copy will be available Aske whether projected 790731 date will be satisfactory.

  COUNSILW.O. Northeast Utilities. 78/11/06 29p. 94383:304.
- 7811170217 Requests that submittal date for lic amend appl be changed from 781108 to 790130. Amend usis incorp NRC Draft Append i Tech 8pscs.
  COUNSIL.H. O. Connecticut Yankee Atomic Power Co 78/11/08 3pp. 94135: 124
- 78i1270i32 Forwards tabulation of data re environ qual of sefety-related elac equip(SEP Topic III-12)for review & completion by licenses ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/11/09. 99p. 94271:290.
- 7811170208 Provides further info on proposed exemption from 10CFR50 Append J re test of continuous Air Monitoring Bys(CMS) as proposed by 770311 NRC Jtr. Util proposes to commence alternated testing bys after 1979 refueing outage.
  CDUNGIL-M.Q. Connecticut Yankes Atomic Power Co. 78/11/13. 2pp. 74134:099.
- 76:1280430 Forwards draft Bys Eval Prog Bafety inputs re Topic Vilin3. A. Station Dattery Test Req. Requeste they be transmitted to licensess. DAVIB.D.K. Bystematic Evaluation Programs Branch (Pre 790625). 78/11/14. 23pp.
- 7812180039 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR/3. Requests pre-workshop registration of attendees to facilitate sending out mati. W/encl Registration Form & List of Locations.
  MILLER.J.R. Assistant Director for Bite & Bafeguards (Pre 791030).
  78/11/15. 5pp. 94133:036.
- 7812190025 Forwards Revei "Draft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Radiological Effluent Tack Specs for Nuc Per Pients" (NUREO-0133).

  GRIMESIS K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:314.
- 781:300212 Reports on fish impingement overruns for 3 species of fish exceeding ETS limits for month of Oct. No apparent cause is known, but no trend toward increased impingement is discerned.

  ORAVES-R. H. Connecticut Yankes Atomic Power Co. 78/11/16. ip. 94073-220
- 7811270183 Responds to 780817 request for comments on Systematic Evai Prog topic assessments. Info is substantively correct, but it is suggested that these & future assessments be written w/ specific ref to documents used by NRC to form conclusions. COUNSIL, H. O. Northeast Utilities, 76/11/20. ip. 94272:081.
- 7812040198 Rept of BEP reviewers visit to subj facil on 780913-14 for familiarization. Consisted hydrological review of site & region outside the site & control room safety sys outside containment. H/list of participants.
  FONTECILLAH. M. Bystematic Evaluation Programs Branch (Pre 790625). 78/11/21. dpp. 94457:129.
- 7812070134 Notice of spminar on 781208 on new Model Radiological Efficient Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet, Proposed Agenda & maps. GRIER, B. H. Region 1, Philadelphia, Office of the Director. 78/11/21. Spp. 74376:200.
- 7812060303 Notification of 781207 meeting w/SEP Owner's Group in Bethesda.MD to discuss plans to address seismic input for use in SEP seismic review.
  LEVIN.H.A. Systematic Evaluation Programs Branch (Pre 790625).
  78/11/24. 2pp.

- 7812140033 Mat) on file is insufficient to allow tech eval re pipe breaks inside containment at subj facil. Requests mosting to allow companison of piant design to current criteria & to eval significance of potential deviations.

  EIBENHUT, D. O. Assistant Director for Systems Engineering (Pre 791030). 78/11/28 3pp. 94127-251.
- --7812140038 Discusses assessment of postulated pipe breaks inside reactor containment. H/enc1 SEP outline of 3 potential approaches for postulating pipe break locations.

  DAVIS. D. K. Systematic Evaluation Programs Branch (Pre 790625).
  78/07/20 13pp. 94127-254
- 7812110041 Discusses possible dangers of LOCA in containment purging during normal plant open. Requeste either commitment to linit purging or justification for continuing. Hyenci ANO: #7812080207
  ZIEMANN. D. L. Operating Reactors Branch 2 (Pre 790825). 70/11/29. Gpp. 94408:171.
- 7812050134 Bubmite ETS/NR 78-12 re rato of change of discharge temp. On 7B1102-reactor trip occurred during surveiliance texting of pressurizer pressure & level six week setpoint check. B degree F rate of change limit exceeded No harm discerned ORAMEB.R.H. Connecticut Yankee Atomic Power Co. 7B/11/30 1p. 94335.036.
- 7812210101 intends to apply GA prog to edd1 requirements of 10CFR71 to transp or delivery for transp.of mati outside site confines in Comm approved package design.
  CDUNBIL.H.O. Connecticut Yankas Alomic Power Co. 78/12/05. 1p. 94267: 208
- 7812280i12 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIG. J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/06 2pp. 94310:209.
- 78:2:30093 Requeste add1 info from SEP licensess re elec penetrations of reactor containments in order to complete eval.
  ZIEMANN.D.L. Operating Reactore Branch 2 (Pre 790625). 78/12/OB.
  4pp. 942:12:002
- 7812210082 Forwards NUREG-0485.Voi 1.No 2 "Status Summary Rept-Sys Evai Prog." W/o enci. ZIEMANN.O.L. Operating Reactors Stanch 2 (Pre 790625). 78/12/08. 2pp. 94269:130.
- 7812220061 Notifies NRC that 24-hour sample of fish impingement baskst for 781112 was accidentally discarded & lost. GRAVES,R H. Connecticut Yankee Atomic Power Co. 78/12/13. ip. 94342-264.
- 7812270106 Bummary of 781107 meeting re geology, geotechnical & seismic review. Discussions focused on Systematic Eval Prog topics.
  LEVIN.H.A. Systematic Evaluation Programs Branch (Pre 790625), 78/12/13. 4pp 94161:037.
- Q. inspection reports, if Bulletine & correspondence
- 7810170030 Forwards IE Bulletin#78-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days. & list of iE Bulletins leaved in 1970, (see AND 7810040293) GRIER, B. H. Region i, Philadelphia, Office of the Director, 78/09/29. 6pp. 94242:003.
- 7811100075 Forwards IE Inepec Ropt#50-213/78-24 on 780911-15 during which no iteme of noncompliance were noted. SRUNNER,E.J. Region i. Philadeiphia, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94179;276.
- --7811100076 IE Inspec Rept#50-213/78-24 on 780911-15 during which no items of noncompilance were noted Major areas inspected included: organization & admin, performance of sudits & followup of previous audits.

  LAZARUS, M. J., KNDLL, R. M. Region 1, Philadeiphia, Reactor Operations Nuclear Support Branch. 78/10/04. 13pp. 94179: 278.
- 7811100092 Forwards IE Inspec Rept#50-213/78-25 on 780911-13 during which no items of noncompliance were noted.
  6MITH.O.H. Region i. Philadelphia. Fuol Facility & Materials Safety Branch. 78/10/04. 2pp. 94173:299.

- Items of noncompliance were noted Major areas inspected included emergency drill, emergency planning & environ
- 7811060182 Forwards IE Circuler#78-17 (84e AND: 7810230221, Docket #50-133.781013 1 ORIER. B. H. Region 1. Philadelphia. Office of the Director 78/10/13 1p 94489.142
- 7811300341 Forwards IE Inspec Rept#50-213/78-26 on 781013-16 during which no items of noncompliance were noted.

  SMITH-Q H. Region 1. Philadelphia, Fuel Fecility & Materials Safety
  Branch 78/10/24 2pp. 94115.197.
- --7811300342 IE Inspec Rept#50-213/78-26 on 781013-16 during which no items of noncompliance were noted Major ereas inspected intl.results of effluent sample split between licensee & Region I.Noonsite time involved. KUITAN.J J Region i. Philadelphie, Fuel Facility & Materiels Befety Branch. 78/10/23 App. 94116.199.
- 78:1290216 Forwards 1E Circular #78-18: "UL Fire Test. "W/encl AND. 7811150002 ORIER.B H Region 1. Philadelphia, Office of the Director. 78/11/06 ip. 94237.339.
- 7812150131 Forwards IE Bulletin#78-12A. suppl to IE Bulletin#78-12. W/encl AND 7811300055 RRIER.BH Region i. Philadelphia. Office of the Director. 78/11/24 pp. 94212.169.
- R. Periodic operating reports & related correspondence
- 7810180134 Forwards Monthly Open Rept for Sept.1978

  QRAVES.R. H. Connecticut Vantee Atomic Power Co. 78/10/13. ip 94401:001
- --7810180136 Monthly Oper Rept for Sept.1978

  a Connecticut Yanice Atomic Power Co. 78/10/13 9pp. 94401:002.
- 7810240093 Rept re fish impingement overruns. As of 780929 estimeted 293 & 60 Hagchaters. 0-3° & 3-6°were impinged.exceeding monthly limits. No apparent cause can be releted to plent oper changes Concludes that total numbers were small QRAVES.R.H. Connecticut Yankes Atomic Power Co. 78/10/13. 1p.
- 7811210282 Forwards Monthly Oper Rept for Oct 1978
  CRAYES.R.H. Connecticut Yankee Atomic Power Co 78/11/14. 1p. 94485 205.
- --7811210284 Monthly Oper Rept for Oct 1978 KCKOSZKA.C. Connecticut Yankee Atomic Power Co. 78/11/14. Spp. 94485: 206
- 7812050160 Forwards rev to Monthly Oper Rept for Oct 1978 ORAVES.R. H. Connecticut Yankes Atomic Power Co. 78/11/28. ip. 94335: 106.
- --7812050164 Rev Monthly Oper Rept for Oct 1978. KCKO87KA.C. Connecticut Yantee Atomic Power Co. 78/11/14. 7pp. 94335: 107.
- 7812210201 Forwards Monthly Open Rept for Nov 1978. GRAVES R H. Connecticut Yankee Atomic Power Co. 78/12/13. 1p. 94279: 079
- --7812210204 Monthly Oper Rept for Nov 1978. ANDERSON, D. Connecticut Yanker Atomic Power Co. 78/11/13. Bpp. 94279.080.
- S. Reportable occurrences, LERs & related correspondence
- 7811240163 Notifles NRC of Reportable Occurrence 78-02/1P: QE terminal block in aluminum bo: falled during test of ability to perform under conservative values of voltage temp & pressure w/satureted stem present. Rept to follow.

  16 GRAMES.R. H. Connecticut Yankse Atomic Power Co. 78/03/23, Ip. 94457: 071.
- 7811210378 Forwards LER#78-002/01T-0. GRAVES.R H. Connecticus Yantes Atomic Power Co. 78/04/04. 1p. 94485: 149.

- test of terminal block/box combinations, elec degradation was observed on GE Co termine) block type EB-25 mounted in eluminum terminel box due to contact w/eluminum box FLEMINO, 8 T Connecticut Yenkee Atomic Power Co. 78/0 78/04/04. 20p. 94485 150.
- 7811210308 Forward: LER#78-002/01X-1. QRAVEB.R H. Connecticut Yankee Atomic Power Co. 78/09/25. 1p. 94488 086
- ---7811210311 LERM78-002/01X-1 on 780322 size degradation observed on a GE terminal block type EB & 25 mounted in aluminum terminal box. Failure traced to interfacing w/aluminum boxes Aluminum boxes replaced w/steel boxes. FLEMING S. T. Connecticut Vantes Atomic Power Co. 78/09/25. 2pp. 94488 087
- 7810130166 Forwards LER#78-019/03L-0. GRAVES-R. H Connecticut Yenkee Atomic Power Co. 78/10/06 94003:049.
- --7810130169 LER#78-019/03L-0 on 780909: Alarm indicated #2 high steam flow indicator had failed low. Caused by fuse failure Load reduction started until trip signal put in the logic. Plant load returned to full power & fuse replaced. LEVING, J. M. Connecticut Yantee Atomic Power Co. 70/10/06. 94003, 050.
- 7810250106 Forwards LER#78-020/03L-0 QRAVES.R. H. Connecticut Yenkoe Atomic Power Co. 78/10/17. 1p.
- --7810250110 LERH78-020/03L-0 on 761004: during normal oper, Svc manualauto selector switch on pRRC-401-1 Charging Flow Recorder/
  Controller felled Caused by component end of 11Pa.
  FERGUSON, J. H. Connecticut Yenkee Atomic Power Co. 78/10/16. 2pp.
- 7811060103 Forwards Reportable Occurrence Rept for third quarter 1978 radioactivity in river weter. QRAVEB.R.H. Connecticut Yenkee Atomic Power Co. 78/10/27. 3pp. 94424: 297
- --7811060107 Reporteble Occurrence on 781027: levels of tritium activity Observed in querterly composite of river weter near discharge area exceeded Middletown Control Station by greater than a factor of 10. Caused by seasonal river flow.

  \*\*Connecticut Yentee Atomic Power Co. 78/10/27. 2pp. 94424:298.
- U. Congressionel/Executive Correspondence
- 7810140036 Response to 780911 itr for comments re individuals who are concerned over radioective milk contamination in area neer fecil. Forwards NRC preliminary evaluation of Steinglass rept on Strontium-90 levels in milk near subj facil.

  DIROKS.M.J. Office of the Executive Director for Operations. 78/10/06 2pp. 94329.073.
- --7810140039 Responds to 771115 ltr requesting NRC to svaluate Sterngla rept re strontium-90 & Ceeium-137 in milk from farms near Buby facil. Concludes no relationship between elevated redioactive milk level & subj fecil.
  HENDRIE, J. M. Commissioners, 78/01/18, 2pp. 94329:075.
- --7810140043 Forwards add1 NRC comments by M Goldman re allegation rais by Dr Sternglass concerning levels of strontium & Cestum near subj fecil. Concludes risks from exposure to low level rediat esposure small DENTON,H.R. Office of Nuclear Reactor Regulation, Director. 78/07/27 1p. 94229:082. 78/07/27
- --7810140045 Review & comment of rept by Dr Sternglase re redicectivity health statistics around nuc facil in CT.Finds no support for contention that CT nuc plants have released sufficient radionuclides to cause significant radiat exposure. QCLDMAN, M Celifornie, Univ. of, Davis. 78/05/31. 4pp. 94329; 0B3.
- --7810140048 Review of Dr Sternglass rept. Concludes data doss not suppl contention that nuc reactors have contributed to significent increases in Strontium-90 & Cesium-137 in milk Additionally. rept did not consider effluent monitoring from reactor. COBTLE.D.M. Environmental Protection Agency. 78/08/09. 10pp. 94329: 087.
- 7812050043 Responds to 78103: Itr.Stetes that all present info is so limited that no meaningful comparisons can be made of the level of radioactivity in dairies near sub; facils & dairies in other regions of the State.

  DIRCKS.M.J. Office of the Executive Director for Operations.
  78/11/27. 2pp. 94334:119.

20350044 Ack receipt of sval of Sterngless rapt Requests any NRC or tearngless data indicating redicactivity concentrations of the State.
CDD.C.J. House of Rsp. 78/10/31 2pp. 94334:121.

T 50-219 OYSTER CREEK NUCLEAR POWER PLANT

4C-194 Responds to 780914 NRC ltr requesting inclusion of sarly ning of local auth in facil Emergincy Plan. Plan rev will Completed by 790131. Forwards ltrs of agreement & caduras of detarmining dose received. FRECK, 1.R. Jeresy Central Power & Light Co. 78/11/16. 27pp. 58: 315.

#### Judicatory correspondance

GO 483 Notice of w/drawal of Appearance by E Friedall & Notice of martenes by C Hoodhead as counsel representing NRC in the euby facilia. Cert of Byc and L. EDELL, E. S. HOODHEAD, C. P. Office of the Executive Legal Director. /11/03 4pp.

DOOBS Forwards environ Tech Spec for subj facil, prepared by NRC ff. Applicant has agread to imposition of the spec. Wiencl 311 Order w/Cert of Svc.751114 joint motion to terminate Ting & Tach SpeceNUREG-OASB.
EDELL,E.B., NOODHEAD.C.P. Office of the Executive Legel Director. /11/02. 122pp. 94336:175.

#### meral correspondence

IOO34 Informs that for SEP normal channel of oral communication has followed, but to expedite revisus direct oral meanication between out, facil staff & members of SEP neh le encouraged.

MANN.D.L. Operating Reactors Branch 2 (Pra 790625). 78/10/10, 74074:358.

OO148 Appointment of new licensing mgr for GPU Bvc Corp. LACE, E. G. General Public Utilities - GPU Barvica Corp. 78/10/23. . 94035:115.

#### swrance & indamnity information

BDO66 Forwards copy of endorsement #61 to Nuc Lisbility Insurance ic y NF-164.
EAU.4.N. General Public Utilities - GPU Service Corp. 78/10/04.

40132 Forwards Endorsament#47 to Nuc Energy Liability Insurance ー44 for subj fecil. EA(以, N. Ganeral Public Utilities - GPU Service Corp. 78/10/19

emmating license stage documents & correspondence

SCIOB2 Forwards initial aval of 8 complete SEP topics & response to usest for clarification of SEP documentation procedures a #90831 meeting. Requests response re facts used to imm plants by NRC staff. (See ANO87811130337.)
EMHUT,D.Q. Assistant Director for Systems Engineering (Pra DCSO), 78708/17. 2pp. 94076:339.

60014 Summary of 780428 meeting w/Jereay Centrel Pur & Light recuss Use of Prepreseurized Fuel Rods in Lead Test embly in Suby Reector during Next Fuel Cycle, W/encl list attendage.

1C Mile J. Operating Reactore Branch 2 (Pre 790625). 78/08/21. 94316:291.

CODIO Forwards Notice of Proposed Issuance of Amend to Provisional r LiceDPR-16. Amend would change Tech Spec to rev Maximum rage Flaner Linear Heet Generation Rate limits for Excon I Types IIIE. IIIF. V & VB. \*\*ANN.b. L. Operating Reactors Brench 2 (Pre 790625). 78/09/01. 9417:269.

12 GOO13 Notice of Proposed Issuence of Amend to Provisional Oper Lic DPR-16. Amend would ray Maximum Average Planar Linear Heat erroration Rate limits for certain fuels. Petitions for leave of intervene must be filed by 781011. IEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/09/01. pp. 94179:271.

- 78:01:01:01:8 Forwards add1 info requested by NRC staff re Tach Spec Change Request #49(Rev#1) submitted 7808-05 Concerns core spray line & Feedwater line breaks effects on energies & Tech Spec limits
  FINFROCK: I. R. Jersey Central Power & Light Co. 78/10/03 19pp 94057: 304.
- 7810190045 Concludes tech space should incl limiting conditions for oper & surveillance requirements for hydrogen content & hydrogen monitors in the off gas sys Requests such space be proposed as suppl to 780503 appl 21EMANN.D L. Operating Reactors Branch 2 (Pre 790525). 78/10/03.6pp.
- 7810260018 Confirme understanding that there will be prompt corp review of oneits radiat protec prog par 780809 itr.
  ALLANJ M. Ragion i. Philadelphia. Office of the Director.
  78/10/06 ip. 94410:057.
- 7810160115 Forwards request to amend Tach Spec so that specs will be consistent w/125V DC Mod currently being instelled Tach Spec survaillance requirements will be clarified by amend to conform w/current 125V DC surveillance standarde FINFROCK, I R. Jarsey Central Power & Light Co. 78/10/10. 4pp. 74003 187
- --7810160120 Request for amend to Tach Space re-provisional operating lic #DPR-16. Change would make space consistent w/125V DC mod & w/currant surveillance requirements. FINFROCK, I. R. Jersey Central Power & Light Co. 78/10/10. Spp 94005-1877
- 78:01:60143 Ack receipt of 780807 NRC itr re deficiencies in subj facilinactor protec sus pur supply Continuous surveillance is being performed. Sequence of swants of low probability of occurence.
  FINEROCK, I. R. Jarsey Central Power & Light Co. 78/10/10. lp. 94004:073
- 7810310298 Forwards corrected page 1.05 which incl Section L.R4 & page 1 to make Table of Contents consistent w/contents. ZIEMANN,D. L. Operating Reactore Branch 2 (Pre 790625). 78/10/10. App. 94089:005
- 7810170240 Forwards check for \$12.300 as requested by 790831 NRC staff ltr.Ray of proposed itc indicates it is in Class III insteed of Ciass IV because amond is addressing single lesue & acceptability of it is clearly defined by an NRC position. FINEROCK.I.R. Jersey Central Power & Light Co. 78/10/12. ip. 94242:159.
- 7810240020 Requests Class IV fas JCP&L for request relating to MAPLHOR of several fuel types for subj fact1. W/o encl NRC 780831 to JCPL which le siready on file in PDR.
  HILLER,W D. License Fee Management Branch. 78/10/13. 2pp.
- 7810300157 Appointment of new licensing mgr for QPU 8vc Corp.

  WALLACE, E. Q. General Public Utilities QPU Bervice Corp. 78/10/23.

  1p. 94035:117.
- 7811070304 Notice that util will use the following shipping contelnars: Model#PN600.HN200.HN1008.HN100 series i & 2. FINFRICK, 1.R. Jaresy Central Power & Light Co. 78/10/23. ip. 94041:021.
- 7811030114 In response to 780626 ltr forwards current rays of drawings in order to facilitate BEP Prog review w/ancl index to drawings to 79 oversize drawings. Available in CF only. FINFROCK, 1. R. Jarrey Central Power & Light Co. 78/10/24. 62pp.
- 7BillOli56 Requests addl info on ESF Switchover from Injection to recirculation mode, isolation of reactor protoc sys from nonsefety sys.ESF sys logic & design.epscific drawings of also sys & complete plant else grawing indices.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26. 3pp. 94047:189.
- 7811130335 Surmary of 780914 meeting w/GE representatives & Mark i Owners Group ra programs of Long Tarm Prog w/attendence list & aganda (RD-9-A-Marki, Standards ) GRIFES, C. Plant Systems Branch (Pre 791030), 78/10/26, 67pp. 94007: 225.
- 7B11060164 Responds to 7B0925 itr granting change in reporting date for second 1978 semiannual rept for Nuc Matl Inventory from 7B0930 to 7B1031. One time change is granted because present refueling results in inventory change.

  ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 7B/10/29.

  19. 94489:081.

- 7811220129 Lists containers to be utilized by JCPL for shipment of radioactive matl generated by subj facil Package approval on container has been issued to Chem Nuc Bys.Inc.
  PINFROCK. 1 R Jarsey Centrel Power & Light Co 78/11/08 ip.
- 7811290095 Forwards Amend#33 to Provisional Oper Lic#DPR-16 rev Tech Specs as requested in 780830 Appl w/Sefety Evaluation & Notice of Issuance. ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790825). 78/11/11 2pp. 94238 204.
- --7811290099 Amend#33 to Provisional Oper Lic#DPR-16 rev Tech Specs re MAPLHOR limits for Exton Fuel types 111 E.F.V & VB & adding MAPLHOR multiplier ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625). 78/11/11 1499 94238 206
- --7811290104 Safety Evaluation supporting Amend#33 to Provisional Oper Lic#DPR-16 concluding that proposed changes to MAPLHR limit are acceptable contain adequate safety margins & will not be inimical to health & safety of pub # Office of Nuclear Reactor Regulation. Director 78/11/11 4pp. 94238-220
- --7811290106 Notice of Issuance of Amend #33 to Provisional Oper Lice DPR-16 new MAPLHGR limits ZIEMANN.D. Deprating Reactors Branch 2 (Pre 790625) 78/11/11 Rpp. 94238-224
- 7811280430 Forwards draft Sys Eval Prog Bafety inputs re Topic VIII-3
  A. Bitation Battery Test Reg Requests they be transmitted to
  iicensees.
  DAVIS.D R Systematic Evaluation Programs Branch (Pre 790625)
  78/11/14 23pp.
- 78i1200160 Requests NRC review & approval of Tech Spec change#68 to Append A of Provisional Oper LiceBPR-16. Change util allow for augmented insec inspec of core spray age sparagers & clarify bases upon which core spray ags to operable. FINENDCK, I. R. Jersey Central Power & Light Co. 78/11/15. 1p. 94475 016
- --7811200164 Tech Spec Change Request #68, submitted by JCPL Change afters sections 3 4 & 4.3 re core spray sys Also enci is Repair Proposal #320-78-1 & drewing of spenger repair bracket assembly.

  FINFROCK.1.R. Jersey Central Power & Light Co 78/11/15. 48pp. 94475 017
- 7812150193 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR23 Requests pre-workshop registration of attendees to facilitate sending out math Wiench Registration Form & List of Locations.
  MILLER, J. R. Assistant Director for Bits & Safeguards (Pre 791030), 78/11/15 3ps
- 7812180251 Forwards Ray#1 "Draft Radiological Effluent Tech Spacs" for BWR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) GRIPES.O.K. Assistant Director for Engineers & Projects (Pra 790625). 70/11/15. 6pp. 94365.245
- 7812070209 Notice of seminer on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants. Requests advence submission of seminer specific questions. W/encl Seminer info Sheet Proposed Agenda & maps.

  ORIET, B. H. Region 1, Philadelphia, Dffice of the Director. 78/11/21. 8pp. 03555:120.
- 7811280262 Request for exemption from certain provisions of 10CFR50. Append J. Gen Design Criteria. Mod 760812 exemption request. Covers Types 4.8 & C Test Requirement & exemption requests. FINFROCK-1.8. Jersey Central Power & Light Co. 78/11/22. 16pp. 07174:231.
- 78120604RO Forwards Page 3.10-2 op App A to Yeth Space containing correct LHGR's for Pusi types III E & III F issued w/Amend #33 to LickWpR-16 on 781111.
  ZIEMANN.D.L. Operating Reactors Brench 2 (Pre 790625). 78/11/22.
  3pp. 94084:357.
- 7812080214 Surmary of 781103 meeting to discuss proposed repair of subj facil cracked core spray spanger. Forwards Jersey Central Pur & Light Co's proposed repair of track & list of attendees.

  NOHICKI. S. J. Operating Reactors Branch 2 (Pre 790625). 78/11/22.

- --78]2130345 Amende34 to Provisional Oper LicMDPR-16 W/enc1 Amended Tech Space. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790825). 78/11/24. 6pp. 94307:324.
- --7812130351 Safety evaluation supporting Ahand #34 to Provisional Oper Lic#DPR-16. \* Office of Nuclear Reactor Regulation, Director. 78/11/24. Bpp.
- --7812130359 Notice of issuance of Amend #34 to Provisional Oper Lic #DRR-16 BlLVER.R.D. Operating Reactors Branch 2 (Pra 790529). 78/11/24. 2pp 94307-339.
- 7812080239 Notification of 781130 meeting re difficulty of obtaining reload fuel, possibility of reloading mixed cores from various vendores impact on lic revisus & scheduling NDWICKI, 8 J Departing Reactors Branch 2 (Pra 790625). 78/11/28. 1p. 94137.153
- 7812110066 Discusses possible dengers of LDCA in containment purging during narmal plant oper. Requests sither commitment to limit purging or justification for continuing Wiencl AND: W7812080207.

  W7812080207.

  ZIEMANN, D. L. Operating Reactors Branch 2 (Prs 790625). 78/11/29.
- 7812200116 Ack receipt of 781117 util 1tr to State of NJ containing info on rapair of core spray sparger.
  BRUNNER.E.J. Ragion 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/11/29, 2pp. 94159:110.

8pp. 94338 189

- --7812200276 Ack 781031 request for info re Core Sparger clemping device.
  Info will be released if licensee does not justify
  withholding IAM 10CFR2.790.
  BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear
  Bupport Branch. 78/11/03. 1p. 94139:112.
- --7812200280 Informs util of 781027 State of NJ request for info re Core Sprey Sparger, Unless info is claimed as proprietary IAW IOCFR2,790 in 20 days, info will be released. SRVNNER,E.J. Region I. Philadelphie, Reactor Operations Nuclear Support Branch. 78/11/03. ip. 94159:113.
- 7812110326 Responds to 780510 ltr. Fredwater trip on high reactor level not necessary for safe operation. Forwards eafety evaluation. 21EMANN, D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/30. 2pp. 94204.234.
- --7812110029 Safety Evaluation concluding feasures pump trip on high reactor level is unnecessary for safe operation of facility.

  \* Operating Reactors Branch 2 (Pre 790625). 78/11/30. 2pp. 94204-236.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. 8080N.k.J. General Electric Co. 78/12/04. 11pp. 94103:174.
- 7812280165 Emphasizes importance of submitting accurate & complete info to NRC by liceness & applicants, info submitted must be substantiated by data & calculations. Licenesse must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J.O. Office of inspection & Enforcement, Office of the Oirector. 78/12/06. 2pp. 94374:360.
- 7812150108 Requests add1 info from SEP licensess relector penetrations of reactor containments in order to complete evel.
  21EMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08.
  4pp. 94212:137.
- 7812210095 Forwards NUREG-0485, Vol 1.No 2 "Status Summary Rept-Sys Eval Prog." W/o encl. ZIEMANN.D.L. Operating Reactors Srench 2 (Pre 790625). 78/12/08. 2pp. 94269:160.
- 781227004B Requests comments on SEP Topic V-10.A "Residual Heat Removal Bys Heat Exchanger Tube Feilures." Info inclidatection & control of redioactive leekage, susiliary cooling water dys & primary coolant sys.

  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/13.

  6pp. 94160:255

10. 74010.011

- 7812220108 Bummary of 781130 meeting w/utll to discuss lic requirements of reload submittal using reload fuel from more than I vendor Util requested a future meeting NOMICKI.5 J Operating Reactors Oranch 3 (Pre 790625) 78/12/18 3pp 94344.138.
- 7812270185 Forwards review of qual tables completed to date plus identity of appropriate references & confirmation of accuracy & completenses of the tables FINEMOCK-1 R Jersey Central Power & Light Co 78/12/19 5pp. 94018 001
- G. Inspection reports. 1E Bulletins & correspondence
- 7810250226 Forwards 1E Inspec Rept#50-219/78-21 on 780830-31 during which no items of noncompliance were noted. gRUNNER,E J. Ragion 1. Philadelphia, Reactor Operations Nuclear gupport Branch 78/09/18 2pp 94393 048
- --7810250227 IE Inspec ReptH50-219/78-21 on 780830-31 during which no items of noncompliance were noted Major areas inspected included review of Monthly Statistical Repts & control room tour.

  MCGABL.E.C. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/18 5pp 94093 050
- 7810160243 Forwards IE Bulletin#78-12 "Atypical Weld Material in Reactor Pressure Vissel Welds" requesting action w/in 60 days.b list of IE Bulletin issued in 1978 (Bee ANDW 7810040253) CRICR.B.H Region 1. Philadelphia. Office of the Director. 78/09/29 6pp 94003.315
- 7811060197 Forwards 1E Circular#78-17 (See AND 7810230221.Docket #50-133.781013.) ORIER.# H Region I. Philadelphia. Office of the Director 78/10/13 ip 94489-184
- 78:1080293 Ack receipt of 78:1004 itr informing NRC of steps taken to correct violations noted during inspect50-219/78-20 MITH.0 H Region I. Philadelphia. Fuel Facility & Materials Safety Branch. 78:10/19 10 94406-127
- ~-7811080258 Responds to 780913 NRC ltr re violations noted in Inspec Rept#50~219/78-20. Corrective actions: dosimeters attred in emergency kits will be placed on dosimeter callibr tickler sheet. RCBB.D A. Jersey Central Power & Light Co. 78/10/04 lp. 94406.128
- --78i1080260 Forwards 1E Inspec Rept#50-219/78-20 on 780822 & Notice of Violation CROCKER.H.W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/09/13 2pp 94406:129
- --7811080264 Notice of Violation from inspec on 780822-24.

  4 Region 1, Philadsiphia, Fuel Facility & Materials Safety Branch.
  78/09/13 1p 94406:131.
- --7811080268 IE Inspac Rept#50-219/78-20 on 780822-24 during which I item of noncompliance was noted; Pailure to spike & leak test self-reading dosimsters prior to being placed into svc. DCNALDSDN.D.E. Region I. Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/ii. Bpp. 94406:132
- 7811080229 Act raceipt of 781006 ltr informing NRC of steps taken to correct violations noted during inspects0-219778-19 BRUNRR.E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/20. 1p. 94406-007.
- --7811080234 Responds to 780913 NRC ltr re violation noted in Inspec Rept #30-219778-19. Corrective ections reemphasis of importance of proper classifying of job orders & review of surveillance procedures #KOS, D.A. Jersey Central Power & Light Co. 78/10/06 2pp 94404-008
- --781108023B Forwards 1E Inspec Rept #50-219/78-19 on 780822-25 & Notice of Violation BRUNNER.E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/15. 2pp. 94406:010.
- --7811080242 Natice of Violation from Inspec on 780822-25 \* Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/15. 2pp. 94406:012.

- BAUNACK W H Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/12 14pp 94406 014
- 7812010275 Forwards 1E Inspec Rept#90-219/78-25 on 780926-29 during which no items of noncompilance were noted BRUNNER,E J Region I. Philadelphia, Reactor Operations Nuclear Support Branch 78/10/23 2pp 94417 217
- --7812010276 1E Inspec Rept#50-219/78-25 on 780926-29 during which no items of noncompliance were noted Major dream suspected inclinefueling outage maintenance procedures & follow up of non-routine Event Rept 78-18
  BRIGOS.L. KALMAN,O. Region 1. Philadelphia, Diffice of the Director 79/10/20 &pp 94417 219
- 78:20:0345 Forwards licensee performance evaluation for Region & No operating reactor in Region i is considered to have either abhurmal or unusual safety concern.
  ORIEN.O.H Region 1. Philadelphia. Office of the Director 78/11/01 4pp 944:8 254
- 7811290208 Forwards JE Circular W78-10. "UL Fire Test "W/encl AND 7811150002 GRIER, D.H. Region i. Philadelphia. Office of the Director 78/11/06. 1p 94238 033
- 7812070284 Act receipt of 781024 itr informing NRC of steps taken to correct violations noted during inspect\$00-219/78-22 BRUNNER,E J. Region is Philadelphia. Reactor Operations Nuclear Support Granch 78/11/16 ip 94005
- --7912070288 Responds NRC 781004 itr re violations noted in Inspec Rep 50-219778-22 Corrective actions: snubbers inspected & snubber accumulator oil level corrected RDBS-D A Jersey Central Power & Light Co 78/10/24. 3pp 94085-224
- --7812070290 Forwards 1E Inspec Rept#50-219/78-22 on 760903-07 & Notice of Violation GRIER, B II Region is Philadelphia. Office of the Director 78/10/04 2pp 94085, 227
- --7812070291 Natice of Violation from inspec on 780905-07.

  Region is Philadelphias Office of the Director 78/10/24 lp 94085 209
- --7812070295 IE Inspec Rept#50-219778-22 on 780905-07 during which 2 liems of noncompliance were noted failure to inspect 2 subbers during periodic snubber inspec & failure to failum procedure during snubber inspec & failure to failum procedure during snubber inspec CCLEMAN. W E . KALMAN. O Region 1. Philadelphia. Office of the Director 78/09/28. 7pp 94085 230
- 7812010130 Ack receipt of 781030 ltr informing NRC of steps taken to correct violetions noted during inspect30-219/78-24 BRUNNER.E J. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 78/11/20 ip 94418 061
- --7812010131 Responds to 781006 NRC ltr re violation nated in Inspec R #50-219/78-24 Corrective actions replaced prints wildtest rev in Document Center. Compliance achieved 780922. RDSS.D.A. Jersey Central Power & Light Co 78/10/30 2pp. 94418 062
- --7812010132 Forwards 1E Inspec Rept#50-219/78-24 on 780919-21 & Notic of Violation BRUNNER, E.J. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 78/10/06 2pp 94418:064.
- --7812010134 Notice of Violation from inspec on 780919-21
  \* Region 1. Philadelphia, Office of the Director 78/10/04 lp 94418 Oak
- --7812010136 IE Inspec Rept#50-219/78-24 on 780919-21 during which 1 is of noncompliance was noted failure to use controlled & up-to-date drawings.
  HIGGINS, J.C., MONG, H.J., FOLEY, T., Region 1, Philadelphia, Dffice of the Director. 78/10/04 Spp. 94418.067.
- 7B12150142 Forwards IE Bulletin#78-12A, suppl to IE Bulletin#78-12 W/encl ANG-7811300053. ORIER, B. M. Region I, Philadelphia, Office of the Director. 7B/11/24. p. 94212.196.

- 7810170200 Forwards 1977 effluent release data u/suggested corrections in margin F1NFRCK. I R Jersey Central Pauer & Light Co. 78/10/11 4pp. 74074 747
- 7810220259 Forwards Monthly Open Rept for Sept 1976 ROSS, D.A. Jersey Central Power & Light Co. 78/10/12 ip 94170:029
- --781023026) Monthly Oper Rept for Bept 1978 MCCLAIN, C H. Jersey Central Power & Light Co. 78/10/12 26pp 94170-030
- 7610270097 'Woodborer Btudy Associated U/Subj Facil Generating Station' for 780504 to 780610. RICHAROB. B. R. DELMORE. C. L. HILLMAN. R. E. Battelle Memorial Institute. Columbus Laboratories. 78/09/15 14pp 94039:763
- 7810270094 Forwards copies of "Thirteenth Quarterly Mondborer Study Rept 780305-780810"
  FINFROCK. I R Jerssy Central Power & Light Co 78/10/20 Jg 94059 262
- 7811210239 Forcerds Monthly Open Rept for Oct 1978 ROBS. D.A. Jersey Central Power & Light Co. 78/11/14. 1p. 94497-342.
- --7811210241 Monthly Open Rept for Oct 1978. MCCLAIN.C M. Jersey Central Power & Light Co. 78/11/14 8pp. 9487-343
- 7812200180 Forcards Monthly Oper Rept for Nov 1978 R089.D A Jersey Central Power & Light Co. 78/12/14. 1p 94158 344
- --7812200182 Honthly Open Rept for Nov 1978 MCCLAIN.C H Jersey Cantrel Power & Light Co 78/12/14 6pp 94158.345 .
- 8. Reportable occurrances. LERe & related correspondenca
- 7811090202 Requests info on occurrences of contro) ross failing to fully insert to position. Reply is requested in 30 days. Recommend resint of ongoing tabulation of any addisvents TIEFANN. D t. Operating Reactors Branch 2 (Pre 790625) 78/09/06 2pp. 94038-265
- 7810100070 Forwards LER#78-018/017-0. ROBB D.A. Jermby Central Power & Light Co. 78/09/29, ip. 44033-078
- --7810100075 LERM78-018/01T-0 on 780916: 3 M81vs(N303A.N304A.N3048) had isology rates in excess of maximum allowable due to stam packing, cracked stellite weld & failure of main poppet to seat properly MSIV failures being investigated ROSS, P. A. Jersey Central Power & Light Co. 78/09/29 4pp.
- 781012007) Forwards LERN78-020/03L-0. ROBS. D. A. Jersey Central Power & Light Co. 78/10/05 lp. 448E. 109.
- --7810120076 LERMTR-020/ODL-0 on 780917 Tech Space Table 3.1.1.A.9 violated when Intermediate Range Monator Channel 17 became inoper in addition to IRM Channel 16 which was already inoper due to maint activities performed under react vessel ROSB-0.A Jarsey Central Power & Light Co. 78/10/05 3pp. 94383-110
- 78:0180006 Forcards LERM78-017/03L-Q 8088.0 A. Jersey Central Power & Light Co. 78/10/12. ip. 94422:018
- --78:0180007 LER#78-017/03L-0 on 780914 Circuit brester for motor operated valve tripped when valve closed by isolation signal Caused by corponent failure allowing switch setting to shift. Setting corrected & set screw tightened. RCSS.D.A. Jarsey Central Power & Light Co. 78/10/12 3pp 94422.019.
- 7810240105 Forwards LERN78-019/03L-0.
  ROSS D.A Jersey Central Power & Light Co. 78/10/16 ip.

- chamber air operated vacuum treaters V-26-16 & V-26-18 ware found inoperatio. Attributed to lack of lubrication & apprator linkage misalignment ROSS.D.A. Jersey Central Power & Light Co. 78/10/16 ip
- 7811080100 RD 30-219/78-21/1P on 781017 discovered possible crack in core spray sparger piping, possibly causing loss of redundany in core spray sys. Further investigation being conducted CARROLL, J. T. Jersey Central Power & Light Co. 78/10/18 3pp 94399 0g1
- 7811070105 Responde to 780906 NRC ltr re failure of control rod to fully insert on screw signal. There was 1 such occurrence on 771203 in future such evants will be recorded to anhance data recovery, though no special affort made to date.

  FINEROCK, I. R. Jersey Central Power & Light Co. 78/10/30. 1p 94043-337
- 7811200204 Forwards LERM-022/03L-0 ROSS D.A. Jamesy Central Power & Light Co. 78/11/15 1p. 94252:041.
- --7811200207 LER#78-022/03L-0 on 781017 during routing surveillance to of Stendby Oss Treatment 8ys. the 8ys II Discharga Valve failed to open due to etuck solenoid in control air supply to operator for V-28-3D.

  RDBS.D A. Jarsey Central Power & Light Co. 78/11/15. 3pp. 94232 042
- 7811210321 Forwards LERW78-023/03L-0. RD88-D A Jersey Central Power & Light Co 79/11/15 ip 94485-263
- --7811210324 LERM78-023/03L-0 on 781019: IRM 12 becama inoperative while cable to IRM 14 was disconnected. IRM 12 failure attributed to maint activities under vessel. Subsequent inspec showed IRM 12 cable damaged.

  RDS8-0 A. Jersey Central Power & Light Co. 78/11/15. 3pp. 94493-264.
- 7811280193 Forwards LERM78~024/03L-0. ROSS, D.A. Jersey Central Power & Light Co. 78/11/16. 1p. 94013:247
- --7811280196 LERW78-024/03L-0 on 781018: isolation valve V-7-31 had damaged nubber seat & drain valva V-7-39 obstructed by piece of cort & filter F-1-58 medium disintegrated Couse of V-7-31 & F-7-58 degradations due to detonations in eye. ROSB.O.A. Jersey Central Power & Light Co. 78/11/16 3pp. 94013 248
- 7812110093 Forwards R0#50-219/78/26-1P on 781121.
  CARROLLU, T. Jersey Central Power & Light Co. 78/11/22 ip. 94338-133
- --7812110097 ROM50-219/78/21-1P on 781121: Torus to Reactor Bidg differential pressure switches OP8-66A & B had ruptured disphrams due to excessive containment pressure, QUINTENZ, T.E. Jersey Cantral Power & Light Co. 78/11/22. 2pp 94338 32A.
- 7812280231 Forwards Reportable Occurance Rept#50-219/29-IP CARROLL.J. T. Jersey Central Power & Light Co. 78/11/30. 1p. 94373:242.
- --7812280236 Reportable Occurence Rept#50-219/78/29-ip: on 781129, containment leakage rate was greater than allowable caused by fealure of Isolation Condenser Vent Valvee & DP866A Switches, Valves repaired & replaced. FICKEIBSEN, X. D. Jersey Central Power & Light Co. 78/11/30. 3pp 94372 243.
- 7812290089 Farwards Reportable Occurence Rept#50-219/78/28-LP CARROLL.J. T. Jarsey Central Power & Light Co. 78/11/30. lp. 94190: 109
- --7812270097 Reportable Occurance Rept#50-219/78/28-1P on 781129: Main Steam Line Orain Valve & TIP isolation valve for TIPs 1-1 & i-3 failed to close 6427 relay replaced. Main Steam Drein Valve repaired & TIP Sys switches & logic adjusted QUINTENZ.T.E. Jarsey Central Power & Light Co. 78/11/30. Ppp. 94190, 109.
- 7812070218 Forwards LERW78-025/03L-0.
  RGBS D.A. Jarsey Central Power & Light Co. 78/12/01. 1p. 0355: 090

- leaking due to galvanic corrosion Leak & other weak spots were patch welded ROS9,D A Jersey Central Power & Light Co 78/11/30. 3pp 03935:091
- '812120133 Forwards LER 78-026/017-0.
  FINEROCK, 1. R. Jerssy Central Pawer & Light Co 78/12/05 lp
- --7812120136 LER 78-026/017-0 on 781121 torve-to-reactor bldg differential pressure suitches DPB-66A & D had ruptured diaphrams (aused by escassive differential pressures FINFROCK. I R. Jarsey Central Powor & Light Co 78/12/05 3pp. 94276:177
- '812120123 Forwarde LER 78-026/01T-1 FINFROCK, I R. Jersey Central Pawer & Light Co. 78/12/07. 1p. 94275.354.
- -7812120127 LER 78-026/01T-1: on 78:121, during performance of integrated primary containment leak rate test torue-to-reactor bldg differential pressure switches found to have ruptured diaphrages Caused by design failure of switches
  FINFROCK.I. R Jersey Cantral Power & Light Co 78/12/05. 3pp
- 812180204 Forwards LER#78-020/017-0 FINFROCK,I.R. Jeresy Central Power & Light Co. 78/12/13 1p 94345-050
- -7812180208 LERW78-028/01T-0 on 781129 during teet.mein steem line drein valve V-1-106 did not close 2 incore probos.did not fully w/drew & reactor coolent valve did not indicate closed Due to Jammad armsture.faulty fuse holder & intorrect settings. FINFROCK.1 R Jersey Central Power & Light Co. 78/12/13 3pp 94365:031.
- 812190105 Forwards LERW78-029/017-0. FINFROCK.1.R. Jersey Centrel Power & Light Co 78/12/14 lp 94381:193
- -7812190107 LERM78-029/01T-O on 781129 during test noted that containment leatage rate greater than allowable. Discovered that vent valves were leaking Caused by leakage past the seating eurfaces.

  RDBs.D.A. Jersey Central Power & Light Co. 78/12/14. 3pp. 94381:194.
- 812200234 Forwards preliminary Reportable Occurrence#50-219/78/33-IP CARROLL J T. Jersey Central Power & Light Co. 78/12/14 Ip.
- -7812200240 Reportable Dicurrence#50-219/78/33-iP on 781214 during routine reactor startup following screm from full purial reactor screm in renge 1 of 18Ms occurred for less than 5 seconds. There was no safety significance.

  RONE,A,H, Jersey Central Power & Light Co 78/12/14 2pp 94162.339
- 812270316 Forwards LERM78-027/03L-0. R08S.D.A. Jersey Central Power & Light Co. 78/12/21. ip 94230:354
- -7812270323 LER#78-027/03L-0 on 781125; switch RE03C was found to trip at pressure less conservative(1075 ps(g)) than specified in Tech Bpacs 2.3.3. Cause of pressure switch tripping is attributed to asmoor repeatability.

  RDS9.10 A. Jersey Central Power & Light Co. 78/12/21. 3pp 94230; 355.
- 912270213 Forwards LER678-030/03L-0. ROBB D.A. Jersey Cantral Power & Light Co 78/12/22. 1p. 94190:357.
- -7812290219 LER#78-030/03L-O on 781126: during testing containment spray pumps 51C & 51A failed to start on signal due to excess friction in circuit breaker trip bar bearings. Bearings were cleaned & jubricated.
  ROB9.D.A. Jersey Central Power & Light Co. 78/12/22. 3pp. 74490:35B.

- F Security, medical, emergency & fire protection plans
- 7810170188 Forwards add1 info as requested in 780710 itr re-subj facil Fire Protec Prog. incl organizational chart, fire & security emergency, equipment for safe shutdown instru & station air sys-safe shutdown sys-valves, failure analysis DISE, D.P. Niagare Mohaus Power Corp. 78/10/06 101pp. 94235-095
- 7811290192 Forwards requested info.Fire Pump Test Curves.Fire Main Connections.Floor Drain Sys Drawings(27). Test Plan & Specs For Pipe & Cable Penetration Fire Stop Qual Tests Oversized drawings available in Central Files
  DISE.D.P. Ningara Mohew! Power Corp. 78/11/17 41pp. 94239 283
- 7812060188 Forwards staff requests for add1 info re facil fire protoc prog.based on 781017-20 site visit.

  IPPOLITO, I. A. Operating Reactore Granch 3 (Pre 790625). 78/11/27.
  2769. 94332 080.
- 78:2140:136 Forwards and to Security Plan to permit storage of equip in new Admin Bldg for Spring 1979 outage Encl w/held pureuant to 2 790. DISE.D.P. Niagara Mohawk Power Corp. 78/12/08. 1p. 94:33-336
- G Adjudicatory correspondence
- 7012130090 Requests that NRC place notice in Fod Register of util's appl to install radioactive wasta volume reduction incinerator to facilitate holding of pub hearing on appl DILLINBECK.L, MARTIN,R, PARKER.R. Boribe, NY 78/10/10 Ip
- 7B11200037 Responds to Bd of Town of Scriba.NY-resolution requesting NRC publish a notice of opportunity for hearing in Fed Register & request of Planning Bd to intervene on behalf of Bcriba Matters are under consideration BORDENICK, B M Office of the Executive Legal Director. 78/11/06. ip. 94213-348
- 7811240102 Forwards Appl for Amend to Operating Lic for subj facil. Appl incls attachments which est forth requested change in Tach Specs & supporting data.
  THOMAS.E.B. LeBosuf, Lamb. Leiby & MacRao. 78/11/21 2pp 94449:240
- --78i1240103 Appl for amend to operating lic for subj facil. Incl attachments on proposed changes to Tech Specs & supporting documentation, Changes involve fuel cladding & limiting safety sys satting.

  OISE. D P Niagara Mohawk Power Corp. 78/11/20. 52pp 94449. 242
- 7812280285 Ack receipt of 781031 ltr re Hiagra Mohauk Pur Corp propose to Instail e low level wests incinerator/celciner at subj facil NRC is now reviewing safety & environ aspects of the proposal & no deciston has been made re issuance of an EIR BTELLO.V. Division of Operating Reactors 78/12/15. 19 94080:114.
- --7812280288 Criticizes NRC's publicly stated position that NRC does replan any environ impact statement(EIS) or Fed Register Notice re-installation of low level waste incinerator/calciner at subj facil

  Ecology Action of Oswego. 70/10/31. 2ps. 94083-115
- 781:090052 Resolution auth Dewego County Planning & Dev Comm to intervene as a perty-at-interest in Ningara Mohawt proposed radiective waste volume incinerator proceeding BEST. J. Oswego, NY. 78/10/12. 1P. 94040:098.
- P. Operating license stage documents & correspondence
- 7810110088 Responds to 780807 NRC request for evaluation of motor generator sets that provide pur to reactor protec sys. Info will be evaluate by 781231. Meanwhile surveillance described in 780807 NRC itr will continue.

  D18E.D.P. Niegara Mohauk Power Corp. 78/10/04 2pp. 94063:360.
- 7810180187 Surmary of 780921 meeting re proposed installation of radioactive waste incinerator at subj facil. Wench meeting agenda.

  BARREIT.L. Environmental Evaluation Branch (Pre 790625). 78/10/05. 25pp 94317:172.

- 7811030006 Porwards request for add1 info re expansion of epent fuel bestorage capacity at subj facil: measured man-man exposure to do the work: increased purification sys aperimater leskage from spent fuel pool.contaminated entl estimation. IPPCLITO.T. A Operating Reactors Branch 3 (Pre 790623). 78/10/18 5pp. 02720:253.
- 7810300146 in response to 780711 submission of licemend to delay inspec of sensitized stainless steel semples to meet termination objective, all semples will be removed during 1979 refusing outage & enalyzed by separate organization. BCKMEIDER, R. R. Niegara Mohawk Power Corp. 78/10/25. ip. 94035:125
- 7811130041 Forwards NRC/NY State contract, w/mod for environ monituring in vicinity of subj facil se requested in 780619 meeting.
  8MITH-0 H. Region 1. Philadelphie, Fuel Facility & Meterials Bafety Branch. Fin 1-5109. 78/10/26. 18pp. 94010:206.
- 7811130335 Summery of 780914 meeting w/OE representatives & Mark 1 Owners Group to progress of Long Term Prog w/attendence list & agende(RD-9-A-Marki, Standards.) ORIMES.C. Plant Systems Branch (Pro 791030). 78/10/26. 67pp. 94007:225.
- 7811160022 Notice of Proposed issuence of Amend to Facil Oper Lic SDPR-63.changing Tech Spec to increase spent fuel storage capacity from 1984 to 3009 fuel assemblies.

  1PPCLITO, T.A. Operating Resectors Branch 3 (Pre 790625). 78/10/27.

  4pp. 94316:307.
- 78:1220251 Forwards "Notice of Proposed issuence of Amend to Fecil Oper-Lic" to be published in Fed Register. iPPC.ITO.T.A. Operating Resotors Branch 3 (Pre 790695). 78/10/27. 2pb. 94379;311.
- --7811220252 Notice of Proposed Issuance of Amend to Fecil Oper Lic. revising Tach Spec to increase spent fuel storage capacity from 1984 fuel assemblies to 3009. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/27. 4pp. 94379:313.
- 7811070114 Advises that subj feril specific Tech Spece will be eubnitted 90 days after finalization of NRC model space, estimated date Feb 1979.

  DISE.D P. Niegara Mohawk Power Corp. 78/10/30. 1p. 94043:300.
- 7811190154 Requests payment of Class 4 fee of re 780901 application for amend to License DPR-63 per 10CFR170, 22. Application relates to installation of radvasts reduction sys & associated wests handling squipment.
  MILLER-W. D. License Fee Management Branch. 78/10/30. ip. 94273: 033
- --7811150139 Ack receipt of fee from Niegra Mohawk dtd 781107, check 231131. DIGOS.R.M. Licenee Fee Menagement Branch. 78/11/13. 1p. 94273.034.
- 7811240058 Forwards request for add1 info re-control rod removals at subj facil. Snfo req w/ln 60 days. iPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/09. 3pp. 94455:309.
- 7811290288 Responds to 781104 request for info concerning licenses reg performence eval for Region 1 plants by NRC frovides details.

  GRIER B.H. Region 1, Philadelphia, Office of the Director. 78/11/09. 9pp.
- 7811220186 Responds to 781023 ltr to Secretary of the Comm re health to safety consequences of operating a low level wester incinerator planned for a wby fecil. Forwards Topical Rept MEI/NNI-77-7-NP & 780901 Niegers Mohewk Pwr Corp ltr. DENTIN-H. R. Office of Nuclear Resector Regulation, Director. 78/11/15. 1p. 94070:155.
- --78i1220191 "RWR-1tm Redwatte Vol Reduction Bys." Describes RWR-1tm vol reduction sys for appl to radioactive waste produced at nuc size generating station utilizing fluidized bad to calcine liquids t incinerate solids.

   Newport News Industrial Corp. (subs. of Newport News Shipbuilding t DryDock Co.). NN1-77-7NP. 77/06/24. 109pp. 94070:156.
- --781130391 Request for tech info re health & sefety consequences of operating low level waste incinerator planned for installation at subj facil. Also seeks info re preparation of EIS.

  CCCHRAN, T.B. Natural Resources Defense Council. 78/10/25. ip. 94008.287.

- --7Bi1220193 Forwards Redwaste Reduction info sys. Bys does not involve unreviewed sefety questions based on fact that no equipment in redwaste bidg is important to sefety. Bidg sched to begin Feb 1979 to be completed by Oct 1980.

  DISE, D.P. Niegara Mohewk Power Corp. 78/09/01. 12pp. 94070:273.
- 78:2150:32 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out math. Myenci Registration Form & List of Locations. MILLER-U.R. Assistant Director for Site & Safeguards (Fre 791030). 78/11/15. 3pp.
- 7Bii300367 Informs NMP that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations. Studies will analyze socioecon impects which occurred during constr & post-constr periode o sach plant. DEYCUNG.R.C. Division of 8its Sefety & Environmental Analysis. 78/11/20. 2pp. 94116:317.
- 7812070163 Notice of seminar on 781208 on new Model Radiological Effluent Tech Bases for nuc pur plante. Requeste advance submission of seminar apecific questions. W/encl Beminar Info Bhast.Proposed Agenda & maps.
  GRIER.B.H. Region i. Philadeiphie. Office of the Director. 78/11/21. Gpp. 94127:041.
- 7812110048 Discusses possible dangers of LDCA in containment purging during normal plant ager. Requests either commitment to limit purging or justification for continuing. W/enci ANO: e7812080207 iPPCL1TO.T. Operating Reactors Branch 3 (Pra 790625). 78/11/29. Bpp. 74408:206.
- 7812050148 Forwards "New solidification & Assoc Waste Handling Equip." Rept for sys capable of splidifying storing & loading radioactive waste for shipment w or w/o vol reduction. Mod does not involve unreviewed sefety questions. DISE.D.P. Niegare Mohauk Power Corp. 78/11/30. 6pp. 94334:355.
- 78:2:40:76 Forwards Oct 1978 Prop Activity Review listing meetings held & providing task-by-tesk activity summary for the month. EGBON.L.J. General Electric Co. 78/12/04. 11pp. 94:03:174.
- 7812280107 Emphasizes importance of submitting securate & complate info to NRC by liceneses & applicants info submitted must be substantiated by deta & calculations. Licenese must notify NRC of any inaccuracies or suforcement action will result. DAVIB.J. 0. Office of Inepaction & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:325.
- 7812200194 Requests approval of radusts reduction eys described in Attachment A per requirements of 10CFR20, 305. Repts wastes processed by radusets reduction eys will decrease amount of solid wests shipped to burial grounds.

  DISE-D-P. Niegera Moheuk Power Corp. 78/12/13. iipp. 94162:249.
- 7812270003 Ack receipt of 781030 ltr re Niegera Mohewk Per Corp's proposal to install a low level weste incinerator at subj Facisi. Informs thet no decision has been made by NRC re EIB preparation, Fed Register Notice, & pub hearing.

  DENION.H.R. Office of Nuclear Rector Regulation, Director. 78/12/15. ip. 94159: 204.
- --7812270009 Forwards 780925 ltr re low level incinerator proposal by Niagar Hohawk Pur Corp.Protests NRC's recommendation that no EIS be prepared, no Fad Regleter Notice be Filed & no pub intervention be required.

  REBNIKOFF, M. Bierra Club. 78/10/30. 3pp. 94159:255.
- 7812290049 Ack receipt of 780413 itr re need for feedwater pump trip on reactor high water level. Finds trip is not necessary for safe open of facil. Forwards safety eval.
  IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625), 78/12/15.
  2pp. 94190:001
- --7812290052 Sefety Eval of proposed actions re BNR feedwater pump trip on reactor high water isvel. Concludes licenses-proposed actions to install high water level trip are acceptable.

   Operating Reactors Branch 3 (Pre 790625), 78/12/15, 2pp. 94190:003.
- 7812270176 Responds to 780821 NRC ltr requesting add1 info re epent fuel mod.Forwards "Boreflex 1 Sultability Rept."
  D18E, D.P. Niegara Mohawt Power Corp. 78/12/20. 75pp. 94018:096.
- 7812270240 Requests refund of \$8300 of amend fee paid 781107 on grounds that the Radwaste Reduction Bys amend actually is a Class 3 amend.
  DISC, D.P. Niagara Mohawk Power Corp. 78/12/21, 1P. 94017:149.

The Total Political Political Control of the Contro

Bit210367 Forwards add! info re multiple consecutive safety/relief valve actuation of Mark I containment program 8030N.L.J. General Electric Co. 70/11/13 3pp 94485.126.

#### Inspection reports, IE Bulletins & correspondence

- BIO260019 Ack receipt of 780928 itr informing NRC of steps taken to correct violations noted during inspece30-220/78-11.
  BRUNER,E J Region I. Philadelphia. Reactor Operations Nuclear Support Branch 78/10/06. ip 94410.050
- -7810260022 Responds to 780906 NRC itr re violations noted in Inspec Reptm30-220/78-11 Corrective actions. Quality Control Manual reviewed by 790101, subj. audits done add1 clorks madde available to Quality Control Oper. SCHNEIDER, R. R. Niagare Mohawl Power Corp. 78/09/28. 3pp. 94410 059
- -7810260023 Forwards IE Inspec Rept#50-220 on 780914-18 & Notice of Violation BRUNNER, E. J. Region 1. Philadelphia. Roactor Operations Nuclear Bupport Branch 78/09/08. 2pp. 94410:062.
- -7810250025 Notice of Violation from inspec on 780814-18.
   Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/08. 2pp 94410.064.
- -7810260028 IE Inspec ReptM30-220/78-11 on 780814-18 during which 4 items of noncompliance were noted Quality Control Manuel not reviewed or roissued in 3 yrs & deficiency & staffing audits not performed in time.
  NAPUDA. G. BECKMAN. D., BAUNACK. H. H. Rogion 1. Philadolphia.
  Reactor Operations Nucloar Support Branch. 78/09/07. 20pp.
- 811060208 Forwards IE Circular#78-17 (See ANG: 7010230221, Docket #50-133, 781013.)
  GRIER, B.H. Region 1. Philadelphia, Dffice of the Director. 78/10/13 1p. 94489: 219.
- 612010037 Forwards IE Inspec Rept#50-220/78-14 on 780925-27 during which no Itoms of moncompliance were noted.

  SMITH.O.M. Region i. Philadolphia. Fuel Facility & Materials Bafoty Branch. 78/10/20. 1p. 94416:002.
- -7812010041 IE Inspec Rept#50-220/78-14 on 780925-27 during which no items of noncompliance were noted. Major areas inspected inclianslytical measurement quality control prograudit results, effluent control records & procedures. KUTTAN.J.J. STOHR.J.P. Region 1. Philadelphia, Fuol Facility & Meterials 8afoty Branch. 78/10/19. 8pp. 94416:084.
- 811150038 Act receipt of 781017 itr informing NRC of stops taken to correct violations noted during inspec#50-220/78-12.
  8M17N.Q.H. Rogion 1. Philadolphia. Fuel Facility & Materials Bafety Branch. 78/11/01. ip. 94112:332.
- -7811130041 Responds to 780927 NRC ltr re violations noted in Inspec Rept 30-220/76-12.Correctivo actions:all radiat work permits drafted by those w/loss than 2 yrs experience have been revisued & will be continued. BGNNc1DER.R.R. Niegara Mohawk Power Corp. 78/10/17 3pp. 94112-333.
- ~7811190043 Porwards IE Inspec Rept#50-220/78-12 on 780828-13 & Notico of Violation. CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/27, 2pp. 94112-336.
- -7811150045 Notice of Violation from inspot on 780828-31.

  \* Region i, Philadaiphie, Office of the Director. 78/09/27. 2pp. 74112:338.
- -7811150049 IE Inspoc Rept 50-220/78-12 on 780828-31 during which 4 items of noncompliance were noted: 4 HP technicians sperience short of requirements, feilure to perform dosimeter calibrations & alpha survoys as req. PLUMLEE, K. Rogion i, Philadelphia, Office of the Director. CLEMONS, P.E., KNAPP, P.J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/22. 9pp. 94112:340.
- 311150184 Ack receipt of 781017 itr informing NRC of steps taken to correct violations noted during Inspece50-220/78-13.
  BRUNNER, E. J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/03. ip. 94242:234.

- personnel & increased surveillance established SCHMEIDER.R R Niagara Mohauk Power Corp. 78/10/17. 2pp. 94242.235
- --7811150190 Forwards 1E Inspec Rept#90-220/78-13 on 780905-08 & Nots of Violation BRANNER: E.J. Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/09/26. 2pp. 94242.237.
- --7811150192 Notice of Violation from Inspec on 780903-08 BRUNNER.E J Rogion I. Philadelphia. Reactor Operations Nuclear Support Orance 78/09/25 ip 94242 234
- --7011150194 IE Inspec Rept#50-220/78-13 on 780905-00 Juring which 1 of moncompliance was noted failure to adhere to admin procedure re control of tost instruments.

  BANNACK. W H. Region i. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/26 Opp 94242:240
- 7811290170 Forwards 1E Circular 878-18, 'UL Fire Tost 'W/encl ANO. 7811150002
  ORIER 8 H Region 1, Philadelphia, Office of the Director. 78/11/06 p 94230.071
- 7812280199 Forwards IE Inspec Rept#90-220/70-15 on 780925-29 & Notice of Violation BNITH-O H Region i, Philadolphia, Fuel Facility & Materiale Safet Branch. 78/11/09. 3pp 94373:166
- 7812270446 Forwards IE Inspec Ropt#30-220/78-18 on 781024-27 during which no items of moncompliance were noted. BRUNNER.E J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 78/11/13 2pp. 94015-149.
- --7812270449 iE inspoc Rept#50-220/78-18 on 781024-27 during which no itoms of noncompliance were noted. Major areas inspected incl:admin controls for facil procedures & format & tech content of facil procedures.

  CONTE.R J , BLUMBERG.N.J , KISTER.H.B. Region 1. Philadelphia. Reactor Operations Nucleor Support Branch 78/11/09. 12pp. 74015:151
- 7812150146 Forwards IE Quiletin#78-12A.suppl to IE Bulletin#78-12. W/encl ANG.7811300055 GRIEFIG H. Region 1. Philadelphia, Office of the Director 78/11/24 1p 94212:207.
- A. Periodic operating reports & related correspondence
- 78:0160119 Forwards Monthly Oper Rept for Bapt 1978 BCHNEIDEM, R. R. Niegera Mohawk Power Corp. 70/10/05 lp. 94007:130
- --7810160121 Monthly Oper Rept for Bopt 1978 PERKING T J. Niagera Mohawk Powor Corp 78/10/04 Spp. 94007:131.
- 7811210302 Forwards monthly Oper Ropt for Oct 1978 8CHNEIDER, R. R. Niegera Mohewk Power Corp. 78/11/08 lp. 94483:094
- --7011210303 Monthly Oper Rept for Oct 1978. FERKINB: T. J. Niagara Mohauk Power Corp. 70/11/06 6pp. 94898:097.
- 7812120102 Forwards Monthly Oper Rept for Nov 1970. 8CHNEIDER, R. R. Niegera Mohawk Power Corp 78/12/07 ip 94275: 024
- --7812120103 Monthly Oper Ropt for Nov 1978.
  FERKINB.T.J. Niegera Mohauk Power Corp. 78/12/05. App. 94275: 025
- 8. Reportable occurrences. LERs & related correspondence
- 7810100054 Forwards LERB78-033/03L-0 8CHNEIDER.R. Niagara Mohauk Power Corp 78/09/29. 1p. 94032:100.
- --7810100059 LERM78-033/031-0 on 780916: Surveillance tests on Parton ModelW289 Pressure Indicating Switches showed changes in setpoints due to instru drift. Ray surveillance lest scheds now adequate to onsure early detection of drifts.

  \* Niagara Mohawk Power Corp. 78/09/29. 1p. 94033.101.

- 7811030141 RO on 781025 waste tanks discharged at rates exceeding calculated has due to failure of flow mater on discharge line & attempts to control discharge rate by manual throttle of discharge valve.
  PERKINS.T. J. Hiagara Mobauk Power Corp. 78/10/26. ip. 02723:311.
- 7811130400 Reportable Occurrence #78-35 on 781026 Sept Proportional Composite found concentrations of sodium & sulfate exceeding maximum increase over lase ambient concentration specified in EIB Caused by waste tanks flow meter failure PERKINS, T. J. Niagara Mohauk Power Corp. 78/10/26. 1p. 94008:326
- 7811130319 RO 78-35: on 781028 during routine surveilience test all B main stream high flow transmitters were set less conservatively than req due to test pressure gouge out of cal the PERKINS. T J Niegara Mohauk Power Corp. 78/10/20. 1p. 94087.067
- 7811090155 Forwards LER#78-036/04T-0.
  6CHNE1DER-R R. Niagara Mohawk Power Corp. 78/11/02. 1p. 94043: 017
- --7811090165 LERM78-036/04Y-0 on 781029 improper appl of Brook Modal#9456 Oval Open Flowmeter combined w/failed seel on coustic addition pump caused high concentration of sodium & sulfate & degraded capability to control rate of discharge. MACVITTIE: D N. Niegara Mohawi Power Corp. 78/11/02. 1p. 94043: 018
- --7011090205 Details event & cause description & preventative ections re-sodium & sulfate discharges eccessing ETS values.

  904NEIDER.R.R. Niagara Mohawh Power Corp. 78/11/02 2pp. 94043:019.
- 7811090271 Forwards LERN78-035/017-0.

  8CHNEIDER: R. R. Niagara Mohawk Power Corp. 78/11/02. ip.
- --7811090273 LERN70-035/01T-0 on 781020:011 moin steam high flow pressure Indicating instr were found wisetpoints less than Tech Spocs Heise 0-200 PSIQ test guage calibrated & used in test had loose screw b was recalibrated. PACVITIE, D. K. Nlagara Mohawk Power Corp. 78/11/01. App. 02729: 356
- 7811210281 Forwards LERM78-037/03L-0. #78-038/03L-0 & #78-039/03L-0. SCHNEIDER, R. R. Niegere Mohawk Power Corp. 78/11/15. ip.
- --7811210283 LER#78-037/03L-0 on 781027: test revealed trip setpoint of 28.5 inches water on one vacuum switch in vacuum relief sys from pressure supression chamber to rx bldg.Caused by instru driff in a Mercoid Model CP4122 vacuum suitch. MCCYTTIE, D.K. Niagara Mohawk Power Corp. 78/11/14. ip. 94485; 202.
- --7811210287 LER#78-038/03L-0 on 781025: review of NI-15P-RE22 test results found 12 instances where procedure was violated. Caused by carelessness in procedure implementation. Re-instruction & closer supervision instituted. MACVITTIE.D.K. Niagara Mohawk Power Corp. 78/11/14. 1p. 94485: 203
- --7811210292 LER#78-039/03L-0 on 781103: \*urveillanc\* test Ni-18P-RE02 revealed Rx Lo-Lo water level switch w/trip setpoint of +2 inches water Caused by instru drift. Setpoint reset, MACVITTIE.D K. Niagara Hohawk Power Corp. 78/11/14. ip. 94485: 204
- 7812140149 Forwards LERK78-040/03L-0. SCHNEIDER, R. R. Niegara Mohawk Power Corp. 78/12/08. 1p.
- --7812140154 LER#78-040/03L-0 on 781113:#112 core spray topping pump motor breaker closed starting pump but breaker closing spring motor was running continuously & not charging closing spring. Caused by misaligned motor assembly at latching paul.

  JUTRAS.R. Niagara Mohawi Power Corp. 78/12/08. 1p. 94127:008.
- DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR P. Operating license stage documents & correspondence
- 7812070055 Requests response concerning subj facil location adjacent to proposed constr of a hydro-electric dam Studies are being conducted by Lowell Corp. WALLACE.T. Lowell, Univ. of. 78/11/27. ip. 94134:030.

- Q Inspection reports. IE Bullatins & correspondence
- 7811020060 Ack receipt of 780926 1tr informing NRC of steps taken to correct violations noted during inspec#50-223/78-03. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/10. ip 94374:159.
- --7811020177 Responds to 780915 Notice of Violation re compilance w/ posting rage As of 780929, 10CFR21 & Energy Reorganization Act of 1974 Section 206 are properly posted BEOHAIN.L.E. Lowell, Univ. of. 78/09/26. ip. 94374:160
- --78:1020178 Forwards 1E Inspec Rept#50-223/78-03 & Notice of Violation BRUNNER.E.J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Brench. 78/09/15 2pp. 94374-161.
- --7811020182 Notice of Violation from inspec on 780817-18 BRUNNER, E. J. Region 1. Philadelphia. Defice of the Director 78/09/15. 1p. 94374:163.
- --7811020186 IE Inspec Rept#80-223/78-03 on 780817-18 during which i Item on noncompliance was noted: failure to comply U/10CFR21 greeing requirements
  GREENMAN, E. G. Region i, Philadelphia, Office of the Director.
  78/09/13. 6pp. 94274:164.
- DOCKET 30-224 UNIV. OF CALIFORNIA RESEARCH REACTOR F. Security, medical, emergency & fire protection plans
- 7811030009 Review of physical security plan revision complete. Plan acceptable. REID.R.W. Operating Reactors Branch 4 (Pre 790623). 78/10/17. 2pp
- DOCKET 50-225 RP1 CRITICAL EXPERIMENT J. Insurance & Indomnity information

02720: 262.

- 781101007; Repts that insurence broker is sending Advance Premium endorsement Indemnity agreement wee forwarded earlier. LEAVITI.J.B. Reneselaer Polytechnic inst. 78/10/26 ip 94481:059.
- DOCKET 80-227 TRIGA THERMIONIC PROTOTYPE REACTOR
- F. Security, medical, emergency & fire protection plans
- 7812190145 Forwards current physical security plan in compliance w/regs.classified as "Netl Security Info" pursuant to certain DOE requirements. Requests that earlier copies be destroyed, and new copies be withheld.
  MDMRY, W.R. Deneral Atomic Co. (subs. of Gulf Dil Co. ). 78/12/15 IP. 94340:070.
- DOCKET 50-236 LOCKHEED AIRCRAFT CORP.
- U. Congressional/Executive Correspondence
- 78:0140036 Response to 780911 ltr for comments re individuals who ere concerned over radioactive milk contemnsts re Individuals we concerned over radioactive milk contemnstion in area near facil. Forwards NRC preliminary evaluation of Steinglass rept on Strontium-90 levels in milk near subj facil.

  DiRCKS.W.J. Dffice of the Executive Director for Operations.
  78/10/06. 2pp. 94329:073.
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7812130228 Classifies lic amend for proposed fuel pool mod as Classes IV & I not Classes III & I.Requires addl charge of 48300 for each of the two applito be paid win 15 days.
  MILLER.H.O. License Fee Management Branch. 78/12/11. 2pp.
- F. Becurity, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Elec Cable Penetration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 3 detailed drawings associated w/test.

ilku/ul/2 rorwards fire protec info incl hydraulic calculations & Automatic Sprinkler Co Drawing#26-1750.of sprinkler sys for pire pump in Crib House. Overeize drawings available in Central Files.

NAUGHTON, W. F. Commonwealth Edison Co. 78/11/30. App. 03555:144.

12120175 Informe NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nut Plant Fire Protec Functional Resonaibilities Admin Controls & QA" will be submitted 790201 NAUGHTON, H F. Commonwealth Edison Co. 78/11/30. 2pp. 94277:099.

## Adjudicatory correspondence

10120112 Applicant's Answer to Petition for Leave to Intervene reproceeding filed 780908 by Attorney Gen of St of IL Includes notices of appearance for M. 1. Miller, J. R. Rowe, & P. P. Steptoe. Includes designetion of person upon whom eve shall be made. BTEPTOE.P. P. Ishem, Lincoln & Resis. 78/07/18. 10pp. 94484:039.

IOI90131 Answer by CEIL to Petition to intervene filed by Atty Gen of IL on 780920. Agrees that Atty Gen has standing, but issues there are no genuine issues to be heard at hearing lequeste that Atty Gen request for EIB be denied. HEPTOE.P.P. Ishem, Lincoln & Beele. 79/10/02. 3pp.

0300063 Natural Resources Defense Council Request for Leave to File Response. Response is to applicant's contention rematitutionality of forced disclosure of group's members' ames in order to oper w/in state.

OIBMAN. A. Z. Natural Resources Defense Council. 78/10/10. App. 4037: 177.

0303324 NRC Staff Answers to Council for Citizens for Batter nviron & Natural Resources Defense Council's Petition for save to Intervens. Staff opposes granting petition, w/Cert f Svc. OPDARD, R J. Office of the Executive Legel Director. 78/10/10. pp. 94253: 337.

0230124 NRC Staff's Response to Petition of TEX-LA Cooperative. Inc. or Leave to Intervene. Staff believes Petition should be rented. EBSY.R.P. . BLUME.M.B. Office of the Executive Legal Otractor 8/10/10. 9pp.

3310223 Staff Answer to State of IL petition for Leave to Intervene, telf does not oppose admission of IL as party to proc. 3DDARD,R. J. Office of the Executive Legal Director, 78/10/10,

1010063 Petition for leave to intervene & for hearing filed by Itizane for Better Environ & Netural Resources Defense suncil Request for leeve to file response to answers igosing petition is grented. ILHOLLIN.G.L. Atomic Befety and Licensing Board Panel. 78/10/13. 1. 94302:360.

.150923 "Natural Resources Defense Council Response to Commonwealth lienn's & Btaff's Answers to Patition for Leave to stervene. "Intervenor urgs Ed to establish a schedule for itefing challenges to contentione. ILEMAN.A. Z. Natural Resources Defense Council. 78/10/23. 16pp. -270: 137.

130216 NRC request to file response to NROC response to Comm Ed & Canswer to petition for leeve to intervene dtd 781023. If anted respi will be served by 78103. Cert of Svc enci.
DDARD.R.J. Office of the Executive Legal Director. 78/10/26. DOARD, R. J. 04 P. 03554: 050.

200070 Request by Comm Ed for leave to file a response to NRDC iff which argues that organizations may show stending to riscipate in NRC proceedings marely by alleging that they present anonymous members. Cert of Svc encl. EPTOE.P. P. Ishem, Lincoln & Beals. 78/10/30. 2pp. 74218:348.

390239 Bd grants request by Citizene for a Better Environ & Natural sources Defense Council for permission to file response to swers opposing their petitions to intervene by 781103.

-HOLLIN, D. L. Atomic Sefety end Licensing Board Penel. 78/11/01.

02761:290.

220203 Forwards "Licensing Report Dreeden Nuc Pur Plant Units 2 & Spent Fuel Rack Modification." deted 780200 W/o encl rept. IDARD, J. Office of the Executive Legal Director. 78/11/01, 1p. 1289: 340.

- 7811160021 Grants request by licenses CEIL to have until 781107 to respond to 781013 Order of ASLB permitting NRDC & Citizens for a Better Environ to file response to answers opposing their petitions to intervene in proceedings re subj facils MILHOULIN.0 L. Atomic Safety and Licensing Board Panel 78/11/1 p 94317-090 78/11/03
- 7811220010 NRC Staff's Response to NRDC's Response to answers to latter's Petition for laws to intervene NRC asserts that NRDC has not demonstrated its standing to intervene as matter of right Cert of Svc anci.
  GODDARD, R. J. Office of the Executive Legal Director. 78/11/03 Bpp. 94273: 334
- 7811200003 Special Preheering Conference in proceedings re subj facils will be held on 781215 in Rock Island.iL All perties to proc & ell petitioners to intervene must ettend & should be prepered to discuss ell issues.

  MILHULLIN. 9 L. Atomic Safety and Licensing Board Penel. 78/11/09.

  2pp. 94215:221.
- 7812130122 Gives notice that A Bielawski enters an eppserance on behalf of applicant CEIL in proceedings re subj facile. Cert of Syc BIELAWBK1, A. P. 1 shem, Lincoin & Beals. 78/11/21. 2pp. 94307:188
- 7812110284 Cencels special preheering conference echeduled for 781215.
  Conference shall be held on 790111 in Tax Courtroom of US
  Courthouse & Fed Bldg, Chicago, it. Perties & petitioners must
  rept to Board by 781215 re progress of negotiations
  MILPOLLIN, O. L. Atomic Sefety and Licensing Board Penal 78/12/01. 2pp. 94203:243.
- 7812270230 Proposed stipulation rs NRDC & CDE's representation of unnamed members in Dredden-Qued Cities transshipment is not acceptable to NRC.NRC position on NRDC's petition to intervene resents as steted in 781103 pleading.

  QDDDARD.R.J. Oppics of the Executive Legal Director 78/12/06 lp. 74017: 13B.
- 7812280271 Forwarde"8tipulation" of NRDC.CDE & Commonwealth Edison Core identification of members of NRDC & CBE to prove they have interests that may be effected. No egreement w/Reg Staff has been reeched. ROISMAN. A. Z. Naturel Resources Defense Council. 78/12/08 19. 94374: 334.
- -- 7812280280 Parties egree that NRDC & CBE have adequately indentified a least one member whose interest mey be edversely effected by the proposed ection. Auth to represent these interested members has not been agreed upon. ROIBMAN, A. Z. Netural Resources Defense Council. STEPTDE, P. P. Commonwealth Edison Co. 78/12/11. 3pp. 94374:335.
- 7812270133 Speciel Prehearing Conf Scheduled for 790111 is postponed until 790201 Perties & petitions ere excused from requirement to rept to 8d by 781215 re negotiations progress. MILHOLLIN, Q.B. Atomic Safety and Licensing Sound Penel 78/12/13. Rpp. 94161:142.

#### H. General correspondence

- 7810310024 Informs that for BEP normal channel of oral communication will be followed, but to expedite reviews direct orei communication between subj facil staff & members of SEP branch is encouraged. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10 2pp. 94094:345.
- 7812080158 Forwards CEIL request for amend of OL to allow spent fuel transfer & storage between facils. W/o enci. GODDARD, R. J. Office of the Executive Legel Director. 78/11/17. 1p. 94107: 356

#### 1. Financial information

7811140199 LERM78-056/01T-0 on 781012; diff press switch isolation valve for DPIS 2-1622A was found closed because of unknown cause.

Bubj valve will be opened slowly after DIS 1600 survey.

LINDERRO.C. Commonwealth Edison Co. 78/11/01. 2pp. 94384: 283.

#### J. Insurance & indemnity information

7812190109 Requests refund of 86 per mut in excess indemity fee peid for Lic#DPR-2, MDPR-19, MDPR-25, MDPR-29, MDPR-30, MDPR-39. WDPR-48 PODLE, R. D. Commonweelth Edison Co. 78/12/13. 1p. 94376: 323.

- P Operating license stage documents & correspondence
- 7811100105 Forwards copy of NUREG-0485, "Status Summary Rept-Systematic Eval Prog ' ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/10/19
- 7812083026 FOIA request for all records incl quantity of radioactive matl disposed of from forcer Manhantten proj in IL known as Chicago Pileski, 2 % 3 Matl disposed of in IL by Lindsay Cos at Morris facil & Dreaden facil.

  HANEELL, D 11:inois. State of 78/11/06 2pp 94104-003
- 7810250198 Notice of Proposed Issuance of Amends to Oper Lics NRC is considering issuance of amenda to Provisional Oper Lic MDPR-17 & Facil Oper Lic MDPR-23, Mould change provision in Tech Specs to allow more spent fuel to be stored at facil ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/08/03 4pp. 94392.220
- 7811130059 Forwards initial eval of B complete SEP topics & response to request for clarification of SEP documentation procedures made at 780531 meeting. Requests response re Pacts used to define plants by NPC staff Elischafty. D.O. Assistant Director for Bystems Engineering (Pre 791030). 78/08/17 2pp. 94010-275.
- 7810170105 Update & conclusion of diesel generator reliability study Almost all corrective actions taken per investigation have been torpleted Results of study summarized in encl BTEPPENSON, B B Commonwealth Edison Co 78/09/28 5pp 94270.047
- 7810102027 Forwards evaluation of reactor protect sys pur supplies to determine whether undetected failures adversely affect the RPS sys.

  TURBAK.M.S. Commonwealth Edison Co. 78/10/04 Spp
- 7810140112 Rosvaluation of Lic amend fees for inter-station spent fuel transfer for subj facils as requested by 700817 itr shows that the class 1 & 3 fees paid for each station are correct MILLER.W D License Fee Management Branch. 78/10/10 ip. 94428:191
- 701100275 NotiPication of 781023-24 site visit to observe discuss & identify site specific seismic design features & info. Agenda, iist of pertinent info required for review by senior seismic review team & description of SEP review encl ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 28/10/11. Bop.
- 7810250165 Notice of meeting on 781023-24 to discuss Gys Evaluation Prog Seismic Review for subj Facil. D'CONVOR.P.N Operating Reactors Branch 2 (Pre 790625). 78/10/16
- 7810240158 Forwards evaluation of surveillence requirements on BWR recirculation pumps & discharge valves in operation u/less than all loops in svc.BWR jet pump operating indications & super pienum injection u/002s affectd in LCOCA TURDAK.M G. Commonwealth Edison Co. 79/10/18 19pp
- 7B11100109 "Status Burmary Rept. Bystematic Evaluation Program" 
  # GPFice of Management and Program Analysis. NUREG-0485 VOI 78/07/22 203pp.
- 7810260153 Requests 45-day extension to allow time to provide add1 inforce accuracy of environ qualification of safety-related electrical equipment TURDAK-M.S. Commonwealth Edison Co. 78/10/23 ip. 94055:338
- 7810270180 Responds to 781002 NRC ltr re requested Tech Spec change for reactor water cleenup sys return valve. Util accepts change as Class 3 & Class 1 amend, & remits appropriate fae REED.C. Commonwealth Edison Co. 78/10/23. ip 94057:081.
- 7811060115 Responds to 780919 request for add1 info re H-431 Response will be in 2 parts, first to be sent 781027 second 781124. H-451 review can be completed by mid-Jan. Also requests ack of 780714 ltr.
  MESERYAN, O. L. Oemeral Atomic Co. (subs. of Quif Oil Corp.).
  78/10/25. | 1p.
- 78:1020322 Withdraws request to amend Tech Space re reporting requirements for reactivity anomalies, as Reg Quide "Interpretation" by NRC on 780701 does not require rept for reactivity increase of less than 5 secs.

  REED.C. Commonwealth Edison Co. 78/10/26. 2pg. 94253:223.

- 7811030161 Forwards proposed Amend changing Tech Specs w/regard to updating station organizational charts Changes have received ansite & affecte approval.

  REED.C. Commonwealth Edison Co. 78/10/26 9pp. 03724 009.
- 7811120335 Surnary of 780914 meeting w/GE representatives & Mark 1 Dwners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Marki,Standards ) GRIMES.C. Plant Bystems Branch (Pre 791030) 78/10/26. 47pp. 94007 225
- 7811140014 Requests add1 info on FSF switchover from injection to recirculation modelisalisation of reactor protect sys from non-safety sys.ESF sys logic b design b specific drawlings of elec sys. b complete plant elec drawling indices ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 70/10/26. Opp 94425 040
- 7811000199 Site visit on 780928 conducted for the purpose of viewing hydrological features & discussing w/licensee hydrological design bases nacessary to perform a detailed SEP review Addi hydrological info also requested STALEY.C B Hydrology Meteorology Branch 78/10/31. 3pp 94405. 136
- 781110013; Summary of meeting w/CEIL on 781023-24 to discuss questions re-seismic design of subj facil & obtain seismic design info M/Pnc.) list of attendees.resting agenda-charter of BRRT.floor response spectra. & deeign repts & tech paper. LEVIN.H A Systematic Evaluation Programs Branch (Pre 790625) 78/11/02 410pp 9429-001
- 7811140105 Responds to 780516 NRC ltr requesting add1 info re reactor vessel metal surveillance specimen fluence valves at time of withdrawal.w/projections based on dosimetry results of praviously tosted capsules & BOX capacity factor.w/o encl. TURBAKIM B Commonwealth Edison Co. 78/11/03 2pp 94425 125.
- 7811140002 Notifies applicant of 781128 NRC-sponsered seminar re-Model Radiological Effluent Tech Bpecs for Nuc Pur Plants Wencl Beminar Info Bheet(to be completed & returned by 781117) & Proposed Agenda KEPPLER, J G Region 3. Chicago. Office of the Director 78/11/07 6pp. 94426 022
- 7811150246 Notifies of forthcoming mtg w/Commonwealth Edison Co to discuss schedule for inspec of type 3 safe ends at subj facil O'CONNOR.P H Operating Reactors Branch 2 (Pro 790625). 78/11/07. 1p. 94273 063
- 7811170207 Requests add1 info for review of proposed subj fac11 Spent Fuel Pool Mod Question items include accupational exposure during 6FP mod.effect on exposure level of rut up low density racks. 6FP cooling sys.vol of conteminated metl ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/08 7pp. 94045:179
- 7811210257 Updates 770510 itr info re control rod drive(CRO)uncoupling prog. Forwards historical data list of all CRO's occurring between 780522 & 771211. Improved Quality Control & filter installation procedures are adequate to prevent uncoupling. TURBAK.H 9. Commonwealth Edison Co. 78/11/13 4pp. 94488:335.
- 7811300058 Forwards Amend#39. #37. #48 & #47 for Lics DPR-19. DPR-25. DPR-19 & DPR-30 respectively Amends revise Tech Space reoperating temp & pressure limits. Also forwards Safety Evel & Fed Register Notice.

  1PPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/13. 300
- --7811300064 Amend#39 to the Operating Lic rev Tech Specs re operating temp & pressure limits iPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13. Soc.
- --781300067 Amend#37 to the Operating Lic rev Tech Specs re operating temp & pressure limits.

  IPPOLITO.T A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.

  Opp
- --7811300070 Amend#48 to the Operating Lic rev Tech Space re operating temp & pressure limits.

  1PPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13
- --7811300073 Amend#47 to the Operating Lic rev Tech Specs re operating temp & pressure limits.

  IPPOLITO.T.A. Operating Reactors Granch 3 (Pre 790625). 78/11/13 Reactors Granch 3 (Pre 790625).

- -7811300077 Safety Eval Rept in support of Amend#39,#37.#48 & #47 to
  Oper Lics DPR-19.DPR-23.DPR-29 & DPR-30.respectively
  \* Office of Nuclear Reactor Regulation. Director 78/11/13 4pp
- -7811300089 Notice of Issuance of Acendal9, #37, #48 & #47 to Oper Lics CPR-19, DPR-25, DPR-29 & DPR-30, respectively 1PPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625) 78/11/13 200
- #2150071 Notification of workshops in Jan-May 1979 in Regions 1-5 to explain techniques of job analysis & performance testing & how to relate such testing to qualification plan development & training Designed for working level personnel MILLER, JR Assistant Director for Bite & Safeguards (Pre 791030) 78/11/15 5pp 94210 215
- 12180248 Forwards Rev#1 "Draft Radiological Effluent Tech Opecs' for BMR'4(RWRE0-0472) & 'Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NURE0-0133)
  ORITES.0 K Assistant Director for Engineers & Projects (Pre 790425) 78/11/15 6pp 94366 123.
- 12050107 Forwards rev page to Topical Rept CE-1-A "Qual Assurance Prog.Rev 5." Rev reflects Reg Quidel 28 & 1 33 rev TUBBAKH B Commonwealth Edison Co 78/11/17 2pp 94335 354
- i1280213 Forwards current lic status list for subj facils REED.C. Cormonwealth Edison Co. 78/11/20 9pp 94012 130.
- 14280246 Forwards "Projected Fluence Values at Mithdraye) for the Capsules Designated to Meet the Requirements of IOCFR90 Append N° Table 1 to be attached to 781103 itr to 1ppolito TURBAK.M S Commonwealth Edison Co 78/11/20 2pp 94012.162
- 12320133 Forwards revised lists u/environ qualification of sefety-elated electrical equipment in response to NRC 780906 ltr (Includes SEP by equipment type-SEP submittal ref. location-lime required & type of environ furrance for type for the following section of the following furrance for the following furrance furrance for the following furrance for the following furrance for the following furrance furrance furrance for the following furrance furrance for the following furrance furrance furrance furrance furrance for the furrance furran
- .2140176 Forwards Oct 1978 Prog Activity Review listing meetings held a providing task-by-task activity summary for the month 308CN.L J. General Electric Co. 7G/12/04 11pp 94103 174
- 2120070 Presents proj & justification for feeduater notile/sparger & ontrol rod drive return line notile inspec progs Concludes hat no further inspec of CRD return line notile is serranted URBAK.M 9 Commonwealth Edison Co 78/12/05 Bpp 94274:001
- 2280129 Emphasizes importance of submitting accurate & complete info o NRC by licensees & applicants info submitted must be ubstantiated by data & calculations Licensee must notify IRC of any inaccuracies or enforcement action will result AVIS.J. G Office of Inspection & Enforcement. Office of the irector 78/12/06 2pp 94311:336.
- 2140361 Requests eval of systems designed to accomplate effects of the breaks inside containment at subj facil in order for RC to complete BEP review
  IEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/07.
  PP. 03557-235.
- 2150099 Requests add1 info from SEP licenseps re elec penetratione f reactor containments in order to complete eval IEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/12/08.pp 94212 032
- 2210078 Forwards NUREG-0485, Vol J. Number 2, "Status Summary Rept. EP." W/o encl. 1EPHANN.D.L. Depositing Reactors Stanch I (Pre 790625) 78/12/08. 30. 94269.360.
- 2:50228 Classifies lic amend for proposed fuel pool mod as Classee / & i not Classes III & 1 Requires addl charge of 48300 for sch of the two applito be paid win 13 days [LLER.W.B. License Fee Management Branch. 78/12/11 2pp.

- 7812050013 Requests views of Regional Directors on Licensee performance eval of subj facils Forwards questions to be answered by 771209
  THORNBURDO. H Division of Reactor Construction Inspection 77/11/23
  200
- 7812190097 Accepts topical reptHCE-1-A RevHo. "Comm Edison Co Quality Assurance Prog for Nuc Generating Stations " Requests substitut of 36 copies HAARS.M.P Quality Assurance Branch 78/12/13 ip. 94376-317
- 7812220067 Summary of 781130 meeting of SEP Setamic Review Yeam in San Francisco. (A re-progress in setamic review of facility List of attendees agenda & outline of draft final rept on facility setamic review end LEVIN. HA Systematic Evoluation Programs Branch (Pre 790629) 78/12/13 Upp 94248 311
- G Inspection reports: 1E Bulletins & correspondence
- 7810110052 Forwards 1E Insp Repts 30-010/78-23.30-237/78-21 & 30-249/78-23 on 780807-10 & 16-18 & nutice of deviation DAVIG.A 8 Region 3. Chirago. Office of the Director 78/09/08 2pp 94080 049
- --78[0][0054 Rintice of Deviation from inspec on 780807-10 & 780816-10 • Region 3. Chicago, Fue] Facility & Materials Safety Branch 78/09708 1p 94063 226
- --78i0i10062 16 Inspec Repts#50-010/78-23,#50-237/78-21 & #50-249/78-23 on 780807-10 & 16-18 during which I stem of deviation was noted Failure to most FGAR commitment for monitoring unit 2/3 liquic rad waste effluents

  OREGER-L R . FISHER-W-L Region 3. Chicago, Office of the Director 78/09/06 lipp 94063 227
- 7811010018 Forwards IF Inspec Repts#30-10/78-25,#90-237/78-22 & 50-249/78-24 on 780705-06.11-12.19-20.780817.23-25.29-31 & 780901. during which has items of noncompliance were noted FIORELLIO Region 3. Chicago, Reactor Deperations Nuclear Support Oranch 78/09/20 2pp 94290 141
- --78:1010022 IE Inspec Repts#30-10/78-25, #50-237/78-22 & #50-249/78-24 on 780703-06.11-12.19-20, 780817, 23-25, 29-31, 780901.during which no items of noncompliance were noted Major areas inspec followup of noncompliances & review of plant oper.

  BATKER, J L Region 3. Chicago, Office of the Director MNOP, R C Region 3. Chicago, Reactor Dyerations Nuclear Support Branch. 78/09/20 7pp.
- 7810110277 Responds to 780908 NRC ltr re deviation noted in Insp. Repts 50-010/78-20, 50-237/78-21, 50-249/78-23 Corrective actions, liquid raduate discharge monitor will be returned to svc & elarm will be made operable REED. C. Componwealth Edison Co. 78/09/22 3pp. 94079:148
- 7B10200203 Ack receipt of 7B0922 ltr informing NRC of steps taken to correct item of noncompliance identified in ltr of 7B0908 DAVIS.A 8 Region 3. Chicago. Fuel Facility & Materials Safety Branch. 70/10/12 lp 94367 089.
- 7810300030 Forwards IE Circular#78-17. (See AND 7810230221) KEPPLER, J. G. Region G. Chicago, Office of the Director 78/10/13
- 7811300261 Forwards IE Inspet Repts#50-010/78-26.50-237/78-23 & 50-249/78-25 on 780903-08.12-14.20-22. & 26-28 & Notice of Violation.
  FIGRELLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Dranch. 78/10/25. 2pp 94075-233
- --7811300264 Notice of Violation from inspec on 780905-08,12-14,20-22 & 26-28

  \* Region 3, Chicago. Reactor Operations Nuclear Support Branch. 78/10/25 jp. 94075 061.
- --7811300268 1E Inspec Repts#50-010/78-26,50-237/78-23 & 50-249/788-25 of 780905-08.12-14,20-22 & 26-28 during which I item of noncompliance was noted failure to rept a 30 day reportable event in 30 days SATKER, J. CHRISSDIMOS, N. HUGHEG, J. Region 3. Chicago, Reactor Operations Nuclear Support Branch 78/10/25 15pp. 94075,237.
- 7811080334 Forwards request for additinfo necessary to continue review of Insvc Inspec Prog proposed for subj facils Request relates to pump & valve testing portion of proposed program Requests response by 781130.
  ZIEMANN, D. L. Operating Reactors Brench 2 (Pre 7906251. 78/10/26 9pp. 94406 288

- 78:205001; Forwards IE Inspec Repts#50-010/78-29, 50-237, -254, -295, -304/78-25, 50-249/78-27 & 50-245/78-26 on 78:002 during which no itoms of noncompliance were noted REPPLER. J & Region 3. Chicago, Office of the Director 78/10/30, 2pp. 94200 183
- --7812050027 IE Inspec Repts for subj facils on 781002 during which no items of noncompilance were noted dajor arees inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station MNDP.R C . PIORELLIAG. Region 3. Chicago. Rector Operations Nuclear Support Dranch. MEPLEG.J.O. Region 3. Chicago. Office of the Director. 78/10/30. 3pp. 94200.183.
- 7811150063 Forwards IE Circular 78-18. "Underwriters Lab Fire Teet " KEPPLER, J. G. Region 3. Chicago, Office of the Director. 78/11/06 1p. 94182.249.
- 7Bi 1280486 Unresolved items noted in IE Inspec Repts#50-010/77-28, #80-237/77-25 & #50-249/77-25 have been revisued & recomendations made Documentation of unresolved items witheid per IOCFR2 790(d) HIND. U.A. Region 3. Chicago. Sefeguards Branch 78/11/16 1p 9408: 358
- 7812050287 Forwards IE Sulletin 78-12A, "Atypical Weld Meti in Resctor Pressure Vessel Welds." KEPPLER, J. G. Region 3, Chicago, Oppics of the Director 78/11/24. 1p 94202.332
- 7812140081 Forwards 1E Image: Repts#50-010/78-28.#50-237/78-24 & #50-249/78-26 on 781010-13.781016-19 & Notice of Violation. KEPPLER, J G. Region 3. Chicago. Office of the Director. 78/12/01. 2pp. 94128 227
- --7812140086 IE Inspec Repts 90-030/78-28:50-237/78-24 & 50-249/78-26 on 781010-13 & 781016-19 Noncompliance noted defective security organizationobserved, including access controls & physical barriers. Info partially withheld (ref FOIA Exemption 3). BELANGER, J.L., HOWELL, J.C., HIND, J.A. Region 3, Chicage, Bafeguards Branch. 78/11/20. 2pp. 94128:229.
- 7012130330 Natification of site visit on 781206-07 to discuss operational considerations re insvc inspec prog. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625) 78/12/05. ip. 94307.332
- 7812290026 Forwards 15 Bulletin 78-14, "Deterioration of Bune-N Components in ASCO Solenoids."

  KEPPLER, J. 0 Region 3, Chicago, Office of the Director. 78/12/19.

  1p. 94208:009.
- R. Periodic operating reports & related correspondence
- 7811140119 Forwards monthly operating rept for Oct 1978.
  BTEPHENSON, B. D. Commonwealth Edison Co. 78/11/08. 1p. 94420: 184.
- 8. Reportable occurrences, LERs & related correspondence
- 7810130165 Forwards LERM78-051/03L-0 BTEPHENBON. D. D. Commonwealth Edison Co 78/10/02. 1p. 94003:018.
- --7810130170 LER#78-051/03L-0 on 780907 during survey DIS 1600-11, valve #2-1601-24 failed to oper in specified time limit, probably caused by foreign matter forging in sciencid oper 4-wey valve.

  # Commonwealth Edison Co. 78/10/02. ip. 94003:019.
- 781:210356 Confirms sys trip on low suction pressure. Veive line-up changed. Operability proven. Caused by low pressure trip switch being out of calibr.
  BTEPHENBON, B. B. Commonwealth Edison Co. 78/10/02. Ip. 94485:019.
- 7810200092 Forwards LER#78-085/01T-0. STEPHENBON, B. B. Commonwealth Edison Co. 78/10/13. 1p. 94140:338.
- --7810200097 LER#78-095/01T-O on 780930: performing DOB 2300-3 the HPC1 turbine tripped on low pump suction pressure of 11.5 peig which exceeds Drasdan set point of 9.4inch Mg vacuum increase. Causad by Instru drift of pr
- 7810270234 Forwards LER#78-053/03L-0. BTEPHENBON.B.B. Commonwealth Edison Co. 78/10/17. ip. 94059:001.

- --7810270236 LER#78-053/03L-0 on 780926 Equip Attendent noted Hain Steam Line Flow Buitch 261-20 wes valved out due to unknown cause. Event had minimal safety significance & switch returned to svc. Surveillance sheets up require delly check of switches. PLLO.R. E. Commonwealth Edison Co. 78/10/17. 19. 94097:002.
- 7811240210 Forwards LER#78-051/03X-1.
  BTEPHENSON-8.8. Commonwealth Edison Co. 78/10/17. 1p. 94461:361.
- --7811240211 LERA78-051/03X-1 on 780907: during surveillance test DIS 1600-11, valve 2-1601-24 failed to operate in specified time limit Caused by foreign matter lodged in solenoid operated 4 way valve, preventing proper blesd off.
  C1682K16WIC2.8. Commonwealth Edison Co. 78/10/17 ip. 94461:362
- 7810270287 Forwards LER#78-052/03L-0 8TEPHENSON:8 B. Commonwealth Edison Co. 78/10/19. 1p. 94025; 339.
- --7810270296 LERM78-052/031-0 on 780922: During surveillance test-dieselfailed to stert due to air start sys fault Second attempt was successful. Air start sys will be mod to provided multiple start attempts.

  DOYLE, J. E. Commonwealth Edison Co. 78/10/19. 1P. 94025: 340.
- 7811030143 Forwards LERW78-054/03L-0 STEPHENSON: B B. Commonwealth Edison Co. 78/10/24. 1p. 02723:312.
- --781:030:43 LER 78-054/03L-0: on 7809:30 torus vacuum relief velve A0-1801-208 would not close Alerm received Valve fully open. Caused by blown fuse in control circuit due to short in A0-1601-203 air operated solenoid valve. PARCELL Commonwealth Edieon Co. 78/10/24 lp. 02783-313.
- 7811090116 Forwards LER#77-015/03X-1 BTEPHENSON.G.B. Commonweelth Edison Co. 78/10/27. ip. 94042:296
- --7811090119 LERW77-015/03X-1 on 770402:CRD L-3 uncoupled & overtrevels6 when w/drawn to pos 48. Caused by unlatched inner filter & abnormally long uncoupling rod Procedure rev & GA coverage improved to prevent future CRD uncouplings.

  WUUCIGA. J. Commonwealth Edison Co. 78/04/02. 28p. 94042:297.
- 78i1090129 Forwards LER#77-022/03X-i. STEPHENBON,B.B. Commonwealth Edison Co. 78/10/27. lp. 94042;303.
- --7811090130 LER#77-022/03X-1 on 770605; CRD L-5 uncoupled & overtraveles when w/drawn to pok 4B. Caused by unistched inner Pilter & abnormelly long uncoupling rod, Procedure rev & GA caverage improved to prevent Puture CRD uncouplinge.

  WUUC1QA: J. Commonweelth Edison Co. 78/06/05. 28p. 94042:304.
- 7811090138 Forwerds LER#76-072/03X-1. BTEPHEN9DN.8.8. Commonwealth Edison Co. 78/10/27. 1p. 94042:319.
- --7811090142 LERN76-072/03X-1 on 761228:CRD J-11 uncoupled & overtrevelse when w/drewn to pos.48. An unlatched inner filter & abnormelly long rod resulted in coupling of CRD J-11.0A coverage improved & procedures rev to prevent uncoupling. HWUC10A.J. Cammanwealth Ediean Co. 76/10/27. 2pp. 94042:320.
- 781:140160 Forwards LER877-014/03X-1. 8TEPHEN9ON, B. B. Commonweelth Edison Co. 78/10/27. 1p. 94383; 311.
- ---78:1140163 LER#77-014/03X-1 on 770402: during normal startup oper,CRD H-B was found to uncouple & overtravel when withdrawn to pos 4B. Causad by an unlatched inner filter & abnormally long uncoupling rod.

  WUCIDA. J. Commonwealth Edison Co. 78/10/27, 2pp. 94383:312.
- 7811210304 LER#76-068/03X-1 on 761212: during 50X core screm testing CRD F-5 uncoupled & overtraveled when withdrean to position #48.Unletched inner filter & ebnormally long uncoupling rod resulted in uncoupling CRD F-5 during testing. #UUCIGA.J. Commonweelth Edison Co. 78/10/27. 2pp. 94486:103.
- 7811210301 Forwards LER#76-068/03x-1. 8TEPHENSON.8.8. Commonweelth Edison Co. 78/10/31. ip. 94487:334.
- 7811140193 Forwards LER#78-056/017-0. BTEPHENSON.B.B. Commonwealth Edison Co. 78/11/01. Ip. 94384:202.
- 7811140203 Forwards LERW77-029/03X-1 "Update". BTEPHEN8ON, B. B. Commonwealth Edison Co. 78/11/02. ip. 94384:342.

- --7811140213 LERW77-029/031-1 on 770802 during 1/2 core scram test.CRD8 F-5 & H-7 uncoupled when w/drawn to position 4B Caused by unlatched inner filter & abnormally long coupling rod A pull test has been incorporated into overhaul procedure • Commonwealth Edison Co 78/10/27 2pp 94384 343.
- 78i1140215 Forwards LER877-054/03X-1 STEPHENSON, B B Commonwealth Edison Co 78/11/02 lp 94400.033
- --781i140220 LER#77-034/03x-i on 77-ii02 during Unit 2 refueling outage. Control rod drivet(RDIH-5 overtraveled indicating uncoupling during functional testing Caused by unlatched inner filter abnormally long uncoupling rod

   Commonwealth Edison Co 78/10/27 200 94400 034
- 78if160122 Forwards Reportable Occurrence#77-054/03X-1 "Update." STEPHENSON.B. 8. Commonwealth Edison Co 78/11/02 1p 94135.182
- --7811160125 ROH77-054/03X-1 on 771102:CRD H-5 uncoupled during functional testing caused by unlatched inner filter & abnormally long uncoupling rod inner filter pull test in reassembly procedure & improved OA coverage incorporated HUUC19A, J. Commonwealth Edison Co. 78/10/27, 2pp. 94135 193.
- '811160112 Forwards LER#78-057/03L-0 STEPHENSON, B 8 Commonwealth Edison Co 78/11/09 ip 94135.138
- -7011160115 LER#7B-057/03L-0 on 781013 2-1402-4b flow test valve failed to close fully against pump pressure Caused by value being inadequately lubricated ACMTERBERG. J. Commonwealth Edyson Co. 78/11/09 2pp 94135:159
- 011210177 Forwards LERW78-058/03L-0. STEPHENSON.B. B. Commonwealth Edison Co. 78/11/13. ip. 94478:327
- -7811210181 LERM78-058/03L-0 on 781018: LPC1 suction valve MQ-2-1501-5C failed to close during operebility test. Failure treced to valve sten not being adequately lubricated. Lubrication interval anortened ACHTERBERG. J. Commonwealth Edison Co. 78/11/13 2pp. 94478-328
- -7812040195 LER#75-048/03-2 on 751007: during normal open a through-well crack was discovered in drywell-torus nitrogen surge line 1604-18. New startup procedure has been written incl procedure. PULLO, R. Commonwealth Edison Co. 78/11/17. 2pp. 94457-116.
- \$12150270 Forwards LER#78-061/03L-0 8TEPHENSON.B B Commonwealth Edison Co. 78/12/08 ip. 94213:162.
- 7812130272 LER#78-061/03L-0 on 781108 AN-2-1601-24 failed to close due to solenoid valve stuck open u/dirt in valve internals Solenoid valve replaced tested & returned to svc PARCELL Commonwealth Edison Co. 78/12/08. ip 94213.163.
- 12180223 Forwards LERM78-062/03L-0.
  BTEPHEN9ON, B O. Commonweelth Edison Co 78/12/08. 1p. 94366:131.
- 7812100228 LERM78-062/03L-O on 781113-AO 1601-56 velve feiled in closed position Caused by shorted out coil on solenoid Solenoid coil b fuso replaced by valve verified operational. CLESZKIENICZ. B. Commonwealth Edison Co. 78/12/08. 1p. 974365; 132
- 12270300 Forwards LERW78-033/03X-t.
  31EPHENBON.B.B. Commonweelth Edison Co 78/12/12 1p. 94230:334
- '812270332 LER#78-033/03x-1 on 780322 during test performed on U-2 D/0 to measure overshoot & dverspeed setpoint, the diesel tripped 4 times due to overspeed caused by governor speed set too high CHAN. J. Commonwealth Edison Co. 78/12/12 2pp. 94230: 335.
- 2210189 Forwards LERW78-063/03x-0. .

  fEPHENSON, B. B. Commonweelth Edison Co. 78/12/15. 1p. 94278: 340.
- 812210195 LERAT8-063/03:-0 on 781003: "A" pump flow was 2.6 SCFM; "B" gump was 0.0 SCFM (flow greater than 2.9 SCFM is normal). Caused by improper velve lineup & normal wear products from carbon impoller venes on sample lines, pump cavity & filter. WEIONER, R Commonweelth Edison Co. 78/12/15, 3pp. 94278.341.
- 2270261 Forwards LERW78-063/03L-0. TEPHENSON.8.8. Commonwealth Edison Co 78/12/19 1p. 94232:331

- 7812290210 Forwards LER#78-064/03L-0 BIEPHENSON.B B Commonwealth Edison Co 78/12/21. 1p 94190
- --7812290215 LCRM78-064/03L-0 on 781124 leak found ist 5"x6"x4" ed on the 2/3 waste collector tank recirculation 1 tho Coursed by acid corresion of carbon steel side of velocarbon steel flahee will be replaced w/flange of stainless at coll JANSEN.T Commonweeith Edison Co. 78/12/21 1 p. 94190 349
- DOCKET 50-243 OREGON STATE UNIV. REGEARCH REACTOR

  9 Inspection reports, IE Builetins & correspondences
- 7812270432 Forwards IE Inspec Rept#50-243/78-03 on 781024-26 durf which no items of noncompliance were noted. CREUS.J L. Region 5. Sen Francisco. Reactor Operations Nuclear Support Branch 78/11/22. 2pp 94312-342
- --7812270436 IE Inspec Rept#50-243/78-03 on 781024-26 during which items of noncompliance were noted Hajor areas immapocted logs & records/review & audit-requal training procedures, refueling, surveillence, experiments & tour of fac 3 length L.P.J. CARLEON, J.C. Region 5, San Francisco, Heatter Operations Nuclear Support Branch 78/11/29 Spp. 94312 14
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

  F. Security, madical, emergency & firs protection plans
- 781025001B Request for edd1 info on fire protec grog & protec of spreading(relay)room.
  ZIEMANN.D L Operating Reactors Branch 2 (Pre 7406251. 70/10/6pp.
- 7810170257 Responds to 780913 ltr requesting info see proposed fir protect structurel design mod. Items 1.2. & 3 of request are ensured [lems 4 & 5 were ensured in fire protect authoriting of 780922.

  WHITE-L.D. Rochester Oss & Electric Corp. 78/10/11. 4pp 74236: 346.
- 7811060088 Forwards responses to 3 of 5 questions submitted in 70 ltr re fire protec. Add1 time is necessary to respond to questions 78 & 79.

  WHITE-L.D. Rochester Oas & Electric Corp. 78/10/31. 11pp 94424:105
- 7812130012 Forwards rev pages of fecil security plans (MAEH), Requesithholding from pub disclosure pursuant to 2 790.
  WHITE, L. D. Rochester Oas & Electric Corp. 78/12/023, 1p.
  94306:326
- Q. Adjudicatory correspondence
- 7810230238 Forwards Appl for Amend to Oper LiceOPR-18 Toch Spec & for \$4000. LAREON.L.K. LeBoeuf, Lemb. Leiby & MacRae. 78/10/12. Lp. 94052:245.
- 7810230256 Appl for amend to License DPR-18 to review Tach Specin App A re DC electrical sys operation requirements.

  WHITE, L. D. Rochester Oss & Electric Corp. 78/10/10. 11pp.
  94052:244.
- H. General correspondence
- 7810310173 Informs that for SER normal channel of Oral communication between subj fecil staff & members of SEP is encouraged.

  ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 7906R3). 70/10/2pp. 74070:227.
- J. Insurance & indomnity information
- 7811290245 Forwards Endorsement#57 to Liability Policy#NELIA NR-8 Endorsement#47 to Policy#MAELU MF-47. HHITE, L. D. Rochester Gas & Electric Corp. 78/11/16. 3pp. 94237:197.

- P. Operating license stage documents & correspondence
- 7811130304 Requests add1 info on pressure shielding start diaphragm in turbine bligs so that ORB#2 can continue eval of mode. ZIEMANN,D L. Operating Reactors Branch 2 (Pre 790625). 78/09/13. 3pp. 94087-241.
- 78:10:60:29 Requests 60 days deferred on response to 7807:1 itr requesting proposed Tech Specs to implement Append I to 10CFR30 Add I time required due to implementing improvements in Health Physics Prog.
  HHITE.L.D. Rochester Gas & Electric Corp. 78/10/10. 1p. 9400A DAA
- 7810170182 Forwards response to 780906 ltr This response is not complete & is pending review w/other BEP utils. Final response will be submitted on or before 781130.

  WHITEL D Ruchester Oas & Electric Corp. 78/10/11. Ip. 94270:071.
- ~-7810170263 Responde to 780906 itr re overpressure protec sys at subj Psc il. Superior eddl alarms have replaced original computer alarm. Tech space submitted 781011 do not inci relise? valve testing & testing requirements. WHITE.L. D. Rochester Gas & Electric Corp. 78/10/11. ip. 94270.072.
- 7810160108 Forwards appl for smend to open lic & snc1 which set forth requested changs in Tech Specs. Tech besis for change, & tech info asserting change is of no safety or environ significance
  LARGON,L. N. LeDbeuf, Lamb, Leiby & MacRae 78/10/12 App. 94001.326.
- --781016031: Appl for amend to operating lic.Requests that Tech Epocs to lic be emended to add definitions for surveiliance intervals Encl pafety eval shows proposed change does not involve change or increase in amounts of effluents.
  WHITE.L. D. Rochester Gas & Electric Corp. 78/30/10. Spp. 94001: 330
- 7810310243 Deniel of PASN's appl for extension of period of interim oper using the installed once-thru cooling sys. Denial based on NRC deference to EPA decision & NRC desire to evaluate that decision before taking action.

  8ALLARD. R. L. Environmental Projects Brench 1. 78/10/13. 3pp. 94091-325.
- 7810180148 Farwerds Appl for Amend to Oper Lic. LARSON-L.K. LeBoouf, Lamb. Leiby & Hackae. 78/10/16. 2pp. 94316:345.
- --7B10180130 Appl for amend to license DPR-18 requesting Tech Specs be changed to rev organisation. Safety Eval & Fes Datarmination are encl. WHITE.L.D Rochester Oas & Electric Corp. 78/10/11. 11pp. 94316:347.
- 7810310147 Ack receipt of 780905 itr re Systematic Eval Prop documentation procedures.Forwards response to util comments. ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/17. 28pp. 94090:179.
- 7810190068 Forwards Appl for amend to open lic#DPR-18 w/requested changes in Tach Space & check for \$4000 to cover appropriate fee.

  LARBON-L.W. LeBosuf, Lamb, Leiby & MecRae. 78/10/18. 3pp. 94413. 113.
- --7810190069 Appl for Amend to Oper LicHDPR-18 w/proposed Tech Spec chenge to include reactor overpressure protect sys requirements, safety eval & justification for classification of emend. HHITE, L. D. Rochester Gas & Electric Corp. 78/10/11. 15pp 94413:118.
- 781:1060172 Burmary of 78:1004 mesting re prog for review & avel of pipe breaks inside subj fecil containment structure. Topics incl aspects of pipe breaks, asymmetric LDCA loads. Mechanistic Approach & costs of addl pipe stress calculations.

  JABBOUR, K. N. Bystematic Evaluation Programs Branch (Fra 770625).

  BHEA J. J. Operating Reactors Branch 2 (Pra 770625). 78/10/20. 6pp. 74487:097.
- 7811100:52 Requests add1 info on EEF Guitchover from injection to recirculation mode, isolation of reactor protec sys from nonsefety sys. ESF sys logic & design.epecific drawings of elec sys & complete plant elec drawing indices. ZIEPANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/26. Gpp. 94047:182.

- 7811070142 Revises sched for completion of Hestinghouse work re resolution of upper planum injection of ECCS water due to resolution of Zirconlum-water inconsistency. Also forwards sched of Esson Nuc Corp work on UP1.

  WHITE, L. D. Rochester Gas & Electric Corp. 78/10/31 2pp. 94044-020
- 7811070182 Proposes to perform radiographic examination of reactor coplant pump casing welds during 1981 refusling & maint outage using portable Linac X-Ray unit by Elec Per Res instead which should be evaliable in 1980.

  WHITELD. Rochester Gas & Electric Corp. 78/11/01. 2pp. 94036.399.
- 7811130315 Rept on 780906-07 site visit & 780908 meeting w/util. Examined site & obtained hydrological info FONTECILLA-H.M. Bystematic Evaluation Programs Branch (Pre 790625). 78/11/02 10pp. 94087:043.
- 7811130232 Notifies that Provisional Oper LicmDPR-18 issued on 780328 omitted Tech Specs for piping penetrations w/sxpansion belique. Lealage testing w/sir medium is not req for containment penetration sys.

  WHITE L.D. Rochester Gas & Electric Corp. 78/11/03. 1p. 03554: 159.
- 7811140241 Furnishes add1 info re 781004 meeting to discuss BEP Topic 3-5.A.High Energy Line Breaks Inside Containment Discusses pipe stress calculations.high energy line break outside containment, Generic Test A-2 & Asymmetric LOGA loads. WHITE.L. D. Rochester Ces & Electric Corp. 78/11/08. 2pp. 94400:099.
- 7811280430 Forwards draft Bys Eval Prog Safety inputs re Topic VIII-3.
  A. Stetion Battery Test Req. Requests they be transmitted to
  licensess.
  DAVIS.D.K. Bystemetic Evaluation Progrems Branch (Pre 790625).
  78/11/14. 23pp.
- 7812130176 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attenders to facilitate sending out matl. W/encl Registration Form & List of Locations. MILLER, J. R. Assistant Director for Bits & Bafeguerds (Pre 791030). 78/11/15. Spp.
- 7812190054 Forwards RevW1 "Draft Rediological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Rediological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133). QRIMEB.8.K. Assistant Director for Engineers & Projects (Pre 790425). 78/11/18. 6pp. 94815:075.
- 7811270260 Ack receipt of request for approval to employ the esisting cooling sus for full core discharge sched for early Spring 1979 et Ginna. Request falls in Class III appl for lic amand & util is requested to forward 64.000.
  MILLER.W. O. License Fee Management Branch. 78/11/17. 1p. 94272: 004.
- 7811280216 Opecribes fuel inepec plans for 1979 shutdown At and of present Cycle 8,8 to 10 Exxon fuel assemblies will be inapec visually withinoculers. Shutdown & inepec planned for lats Feb & sanly Narch. 1979.
  WHITE, L. D. Rochester Gas & Gisctric Corp. 78/11/20. 2pp. 94012:061.
- 7812070146 Notice of seminer on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants. Requests advance submission of seminer specific questions. W/encl Saminer Info Shest.Proposed Agenda & maps.
  ORIER. B. H. Region 1. Philadelphia. Office of the Director. 78/11/21.
- 7811290179 Forwards add1 drawings for systematic eval prog(SEP)in response to 780626 request. Proprietary drawings will be provided under cover. 26 oversize drawings in Central Files. WHITE, L. D. Rochester Gas & Electric Corp. 78/11/22. 443pp. 94474: 218.
- 7812010373 Rept on 781109 measurement of nuc pur reactor environ to determine capability of existing personnel dosimetry sys et subj facil. Results will be forwarded to NRC for study. Util cooperation was examplery.

  BLOCK. 8. Environmental Evaluation Branch (Pre 790625). 78/11/24.

  2pp. 94416:334
- 7812060303 Notification of 781207 meeting w/BEP Dwner's Group in Bethesds.MD to discuss plans to address seismic input for use in BEP seismic review. LEVIN.H.A. Bystsmatic Evaluation Programs Branch (Pre 790625). 78/11/24.

- from reactor vessel 15 days after shutdown per existing Tech Specs. Refueling should proceed so reactor vessel inspec can be accomplished. ZIETHANN. D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/27. 3pp. 74127: 232.
- 7812140316 Forwards Amend#20 to Provisional Oper Lic#DPR-18 & Notice of Issuance.
  ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/27.
  3pp. 03556:330.
- 7812110038 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wencl AND 47812080207.

  ZIEFFANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29.

Bpp. 94408: 147

- 7812050152 Forwards "Ginna Stetion Insvc Pump & Valve Test Prog for the Period 790501-801231: " Append C to Period Quelity Assurance Manuel.

  WHITE L.D. Rochester Ges & Electric Corp 78/11/30 3app. 94318:309.
- 7812090187 Responds to 780906 NRC request for review of environ qualtable for size equip at subjecti. Forwards requested into & rev pages for initial 780224 environ qual rept. Facil does not use connectors or junction boxes.

  HHITE-L D. Rochester Ges & Electric Corp. 78/12/Q1. 31pp. 94335:176.
- '812080123 Bummary of 781004 meeting re High Energy Line Breaks inside Containment. Add1 info is being gethered on this subj. WHITE-L.D. Rochester Ges & Electric Corp. 78/12/04. 1p. 94106:335.
- '812080128 Forwards ref list inadvertently omitted from encl of Environ Qual of Elec Equip Rev 1 submitted 781201.

  WHITE L.D. Rochester Ges & Electric Corp. 78/12/04. 2pp. 74100:349.
- 812280075 Emphasizes importance of submitting accurate & complete info to NRC by licensees & epplicants. Info submitted must be substantiated by dete & calculations. Licensee must notify NRC of eny inaccuracies, or enforcement action will result. DAVIS.J.O. Office of inspection & Enforcement, Office of the Director. 78/12/06. App. 03555:191.
- 812150101 Requests add1 info from SEP licensess re elec penetrations of reactor containments in order to complete avai.
  11EMANN-0.L. Operating Reactors Branch 2 (Pre 790625). 78/12/08.
  4pp. 94212:058.
- 312210021 Forwards NURE9-0485.Vol 1.No 2 "Btatus Summery Rept-Bys Evel Prog." W/o encl. 21EMNN.D.L. Operating Reactors Branch 2 (Pre 790625): 78/12/08: 2pp. 94249:337.
- HERMOO47 Forwards AmendWR1 to Provisional Oper LicMDPR-18 revising Tech Space as requested in 780508 itr w/8efety Eval & Notice of issuance.
  HERMANN.D.L. Operating Reactors Branch R (Pre 790625). 78/12/08.
  2pp. 94269:019.
- 7812210050 Amend#21 to Provisional Oper Lic\*DPR-18 revising Tech Speca re reduction in maximum pressurizer heatup rate from 200F per hour to 100F; reduction in frequency of tests for Low Nuc Pur 25% trip setpoint & elimination of valve test.
  21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/08.
  78p. 94265:021.
- 7812210052 Sefety Evel Rept supporting Amend#21 to Provisional Oper LickDPR-1B concluding that proposed changes are acceptable & heelth & sefety of public will not be endangered by oper in proposed manner. • Office of Nucleer Reactor Regulation, Director. 78/12/08. App. 94269:028.
- 7812210055 Notice of Issuence of Amend#21 to Provisionel Oper LiceDPR-18. ZIEMANN, Q. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94269:032.
- 2260010 Notice of 780110 meeting to discuss 10CFR50 Tech Spec equirements for subj facil.
  HEA.J. Operating Resctors Branch 2 (Pre 790625). 78/12/13. 3pp. 94020:303.

- Full-Term Oper Lic.& RevA4 to Suppl 1V to Applicant's Tech Suppl Accompanying Appl for a Full-Term Oper Lic FARON.R. B LeBoauf, Lamb, Leiby & MacRae 78/12/21 43pp. 94344: 144.
- --7812220118 Amend 8 to appl to convert Provisional License DPR-18 to full term license. Amend transmite Rov#4 to Suppl IV to applicant's tech suppl accompanying appl for full term oper lic. Cert of Svc encl.

  HHTTE.L. D Rochester Cas & Electric Corp. 78/12/Ob. 2pp. 94344:062.
- 7812290090 Atk receipt of 781115 ltr from NRC providing ROE w/rev Standard Tech Specs re radiological effluents Due to delay in reteipt of itr & to provide time for reviews. RGE plans to submit proposed Tech Specs by 780210161c). HMITE.L.D. Rochester Ose & Electric Corp. 78/12/21. 1p. 74190:111.
- O Inspection reports. IE Bulletine & correspondence
- 7810180177 Forwards IE Inspec Rept#50-244/78-18 on 780814 during which no items of honcompliance were noted BRUNNER.E.J. Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/09/05. Spp. 94317:129
- ---7810180179 IE Inspec Rept#30-244/78-18 on 780814-10 during which no teams of nancompliance were noted Major areas inspected included; plant operatetes of previous inspecs findings, them & voi control eys. followup actions.

   Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/05. 15pp. 94317:131.
- 7B11060174 Forwards IE Circuler#7B-17, (See AND: 7810230R21. Doctet #30-133, 781013.)
  GRIER, B. H. Region 1, Philadelphia, Office of the Director.
  7B/10/13. ip. 94489: 108.
- 7812010147 Forwards IE Inspec ReptW50-244/78-19 on 780919-21 during which no items of noncompilence were noted.

  8MITH.O.H. Region i, Philadelphie, Fuel Fecility & Materials Bafet Branch. 78/10/18. 2go. 94418:089.
- --7812010150 IE inspec Rspt#50-244/78-19 on 780919-21 during which no items of noncompliencs were noted. Major areas inspected incliprog for quelity control of analytical neasurements, audit results & effluent control procedures.

  KOTTAN.J.J., BTOHR.J.P. Region 1, Philedelphia, Fuel Facility & Material's Serety Grench. 78/10/18. 9pp. 94418:091.
- 7811010036 Responds to 780323 & 780728 itre protesting proposed clv11 penetities eterming from Inspect50-244/78-03. Item 9 of Inspectest is recebegarized as a deficiency, reducing genalty from \$31,000 to 994,000.
  DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director. 78/10/94. 3pp. 94302:249.
- --7Bii010041 Orders licensee to pay civil penelties of 624.000 within days because of noncompitance in Notice of Violation resulting from inspac on 7B0120-7B0203 & 7B0213-17. W/anci Appendices: correspondence re mitigation of panelty. DAV18.J. 0. Office of Inspection k Enforcement. Office of the Director. 7B/10/20. 4pp. 94302:245.
- 7812060298 Forwards 1E Inspec Rept#50~244/78-20 on 780927-28 during which no items of noncompliance were noted.
  BRUNNER.E. J. Region 1, Philadelphie, Reactor Operations Nuclear Support Branch. 78/10/27. Spp. 94382:231.
- --7812060304 IR Inspec Rept#50-244/78-20 on 780927-28 during which no items of noncompliance were noted. Mejor areas inspected inclicated splice insulation & 918 reast feature. RAYMOND, M. J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/10/27. Bpp. 94382:233.
- 7811390154 Forwerds IE Circular #78-18, "UL Fire Test. "W/encl AND: 7811150002.
  GRIER, B. H. Region i, Philadelphia, Office of the Director. 78/11/04. 1p. 94239:357.
- 78:2180032 Forwards IE Bulletin#78-12A. Buppl to IE Bulletin 78-12. W/encl AND:78:1300085. ORIER. B. H. Region 1, Philadelphia, Office of the Director. 78/11/24. 1p. 94133:009.
- 7812130318 Ack receipt of 781110 ltr & check in the amt of \$24,000 remitted in full payment of Order Imposing Civil Monetary Penalties dtd 781020.

  BRYAN, S. E. Repton i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/12/06. ip. 94306:338.

- R Periodic operating reports & related correspondence
- 7810170213 Forwards Monthly Oper Rept for Sept 1978 BNDH B Rochester Gos & Electric Corp 78/10/06 ip 94236-145
- --7810170215 Honthly Oper Rept for Bept 1978.
  MCNAMARA, A. E. Rochester Oas & Electric Corp. 78/10/05. Spp. 94234 146
- ODCKET 30-245 MILLSTONE NUCLEAR POWER STATION. UNIT 1 8. Utility Prelyminary Bafety Analysis Report, amends
- 7811240189 Emergency Plan Unit 1 Final Bafety Analysis Rept Append O. Amend 37 & Emergency Plan Unit 2 Final Bafety Analysis Rept Append 12A. Anend 45. covering organizational control of emergencies.coordination w/off-site groups & protec actions.

  \* Northeast Utilities. 78/11/17. 100pp.
- F. Security, medical, emergency & fire protection plans
- 7811290148 Finds changes to Site Security Plan submitted 781004 de not decrease the effectivness of the Pion & are acceptable ZIEMANN,D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/15 2pp 94239 333
- Q. Adjudicatory correspondence
- 7811020323 Forwards recent memorands re certain problems experienced in connection w/pipe support base plate design. Staff is determining if these problems have generic implications for oper facils & will keep Lic Bd informed of any new info. ORAY. J. R. Office of the Executive Legal Director 78/10/19 lp. 94240-221
- --78ii020332 Forwards 780628 memo to R Mattson, re into on failures of safety-related pipe supports at Millstone 1 & design deficiencies on similar equip on Shorsham 1. Hemo gives Bd notification of pipe support base plete design.
  BEELLO, V Division of Operating Reactors 78/09/28. 2pp. 94240, 222.
- ~-7811020393 Addresses pipe support base plate problem Discusses review of support redesigns & cepability of the anchor boits to withstand cyclic loadings.

  NCOMAN. V S. Engineering Branch (Pre 791030). 78/06/02. 2pp. 94240 228
- H General correspondence
- 7810310037 Informs that for BEP normal channel of oral communication will be followed, but to appedite reviews direct oral communication between subj facil staff 6 members of BEP branch is encouraged.

  ZIEFANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/10 2pp. 94094-360.
- K. Utility Final Bafety Anelysis Report (FBAR) & amends
- 7811240187 Forwards Append Q of Milistons Unit i Finel Sefety Analysis Rept & Append 12A of Millstone Unit 2 Finel Sefety Analysis Rept Covering site emergency plan. These have been designated Amendment Nos 37 and 45 respectively.

  COUNGIL, N. Q Northeast Utilities. 78/1/17. 2pp.
- P Operating license stage documents & correspondence
- 7812050004 Forwards Licensee Performencs Evel Questions for subj facils in response to 771123 request. Feels it is possible that dev of statistical methodology for such evel mey not justify the effort. Qualitative sval may be as good. Urgss I-year tsst. ORIER, B.H. Region I. Philadelphia. Office of the Director. 77/12/13. 12pp. 94200:114.
- 7811130088 Forwards Initial eval of 8 complete SEP topics & response to request Por clarification of SEP documentation procedures made at 780331 meeting. Requests response re facts used to define plants by NRC staff. (See AND#7811130337.) EISCHHUT. D.Q. Assistant Director for Systems Engineering (Pre 791030). 78/08/17. 2pp 94076:334.
- 7810110070 Forwards Amend#85 to Facil Oper Lic#DPR-21 revising Tech Bpecs as requested in 780303 ltr u/Safety Evaluation & Notice of Issuance. ZIEMANN.D. L. Operating Reactors Brench 2 (Pre 790625). 78/09/26. 39p. 94064:045

- --7810110073 Amend #53 to Facil Oper Lic#DPR-21 revising Tech Specs re to require 3 operable fire pumps & add1 spray &/or sprinkler sys & fire hose stations to be operable in the turbine bldg. ZIEMAWN,D L. Operating Reactors Branch 2 (Pre 790625). 78/09/26. 10pp. 94061.050
- --7810110074 Safety Evaluation Rept supporting Amend#33 to Facil Oper Lic #DPR-21 concludes that the fire protect plan assures that 14 the public health & safety will be protected a Office of Nuclear Reactor Regulation, Director. 78/09/26, 33pp. 94061.059
- --7810110075 Notice of Issuance of Amend#53 to Fec11 Open Lic#DPR-21 on 780926 WAMBACH,T V Operating Reactors Branch 2 (Pre 790625). 78/09/26 3pp. 94061:111
- --7810110076 Submits evaluation of SER. Recommends change in valve supervision
  HALL:R E Brookheven National Laboratory 78/08/23. 2pp 94061:114
- 7810110140 Forwards rev plant unique assessment of multiple consecutive safety/relief valve actuations, but w/o using staggered & elevated SRV setpoints as originally submitted on 780731.

  CDUNBIL.H.O. Northeast Utilities. 78/10/04 i2pp. 94064:262.
- 7810110176 Responds to requirements re undetected single failure to adversally affect reactor protects. COUNBILLY 0 Northeast Utilities 78/10/06. 2pp. 94069:100.
- 79:0:30:39 Performance evaluation of process radiat monitoring sys redetecting fuel leakage. There have been no ebnormal fuel related events resulting in sufficient coolant ectivity changes. Honitors very sensitive to pur level changes.

  CDUNSILW Q. Northeast Utilities. 78/10/10. 2pp. 94003:045.
- 7810170140 Objects to request to follow Unit 2 re 740516 emergency plan as unwerranted & imprectical.Matter was discussed w/IE & NRR who agreed that Rev 4 af 770805 will remain in effect at this time Rev 5 should be issued by 781115.

  COUNSIL, N. O. Northeast Utilities. 78/10/10. 2pp. 94235:359.
- 7810240099 Reiterates that NRC Blaff concurrence will be obtained before new high density spent fuel racks are used in either the originally lic configuration or in less than optimum pattern

  COUNBIL. N. O. Northeest Utilities. 78/10/13. 2pp.
- 7810270203 Forwards proposed rev to Environ Tsch Spec & to SsPety Yech Spec for subj facil.psrmitting the STB & STB to become two independent documents.

  COUNBIL, N. O. Northeest Utilities. 78/10/20. 35pp. 94036: 313.
- 7810310073 Informs of piens to resolve Staff concerns re seismic loads & Multiple Safety/Relief Value ectuetions. Util will reinforce outer torus support columns to meet short-term ecceptance criterie w/o question by mid-Dec. 1978. COUNSIL, W. O. Northsest Utilities. 78/10/23. 1p. 94094:312.
- 78:1010166 Notifies that licenses intend to enter into certain sale 1 leaseback arrangements in order to finance constr. of a refuel outage bldg at Millstone site. Various espects of financing are described.

  OARFIELD. 0. Day, Berry & Howard. 78/10/25. 5pp. 94391:239.
- 7811130335 Surmary of 780914 meeting w/GE representatives & Merk 1 Owners Group re progress of Long Term Prog w/ettendance list & agenda (RD-9-A-Merkl, Stendards.) GRIPES.C. Pient Systems Shanch (Pre 791030). 78/10/26. 67pp.
- 7811070208 Responds to 780928 FOIA request for documents submitted to EJ Brunner re a besslins eval for RIP. The NRC hes located no documents subject to this request. FELTON.J.M. Division of Rules and Records. 78/10/31. 1p. 94040: 339.
- --7811070294 FDIA request for repts submitted to EJ Brunner rs baseline eval for RIP. M/encl 780630 Brunner memo. JOHNSON: L. C. Affiliation Unknown. 78/09/28. 1p. 94040:340.
- 7811130193 Forwards "Boron Carbide" rept prepared by Carborundum Codescribing requal prog tests & results re subj facils.

  Answers to NRC queries & other analyses are elso encises is non-proprietary version of Carborundum rept.

  COUNBIL.W. Q. Northeast Utilities. 78/11/03. 14pp.

- '81i140155 Discussee Progress of NUSCO Nuc Records Prog for CN Yenkee Atomic Pur & NE Nuc Energy Co Hitrofilming may not be completed by 790731.but hard copy util be evaliable Asks whether projected 790731 date util be settificatory COUNSIL.H Q Northeast Utilities. 78/11/06 2pp 94383 304
- B11290288 Responds to 781105 request for info concerning licensee reg performence eval for Region 1 plants by NRC Provided details
  ORIER H. Region 1. Distance the Director
- ORIER, BH Region I. Philadelphia. Depice of the Director. 78/11/09. 9pp
- Bi1280430 Forwards draft Sys Eval Prog Safety inputs re Topic Viji-3 A. Station Battery Test Rag Requests they be transmitted to licensess
  DAVIS.D. N. Bustacette Evaluation Programs Branch (Pro 790405)
- DAVIS,D.R. Systematic Evaluation Programs Branch (Pre 790625) 78/11/14. 23pp
- B12150097 Notice of workshops re implementation of training & quatrequirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendess to facilitate sending out meti Wienci Registration Forn & Liet of Locations MILLER. JR Assistant Director for Site & Safaguards (Pre 791030) 78/11/15 Spp. 94212-006.
- 112180253 Forwards RevM1 "Draft Rediological Effluent Tech Specs" Por BUR's (NUREQ-0473) & "Praparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREQ-0133) GRIMERS K. Assistant Director for Engineers & Projects (Pre 790425) 78/11/15 App 94365, 290
- II2210066 Responds to 781116 telecon. Forwards copies of ANS meeting papers which demonstrate attention to ALARA per RGB.8. D'HARA:JC. Ebasco Services, Inc. (subs. of Enserch Corp.). 78711/17. 19
- 7812210070 "Experience in Decontamination & Repair of Redwaste Concentrator at Milistone Unitell " Describes procedures SWMAJ Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/11/17. 19pp.
- 7812210074 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Cham Contamination & Spal Ring Repairs." Describes work performed In 1977 & 1978. ROWNER.M.M. Philadelphia Electric Co. 78/96/96. 22pp.
- 7812210077 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Cham Decontamination & Solidification," Describes work performed in 1977. CASEY, 6. E. Dow Chemical Co. 78/02/16. 38pp.
- 11270183 Responde to 780817 request for comments on Bystematic Eval rog topic essessments. Info is substantively correct, but it is suggested that these & future sessements be written w/ specific ref to documents used by NRC to form conclusions.

  COUNCIL.H G. Northeast Utilities 78/11/20 1p. 94272-081.
- .2070166 Notice of seminar on 781208 on new Model Radiological iffluent Tech Space for nuc pur plants. Requests advance submission of seminar spacific questions H/encl Seminar Info heat. Proposed Agenda & maps.
  RIER. B. H. Ragion i, Philadelphia. Office of the Director. '8/11/21. Spp. 03355:128.
- 2060303 Notification of 781207 mesting w/8EP Dwner's Group in ethesds/MD to discuse plans to address seismic input for se in 8EP seismic review. EVIN, H.A. Bystematic Evaluation Programs Granch (Pre 790625). 8/11/24 2pp.
- 2140318 Amend#20 to Provisional Oper Lic#DPR-18 revising Tech Epecs o define existing requirements for survaillance frequency. IEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/27. pp. 03556:353.
- 812140339 Notice of Issuance of Amend#20 to Provisional Oper Lic #DPR-18 revieing Tech Space to define existing requirements for surveillance frequency. 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790623). 78/11/27. 2pp. 03056:357.
- 2110019 Discusses possible dangers of LDCA in containment purging using normal plant oper. Requests either commitment to limit using or justification for continuing. W/snc1 ANO: 7812080207.

  [EMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. 19. 94339:271.

- 7812110328 Approves proposed schedule for installing feedwater pump trip during refueling outage, currently scheduled for 1979 ZIEMAMN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/30 2pp 74204 280
- 7812140024 Forwards Amend#34 to Provisional Oper Lic#DPR-21 for subj facil as requested in 780320 ltr Wiencl Bafety Eval & Notice of Essuance ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/12/01 2pp 94127 238
- --7812140027 Arend#34 to Provisional Oper Lic#DPR-21.rev provision of Append A Tech Space to allow in-place testing of Standby gas Treatment Bys at lower flow rates IIEMANN.D L. Deprating Reactors Branch 2 (Pre 790625). 78/12/01. 7pp. 94127-240
- --7812140030 Refety Evaluation Rept Bupporting Amend#54 to Provisional Oper Lic#DPR-21 concluding that proposed change is accepteble & safety of pub will not be endangered # Office of Nuclear Reactor Requisition. Director 78/12/01 2pp 74127.24
- --7812140034 Notice of Issuence of Amend#34 to Provisional Oper Lic #DPR-21 to allow in-place testing of Standby Gas Treatment Bys at lower rates. 71EMAN.D L. Operating Reactors Branch 2 (Pre 790623) 78/12/01 20p. 94127
- 7812080121 Forserds list showing clerical logistics & reasons for each change to Gefsty Tach Space for subj facil List inadvertently omitted from util 781020 ltm COUNTIL N. 0 Northwest Utilities. 78/12/04 9pp. 94106:326
- 7812130322 Forwards Tech Spec pages 3/4 2-6 & 2-7 omitted from Amend 34 due to clerical error 21EMANN.D L Derating Reactors Branch 2 (Pre 790625). 78/12/04. 4pp. 94307.058
- 7812140176 Forwards Oct 1978 Prog Activity Revised listing meetings held & providing task-by-task activity summary for the manth BOSCN, L. J. Osmeral Electric Co. 78/12/04. 11pp
- 7812150072 Forwards Amend#55 to Provisional Oper LicMDPR-21 & Amend 44 to Facil Oper LicMDPR-65 & Notice of Issuence ZIEMANN.D. L. Operating Reactors Oranch 2 (Pre 790625). 78/12/04. 3pp. 49210 292
- --7812150077 Amend#55 to Provisional Oper LicaDPR-21. Changes lech Space re-redioactive liquid sampling & analysis ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/04 2pp. 94210:295.
- --78121500B2 Amend\$44 to Fatil Oper LicMDPR-65 Changes Tech Space re radioactive liquid sampling & analysis. REID.R H. Operating Reactors Brench 2 (Pre 790625). 78/12/04, Spp. 94210:297.
- --7812150086 Notice of Issuence of Amend#55 to Provisional Oper Lic #DPR-21 & Amend#44 to Fec11 Oper Lic#DPR-65 ISEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/12/04. Rop
- 7812190176 Responds to 780203 & 781020 itrs. Concludes, that since implementation of Append I Tech Specs will cover items proposed by requests plan to defer ection on these requests so they are reviewed concurrent w/Append 1 implementation. IIEMANN.D.L. Operating Reactors Granth 2 (Fre 790525). 78/12/05. 200. 94340-055.
- 7812260012 Intends to apply quality assurence requirements 10CFR50 Append B & 10CFR71 to delivery of metly to a carrier for transport or transport of euch matle outside confines of site in Comm approved package design.

  COUNSIL.4.0. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/12/05. ip. 94020:307
- 7812280135 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants, info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. O. Office of inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94311:312.
- 7812150105 Requests add1 info from BEP licensees relect penetrations of reactor containments in order to complets eval.

  ZIEMANN.D.L. Derating Reactors Branch 2 (Pre 790625), 78/12/08.

  App. 94212:085.

- 7812180143 Informs that reinforcement of all outer torus columns 14 complete Short Term Program strength ratio is now 0 353. COUNSIL, W O Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 78/12/08. 10 94365:278
- 7812210031 Forwards NUREG-085. Vol 1. No 2 "Status Summary Rept-Bys Eval Prog " W/o encl. ZIEMANN.D L OP 200 94249.355. Operating Reactors Branch 2 (Pre 790625) 78/12/08
- 7812260285 Forwards Amend#36 to Provisional Oper Lic DPR-21 & Amend#45 to Facil Oper LicaDPR-65 revising Tech Specs es requested in 14 ltrs between 770221 & 780321 w/Safety Evel & Notice of Issuance. Operating Reactors Branch 4 (Pre 790625) 78/12/04. 4pp.
  - 74155: 280.
- --7812260289 Amend#36 to Provisional Oper LiceDPR-21 revising Tach Specs re admin controls to reflect organizational struc & greater flexibility of entry into high radiat areas.
  ZIEMANN. D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 20pp. 94155: 264.
- --7812260295 Amend#45 to Facil Open LicHDPR-65 revising Tech Specs re refueling water storage tank sump recirculation ectuation estpoint engr eafaty features response times incore detector cperability, metaorological monitoring instru & admin REID.R W. Operating Reactors Branch 4 (Pre 790625). 78/12/08. 620p. 94160 050
- --7812260301 Sefety Evel Rept Supporting Amend#56 to Provisionel Oper Lic #DPR-21 & Amend#45 to Fecil Oper Lic#DPR-65 concluding that proposed changes are acceptable & selety of public will not be endangered by oper in proposed manner. » Defice of Nucleer Reactor Regulation, Director, 78/12/08
- --7812260006 Notice of issuance of Amend#36 to Provisional Oper Lic #DPR-21 & Amend#45 to Fecil Oper Lic#DPR-65. REID.R. W. Operating Reactors Branch 4 (Pre 790625). 78/12/08. 3pp. 94136:020.
- 7812190083 Internal "plant design change procedure" for the purpose of venting high density spent fuel racks has been processed & approved Change does not constitute on unreviewed sefety question COUNSIL. N. O. Northeest Utilities. 78/12/12. 2pp 94343:018.
- 7812050013 Requests views of Regional Directors on Licenses performance eval of subj facile. Forwards questions to be enswered by 771209. THORNSURG. H Division of Reactor Construction Inspection. 77/11/23.
- 7812270462 Notice of 790111 meeting to discuss Feedwater Sperger Prog incl review of Feedwater Nozzle Cladding. Sperger Design & Plans for Replacement. BHEA.J. Deprating Reactors Branch 2 (Pre 790625), 78/12/13. 1p. 94015:309.
- 7881210367 Forwards addl into re multiple consecutive safety/relief Velve actuation of Merk I containment program BOBEN.L.J. General Electric Co. 78/11/13. 3pp. 94485:126.
- Q. Inspection reports. IE Bulletine & correspondence
- 7811060205 Forwards 1E Circuler#78-17. (See ANO:7810230221.Docket #50-133.781013.) QRIER, B. H. Region is Philadelphies Office of the Director. 78/10/13. ip. 94489:210
- 7812010272 Forwards IE Inspec Repts#50-245/78-32 & 50-336/78-28 on 780B14-13 during which no items of noncomplience were noted. GRIER.B.H. Region i. Philadelphie, Dffice of the Director. 78/10/20. 2pp. 94417:212.
- --7812010274 1E 1mapec RepteM50-245/78-32 & #50-336/78-29 on 780814-15 during which no items of noncompliance were noted Major ereas inspected incl: security plen, security organization access controls, response procedure to 780811 truck fire. BMITH.R. H. Region is Philadelphia, Bafeguerds Branch. 78/10/20. 3pp. 94417: 214.
- 7812110314 Forwards IE Insp Rept 50-245/78-29 & 50-336/78-24 on 760723-28 t 760814-16 No noncompliance noted.

  BRUNNER, E. J. Region 1. Philadelphie, Resctor Operations Nuclear Support Branch. 76/10/23. 3pp. 94204:117.

- --7812110316 IE Insp Repte 50-245/78-29 & 50-336/78-24 on 780723-28 t 788814-18 No noncompliance noted the par areas inspected Unit 2 turbine bldg.euxillery bldg.control room portions of enclosure bidg & fire protection sys.

  SHEDLOSKY, J. T. Region i, Philadelphia, Office of the Director MCCABE, E.C. Region i, Philadelphia, Reactor Operations Nuclear Bupport Branch, 78/10/23 21pp. 94204.120.
- 7811020236 Responds to 780308 ltr requesting NRC IE Repts#50-245/77-29 & 50-336/77-28 Portions of Appendix A not subj to 2.790 forwarded to recipient W/out ancls. FELTON.J. M. Division of Rules and Records. 78/10/26. 1p. 94247: 071
- 7812110303 Forwards IE Insp Rept 90-245/78-34 on 781003-06 & notice of violation. BRUNNER.E.J. Region 1. Philadelphie. Resctor Operations Nuclear Support Branch. 78/10/27. 3pp. 94204:079.
- --7812110303 Notice of violation from inep on 781003-06.
  W Region i, Philadelphia, Office of the Director. 78/10/27 lp 94204.0B2
- --7812110310 1E lnep Rept 50-245/78-34 on 781003-06. Noncompliance notes: failurs to perform surveillence procedure per instructions.

  BAUNACK.H.H. Region I. Philadelphia: Office of the Director.

  BETTENHAUSEN.L. KIBTER.H B. Region I. Philadelphia: Reector

  Operations Nucleer Support Brench. 78/10/27. 7pp 94204:083.
- 7811160152 Forwards Inservice Insec Class II Rept from examinations conducted from Fab-Bept 1978 re discrepancies in isometric drawings.LPCI pipe weld indications structural defects in Low Pressure Coolent Bys. Core Spray, & Isolation Condenser. COUNBIL, W. O. Northeest Utilities. 78/11/01. 28pp. 94135: 297.
- 7812010345 Forwards licensee performence evaluation for Region 1.No. operating reactor in Region I considered to have either abnormal or unusual safety concern GRIER, B.H. Region i. Philadelphia. Office of the Director. 78/11/01. 4pp. 00002:239.
- 7812150214 Forwards IE Inspec Rept#50-245/78-33 & #50-336/78-29 on 780906-07 & 780919 during which no Items of noncompliance were noted. Region 1. Philadelphie. Bafeguarde Branch. 78/11/01. MARTIN. H. Q. 2pp. 94212: 358.
- --7812150240 IE Inspec Rept#50-245/78-33 & #50-336/78-29 on 780906-07 & 780919 during which no items of noncompilence were noted. Mejor arese inspected Incl:special security inspec of Interstets Security Svcs & watchmen test of security sys. JONES, E. D. GALLINA, C., DEVLIN, J. W. Region I. Philadelphie. Befeguards Brench. 78/10/24. 3pp. 94212:360.
- 7811290164 Forwards 1E Circular #78-18, "UL Fire Test, "W/encl ANO: 7811150002.

  ORIER, B. H. Region is Philadelphie. Office of the Director. 78/11/06. 1p. 94238:058.
- 7812150150 Forwards 1E Bullstin#78-12A, suppl to 1E Bullstin#78-12. W/encl AND: 7B11300055. QRIER.B. M Region i. Philadelphia. Défice of the Director. 7B/11/24. 1p. 94212:213.
- 78)2210053 Ack receipt of 781116 ltr Informing NRC of steps taken to correct violations noted during Inspec#50-245/78-34.

  ORIER, B. M. Region i. Philadelphie. Office of the Director.
  78/11/24. ip. 94269:034.
- -- 7812210056 Responds to 781027 NRC Itr re violations noted in inspec Rept#50-245/78-34, Corrective actions: diasel generator date sheet rewritten & clarified, personnel reministructed on Tech Spec & procedure compliance. CONBIL.M.Q. Northeast Nucleer Energy Co. (subs. of Northeast Utilityee). 78/1/16. 2pp. 94269:035.
- R. Periodic operating reports & related correspondence
- 7810200087 Forwards Monthly Oper Rept for Sept 1978.

  OPEKA, J. F. Northeest Utilities. 78/10/13. 1p. 94367:336.
- --7810200088 Monthly Open Rept for Sept 1978. YOUNG, R. Northeast Utilities. 78/10/13. 6pp. 94367:357.
- 7811170104 Forwards Monthly Oper Rept for Oct 1978.

  OPEKA, J. F. Northeast Utilities. 78/11/13. 1p. 02766:267.
- --7811170115 Monthly Oper Rept for Oct 1978. YOUNG, R. Northeast Utilities. 78/10/31. 6pp. 02766:268.

- QRIER, B. H. Region i. Philadelphia, Defice of the Director 78/11/13 to. 94239: 243
- -7811290292 Forwards estimates of total errors in total quantities released which were not incl in 780101-780630 Semi-Annual Radioactive Effluent Release Repte OPEKALJ F Northeast Nuclear Energy Co. (subs of Northeast Utilities) 78/09/15. 2pp. 94239:244
- 7812270169 Forwards corrected Monthly Oper Rept for Nov 1978. OPEKA J. F. Northeast Utilities 78/12/20 1p 94190:312.
- --7812290173 Corrected Monthly Open Rept for Nov 1978
   Northeast Utilities. 78/12/06. 6pp. 94190:313
- 3. Reportable occurrences, LERs & related correspondence
- /810120089 Forwards LERe/8-018/03L-0.

  OPEKA, J. F. Northeast Utilities. 78/10/04. 1p. 94473.352.
- --7810120096 LER#78-018/03L-0 on 780905: during surveillence on vessel level instructives found that 1 of the 4 reactor low-low water level switches wes nonfunctional, due to mech hengup ceused by dry lubrication.

  YOUNG, R. H. Northsest Utilities. 78/10/04 3pp. 94473:353
- -78:0160123 LER478-019/03L=0 on 780912:during surveillance.setting of one of the four time delay turbine control fast YOUNG.R. H. Northeest Utilities. 78/10/10. 2pp. 94007:128
- B10200071 Forwards LERW78-021/03L-0.

  \* Northeest Utilities. 78/10/12 1p
- -7810200072 Lar#78~021/03L-0 on 780914: Qas turbine tripped while output voltage was being adjusted. Caused by faulty gas generator speed switch 3A in electronic control YUNG-R. H. Northeest Utilities. 78/10/12. ip.
- B10230207 Forwards LERW78-022/03L-0. OPEKA-J.F. Northeast Utilities. 78/10/13. 1p. 94489:032.
- -7810230210 LER#78-022/03L-0 on 780914:dryws11 vent bypess valve failed to fully close due to particle contemhation in air operator, resulting in insufficient pressure. YOUNG.R.H. Northeast Utilities. 78/10/13. 2pp. 94489:033
- 111140187 Forwards LERW78-023/03L-0.

  OPEKA, J. F. Northeast Utilities. 78/11/06. 1p 94384:275.
- -7811140191 LER#78-023/03L-0 on 781011: feiture of pressure ewitch 2206-1421C to trip at proper point due to dry lubricant & setpoint drift. Bwitch was cleaned & readjusted. YOUNG.R.H. Northeest Utilities. 78/11/06. 2pp. 94384: 276.
- 111140167 Forwards LERW7B-024/031-0, OPEKA, J. F. Northeest Utilities, 78/11/07, 1p. 94383:320.
- :11160089 Forwards LER#78-024/03L-0.

  OPEKA-J.F. Northeast Utilities. 78/11/07. ip. 94134:348.
- 7811160093 LER#78-024/02L-0 on 781011: while conducting drywell high pressure functional/celibr survailance for ECCS, pressure switch was found to be tripping at 2.3 PBI, caused by setpoint drift. YOUNG.R. H. Northeast Utilities. 78/11/07. 2pp. 94134:350.
- 11210291 LERB78-023/03L-0 on 781019: Inadvertent initiation of isolation condenser resulted from setpoint drift & intermittent tripping of various logic chennel switchss. Bwitches readjusted tested & returned to svc. YOUNG.R.M. Northeast Utilities. 78/11/16. 3pp. 94485:198.
- 12070184 Responds to 780906 ltr re info on Control Rods falling to fully insert after acram. During 1977, eight different control rods did not insert seven rods were overhauled & one continued to function satisfactory.

  100MBIL.M.O. Northeast Utilities. 78/11/28. 2pp. 94375:046.

- --7812080118 LER478-026/03L-0 on 781106 Barton 289 pressure indicating ewitch P8-2206-16210 was found to trip at 2 1 P81 due to setpoint drift. Switch was readjusted, tested & returned to svc YDUNG.R H. Northeast Utilities. 78/11/30 2pp 94106 321.
- 7812080126 Forwards LERW78-027/03L-0 OPEKA, J.F. Northeast Utilities 78/12/01 ip 94106:343
- --7812080129 LERW78-027/03L-0 on 781106 one of four level suitches (LI8-263-728)was tripping outside Tech Spec band Caused by instru drift YOUNG.R H. Northeast Utilities 78/12/01 2pp 94106-344.
- 7812260213 Forwerds LERN78-028/03L-0 GPEKA, J. F. Northeast Utilities. 78/12/14 10. 94160 183.
- --7812260219 LERN78-028/03L-0 on 781121 on two occasions defective car were used to ship radioactive waste to burial site due to confusion between procedural controle & trial GA prog. YOUNG.R N. Northeast Utilities 78/12/05. 3pp 94160 184
- 78:2290205 Forwards LERW78-029/03L-0

  UPEKA, J F Northeast Utilities 78/12/22 ip 94190:341
- --7812290212 (ERW78-029/03L-0 on 781122 while checking Emergency Gas Turbine Generator, burned out indicator bulb was found on lube oil pump circuit breaker Opening breaker resulted in gas turbine impose Bulb & bulb socket replaced & tested. YOUNG.R H. Northeast Utilities. 78/12/22 2pp. 94190:342
- 7811210280 Farwards LER#78-025/03L-0 DPEKA, J. F. Northeast Utilities 78/11/16 ip 94485:197
- U Congressionel/Executive Correspondence
- 7810140036 Response to 780911 ltr for comments re individuals who are concerned over radioactive milk contemination in area neer facil. Forwards NRC preliminary eveluation of Bteingless rept on Strontium-90 levels in milk neer subj facil DIRCKS.4. J Office of the Executive Director for Operations 78/10/06. 2pp. 94329-073.
- --7810140039 Responds to 771115 ltr requesting NRC to evaluate Sterng rept re strontium-90 & Ceslum-137 in milk from farms near sub; fecti. Concludes no relationship between elevated radioactive milk level & sub; fecti.

  HENDRIE, J. H. Commissioners 78/01/18. 2pp. 94329:075.
- --7810140043 Forwards add1 NRC comments by M Goldman re allegation raby Dr Sternpless concerning levals of strontium & Cesium near subj facil. Concludes risks from exposurs to low leval radiet sposure small.
  DENTON-H R. Office of Nuclear Reactor Regulation, Director. 78/07/27, [p. 94329-082]
- --7810140043 Review & commant of rept by Dr Sterngless re radioectivi health statistics around nuc facil in CT. Finds no support for contention that CT nuc plents have released sufficient radionuclides to cause significant radiat exposure QLDMAN.h California. Univ. of. Davis. 78/03/31. 4pp 9439-089
- --7810140048 Review of Dr Sterngless rept Concludes data does not supcontention that nuc reactors have contributed to significent increases in Betrontium-90 & Cesium-197 In milk, Additionally, rept did not consider effluent monitoring from reactor. CUSTLE, D. M. Environmental Protection Agency 78/08/09, 10pp. 94329:087
- 7812050043 Responds to 781031 ltr. States that ell present info is so limited that no meaningful comperisons can be made of the level of radioectivity in dairies neer subj fecils & deirles in other regions of the State.

  DIRCKS, M.J. Dfice of the Executive Director for Operations.

  78/11/27. 2pp. 94334:119.
- --7812050044 Ack retript of evel of Sternglass rept. Requests any NRC Sternglass deta indicating radioactivity concentrations of other areas of the State.
  DCOD.C. J. House of Rep. 78/10/31. 2pp. 94334, 121.

- 7811200181 Forwards rays to Mod Amend Becurity Plan of subj facil & requests withholding from public disclosure IAM Section 2.790(d) GARILL.H.J. Consolidated Edison Co. of New York 78/11/09. 1p. 74232.297.
- 7811070274 Responds to 780918 request for add1 info on admin control of fire protec prog. Forwards responses to NRC staff positions re Admin Controls.

  CAHILL-W J Consolidated Edison Co. of New York. 78/10/31. 23pp. 94040:300
- 78iii50249 Forwards request for addi info re facil fire protec review. Request response by 78iii7. SCHENGER, A. Operating Reactors Branch i (Prs 790625). 78/ii/02. 5pp. 74273:069.
- 78:1200:55 Responds to 78:102 NRC request for info rs subj facil fire protec prog. Forwards responses & rev to paregraph 8:40 of Apr 1977 Fire Protec Prog Rept. CAHILL.M.J. Consolidated Edison Co. of New York. 78/11/16. 16pp.
- 7812190102 Forwards Suppl info re April 1977 Fire Protec Prog Rept Encl 1 mods peragraph 8.31 of Rept.Encl 2 contains sched for mods.Encl 3 & 4 contain addit info re steff positions. Deteils w/hald from pub disclosure pursuent to 2.790 CAHILL.N.J Consolidated Edison Co. of New York 78/12/12. 12pp. 94376-300.

#### G. Adjudicatory correspondence

:

Ì

÷

- 7811090188 Forwards recent NRC mesons re problems w/pips support bess plate design. Bteff will inform Bd of conclusions after study of add info from licensee. (See ANG: 7811020332-7811020336- & 7811020343.)
  BMTM-8-H. Office of the Executive Legal Director. 78/10/24. 2pp. 94031-07B.
- 781026020t Per 10CFR2, 772, time for NRC to review decision in ALAB-487 is estanded until 781115.
  CHILK, 8. J. Office of the Secretary of the Commission. 78/10/19.
  1p. 94058:022.
- 7812260307 Motion of the Utility Wetsr Act Group at al.for Lseve to File Briaf as Amici Coriae.
  BMITH.T. T. Hunton & Williams. 78/11/13 6pp. 94160:074.
- 78:1290:84 Notion by NRC Steff to w/draw its petition sasking review of decision ALAB-399 is granted. All parties now agree that ALAB-493 resolves pre-emption issue raised in ALAB-399:issue is now moot.

  CHILK. B. J. Diffice of the Becratery of the Commission. 78/11/13.
  2pp. 94239:275.
- 7812010134 Comm will review decision of ABLB in ALAB-487. In perticular issues azamined will be implication of "Bestroot" decision. CLI-77-9. SNRC030.3061.CLI-78-1.7NRC1.28-26. & to what extent lic conditions should reflect EPA's authority. CHILK. B. J. Office of the Secretary of the Commission. 78/11/15. 3pp. 94410-122.
- 7812070261 Order extending date to 790112 for NRC to slect whether to review ALAB-487 decision.
  CHILK: 8. J. Office of the Secretary of the Commission. 78/11/29, 1s. 03355:010.
- 7812110224 Forwards NRC's 781115 Mamo & Order To Subj Pacif inviting participation in review of ALAB-487. Also advises that time to receive raply briafs is extended to 790112 TRUBATCH. B. L. Office of the General Counsel. 78/11/29, ip. 94037:361.
- 781210226 Forwards NRC's 781115 Hean & Order re subj fecil inviting participation in review of ALAB-487. Also edvises that time to receive reply briefs is extended to 790112.
  TRUBATCH S. L. Diffice of the General Counsel. 78/11/29. 1p. 94337:342.
- 78:21:10228 Forwards NRC's 78:11:5 Memo & Order re subject1 inviting participation in review of ALAB-487. Also advises that time to receive reply briefs is extanded to 79:01:2.

  TRUBATCH.S.L. Office of the General Counsel. 78:11/29. ip. 94:380.029.

94312: 331.

- --7812270430 Memorandum & Order inviting comments of EPA & PASNY redetermination of preferred alternative closed cycle cooling sys. Initial briefs shall be received by 78120i reply briefs by 781213. CHILK.B. J. Office of the Secretary of the Commission. 78/11/15. 33p. 443[2:332.
- 7812210306 Forwards brief by Util Heter Act Group.Edison Elec Inst & Netl Rural Elec Coop Assoc re water quality regulation. BMIDH, T T Hunton & Hilliams. 78/12/15. ip. 94407:255.
- --7812210311 Brief filed on behalf of Util Weter Act Group, Edison Elsc Inst & Netl Rural Elsc Coop Assoc re weter quality regulation & jurisdiction under Clean Water Act section 511(c)(2) Cert of Svc snc1. BMITH.T.T. Hunton & Williams. 78/12/13. 7pp. 94407:256.
- 7812260002 Rasponse of Hudson River Fishermen's Assoc to NRC memo to order of 781115. Urges that NRC retein present NRC lic conditions req cassation of once-thru cooling at subj fecil by 820501.

  CHABIS.8. Nature) Resources Defense Council. 78/12/15. 19pp. 94021:279.
- 7812270060 Brief submitted by CENY in response to 781115 Hamo & Order. Asserts that NRC must relinquish its regulation of water quality impacts of subj facil. Supporting documentation enci. BLOCK.J.D., SACK.E.J. Consolidated Edison Co. of New York. 78/12/15. 33pp. 94160:292.
- 7812280262 NRC Staff's Comments in response to 781115 NRC Order announcing Comm intention to review decision ALAB-487. Bteff claims that decision in CLI-78-1-7NRC1.does not req NRC to mod lies of subj facil. W/documentation & Cart of Bvc. LEWIB.8 H., MULKEY, M.E. Office of the Executive Legal Director. 78/12/15. 39pp. 94374:260.
- 78:2270:38 Informs that US Court of Appeals for Bacond Circuit denied patition for rehearing & rehearing an banc re closed-cycle conting conditions.
  FIDELL.E.R. LeBosuf, Lemb, Leiby & MacRes. 78/12/19. 2pp. 94:16:144

#### P. Operating license stege documents & correspondence

- 7812190016 Forwards RevMi "Draft Radiological Effluent Yech Space" for PWR's (NUREO-0473) & "Preparation of Radiological Effluent Tach Space for Nuc Pur Plants" (NUREO-0133).

  GRIMES. M., Assistant Director for Engineers & Projects (Pre 790623). 78/11/15. 6pp. 94214:286.
- 7812050004 Forwards Licensee Performance Evel Questions for subj fecil in response to 771123 request. Feels it is possible that day of statistical methodology for such eval may not justify the effort. Quelitative evel may be as good. Urgas 1-year test. ORIGR.B.H. Region 1. Philedelphia. Office of the Director. 77/12/13. [229.]
- 7810230057 Notice of issuance of Amend#41 to Fetil Oper LicsDPR-26 which rev provisions in lic to conform to Order of ABL8 dtd 780614 re receipt of govt approvals required to proceed w/constr of closed cycle cooling sys.

  3ALLARD,R.L. Environmentel Projects Brench 1. 78/07/23. 2pp. 94199-199
- 7810110099 Notifies NRC that utl1 sysects to receive results of Westinghouse ECCS cooling performence remalysis by 781130. CENY will submit its revised enalysis by 781231. CAHTLL, M. J. Consolidated Edison Co. of New York. 78/10/03. 1p. 940&6:350.
- 7810240108 Forwards date epecified in Saction 401 Certification for Sept. Includes epecies code list, gress plec output, circulating water tamp, river water discharge, chem discharge & deily fish counts. MONTIN M. Consolidated Edieon Co. of New York. 78/10/13. 17pp.
- 7810310240 Response to PABN 1tr of 7808021 forwards deniel of PASN's appl to extend period of intarim oper using the installed once-thru cooling sys at suby facil. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/10/13. 3pp. 94091:322.

- estuary which NRC is conducting or in which it is partitipating as per ity request of 780901 LEMBS BH Office of the Esecutive Legal Director. 78/10/17 Jpp. 94034-004
- 7810310299 Forwards Amend#41 to Facil Oper Lic#DPR-26, changing Tech Bpec BCHLENCER. A Operating Reactors Branch i (Pro 790625). 78/10/17 2pp.
- --7810310304 Amend#41 to Facil Oper Lic#DPR-26.changing Tech Bpec re redioactive mati surveillance & sealed redioactive sources. SCHMENCER.A Operating Reactors Branch 1 (Pro 790625). 78/10/17. Boo
- --7810310305 Safety Eval Supporting Amend#41 to Facil Oper Lic#DPR-26.
  Concludes that no harm will result.
   Operating Resctors Branch 1 (Pre 790625). 78/10/17 2pp
- '811010001 Summary of 781012 meeting w/util re steam generator prog for sub; facil.

  OLSHAN: L Operating Reactors Branch 1 (Pre 790625). 78/10/18.

  4699. 94290-283
- 811070120 informs NRC iAH Tech Spec that Strawtown Dairy has ceased oper & therefore mill sample is unobtainedle. Samples of leafy green vegetables & milk from Shenendock Farm will be taken.

  CAHILL-H.J. Consolidated Edison Co of New York. 78/10/30 2pp. 94078-290
- -78i1070163 Appi for emend to Oper Lic DPR-26, requesting mod of Tech Bpsc 3 i.J.3. Table 3-3. Table 4.1-1 & 6.9,2 & addition of new Tech Spec 4,16 to establish limiting conditions of oper. Burveiliance requirements for OPS detailed in enci. GAHLL.W.J. Consolidated Edison Co. of New York. 78/11/03. 22pp. 94044:107.
- 311150171 Forwards reissued 781017 Amend, renumbered as Amend#42, to Facil Opsr LiceBPR-26 SCHHENCER, A. Operating Reactors Branch i (Pre 790625). 78/11/06 2pp. 94242:329
- -7811130175 Amend#42 to Facil Oper Lic#DPR-26, changing Tach Spec re radioactive mati surveillance. SCHMENCER.A Operating Reactors Branch 1 (Pre 790695). 78/10/17. Sps. 94242:331.
- -7811150182 Safety Eval supporting Amend#42 to Facil Oper Lic#DPR-26. Concludes that no harm will ensue.

   Office of Nuclear Reactor Regulation, Director. 78/10/17. 2pp. 94242:339.
- Hi200047 Bletus of iE outstanding review request:weiting for additinfore requirements for pressuritation of eir lock door seals that support a proposed change to subj facil tech specs.

  LAINBLO, Piant Bystems Branch (Pre 791030), 78/11/09, 1p. 94215-330
- 11290288 Responds to 78:106 request for info concerning licensee reg performance eval for Region i plants by NRC. Provides details. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 78/11/09, 9ps.
- 11170160 Forwards data specified in Section 401 Certification for the month of October 1978.

  MONYI, M.A. Consolidated Edison Co. of New York, 78/11/10. 16pp. 94048:051.
- 11210274 Act receipt of 781013 itr responding to request for extension of interim open of subj facil using the installed once-thru cooling sys. Believes hearing would be premeture. EARLY-P.U. Power Authority of the State of New York. 78/11/13. 2pp. 94485:167.
- i2:30088 Notice of workshops re implementation of training & qual requirements contained in Appand B of 10CFR73. Requests ine-workshop registration of attenders to facilitate sending out meth. Wrencl Registration Form & List of Locations.

  ILLER. J. R. Assistant Director for Site & Refeguerds (Pre 791030). 78/11/15. 3pp. 9421:1343.

- BUR's (NAREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREO-0133) GRIMES B K Assistant Director for Engineers & Projects (Pro 790623). 78/11/13. 6pp 94365 334.
- 7812070153 Notice of seminar on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants Requests advance submission of seminar specific questions. W/encl Seminar Info Sheat-Proposed Agende & maps ORIER. B H Region i. Philadelphia. Dffice of the Oirector. 78/11/21 Spp. 94375:192
- 7812190026 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wienci ANOM 7812080207.

  8CHMENCER: A Operating Reactors Branch I (Prs 790629). 78/11/28 6pp. 74210 001.
- 7812150321 Responds to 781121 memo requesting mod to Environ Tech Specs to rea continuous monitoring & recording of effluents from detergent Wasts Collsctor tanks hemo has been forwarded to DBE.
  EIBENHUT.D.O Assistent Director for Systems Engineering (Pre 791030) 78/12/04 1p 94022-014
- 7812070180 Forwards application for anomal to OLs. ZARAKAB.P. Consolidated Edison Co. of New York. 78/12/05 ip 94375. 030.
- --7812070182 Application for amend to QLs Certificate of Svc encl CAHILL.M J. Consolidated Edison Co. of New York 78/12/05 12pp. 94378-021.
- 7812280126 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by date & calculations Licensee rust notify NRC of any inaccuracies or enforcement action unil result DAVIB, J. O. Office of inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94310.262
- 7812190075 Forwards info re fracture toughness & potential for lampllar tearing of steem generator & resotur coolant purp support metis. Mili forward eddi info upon completion of record search. M/encl 4 oversized drewings eveilable in CF CRAHILL. U. U. Consolidated Edison Co. of New York 78/12/12. 14PP. 94215: 197.
- 7812050013 Requests views of Regional Directors on Licenses performance sval of subjectis Forwards questions to be answered by 771209.
  THORNBURGH Division of Reactor Construction Inspection 77/11/23.
  200.
- 7812190174 Forwards copies of "Appl for Amend to Oper Lic" which request emends to section 4 1.2a of Environ Tech Spec Requirements for subj fecils. Amends would restructure present Aquetic Environ Monitoring Prog. Cert of Svc encl. CAHILL.H.J. Consolideted Edison Co. of New York 78/12/14 3pp. 94349; OO2.
- --7812170180 Appl for emend to Licenses OPR-5, DPR-26 & DPR-64 requesting rev to Environ Tech Specs. Rev Tech Specs & proposed mode are designed to provide a monitoring prog for continuous assessment of Hudeson River fish population. CAHILL. M. J., EARLY, P. J. Consolidated Edison Co. of New York, 78/12/14, 46pp. 94340-005.
- 7812260014 Comments of PASN re closed-cycle cooling conditions Asserts that lic condition should either be eliminated of delayed indefinitely Cert of Svc encl.
  TROSTEN.L.M., FIDELL.E.R. ANCARROUM R. Legoeuf, Lemb, Leiby & MacRas. 78/12/15. 18pp. 94021:045.
- ~~7812260019 Forwards appl for extension of period of interim oper using installed once-thru cooling systems, final determination of permissibility of such systems.

  EARLY.P. J. Power Authority of the State of New York. 79/08/02.

  2pp. 94021:063.
- --7812260023 App) for extension of period of interim oper using installs once-thru cooling sys. Appl contains motion for expedited relief. Also encl is affidavit of PJ Eeriy of PABN in support of extension.

  # Pauer Authority of the State of New York. 78/08/07. 58pp. 94021:045.

- 7811090016 Forwards IE Inspec Rept#50-247/78-28 on 780825 during which no itsms of noncompliance were noted.

  BRUNNER, E. J. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/25 Zpp. 94040:013.
- --7811090017 IE inapec ReptM50-247/78-28 on 780825 during which no items of noncompliance were noted. Major errors inspecting: previously identified unresolved items ufrespect to records. NAPUDA. 0. BECKMAN.D. KISTER.M.B. Region 1. Philadelphie. Reactor Construction & Engineering Support Branch. 78/09/14. 4pp. 94040:015.
- 78:0160246 Forwards IE Bullstin#78-12: "Atypical Hald Material in Reactor Pressure Vessel Helde" requesting action win 60 days.4 list of IE Bullstin Issued in 1978. (See ANO # 7810040253)

  ORIER.8. H. Region I. Philadalphia. Office of the Director. 78/09/29. 6pp. 94003:308.
- 7811060201 Forwards IE Circular#78-17. (See ANG: 7810230221: Docket #50-133, 781013.)
  GRIER, B.H. Region 1- Philadelphia. Office of the Director. 78/10/13. 1p. 94489: 200.
- 7811300337 Forwards IE Inspec Rapt#50-247/78-30 on 780913-14 during which no items of noncompliance were noted.

  BRUNNER.E. J. Region 1. Philadelphia, Reactor Operations Nucleer Support Branch, 78/10/19. 2pp. 94116:188.
- --7811300340 1E Inspec Rept#50-247/78-30 on 780913-14 during which no items of noncompliance were noted Major areas inspected incl:licensee response to IE Circular 78-08 "Environ Guai of Safety Ralated Elec Equip."

  REBELOWSKI. T. Region 1. Philadelphia. Reactor Operations Nuclear Buppart Branch. 78/10/19. 3pp. 94116:190.
- 7811060224 Ack receipt of 780818 ltr informing NRC of steps taken to correct violations noted during inspec#50-003/78-06 & #50-247/78-19.

  GRIER.B.H. Region i. Philadelphia. Dffice of the Director. 78/10/20. Zpp. 94488:141.
- ~~781106023B Responds to 780712 NRC ltr re Violations noted in Inspec Raptem50-003/78-06 & #50-247/78-19. Corrective actions: Gueilty Assurance checklists modienviron audit procedures & related environ procedures revised. ZARAKAS.P. Consolidated Edison Co. of New York. 78/08/18. 4pp, 94488-143.
- --7811060239 Forwards 1E Inspec Repte#50-003/78-06 & #50-247/78-16 on 780516-18 & 780522-23 & Notice of Violation. ORIER, B.H. Region i. Philadelphia, Office of the Director. 78/07/12. 3pp. 94488:147.
- -7811060244 Natice of Violation from Inspec on 780516-18 & 780522-23, STOHR, J. P. Region i. Philadelphia. Office of the Director. 78/07/12. 3pp. 94488:150.
- --7811060247 IE Inspec Repts#50-003/78-06 & #50-247/78-19 on 780516-18 during which 5 items of noncompliance were noted: failure to monitor cooling water systems & approva procadural changes in accord w/ESTR: failure to submit timely measurement rapts. BCREB.R. J. Region i. Philadelphia. Office of the Director. 78/07/07. 24pp. 94488:153.
- 7812010345 Forwards licenses performance evaluation for Region i.No operating reactor in Region i considered to have either ebnormal or unusual eafety concern.

  GRIER.B.H. Region i. Philadeiphia. Office of the Director.

  78/11/01. 4pp. 00002:259.
- 78:1140252 Ack receipt of 78:018 itr informing NRC of steps taken to correct violations nated during inspec#50-003/78-11 & #50-247/78-29.

  BMTH, O. H. Region 1. Philadelphia. Fuel Facility & Materials Safety Brench. 78/11/03. 1p. 94400:106.
- --78iii40255 Responds to 780726 NRC itr re violation noted in Inspec Repts850-003/78-11 & 850-247/78-29. Corrective actions: maifunctioning psn linkage methanism in recorder of monitor CT-1014 repaired & monitor flushed. CAHILL. W. J. Concolidated Edison Co. of New York. 78/10/18. Epp.

- --7811140262 IE Inspec Repts#50-003/78-11 & #50-247/78-29 on 780905-08 during which 1 item of noncompliance was noted:failure to continuously monitor & record liquid effluent discharges. THONUGL. Region i, Philadelphia, Office of the Director. 78/09/26. App. 94400:112.
- 78:2160057 Forwards IE Inspec RepteM50-003/78-12 & 50-247/78-33 on 78:101:-12 during which no items of noncompliance were noted. 8MiTh. O. H. Region i. Philadelphia. Fuel Fecility & Materials Bafety Branch. 78/11/03. 2pp. 94:33:092.
- ~~7812180058 IE Inspec Repts#50-003/78-12 & #50-247/78-33 on 781011-12 during which no items of noncompliance were noted. Hajar areas inspected incl: lobservation of licenses conducted emergency drill & circulating cooling water temp monitor. BORES.R. J., BYDHR.J.P. Region 1. Philadalphia, Fuel Facility & Materials Bafaty Branch. 78/11/02. App. 94133:094.
- 7811290214 Forwards IE Circular #78-18: "UL Fire Test, "W/encl AND: 7811150002.
  ORIER.B. H. Region 1. Philadelphis. Office of the Director. 78/11/06. 1p. 94237: 329.
- 7812150133 Forwards IE Builstin#78-12A.suppl to IE Builstin#78-12, W/anci AND:7811300055.
  ORIER, B. H. Region 1, Philadelphia, Opplice of the Director, 78/11/24. ip. 94212:174.

#### R. Pariodic operating reports & releted correspondence

- 7812010206 Forwards corrected copy of Cham Discherges sheet in Section 401 Cert Rept for Oct 1976.

  MONTI-M.A. Consolidated Edieon Co. of New York. 78/11/15. 2pp. 94409; 265.
- 7810200064 Forwards tabulation of daily record of fish collections for Sapt 1978 including breekdown & total weight.
  CAMILLIA. J. Consplicated Edison Co. of New York. 78/10/13. Spp. 94412:171.
- 7B10230149 Forwards Monthly Open Rept for Bept 1978.
  CAHILL-M.J. Consolidated Edison Co. of New York. 78/10/16. 1p. 94164:191.
- --7810230150 Manthly Oper Rept for Bept 1978.

  KANULA-L. Consolidated Edison Co. of New York. 78/10/16. App. 94164: 192.
- 7811210340 Perwards Monthly Open Rept for Oct 1978. CAHLLLW J. Consolidated Edison Co. of New York. 78/11/15. ip. 94484:328.
- --7811210344 Monthly Oper Rapt for Oct 1978. KAMULA,L., MAKEPEACE,J. Consolidated Edison Co, of New York, 78/11/08. 9pp. 94484:329.
- 7811220153 Forwards tabulation of daily record of fish collections for Oct 1978 w/deily epacies breakdown & total weight. CAHILL-W.J. Consolidated Edison Co. of New York. 78/11/16. 4pp. 94074:277.
- 7812180182 Forwards data epecified in Baction 401 Certification for Nov 1978. MDNTI-M.A. Commonwealth Edison Co. 78/12/10. 17pp. 94366:036.
- 7812270188 Forwards rept of fish impingement & corrective action for Nov 1978. CAHILL.W.J. Consolidated Edison Co. of New York, 78/12/14. Spp. 94018: 007.
- 7812210207 Forwards Monthly Open Rept For Nov 1978. CAHLLIM J. Consolidated Edison Co. of New York, 78/12/15. ip. 94279:103.
- ~~7812210211 Monthly Oper Rept for Nov 1978. KANUA:L. Consolidated Edison Co. of New York. 78/12/05, 7pp, 94379:104.

- 8. Reportable occurrences. LERs & related correspondence
- 7810100067 Forwards LER#78-025/04L-0. CAHILL-M. J. Consolidated Edison Co. of New York, 78/09/27. 1p. 94030:083.
- --781010007: LER#78-025/04L-0 on 780828: w/Unite 2 & 3 oper at 100 & 90X pur.caiculations performed utilizing equation prescribed by ETB12.1.3.1, indicated heat rejection to river was in excess of BTU/HR maximum permitted by ETB8.

  \* Consolidated Edison Co. of Neu York. 78/09/27. 2p. 94093:084.
- 7810110153 Forwards LER #78-028-017-0. CANDL-M. J. Consolidated Edison Co. of New York. 78/10/04. 1p. 94069: 172.
- --7810110155 LER #78-028/017-0 on 780920; At cold shutdown leek discovered in elbow connection between containment isolation valves in recirculation path from residual hest removal pumps. Affected section replaced & successfully hydro tested. MAKEPEACE, J. M. Consolidated Edison Co. of New York, 78/10/04. 2pp.
- @10160105 Forwards LER#78-014/03X-1,78-018/03X-1,78-019/03X-1. CAHILL-H.J. Consolidated Edison Co. of New York, 78/10/06. 1p. 74001:349.
- -7Bi0i60ii0 LER@7B-0i4/03X-i on 7B0523: during low pur physics test of i high head BIB pump.isakage was confirmed past the seat of i swing check valve downetream of pump#22, caused by feuity valve disc mounting. MAKEPEACE, J. M. Consolidated Edison Co. of New York. 7B/10/06. 2pp. 94001:344.
- ~7810160113 LERW78-019/03X-1 on 780629: during normal oper leakage wes found at socket weld connection on seel injection header downstream of seel injection filters due to pinhole lask. MAKEPEACE.J.M. Consolidated Edison Co. of New York. 78/10/06. 2pp. 94001: 346.
- -7810160165 LERM78-018/03X-1 on 780626: during normal oper.e slight leak wes found at velve 1823D in a level instru line from boron injection tank.due to crack in bonnet.

  MAKEPEACE.J.M. Concolidated Edison Co. of New York. 78/10/06.

  299. 94001:348.
- 310160138 Forwards LER#78-027/03L-0. CAHELLIH.J. Consolidated Edition Co. of New York. 78/10/06. ip. 94005:304.
- -7810160141 LERW78-027/03L-0 on 780708: during normal oper the #21 Boric Acid Transfer Pump underwent mech seal failure. Following repairs, pump returned to svc w/in time limit specified in Tech Spec 3.2. C.2.
  MAKEPEACE, J. M. Consolidated Edison Co. of New York, 78/10/06.
  1p. 94005:305.
- Hi07022: Forwards LER#78-029/03L-0.
  CARILLH.J. Consolidated Edison Co. of New York. 78/11/01. ip. 74039: 138.
- 7811070230 LERM78-029/03L-O on 781003: in hot shutdown condition, the amount of water in condensate storage tank was reduced to below Tech Spec requirement to combat successive charides in condensate & feedwater sys. Caused by bleed & feed open. MAKEPEACE. J. M. Conscilleted Edison Co. of New York. 78/11/01. Spp. 94039: 139.
- ii280260 Forwards LER878-030/03L-0 & LER878-031/03L-0. CAMILL-M.J. Consolidated Edison Co. of New York, 78/11/18. ip. 94395:200.
- 7811280263 LERB78-030/03L-0 on 781018: setting of bistable PC-439A found to be below Tech Spec minimum. Coused by Instru drift. MAKEPEACE, J. M. Northern States Power Co. 78/11/17. ip. 94395: 201.
- 78ii280270 LERW78-03i/03L-0 on 78i022:during normal oper.one instructional of containment pressure safeguards logic become deenergized. Caused by failure of static inverter associated withat channel.

  MAKEPERGE.J.M. Consolidated Edison Co. of New York. 78/11/17.

  19. 74375:202.
- 12040229 Confirms 781127 verbal notification of reportable occurrence .ER-78-033/01. During cold shutdown outage, a blockage was liscovered in discharge line from boron injection tank. IDNT1-M.A. Consolidated Edison Co. of New York. 78/11/27. ip. 74439: 323.

94340: 357.

--7812190131 LERMYB-033/017-0 on 781126: blockege discovered in dischaline from boron injection tank caused by a defective heat

CAHILL. H. J. Consolidated Edison Co. of New York. 78/12/08.

781219012: Forwards LER#78-003/01T-0.

- --7812190131 LERW7B-033/01T-0 on 781126; blockage discovered in dischaline from boron injection tank caused by a defective heat trace circuit wirs Defective wire replaced & blockage cleared. Else heat tracing test PT-07 rev.

  MAKEPEACE.J.M. Consolidated Edison Co. of New York. 78/12/08.
  1P. 94340:358.
- 7812200193 Forwards LER878-032/03L-0. CANILL-N. J. Consolidated Edison Co. of New York. 78/12/13. Lp. 74148: 336.
- --7812200195 LERM78-032/03L-0 on 781116: during normal open-routine is revealed leak from socket weld connection of drain valve c-15 to seal injection header. When leek was 8.00PM, unit was ebut down for repeir. Leek caused by vibration.

  \*\* Commonwealth Edison Co. 78/12/13. ip. 94148:357.
- 7812200206 Forwards LER678-034/04L-0. CANICL-N. J. Consolidated Edison Co. of New York. 78/12/13. 1p. 441621278.
- ~-78:2200208 LERM78-034/041-0 on 780705; heat rejection to river in earlie 32:00 STU/hr. Caused by method prescribed by ETRR for calculating heat rejected. More accurate method showed heat rejected to be less than ETBR meximum allowed.

  MAKEPEACE, J. M. Consolidated Edison Co. of New York, 78/12/13.
  19. 94162:279.

# DOCKET 50-249 DREBDEN NUCLEAR POWER STATION, UNIT 3 F. Security, medical, emergency & fire protection plans

- 7810120080 Forwards analysis of Elec Cable Penetration Fire Barrier Test conducted on 780619 Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test. NAUGHTON.H.F. Commonwealth Edison Co. 78/09/29. 44p. 94049: 330.
- 7812070172 Forwards fire protec info inci hydraulic calculations & Automatic Sprinkier co Drawing W26-1730. of aprinkier sys for fire pump in Crib House. Overate drawings available in Central Files.

  NAUGHTON. N. F. Commonwealth Edison Co. 78/11/20. 6pp. 03555: 144.
- 7812120195 Informe NRC neme of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Piant Fire Protec Functional Responsibilities Admin Controls & QA" will be submitted 790201.

  NAUGHTON.H.F. Commonwealth Edison Co. 78/11/30. 2pp. 94277:099.

#### 9. Adjudicatory correspondence

- 7811090259 Bd grants request by Citizens for a Better Environ & Natural Resources Defense Council for permission to file response to answers opposing their patitions to intervene by 781103. MILHOLLIN. Q.L. Atomic Sefety and Licensing Board Penei. 78/11/01. ip. 02761:290.
- 7812110284 Cencele special prehearing conference acheduled for 78121 Conference shall be held on 790111 in Tex Courtnoom of US Courthouse & Fed Bldg. Chicago, IL. Parties & petitioners must rept to Board by 781215 re progress of negotietions.
  MILHOLLIN.O.L. Atomic Befety and Licensing Board Panel. 78/12/01 2pp. 98203:281
- 7810120112 Applicant's Answer to Petition for Leave to Intervene reproceeding filed 780908 by Attorney Gen of St of IL Includes notices of appearance for M. I. Miller. J. R. Rowes & P. P. Steptoe. Includes designation of person upon whom wave shall be made. STEPTUE. P. P. leham, Lincoln & Seale. 78/09/18. 10pp. 94484: 039.
- 78:0190131 Answer by CEIL to Patition to intervene filed by Atty Gen of IL on 780920. Agrees that Atty Gen has standing, but asserts there are no genuing issues to be hard at hearing. Requests that Atty Gen request for EIB be denied.
  BIEPTOE.P. P. Isham, Lincoln & Beele. 78/10/02. 3pp.
- 7810300063 Natural Resources Defense Council Request for Leave to Fi a Response. Response is to applicant's contention reconstitutionality of forced disclasure of group's members' names in order to oper w/in state.
  ROIBMAN.A. 2. Natural Resources Defense Council. 78/10/10. 4pp. 94037:177.

\_\_\_\_\_

- 7810300324 NRC Staff Answers to Council for Citizens for Setter Environ & Natural Resources Defense Council's Petition for Leave to Intervens Staff opposes pranting petition.w/Cert of Svc. QUDDARD, R. J. Office of the Executive Legal Director. 78/10/10. 3pp. 94253.397
- 7810230124 NRC Staff's Response to Petition of TEX-LA Cooperative.Inc For Leave to Intervene. Staff believes Patition should be granted.

  LEGSY.R.P., DLUME.H.B. Office of the Executive Legal Director 79/10/10. 9pp.
- 7811010063 Petition for leave to intervene & for hearing filed by citizens for Batter Environ & Naturel Resources Defense Council Request for leave to file response to enswere opposing petition is granted.

  MILHDLLIN.O.L. Atomic Bafety and Licensing Board Panel. 78/10/13.
  1p. 94302:360.
- 78i1150223 "Natural Resources Dafenes Council Response to Commonwealth Edison's & Staff's Answers to Patition for Leave to Intervene. "Intervenor urges 8d to establish a schedule for briefing challenges to contentione. R
- 7011130216 NRC request to file response to NRDC response to Coam Ed & NRC enswer to patition for leave to intervene dtd 781023 If granted reply will be served by 781103. Cert of 8vr enci. GODDARD, R. J. Office of the Executive Legal Director. 78/10/26. 2pp. 03554:050.
- 78i120070 Request by Comm Ed for ieevs to file a response to NRDC brief which argues that organizations may show standing to participate in NRC proceedings merally by alleging that they represent shonymous members. Cert of Svc encl.
  BTEPTOE, P. P. Isham, Lincoin & Besie. 78/10/30. 2pp. 942i8:348.
- 7811220233 Forwards "Licensing Report Dreaden Nuc Per Plant Units 2 & 3- Spent Fuel Rack Modification." dated 780203.W/o and rspt. GDDAND.R. J. Office of the Executive Legal Director. 78/11/01. 1p. 94289:360.
- 7811160021 Grants request by licansee CEIL to have until 781107 to respond to 781013 Order of ASLS permitting NRDC & Citizene for a Better Environ to file response to answer opposing their petitions to intervene in proceedings re subj fecile. HILHOLLIN.O.L. Atomic Safety and Licansing Board Penel. 78/11/03. Ip. 94317:090.
- 7811220010 NRC Staff's Response to NRDC's Response to Answere to latter's Patition for leave to intervene. NRC saserts that NRDC has not demonstrated its standing to intervene as matter of right. Cent of Svc encl. ODDDARD.R. J. Office of the Executive Legal Director. 78/11/03. Bpp. 94273: 334.
- 78:1200003 Special Prehearing Conference in proceedings re subj fecils will be held on 78:215 in Rock Telend. IL. Ail parties to proc & all petitioners to intervene must attend & should be prepared to discuss ail lesues.

  MILHOLLIN. Q.L. Atomic Sefety and Licensing Board Panel. 78/11/09. 2pp. 94215:221.
- 7812130122 Gives notice that A Bislaushi enters an appearance on behalf of applicant CEIL in proceedings re-subj facils. Cert of Bvc encl.
  BISLAMBRI. A.P. Isham. Lincoln & Besis. 78/11/21. 2pp. 94307:188.
- 7812270230 Proposed stipulation to NRDC & CRE's representation of unnamed members in Dreadan-Guad Cities transshipment is not acceptable to NRC.NRC position on NRDC's petition to intervene transine as stated in 781103 pleading.

  QUDDARD.R.J. Qffice of the Executive Legal Director. 78/12/06. ip. 94017:138.
- 7612280271 Forwards "Stipulation" of NRDC. CDE & Commonwealth Edison Core identification of members of NRDC & CBE to prove they have interests that may be affected. No agreement w/Reg Steff has been reached.
  ROIEMAN. A. 2. Natural Resources Defense Council. 78/12/08. 1p. 94374:394.
- ---7812280280 Parties agree that NRDC & CBE have edequately indentified at least one member whose interest may be advarsely affected by the proposed action. Auth to represent these interested members has not been agreed upon.
  ROIBMAN. A. 2. Natural Resources Defense Council. STEPTOE, P. P. Commonwealth Edison Co. 78/12/11. 3pp. 94374:335.

7812270133 Special Prehaming Conf Scheduled for 790111 is postponed until 790201. Parties & petitions are excused from requirement to rept to 8d by 781215 rs negotiations progress.
MILHOLLIN. 6 B. Atomic Safety and Licensing Spard Panel. 78/12/13. 2pp. 94161.142.

### H General correspondence

- 7812080138 Forwards CEIL request for amend of DL to allow spent fuel transfer & storage between facils. H/o encl.
  ODDARD.R J Office of the Executive Legal Director. 78/11/17. ip. 94107:336.
- J. Insurance & indomnity information
- 7812190109 Requeste refund of 86 per mut in excess indemity fee pald for LiceDPR-2, MDPR-19, MDPR-25, MDPR-29, MDPR-30, MDPR-39, MDPR-39, MDPR-48, P.O. Commonweith Edison Co. 78/12/13 ip. 94376:323.
- P. Operating license stegs documents & correspondence
- 7B111702B7 Requests eddi info for review of proposed subj facil Spent Fuel Pool Mod. Question items include occupational exposure during SFP mod. seffect on exposure level of cut up low density racks. SFP cooling eys. vol of contaminated metl. 21EMANN, D. L. Operating Reactors Branch 2 (Pre 770625). 78/11/08. 7pp. 94045:179.
- 7812080026 FOIA request for all records incl:quantity of radicective meth disposed of from former Manhatten proj in IL known as Chicago Pilessi-2 & 3. Meth disposed of in IL by Lindsay Cos et Morris facti & Drasden fecil.

  HANEELL-D. Illinois, State of. 78/11/06. 2pp.
- 7812150228 Ciassifies iic amend for proposed fuel pool mod as Classes 1V & 1 not Classes III & 1. Requires add1 charge of 88300 for sech of the two app1, to be paid w/in 15 days. MILLER.W.O. License Fee Management Branch. 78/12/11, 2pp. 94213:329
- 7810250198 Notice of Proposed Issuance of Amende to Oper Lics.NRC is considering issuance of amende to Provisional Oper Lic MPR-19 & Faci i Oper LiceUPR-29. Mould change provision in Tach Spece to ellow more spent fuel to be stored at facil. ZIEMANN.D.L. Operating Resectors Branch 2 (Pre 7906251. 78/08/03.4pp. 74392:220.
- 7810170185 Update & conclusion of dissel generator reliability study. Aimost ail corrective actions taken per investigation heve been completed. Results of study summarized in encl. BTEPHENSON.8.B. Commonwealth Edison Co. 78/09/28. 5pp. 94270: 047.
- 7810100027 Forwards avaluation of reactor protect sym pur supplies to determine whather undetected failures adversely affect the RPS sys.

  TURBAK-M.S. Commonweelth Edison Co. 78/10/04. 5pp.
- 7810140112 Resvaluation of Lic amend fees for inter-station spent fuel transfer for subj facile as requested by 780817 itr shows that the class i & 3 fees paid for each station are correct.
  MILLER.W.O. License Fee Management Branch. 78/10/10. ip. 94421:151.
- 7810270190 Responds to 781002 NRC itr re requested Tech Spec change for reactor water cleanup sus return valve. Util eccepts change as Claes 2 & Claes 1 amend. & remite eppropriete fas.

  REED.C. Commonwealth Edison Co. 78/10/23. 1p. 74057:081.
- 7811020322 Hithdraws request to amend Tech Specs re reporting requirements for reactivity anomalies as Reg Gulds "Interpretation" by NRC on 780701 dose not require rept for reactivity increase of less than 5 esca.

  REED. C. Commonweelth Edison Co. 78/10/26. 2pp. 94255:223.
- 7B11030161 Forwards proposed Amend chenging Tech Specs w/regard to updating station organizational charts. Changes have received onsite & offsite approvel.

  REED.C. Commonwealth Edison Co. 7B/10/24. 9pp. 02724:009.
- 7811130335 Summary of 780914 weeting w/GE representatives & Merk 1 Owners Group re progress of Long Term Prog w/attendance list & agende(RD-9-A-Merk), Standarde.) ORINES.C. Plant Systems Branch (Fre 791030). 78/10/26. 67pp.

hydrological features & discussing w/licanise hydrological design bases necessery to perform a detailed BEP review Addl hydrological info also requested.

STALEY.O.B. Hydrology Nateorology Branch. 78/10/31. 3pp. 74405:156

- Biii00i31 Bummary of meeting w/CEIL on 78:023-24 to discuss questions re seismic design of subj facil & obtain seismic design info. W/encl list of attendess meeting agends charter of BSRT, floor response spectra. & design rapts & tech paper. LEVIN.H A. Systematic Evaluation Programs Branch (Pre 790625). 78/11/02. 410pp. 94259:001.
- 3iii40105 Responde to 780516 NRC itr requesting addi info re reactor vases metal surveilience specimen fluence valves at time of withdrawel. w/projections based on desimetry results of previously tested cepaules & 80% capacity fector; w/o sncl. TURBAK.M.S. Commonwealth Edison Co. 78/11/03. 2pp. 94425:125.
- iili40002 Notifies applicant of 78ii28 NRC-sponsered seminer re Model Radiological Effluent Tech Spece for Nuc Pur Plants W/encl Beminer Info Sheetito be completed & returned by 78ii171 & Proposed Agenda. KEPPLER, J. 0. Region 3, Chicago, Office of the Director. 78/11/07. App. 94426:022.
- ii210257 Updates 770510 itr info re control rod drive(CRD)uncoupling prog. Forwards historical data list of eli CRD's occurring between 760522 & 771211. Improved Quelity Control & filter installation procedures are adequete to prevent uncoupling. TURBAKIM.8. Commonwealth Edison Co. 78/11/13. 4pp. 94488:335.
- 11300056 Forwarde Amend#39.#37.#48 & #47 for Lics DPR-19.DPR-25. DPR-19 & DPR-30 respectively.Amende review Tech Space reoperating temp & pressure limits. Also forwards Safety Eval & Fed Register Notice. IPPCLITO.T.A. Operating Reactors Brench 3 (Pre 790625). 78/11/13. 3nd.
- 7811300067 Amend#37 to the Operating Lic rev Tack Space re operating temp & pressure limits.

  1PPDLITD.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
  80s.
- 78i1300077 Sefety Evel Rept in support of Amend#39.#37.#48 & #47 to Oper Lice DPR-19.DPR-25.DPR-29 & DPR-30.respectively. # Office of Nuclear Reactor Regulation. Director. 78/11/13. App.
- '811300085 Notice of Issuance of Amend#39.#37.#48 & #47 to Oper Lics DPR-19.DPR-25.DPR-29 & DPR-30.respectively.
  IPPGLIYO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
- 2150071 Notification of workshops in Jen-Mey 1979 in Regions 1-5 to explain techniques of job energy is a performance testing thow to raise such testing to qualification plan evelopment a training Designed for working level personnel, ILLERUUR. Assistant Director for Site & Sefeguerds (Prs 791030). 78/11/15. 5pp. 94210:215.
- 2180248 Forwards Revel "Dreft Radiological Effluent Tech Specs" for WR'elNUREG-0473) & "Preparation of Radiological Effluent ach Specs for Nuc Pur Plants" (NUREG-0133). RIMES.B.K. Assistant Diractor for Engineers & Projects (Pre 90425), 78/11/15. App. 94366:125.
- 2050107 Forwards rev page to Topical Rept CE-1-A, "Gusi Assurance rog.Rev 6." Rev raflects Reg Quidel, 28 & 1.33 rev. URBAK.M 8. Commonwealth Edison Co. 78/11/17. 2pp. 94335:334.
- 1280213 Forwards current lic status list for subj fecile. EED.C. Commonwealth Edison Co. 78/11/20, 9pp. 94012:130.
- 1280246 Forwards "Projected Fluence Values at Hithdrawel for the epsules Designated to Meet the Requirements of 10GFR50 ppend H." Teble 1 to be ettached to 781103 it to 1ppoilto. JRBAK.M.S. Commonwealth Edison Co. 78/11/20
- 2140176 forwards Oct 1978 Prop Activity Review listing meetings held providing teek-by-tesk activity summary for the month. BER.L.J. General Electric Co. 78/12/04. hipp.
- AMBO 129 Emphasizes importance of submitting accurate & complete info info type itemsees & applicants. Info submitted must be instantiated by data & calculations, Licansea must notify IC of any inaccuracies or enforcement action will result. WIS.J.O. Office of inspection & Enforcement, Office of the ractor, 78/12/06. 2pp. 9431:1336.

- containment leak rate test procedure re temp & humidity measurement in subvol bounded by water level Requests exemption from IOCFRDo in order to eliminate subvol problem.

  TURBAK-M B. Commonweelth Edison Co. 78/12/12. 6pp. 94343:334.
- 7812050013 Requeste views of Regional Directors on Licenses performance eval of subj facils Forwards questions to be ensured by 771207.
  THORNBURGH Division of Reactor Construction Inspection. 77/11/23. 200.
- 78:2190097 Accepts topical reptWCE-i-A RevM6, "Comm Edison Co Quality Assumence Prog for Nuc Generating Stations." Requests submittel of D6 copies. HAASS: W P. Quality Assumance Brench. 78/12/13. ip 94376:317.
- 7811210367 Forwards add1 info re multiple consecutive eafsty/relief velve actuation of Meri I conteinment progrem. SBBON. U. J. General Electric Co. 78/11/13. 3pp. 94485:126.
- Q. Inspection reports. IE Bulletins & correspondence
- 7810110052 Forwards IE insp Rapte 50-010/78-23.50-237/78-21 k 50-249/78-22 on 780807-10 k 16-18 k notice of deviation. DAVIB-A B. Region 3. Chicego. Office of the Director. 78/09/08. 2pp. 94080:049.
- --7810110054 Notice of Daviation from Inspec on 780807-10 & 780816-18.

  \* Region 3, Chicego: Fuel Fecility & Materials Bafety Branch.
  78/09/08. ip. 94063:226.
- --78:0110062 IE Inspec Repts#50-010/78-23.#50-237/78-21 & #50-249/78-23 on 780807-10 & 16-18 during which I item of deviation was noted. Failure to mast FBAR commitment for monitoring unit 2/3 liquid rad waste efficients.

  @KSGER.L. R., FIBHER.W.L. Region 3. Chicago, Office of the Director. 78/09/06. 11pp. 94063:227.
- 78:10:00:18 Forwards 1E Inspec Repts#50-10/78-25.#50-237/78-22 & 50-249/ 78-24 on 780705-06.11-12.19-20.780817.23-25.29-31 & 780901. during which no items of noncompliance were noted. FIORELL.2. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/20. 2pp. 94290:141.
- ---7811010022 iE Inspec Repts#50-10/78-25,#50-237/78-22 & #50-249/78-24 o 780705-06,11-12.19-20.780817.23-25.29-31.780901.during which no items of noncompliance were noted Mejor eress inspect following of noncompliances & review of plant oper.

  BARKER, J. L. Region 3. Chicago, Office of the Director. KNOP.R. C. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/20. 7pp.
- 78:01:0277 Responds to 780708 NRC ltr re deviation noted in Insp. Repts 50-010/78-23.50-237/78-21.50-249/78-23.Corrective ections: liquid radweste discherge monitor will be returned to svc & slarm will be made operable.

  REED.C. Commonwealth Edison Co. 78/09/22. 3pp. 94079:148.
- 7810200203 Ack receipt of 780922 itr informing NRC of eteps taten to correct item of noncomplience identified in itr of 780908. DAVIBA. B. Region 3. Chicago. Fuel Facility & Materials Sefety Branch. 78/10/12. ip. 94267:089.
- 7810300000 Forwards 1E Circular#78-17. (See AND: 7810330221)
  KEPPLER, J. G. Region 3. Chicego. Office of the Director. 78/10/13.
- 7811300261 Forwards IE Inspec Reptem50-010/78-26.50-237/78-23 & 50-247/78-25 on 780905-08.12-14.20-22. & 26-28 & Notice of Violation.
  FIORELLI.G. Region 3. Chicago, Reactor Operations Nucleer Bupport Branch. 78/10/25. 2pp. 94075: 233.
- --7811300264 Notice of Violetian from inspec on 780905-08, 12-14, 20-22 & 26-28.

  Region 3, Chicago, Resctor Operations Nuclear Support Branch. 78/10/25. jp. 94075:061.
- --7811300268 IE inspec Repts#50-010/78-26, 50-237/78-23 & 50-249/788-25 o 780705-08, 12-14, 20-22 & 26-28 during which i item of noncomplience was noted: failure to rept a 30 day reportable event in 30 days.

  8ARKER, J. L., CHRISBOTIMOS, N., HUGHES, J. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. 15pp. 94075:237.

- 7812050011 Forwards IE Inspec Repts#50-010/78-29.50-237.-254.-295.-304/78-25.50-249/78-27 & 50-265/78-26 on 781002 during which no items of noncompliance were noted.

  KEPPLER.J. G. Region 3. Chicago, Office of the Director. 78/10/30.
  2pp. 94200 183
- --7812050027 IE Inspec Repts for subj facils on 781002 during which no itams of noncompliance were noted. Hajor areas inspected inclidiscussion of actions being taken by util to improve ita rag performance & tour of Zion etation MNDP.R.C., FIDRELLIO. Region 3. Chicago. Reactor Operations Nuclear Bupport Branch. KEPPLER.J.O. Region 3. Chicago. Diffice of the Director. 78/10/30. 3pp 94200:185.
- 78iii50063 Forwards IE Circular 78-18, "Underwriters Leb Fire Test "
  KEPPLER, J O Region 3, Chicago, Office of the Director. 78/ii/06.
  19. 94i12.240.
- 7811280486 Unresolved items noted in IE Inspec Repts#50-010/77~28, #50-237/77-29 & #50-249/77-25 have been reviewed & recommendations and e Documentation of unresolved items withold per 10CFR2 790(d).
  HIND.J.A. Region 3. Chicago, Bafeguards Branch. 78/11/16 1p. 94381:358
- 78:2050287 Forwards IE Bulletin 78-12A. "Atypical Weld Metl in Reactor Pressure Vessal Helds." KEPPLER.J D. Region 3. Chicago. Office of the Director 78/11/24. 1p. 94202.332.
- 7812140081 Forwards IE Inspec Reptambo-010/78-28, m50-237/78-24 & m50-249/78-26 on 781010-13, 781016-19 & Notice of Violation. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 78/12/01 2pp 94128, 227.
- --7812140086 IE inapsc Rapta 50-010/78-20.50-237/78-24 & 50-249/78-26 on 781010-13 b 781016-19 Noncompliance noted:defective sacurity organizationobserved.including access controls & physical berriers. Info partially withheld fref FOIA Examption 31. BBLANGER, J. L. . HOMELL J. C. . HIND, J. A. Region 3, Chicego, Bafeguards Branch. 70/11/20 2pp. 94128:229.
- 7812130330 Notification of Site visit on 781205-07 to discuss operational considerations re insvc inspec prog. ZIEMANN.D L Operating Reactors Branch 2 (Pre 790525). 78/12/05. 19. 94307:332.
- 7812290025 Forwards 1E Bulletin 78-14. "Deterloration of Buna-N Components in ASCO Solenoids." KEPPLER.J. O. Region 3. Chicago. Dffice of the Director. 78/12/19. ip. 94208;009.
- R. Pariodic operating reports & related correspondence
- 7811140119 Forwards monthly operating rept for Oct 1978. STEPHENSON.8 B. Commonwealth Edison Co. 78/11/08. 1p. 94425:184.
- S. Reportable occurrences. LERs & related correspondence
- 7810170195 Forwards LERW78-03B/03L-0.
  8TEPHENSON, B.B. Commonwealth Edison Co. 78/10/06. lp. 94234:342.
- --7810170203 LER#78-038/03L-0 on 780916; inepec revealed that one hydraulic of 4 enubbars on valve had less than required shount of fluid. Subsequent test proved shubbar inoperative, Caused by fluid lest resulting from loose hydraulic lines. HARRIS.8, M. Cammonweelth Edison Co. 78/10/06. 1p. 94234:343.
- 7B10240100 Forwards LER#7B-036/03L-0. BYEPHENSON, B. B. Commonwealth Edison Co. 78/10/12. 1p.
- --78:0240102 LER#78-036/03L-0 on 780917:While performing routine surveillance DIS 1300-2.0918-1349 tripped et 38.5 water DP. Caused by instr drift. isolation switch will continue to be tested monthly per DIS 1300-2.

  LINDBERG.C. Commonweelth Edison Cq. 78/10/12. 1p.
- 7810240116 Forwerds LER#78-040/03L-0. 8TEPHEN90N.8.B. Commonwealth Edison Co. 78/10/12. 1p.

--7810240141 LERR78-037/03L-0 on 780918. Leaks discerned in feed pump minimum flow lines Caused by crecks & holes in piping due to

STEPHENSON, B. B. Commonwealth Edison Co.

- minimum flow lines Caused by cracks & holes in piping due to excessive flow velocity JANSEN.T Commonwealth Edison Co 78/10/17. 2pp
- 7810270229 Forwards LERN78-039/03L-0.
  8TEPHENSON.B.B. Commonwealth Edison Co. 78/10/17. 2pp. 94053; 247.

78/10/17. 10

- ~-7810270231 LERM78-039/03L-0 on 780922.conteinment cooling Water Svc LPCI heat exchanger valve MD-3-1501-3A failed to oper in automatic mode while attempting to start torus cooling. caused by motor oper valves "chattering" ACHTERBERG-J Commonwealth Edison Co. 78/10/17 ip. 94053.248.
- 7810270302 Forwards LER#77-03B/01x-1.

  8TEPHEN90N.B B. Commonwealth Edison Co. 7B/10/17. ip 06403:358
- ~-7810270305 LERW77-038/01X-1 on 770914.D/G cooling water pump feilure, due to piceseive bearing wear,ellowed rotor to contact canned motor windings & caused cooling water to short out pump.
  CIESZKIEWICZ-9. Commonwealth Edison Co. 78/10/17, 2PP. OA403:359
- 7811090125 Forwards LERM78-041/03L-0.
  BTEPHENSON.B.B. Commonwealth Edison Co. 78/10/19. 1p. 94042:301.
- ~-7811090126 LER#78-041/03L-0 on 780924: following unit startup while inerting containment the N2 level in storege tenk dropped to less than 60 inches. Level in tenk was below 60 inches for about 3 hours due to late N2 delivery.

  RALPH.R. Commonwealth Ediaon Co. 78/10/19. ip. 94042.302.
- 7B110301B4 Forwards LERN7B-043/03L-0.
  8TEPHEN90N,B.B. Commonweelth Edison Co. 7B/10/27 1p. 02724:100.
- --7811030i91 LERA78-043/03L-0 on 780929: contractor cut hole in HPCI ate line w/cutting torch while removing sieeve metl from line restreint resulting in minor redirective ateem release to reactor bidg. Contractor admonished hole welded over. JANSEN.T Commonwealth Edieon Co. 78/10/27. 1p. 02724:101.
- 7811060159 Forwards LERW78-044/03L-0 BTEPHENSON, B. B. Commonwealth Edison Co. 78/10/30, 1p. 94489:07B.
- --7811060162 LER 78-044/03L-0 on 780930; indicated level increesed on wi Range Monitor LE. 1602-8 while pumping down torus during normal oper Ceuesd by stretic movement of cem resulting from binding of mechanical linkage connecting tube drive to cam. LINDBERG.C. Commonweelth Edison Co. 78/10/30. 2pp. 94489:079.
- 7811140222 Forwards LER#78-048/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 78/11/01. 1p. 94400:054.
- --7811140227 LER 78-048/03L-0: on 781012.D18 1600-3.d1ff press switeoletton velve for DP18 3-1622A.wes found classed.apperently aince completion of previous querterly survey on 780711.

  Cause unknown.

  LINDBERG.C. Commonweelth Edison Co. 78/11/01. 2pp. 94400:055.
- 7811210333 Forwards LERW78-049/03L-0. STEPHENSON, B.B. Commonwealth Edison Co. 78/11/01. 1p. 94484:322.
- --7811210339 LERM78-049/03L on 781014: while performing Turbine Stop Val Closure Scram Circuit Sensor Tests(DDS 500-10), M2 turbine stop velve 10% Closure switch did not actuate until velve was 20% closed. Valve was not of adjustment. KORCHYNSKY, M. Commonwealth Edison Co. 78/10/14. 1p. 94484:323.
- 7811280301 Forwards LER#78-050/03L-0. STEPHENSON.B.B. Commonwealth Edison Co. 78/11/13. 1p. 94395:297.
- --7811280309 LERM78-050/03L-0 on 781021: during monthly survey D18 250-1 Main 8tm Line HI Flow feet 8w, DPIS 3-261-2C tripped at 120 PBID. Caused by Priction in switch mechanism. Bellows essembly will be replaced.
  LINDSERG.C. Commonwealth Edison Cq. 78/11/13. 1p. 94395: 298.

JANSEN, I Commonwealth Follow Co

120130 Forwards LER 78-052/03L-0. EPHERSDN.B B. Commonwealth Edison Co. 78/11/30 ip 94275 158.

12120134 LER 78-052/03L-0. on 781104 during leak check of maisture separator area steam was found blowing from bottom of en slow downstreem of orifice RO 3-3041-09. Caused by erosion from high velocity steam/water mixture on allow RALPH.R Commonwealth Edison Co. 78/11/30. 1p. 94276.159

210242 Forwards LER#78-053/03L-0

EPHENSON. B. G. Commonwealth Edison Co 78/11/30. 1p. 94279 192

12210245 LER#78-053/03L-0 on 781104 during DCP 2700-11 (Offges Radiat Honitor Calibr).3"A" monitor failed downscale.As req. inoperable monitor was then tripped in upscale position Cause was failed amplifler in 3"A" Offges log Red Monitor. LINDBERO.C Commonwealth Edison Co 78/11/30 ip 94279 193

210244 Forwards LER#78-054/031-0. EPHENSON.B B Commonwealth Edison Co. 78/11/30 lp. 94279.197.

12210252 LERM78-054/031-0 on 761104 during normal surveillance, while testing MSIV closure time. MSIV 3-203-2A closed 2 8 seconds after initiation signal Caused by MSIV 3-203-2A valve timing which was out of adjustment RALPH.R Commonwealth Edison Co. 78/11/30 ip 94279 198

180175 Forwards LER#78-035/03L-0. EPHENSON.B B. Commonwealth Edison Co. 78/12/07. lp. 94359-355

12180178 LER#7B-055/03L-0 on 781116 small leak noted on recently installed drain attached to 3D2 feedwater heater drain line Ceused by lack of fusion & elag inclusion on socket welded drain line. Repaired by grinding defect & rewelding. JANSEN, T. Commonwealth Edison Co. 78/12/07. ip. 94359:336

180145 Farwerds LER#78-056/03L-0 EPHENSON,B 8 Commonweelth Edison Co 78/12/08. 1p. 94365-261

12180148 LER#78-056/03L-0 on 781122 during routine inspec of containment spray interlocks, noted that face plats on Yarway model 4418C was broken holding pointer set in Fixed position ebove trip setpoint. Cause unknown LINDBERG. C. Commonwealth Edison Co. 78/12/08 lp. 94365.262.

270284 Forwards LERM78-097/03L-0. EPKENSON.B.B. Commonweelth Edison Co. 78/12/14. lp. 94229.316

12270289 LERM78-057/03L-0 on 781130:during test on U3 D/G, the "D/O 3 Day Tank Level Hi/Lo" alerm sounded Caused by the solenoid velve which wes stuck closed.

CHAN. J Commonwealth Edison Co. 78/12/14. 1p 94229 317

ET 50-250 TURKEY POINT PLANT, UNIT 3

ecurity, medical, emergency & fire protection plans

120075 Forwards copies of Rev 4 to subj fecil Emergency Plan. RIG.R.E. Floride Power & Light Co. 78/09/27, 2pp. 94402.221.

10120081 Rev 4 to State of FL Radiological Emergency Plan dtd Mey 1975 Ltr of support w/ERDA dtd 750410.FL Highwey Patrol Order 32 dtd 740401 & Coest Guard 740426 ltr encl \* Florida Power & Light Co. 78/09/27 164pp. 94402:223.

300325 Ack reciept of 780623 ltr re position that 3-man fire igade is edequate to cope w/eny fire et subj facil quests addi info so NRC mey evaulate proposal.

HRENCER, A. Operating Reactors Branch I (Fre 790625). 78/10/16. 94253: 341.

310121 Forwards Rev O to security plan dtd 780526 Hithheld ef 10CFR2. 790).
RIO.R.E. Florida Power & Light Co. 78/10/24. 111pp.

rowit uper Lickupu-41 Amena tech Hapcs for Fire Protec His & Admin controls in Response to 771222 Appl(1-77-390) BCHNENCER. A Operating Reactors Brench 1 (Pre 790625) 78/11/08. 94013 173.

- ---7811280172 Amend#42 to Lic#DPR-31 rev common station Tech Specs to incorp liniting conditions for oper & surveillance requirements for existing fire protec sys SCHMENCER, A Operating Reactors Granch ( Pre 790625). 78/11/08 2pp 94013 178
- --7811280174 ArendW34 to LicMDPR-4; rev common station Tech Space to incorp limiting conditions for oper & surveillance requirements for existing fire protec sys SCHMENCER. A Operating Reactors Branch | IPre 790625) 78/11/08. 20pp. 94013 180
- --7811280178 Notice of issuance of erend#34 & 42 to Facil Oper Lic# DPR-31 & DPR-41 Amend rev Tech Specs to incorp limiting conditions for oper & surveillance requirements for existing Pire protec sys.

  BCHWERCER, A Decreting Reactors Branch 1 (Pre 790623) 78/11/08. 2pp. 94013.200
- 7812080148 Licensee has been orally nutified that Emergency Plan through Revision 4 dtd 780927 is acceptable based on 781025 memo Wenct AND 781030177. SCHWENCER. A Operating Reactors Branch 1 (Pre 790625) 78/11/28 1p 94104 349.
- 7812110010 Pending staff approval of Rev D requests util commit to prepare special security procedures applicable to the replecement of steem generators

  8CHRENCER. A Operating Reactors Branch 1 (Pre 290629) 78/12/01 2pp 94339 235
- 7812120119 Discusses fire protection in operating nuclear power stations, in pertituiar providing analysis of facilities. SER Proposed fire protection mod increases level of protection against fire hexards.
  HALL-R E Oronkhaven Netional Laboratory. 78/12/06 Spp 94279 340
- --7812120125 Requests addl info re fire protec at subj facils. Info concerns water supply cable protecty and hydrants smoke venting equip & smoke removal Documentation re info sought encl. HALLR E Brookheven National Laboratory 78/09/21, 9pp. 94275:245.
- 7812270190 Responds to 701201 NRC request for special security procedures Agrees to prepare security procedures 1AW Mod Amend Security Plan at least 90 days prior to commencing steam generactr repeir ectivity.
  UHR10,R.E Florida Power & Light Co 78/12/15. 1p. 94018:042

# H General correspondence

78:2270168 Requests placement on distribution list for correspondence & repts deeling w/oper status for tuby facils
SHREVE.J. Floride, State of 78/12/18 in 94018 C90

# I Financial information

7811070144 Forwards req guerantess under Price-Anderson as amend 1978 under option 5 Encl provides info re 1977 annual rept. consolidated finencial statements cash flow projections. capital expenditure curtailments & cash flow sources UHR10.R E. Florida Power & Light Co 78/10/30. 45pg. 94044:022.

# J. Insurance & indemnity information

7810230140 Forwards Endorsement#37 to Nuc Energy Liability insurance MMF-35 Also States that EndorsementM36 to Nuc Energy Liability InsuranceMNF-185 was forwarded w/760618 FFL 1tr (L-76-228) UHR10, R. E. Floride Power & Light Co. 78/10/09. 2pp. 94164; 203.

7810300107 Forwards Endorsement#36 to Policy#NF-185 & Endorsement#37 to policy#NF-55. UHR1G.R.E. Florida Power & Light Co 78/10/09. 1p. 94035:236



### M. Antitrust correspondence

- 7811080144 "Notice of Appearance"re proceedings. Cert of Svc encl EVANG.D. J. Office of the Executive Legal Director. 78/10/30. 3pp. 94399:291.
- 7812270071 Provides notice that RC McDiarmid & DA Giscalona w/draw as representatives of FL Cities in proc re subj facila JABLONR. A. Spiegel & McDiarmid, 78/12/13 4pp. 94161:011
- P. Operating license stage documents & correspondence
- 7812010382 Response to 780613 ltr rs comments & corrective actions in 780404 NRC ltr rs Diesel Generator Lockout. Util's response is adequate.

  8CHMENCER. A. Operating Resctore Branch 1 (Pre 790625). 78/06/30.
- 7810250175 Notice of Proposed Issuance of Amends to Fecil Oper Lice NRC is considering issuance of exends to Fecil Oper Lice DPR-31 & DPR-41 Amends rev Tech Specs re trensient & eccident analysis.

  BCHNENCER, A. Operating Resctors Brench 1 (Pre 790625). 78/08/04.
  4pp. 94393.062.
- 7810200075 "Containment Structure Post"Tensioning Sys.Fifth-Year Surveillance Rept."
  SHALL R. Bechtel Power Corp. (aubs. of Bechtel Corp.). 78/09/13.
  100pp. 94029:087.
- 7811210191 Notice of Issuence of Amends 38 & 31 to Fecil Oper LichDPR-31 & BDPR-41. Amends thangs Tack Specs as refueling of Unit 4 Cycle 5 oper. BCHMENCER. A. Operating Reactors Brench 1 (Prs 790625). 78/09/22. 3pp. 94488 003.
- 7810120022 Forwards test rept for 770701-780630 psr 10CFR50 596. UHR10-R,E, Fiorida Power & Light Co. 79/10/04 lp. 94330:174.
- ---7810120023 Test rapt details plant change/mods.procedure changes.tests & expere. Major areas:cash-crane-add-limit switthes.diesel emergency diesel eurgs tank.NDDT overpressure relis? protection.reactor coolent pump seel mod.flamestic eddition. e. Florida Power & Light Co. 78/10/04. 45pp. 94330:175.
- 7810110159 Responde to 780802 NRC ltr re meterological dete. Forwards info tables re wind frequency. URRIGA.E. Florida Pauer & Light Co. 78/10/05. 9pp. 94069 226.
- 7810120028 Forwards check for \$4000 rs lic smand request of 780926. UHRIG.R.E. Florids Power & Light Co. 78/10/06. 2pp. 94470:354.
- 7810170191 Forwards Fifth year Surveillance Rept re containment struc post-tensioning sys. Minor arror in Third Year Burveillance Rept. eubmitted by 1tr of 730825.1-73-404.le corrected.
  UHRIGR.E. Florida Power & Light Co. 78/10/10. 2.3pp. 94235:197.
- 7810200045 Forwards "Containment Structure Post-Teneloning Bye-Fifth-Year Surveillance Rept." UHRIO-R. E. Florida Power & Light Co. 78/10/16. 1p. 94029:086.
- --7810170194 Fifth Year Surveillance Rept of contellment struc post-tensioning age, Concludes that sys is performing w/in limits eat by design criteria & specs, includes wire testing & analysis of sheath filler.

  ANREWS.C. W. Bechtel Power Corp. (subs. of Bechtel Corp.), 78/07/31. 899p. 94233:200.
- 7810250252 Summary of Mesting held on 781002 to discuss an extension of oper interval for 4 add months in response to submittal of assaud on 780756. Impact—related info presented included: remerposure from shutdown & replecement pur costs.

  ORDITEMBUS.M. Operating Reactors Branch 1 (Pre 790625). 78/10/16.
  3pp. 94392:343.
- 7811140030 Forwards Amend 39 to Licenst DPR-31, safety evaluation & notice of issuence.

  8CHENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/16.
  2pp. 94420: 292.
- --7811140033 Amand#39 to Facil Oper Lic#DPR-31 rev lic to reg gaging inepec of steam generator in case of 0.3pm or greater leak or shutdown to repair leak due to denting & Inspec of all 3 generators in event of 2nd isek w/in 20 days.
  SCHMENCER.A. Operating Reactors Brench 1 (Pre 790625). 78/10/16.3pp. 94420:294.

- --7811140036 Safety Evel Rept Supporting Amend 39 to License DPR-31.

  \* Operating Reactors Branch 1 (Pre 790625). 78/10/16. Spp. 94420.297.
- --7811140039 Notice of Issuence of Amend#39 to Fac11 Open Lic MDPR-31 to 781016 SCHWENCER.A Openating Reactors Branch 1 (Pre 790625). 78/10/16. 2pp. 94420-302.
- 7810270182 Ack receipt of 780719 ltr requesting proposed 7sch Specs be submitted addressing overpressure protec. Will submit info by 781115. URRIO, R.E. Floride Pauer & Light Co. 78/10/19. 1p. 94057:083.
- 7810300003 Requests edd1 \$400 fee to procees 780809 appl for amend to Facil Lic MDPR-31 & DPR-41.
  MILLER.W.D. Licenes Fee Management Brench. 78/10/19. 1p.
- 78i1030177 Act review of Rev 1,2,3,4.Rsv 1 & 2 found acceptable, Rev 3 & 4 updats errangements w/verious radiol amergency support groups.Back-up hospital changed to Beptist Hosp.After review.3 & 4 found ecceptable.
  KNIGHTON, 9. Environmental Evaluation Branch (Pre 790625). 78/10/RS. 1p. 94104:330.
- 7811030203 Forwards corrected page#1 to Amend#30 to Lic#DPR-41 dtd 780921.

  8CHLENCER.A Depreting Reactors Branch 1 (Pre 790625). 78/10/25.
  2pp. 02724.139.
- 7811090015 Forwards Amend#40 & 32 to Facil Oper Lic#DPR-31 & DPR-41. chemping Tach Operating reduce pressuritor heatup rate. BCHENCER.A Operating Reactore Brench i (Pre 790625). 78/10/25. 2pp. 74040.001.
- --7811090018 Acend#40 to Facil Oper Lic#DPR-31, changing Tech Spec to reduce pressurizer heatup rate. SCHMENCER.A. Operating Reactors Branch I (Fre 790625). 78/10/25. 2pp. 94040:003.
- --7811090021 Amend#32 to Fecil Oper Lic#DPR-41.changing Tech Spec to reduce pressurizer heatup rate. BCHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/25. 4pp. 94040:006.
- --7811070024 Safety Evel Supporting Amend#40 & 32 to Lic#DPR-31 & DPR-41 Concludes that no adverse effects will result.

  \*\*Office of Nuclear Resector Regulation, Director, 78/10/25. 3pp. 94040:010.
- 7811120075 Forwards relassed AmendW3B & W31 to Facil Lic\*DPR-31 & WDPR-41 w/corrected amend numbers. BCHWENCER, A. Operating Reactors Branch I (Pre 790625). 78/10/26. 2pp. 94478: 329.
- --7811130080 Amend#38 to Facil Oper Lic#DPR-31.changing Tech Spec to auth oper w/25% of tubes in plugged condition.
  EIBENUT.D.Q. Assistent Director for Systems Engineering (Pre 791030). 78/09/22. 2pp. 94076:314.
- --7811130083 Amend#31 to Fecil Oper Lic#DPR-41, changing Tech Bpec re refueling of Cycle 5 oper & auth oper w/25 percent tubes to plugged condition. EIBEN\*UT.D.O. Assistant Director for Systems Engineering (Pre 791030). 78/09/22. 13pp. 94076:344.
- --7811130170 Safety evaluation supporting Amend#38 & 31 to LiceDPR-31 & #DPR-41.Concludes that no harm will ensue.

  \* Office of Nuclear Reactor Regulation, Director, 78/09/22.
  18pp. 94011:137.
- --7811130173 Notice of Issuance of Amend#38 & #31 to Facil Oper Lic@DPR-31 & #DPR-41, changing Tech Spec re Cycle 5 oper & oper w/ tubes in plugged condition.

  SCHWENCER, A. Operating Reactors Brench 1 (Pre 790625), 78/09/22.

  3pp. 74011; 155.
- 7811070180 Forwards check in response to 781019 requeet.

  UHRIG.R.E. Florida Power & Light Co. 78/10/30, ip. 94036:357.
- 7811290068 Amends#38 & #31 to Facil Oper Lic#DPR-31 & #DPR-41 for subj facils were completed on 780922. W/isvance of these two amends/all prior NRC Orders are subj facile have been setisfied. Audit tabulation encl.

  8CHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 3pp. 94193:222.

- phantom on whole body counter Enci 1 contains actual amount of each redionuclide present.enci 2 gives resta of examples to DDE values & enci 3 gives recommendations SUTHERLAND, J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 78/11/09. 3pp. 94419.164.
- 781121025 Natifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Space & ancl seminar info eheat, registration form. & proposed agenda O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/11/09. 5pp. 94488:330
- 781116039 Forwards info in response to 780518 NRC request for info re steam generator & reactor coolant pump supports sufficient to show geometry of all principal elements Oversize drawings available in Central Files UHRIGAR E Florida Power & Light Co. 78/11/10. lp. 94135:249
- --7811160142 "Report on Frecturs Toughness & Potential for Lamsllar Tearing of Steam Gensrator & Reactor Coolent Pump Supports." w/27 oversize drawings showing geometry of all principal elements available in Central Files • Florida Power & Light Co 78/09/30. 40pp. 94135:250
- 7811300041 Forwards NRC staff paper, Policy Session Item(8ECY-78-554) relicenses reg performance evaluation Three methods for evaluation are statistical trend analysis & regional survey method W/o encl.
  D'REILLY.J.P. Region 2. Atlanta, Office of the Director 78/11/15 2pp. 94071-035
- 78:2180038 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendess to facilitate sending out mati H/encl Registration Form & List of Locations. HILLER.J.R. Assistant Director for Site & Safeguards (Pre 79:030). 78/11/15 5pp 94:33:031.
- 78:2190036 Forwards RevMi "Draft Radiological Effluent Tech Space" for PMR 's(NNREO-0473) & "Preparation of Rediological Effluent Tech Space for Nuc Pwr Plante" (NUREO-0133) ORIJEES. 8. K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15. App. 942:5:009.
- 78i1270161 Forwards appl for Amend to Facil Operating Lics#DPR-31 & DPR-41 Proposed amend addresses Overpressure Mitigating Sys (OMS). Discusses limiting conditions for oper of Reactor Coolent Sys
  UMR10.R.E. Florida Power & Light Co. 78/11/20. 11pp. 94232:324
- 7811280228 In response to 780915 NRC ltr. submite euppl to 760604 itr to meet requirements of Sec V. 8 of Append I to 10CFR50 to operationally evaluate drain floor treatment eye which is suppl by a portable demineralizer.

  UHR10.R E. Florida Power & Light Co. 78/11/20. Dpp. 94012:047.
- 7812140357 Discusse possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANOW 7812080207.
  - 7812080207.

    8CH-ENCER.A Operating Reactore Branch 1 (Pre 790623). 78/11/28-6pp. 03557; 223.
- 7812040336 Requeste \$1.600 in lic fees since emend does not qualify for exemption under IOCFR170. 22 footnote#2.
  MILLER.W 0. License Fee Management Branch. 78/11/29. ip. 94129:354
- 78122017; Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants, info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J. G. Office of inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94375:011.
- 7812280017 Farwards copy of nswly rev NPDES psrmit for eubj fecti. No environ impact will result from changes incorp into new permit.

  UHRIO, R. E. Florida Powsr & Light Co. 78/12/07. Ip. 94131:036.
- --7812280026 Forwarde NPDE8 permit for subj facil Permit to become effective on date noted provided no request for adjudicatory hearing is filed with EPA Wenci EPA Correspondence.

  TRAINALP J. Environmental Protection Agency. 78/06/14. Ip. 94(3):037.

- facils to circulating water conling canal sys, to become effective 780701
  TRAINAP J Environmental Protection Agency. 78/12/14 13pp. 94131 038
- 7812140150 Submits request to amend Append A of Facil Oper Lic#DPR-DFR-41.in response to 780719 NRC itr Amend concerns operability & surveillance of facil Overpressure Mitigating UHRIO.R.E Florida Power & Light Co 78/12/11. 11pp. 94127 OC
- 7812180378 Notice of 781218 meeting u/FL Light & Pur Co to discuss review of subj facil's Steam Generator Replacement Prog. GRDTENRUIS.N. Operating Reactors Granch 1 (Pre 790629). 78/12/1
- 2pp. 94358 215
  7812270195 Forwards addi info to suppl 780329 itr in response to NR
- request for detailed schedule for providing eval of effects of segmentric loss of coolent eccident loads.

  UHRIO.R E. Florida Power & Light Co. 78/12/19. ip. 94010:087
- 7812270187 Forwards Mati Statue Rept for period 771001 to 780331 for LiceOPR-31. DPR-41. DPR-45 & SNM-1314 & Nuc Meti Transection Rept for LiceOPR-31 & DPR-41. UHRIO, R.E. Florids Power & Light Co. 78/12/20. 31pp. 94018:00
- UHRIO,R.E. Florida Power & Light Co. 78/12/20. 31pp. 94018:0
- 7812270221 Forwards request to amend Append A of Facil Oper Lics OP & 41.80b; proposal requests changes in rod insertion limits for both unite to allow more flexibility in long range reload planning W/encl sefety evaluation.

  UHRIO.R. E. Pennsylvania Power & Light Co. 78/12/22. 7pp. 94017-122.
- 7812280139 informs of plans for next facil refusing & results of review of refueling analysis method Unit 3 is in oper cycle 5 & next refueling is sched for 791230. Westinghouse FLARE code will be used for reload design.

  UHRIO.R E Florida Power & Light Co 78/12/22 2pp. 94310:350
- 7811210338 Requeste relisf from ASHE Code requirements re ultresoni exeminations of piping welde. Recording & eval indications at 20% DAC is impractical. Primery reference level(100% DAC) criteria for UT exem provides compareble sefety level UHRIQ.R.E. Florida Power & Light Co. 79/11/15. 4pp. 94484: 324
- G. Inepection reports, iE Bulletine & correspondence
- 7811130003 Forwards it inspec Repts#30-250/78-17 & #50-251/78-17 on 780718-19 during which no items of noncompliance were noted. KENNA-W.D. Region 2, Atlanta, Bareguards Branch. 78/08/24. 2pp 94077; 008.
- --781ii30007 IE Inspec Repts#50-230/78-17 & #50-231/78-17 on 780718 during which no items of noncompliance were noted Major stees inspected; special security inepec re discovery of a hose bomb device MODRE.D E. GilleBPIE.F P. Region 2, Atlanta, Office of the Director. 78/08/20. 3pp. 94077 013
- 7811010407 Forwards IE Inepac Rept#50-250/78-16 & #50-251/78-16 on 780724-27 during which no iteme of noncompliance were noted. 8UTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Base Branch. 78/09/21. 2pp. 94388.330.
- --7811010411 iE Inspec Rept#30-250/7D-16 & #50-251/78-16 on 780724-during which no items of noncompliance were noted Major Areas inspected included: rediological environ protec & emergancy planning.

  OIBBON.0.T. Region 2. Atlenta. Office of the Director. 78/09/4pp 94388:332.
- 7810110247 Orants requests in 1tr of 780914 to w/hold proprietary in Inspec Rapts#50-230/78-14 & 50-231/78-14.
  LONG, F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 78/10/02. 1p. 03555-230.
- --7810110291 Requests w/holding proprietary info in Inspec Repte #50-250/78-14 & 50-250/78-14. UMRIG.R.E. Floride Power & Light Co. 78/09/14. lp. 94068:20
- --7810110256 Forwards IE inspec Repte#50-250/78-14 & #50-251/78-14 780717-21 during which no items of noncompliance were noted. LQNO.F.J. Region 2. Atlenta, Reactor Operations Nuclear Suppor Branch. 78/08/21. 2pp. 94068:203.

- --7810110262 IE Inspec Rapte#30-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted Major Areas inspected included: calibration, surveillance, & procurement.

  OUTS, J. E. . KELLOGO, P. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/08/17. Spp. 94068:205.
- 7810200188 Ack receipt of IE inspec Reptem50-250/78-15 & #50-251/78-15.

  Does not consider any info therein to be proprietary.

  UHRIG-R.E. Florids Power & Light Co. 78/10/03 ip. 94366:319.
- 7810240067 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted during inspec#50-250/78-12 & #B0-251/79-12.
  LDNG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/10. 1p
- --7810240075 Responds to 780814 NRC itr re violations noted in inspec RepteMSQ-250/78-12 &M50-251/78-12. Corrective actions:Ltr to be issued requiring operational release must be obtained prior to sterting work on sefety related equip. UHR10, N. E. Fiorida Power & Light Co. 78/09/29. 2pp.
- --7810240071 Responds to 780814 NRC 1tr re violations noted inspec Repts #50-250/78-12 & #50-251/78-12. Corrective actions include: procedures implemented to document signature of plant work orders documenting equip release URRIO.R. E. Floride Power & Light Co. 78/09/18. Spp.
- --7810240208 Forwards IE Inspec Repts#50-250/78-12 t #50-251/78-12 on 780626-29 t Notice of Violation.
  LUNG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/08/14. 2pp.
- --7810240211 Notice of Violation from inspec on 780626-29. LB-IB.R.C. Region 2. Atlents. Reactor Operations Nuclear Support Branch. 72008/14. 2pp.
- --7810240217 1E Inspec Repts#50-250/78-12 & #50-251/78-12 on 780626-29 during which 3 trams of noncompilance were noted failure to document proper approval of plant work orders & operational release of safety related equip & control clearance of equip LEHIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/08/14. 13pp.
- 7B10260004 Ack receipt of 7B0823 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/78-10 & 50-251/78-10.

  O'REILLY, J. P. Region 2. Atlenta, Office of the Director, 7B/10/13.

  3pp. 74404:216.
- --7810260007 Responds to 780717 NRC ltr re violetions noted in inspec Rept#850-250/78-10 & 50-251/78-10. Clerifies info re training of Fire Team members & requests change to unresolved item. Requests suspendion of deviation to review NUREO 0041. UHRIG.R. E. Fiorida Power & Light Co. 78/08/23. App. 94404:219.
- --7810260010 Forwards 1E inapec Rept#50-250/78-10 & #50-251/78-10 on 780526-0602 & Notice of Violation & Notice of Deviation. BUTHERLAND, J. T. Region 2, Atlanta, Office of the Director, 78/07/17. 2pp. 94404; 223.
- --7810260064 Notice of Violetion From inspec on 780526-0602.

   Region 2. Atlenta. Office of the Director. 78/07/06. 1p. 9404:225.
- --7810260069 Notice of Dsylation from Inspec on 780526-0602. On 780601, 52 of 57 fire brigade trained mambers were not cartified as respiratory protection qual per NUREQ-0041. • Region 2, Atlanta, Office of the Director. 78/07/06, ip. 9404:226.
- --7810260073 IE Inspec Repte#50-250/78-10 & #50-251/78-10 on 780526-0602 during which item of noncompliance & item of deviation were noted training of fire team personnel & certification of fire team personnel in respiratory protec.

  91880N.0.T. Region 2, Atlante, Office of the Director. 78/07/06.
  6pp. 94404:227.
- 7810300321 Forwarde IE Circular 78-17.
  D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/10/13.
  1p. 94253: 329.
- 7812010123 Ack receipt of 781031 ltr informing NRC of steps taken to correct violations noted during inesect50-230/78-10 k

- --7812010128 Responds to 781013 NRC Itr re violations noted in Inspec Repts#30-290/78-10 & #50-251/78-10. Corrective actions: respiratory protec training will be introduced by 781101 for members of each shift. UH104R.E. Florida Power & Light Co. 78/10/31. 1p. 94418:097.
- 7812120232 Forwards IE Inspec Repts#50-250/78-20 4#50-251/78-20 on 780905-08 & Notice of Violation. LONG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/17. 2pp. 94277:206
- --7812120235 Notice of Violation from inspec on 780905-08
   Region 2: Atlanta: Diffice of the Director: 78/10/17. \$p. 94277.208.
- --7812120237 IE Inspec Repts#50-250/78-20 & #50-251/78-20 on 780905-08 during which 2 items of noncompliance were noted; use of or failure to rev obsolete procedure for meint or surveillance. MRTIN-R.D. Region 2. Atlante, Office of the Director. JOHNSON.A.H., WHITENER.H.L. Region 2. Atlante, Reactor Operations Nuclear Support Branch. 78/10/17. 7pp. 9427:209.
- 7811070309 Ack receipt of 1E inspec Rept(e)#50-250/78-18,#50-251/78-18, on 780822-25, Does not consider any info therein to be proprietery.

  UHRIG.R. E. Florida Power & Light Co. 78/10/22. 1p. 94041: 146.
- --7811070314 Forwards 1E Inspec Rept(s)#50-250/78-18 & 50-251/78-18 on 780822-25 during which no Itams of noncompliance were noted. LCNG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/29, 2pp. 94041:147.
- --7811070320 1E inspec Rept(e)#50-250/78-18 & 50-251/78-18 on 780822-25 during which no items of noncompliance were noted. Major areas inspected included; organization & admin.followup on noncompliance.IE Bulletins & circulars.reportable events. VERDERY, E. H., LEWIS.R. C. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/09/29 7pp. 94041:149.
- 7811030003 Ack receipt of 780914 itr informing NRC of eteps taken to correct violations noted in IE insp Repts 50-250/78-11 & 50-251/78-11.

  SUTHERLAND, J. T. Region 2. Atlants. Fuel Facility & Meterials Befety Branch. 78/10/24. 1p. 02720:221.
- --7811030168 Responds to 780811 NRC itr re violations noted in Inspec Repts#50-250/78-11 & #50-251/78-11. Corrective actions: radiation controlled Area inspec every shift; seeled sources being tested; contaminated respirators removed. UHRIO,R.E. Floride Power & Light Co. 78/09/14. 5pp. 02720: 222.
- --7811030171 Forwards IE Inspec Repts#50-250/78-11 & #50-251/78-11 on 780619-23 & Notice of Violation.

  8UTHERLAND.J.T. Region 2. Atlente. Fuel Facility & Materials Sefety Branch. 78/08/11. 2pp. 02720:227.
- --7811030175 Notice of Violation from inspec on 780619-23.

  8UTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials
  Befety Branch. 78/08/11. 3pp. 02720; 229.
- --7811030178 IE Inapec Repts#50-250/78-11 & #50-251/78-11 on 780619-23 during which 4 items of noncompliance were noted:control of high rediation areas/health physics procedures/periodic leak teetihealth physics retraining program.

  \* Region 2. Atlents. Fuel Facility & Materials Sefety Branch. 78/10/24. 16pp. 02720:232.
- 7812010043 Ack receipt of IE Image: Repts#50-250/78-17 & #50-251/78-17. Does not consider any info therein to be proprietary. UHRIO.R.E. Fiorida Power & Light Co. 78/10/24. 1p. 94416:118.
- 7811100082 Ack receipt of 781031 itr informing NRC of steps taken to correct violations contained in IE Insp Repts 50-250/78-13 & 850-251/78-13.

  KENNA: M.S. Region 2. Atlanta, Sefsguards Branch. 78/10/31. 1p. 94179:302
- --7811100083 Responds to 780915 NRC ltr re violations noted in Inspec Repts850-250/78-13 & \$50-251/78-13 Corrective actions withheld (ref 10CFR2.790). URRIG.R.E. Fiorida Pawer & Light Co. 78/10/19. ip. 94179:333.
- --7811100086 Forwards IE Insp Rept 50-250/78-13 & 50-251/78-13 on 780710-13.
  KENNA-H B. Region R. Atlante: Safeguards Brench 78/09/15 288.

- 7811180103 Forwards IE Circular 78-18. D'REILLY, J. P. Region 2. Atlante, Office of the Director. 78/11/06 1p. 94113:293.
- 7811240025 Ack receipt of IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31. Does not consider any info therein to be progrietary. UHRIG.R.E. Florida Power & Light Co. 78/11/09. 1p. 94457.326.
- --7811240027 Forwards IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 760828-31 during which no items of noncompliance were noted. HURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 78/10/17. 2pp. 94457:327.
- --7811240033 IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted Major areas inspected included: inever inspec activities & records & meint & mod welding & NDG Activities & Prog.

  BLAKE, J., CONLON, T. E. Region 2. Atlante, Reactor Construction & Engineering Support Branch. 78/10/12. App. 94457:329
- 7812010100 Ack receipt of IE Inspec Rept#50-250/78-23 & #50-251/78-23. Does not consider any info therein to be proprietary.
  UNRIG.R.E. Florida Power & Light Co. 78/11/15, 8pp. 94417:082.
- --7812010104 Forwards IE Inspec Rept#50-250/78-23 & #50-251/78-23 on 780912-15 during which no items of noncompliance were noted. LONG.F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/23, 2pp. 94417:083.
- --7812010109 1E Inspec Rept 50-250/78-23 & 50-251/78-23 on 780912-15 during which no items of noncompliance were noted Major areas inspected incl:plant open Policeing of rept events IE bulleting & circulers.

  VERDERY, E. H., LEWIS, R. C. Region 2, Atlanta, Reactor Operations

  Nuclear Support Branch. 78/10/23. 5pp. 94417:085.
- 7812010116 Ack receipt of 781024 itr informing NRC of steps taken to correct violations noted during inspec#50-250/78-16 & #50-231/38-j6.

  8UTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Bepaty Branch. 78/11/16. | 1p. 94418:021.
- --7812010119 Responds to 781016 NRC ltr re violations noted in inspec Repts#50-250/78-16 & #50-251/78-16. Corrective actions: aprial requirements will be astablished for Ci/sec rate.

  URRIGAR, E. Florida Power & Light Co. 78/10/24. 3pp. 94410:022.
- 7812050240 Ack receipt of 1E Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15. Dose not consider any info therein to be proprietary.
  UHR19.R.E. Fiorida Power & Light Co. 78/11/16. ip. 94202:046 UHR 10. R. E.
- --7812050242 Forwards [E Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15 & Notice of Violation. BUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materiele Sefety Branch. 78/11/00. 2pp. 94202:047.
- --7812050246 Notice of Violation from Inspec on 780912-15.

  # Region 2, Atlante: Fuel Fecility & Meterials Safety Branch, 78/11/03. 1p. 94202:049.
- --7812050249 IE Inspec ReptM50-250/78-22 & M50-251/78-22 on 780912-15 during which I item of noncompliance was noted; review of groundwater monitoring sched not done quarterly but semi-amusliy w/out benefit of req amend to Iic. CUNNINGHAN, A. L., HUFHAM, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/10/12. 6pp. 94202:050.
- 7812120057 Forwards reproductions of articles that appeared in Juns & Aug 1978 editions of Nuc Security Bafeguards Newsistter.
  KENNA, M. B. Region 2, Atlanta, Bafeguards Branch. 78/11/17, 4FP. 94278: 092
- 7812040308 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl AND: 7811300055.

  O'REILLY, J. P. Region 2. Atlante. Office of the Director. 78/11/24. 1p. 94129: 160.
- 7812120206 Ack receipt of 781114 ltr informing NRC of steps taken to correct violations noted during inspec#50-250/78-20, #50-251/78-20.

  LDNG-F.J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/12/04. ip. 94277:202.

7812190235 Ack receipt of 16 Inepec Repts#90-230/78-25 & #50-231/78-2 on 781016-20 Does not consider any info therein to be proprietory. UHRIG.R.E. Florida Power & Light Co. 78/12/06. 1p. 94374: QQL.

94277:203

UPRIO.R. E. Florida Power & Light Co. 78/12/04. 3pp.

- --7812190238 Forwards IE Inspec RepteM50-250/78-25 &M50-251/78-29 on 781016-20 during which no items of noncompliance were noted. LONG-F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 70/11/17. 2pp. 94376
- --7812190243 IE Inspec RapteM50-250/78-25 & M50-251/78-25 on 781014-2 during which no items of noncompliance were noted. Major areas inspected incl:plant oper after refueling, followups of noncompliance.oper items. IE publications, smergency drills. VERDERY, E.H. Region 2, Atlanta, Reactor Operations Nuclear Suppo Branch. 78/11/17. 7pp. 94376:004.
- 78:2180138 Forwards facil Steam Generator inspec Prog planned for Jan UHR19.R.E. Florida Power & Light Co. 78/12/11. 1p. 94345: 284.
- --7812180141 "Turkey Point Unit#3 Bleam Generator Inspec Prog Planned January 1979. \* Fiorida Power & Light Co. 78/12/11. 2pp. 94365.285.
- 7812210068 Ack receipt of IE Inspec RepteM50-230/78-24 & M50-281/78-2 Does not consider any info therein to be proprietary. UHR10-R.E. Florida Power & Light Co. 78/12/11. 1p. 94269: 338.
- --7812210071 Forwards 1E Inspec Repts#50-250/78-24 & 50-251/78-24 on 781018-19 during which no items of noncompliance were noted. SUTHERLAND, J. T. Ragion 2: Atjanta Fuel Facility & Materials Bafety Branch. 79/11/22. 2pp. 94269, 339.
- ~7812210076 1E Inspec RepteM50~250/78-24 % M50~251/78-24 on 781018-1 during which no items of noncompliance were noted. Major aress inspected incl: observation of annual Emergency exercise, iconses fire drill b discussions e/personnel. HUFHAM.J.M., 01880N.Q.T. Region-2. Atlanta. Fuel Facility & Materials Bafety Grench. 78/11/22 5pp. 94269:341.
- 7812280328 Ack receipt of 781201 itr Informing NRC of steps taken to correct violations noted during inspec#50-250/78-21 % W50-251/78-21. SUTHERLAND, J. T. Region 2. Atlante. Fuel Facility & Meterials Bafet Branch. 78/12/19. 2pp. 94082:155.
- --7812280339 Responds to 781106 NRC ltr re violations noted in Inspec Repts#50-250/78-21 & #50-251/78-21. Corrective actions: respiratory protec equip training classes & health physics
- UHR19, R. E. Florida Power & Light Co. 78/12/01, 5pp. 94082:157 --7812280342 Forwards 1E Inapec Repts#50-250/78-21 & #50-251/78-21 or 780911-15 & Notice of Violation. SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/11/06. 2pp. 94082:162.

training classes held.

- --7812280344 Notice of Violation from inspec on 780911-15. \* Region 2. Atlanta, Office of the Director. 78/11/06. 2pp. 74082:164.
- --7812280348 IE inspec Repts#50-250/78-21 & #50-251/78-21 on 780911-1 during which 3 items of noncompliance were noted; issuance & use of respirators, preparation of shipments of radioactive matl not in requirements & failure to lock high radiat areas CCLLINS.D.M., ZAVADDEKI.R.M., 01880N.A.F. Region 2. Atlanta. Office of the Director. 78/11/03. 13pp. 94082:1&6.
- 7812290087 Forwards IE Bullstin 78-14. D'REILLY, J.P. Region 2. Atlants, Office of the Director, 78/12/15 2pp. 03669:358.
- B. Reportable occurrences. LERs & related correspondance
- 7811060142 Forwards LERM78-013/03L-0.
  BCHM1D7.A.D. Floride Power & Light Co. 78/10/27, 1p. 94424; 281.

- 7811050144 Forwards LERM78-014/03L-O.
  BCHM1DT, A.D. Florida Power & Light Co. 78/10/27. ip. 94489:059.
- --7811050148 LERM78-014/03L-0 on 780929:Comparator pur supply FC-3-484 maifunctioned due to faulty regulating oper amplifier in comparator's pur supply bd Amplifier was replaced & comparator tested satisfactorily.

  SCHOPPMAILH A Florida Power & Light Co 78/10/27. lp. 92450 050
- 7811220201 Forwards LER#78-015/03L-0.
  BCHM1DT.A D. Florida Power & Light Co. 78/11/08. ip 03695.278.
- --7811220203 LERH78-015/03L-0 on 781010, i9 accessible safety related snubbers were replaced one at a time w/mschanical snubbers. SCHOPPMAN.M.A. Fibride Power & Light Co. 78/11/08 lp. 03695.279
- 7812040187 Forwards LER#78-016/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 78/11/24. lp. 94457:106.
- --7812040189 LERM78-016/03L-0 on 781025 during pur oper-intake cooling water pumps were running when 38 pump mater failed. The 38 pump motor failed because of short circuit in the motor windings

  SCHOPPMAN.M. A. Fioride Power & Light Co 78/11/24. 1p. 94457-107
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

  F. Becurity, medical, emergency & fire protection piens
- 7812080148 Licensee has been orally notified that Emergency Plan through Revision 4 dtd 780927 is acceptable, based on 781025 memo M/enci ANG 7811020177.

  BCHWENCER: A Operating Resitors Granch 1 (Pro 790625). 78/11/28 ip. 94104.349.
- 7812110010 Pending staff approval of Rev O, requests util commit to prepers special security procedures applicable to the replacement of steem generators.

  8CH-ENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/12/01. 2pp. 94339 235.
- 7812120119 Discusses fire protection in operating nuclear power stations in particular providing analysis of facilities' SER. Proposed fire protection mod increases level of protection against fire hazards.

  HALL.R.E. Brochhaven National Laboratory. 78/12/06. Spp. 74275: 340
- 7810120075 Forwards copies of Rev 4 to subj facil Emergency Plan. UHR10.R E. Fiorida Power & Light Co. 78/09/27, 2pp. 94402:221.
- --7810120081 Rev 4 to State of FL Radiological Emergency Plan dtd May 1975.Ltr of support w/ERDA dtd 730410.FL Highway Patrol Order 32 dtd 760401 & Coast Guard 760426 ltr encl \* Florida Power & Light Co. 78/09/27. 166pp. 94408:223.
- 7810300325 Ack recispt of 780623 ltr rs position that 3-man fire brigads is adequate to cope w/eny fire at subj facil. Requests add1 info so NRC may evaulate proposal. SCHENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/10/16. 3pp. 94253:341.
- 7810310121 Forwards Rev 0 to security plan dtd 780526 Withheld (ref 10CFR2.790).
  URRIO.R.E. Florida Power & Light Co. 78/10/24. 111pp.
- 7811130221 Forwards response to 781016 NRC ltr requesting info re availability of supplementary fire brigade support personnel actions req of personnel & training & squal of Individual who established size of brigade & training prog. URRIG.R. E. Floride Power & Light Co. 78/11/07. Spp. 03554:109.
- 7811280170 Forwards Amend#42 to Facil Oper Lic#DPR-31 & Amend#34 to Facil Oper Lic#DPR-41. Amend Tech Specs for Fira Protec Sys & Admin controls in Response to 771222 Appl(1-77-390). BCHMENCER: A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 5pp. 94013:173.

- --7811280172 Amend#42 to Lic#DPR-31 rev common station Tech Spece to incorp limiting conditions for open & surveillance requirements for existing fire protec sys. SCHHENCER.A. Operating Reactors Branch 1 (Pre 790625) 78/11/08. 2pp. 94013:178
- --7811280174 Amend#34 to Lic#DPR-41 rev common station Tech Specs to Incorp limiting conditions for oper & surveillance requirements for existing fire protec sys. SCHEMERCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 20pp. 94013:180.
- --7811280178 Notice of Issuence of smend#34 & 42 to Facil Oper Lick PPR-31 & DPR-41 Amend rev Tech Specs to incomp limiting conditions for oper & surveillance requirements for existing fire protecting. SCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 78p. 94013:200.
- 7812:20125 Requests add1 info re fire protec at subj facils, info conterns water supply cable protectyard hydrants, smoke vanting equip & smoke removal Documentation re info acught enci.

  HALL R.E. Brookhaven National Laboratory. 78/09/21. 9pp 94275:245.
- 7812270190 Responds to 781201 NRC request for special security procedures. Agrees to prepare security procedures IAW Mod Amend Security Plan at lesst 90 days prior to commencing steem generact repair sctivity.
  UKRIO,R.E. Florida Power & Light Co. 78/12/15. 1p. 94018:042
- H. General correspondence
- 7819270168 Requests placement on distribution list for correspondence & repts dealing w/oper status for subj facils.

  BHREVE-J. Floride, State of. 78/12/18. 1p.
- 1. Financial information
- 78:1070144 Forwards req guarantees under Price-Anderson as emend 1975 under option 5.Enci provides info re 1977 annual rept, consolidated finencial statements.cash flow projections, capitel expenditure curtailments & cash flow sources.

  UHR10.R E. Florida Power & Light Co. 76/10/30. 45pp. 94044:022.
- J. Insurance & Indomnity information
- 7810230140 Forwards Endorsement#37 to Nuc Energy Liability Insurance MMF-55. Also States that Endorsement#36 to Nuc Energy Liability Insurance#NF-185 was forwarded w/760618 FPL ltr
- UHRIG.R.E. Fiorida Power & Light Co. 78/10/09. 2pp. 94164:203.
- 7810300107 Forwards Endorsement#36 to Pollcy#NF-185 & Endorsement#37 to pollcy#NF-55. URR10.R.E. Florida Power & Light Co. 78/10/09. 1p. 94035:236.
- M. Antitrust correspondence
- 7811080144 "Notice of Appearance"re proceedings. Cert of Svc encl. EVANG. D. J. Office of the Executive Legal Director. 78/10/30. 3pp. 94399: 291.
- 7812270071 Provides notice that RC McDiermid & DA Giacalone w/draw as representatives of FL Cities in proc re subj facils.
  JABLON.R.A. Bejegel & McDiarmid. 78/12/13. 4pp. 94161:01).
- P. Operating license stage documents & correspondence
- 78:01:01:23 Forwards "Rept of Abnormal Indications from Metal Impact
  Monitoring Bys," during 78:09:22-25 reactor coolant pump runs.
  UHR10,R.E. Florida Power & Light Co. 78/10/06. 2pp. 94067:349.
- 7812010382 Response to 780613 ltr re comments & corrective actions in 780404 NRC ltr re Diesel Generator Lockout. Util's response is adequete.

  8CHWENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/06/30. is.
- 7812180378 Notice of 781218 meeting w/FL Light & Pur Co to discuss review of subj facil's Steam Generator Replacement Prog. GROTENHAIS.M. Operating Reactors Branch 1 (Prs 790525). 78/12/14. 2pp. 94358:215.

- 7812190035 Porwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Praparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

  ORIMES-8 K. Assistant Director for Engineers & Projects (Pre 79023).
  78/11/15. 6pp 94215.009
- 7812290026 Forwards NPDES permit for subj facil Permit to become effective on date noted provided no request for adjudicationy hearing is filled with EPA. W/enc1 EPA correspondence.
  TRAINA-P. J. Environmental Protection Agency. 78/06/14. ip 94131:037
- 7810250175 Notice of Proposed Issuence of Amends to Facil Oper Lics NRC is considering issuence of amends to Facil Oper Lics DPR-31 & DPR-41. Amends rev Tech Space re transfert & accident analysis.

  BCHWENCER, A Operating Reactors Brench i (Pre 790625) 78/08/04 4ps. 94393:062.
- 7811210191 Notice of Issuance of Amenda 38 & 31 to Facil Oper LickDPR-31 & MDPR-41. Amends thange Tech Space to refueling of Unit 4 Cycle 3 oper. 8CHENCER. A Operating Reactors Branch ( Pre 790625). 78/09/22. 3pp. 94488-003.
- 7810120022 Forwards test rept for 770701-780630 per 10CFR50 59b. UMRIO,R E. Floride Power & Light Co. 78/10/04. 1p. 94330:174.
- --7810120023 Test rept details plant change/mods.procedure changes, tests & szpers. Mejor arase: task-crehar-add-limit switches, diesel swargenty diesel surge tank.NDDT overpressure relief protection, reactor coalent pump seel mod.flamestic addition. \* Florida Power & Light Co. 78/10/04. 65pp 74/30:175
- 7810110159 Responds to 780802 NRC itr re meterological data.Forwards info tables re wind frequency.

  UHRIG.R.E. Floride Power & Light Co 78/10/05. 9pp. 94069:226
- 7810270182 Ack receipt of 780719 ltr requesting proposed Tech Boecs be submitted addressing overpressure protec. Will submit info by 781115.

  URRIO-R.E. Florida Power & Light Co. 78/10/19. 1p. 94057:083.
- 7810300003 Requests addi 4400 fee to process 780809 appl for amend to Facil Lic WDPR-31 & DPR-41.
  MILLER.W D. License Fee Management Branch. 78/10/19. ip. 94034:224.
- 7811030177 Ack revism of Rev 1.2,3,4.Rev 1.& 2 found acceptable.Rev 3 & 4 update arrangements w/various radio1 emergency support groups.Back-up hospital changed to Baptist Hosp, After review-3 & 4 found acceptable.

  KNICHTON.O. Environmental Evaluation Branch (Pra 790625). 78/10/25.

  1p. 94104:350
- 7811030203 Forwards corrected page#1 to Amend#30 to LicHDPR-41 dtd 780921.
  8CHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/25.
  28p. 02724:137.
- 7811090015 Forwards Amend#40 & 32 to Fecil Open Lic#DPR-31 & DPR-41, changing Tech Spec to reduce pressurizer heatup rate.
  8CHMENCER: A. Operating Reactors Branch 1 (Pra 790825). 78/10/25.
  2pp. 94040:001.
- --7811090018 Amend#40 to Fecil Oper LickDPR-31, changing Tech Spec to reduce pressurizer heatup rate.

  BCHWENCER.A Operating Reactors Brench 1 (Pre 790623). 78/10/25.
  2pp. 94040:003.
- --78i1090021 Amend#32 to Facil Oper Lic#DPR-41.chenging Tech Epec to reduce pressurizer heatup rate. 8CHMENCER.A. Operating Reactors Brench 1 (Pre 790625). 78/i0/25. 4pp. 94040:006.
- --7811090024 Safety Eval Supporting Amend#40 & 32 to Lic#DPR-31 & DPR-41 Concludes that no adverse affects will result.

  Office of Nuclear Reector Regulation, Director, 78/10/25, 3pp. 94040:010.
- 7811130075 Forwards relaxived Amend#38 & #31 to Facil Lic#DPR-31 & #DPR-41 w/corrected amend numbers.

  SCHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/26.

  2pp. 94478:329.
- --7811130080 Amend#38 to Facil Oper Lic#DPR-31, changing Tech Spec to auth oper w/23% of tubes in plugged condition. EISE-H-UT.D.O. Assistant Director for Systems Engineering (Pre 791030). 78/09/22. 2pp. 94076:314.

- ~-7811130083 Amend#31 to Facil Oper Lic#DPR-4: changing Tech Spec re refueling of Cycle 5 oper & auth oper u/25 percent tubes in plugged condition EISENUT. D Q Assistant Director for Bystems Engineering (Pre 791030) 78/09/22 13pp 94076: 344.
- --7811130170 Bafety evaluation supporting Arend#38 & 31 to Lic#DPR-31 #DPR-41 Concludes that no harm will those e Office of Nuclear Reactor Regulation. Director. 78/09/22. 1800. 94011 137
- --7811130175 Notice of Issuence of Amend#38 & #31 to Fec11 Oper Lic#DF 31 & #DPR-41, changing Tech Spec rs Cycle 5 oper & oper u/ tubes in plugged condition. BCHMENCER, A Operating Reactors Brench i (Pre 7906251. 78/09/22 3pp. 9401:135
- 7811070180 Forwards theck in response to 781019 request UHRIGAR E Florida Power & Light Co 78/10/30. 1p 94036:357.
- 7811290068 Anends#38 & #31 to Facil Oper Lic#DPR-31 & #DPR-41 for subj facils were completed on 780922 Wissuence of these two amends.all prior NRC Orders is subj facils have been setisfied. Audit tabulation encl.

  BCHENCER, A. Operating Reactors Brench 1 (Pre 790625) 78/11/08 3pp. 94193.223.
- 7811200417 Forwards results of measurements of radioactive mat1 in NRC phantom on whole body counter Enci 1 contains actual enount of each radionucilds present.sncl 2 gives ratio of measurements to DDE values & encl 3 gives recommendations BUTHERLAND, J T Region 2. Atlants. Fuel Fecility & Materials Bafsty Branch. 78/11/09. 3pp 94419.164
- 7811210256 Notifies util of 781205 teminar in Atlanta to discuss new Model Rod Gefluent Tech Bacca & encl seminar Enfo sheet, registration form. & proposed agenda O'fEilLY.J P. Region 2. Atlanta. Office of the Director. 78/11/09 Spp. 74488 330
- 78:11:60139 Forwards info in response to 780518 NRC request for info restand generator & reactor coblent pump supports sufficient to show geometry of all principal elements. Oversize drawings available in Central Files

  UHRIGAR E Floride Power & Light Co. 78/11/10 ip 94135:249.
- --78iii60i42 "Report on Frecture Toughness & Potential for Lameiler Tsering of Steem Osnerator & Reactor Coolent Pump Supports." w/29 oversize drawings showing geometry of all principal elements available in Central Files.

  \*\*Florida Power & Light Co 78/09/30. 40pp. 94135:250.
- 7811300041 Forwards NRC stepf paper.Policy Bession Iter(BECY-78-354) 1 licensee reg performence evaluation. Three methods for evaluation are: stetlatical.trend enalysis & regional survey method W/o ancl D'REILLY, P. Region 2, Atlante. Oppice of the Director 78/11/15 2pp. 94071-035.
- 7812180036 Notice of workshops re implementation of training & qual requirements contained in Append B of 100FR73 Requests pre-workshop registration of attendees to facilitate sending out matl. Wyencl Registration Form & List of Locations. MILLER-J.R. Assistant Director for Site & Safeguards (Pre 791030), 78/i1/15. Spp. 94i33:031.
- 7811270ibl Forwards appl for Amend to Facil Operating Lics#DPR-31 & DPR-41.Proposed erend addresses Overpressure Mitigeting Sym (OMS). Discusses limiting conditions for oper of Reactor Coolant Sys.

  UHRIOR. E. Florida Power & Light Co. 78/11/20. 11pp. 94252:324.
- 7811280228 In response to 780915 NRC ltr.submits suppl to 760604 ltr meet requirements of Sec V.B of Append I to 10CFR50 to operationally evaluate drain floor treatment sys which is suppl by a portable demineralizer.

  UMR19.R.E. Florida Power & Light Co. 78/11/20. 3pp. 94012:047.
- 7812140357 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wanci ANDS 7812080207. SCHENCER. A. Operating Reactors Branch 1 (Fre 790625). 78/11/28. App. 03557:223.
- 7812040336 Requests \$1,600 in lic fact since amend does not qualify for exemption under 10CFR170.22 footnote#2.
  MILLER.W.O. License Fac Management Branch. 78/11/29. 1p. 74127:356.

- 78:220017: Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants Info submitted must be substantiated by date & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIS.J G Office of Inspection & Enforcement, Office of the Director 78/12/05 2pp 94375 011
- 7812280019 Forwards copy of newly rev NPDES permit for subj facil No environ impact will result from changes incomp into new armit. UHRIG-R E Florida Power & Light Co 78/12/07 ip 94131: 036.
- --7812280040 Authoritation to discharge under NPDES from FL Pur & Light facile to circulating water cooling canal sys. to become affective 780701 TRAINA.P. J. Environmental Protection Agency 78/12/14 13pp. 94131 038
- 7812140146 Forwards "Cycle S Startup Rept.
  UHR10+R E | Florida Power & Light Co | 78/12/08 | 1p | 94479.001.
- --7812140152 "Cycle 5 Startup Rept " Test began 780927 w/initial CTITICALITY & was completed 780930.

  MENDE.R. Q., TOMONTO.J.R., KAMINSKAS,V A. Floride Power & Light Co. 78/12/08 | 28pp | 94479 002.
- 7812140150 Submits request to arend Append A of Facil Oper Lic#DPR-31 & DPR-41-in response to 780719 NRC ltr.Amand concerns operability & surveillance of facil Overpressure Mitigating.
  UHR10.R.E Florida Power & Light Co 78/12/11 11pp 94127.009.
- 7812210196 States acceptance criteria on rod worths is w/in 10% from design For Cycle 4 the difference from Westinghouse design was 7 8% Provides measured vs design values for rod worth in ppm boron concentrations.
  UHR10-R E Florida Power & Light Co. 78/12/14, 1p. 94279:067.
- 7812270195 Forwards additinfo to suppl 780529 ltr in response to NGC request for detailed schedule for providing eval of effects of asymmetric loss of coolant accident loads. UHR10-R E Florida Power & Light Co. 78/12/19 ip 94018:087.
- 7812270187 Forwards M4tl Statue Rept for period 771001 to 780331 for LicMDPR-31.DPR-41.DPR-67 & 8NM-1514 & Nuc Metl Transaction Rept for LicMDPR-31 & DPR-41 UMR10.R E Florida Power & Light Co. 78/12/20 31pp. 94018:006.
- 7812270221 Forwards request to emend Append A of Fecil Oper Lice DPR-31 & 41 Buby proposed requests changes in rod insertion limits for both units to allow more flexibility in long range reload planning W/encl safety evaluation. UHR10-R.E. Pennsylvania Power & Light Co. 78/12/22 7pp 94017: 122
- 7812280139 Informe of plans for next facil refueling & results of raview of refueling analysis method Unit 3 is in oper cycle 5 & next refueling is sched for 791230 Hestinghouse FLARE code will be used for reload design UHRIO.R.E Florida Power & Light Co. 78/12/22 2pp. 94310:350.
- 7811210338 Requests ratief from ASME Code requirements re ultrasonic exeminations of piping welds. Recording & eval indications at 20% DAC is impractical Primary reference level(100% DAC) criteria for UT esam providas comparable asfety lavel
  UHRIO.R E. Florida Power & Light Co. 78/11/13 4pp 94484.324
- Q Inspection reports. 1E Bulletins & correspondence
- 7811100082 Ack receipt of 781031 itr informing NRC of steps taken to correct violations contained in IE Insp Repts 50-250/78-13 & #50-251/78-13 KENNA, W. B. Ragion 2: Atlenta, Safeguards Branch. 78/10/31. Ip 94179: 332
- --7811100083 Responds to 780915 NRC itr re violations noted in Inspec Repts#80-250/78-13 & #50-251/78-13 Corrective actions withheld (ref 10CFR2 790) UR10-R.E. Florida Power & Light Co. 78/10/19, 1p. 94179:333.
- --7811100086 Forwards IE Inep Rept 50-250/78-13 & 50-251/78-13 on 780710-13 KENNA, N B. Region 2. Atlanta, Safaguards Branch. 78/09/15. 2pp. 94179 335.
- 7811130003 Forwards IE Inspec Repts#50-250/78-17 & #50-251/78-17 on 780718-19 during which no items of noncompliance were noted.
  KENNA. H. B. Region 2: Atlanta: Safeguarde Branch. 78/08/24, 2pp. 94077: 008

- --7811130007 IE Inspec Repts#30-230/78-17 & #30-231/78-17 on 780718-19 during which no items of noncompliance were noted. Major areas inspected: special security inspec of discovery of a hose bomb device
  MODRE.D E . OILLESPIE.F.P Region 2. Atlanta. Office of the
  Director . 78/08/23 3pp. 94077 013
- 7812010043 Act receipt of 1E Inspec Repts#50-250/78-17 & #50-251/78-17. Does not consider any info therein to be proprietary.
  UNRIG.R E. Florida Power & Light Co 78/10/24. lp. 94416:118
- 7812010100 Act receipt of 1E Inapec Rept#50-250/78-23 & #50-251/78-23. Does not consider any info therein to be proprietery.

  UHRIG.R.E Florida Power & Light Co. 78/11/15 8pp. 94417:082.
- --7812010104 Forwards IE Inspec Rept#50-250/78-23 & #50-251/78-23 on 780912-15 during which no items of noncompliance ware noted. LONG.F. J Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/23. 2pp 94417:083
- --7812010109 IE Inspec Rapt 30-250/78-23 & 50-251/78-23 on 780912-15 during which no items of noncompilance were noted Major ereas inspected inci:plent open-following of rept avants. IE bullating & circulare. Pullating & Circulare. VERDERY, E. H., LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 78/10/23. Spp. 94417-085.
- 7812010116 Ack receipt of 781024 ltr Informing NRC of steps taken to correct violations noted during inspect50-250/78-16 & 850-251/78-16 BUTHERLAND.J T. Region 2. Atlenta, Fuel Facility & Materials Safety Branch. 78/11/16. ip 94418:021.
- --7812010119 Responds to 781016 NRC itr re violations noted in Inspec Repts#50-250/78-16 & #50-251/78-16. Corrective actions: serial survey will be performed over sub; facil, procedural requirements will be established for Cifesc reta. URIG.R.E. Florida Power & Light Co. 78/10/24. 3pp. 94418:022.
- 7812010125 Ack receipt of 781031 ltr informing NRC of steps taken to correct violetians noted during inspec#50-250/78-10 & #50-251/78-10 #5D-251/78-10 BUTHERLAND.J T Region 2. Atlante- Fuel Fecility & Materials Bafety Branch 78/11/16. 1p. 94418:03b.
- --7812010128 Responde to 781013 NRC ltr re violations noted in inspec Reptem50-230/78-10 & #50-251/78-10. Corrective actions: respiratory protec training will be introduced by 781101 for members of each ehift.
  UHRIG-R.E. Florida Power & Light Co. 78/10/31. ip. 94418:057.
- 7812120057 Forwards reproductions of articles that appeared in June & Aug 1978 aditions of Nuc Security Gefeguards Newsletter. KENNA, W.B. Region 2. Atlanta, Sefeguards Branch. 78/11/17. 4PP. 94278:092
- 7811010407 Forwards IE Inspec Rept#50-250/78-16 & #50-251/78-16 pm 780724-27 during which no items of noncompliance were noted.

  8UTHERLAND.J. T. Region 2. Atlente, Fuel Facility & Meterials Safety Brench. 78/09/21, 2pp. 94388: 330.
- --7811010411 IE Inepac Rept#50-250/78-16 & #50-251/78-16 on 760724-27 during which no items of noncompliance were noted. Major areas inepected included: radiological environ protec & emergency planning.

  GIBBON, G.T. Region 2. Atlanta, Office of the Director. 78/09/11.

  4pp. 94388:332.
- 7810110247 Orants requests in 1tr of 780914 to w/hold proprietary info in Inspec Repts#50-250/78-14 & 50-251/78-14. LONG.F.J. Region 2: Atlanta. Resctor Operations Nuclear Support
- --7810110251 Requests w/holding propriatory info in Inspec Repts #50-250/78-14 & 50-250/78-14. UHRIG. R. E. Florida Power & Light Co. 78/09/14, 1p. 94068:202.
- --7810110256 Forwards IE Inspec Repts#50-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted. LONG.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/08/21. 2pp. 94068:203.
- --7810110262 IE Inspec Repts#50-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted Major areas inspected included: calibration, surveillance, & procurement.
  OVITS, J. E. KELLDOO, P. J. Region 2. Atlanta, Reactor Operations
  Nuclear Support Branch. 7B/08/17. 8pp. 94068:205.

- 7810240067 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted during inspect50-250/78-12 & 850-251/78-12. LDNG.F.J Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/10. 1p.
- --7810240075 Responds to 780814 NRC ltr re violations noted in Inspec Repts#50-250/78-12 L#50-251/78-12 Corrective actions: Ltr to be issued requiring operational release must be obtained grior to starting work on sefety releted equip. URIOR E. Florids Power & Light Co. 78/09/29. 2pp.
- --7810240071 Responds to 780814 NRC ltr re violations noted inspec Repts 850-250/78-12 & 850-251/78-12. Corrective actions include: procedures implemented to document signature of plant work orders documenting equip relesse. UR10/R E. Fiorida Power & Light Co. 78/09/18. 5pp.
- --7810240208 Forwards 1E Inspec Repts#50-250/78-12 & #50-251/78-12 on 780526-29 & Notice of Violation LCNO.F. J. Region 2, Atlants, Reactor Operations Nuclear Support Brench. 78/08/14. 2pp.
- --7810240211 Notice of Violation from inepec on 780626-29. LEMIS.R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Brench. 78/08/14. 2pp.
- -7810240217 IE Inspec Repts#50-250/78-12 & #50-251/78-12 on 780626-29 during which 3 items of noncompliance were noted:fellure to document proper approvel of plent work orders & operational release of safety releted squip & control clearance of squip LEM18-R. C. Region 2, Atlanta, Resctor Operations Nuclear Support Branch 78/08/14 13pp.
- 7810260004 Ack receipt of 780823 ltr informing NRC of steps taken to correct violations noted in IE lnep Repts 30-230/78-10 & 50-23178-10.

  D'RELLLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/13.
  3pp. 74404:216.
- --7810260007 Responde to 780717 NRC ltr re violations noted in Inspec RepteM50-250/78-10 & 50-251/78-10. Ciarifies info re training of Fire Team members & requests change to unresolved ltem. Requests suspension of deviation to review NUREO 0041. URIO.R.E. Florida Power & Light Co. 78/08/23. App. 94404.219.
- --7810240010 Forwards IE Inspec Rept#50-250/78-10 & #50-251/78-10 on 780526-0602 & Notice of Violation & Notice of Deviation, BUTHERLAND.J. T Region 2. Atlanta. Dffice of the Director. 78/07/17. 2pp. 94404:223.
- --7810260064 Notice of Violetion from inspec on 780526-0600, \* Region 2, Atlanta, Office of the Director, 78/07/06, ip 9404:225.
- --7810260069 Notice of Deviation from Inspec on 780526-0602. On 780601, 32 of 37 fire brigede trained members were not certified as respiratory protection qual per NUREG-0041.

  Region 2. Atlanta. Office of the Director. 78/07/06. 1p. 94404:226.
- --7810260073 IE Inspec Repte#50-250/78-10 & #50-251/78-10 on 780526-0602 during which I item of noncompliance & I item of deviation were noted; treining of fire teem personnel & certification of fire teem personnel in respiratory protec.
  01880N.Q.T. Region 2. Atlanta, Office of the Director. 78/07/06. 6pp. 94404:227.
- 7810300321 Forwards IE Circuler 78-17.
  O'RELLLY.J. P. Region 2. Atlanta. Office of the Director. 78/10/13.
  1p. 94253:329.
- 7812120232 Forwards IE Inspec Repts#50-250/78-20 \$450-251/78-20 on 780905-08 & Notice of Violetion. LDNG-F, J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/17. 2pp. 94277:206.
- --7819120235 Notice of Violation from inspec on 780905-08.

  \* Region 2, Atlanta, Office of the Director. 78/10/17. ip. 94277:208.
- --7812120237 iE Inspec Repts#50-250/78-20 & #50-251/78-20 on 780905-08 during which 2 items of noncompliance were noted: use of ar feilure to rev obsolete procedure for maint or surveillance. MARTIN.R.D. Region 2. Atlente. Office of the Director. JOHRON.A.H., WHITENER,H.L. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/17. 7pp. 94277:209.

- 7811070309 Ack receipt of 1E inage: Rept(a)#50-250/78-18.#30-291/78-18. on 780822-25. Does not consider any info therein to be proprietary UMRIO.R E. Florida Power & Light Co. 78/10/22. ip 94041:146.
- --7811070314 Forwards IE Inspec Rept(s)#50-250/78-18 & 50-251/78-18 on 760822-25 during which no items of noncompliance were noted. LDNO:F.J Region 2. Atlanta, Reector Operations Nuclear Support Branch 78/09/29. 2pp 9404:147.
- --7811070320 IE Inspec Rept(e)#50-250/78-18 & 50-251/78-18 on 780892-85 during which no items of noncompliance were noted Major areas inspected included organization & admin.followup on noncompliance.iE Bulletins & circulare.reportable events. VERDERY.E H.; LEHIB.R.C. Repion 2, Atlanta. Reactor Operations Nuclear Support Brench 78/09/29 7pp. 94041:149.
- 78i1030003 Ack receipt of 7809i4 itr informing NRC of steps taken to correct violetions noted in iE insp Rapte 50-250/78-i1 & 50-251/78-i1. BUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materiale Safety Branch. 78/10/24. ip. 02720:221.
- --7811030168 Responds to 780811 KRC its re violations noted in Inspec Repts950-250/78-11 & 850-251/78-11. Corrective actions radiotion controlled Area inspec every shift-sealed sources being tested/conteminated respirators removed URRIOR E. Florids Power & Light Co 78/09/14. 5pp 02720:222.
- --7811030171 Forwards IE lnapec Repts#50-250/78-11 & #50-251/78-11 on 780519-23 & Notice of Violetion BUTHERLAND,J.T. Region 2, Atlanta, Fuel Facility & Meterials Bafety Branch 78/08/11. 2pp. 02720.227.
- --7811030175 Notice of Violation from inspec on 780619-23 BUTHERLAND, J. T. Region 2, Atjenta, Fuel Fecility & Meterials 8afety Brench, 78/08/11. 3pp. 02720:229
- --7811030178 iE Inepec Repts#50-250/78-11 & #50-251/78-11 on 780619-23 during which 4 items of noncompilance were noted:control of high radiation areas shealth physics procedures; periodic leak test-health physics retraining program Region 2. Atlanta. Fuel Facility & Meterials Safety Branch 78/10/24. 16pp. 02720:232.
- 7811210108 Responds to NRC ltr re-violations noted in Energy Repts#30-250/77-28 & #50-251/77-28. Corrective actions: 2 thermouslis & 2 couplings were replaced & welds liquid penetrant tested.

  UlRIO.R.E. Florida Power & Light Co. 78/10/31. 2pp. 94488:039.
- 7811150103 Forwards IE Circular 78-18.

  O'RETLLY, J. P. Region 2. Atlants. Dffice of the Director. 78/11/06.
- 7811240025 Ack receipt of IE Inspec Repte#50-250/78-19 & #50-251/78-19 on 780828-31. Does not consider any info therein to be proprietary. URIO.R.E. Floride Power & Light Co. 78/11/09. 1p. 94457: 326.
- --7811240027 Forwards 1E Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted. HURPMY.C.E. Region 2. Atlente. Reactor Construction & Engineering Bupport Brench. 78/10/17
- --7811240033 IE Inspec RepteM50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted. Hejor areas inspected included:insex ectivities & records & meint & mod welding & NDE Activities & Prog. BLAKE.J., CONLON.T.E. Region 2. Atlants. Resctor Construction & Engineering Support Branch. 78/10/12. App. 94457-327.
- 7812050240 Ack receipt of 16 Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15 Does not consider any info therein to be proprietery.
  UHR10.R.E. Florida Power & Light Co. 78/11/16 ip. 94202:046.
- --7812030242 Forwards IE Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15 & Notice of Violation.
  SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Naterials 84fety Branch. 78/11/03. 2pp. 94202:047.
- --78:2030246 Notice of Violation from inspec on 7809:2-15.

  \* Region 2, Atlanta, Fuel Facility & Materials Bafety Branch.
  78/11/03. ip. 94202:049.

- 7812040308 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/ancl AND.7811300055 D'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/11/24. ip. 94129:160.
- 7812120236 Ack receipt of 781114 ltr Informing NRC of steps taken to correct violations noted during inspec#30-250/78-20. #50-251/78-20. LONG.F. J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/12/04 1p. 94277: 202.
- --7812)20239 Responds to 781017 NRC ltr re violations noted in Inspec Reptam50-250/78-20 & 50-251/78-20 Corrective actions: work packages w/most recent info will be made & released to field & review of new Tech Space initiated. UHTIO, R. E. Florida Power & Light Co. 78/12/04. 3pp. 94277:203.
- 7812190235 Ack receipt of 15 Inspec Repts#50-250/78-25 & #50-251/78-25 on 781016-20, Does not consider any info therein to be proprietary.

  UHRIO-R. E. Florida Power & Light Co. 78/12/06. 1p. 94376:001.
- --7812190238 Forwards 1E Inspec Repts#50-250/78-25 t#50-251/78-25 on 781016-20 during which no items of noncompliance were noted. LCNG.F.J. Region 2. Atlente. Reactor Operations Nuclear Support Branch. 78/11/17 2pp. 94376-002.
- --7812190243 IE Inspec Repts#50-250/78-25 & #50-251/78-25 on 781016-20 during which no itsms of noncompliance were noted Hapor areas inspected inclient oper efter refueling, followups of noncompliance oper items, iE publications, emergency drills. VERDERY, E.H. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/17. 7pp. 94276:004.
- 7812210068 Ack receipt of LE Inspec ReptsM50-250/78-24 & W50-251/78-24.

  Under not consider any info therein to be proprietary.

  UHR10/R.E. Florids Fower & Light Co. 78/12/11. ip. 94269:338.
- --7812210071 Forwards IE Inspec Repts#50-250/78-24 & 50-251/78-24 on 781018-19 during which no items of moncompliance were noted. SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Meterials Befety Branch. 70/11/22. 2pp. 94269:339.
- ---7812210076 IE Inspec Reptemb0-250/78-24 & #50-251/78-24 on 781018-19 during which no items of noncomplience were noted. Hajor areas inspected incl:observation of annual Emergency exercise-licenses fire drill & discussions w/personnel.

  HUFHAM.J. M., OIBBON.G. T. Region 2, Atlenta, Fuel Facility & Materials Safaty Branch. 78/11/22 Spp. 94269:341.
- 7812280328 Ack receipt of 781201 itr informing NRC of steps taken to correct violations noted during inspec#30-250/78-21 & #50-251/78-21.

  SUTHERLAND.J. T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/12/19. 2pp. 94082:155.
- --7812280339 Responds to 781106 NRC itr re violations noted in Inspec Repta#90-250/78-21 & #50-251/78-21. Corrective actions: respiratory protec equip training classes & health physics training classes held. URR14.R.E. Florida Power & Light Co. 78/12/01. 5pp. 94082:157.
- --7812280342 Forwards IE Inspec Repts#50-250/78-21 & #50-251/78-21 on 780911-15 & Notice of Violation. SUTHERLANO, J. T. Region 2. Atiente. Fuel Facility & Naterials Safety Branch. 78/11/06. 2pp. 94082:162.
- --7812280344 Notice of Violation from inspec on 780911-15.
  A Region 2, Atlanta, Office of the Director. 78/11/06. 2pp. 94083-164
- --78:2280348 IE Inspec Repts#50-250/78-21 & #50-251/78-21 on 780911-15 during which 3 Itame of noncompliance were noted: Issuance & use of respirators, preparation of ehipments of radioactive mati not in requirements & feiture to lock high radiat areas CCLLING.D.M., ZAVADOBKI,R.M., GIBSON.A.F. Region 2, Atlanta, Office of the Director. 78/11/03. 13pp. 94082:166.
- 7812290087 Forwards IE Sulletin 78-14.

  O'RELLY, J.P. Region 2: Atlants: Office of the Director. 79/12/19.
  2pp. 03649:338.

- anubbars failed functional tests due to control block poppat valve & rallef valve malfunctions & excessive mein cylinder wast Hydraulic type replaced w/mechanical type anubbara BCHOPPMAN.M.A. Florida Power & Light Co. 78/09/30. ip. 94471: 347
- 7810200093 Forward's LERW78-010/03L-0.

  ECHMIDT,A.D. Florida Power & Light Co. 78/10/11. 1p. 94140:346.
- --7810200096 LERM78-010/03L-O on 780911:Laskage of radioactively contamineted water to paved area outside of pump room for 30 minutes, caused by spent fuel pit cooling pump mech seal failure.

  BCHOPPMAN, M. A. Florida Power & Light Co. 78/10/11. ip. 94140:347.
- 7810200114 Farwards LER#78-012/017-0.

  SCHMIDT.A. D. Floride Pawer & Light Co. 78/10/11. lp. 94401:215.
- --7810200117 LER#78-012/017-0 on 780927: No Adverse affect from substitute of fuel assembly N-07 for an N-04 in core position F-14. Cycle 5 reload Bafety Eval remeins valid. BCHOPPHAN, M. A. Florida Power & Light Co. 78/10/11. 1p. 94401:216.
- 7810230250 Forwards LER#78-011/03L-0. SCHM10T,A.D. Florida Power & Light Co. 78/10/13. 1p. 94052:280.
- --7810230253 LERW78-011/03L-0 on 780920: Preventive maintenance checks of MSIV's solengid valves revealed defective colls. Failure of colls caused by high temp & moisture in area. Preventive maintenance re solenoid colls is planned.

  BCH0PPMAN.M.A. Florida Power & Light Co. 78/10/13. Upp. 94052:281.
- 78:10:60157 Forwards LERW78-013/03L-0.

  8CHM1DT,A.D. Florida Power & Light Co. 78/10/27. 1p. 94489:076.
- --7811060163 LERB78-013/03L-0 on 780929: condensate storage tent held less than 185.000 gailons for about 8 hours. Caused by lests in condenser tubes, necessitating increased steam generator blowdown. Flow demand sicesded output of treatment plant. SCHOPPHAN. M. A. Floride Power & Light Co. 78/10/27. 1p. 94489-077
- 7811080148 Forwards LER#78-014/03L-0.
  8CHMIDT, A. D. Florida Power & Light Co. 78/11/01. 1p. 94399:307.
- --7811080150 LER#78-014/00L-0 on 781002: condensate storage TenkiCST)fell to 192,000 gallons because of water damand increase for steam generator blowdown resulting from cation resin bed ragemeration. CST filled after resin bed regeneration. SCHOPPHAN.M.A. Florida Power & Light Co. 78/10/02, 1p. 94399:308.
- 7812040221 Forwards LERW78-015/01T-0, BCHM1DT.A.D. Florida Power & Light Co. 78/11/RO. 1p.
- --7812040222 LERM78-015/017-0 on 781106: Boron Injection Tank(BIT) semple showed low Boron lavel, Exact cause is unknown but it is suspected the actual BIT concentration was proper & the sample was diluted & invalid.

  8CHOPPHAN.M.A. Florida Power & Light Co. 78/11/20. 3pp. 74452: 309.
- 7812050176 Forwards LERW78-010/03L=1.

  8CHM1DT.A.D. Florida Fower & Light Co. 78/11/27. ip. 94335:134.
- --7812050181 LERM78-010/03L-1 on 780911: Spent fuel pit cooling pumps each seel felied causing 150 gallons of radioactively conteminated water to leak to paved area outside pump room caused by inadequately lubricated pump bearing.

  BCHOPPHAN.M. A. Fiorida Power & Light Co. 78/11/27. 1p. 94395: 135.
- 7812270307 Forwards LERA78-016/03L-0.
  8CHM1DT.A.D. Fiorida Power & Light Co. 78/12/15. 1p. 94230:345.

--7812270312 LER#7B-016/03L-0 on 781115: Crack in 4A charging pump discharge piping drain line developed due to crack in a 1 inch nipple (type 316 stainless steel), which was subsequently replaced SCHOPPMAN. M. A. Florida Power & Light Co. 78/12/15. 2pp. 94200.346.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR
J. Insurance & indemnity information

7812140153 Forwards Amend89 to Indemnity Agreement8E-47. RICHARDS, B. New Mexico, Univ. of. 78/12/06 1p. 94133:344.

--7812140157 Amend#9 to Indemnity Agreement#E-47. Article III. Paragraph 4(b)(2) emended by changing amount to \$140000000 SALTMAN.J. Antitrust & Indemnity Group. 78/12/05. ip. 6432-744

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

78101200B0 Forwards analysis of Elec Ceble Penetration Fira Barrier Test conducted on 780619. Also forwards 3rd party observer rept of tast & 5 detailed drawings associated w/test. NAUGHTON.M.F. Commonwealth Edison Co. 78/09/29. 44p. 94049: 330.

7811020349 Responds to 780929 ltr requesting NRC agreement to respond to requests in case of affeits emergency. Under interagency Agreement DGC Chicago Oper Ofc coordinates requests in area, KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/25. lp. 94241:087.

--7811020375 Requests NRC assistence in event of emergency at subj Pacii. KALIVIANAKIS.N. Cammonwealth Edison Co. 78/09/29. 1p. 94241:088.

7812120175 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Controls & OA" will be submitted 770201.

NAUCHTON, M. F. Commonweelth Edison Co. 78/11/30. 2pp. 94277:099.

#### Q. Adjudicatory correspondence

7811090259 Bd grants request by Citizens for a Batter Environ & Natural Resources Defense Council for permission to file response to answers opposing their petitions to intervene by 781103. MILHOLLIN. Q.L. Atomic Bafety and Licensing Board Penel. 78/11/01. ip. 02761:290.

7812110284 Cencels special prehearing conference scheduled for 781215. Conference shell be held on 790111 in Tax Courtroom of UB Courthouse & Fed Bldg. Chicago. IL. Parties & petitioners must rept to Board by 781215 re progress of negotiations. MILHOLLIN.O.L. Atomic Befety and Licensing Board Panel. 78/12/01. 2pp. 94203:243.

7810190131 Answer by CEIL to Petition to intervena Piled by Atty Cen of IL on 780920. Agrees that Atty Cen has standing-but asserts there are no genuine Issues to be heard at hearing. Requests that Atty Cen request for EIB be denied. SYEPTOE, P. P. Isham, Lincoln & Beale. 78/10/02. 3pp.

7810300063 Natural Resources Defense Council Request for Leave to File a Response. Response is to applicant's contention reconstitutionality of forced disclosure of group's members' names in order to oper w/in stata.
RDIGHAN, A. Z. Natural Resources Defense Council. 78/10/10. 4pp. 94037:177.

7810300324 NRC Staff Answers to Council for Citizens for Setter Environ & Natural Resources Defense Council's Petition for Leave to Intervens. Staff apposes granting petition. w/Cart of Syc.
ODDARD, R. J. Office of the Executive Legal Director. 78/10/10.
3pp. 94253:337.

7810230124 NRC Staff's Response to Petition of TEX-LA Cooperative Inc for Leave to Intervene Staff believes Petition should be granted.
LESSY, R. P. , BLUME, M. B. Office of the Executive Legal Director.
78/10/10. 9pp.

7811010063 Petition for leave to intervene & for hearing filed by citizens for Better Environ & Natural Resources Defense Council Request for leave to file response to answers opposing petition is granted.

MILHOLLIN.O.L. Atomic Befety and Licensing Board Panel. 78/10/13 ip. 94302-360.

78ii150223 "Natural Resources Defense Council Response to Commonwealth Edison's & Staff's Answers to Petition for Leave to Intervene, "Intervener urges Bd to establish a schedule for briefing challenges to contentions.

ROIBMAN.A. 2 Natural Resources Defense Council 78/10/23 16pp 94270: 137.

7811130216 NRC request to file response to NRDC response to Comm Ed & NRC answer to petition for leave to intervene dtd 781023 lf granted-repty will be served by 781103 Cert of Svc encl 9000ARD.R J. Office of the Executive Legal Director. 78/10/26 Zpp. 03554-050.

7811200070 Request by Comm Ed for leave to file a response to NRDC brief which argues that organizations may show standing to perticipate in NRC proceedings merely by alieging that they Pepresent enonymous members. Cert of Svc encl.
BTEPTOE.P. P. Isham, Lincoln & Beale. 78/10/30. 2pp. 94218:348

7811160021 Grants request by licensee CEIL to have until 781107 to respond to 781013 Order of ABLB permitting NRDC & Citizens for a Better Environ to file response to answers opposing their petitions to intervene in proceedings re-subj facils. MILHOLLIN. 0.L. Atomic Sefety and Licensing Board Pamei. 78/11/03 lp. 94317:090.

7811220010 NRC Staff's Response to NRDC's Response to Ansuers to latter's Petition for leave to intervene.NRC asserts that NRDC has not demonstrated its standing to intervene as matter of right. Cert of Svc enci.

40000ARD.R.J. Office of the Executive Legel Director. 78/11/03.

8pp. 94273:334.

7811200003 Special Prehearing Conference in proceedings re subj facils will be held on 781215 in Rock Island, IL.All parties to proc & all petitioners to intervene must attend & should be prepared to discuss all issues.

MILPOLLIN, O. L. Atomic Safety and Licensing Board Panel. 78/11/09.

2pp. 94215:221.

7812/30122 Olives notice that A Bielawaki enters an appearance on behalf of applicant CEIL in proceedings ra subj facils. Cert of Svc anci.

BIELAWSKI, A. P. 1 sham. Lincoin & Deale. 78/11/21. 2pp. 94307:183.

7812270230 Proposed stipulation re NRDC & CGE's representation of Unnamed members in Dresden-Quad Cities transshipment is not acceptable to NRC. NRC position on NRDC's patition to intervene remains as stated in 781103 pleading.

QDDDARD/R.J. Office of the Executive Legal Director. 78/12/06. ip.

781228027; Forwards"Btipulation" of NRDC.CBE & Commonwealth Edison Core identification of members of NRDC & CBE to prove they have interests that may be affected. No agreement w/Rag Staff has been reached.

RDISMAN.A. Z. Natural Resources Defense Council, 78/12/09 lp. 94374:334.

---7812260280 Parties agree that NRDC & CSE have adequately indentified a lest one member whose interest may be adversely affected by the proposed action. Auth to represent these interested members has not been agreed upon.
ROISMAN, A. Z. Natural Resources Defense Council BIEPTOE, P. P. Commonwealth Edison Co. 78/12/11. 3pp. 74374:335.

7812270133 Special Prehearing Conf Scheduled for 790111 is postponed until 790201. Parties & patitions are excused from requirement to rept to 8d by 781215 re negotiations progress.

MILHOLLIN. O. B. Atomic Safety and Licensing Board Panel. 78/12/13. 2pp. 94161:142.

#### H. Gameral correspondence

7812080138 Forwards CEIL request for amend of CL to allow spent fuel transfer & storage between facils. W/o encl.

QODDARD, R. J. Diffice of the Executive Legal Director. 78/11/17. Ip. 74107:356.

### J. Insurance & indemnity information

- 7812190109 Requests refund of %5 per mut in excess indemity few paid for LiceDPR-2, #DPR-19, #DPR-25, #DPR-29, #DPR-30, #DPR-37, #DPR-48.
  PDDLE, R D. Communuseith Edison Co. 78/12/13. ip.
- P. Operating license stage documents & correspondence
- 7812080072 FOIA request for all records incl:quantity of radioactive math disposed of from former Manhatten proj in it incum as Chicago Pileswinz & J.Meth disposed of in it by Lindsay Cos at Morris facil & Dreaden facil.

  HANSELLD. Illinois. State of. 78/11/06. 2pp.
- 7812150278 Classifies lic anend for proposed fuel pool mod as Classes IV & 1 not Classes III & I. Requires addi charge of \$8300 for each of the two applies be peid with 15 days.
  MILLER.W.O. Licenes Fee Management Brench. 78/12/11. 2pp. 94213-339
- 7810110030 Requeste add1 fee of \$2800 ra eppi for amand to Facil Dyer LicWDPR-29 & DPR-30 since review involves Classes I & III. single sefety issue w/total fee of \$4400. MILLER: N.D. License Fee Menegement Brench. 78/10/02. ip. 94063:150.
- 78i0100027 Forwards evaluation of reactor protect sys pur supplies to determine whether undetected failures edversely effect the RPB sys.

  TURBAK.M.S. Commonwealth Edison Co. 78/i0/04. 5pp.
- 7810140112 Resvaluation of Lic amend feas far inter-station spent fuel transfer for out; facils as requested by 780817 ltr shows that the class 1 & 3 fees paid for each station ere correct.

  MILLER.H. D. Licence Fee Management Branch. 78/10/10. 1p. 94421:151
- 7811240237 Forwards LER#78-010/03L-1.
  KALIVIANAKIB.N. Commonweelth Edison Co. 78/10/25. ip. 94458:227.
- 78i1020322 Request to amend Baction 6.6.8.1.0 of Append A to Tech Boocs to facil open lic re-reporting req for reactivity anomelies is w/drewn.ee Rep Quide"Interpretation"sy NRC on 780701 does not req rept for reactivity increese of less than 5 secs.

  REED.C. Commonwealth Edison Co. 78/10/26. 2pp.
- 78i103016i Forwerds proposed Amend chenging Tech Space w/regard to updating station organizational charts Changes have received obsite & offsite approva).
  RESD.C. Commonwestth Edison Co. 78/10/26. 7pp.
- 78ii130035 Bummary of 780914 meeting w/GE representatives & Mark 1 Cunses Group to progress of Long Term Prog w/attendence list & egende(RD-9-A-Mark1. Standarde.) ORIMES.C. Plant Systems Branch (Pro 791030). 78/10/26. 67pp.
- 78ii140t05 Responds to 780516 NRC itr requesting eddl info re reactor vestal metel surveillance specimen fluence valves at time of withdrawal. w/projections besed on dosimetry results of previously tasted capsules & 80% capacity factor; w/o enci. TURBAK.M.B. Commonwealth Edlson Co. 78/11/03. 2pp. 94425:125.
- 7811140002 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plents w/encl Beminar Info Shest(to be completed & returned by 78117) & Proposed Agenda.

  KEPPLER. J. O. Region 3. Chicego. Office of the Director. 78/11/07.
- 7811300058 Forwards Amend#37.#37,#48 & #47 for Lics DPR-19.DPR-25. DPR-19 & DPR-30 respectively Amends revise Tach Specs reoperating temp & pressure limits. Also forwards Safety Eval & Fad Register Notice.

  1PF0\_ITO.T.A. Operating Reactors Brench 3 (Pre 790625). 78/11/13. 3pp.
- ~~7B11300070 Amend#4B to the Operating Lic rev Tech Spece re operating temp & pressure limits. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790523), 78/11/13. Boo.
- --7811300077 Safaty Eval Rept in support of Amend#39.#37.#48 % #47 to Oper Lice DPR-19.DPR-28.DPR-29 & DPR-30, respectively. \* Diffice of Nuclear Reactor Regulation, Director. 78/11/13. 4pp.

- --7811300085 Notice of Issuence of Amend#39.#37.#48 & #47 to Oper Lics DPR-19, DPR-25, DPR-27 & DPR-30, respectively. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/13. Epp.
- 7812180044 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out math. W/ancl Registration Form & List of Locations. MILLER-J.R. Assistant Director for Site & Bafaguards (Pre 791030), 78/11/13. Spp. 94133:049.
- 7812180266 Forwards Revmi "Draft Radiological Effluent Tech Speca" for SWR's (NAREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREQ-0133). GRIMES-B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94365:349.
- 7812080107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev 6." Rev reflecta Reg Quidel. 28 & 1.33 rev. TURBAK: M. B. Commonwealth Edison Co. 78/11/17. 2pp.
- 7811270170 Lic#DPR-29 Appl for amended Tech Specs to support cora reload#4. M/enci plant analysis on suppl reload lic submittel:Barrier Leed Test Assemblies. & LOCA Analysis Rept for Dresden Units 28:3 & Quad Cities Units 182.
  REED.C. Commonwealth Edison Co. 78/11/20. 109pp. 94199:001.
- 78i12B0213 Forwards current lic status list for subj facils. REED.C. Commonwealth Edison Co. 78/11/20. 9pp.
- 7811280246 Forwards "Projected Fluence Values at Withdrawal for the Capsules Designated to Meet the Requirements of 10CFR50 Append H. " Table 1 to be attached to 781103 ltr to Ippolito. TURBAK.M. 8. Commonwealth Edison Co. 78/11/20. 2pp. 94012:162.
- 7812060166 Informs NRC that response to 781115 NRC itr re lic emend appl & ownership for subj facil will be made by Commonwealth Edison.
  MILLER.R.B. lowe-lllinois Gee & Electric. 78/11/24. 1p. 94371:260.
- 7812110001 Discusses possible dangers of LOCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.W/ancl ANO: W7812080207. IPPOLITO.T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Spp. 94339:089.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held % providing task-by-task activity summary for the month. 8080N.L.J. Gameral Electric Co. 78/12/04. 11pp.
- 78:2080149 Requests add1 info within 60 days re 76:1106 & 780921 submittals on instru estpoints.

  1PPCLITO.T.A. Operating Reactors Branch 3 (Prs 790625). 78/12/05.
  3pp. 94:104:38:
- 7819280129 Emphasizes importance of submitting accurate & complete info to NRC by liceneess & applicants. Info submitted must be substantiated by deta & calculations. Liceness must notify NRC of any inaccurecies or anforcement action will result. DAVIS, J. Q. Office of Inspection & Enforcement. Office of the Director. 78/12/06. App.
- 7812190097 Accepts topical rept@CE-1-A Rev@d. "Comm Edison Co Quality Assurance Prog for Nuc Generating Stations." Requeste submittel of 36 copies.

  HAABB.M.P. Quelity Assurance Branch. 78/12/13. 1p.
- 7812270225 Provides addi Info re gaseous releases described in 781030 ltr.Cause of increase in off-gas activity is believed to be fuel leakers & corrective action for high gaseous activity is to maintain manimum leakage by close surveillance.

  KALIVIANAKIS.N. Commonwealth Edison Co. 78/12/13. 2pp. 94017:139.
- 7812200219 Forwards add1 info re core loading pattern for reload#4. Indicating that reactor abutdown margin, loading error, & rod withdrawal were recalculated.
  TURBAK-M. S. Commonwealth Edison Co. 78/12/15. 9pp. 94162:293.
- 78:1210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program.
  8D8CN.L.J. General Electric Co. 78/11/13. 3pp.

## repection reports, iE Bullstins & correspondence

Di0067 Forwards IE inspec Repts #50-254/78-19 & #50-265/78-20 on D713-14.780719-20.780726-27.780802-03. & 780810-11.during ich no items of noncomplaince were noted. DRELLI.0. Region 3. Chicago, Reactor Operations Nuclear Support ench. 78/09/19. 2pp. 94290:103.

11010076 IE Inspec Repts#50-254/78-19 & #50-265/78-20 on 780713-14 780719-20, 780725-27, 780802-03, & 780810-11, during which no these of noncompliance were noted. Major erest inspected included: plant open & out-of-sec activities.

JACKIM, 1, N., KNOP, R. C. Region 3, Chicago, Office of the Director. 7809719, 6pp. 94290:105.

D80077 Forwards IE Inspec Repts#50-254/78-20 & #50-265/78-21 on D802-25, 29.0901 during which no items of noncompliance re-noted.

VIS.A.B. Region 3. Chicago. Fuel Facility & Materials Bafety anch. 78/10/02. 2pp. 94271:124.

ii080080 lE inspec Repte#50-254/78-20 & #50-265/78-21 on 780822-23. 27.0701 during which no items of noncompliance were noted. Hajor ereas inspected included: radioactive weste sys. effiuent releases & effiuent control instru. HETER, L. U. FIBHER, W. L. Region D. Chicago, Fuel Facility & Hateriel's Safety Brench. 78/10/02 ilpp.

110293 Ack receipt of 780901 itr informing NRC of steps taken to frect violations noted in 780810 NRC itr.
PPLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/03.
p. 03356:074.

0-60120 Presents control rod drive return nozzle & feedweter nozzle spec grogs to be implemented during next refueling outage, wacheduled for Jen 1979. Justification for progs is ovided & also plan for mod of feedweter nozzles. RBAK.M. 8. Commonwealth Edison Co. 78/10/27. App.

070002 Ack receipt of 781006 itr informing NRC of steps taken to rect violations noted in 780920 Notice of Violation. ND.J.A. Region 3. Chicago, Bafeguards Brench. 78/10/27. ip. 037:072.

05001: Forwards IE Inspec Repts#50-010/78-29,50-237,-254,-295,-304/-25,50-249/78-27 & 50-249/78-26 on 781002 during which no +Ms on noncompliance were noted.

PPLER. J. Q. Region 3, Chicago, Office of the Director, 78/10/30.

040033 Forwards 1E Inspec Repts#50-284/7B-21 & #50-265/78-22 on OBQ1-25, 780831, 780901, 780906-07, 780913-14, 781003-04 & tice of Deviation.

GRELLI-0. Region 3, Chicago, Reactor Operations Nuclear Support anch. 78/10/31. 2pp. 94129:092.

11204003B Notice of Deviation from Inspec on 780821-25. 4 Region 3, Chicago, Office of the Director. 78/10/31. ip. 74127:074.

112040046 1E Inspac Repts#50-2543/78-21 & #50-265/78-22 on 780821-25 during which I item of deviation was noted: excessive amounts of oil stored near vital cabling, smoking in No Emoking Area, JACKIH, I.N., BROWN, C.H., KNDP, R.C. Region 3, Chicago, Office of the Director, 78/10/30, 6pp.

:060225 Forwards IE Inspec Repts#50-254/78-24 & 50-265/78-23 on 11004-05 during which no items of noncompliance were ited.
IERANN.R.F. Region 3. Chicago. Reactor Construction & Engineering pport Branch. 78/10/31. 2pp. 94382:174.

H2060230 IE Inspec Repts#50-254/78-24 & #50-265/78-25 on 781004-06 during which no items of noncompliance were noted Major areas inspectsd incl: iE Bulletins & Circular followup relative to quel of elec equip.

HWOHES-J., SPESBARD.R.L. Region 3, Chicago, Office of the Director, 78/10/31. 6pp. 94382:176.

150063 Forwards IE Circular 78-18. FPLER, J. C. Region 3, Chicago, Office of the Director. 78/11/06.

RO40020 Responds to 7B1031 NRC ltr re violations noted in Inspec pss850-254/7B-21 k 850-265/7B-32. Corrective actions:areas 7812050287 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl AND: 7811300055 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 78/11/24. ip.

7812260292 Ack receipt of 781120 ltr informing NRC of steps taken to correct violations noted in 781031 NRC ltr FIDRELLI.O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/12/14. ip. 94160:043.

7812290026 Forwards IE Bulletin 78-14.
KEFPLER.J. O. Region 3. Chicago, Office of the Director 78/12/19.

### R. Periodic operating reports & related correspondence

7810250111 Monthly performance rept for Bept 1978. Includes maint summary, everage daily unit pur level, refueling info request & LEP's.

• Commonwealth Edison Co. • Iowa-Illinois Gas & Electric.
78/09/30. 25pp. 94368.332.

7811220031 Forwards Monthly Operating Rept for Oct 1979
KALIVIANAKIS, N. Commonwealth Edison Co. 78/11/09 lp. 94309:010.

--7811220033 Monthly Operating Rept for Oct 1978.
# Commonwealth Edison Co. 78/10/30. 30pp. 94309:011.

7812200235 Forwards Monthly Oper Rept for Aug. Sept. Oct 1978, correcting mistakes made in Aug & Sept Average Daily Unit Pur Level Rept & in the Sept & Oct Operating Data Repts.
KALIVIANAKIB.N. Commonwealth Edison Co. 78/11/28. ip 94162:325

--7812200241 Monthly Oper Rept for Aug. Sept.Oct 1978. Corrections are circled in red. HANNUM.D. Commonweelth Edison Co. 78/11/08. 4pp. 94162: 326.

7812200188 Monthly Oper Rept For Nov 1979.

# lowe-1111nois Ope & Electric. 78/11/30. 26pp. 94145:314.

#### B. Reportable occurrences. LERs & related correspondence

7810170232 Forwards LERW78-027/03L-0.
KAL1VIANAKI8.N. Commonwealth Edison Co. 78/10/05. 1p. 94236:312.

---7B10170235 LERW78-027/03L-0 on 780928: Unit One dissel fuel transfer lines 1-3201 & 1-3204 were taken out of svc at 4:55a m. 780928 to replace 2 sections of piping. Bys returned to svc same day.

VAIRENMALD.J. Commonwealth Edison Co. 78/10/05. 2pp. 94236:313.

7811240175 Forwards LERW78-026/03L-0.
KALIYIANAKIB.N. Commonwealth Edison Co. 78/10/19. ip. 94438:268.

--7811240177 LER#78-026/03L-0 on 780920: "A" RHR room watertight door found open. Caused by contractor personnel ignorance. Personnel admonished to heed procedures et all these. KCOI-M. Commonweelth Edison Co. 78/10/19. 2pp. 94458:269.

7811240240 LER#78-010/03L-1 on 780420: during routine Hydreulic Shubber Surveillance Inspec, Shubber Mark 149 was found inoper due to empty fluid reservior & Mark 144 was found w/missing cotter plin.dus to component failure.

VAHRENHALD, J. Commonwealth Edison Co. 78/10/25. 3pp. 94458.228.

7811240179 Forwards LERW78-028/03L-0.
KALIVIANAKIS.N. Commonwealth Edison Co. 78/10/27. 1p. 94458:275.

--7811240191 LERA78-028/03L-0 on 780929: the A SJAE off gas log radiat monitor failed downscale. Caused by component failure: the A radiat monitor high votage pur supply capacitors were not in proper contect w/monitor chassis.

MRRAY/R. Commonwealth Edison Co. 78/10/17. 2pp. 94458: 276.

781107011B Notifies NRC that average release rate for radioactive matls w/half-lives greater than B days between 780701 & 780930 was 2.03 times Tech Spec 3.8.B.3.Cl)design objective. Eval of elevated main chimney release rate has started.

KALIVIANAKIS.N. Commonweith Edison Co. 78/10/30 2pp. 94043:319.

7812110191 Forwards LERE78-029/03L-0.

- --7812110183 LERM78-029/03L-0 on 781025 anote detectors were removed from evc in cable spreading room, elect equip room & control room for installation of new fire detection/suppression sys.

  REED.M. Commonwealth Edison Co. 78/11/15. 1p 94337:105.
- 7812110176 Forwards LER#78-030/03L-0.
  KALIVIANAKIS.N. Commonwealth Edison Co. 78/11/21. ip. 94337:096.
- --78121i017B LER#78-030/03L-O on 781026: dual position indication was received for supression chamber to drywell vectoum breaker, valvemi-1601-33E. Caused by position indication problem. CLARM.D. Commonwealth Edison Co. 78/11/20. 1p. 94337:097.
- DOCKET 50-255 PALISADES NUCLEAR PLANT
- F. Security, medical, emergency & fire protection plans
- 7812130161 Forwards rev security plans for subj facils as requested by NRC.Pians withheld (ref 10CFR2.790).
  HOFFMAN.D.P. Consumers Power Co. 78/12/08. ip. 94305: 120.
- K. Utility Final Safety Analysis Report (FSAR) & smends
- 7812270146 Forwards rev page 8-18 of Section8 of subj facil FBAR. Change consists of changing a-c sys supply from motor control centers it 2 to Motor Control Centers it 3 & having only 1 MCC automatically supplied by emergency generator. FGOO.N.O. Consumers FOURPER STIZZEL 2pp. 94139:148.
- P. Operating license stage documents & correspondence
- 7810110030 Requests add1 fee of \$2800 re appl for ement to Facil Oper LiceDPR-29 & DPR-30 since review involves Classes I k III, single safety issue w/total fee of \$4400. MILUER.W. O. License Fee Management Branch. 78/10/02. 1p. 94063:130
- 7812110011 Discusses possible dangers of LOCA in conteinment purging during normal pient oper Requests either commitment to limit purping or justification for continuing Wienci ANG: 47812080207.
  ZIEMANN.D. C. Operating Reactors Brench 2 (Pre 790625). 78/11/29. 8pp. 94339:297.
- 7810110111 Clarifies interpretation of Tech Spec 3.1, is etating that one primary coolant pump shall be in oper whenever a reduction in primary coolant sys boron concentration is being made.

  HOFFMAN, D. P. Consumers Power Co. 78/10/04, ip. 94066:357.
- 781019021B Forwards electric diagrams umitted from 780808 package. Sat of apertura cerds advanced directly to 8 811ver. HOFFMAND, P. Consumers Power Co. 78/10/10, 1p. 94415:191.
- 7810310027 informs that for BEP normal channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil etaff & members of BEP brench is encouraged.

  ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625), 78/10/10.
  ZPp. 94094:347.
- 7810160097 Informs of delay in providing NRC w/info re snviron qualification of sefety-releted equip due to slow review of tables presented.

  BiXEL.D.A Consumers Power Co. 78/10/11. 1p. 94004:221.
- 7810270278 Forwards Amend #44 to Provisional Operating Lic #DPR-20.
  Amend auth delation of requirement to perform weekly
  monitoring of fish impingment on intake traveling screene.
  ZIEFANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/16.
  3pp. 94030:287.
- --7810270285 Amend #44 to Provisional Lic #DPR-20, deleting requirement to perform weakly monitoring of fish impingement on intake traveling screens.

  ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790525). 78/10/16.
  4pp. 94030; 290.
- --7810270293 Notice of leauence of Amend #44 to Provisional Oper Lic #DPR-20, such deletion of requirement to perform weekly monitoring of fish impingement on inteks traveling screens ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/16. 28p. 94030:294.
- 7810270075 Responds to 780817 NRC ltr requesting review of initial evel

- 78ili30047 Requests add1 info re EEF switchover from injection to recirculation mode.isolation of reactor safety protec sys from non-sefety sys & engr safety features.(E8F) sys logic & design.
  ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.3pp. 94010:231.
- 78ii130i67 Notifies applicant of 78ii28 NRC-sponsored seminar re Model Radiological Effluent Tech Spece for Nuc Pur Plants. Encl w/Beminar Info Sheetito be completed & returned by 78ii17) & Froposed Agenda.

  KEPPLER, J. O. Ragion 3, Chicago, Office of the Director. 78/11/07.

  6pp. 03353:215.
- 7812180035 Notice of workshops re implementation of training & qual requirements contained in Append 8 of IOCFR73. Requests pre-workshop registration of attendees to facilitate sending out meth. W/encl Registration Form & List of Locations. HILLER.J.R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. 5pp. 94133:024.
- 7812190017 Forwards Rav#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Pur Plents" (NUREG-0133). GRIMES,D.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:292.
- 78:20:60303 Notification of 78:207 meeting w/BEP Owner's Group in Bathasda, MD to discuss piens to address saismic input for use in BEP saismic review.
  LEVIN.H.A. Bystematic Evaluation Programs Branch (Pre 790625).
  78/11/24. 2pp.
- 7812040164 Forwards 781026 Notice of Noncompliance & Order to comply from HI Water Resources Comm. & 781116 utll reply. Effluent in violation: oil & greece.
  HOFFNAN, D. P. Consumers Power Co. 78/11/27. 5pp. 94456: 164.
- 7812030119 Forwards completed tabulation of environ qual of safetyrelated elec equip requested by NRC on 780906. Btates that equip addressed must ensure safe shutdown of plant during LOCA & main steam line breek. HOFFNAN.D.P. Consumers Power Cq. 78/11/30. 37pp. 94333:291.
- 7812120100 Presents justification for installation & use of high density spent fuel storage racks. Includes responses to 780613 NRC request for addl info. Concludes that tauts demonstrate structure adequacy of 84C matt.

  HDFFMAN.D.P. Consumers Power Co. 78/12/04. 19pp. 94275:00t.
- 7812140343 Determines that 781002 emergency pur sys mods will req steff review & approval. Since review involves a single safety issue it is subj to a 44,000 Class III fee.
  MILLER, W. O. License Fee Management Branch. 78/12/04. 1p. 03557: 147.
- 76:2280:18 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J.Q. Office of inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 943:0:213.
- 7812120182 Informs NRC of filter testing condition in respiratory protec equip which is different from regulation in Reg Guide 8.15. but which meets the regulatory requirements.

  BIXEL-D.A. Consumers Power Co. 78/12/0B. ip. 94277:082.
- 7812150085 Requests add1 info from SEP licensess re electrical panetrations of reactor containments to complete evaluation. ZIEMANN,D.L. Operating Reactors Brench R (Pre 790625). 78/12/08. 4pp. 9421:339.
- 7812030013 Requests views of Regional Directors on Licenses performance aval of subj facils. Forwards questions to be enswered by 771209.

  THORNBURG. H. Division of Reactor Construction Inspection. 77/11/23.
- 7819270147 Requests info re positive displacement charging nump vibration levels & discharge pressure pulsations to complete review.

  21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/14.

  3pp. 94018:053.

- tee. Changes involve nuc eteam supply eye & fuel assembly leasing. IDFFMAN.D.P. Consumers Power Co. 78/12/18. 33pp. 94160:140.
- (2270174 Clarifies Tech Spec 3.1.1a re boron dilution in order to take it consistent w/subj Fecil Standard Tech Specs. (DFFMAN.D.P. Consumers Power Co. 78/12/21. 1p. 94018:095.
- IRRO134 Responde to 781208 request for add1 info re 8EP Topic VIII-4 'Electrical Penetrations of Reactor Containments." Requires tabulation of info selected by NRC in docket search by early Jan to prepare reply within echedule.

  31XE.,D.A. Concusers Power Co. 78/12/22. ip. 94310:339.
- Inspection reports. IE Bulletine & correspondence
- 12120212 Forwards IE Inspec Rept#50-255/78-05 on 780111-13,18-20, 24-27,31 & 780201-03,16-17 during which 5 items of uncompilance were noted. Inspec Rept withheld [ref 10CFR2, 790).

  \*\*EPPLER.J.O. Region 3. Chicago, Office of the Director. 78/04/27.

  \*\*Jpp. 94276:067.
- LW040172 Ack receipt of 780512 ltr informing NRC of etape taken to correct violetions noted during inepec#50-255/78-05. KEPPLER.J. Q. Region 3. Chicago, Office of the Director. 78/06/12. 3pp. 94456: 228.
- 7812040174 Responds to 780421 NRC ltr & submits attachment w/ request that it be withheld pursuent to 2.790. YOUNDOMHLR.C. Consumers Power Co. 78/05/12. ip. 94456:230.
- 7812040178 Responds to 780421 NRC ltr re violations noted in Inspec Repte30-235/78-03. Attachment withheld from pub disclosure pursuant to 2.790. BIXELD.A. Consumers Pawer Co. 78/05/12. ip. 94436:231.
- 11300314 Forwards IE Inspec Rept#50-255/78-17 on 780724-28,780730,780801-03 & 780814-18 during which no items of noncompliance were noted to the state of the sta
- 78i1300318 IE Inspec Rept #50-255/78-17 on 780724-28,780730,780801-03 & 780814-18 during which no itmee of noncompilance were noted. Hajor areas inspected incl:open.reportable events.records.review & audit procedures & safety injection sys open. HANTEN.D.R. JORGENBEN.B.L. Region 3. Chicago. Office of the Director. 78/09/29. 17pp. 94i37:001.
- II 0110186 Ack receipt of 780908 ltr informing NRC of steps teken to correct violations noted in 780818 NRC ltr.
  HIND. J.A. Region 3. Chicago, Sefeguards Branch. 78/10/02. ip. 94069:130.
- Nation 130195 Ack receipt of 780905 ltr in response to Inspec Rept#50-955/76-16. Clerifies NRC position on 5 items of noncomplience objected to by licensee. Also requests that mgt control of radiat sefaty prop be addressed by future response.

  KEPPLERIJ. O. Region 3. Chicago. Office of the Director. 78/10/05.

  4pp. 94003:130.
- \$11090298 Forwards IE Inegec Repte#50-255/78-20 on 780828-31 & 780907-08 during which no items of noncompliance were noted. DAVIB.4.8. Region 3. Chicago. Fuel Ferility & Materials Safety Branch. 78/10/05. 2pp. 02762:345.
- -7811090303 1E Inepec Rept#50-255/78-20 on 780828-31 % 780907-08 during which no items of noncomplience were noted Major eress inspected incliffergency Plan procedure, examination of facil & samples, OREER, J. Region 3, Chicago, Office of the Director, 78/10/05, 8pp. 02762; 347.
- 911300225 Forwards IE Inspec Rept#50-255/78-05 during Jan-Feb 1978 & Notice of Violation. W/encl ANG#7811300177.

  KEPPLER, J. G. Region 3. Chicego. Office of the Director. 78/10/06.
  2pp. 94027:124.
- 810230334 Forwards IE Circular#78-17. (8ae AND: 7810930921, Docket 50-313,781013)

  KEPPLERJ, J. Region 3. Chicago, Office of the Director, 78/10/13, 1p. 94194:305.

- Qan Office Health Physics group in procedure dev & training. ALARA review group. HDFFMAN.D.P. Consumers Power Co. 78/10/27 2pp. 94218.355.
- 7811300349 Forwards IE Inspec Rept#50-255/78-22 on 780925 & Notice of Violation. FIORELIJ O Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94116:219
- --7811300330 Notice of Violation from inspec on 780925-29.

  \* Region 3, Chicago, Office of the Director. 78/10/27. ip.
- --7811300354 IE Inspec Rept#30-253/78-22 on 780925-29 during which i ite of moncomplience was noted: Peilure to complete appropriete admin review, Noncomplience w/Tech Specs 6 8.1.
  HUNTER, D. R. . JORGENBEN, D. L. Region 3. Chicago, Office of the Director. 78/10/26. Spp. 94116: 222.
- 7812010124 Forwards IE Inspec Rept#50-255/78-23 on 781002-06 & Natice of Violation. FiDRELLI.9. Region 3. Chicago. Reactor Sperations Nuclear Support Branch. 78/10/27. 2pp. 94418-048.
- --7812010126 Notice of Violetion from inepec on 781002-06. \* Region 3. Chicago. Défice of the Director. 78/10/27 ip. 74410:050.
- --7812010129 IE Inspec Rept#30-255/78-23 on 781002-06 during which 2 items of noncomilance were noted: failure to follow procedures & failure to implement an acceptable inevotesting prog for pumps.

  REYES.L.A., BIREETER-J.F. Repion 3. Chicego, Defice of the Director. 78/10/27. Spp. 94418:031
- 7811150051 Forwards IE Circular 78-19.
  KEPPLER, J. G. Region 3. Chicago, Dffice of the Director. 78/11/06
  1p. 94112 163.
- 7811210437 Ack receipt of 781027 itr responding to item of concern in 781005 itr Will exemine action during future inspec.

  KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/11/14 ip. 03558:362.
- 7B12060022 Notifies that installation of evacuation sirens in new evobldg addition per IE Inspect50-255/78-20 req more work than anticipated & will be completed by 79015 HOFFMAN,D.P. Consumers Power Co. 7B/11/14. ip. 94415:335.
- 7819200299 Forwards 1E Inapac Rept#50-255/78-21 on 780921-22 & 0926-29 & Notice of Violation. DAVIB.A.B. Region 3. Chicago. Fuel Facility & Materials Bafety Brench. 78/11/15. Spp. 94206:307.
- --7812200302 IE Inspec Rept#80-253/78-21 on 780921-22 during which 2 items of noncomplience were noted: Pailure of effluent control instrumentation & reported oversiposure of amployme, HUETER, L. J., FIBHER, M.L. Region 3, Chicago, Office of the Director, 78/11/14. iipp. 94206:310.
- 7812060024 Responde to 781027 NRC ltr re violetion noted in Inspec Rept#50-2557/8-22. Check w/personnel showed meint activity had been correctly done. Admin procedures will be rev. HOFFHAN.D.P. Consumers Power Co. 78/11/16. 2pp. 94415:337.
- 7812060361 Responds to 780521 NRC 1tr re violetions noted in inspec ReptM50-235/78-23 Corrective actions: flow trensmitter repeired & recalibrated tagging proc rev to repair Instruprior to testing.
  HDFFHAN.D.P. Consumera Power Co. 78/11/16. 3pp. 94382:317.
- 7811300114 Forwards IE Inspec Rept#50-255/78-05 on 780111-13, 18-20, 24-27, 780131-780203 & 780216-17.
  KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/20. 1p. 94078; 324.
- --7811300117 IE Inspec Rept#50-255/78-05 on 780111-13,780118-20,780124-27.780131-780203 & 780216-17 during which 5 items of noncampliance were nuted; physical security organization, access requirements, access controls & testing & maint, CARLBON, D. M., MADEDA, T. J., NDRELIUB, C.E. Region 3, Chicago, Office of the Director. 78/11/20, 17pp. 74072:325.

- 7812290059 Forwards IE Inspec Rept #50-255/78-24 on 781016-18 during which no items of moncompliance were noted DAVIB.A B Region 3. Chicepo. Fuel Facility & Materials Safety Branch. 78/11/21 2pp. 94190.033
- 7812290063 IE Inspec Rept #30-255/78-24 on 781016-18 during which no item of noncompliance were noted Major areas inspected incl confirmatory measurements prog. OREER R. J. JANUSKA. A. G. ESSIO. T. H. Region D. Chicago, Fuel Facility & Materials Safety Branch 78/11/21 3pp 94190:035
- 7812050314 Forwards 1E Builetin#78-12A.suppl to IE Builetin 78-12 H/enc1 AND.7811300055 KEPPLER.J O Region 3, Chicago. Office of the Director. 78/11/24. 1p 94393 195
- 7812290017 Forwards 1E Inspec Rept#50-255/78-26 on 781024-25 & Notice of Vigistion FioRELI.0. Region 3. Chicago: Reactor Operations Nuclear Support Branch. 78/11/24 2pp. 94207.341
- --7812270020 Natice of Violation from inegec on 781024-25.

  a Region 3 Chicago, Office of the Director. 78/11/24. Ip 9207 143
- --7812290025 IE Inspec Rapt#50-255/78-26 on 781024-29 during which 1 Item of noncompliance was noted: fallure to adhere to procedurae for training & documentation LITTLE.M.S., SMANSON.E.R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/11/20 4pp 94207.344
- 7812150202 Notification of meeting w/CPC on 781220 in Jackson M1 to discuse recent inspec conducted by Performence Appraise1 Team at Corp Office & noc plant.
  KEPPLENJ G Region 3, Chicago, Office of the Director. 78/12/07.
- 7812260293 Ack recaipt of 781116 itr informing NRC of steps taken to correct violations noted in 781027 NRC itr.
  F10RELL1.Q Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/12/14 ip 94160.048.
- 7812260314 Ack receipt of 781114 ltr re 2 month delay in instellation of evacuation sirens in the new svc bldg.Compliance u/this commitment will be reviewed during future inspec DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Befaty Branch. 78/12/14 ip. 94160.097
- 7812280059 Forwards IE Bulistin 78-14 KEPPLER.J O Region 3. Chicago. Office of the Director 78/12/19. 1P. 03554 348
- R. Periodic operating reports & related correspondence
- 7810110119 Forwards Monthly Open Rept for Sept 1978
  ADAMS.W E Consumers Power Co 78/10/04, 1p 94067.336.
- --7810110122 Monthly Oper Rept for Sept 1978.
  BCLLNOW, D 1. Consumers Power Co 78/10/04, 4pp. 94067: 337
- 7810190233 Forwards annual NPDES compilance eval inspec rept 6td 780912 HDFFMAN.D.P. Consumers Power Co. 78/10/04. ip. 94168:173.
- --7810190237 Forwards compliance eval rapt conducted 780817. Found subj facil to be in compliance u/conditions of NPDE9 Parmit M1 0001457. PRZYBYBZ.R. Michigan, State of. 78/09/12. lp. 94414:215
- --7810190240 Annual NPDEB compilance evaluation inep rapt Facil found to be in compilance PRZYBYSZ:R Michigan, State of. 78/08/23, 9pp. 94168:175.
- 7810130137 Furnishes long term cooling equip mod & blmonthly status rept. HOFFMAN, D. P. Consumers Power Co. 78/10/10. 1p. 94003:168
- 7811140147 Forwards Monthly Oper Rept for Oct 1978, ADAMS. H. E. Consumers Power Co. 78/11/08. 1p. 94383:269.
- --7811140148 Monthly Oper Rept for Oct 1978.
  BOLLNOW, D. I. Consumers Power Co. 78/11/03. 4pp. 94383: 270.
- 7811200112 Long Term Equip Mod Bimonthly Status Rept for Sept-Oct 1978. W/encl. MJFFMAN.D.P. Consumers Power Co. 78/11/15. ip. 94220:230.

- 7812110122 Forwards Mantly Oper Rept for Nov 1978 ADAMS, H E Consumers Power Co. 78/12/04 1p 94339 313
- --7812110125 Monthly Oper Rept for Nov 1978 BOLLNOH, D. I. Consumers Power Co. 78/12/04 4pp. 94339 314
- 8 Reportable occurrences. LERs & related correspondence
- 7810170244 Forwards LER#77-045/01X-2 HOFFMAN,D P. Consumers Power Co 78/09/29 1p 94236 329.
- --7810170248 LERM77-045/01x-2 on 780916 initial value design did not consider failure of T-ring air supplies, which could result in loss of containment intagrity. Backup air supplies were installed & retested Aug '78 & are now acceptable a Consumers Power Co. 78/09/29. 1p. 94236:330.
- 7810100015 Forwards LERM78-031/01T-0 HOFFMAN.D P Consumers Power Co. 78/10/02 1p 94415 171.
- --7810100019 LERM78-031/01T-0 on 780917 During routine plant oper CRDMcould not be withdrawn in order to prevent rod miselignment rod insertion was blocked by removing CRDM control fuses Caused by shorting of motor windings from water a Cansumers Power Co. 78/10/02 ip.
- 7811210333 Confirms reportable occurrence. Chamletry samples taken from safaty injection tanks 0 & D on 781013 & 781019 respectively showed boron concentration of each tank to be below Tech Bpac limits
  LEMIS.J.O., PETITJEAN.H R. Consumers Power Co. 78/10/23 1p 94494:364
- 7811210418 Reportable Occurrence: on 781025-26, during Tech Spec Test, snubbers 5 & 28 of Tech Spec Table 3.20.1 were found inoper. LEWIR, J. Q., PETITJEAN, H. R. Consumers Power Co. 78/10/27 1p. 94482: 150.
- 7811070210 Forwards LERN78-032/01T-0. HOFFMAN, D.P. Consumers Power Co. 78/11/02. tp. 94039.112
- ~-7811070218 LERW78-032/017-0 on 781019 during monthly sampling of 81 tanks the boron concentrations in tanks 0 & D were 1703 & 1655 ppm, respectively. Caused by divition of 81 tank contents from water left in shutdown cooling lines after shutdown \* Consumers Power Co. 78/11/02 1p. 94039 113
- 7811070183 Forwards LERN78-033/017-0.
  HDFFMAN, D. P. Consumars Power Co. 78/11/03 lp. 94044.183.
- --7811070206 LERR78-033/01T-0 on 781025: laskage of waste gas decay tank T-698.w/xa-133 tha pradominant nuclida thru leaking tank relief valva from elevated pressura. Caused by faulty pressure instru.

  \*\* Consumers Power Co. 78/11/03 1p. 94044:186
- 7811140223 Forward# LERM78-034/01T-0 HDFFMAN.D.P Consumers Power Co. 78/11/09. 1p. 94400.057.
- --7811140228 LERM7B-034/01T-0 on 781026 during surveillance of safetyrelated shock suppressors enubbers 83 & 828 found inoper. Caused by oil leakage past failed O-ring in both enubbers. O-ring failure dus to aga & high temp conditions. a Consumers Power Co. 78/11/09. ip. 94400:038.
- 7811210330 Forwards LERW78-035/03L-0 t #78-036/03L-0. HOFFMAN,D P. Consumers Power Co. 78/11/16 1p. 94404.316.
- --7811210335 LERM78-035/03L-0 on 781020: channel D pressure instrupt-0102D found to be out of calibr Caused by zero shift. Calibr frequency changed from annually to sani-annually. 
   Consumers Power Co. 78/11/16 ip. 94489: 311.
- ~-7811210337 LERM78-036/03L-0 on 781021; during monthly surveillance, how station found to have 50 foot hose rather than req 75 foot hose. Hose normally stored in that station had apparently been replaced.

  4 Consumers Power Co. 78/11/16. 1p. 94489:312.
  - " Collegia Fower Co. 70711710. 19 34401 312.
- 7812050167 Forwards LER#78-037/03L-0. HUFFMAN, D. P. Consumers Power Co. 78/11/30. 1p. 94335:118.
- --7812050175 LERH7B-037/03L-0 on 7B1031: during open deisal generator#iwas taken out of svc for repair of pre-lube oil pump, during which time charging pump P-55c was also taken out of svc. due to leaking seals. Event is under raviaw. # Consumers Power Co. 78/11/30 Lp. 94335:119.

7812110205 Forwards LERR78-038/03L-0 HOFFMAN, D.P. Consumers Power Co. 78/12/05 1p. 94337:331

--7812110210 LER#78-038/03L-0 on 781106 during constructivities.2 electrostron fire barriers opened to permit cable routing w/o fire tour being established Caused by failure of contractor pareonnel to comply w/plant procedures

\* Consumers Power Co 78/12/06 ip. 94337 332

J012120095 Forwards LER 78-039/03L-0 HOFFMAN, D. P. Consumers Power Co. 78/12/07 ip. 94274.225.

--7812120097 LER 78-039/03L-0 on 781110 during normal aperation steam presenter pH & conductivity exceeded Tech Spec steady-state limits Caused by inadvertent addition of morpholine to condensete sys thru leaking drain valve.

• Consumers Power Co. 78/12/07. pg. 94274:226

781215026] Forwards LERM78-040/01T-0 HOFFMAN, D. P. Consumers Pawer Co. 78/12/12 1p. 74213 057.

--7812:30265 [.ERW78-040/01T-0 on 78112B volume control tank venting to leaking waste gas surge tank resulted in gaseous release Cause under investigation.

\* Consumers Power Co. 78/12/12 pp. 94213.058.

7812220106 Forwards LERW78-037/03X-1 HDFFMAN.D.P. Consumer4 Power Co. 78/12/14. 1p. 94343 350

--7812220107 LER#78-037/03X-1 on 781031: with diesel generator#1-2 out of syc.pur supply for elternate changing pumps was shifted to D/O 1-1 before charging pump P-55c was removed from syc. Caused by personnel error.

\* Consumers Power Co. 78/12/14. 1p. 94343: 359.

7612210230 Forwards LERW78-040/01X-1. KOFFMAN, D. P. Consumers Power Co. 78/12/18 1p. 94279.161.

--7812210232 LER#78-040/01X-1 on 781128:during venting of control tank.

leakage from surge tank resulted in gaseous release w/out 15
day holdup time required by Tech Spece Cause is still under

etem:updated rept will be submitted by 790103

Consumers Pawer Co 78/12/18 ip. 94279:162.

7812290202 Forwards LERM78-041/01T-01.
HDFFMAN.D P Consumers Power Co. 78/12/26 1p 94190.338.

--7812270207 LER W78-041/017-01 on 781214: insufficient HP91 flow would reach core during postulated LOCA due to redundant HP91 header being valved out of svc because of HP91 pump NP9H considerations. Mod is being considered Consumers Power Co. 78/12/28. 2pp. 94190: 339.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION. UNIT 1

7811280187 Forwards LER878-033/03L-0. FOX:H. 8 Tennessee Valley Authority, 78/11/21, 1p. 94013:224.

F. Bsturity, medical, emergency & fire protection plans

7810310074 Forwards rev to copies 5 thru 10 of subj facil security plan std 780926, Revs reflect letset changes in proposed security sys & procedures. Revs are proprietary (ref 100CR2. 790). OILLELAND, J.E. Tennessee Valley Authority. 78/10/25. 79pp. 94094:315.

7811200200 Forwards rave to Physical Security Plan of subj facils re installation of emergency lighting fixtures. Requests withholding from pub disclosure per 10CFR2 790. GILLELAND, J. E. Tennessee Valley Authority. 78/11/15. 1p. 94232:036

G. Adjudicatory correspondence

7812260057 Motion of MN Pollution Control Agency is grented & licensee is ordered to creese & desist from further installation of any spent fuel storage reck at subj facil pending further order.

order.

Atomic Safety and Licensing Board Panel. 78/12/15. Opp.

# H. General correspondence

7812210336 Comments on 780727 constituent ltr to Legomarsino revalidity of the Reactor Bafety Study the aubj facil fire. & the Operating performance of commercial nucleur plants OBSICK, LV Office of the Executive Director for Operations 78/12/12 13pp 94014.305.

### J Insurance & indemnity information

7811090096 Advance premium & standard premium endorsement for 1978 BARDEG.C R Nuclear Energy Liability Insurance Association 78/10/11 ip. 94042 141.

7812010256 Forwards PolicyMMF-66, Endorsement#37 for subj facil States advance promium \$94768.89, reserve premium \$71349.36 & return premium \$1325.17.
FIEDLER. J. Nuclear Insurance Consultants. 78/11/28. 2pp.

K Utility Final Bafety Analysis Report (FBAR) & amends

7812200244 Forwards Amend#67 which rev FBAR to reflect current plant configuration Amond does not req review & is available in PDR CILLELAND. J E Tennessee Valley Authority. 78/11/30 2pp. 94159-001

--7812200246 AmondM67 to F8AR, Vols i-7. This emand does not req review it merely rev FSAR to reflect current plant configuration

Tennessae Valley Authority 78/11/30. 2900pp.

## P Operating license stage documente & correspondence

78112000B0 Requests addi info for review of recirculation jump trip for the to militate Anticipated Transient w/o Screen info due w/in 60 days

LEAR: 0 Operating Reactors Branch 3 (Pre 790625) 78/05/15 5pp. 94217:360.

7812110245 Responds to 780928 request for amend to License DPR-33 to permit operation at greater power levels Class III fee is applicable & should be submitted MILLER-W O. License Fee Management Dranch. 78/11/30. ip. 94377-248

7810200131 Notice of issuance of Amend#40 to Facil Operating Lick DPR-33-Amend#38 to Facil Operating LickDPR-32 & Amend#34 to Facil Operating LickDPR-360 rev Tech Operating Amend#34 to Facils. Amends lower low water level satpoint 1PPDL110.1 A. Operating Reactors Branch 3 (Pre 790625), 78/08/02.2pp. 94411:287

7810130200 Forwards Amend#43 to DPR-33 Bafety Evaluation Rept.& Notic of Issuance IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625) 78/09/29. 2pp. 94079: 261

--7810130202 Amend#43 to Lic#DPR-33imod conditions for oper & euroeillance aquip.
IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625) 78/09/2 2pp. 94079-263.

--7810130203 Safety Evaluation Rept supporting Amend#43 to LicMDPR-33 Covering pump seliure accident, inadvertent Cold Loop Startup Transient & monitoring of selety margins for 1 loop oper.

\*\* Operating Reactors Branch 3 (Pre 790623), 78/09/29, 4pp. 94079, 268.

--7810130210 Notice of Issuance of Amend to Facil Oper LickOPR-33 to permit oper at maximum of 50% lic pur level w/i recirculation loop isolated.

1PPDLITG.T A. Operating Reactors Branch 3 (Pre 790625) 78/09/2 2pp. 94079:272

7810140033 Notice of Issuance of Amend443 to Facil Open Lice DPR-33 on 780929 re 82% lic pur level w/ one recirculation loop isolated.
IPPOLITO.T.A. Openeting Reactors Brench 3 (Pre 790428), 78/09/29, 290. 94329.063.

7810110107 Responds to 780829 ltr indicating there have been no incidents of control rods failing to fully insert on demand et sub; facils.

OILLELAND, J E Tennessee Valley Authority. 78/10/05. Ip. 94064.353

- 7810120065 Forwards replacement pages of proposed Tech Bpec changes to of justification for the proposed changes.NEOC-24136. correcting typographical errors of amend request submitted 780908.
  OILLELAND, J. E. Tannessee Valley Authority. 78/10/05. 9pp. 94421.184.
- 7810230244 Forwards responses to verbal questions re-proposed changes to Tech Specs of subj facil as submitted 780322.
  GILLELAND, U.E. Tennesses Valley Authority. 78/10/10. 6pp. 94170-222
- 7810240153 Forwards add1 info re proposed differential pressure control & torus water level Tech Specs for subj facils.
  OILLELAND, J.E. Tennesses Valley Authority 78/10/18. 3pp.
- 7810240144 In response to 780807 ltr to N. S. Hughes, the recommended surveillance of reactor protec squastl continue. Request response date extension to 781219.

  OILLELAND, J. E. Tennesses Valley Authority. 78/10/19. 1p.
- 7811130335 Summary of 780914 mesting w/GE representatives & Mark I Owners Group re-progress of Long Term Prog w/attendance liet & agenda (RD-9-A-Merthi, Standards.)
  ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/26.
- 7811200406 Forwards results of measurements of radioactive mati in NRC phantom on whole body counter Enti I contains actual amount of each radiomyclide present-enti 2 gives ratio of measurements to DOE values & enti 3 gives recommendations.

  SUTI-ERLAND, J. T. Region 0, Atlanta, Fuel Facility & Materials Befety Branch. 78/11/09. Spp. 94419:305.
- 7811210208 Notifies util of 781205 seminer in Atlanta to discuss new Model Rod Effluent Tech Specs & encl seminer info sheet, registration form & proposed agenda UREILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09. 3ps. 74485:212
- 7811170113 Reports that NRC will assist Los Alamos Scientific Leb team in performing vital area analysis at subj facil during the week of 781126.
  OILLELAND, J.E. Tannessee Valley Authority. 78/11/13. ip. 94047-145
- 7811170175 Requests that NRC review indemnity fee invoice#23-79 & #27-79.dtd 781024.which appears to be incorrect & rebill util.
  OILLELAND. J. E. Tennessee Valley Authority. 78/11/13. ip.

94136: 029

- 7811170215 Responds to NRC questions prompted by Gillsland's 780811 ltr requesting Tech Spec changes. Change ensures reconfiguration of SRM's & IRM's & will be placed in non-coincidence trip mode.

  MILLS.L.M. Tennesses Valley Authority. 78/11/13. 1p. 94136:122.
- 781128036: Licensee's supporting documentation for approval of Recirculation Pump Trip(RPT) for reactor protec sys fails to address most criteria of IEEE 279 or equip qual & adequate surveillance testing Tach Specs. Addl Info requested. LAINAS-0. Plant Bystems Oranch (Pre 791030). 78/11/14. 2pp. 94377:224
- 7811300049 Forwards NRC staff paper, Policy Bassion Itam(BECY-7B-354) relicenses reg performance evaluation. Three methods for evaluation ere: statistic; trend analysis & regional survey eathod. M/o encl.
  O'REILLY, J. P. Region 2. Atlante, Diffice of the Director. 78/11/15.
  2pp. 94071:051.
- 78:12130148 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CR72. Requests pre-workshop registration of attenders to facilitets sending out meth. W/ench Registration Form & Liab of Locations. HILLER/J. R. Assistant Director for Bits & Bafaguerds (Pre 79:030). 78/11/15. 3pp.
- 7812180273 Forwards RevWi "Draft Radiological Effluent Tach Specs" for BHR's(NUREO-0473) & "Preparation of Radiological Effluent Tach Specs for Nuc Per Plants" (NUREO-0133). ORINES, B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94356:340.
- 7812050003 Porwards Amends#44.40 & 17 to Lic#DPR-33, DPR-52 & DPR-68 safety sval & Notice of Issuance. 1PPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 3PP. 94200:021.

- ---7812050009 Amend#44 to Oper Lic Permits average pur range monitor systoble inoperable in refusi mode; permits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs re rod block monitor. IPPOLITO, I.A. Upperating Reactors Branch 3 (Pre 790625). 78/11/16 29pp. 94200:024.
- --7812050017 Amend#40 to Oper Lic.Permits average pur renge monitor systobe inoperable in refuel modespermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tach Specs re
- --7812050022 Amend#17 to Open Lic.Permits everage pur range monitor sys to be operable in refuel modesparmits less than 3 intermediate range monitors per trip channel to be open in shutdown mode & clarifies Tech Speck re:rod block monitor. • Operating Reactors Branch 3 (Pre 790623). 78/11/16. 16pp. 94200:084.
- ---7812050023 Concludes emende do not involve significant hezerds, health & sefety of public will not be endangered by oper in proposed manner & ectivities in compliance w/regs.
  4 Office of Nuclear Reactor Regulation, Director. 78/11/16. 9pp. 94200:102.
- --7812050026 Notice of Issuance of Amend#44 to LicMDPR-33 emend#40 to Lic MDPR-52 & emend#17 to LicMDPR-68 which revise Tech Bpecs. IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 3pp. 94200:111.
- 7812050012 Forwards Amend#45.41 & 18 to Facil Oper Lic#DPR-33.DPR-52 & DPR-58 rev Tech Space as requested in 780803 ltr w/Befety & Evaluation & Notice of Issuence IPPCLITO.Y.A. Operating Reactors Branch 3 (Pra 790625). 78/11/18. 2pp. 94200:188.
- --7812050016 Amend#45.41 & 18 to Facil Oper LiceDPR-33.DPR-52 & DPR-68 rev Tech Bpacs to incorp minor changes for leak testing containment isolation & check vaives.Amend#18 changes limit of 2000 HMD/t fuel exposure.

  IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790628), 78/11/18. 60pp. 94200:190.
- --7812050019 Befaty Evaluation Rept supporting Amend#45.41 & 18 to Facil Oper LiceDPR-33. DPR-52 & DPR-58 concluding that proposed changes are acceptable & safety of pub will not be endangered by oper in proposed manner.

   Office of Nuclear Reactor Regulation, Director. 78/11/18. 18pp. 94200:280.
- --7812050020 Notice of Issuance of Amend#45.41 k 18 to Facil Oper Lic #DPR-33, DPR-52 k DPR-68. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. 2pp. 94200:268.
- 7812060062 Requests add1 info re reload analysis for oper of subj facil in third fuel cycle incorporating prompt racirculation pump trip feature.
- trip feature.

  IPPULITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/82.

  Dpp. 94234:126.
- 7812110029 Discusses possible dangers of LDCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Went1 ANO: 97812080207.

  1PFCLITO, T. Operating Reactors Branch 2 (Pre 790625). 78/11/29.
  - 1PPCLITG.T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. 8pp. 94408;101.
- 7812050243 Forwards results of MCPR analysis to aid NRC in review of amend request & corrections to amend request. Also forwards 0E rapt "Suppl Raibad Lic Bubmittal for Browns Ferry Nuc Plant unit inRaibad 2."
  OILLELAND, J.E. Tennessee Valley Authority. 78/11/30. 11pp. 94202.056.
- --7812050251 "Suppl Relead Licensing Submittel for Browns Ferry Unit 1. Relead 2," Revision 1. FREEMON, A.M. General Electric Co. NEDO-24136 RO1. 78/11/30. 33pp. 94432:198.
- 7812050189 Informs that due to delays, complete response to suppression pool temp trenslants will be submitted by 780315.
  OllLELAND, J.E., Tennassas Vallay Authority. 78/12/01. 1p. 94306: 123.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings hald

1070170 Forwards add1 info re cycle 3 reload analysis quested in 781122 NRC 1tr. Transient analysis in "-1 submittal has been performed w/REDY Code LIELAND, J.E. Tennessee Vallay Authority, 78/12/05, 7pp. 1559: 136

128044 Emphasizes importance of submitting accurate & complete info 
NC by licensees & applicants. Info submitted must be 
bitantiated by data & calculations. Licensee must notify 
IC of any inaccuraties or enforcement action will result. 
VIS.J.O. Office of Inspection & Enforcement, Office of the 
-rector. 78/12/06. 2pp. 94310:334.

2200154 Provides details of mod motor-generator set characteristics 'postulated M-Q set oper modes for low-pressure coolant spection valve pur supply. Installation will be delayed till end of 2nd refueling outage of Unit 3 (LLELAND, J.E. Tennassee Valley Authority, 78/12/13, 4pp. 1420: 271.

2200236 Responds to NRC ltr of 780807 re reactor protec sys pwr ppply at sub; facil. TVA does not balleve that concerns oprassed by NRC are a problem. Further survaillance of the factor protec sys supplies is unwarranted.
ILLELAND, J. E. Tannessee Valley Authority. 78/12/13. 1p. 1206; 00f.

2260163 Response to 781122 request for add1 1nfo needed for reload helysis for cycle 3 open of facil. LLELAND, J. E. Tannassee Velley Authority. 78/12/14. 4pp. 3157:232.

2270175 Due to incomplete resolution of insvc prog for Unit institted of rev Tach Space has been postponed until after stails of Unit 3 insvc inspect prog are resolved.

ILLELAND, J. E. Tennessee Valley Authority. 78/12/19. 1p. 4017:341

2290217 Responds to 781:29 NRC itr re-containment purging during creal plant oper & request for info re-design of all safety . Ctuation signal circuits which incorp a manual feature. esponses will be submitted by 790301.
ILLELAND. J. E. Tennessee Velley Authority, 78/12/21, 2pp. 4191:188.

1210367 Forwards add1 info re multiple consecutive safety/reliaf alve Actuation of Mark I containment program
080%.L.J. General Electric Co. 78/11/13. 3pp.

Inspection raports: IE Bullatins & correspondance

0310050 Ack receipt of 780127 itr informing NRC of steps taken to przect violetions noted during Inspec #50-259/77-26. 50-260/77-26 & #50-296/77-26. 50-260/77-26. Region 2: Atlanta: Reactor Operations Nuclear Support ranch. 78/03/01. 1p. 94094:129.

810310064 Responds to 780103 NRC ltr ra violations noted in Inspec Rapts 850-259/77-26, #50-260/77-26 & 50-296/77-26. Corrective actions are exampt from disclosure dua to security info contained in response.
01LLELAND.U.E. Tennesses Velley Authority. 78/01/27. ip. 94094:130.

'810310069 Forwards IE Inspec Rapts #50-259/77-26, #50-260/77-26 k #50-296/77-26 on 771213-16 & w/o Notics of Violation, w/hald pursuant to 2, 790. LONG: F, J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/01/03, 2pp. 94094:131.

'BlC010074 IE Inspec Rapts #50-259/77-26, #50-260/77-26, #50-26/77-26, on 771213-16 during which 1 item of noncompliance was noted: vital green area gate was open & unattended.

BRADFORD.W.H. Region 2, Atlanta, Office of the Director.

ALDERBON.C.E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/01/03. Spp. 94094: 133.

.0110265 Forwards IE Inspec Repts950-259/78-15, 850-260/78-16, & 850-196/78-14 on 780626 during which no itams of noncompliance erro noted.

SUTERLAND.J.T. Region 2, Atlents, Fuel Facility & Materials Bafety Franch. 78/08/31. 2pp. 94079; 142.

7810120004 IE Inspec Repts#50-259/78-15,#50-260/78-16, % #50-296/78-14, on 780626, during which no items of noncompliance were noted. Heyer area inspected: whole body counting practices & procedures & test count of NRC phentom.

HILLBAP, M. J. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/08/30. 4pp.

7810110283 Forwards 15 Inspec Repts#50-259778-19,#50-260/78-20 & #50-26/78-18 on 780720-21 during which no items of noncompliance were noted.

8UTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/09/01. 2pp. 03556:076.

- --7810110286 lE Inspec Repta#50-259/78-19&#50-260/78-20.#50-296/78-18, on 780720-21 during which no items of noncompliance were noted Major areas inspected included: emergency planning & simulated emergency conditions.

  PERROTTI.D.J. Region 2, Atlanta, Fuel Facility & Materials Sefety Branch. 78/08/31. 4pp. 94079:144.
- 78:1010269 Forwards IE Inspec Repts#50-259/78-20.#50-260/78-21 & #50-296/78-19 on 780807-10.during which no items of noncompliance were noted.

  LONG F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/13. 2pp. 94392:160.
- ~-7811010280 IE Insp Rapts 50-259/78-20.50-260/78-21 & 50-296/78-19 on 780807-10.during which no items of noncompliance were noted Major ereas inspacted:plant operations.reportable occurrances & alactrical mods.

  BLLIVAN.R.F. Region 2. Atlanta. Office of the Director. 78/09/12 Spp.
- 7810110056 Forwards 1E Inspec Rept 30~259/78-24.50-260/78-27 & 50~276/78-23. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/09/26. 2pp. 94063:246.
- --7810110039 IE Inspec Rept 50-259/78-24.30-260/78-27 & 50-296/78-23 on 780913. Meeting held re TVA security program & managariai changes being implemented. QILLESPIE.F.P. Region 2. Atlanta. Safaguards Branch. 78/09/22. 3pp. 94063:248.
- 7810230226 Ack receipt of 780922 itr re-corrective steps taken on items of noncompliance found in inspec as notified by KRC ltr of 780825.

  O'REILLY, J. P. Region Q. Atlanta. Office of the Director. 78/10/06.

  ip. 94165:093.
- --7810230227 Responds to 780825 NRC ltr ra violations noted in Inspec Repts#50-239/78-16.#50-260/78-19.#50-296/78-17. GillELAND, J. E. Tennessea Vallsy Authority. 78/09/22 ip. 94165:094.
- --7810230230 Forwards IE Inspec Repts#50-259/78-18.#50-260/78-19.#50-295 78-17 on 780726-28. O'REILLY,J.P. Region 2. Atlanta. Office of the Director. 78/08/25. 3p. 94165:095.
- 7810230300 Forwards IE Circular#78-17. (Sea AND: 7810230221, Docket 50-313, 781013)
  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/10/13. 
  1p. 94164: 183.
- 7811090198 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec#30-259/78-18, #50-260/78-19 & #50-296/78-17. KENNA, W. B. Region 2, Atlanta, Offica of the Director. 78/10/26. lp. 94038:260.
- --7811090204 Responds to 780825 NRC itr ra violations noted in Inspec Repts#50-259/78-18,#50-260/78-19 & #50-296/78-17. Corrective actions are exempt from disclosure IAM 10CFR2, 790. O'LLELAND, J. E. Tennessee Valley Authority. 78/10/16. 1p. 94038: 261.
- 7812030053 Forwards IE Inspec Repts#50-259/78-21.#50-260/78-23 & #50-294/78-20 on 780828-0901 during which no itsms of noncompliance were noted.

  LONG, F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Stanch. 78/10/27. 2pp. 94334:218.
- --7812050057 IE Inspec Repts#50-259/78-21,#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted Major areas inspected incl:reporteble occurrences & followup on IE bulletins & circulers.

  GLLIVAN.R.F., OUZTB.J.E. Region 2, Atlanta, Office of the Director. 78/10/26, 10pp. 94034:220.
- 7811130006 Ack receipt of 781010 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-17, 50-260/78-18 & 50-296/78-16. SUTHERLAND.J.T. Region 2, Atlenta, Fuel Facility & Materials Bafety Br

- --7813530033 Responds to 780935 NRC ltr re violations nated in laspac Repta#50-259778-17, #50-260778-18 &850-296778-16. Corrective actions: IB & DA RHR heat exchanges inspected & task test initiated OfficeLAND J. E. Tennessee Valley Authority. 78/10/10. 2pp. 94077:012.
- --7811130018 Forwards IE Inspec Repta#90-259/78-17.#50-260/78-18 & #850-299/78-16 on 780725-28 & Notice of Violation.

  BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials

  Bafety Branch. 78/09/15. 2pp. 74075:278.
- --7811130022 Notice of Violation from inspec on 780725-28.

  \* Region 2. Atlenta, Fuel Facility & Materials Safety Branch.
  78/09/15. ip. 94075:280.
- --7811130022 Notice of Violation from inspec on 780725-28.

  \*\* Region 2. Atlanta. Fuel Facility & Materials Safety Branch.
  78/09/15. 1p.
- --7811130049 IE Inspec Repts#30-259/78-17.#50-260/78-18 & #50-296/78-16 on 780725-28 during which I item of noncomplience was noted: release of radioactive effluents above limits. TRGUP, O. L. GIBSON, A. F. Region 2, Atlente, Fue) Facility & Materials Safety Brench. 78/09/15. Bpp. 94075:282.
- 7811130073 Formerds IE Circuler 78-18.
  O'REILLY, J.P., Region 2. Atlanta. Office of the Director. 78/11/06.
  1p. 94112.288.
- 7812210355 Forwards 1E Inspec Repts#50-259/78-26.#50-260/78-29 & #50-276/78-25 during which no items of noncompliance were notes.

  KENNA-H B. Region 2. Atlanta. Bafeguards Branch. 78/11/09. Spp. 94014:353.
- --7812210363 IE Inspec Repts#50-259/78-26.#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted. Major areas inspected incliphysical security requirements previous items: sierm.access.communications.
  BEBECKER.K.H. GILLEGPIE.F.P. Region 2. Atlanta. Befeguards
  Branch. 78/11/08. 4pp. 94014:355
- 7812180320 Forwards IE Inspec Repts450-259/78-25.450-260/78-28 & #50-296/78-24 on 780925-27 during which no Items of moncompliance were noted.

  LDNO, F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 78/11/09, 2pp. 94356-285.
- --7812180325 IE Inspec Repts#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of noncompliance were noted, Mejor areas inspected incl:refueling plant oper & LER & IE Circulars/Rulletins review.
  SULLIVAN,R,F., DANCE,H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/09. 6pp. 94356:287.
- 7812130372 Forwards ampided response to IE Bullstin#78-09, describing steps taken to effect a good seel between drywell head & containment flange.

  O'LLELAND, J.E. Tennesse Valley Authority, 78/11/13, 2pp. 04090-103
- 7812120031 Forwards reproductions of articles that eppeared in June & Aug 1978 aditions of Nuc Security Bafeguards Newsletter. KENNA.W.B. Region 2, Atlanta, Safaguards Branch. 78/11/17. 4PP. 94278:068
- 7812060015 Ack receipt of 781122 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-82, #50-260/78-25 & #50-296/78-21.
  BUTTERLANO.J.T. Region 2. Atlenta, Fuel Facility & Materials Sefety Branch. 78/11/28. 1p. 94418:338.
- --7812050021 Responds to 781027 NRC ltr re violations noted in Inspec Rept#850-239778-22.#850-250778-25 t #850-295778-22.Corrective actions: survaillence instruc sched change to reflect 18 month testing req. GiltELAND.J.E. Tennessee Valley Authority. 78/11/22. 3pp. 9418:339.
- --7812060026 Farwards IE Inspec Rept#50-259/78-22, #50-260/78-25 k #50-294/78-21 on 780911-14 & Notice of Violation. BUTHERLAND, J. T. Region R. Atlante, Fuel Facility & Materials Barbety Brench. 78/10/27. 2pp. 94415:312.

- --7812060030 Notice of Violatian from inepec on 780911-14.

  \* Region 2: Atlanta, Office of the Director. 78/10/27. ip. 94415-314.
- --7812060033 IE Inspec Rept#50-259/78-22,#50-260/78-25 & #30-296/78-21 on 780911-14 during which I item of noncompliance was noted: surveillance teating of air cleening sys.
  TROUP, Q. L. JACKGON, L. L., QIBSON, A. F. Region 2, Atlanta, Office of the Director. 78/10/27. 9pp. 94415:315.
- 7812280014 Forwards IE Bulletin 78-14.
  O'REILLY.U.P. Region 2. Atlanta. Office of the Director. 78/12/19.
  2PP. 94131:032
- R. Periodic operating reports & related correspondence
- 7810160106 Forwards Monthly Oper Rept for Sept 1978.
  DEWEASE, J. Q. Tennessee Valley Authority. 78/10/10. 1p. 94004:281.
- --7810160109 Monthly Oper Rept for Sept 1978.

  DEMEASE, J. G. Tennessee Velley Authority. 78/09/30, 34pp.
  94002 087
- 7810170161 Monthly Open Rept for Bept 1978.
  DEWEASE, J. O. Tennesse Valley Authority. 78/10/31. 31pp. 94236:097.
- 7810300103 Files fish impingement rept for subj facil for 3rd quarter 1978 01LLELAND, J. E. Tennessee Vellsy Authority. 78/10/19. 14pp. 98008:048.
- 7811140137 Forwards Monthly Open Rept for Oct 1978.
  DEWEASE, J. C. Tennesses Valley Authority. 78/11/09. lp. 94425.275.
- --7811140140 Monthly Open Rept for Oct 1978.

  OREEN,D. Tennesse Valley Authority. 78/11/02. 33pp. 94425.276
- 7812190161 Forwards Monthly Open Rept for Nov 1978.
  DEWEASE, J. Q. Tannessee Valley Authority. 78/12/02. 1p. 94340/160.
- --7812190162 Monthly Oper Rept for Nov 1978.

  DEMEAGE J. O. Tennesses Valley Authority. 78/12/02. 2999.
  9410-181
- B. Reportable occurrences. LERs & related correspondence
- 7811020362 ROM50-259/7827: on 780713"A" recirculation loop flow decreased from 41,000 to 33,000 cpm w/corresponding increase in pump delte F, caused by valve astem separating from valve disc.

  DEWERSE, J. Q. Tennessee Valley Authority. 78/07/14. 1p. 94241:136.
- 7810100036 Forwards L6RM78-028/01T.
  FGX.H. 8. Tennessee Velley Authority. 78/10/02. 1p. 94033:028.
- --7810100040 LERW78-028/01T-O on 780717: Forbaro Model 510 per supplies provided under TVA contect 75K11-8580 were not seismicelly qualified qualified per supplies have been provided & will be installed.

   Tennesses Velley Authority. 78/10/02. 2pp. 94033:029.
- 7810310183 Forwards LERW78-029/017-0. FOX.H.B. Tennesses Valley Authority. 78/10/25. 1p. 94090:239.
- --7810310184 LERM78-029/03L-0 on 78101R: cable raceway between Dissel Operator Sidg & Standby Oas Treatment Bldg appeared to have sattled 2 inches at Dissel Generator Sidg & expension joint. Cause unknown but new supports will be installed on receway. a Tennesses Valley Authority. 78/10/R4. 3pp. 94090:240.
- 7811140217 Forwards LERW78-030/03L-0. FDX.M. 8, Tennesses Valley Authority. 78/11/08. 1p. 94400:046.
- --7811140221 LER 78-030/03L-0: on 781013, four heet detectors found to be connected to incorrect aprey zones. Elec panel 1-25-281A wes wired incorrectly causing improper sequencing. Detectors were rewired & returned to oper per Tech Byess.

  \*\*Tennessee Valley Authority. 78/11/06. 2pp. 94400:047.
- 7811140240 Forwards LSR#78-031/03L-0. FOX.H.S. Tennessee Valley Authority. 78/11/08. 1p. 94400:096-

- 7811280214 Suppl to 780331 ltr re Reportable Occurrence 50-259/288 & interia measures taken to alleviate potential adverse implant voltage conditions on Unit 3:4-KV unit boards, the 161-KV eye. & the 4-KV ehutdown boards.

  FOX.H.S. Tennesses Valley Authority. 78/11/20. 2pp. 02785:338.
- 7811283191 LERM78-033/03L-0 on 781025: redwater airborns effluent monitor recorder RM-90-232 failed to oper resulting in lass of continuous effluent monitoring. Caused by broken input signal lasd.

  \* Tennessee Valley Authority. 78/11/15. 2pp. 94013:225.
- 7811280205 Forwards LERW7B-032/03L-0, FOX:H. S. Tennesse Valley Authority. 78/11/22. 1p. 94013:265.
- --7811280207 LERE78-032/03L-0 on 781022: offgss sampling Pump A maifunctioned & pump B motor would not ebert. Caused by vance sticking on pump A model HB21 H62 by Metal Bellows Corp. Bearings & centrifugel sultch feiled on pump B motor.

   Tennesses Valley Aushorlty. 78/11/15. 2pp. 94013: 266.
- 7812270265 Forwards LERW78-034/017-0. FGX:H. 8. Tennesse Valley Authority. 78/12/19. 1p. 94232:036.
- --7812270269 LER#78-034/017-0 on 781205:during refueling outage 6 MSIV's exceeded leekage limits. Caused by degredation of velve seating eurfaces thru normal oper.
  4 Tennessee Valley Authority. 78/12/18 2pp. 94232:037.
- DOCKET 50-260 SHOWNS FERRY NUCLEAR POWER STATION, UNIT Q F. Security, medical, emergency & fire protection plane
- 7810310075 Forwards ray to copies 6 thru 10 of subj facil security piend td 780926. Rays raffect latest change in proposed security sys & procedures. Rays are propriatery (ray 100FR2.770). ellLELAND. J.E. Tennesse Valley Authority. 78/10/25. 79pp. 94094; 315.
- 7811200200 Forwards reve to Physical Becurity Plan of subj facils reinstalletion of emergency lighting fixtures. Requests withholding from pub disciosurs per IOCFRR. 790.
  91LLELAND, J. E. Tennesses Velley Authority. 78/11/15. lp. 94292:036.

# H. General correspondence

- 7812210336 Comments on 780927 constituent ltr to Legomeraino revelidity of the Reactor Befety Study, the subj facil fire, & the operating performance of commercial nuc pur plants. 90881CK.L. V. Diffice of the Executive Director for Operations. 78/19/12. 13pp. 94014:305.
- J. Insurance & Indomnity information
- 7819010256 Forwards PolicyMMF-66.Endoresment#37 for subj fscil.States Advance premium #74768.89, reserve premium #71049.36 & return premium #3125.17.
  PIELER,J. Nuclear Insurance Consultants. 78/11/28. 2pp.
- 78:109009å Advence premium & standard premium endorsement for 1978, SARDES.C.R. Nuclear Energy Lisbility Insurance Association. 78/10/11. 1p. 94042:141.
- K. Utility Finel Befety Analysis Report (FSAR) & amends
- 7812200244 Forwards Amend#67 which rev FBAR to reflect current plant configuration, Amend does not req review & le available in FDR.
  91LELAND, J. E. Tennasses Valley Authority, 78/11/30, 2pp. 94189; 001.
- --7819200246 Amendéé? to FBAR, Vols 1-7. This amend dose not req review, as it sersly rev FBAR to reflect current plant configuration.

  \* Tennesses Valley Authority. 78/11/30. 2900p.

- GILLELAND, J. E. Tennesses Valley Authority. 78/11/13. 1p. 94047:145.
- 7811170175 Requests that NRC review indomnity fee involce#23-79 & #27-79, dtd 781024-which appears to be incorrect & reblil util.

  07LLELAND, J. E. Tennessee Vellay Authority. 78/11/13. ip. 94134:029
- 7811170215 Responds to NRC questions prompted by Oilleland's 780811 it requesting Tech Spec changes. Change ensures reconfiguration of ERM's & IRM's & will be placed in non-coincidence trip mode.

  Millel, L.M. Tennesses Valley Authority. 78/11/13. ip. 94136: 122.
- 78:1200080 Requests eddl info for review of recirculation pump trip for use to mitigate Anticipated Translant w/o Borem Info due w/in 60 days.

  LEAR G. Operating Resolve Branch 3 (Pre 790625). 78/05/15. 5pp. 74217:360.
- 7810200131 Notice of issuance of Amend#40 to Facil Operating Lic# DPR-03.Amend#38 to Facil Operating Lic#DPR-52 & Amend#14 to Facil Operating Lic#DPR-56 rev Yes Byses for oper of subj facils.Amends lower low water level setpoint.

  IPPQLITG.T.A. Operating Reactors Branch 3 (Pre 790625). 78/08/02.
  Zpp. 94411:287.
- 7810110107 Responds to 780829 ltr indicating there have been no incidente of control rads failing to fully insert on demend at subj fecile.

  OILLELAND.J.E. Tennesse Valley Authority. 78/10/05. ip. 94066:333.
- 7810230244 Forwards responses to verbal questions re-proposed changes to Tech Spacs of subj facil as submitted 780322. OILLELAND. J.E. Tennesses Valley Authority. 78/10/10. 6pp. 94170;242.
- 7810240153 Forwards additinfo re proposed differential pressure control torus water level Tech Space for subj facils.

  OILLELAND, J. E. Tannasses Valley Authority. 78/10/18. 3pp.
- 7810240144 in response to 780807 itr to N. D. Hughes, the recommended surveillence of resetor protec eys will continue, Request response date extension to 781215.

  OILLELAND, J. E. Tennesses Valley Authonity. 78/10/19. ip.
- OILLELAND, J. B. Tennesses Valley Authority. 78/10/19. ip.
- 7810250082 Forwards summary raps of refueling test proy conducted after subj facil earling 1978 outage.
  GILLELAND, J. E. Tennasses Valley Authority. 78/10/19. 1p.
- --7810250085 "Summary Rept:Refusling Teet Program." Summerizes tests performed as of 780810.
  DEMEASE.J. Q. Tennesses Valley Authority. 78/10/19. Spp.
- 7811130335 Bummary of 780714 meeting w/OE representatives & Mark 1 Dumers Group re-progress of Long Term Prog w/sthendence itst & agenda(RD-9-A-Mark), Standarda, GRIMEB, C. Plent Systems Branch (Pre 791030), 78/10/26. 67pp.
- 78ii1001R8 Forwards "Reactor Containment Bldg Integrated Leak Rate Test."
  GILLELAND, J. R. Tennessee Velley Authority. 78/ii/07. ip. 94242:362.
- --7811150129 "Reactor Bldg Containment Integrated Leak Rate Test" on 780513-15. Dutlines objectives, principal events & special equip used in the CILRT. Concludes that accurate results can be obtained while significantly reducing test time. GILLELAND. J. E. Tennessee Valley Authority. 78/11/07. 71pp. 9428-318.
- 7811200400 Forwards results of measurements of radioactive metl in NR phentom on whole body counter. Entil contains actual amount of sech radionuclide presents and 12 gives resto of measurements to DOE values & entil 2 gives recommendations. SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafet Branch. 78/11/09. Spp. 94419:305.
- 7811210288 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & enci seminar info sheet, registration form & proposed agenda. O'REILLY, J.P. Region 2. Atlanta. Dffice of the Director. 78/11/09. 5pp. 94485:212.

≥pp. 94071:051

7812150148 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. Wench Registration Form & List of Locations. MILLER, J. R. Assistant Director for Site & Bafeguards (Pre 791030). 78/11/15. Spp

- 7812180273 Forwards Revki "Draft Radiological Effluent Tech Specs" for BKR's(NNREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plante" (NUREO-0133). ORINES, B. W. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15 App. 94356:340.
- 7812050003 Forwards Arends#44,40 & 17 to Lic#DPR-33,DPR-52 & DPR-68 safety eval & Notice of Issuence.

  IPPCLITO.T.A Operating Reactors Branch 3 (Pre 790625) 78/11/16.

  3PP. 94200:021.
- --7812050009 Amend#44 to Oper Lic.Permite average pur range monitor eye to be inoperable in refuel modespermite less than 3 intermediate range monitors ger trip channel to be oper in shutdown mode & clarifies Tech Specs re.rod biocs monitor. PPDLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 29pp. 94200:024.
- --7812030017 Amend#40 to Oper Lic. Permite average pur renge monitor systobe imparable in refusi modespermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Spets rered block monitor. iPPOLITO.T.A. Operating Reactors Brench 3 (Pre 790625). 78/11/16. 27pp. 94200.035
- --7812050022 Amend#17 to Oper Lic. Permits everage pur range monitor systobe operable in refusi mode/permits less than 3 intermediate renge monitors per trip channel to be oper in shutdown mode & clarifies Tech Space re-rod block monitor.

  \*\*Operating Reactors Branch 3 (Pre 790625). 78/11/16. 16pp. 94200:084.
- --7Bi2050020 Concludes amends do not involve significant hezerds health & safety of public will not be endangered by oper in proposed menner & activities in complience w/rege.

  \* Office of Nuclear Reactor Regulation, Director. 78/11/16. 9pp. 94200:102
- --7812050026 Notice of issuance of Amend#44 to Lic#DPR-33 amend#40 to Lic #DPR-52 & amend#17 to Lic#DPR-68 which revise Tech Spece. \*\*SPPOLITO.1.A. Operating Reacture Branch 3 (Pre 790625). 78/11/16. 3pp 94200 iii.
- 7812090012 Forwards Amend#45.41 & 18 to Fecil Oper Lic#DPR-33.DPR-52 & DPR-68 rev Tech Specs as requested in 780803 itr w/8efety Evaluation & Notice of lesuence. IPFC\_ITO.T.A. Operating Reactors Branch 3 (Pre 790825). 78/11/18. 2pp. 94200:189.
- --7812030016 Amend#45.41 & 18 to Fecii Oper Lic@DPR-33.DPR-52 & DPR-68 rev Tech Specs to incorp minor changes for lesk testing containment lealstion & check valves Amend#18 changes limit of 2000 MHG/t fuel exposure.

  IPPOLITO.T A. Operating Reactors Brench 3 (Pre 790625). 78/ii/i8. 60pp. 94200:190.
- --7812050019 Bafety Evaluation Rept supporting AmendW45,41 & 18 to Facil Oper Lic WDPR-33, DPR-32 & DPR-68 concluding that proposed changes are acceptable & sefety of pub will not be endangered by oper in proposed menner.

  A Dffice of Nuclear Reactor Regulation, Director. 78/ii/i8 18pp. 94200:250.
- --7812030020 Notice of lesuance of Amend#45.41 & 18 to Facil Oper Lic MDR-33.0PR-52 & DPR-68. 1PPDL1T0.1.A. Operating Reactors Branch D (Pre 790625). 78/11/18. 2pp. 94200:268.
- 7812110029 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing. Wyencl AND: #7812080207 IPPOLITO. T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 94408:101.

- 78:2030189 Informs that due to delays-complete response re suppression pool temp transients will be submitted by 780315.
  GILLELAND, J. E. Tennessee Valley Authority. 78/12/01 1p.
- 7812140176 Forwards Dct 1978 Prog Activity Review listing meetings held to providing task-by-teek activity summary for the month. 8080N.L.J. General Electric Co. 78/12/04 ilpp.
- 7812280141 Emphasizes importance of submitting accurate & complete into to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracise or enforcement action will result. DAVIS.J.Q. Office of Inspection & Enforcement, Office of the Director. 78712705. 2pp 94310:354.
- 7812200134 Provides details of mod motor-generator set characteristics u/postulated M-O set oper modes for low-pressure coolent injection valve pur supply installation will be deleyed until and of 2nd refueling outage of Unit 3. oILLELAND. J.E. Tennessee Veiley Authority. 78/12/13. 4pp. 94420:271.
- 7812200256 Responds to NRC ltr of 780807 re reactor protec sys pur supply at subj facil. TVA does not believe that concerns expressed by NRC are a problem. Further surveillence of the reactor protec sys supplies is unwerrented. 07LLELAND. J.E. Tennesse Valley Authority. 78/12/13. ip. 94206:001.
- 7812290217 Responds to 781129 NRC ltr re containment purging during normal plant oper & request for info re design of eif eafety actuation eighel circuits which incorp a menual feature. Responses will be submitted by 790301.
  QILLELAND, J. E. Tennesses Valley Authority. 78/12/21. 2pp. 94191:188.
- 7811210367 Forwards add1 info re multiple consecutive sefety/relief valve actuation of Mark i containment program. SDBRN, U. J. Ceneral Ejectric Co. 78/11/13. 3pp.
- G. Inspection reports, IE Bulletins & correspondence
- 781109019B Ack receipt of 781016 ltr informing NRC of eteps teken to correct violations noted during inepec#50-259/78-18: #50-260/78-19 & #50-296/78-17. KENNA.U.B. Region 2. Atlante. Office of the Director. 78/10/26. ip. 94038: 260.
- --78ii090204 Responds to 780825 NRC itr re violetions noted in inspec Repts#50-259/78-i8, #50-260/78-19 & #50-296/78-17. Corrective actions are exampt from disclosure IAW 10CFR2. 790. GILLELAND, J. E. Tennessee Velley Authority. 78/i0/i6. ip. 94038: 261.
- 781i130006 Ack receipt of 781010 ltr informing NRC of steps taken to correct violations noted durling inspece30-259/78-i7. 50-260/78-18 & 30-296/78-i6. SUTHERLAND, J. T. Ragion 2. Atlenta, Fuel Facility & Meteriels Sefety Branch. 78/10/31. ip. 94075:275.
- --78iii300i3 Respands to 780915 NRC ltr re violations noted in Insper Repts#30-259/78-17, #50-260/78-18 &#50-296/78-16, Corrective actions: 18 & 3A RHR hest exchanges inspected & task test initiated. GillELAND, J. E. Tennessee Valley Authority, 78/10/io. 2pp. 94077:012.
- --78iii300i8 Forwards 1E Inspec Repts#50-259/78-17, #50-260/78-18 & #50-276/78-16 on 780725-28 & Notice of Violation.

  SUTHERLAND.J.T. Region 2. Atlente, Fuel Fecility & Materiels Selety Branch. 78/09/15. 2pp. 94075:278.
- --78iii30022 Notice of Violation from inspec on 780725-28.

  Region 2: Atienta, Fuel Facility & Meteriale Befety Branch. 78/09/15. ip. 94075:280.
- --7811130049 IE Inspec Repte#50-259/78-17.#50-260/78-18 & #50-294/78-16 on 780725-28 during which I item of noncomplience wes noted: release of radioactive efficients above limits. TROUP.G. L., 01880N.A.F. Region 2, Atlants, Fuel Pacility & Materials Bafety Branch. 78/09/15. Bpp. 94075:282.

1 1978 editions of Nuc Security Safeguards Newsletter. WHALES. Region 2, Atlanta, Safeguards Branch. 78/11/17. 4PP. 278:049

310060 Ack receipt of 780127 itr informing NRC of steps taken to rect violations noted during Inspec 830-259/77-26. >-260/77-26 & 850-296/77-26 Region 2. Atlenta. Reactor Operations Nuclear Support Inch. 78/03/01. ip. 94094:129.

-Q310064 Responds to 780103 NRC ltr re violations noted in Inspectants #50-259/77-26. #50-260/77-26 & 50-296/77-26 for rective actions are exempt from disclosure due to recurity info contained in response.

\*\*ILLELAND.J.E.\*\* Tennessee Veiley Authority 78/01/27. ip. 14094:130.

Q310069 Forwards IE Inspec Repts #50-259/77-26, #50-260/77-26 \$ #50-296/77-26 on 771213-16 & w/o Notice of Violation, #/hels pursuent to 2, 790 CNG,F.J. Region 2, Atlanta, Resector Operations Nuclear Support tranck, 78/01/03 2pp 94094:131.

OGIO074 IE Inspec Repts #50-259/77-26, #50-260/77-26, #50-296/77-26, n 771213-16 during which I item of noncompliance was noted; item green area gets was open & unattended. RADFORD, H. H. Region 2. Atlants. Office of the Director. LDERSGN.C.E. Region 2. Atlants. Reactor Operations Nuclear upport Brench. 78/01/03 5pp. 94094:133

102bb Forwards IE Inspec RepteM50-2b9/78-15.M90-2b0/78-15. & M50-/78-14 on 780626 during which no items of noncompliance e noted. HERLAND, J. T. Region 2. Atlants, Fuel Facility & Materials Safety nch. 78/08/31. 2pp. 94079 142.

O120004 IE Inspec Reptem50-259/78-15, #50-260/78-16, & #50-296/78-14, n 780626, durling which no items of noncompliance were noted. sjor area inspected; whole body counting practices & rocedures & test count of NRC phantom. ILLEBAP, W.J. Region 2, Atlanta, Fuel Facility & Materials Sefety ranch. 78/08/30. App.

Di 10286 IE Inspec Repts#30-259/78-19&#50-260/78-20,#50-296/78-18-1780720-21 during which no items of noncomplience were sted. Hajor areas inspected included: energency planning & implated emergency conditions.

DRROTTI.0. J. Region 2. Atlanta. Fuel Facility & Materiele Safety ranch. 78/08/31. 4pp. 94079:144.

10269 Forwards IE Inspec ReptsM50-259/78-20. W50-260/78-21 & -296/78-19 on 780807-10. during which no items of complience were noted. F.J. Region 2. Atlants, Resctor Operations Nuclear Support sch. 78/09/13. 2pp. 94392:160.

1010280 IE inap Repts 50-259/78-20.50-260/78-21 & 50-296/78-19 s 780807-10.during which no items of noncompilance were sted. Helpor areas inspected: plant operations, reportable ic Urrences & electrical mods.

LLIVAN.R.F. Region 2. Atlante. Office of the Director. W09/12. Spp.

0056 Forwards IE Inspec Rept 50-259/78-24,50-260/78-27 & 96/78-23.
ILLYJ.P. Region 2, Atlante, Office of the Director. 78/09/26.
94063:246.

110099 IE Inspec Rept 50-259/78-24, 80-260/78-27 & 50-296/78-23 on O915. Heating held re TVA security program & managerial angee being implemented. LLESPIE.F.P. Region 2. Atlanta. Befaguerde Branch. 78/09/22. p. 94063: 248.

0226 Act receipt of 780922 itr re-corrective steps taken on e of mancompliance found in inspec es notified by NRC of 780825.
LLLYJP, Region 2, Atlanta, Office of the Director, 78/10/06. 94165:093.

230227 Responds to 780828 NRC ltr re violations noted in Inspec 14480-259/78-18.850-260/78-19.850-296/78-17. LLELAND.J.E. Tennesses Valley Authority. 78/09/22. ip. 165:094. 7810230300 Forwards IE Circular#78-17 (See ANO 7810230221.Docket 50-313.781013)
O'RETILLY.J P Region 2: Atlants: Office of the Director. 78/10/13. 10. 94164 103

O'REILLY. JP Region 2. Atlanta. Office of the Director. 78/08/25 3p 94165 095

78-17 on 780726-28

ASIONRY FOLMETOR IE TUBBEC MEDIRADI-NDANNE-18' ADA-NGALIA' ADA-KADA

- 7812040322 Forwards 16 Inspec Rept#50-260/78-24 on 78091-22 during which no items of honcompilance were noted.
  KENNA.H.B. Region 2. Atlanta. Sefeguarde Branch. 78/10/23 2pp.
- --7812040325 IE Inspec Rept#50-260/78-24 on 780920-22 during which no items of noncompliance were noted. Major ereas inspected inclifacii organization, shipping & receiving, storage & internal control, inventory, records & repts.

  HDD0EB, J. W. Region 2- Atlanta, Safeguards Brench. 78/10/23. 3pp. 94121 349
- 7812050053 Forwards IE Inspec Repts#50-259/78-21.#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94334.218.
- --7812050037 IE Inepec Repte#50-259/78-21.#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no item of moncospilence were noted He jor areas inepected inclineportable occurrences & Followup on IE bulletine & circulars.
  SULLIVAN.R F. OUZTS.J.E. Region 2. Atlante. Office of the Director. 78/10/26 10pp 94334:220.
- 7811150073 Forwards IE Circular 78-18.

  O'REILLY.J P Region 2. Atlanta. Office of the Director. 78/11/06.
- 7812210355 Forwards IE Inspec Repte#30-259/78-26.#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted.

  KENNA, H. D. Region 2. Atlants. Sefequends Branch. 78/11/08. 2pp. 94014:353.
- --7812210363 IE Inepec Repts#50-259/78-26. W50-240/78-29 & W50-296/78-25 during which no liters of noncompliance were noted. Major areas inspected incl. Physical security requirements previous liters: alerm. access.co.munications.
  BEECKERIK M. W. GILLESPIE.F.P. Region 2. Atlenta. Safeguards Branch. 78/11/08. 4pp. 94014:335.
- 7812180323 IE Inspec Repts#50-239/78-25.#50-260/78-28 & #50-296/78-24 on 780923-27 during which no items of noncompliance were noted, Major ersee inspected incl: refueling plant oper & LER & IE Circulere/Bulletins review BULLIVAN,R F., DANCE,H.C. Region R. Atlante, Reactor Operations Nuclear Bupport Branch. 78/11/09. 6pp. 94356:287.
- 7812130372 Forwards amended response to IE BulletinW78-09, describing eteps taken to effect a good seal between drywell head to containment flenge.

  GILLELAND, J.E. Tennessae Velley Authority. 78/11/13. 2pp. 94292: 125.
- 7811220087 Act receipt of 781102 itr informing NRC of steps teken to correct violations noted during inspec#50-260/78-22.
  LONG, F. J. Region 2. Atlants. Rescitor Operations Nuclear Support Branch. 78/11/13 1p. 74273:267.
- --7811220091 Responde to 781010 NRC ltr re violation noted in Inspec Rept #80-280/78-22. Corrective actions: Tech Spec change to be requested re calibr requirement & ell changes for refueling test instr to be properly documented.

  OILLELAND, J. E. Tennessee Valley Authority. 78/11/02. 19. 94273: 270.
- --7811220093 Forwards IE Inspec Rept#50-260/78-R2 on 780815-18 & Notice of Violetion.
  LCNO.F.J. Region 2. Atlanta, Resector Operations Nuclser Support Branch. 78/10/10. 2pp. 94273:271.
- --7811220095 Notice of Violation from inspec on 780915-18.

  \* Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/10/10. 19. 94273:275.

- --7811220099 IE Inspec Rapt#30-260/78-22 on 780815-18 during which 2 items of noncompliance were noted failure to adhers to all qual requirements for GA records & to all requirements for survesiliance instru content VOOT-LOWELL, R. MARTIN, D. Region 2. Atlanta, Reactor Operationa Nuclear Support Granch 78/10/10. App. 94273:276
- 7812040359 Forwards 1E Bulletin478-12A.suppl to 16 8ulletin 78-12. W/encl AND.7811300055. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 78/11/24 16. 94127-177.
- 7812060015 Act receipt of 781122 ltr informing NRC of steps taken to correct violations noted during inspects0-259/78-22, #50-260/78-25 & #50-296/78-21 SUTHERLAND.J.T. Region 2, Atlanta, Fuel Fecility & Meteriele Befety Dranch, 78/11/28, lp 94418:339.
- --7812060021 Responds to 781027 NRC itr re violetions noted in Inspec Rept#50-259778-22.#50-260778-23 & #50-296778-22 Corrective actions, surveillance instruc sched change to reflect 18 month testing req. OllELAND.J. E. Tennesses Valley Authority, 78/11/22. 3pp. 94418: 339
- --7812060026 Forwards IE Inepec Rept#50-259/78-22.850-260/78-25 & #50-296/78-21 on 780911-14 & Notice of Violation.
  SUTHERLAND.J. T. Region 2, Atlanta. Fuel Fecility & Materiele Safety Branch. 78/10/27 2pp. 94915 312
- --7B12060030 Notice of Viciation from inspec on 780911-14.

   Region 2. Atlanta, Office of the Director. 78/10/27. ip 74415:314.
- --7812060033 IE Inspec ReptH50-259/78-22, H50-260/78-25 & H50-296/78-21 on 780911-14 during which I item of noncompliance was noted: survaillence testing of air cleaning eye TROUP.9 L. JACKBON.L L. 61880N.A F. Region 2. Atlanta. Office of the Director. 70/10/27 9pp. 94415:315.
- 7832280014 Forwarde 18 Bulletin 78-14. O'REILLY, P. Region 2. Attenta, Office of the Director. 78/12/19. 2PP. 94131.022.
- R. Periodic operating reports & relates correspondence
- 7810160106 Forwards Monthly Oper Rept for Bept 1978.
  DEMEASE, J. G. Tennessee Valley Authority. 78/10/10. 1p. 94004:281.
- ~-7810150109 Monthly Oper Rept for Sept 1978.
  DEMEASE, J. G. Tennesses Valley Authority. 78/09/30. 34pp. 94002; 087.
- 7810170161 Monthly Oper Rept for Sept 1978.
  DEWEASE.J 0 Tennesses Veiley Authority. 78/10/31. 31pp. 94236:097
- 7B10300103 Files fish impingement rept for subj facil for 3rd quarter 1978
  OILLELAND, J.E. Tennesese Valley Authority. 7B/10/19 14pp.
- 7811140137 Farwards Monthly Open Rept for Oct 1978.

  DEMEASE, J. O. Tennesses Valley Authority. 78/11/09. 1p. 94425:275.
- --7811140140 Monthly Oper Rept for Oct 1978. OREEN, D. Tennessee Valley Authority. 78/11/02. 33pp. 94423:276.
- 7812190161 Forwards Monthly Oper Rept for Nov 1978.
  DEWEASE, J. G. Tennessee Valley Authority, 78/12/02. 1p. 94340:180.
- --7812190162 Monthly Oper Rept for Nov 1978, DEMEABE, J Q Tennessee Valley Authority, 78/12/02, 29pp. 94340.181.
- S. Reportable occurrences. LERs & related correspondence
- 7810250035 Reportable Occurrence #50-260/7816 on 780930:During routine inspec of degusi1 several pipe cracks were found, probably caused by vibration. (Revision#i)
  DEMEABE, J. G. Tennassee Velley Authority. 78/10/05. 2pp.
- 7810180138 Forwards LERM78-016/017-0.

- --7810180142 LER#78-016/017-0 on 780930: discovered 1 inch instru line to Pdt-68-82 & s 3/4 inch bonnet vent line on FCV-68-1 were cracked & leaking Exact cause unknown.

  Thinesse Velley Authority. 78/10/13. 1p. 94368:314.
- 7810300168 Forwards LERW78-017/03L-0. FOX:H S Tennessee Valley Authority. 78/10/25. 1p. 94034:131.
- --7810300171 LER 78-017/03L-0 on 781004: drywell oxygen concentration was not reduced to 4% w/in 24-hour period after placing reactor in run mode due to personnel effety considerations during repair of inner drywell eir lock repeirs.

  \* Tennessee Valley Authority. 78/10/25 2pp. 94034:132.
- 7812070264 Notification of 781116 abnormal occurrence. Betpoint on main steam line radiation monitor nonconservative. Caused by reduced radiation level background in main steam line tunnel due to Cycle 2 reload.

  DEWEASE.J. G. Tennessee Valley Authority. 78/11/17. 1p. 03555:018.
- 7811280201 Forwards LERW78-019/017-0 FOX:H S Tennessee Valley Authority. 78/11/24. 1p. 94013:259.
- --7811280203 LER#78-019/01T-0 on 781114: during normal oper.main stess line radiat monitors RM-90-135.-136,-137 & -138 were found less conservative then allowed by T.S. 3. i. A. Caused by decrease in background from cycle 1 to cycle 2 fuel.

  \* Tennessee Valley Authority. 78/11/24. 2pp. 94013:260.
- 7812080101 Forwards LERW78-018/03L-0. FDX-H.S. Tennesses Velley Authority. 78/12/04. 1p 94107;289.
- --7812080103 LERW78-018/03L-0 on 781103; reactor pressure switch P8-58-96, switch i failed to operate during survaillance testing Switch exercised & adjusted.

  \* Tennesses Valley Authority. 78/12/04. 2pp. 94107:290.
- 7812120174 Forwards LER 78-020/03L-0. FOX.H. 9. Tennesses Valley Authority. 78/12/07. 1p. 94276:009.
- --7812120177 LER#78-020/03L-0 on 781110; during normal pur oper.Resctor & Turbine Bidg & Refusling Zone Ventilation Exhaust Monitor. RM-90-230 became inoperable.Instr & its sensing line dried out & returned to svc.

  \* Tennesses Valley Authority. 78/12/07. 2pp. 94276:010.
- 7812290221 Forwards LER#78-021/03L-0. FDX.H 8. Tennesses Valley Authority. 78/12/21. 1p. 94191:190.
- --7812290224 LERW78-021/03L-0 on 781201; suppression chamber hydrogen monitoring sus feiled to meet Tech Spec requirements, Coused by low signal output of torus hydrogen sensor.

  \* Tennesse Valley Authority. 78/12/20. 2pp. 94191:191.

# DOCKET 50-261 H. B. ROBINSON PLANT. UNIT 2

- F. Security, medical, emergency & fire protection plans
- 7810270147 Responds to 780313 request for add1 info on Fire Protec. Requests delay in responding to item 8(Lube 0il 8p11) Control 8ys for Reactor Coolant Pumpeluntil 781201 due to late arrival of design info.
  UTLEY.E.E. Caroline Power & Light Co. 78/10/20. 1p. 94037:007.
- 7811270136 Forwards NRC staff position & request for add1 info re subj facil Emergency Plan. Requests submission of rev plan w/in 90 days.

  8CHENCER, A. Departing Resectors Branch 1 (Pre 790625). 78/11/09.
  5pp. 94271:309.
- 7812110133 Forwards edd1 info re fire protec prog for subj facil in response to items#8,#12 of NRC 780313 itr. Info covers lube oil spill control sys for reactor coolant pumps & flame reterdent coatings.

  UTLEY.E.E. Caroline Power & Light Co. 78/12/05. 4pp. 94339:357.

### Q. Adjudicetory correspondence

781214006; NRC Staff is directed to Furnish ABLB & Other parties in proc w/current etatue of final suppl to SER Staff is also directed to furnish Bd & all perties w/deteiled etatus rept of any devs in case once each month.

WCLF.J.F. Atomic Sefety and Licensing Board Panel. 76/12/05. 299-94127:326.

# J Insurance & indomnity information

- 7812190118 Forwards ltr of 781214 to NRC edvising that funds have been transferred to NRC in amount of \$26.400 to cover indemnity fee for LickSPR-23 Requests refund resulting from reduction of indemnity fee.
  LANCASTER. J L. Caroline Power & Light Co 78/12/14 ip. 94374.280
- --7812190123 Advises that funds have been transferred to NRC in amount of \$25,400 to cover indemnity fee for LicADPR-23 NRC invoice not enc!
  LNNCASTER, J L. Carolina Power & Light Co 78/12/14 iP.

# P Operating license stage documents & correspondence

- 7810110108 Requests submittal data for Flams Retardant Coatings by sitended to 781201 in reply to 780313 ltr
  UTLEY.E.E. Cerolins Power & Light Co. 78/10/05. ip. 94066:354.
- 7810310233 Forwards Ambnd 34 to Liceboo DPR-23 safety evaluation & notice of issuance. BCHENCER. A Operating Reactors Branch i (Pre 790625). 78/10/06. 2p. 74091 001.
- --7810310237 Amend#34 to Lic MDPR-23 changing Tech Spec re containment spray additive valves & refueling water storage tank outlet velve test requirements.

  8CMMENCER, A. Operating Reactors Branch ( Pre 790625) 78/10/06.
  4pp. 7409:003.
- --7Biddi024: Sefety Evaluation supporting Amend G4 to License DPR-03

  \* Operating Reactors Branch : (Pre 790625) 78/10/06 Opp.
  94091:007.
- --7810310346 Notice of issuance of Amend 04 to Literas DPR-23. SCHENCER, A. Operating Reactors Branch i (Pre 790625) 78/10/06 3pp. 94091:010
- 7810200196 Forwards Amend#33 to Fecil Oper Lic#UPR-23 for subj Pacil revising tech space as requested in 780813 ltr.w/Notice of lesuance.

  8CHENCER.A. Operating Reactors Brench ( Pre 790625) 78/10/10.
  3pp.
- --7810200199 Amend #33 to Pacil Open LichtpR-23 revising tech specs re CPI organizational changes. Wencl resease of tech spece SCHMENCER. A Departing Reactors Branch 1 (Pre 790625). 78/10/10. 847pp.
- --781020020) Notice of Issuence of Amend#33 to Facil Oper Lic#DPR-93. BCHMENCER.A. Operating Reactors Branch 1 (Pre 790623). 78/10/10. Spp.
- 7811210273 Nutifies util of 781205 asminer in Atlants to discuss new Model Rod Effluent Tach Specs & encl seminer info sheet, replatration form, a proposed agends.

  D'REILLY, J. P. Region 2, Atlants, Office of the Director 78/11/09. Spp. 94485:162.
- 7811290406 Forwards NRC staff paper, policy esseion item (SECY-78-554) reliceness reg performence eval. Three methods for evel are: statistical, trend enalysis & regional survey method. W/o encl. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/11/15. App. 94180:099.
- 7BIRIBO033 Nutice of workshops is implementation of training & qual requirements contained in Append B of lOCFR73. Requests pre-workshop registration of attendees to facilitate sending out math. W/enci Registration Form & List of Locations. MILLER, J. R. Assistant Director for Bits & Bafaguards (Pre 791030). 7B/11/15. 5pp. 94133:014.
- 7812190023 Forwards Rev#i "Dreft Radiological Effluent Tach Space" for PHR's(MUREO-0473) & "Preparation of Radiological Effluent Tach Space for Nuc Per Plante" (NUREO-0133).
  ORINES, 8.8, Assistant Director for Engineers & Projects (Pre 790625) 78/(1/15. App. 94214:306.
- 7812150064 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests atther commitment to limit purging or justification for continuing. W/enc1 ANO: 7812080207. SCHMENCEN. A. Operating Reactors Brench i (Pre 790625). 78/11/28.6pp. 94210:145.

- 7812290144 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantiated by date & calculations Licenses must notify NRC of any inaccuracies or enforcement action will result DAVIS.J C. Office of inspection & Enforcement. Office of the Director 78/12/06 2pp 94133 228
- G inspection reports. IE Bulietins & correspondence
- 7810260063 Forwards IE Inspec Rept#50-261/78-20 on 780807-10 during which no items of honcompliance were noted BUTHEROLAND.JT Region 2. Atlanta. Fuel Facility & Materials Safety Branch 78/09/15 2pp. 94392 320
- 7810260067 IE Inepec Repte30-261/78-20 on 780807-10 during which ho items of noncompliance were noted Hajor areas inspected included radiological solviron monitoring prog. mgt controls & inspec of environ monitoring stations.
  PEERY, W W , HUFHAN, J. W. Region 2, Atlante. Fuel Facility & Materials Safety Branch 78/09/12 4pp 94392:316
- 7810310138 Forwards IE Inspec ReptH50-261/78-19 on 780807-10 during which no items of noncompliance were noted LONG,F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Dranch 78/09/19. 2pp. 94090 160
- --7810310144 iE Inspec Rept#50-261/78-19 on 780807-10 during which no items of noncompliance were noted Mejor srees inspected included, training progs for nonlicensed personnel & operator requel prog KELLOQQ,r J., BRADFORD.W H. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/09/19. 3pp. 94090-162
- VB11080286 Forwards 1E Inapsc Rapt#50-261/78-21 on 780822-29 during which no items of honcorpliance were noted LONG.F.J. Region 2. Atlanta. Resctor Operations Nuclear Support Branch 78/09/27. 2pp. 94406-189.
- --7811080289 IE Inspec Rept#50-261/78-21 on 700822-25 during which no items of noncompliance were noted. MCHENRY.T.J. Region 2, Atlante. Reactor Operations Nuclear Support Branch. 78/09/26 app. 94406-191
- 7810110225 Act receipt of 780913 itr informing NRC of steps taken to correct violations noted during image:e30-261/70-15 LONG-F.J. Region 2. Atlanta. Resctor Operations Nuclear Support Branch. 78/09/20 ip 03395.287
- --PBIOL1022P Responds to 200817 NRC its re violation noted in Inspec Repts#80-261/7B-ID Corrective actions interlock sys tested when modification completed. Checkout procedure to be implemented. FURR.B. J. Caroline Power & Light Co. 78/09/13 2pp. 94062-169
- --7810110231 Forwards 1E Inspet Repis#50-261/78-15 on 780705-07 & Notice of Violation LCNO.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 78/08/17 Spp. 94062:171.
- --7810110233 Notice of Violation from inspec on 780705-07

  \* Region 2- Atlanta Reactor Operations Nuclear Support Branch, 78/08/17

  19. 94062:173
- --7810110236 IE inspet Rept(#1850-261/78-15 on 780705-07 during which item of noncompliance was noted no tests of interlock eys since mod MARTIN.R.D., BURNETI,P.T. Region R. Atlante, Reactor Operations Nuclear Support Branch. 78/00/15 4pp. 94062:174.
- 7810230013 Act receipt of 781002 ltr informing NRC of eteps taken to correct violetions noted during inspect90-261/78-17. LONG,F.J. Region 2. Atlenta. Reactor Operations Nuclear Support Branch. 78/10/11. ip. 94169:193.
- --7810230020 Responds to 780908 NRC ltr re violations noted in Inspec Rept#50-261/78-17. Corrective actions, revisu of periodic tests & operating procedure checklists & grag to insure compliance w/latest rev will be dev by 781231. BANKS, H.R. Caroline Power & Light Co 78/10/11 2pp. 94169: 194.
- --7810230023 Forwards IE Inspec Rept#50-261/78-17 on 780801-04 & assoc Notice of Violation. LCN0.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/08. 2pp. 94169.196.
- --7810230025 Notice of Violation from inspec on 780801-04.
  \*\* Region 2, Atlanta, Office of the Director. 78/09/08. Ip. 94169: 198.

- --7810230027 IE Inagec Rept#50-261/78-i7 on 78080i-04 during which I than of noncompliance was noted failure to dist &/or use Current revs of plant procedures

  \* Region 2: Atlanta: Office of the Director. 78/09/08. 3pp. 94169:199
- 7810230366 Forwards 16 Circular#78-17. (See ANO.7810230221.Docket 50-133.7810131 D'ÆEILLY, J.P. Region 2. Atlants. Office of the Director. 78/10/13. 1p. 94169-165.
- 7811220254 Forwards IE Inspec Rept#50-261/78-22 on 780912-15 during which no items of noncompliance were noted LONG, F.J. Region 2. Atlants, Reactor Operations Nuclear Support Branch. 78/10/16. 2pp. 94379:318
- --7811220256 1E Inspec Rept#50-261/78-22 on 780912-15 during which no items of noncompliance were noted Hejor press inspected incl: inspec of followups of licenses event-noncompliance, headquarters request/IE Circulars
  HOHENRY, T. J., DANCE, H. C. Region 2. Atlanta, Office of the Director 78/10/16 5pp. 94379.320.
- 7810310122 Transmits Inservice inspec prog for pump & velve testing & weld inspec progs. Also transmits 3 copies of renaining revisive drawlings not submitted during 780822 & 23 meetings. Encl evallable in CF only.

  UTLEY.E E Caroline Power & Light Co. 78/10/25 2pp. 94090:027.
- 7812070301 Forwards IE Insps: Rest450-261/78-23 on 781002-06 & Notice of Violation.

  BUTHERLAND, J. T. Region 2. Atlanta, Fual Fecility & Materials Sefety Branch. 78/10/30. 2pp. 94355:329.
- --7812070309 Natice of Violation from Inspec on 781002-06. \* Region 2, Atlante: Fuel Facility & Materials Safety Branch. 78/10/20 ip. 94355:331.
- ---TBIRO70312 IE Inspec Rept#50-261/78-23 on 781002-06 during which 2 items of noncompliance were noted exposure greater than 5(N-18) & Fallure to survey wests drums for contemination prior to shipment.

  GIBSON, A.F., JENKINS-O.R. Region 2, Atlants, Fuel Facility & Meterial & Bafety Branch 78/10/30. Spp. 94355:332.
- 7812060288 Forwards IE Inspec Rept#50-261/78-25 on 781017-19 during which no items of noncompliance were noted. KENNA-H.B. Region 2. Atlente. Sefeguerds Branch. 78/11/01. 2pp. 94372; 307.
- --7812060293 IE Inspec Rept#50-161/78-25 on 781017-19 during which no items of noncompliance were noted. Hejer areas inspected incl:11c's physical protec prog as implemented by approved security plan.

  DAVIB. C. L. Region 2, Atlanta, Sefeguerds Branch, 78/11/01. 3pp. 94372:309.
- 78i1150087 Forwards IE Circular 78-18.
  D'RELLLY, J.P. Region 2. Atlanta, Dffice of the Director, 78/11/06.
  Tp. 94i13:199.
- 7812150037 Forwards 1E Inspec Rept#30-261/78-24 on 781003-06 during which no items of noncompliance were noted.

  LONG F.J. Region 2, Atlenta, Reactor Operations Nuclear Bupport Brench. 78/11/07. 2pp. 94210:235.
- --7812180062 IE Inepec Rept#50-261/78-24 on 781003-06 during which no items of noncompliants were noted Mejor areas inspected inclinavisus.audits. IE Bulletin & licenses event followup & itemses extion on previous inspec repts.

  MCHENRY,T J. SELIBLE.Q.A., DANCE,M.C. Region 2, Atlente, Resctor Operations Nuclear Support Brench. 78/11/07. 7pp. 94210:257.
- 7811170127 Refers to 780912 CPL ltr re review of velves for pressure isolation function:concludes that ell sus whigh to low pressure interface have enough overpressurization protects that velves do not need to be recetagorized & leek test. UTLEY.E.E. Ceroline Power & Light Co. 78/11/09. ip. 94048:290.
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Newsletter. KENNN, M. B. Region 2, Atlente. Befeguards Brench. 78/11/17. 4PP. 94277:003.
- 7812040359 Forwards IE Bulletin#78-12A suppl to IE Bulletin 78-12. W/encl AND:7811300055. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24, 5pp. 94127:142.

- 7812070039 Ack receipt of 781106 ltr informing NRC of steps taken to correct violations noted during inspec#50-261/78-18
  SUTHERLAND.J.T. Region 2. Atlants. Fuel Facility & Meterials Sefety Branch 78/11/28. 1p. 94344.303
- --7812070065 Responds to NRC 781011 ltr re violation noted in Inspec Rept #30-261778-18 Corrective actions batteries were removed from instruments & porper number of respirators were restored. FURR B J. Carolina Power & Lipht Co 78/11/06. 2pp 94244:304
- --7812070069 Forwards IS Inspec Rept#50-261/78-18 on 780807-11 & Notice of Visittion.

  BUTHERLAND. J T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch 70/10/11 2pp. 94344 306
- --7812070074 Notice of Violation from inspec on 780807-11, 4 Region 2. Atlante, Office of the Director, 78/10/11, 1p. 94344:308.
- --T812070075 iE inspec Rept#50-261/78-18 on 780807-11 during which I lied of honcomplience was noted plant access emergency sit had survey instrument w/batteries left in & hed the wrong number of respiretors.

  PERROTTI.D J., HUFHAM, J.W. Region 2. Atlenta, Fuel Fecility & Meteriels Sefety Brench. 78/10/11. 18pp. 94344:309
- 781213024) Ack receipt of 781127 itr informing NRC of steps taken to correct violations noted during inspec#30-261/78-23.

  8UTHERLAND.J.T. Region 2. Atlents. Fuel Fecility & Meteriels Safety Brench. 78/12/07 tp. 94336-098
- --TRIRIBORDI Responde to NRC 781030 ltr re violation noted in Insp. Rept 50-261/78-23 Corrective ections: redicactive control personnel instructed in drum exterior smarr procedure on 781005.
  BANGH.R. Carolina Power & Light Co. 78/11/27. 2pp 94336:099
- 7812290081 Forwards IE Bulletin 78-14.

  O'REILLY, J. P. Region 2. Atlente, Office of the Director. 78/12/19.

  Zpp. 03693:204
- R. Periodic operating reports & related correspondence
- 7810190270 RD: on 781003, both containment spray pumps were inoper due to eir binding Event placed containment spray eys in condition less conservative than less transarvative aspects of section 3.3.2.1. b of Tech Specs.

  BTARKEY, R. B. Caroline Power & Light Co. 78/10/04. ip. 94052:013.
- 7810160147 Forwards Monthly Oper Rept for Bept 1978.

  BANKS, H. R. Ceroline Power & Light Co. 78/10/10. 1p. 94001:330
- --7810160149 Monthly Open Rept For Sept 1978. WATFORD M.L. Caroline Power & Light Co. 78/10/03 4pp. 94001:351.
- 7811160119 Forwards Monthly Oper Rept for Oct 1978.

  BANKS.H.R. Caroline Power & Light Co. 78/11/09. 1p. 94135:174.
- --7811160120 Monthly Open Rept for Oct 1978. WATFORD, M.L. Carolina Power & Light Co. 78/11/02. 4pp. 94135-175.
- 7812010232 Forwards corrected peges#12 & 14 to Semi-ennual Effluent & Waste Disposel Rept for 780101-780630.

  BANKS, H. R. Ceroline Power & Light Co. 78/11/21. 4pp. 74409:339.
- 7812150348 Forwards Monthly Oper Rept for Nov 1978.

  8ANKS.H.R. Ceroline Power & Light Co. 78/12/11. ip. 94418:132
- --7812150351 Monthly Oper Rept for Nov 1978. WATFORD.M.L. Caroline Power & Light Co. 78/12/06. Spp. 74418:133.
- 9. Reportable occurrences, LERs & releted correspondence
- 7810100048 LERM79-022/03L+O on 780901: momentary loss of 480 volt 3 phase AC pur to MCC-5 occurred due to decreasing spring tension in knife blade contact of safety switch. Switch to be replaced by 2 cirulot breakers.

  BTANKEY, R. B. Carolina Power & Light Co. 78/10/02. 3pp. 94032:183.
- 7810100043 Forwards LER#78-021/03L-0. BANKS.H.R. Carolina Power & Light Co. 78/10/02. 19. 94032:182.

- 7610270215 Forwards LER#78-026/01T-0.
  BANKS-M.R. Carolina Power & Light Co. 78/10/16. 2pp. 94053:229.
- --7810270226 LER#78-026/017-0 on 781003 During normal oper "A" & "B" containment spray pumps failed to meet the Delta P requirement dus to air bining Pumps vented at 2150 making them oper.

  BTARKEY.R.B. Caroline Power & Light Co. 78/10/16 ip. 94053:230.
- 7810310123 Forwards LERM78-022/03L-0. FURR.B.J. Carolina Power & Light Co. 78/10/20. ip. 94090:126
- --781C310127 LER 78-022/03L-0 on 780921 during full pur oper a primary to secondary leak use detected in A Steam Cenerator of 0.620PM.

  Caused by fetture of 2 steam generator tubes.

  BTARKEY, R B. Carolina Power & Light Co 78/10/20. 2pp.

  74090:127.
- 7810310143 Forwards LERN78-023/03L-0.

  BANKS, H.R. Carolina Power & Light Co. 78/10/23. ip. 94090:171.
- --7810310133 LERW78-023/03L-0 on 780722. While proceeding from hot to cold shubdown the concentration of boric acid storage tenk B was 22796PPM, due to insufficient sampling during batching & tenk A level was low as result of borating the RCS.

  STARKEY, R. B. Cerolina Power & Light Co. 78/10/23. 2pp. 94090:172.
- 7810310219 LER #78-024/03L-0 on 781001: engine-driven fire water pump failed to start due to moisture in distributor cep. Ceused by heavy rains & access door being lieft open. Moisture removed & engine test eterted w/eatiefectory results on 781006.

  STARKEY, R. B. Caroline Power & Light Co. 78/10/25. 2pp. 94090: 324.
- 7811090186 Forwards LERM78-025/03L-0.
  BANKB, H.R. Carolina Power & Light Co. 78/11/01. 1p. 94038: 233.
- --7811090191 LERe78-025/O3L-O on 781003: during normal oper PPS leakage past Containment Purge Outlist isolation valve 50-FR was in excess of Tach Spec limits due to normal wear of Nordal rubber seat.

  BIARKEY, R. B. Carolina Power & Light Co. 78/11/O1. 2pp. 94038:234.
- 7812140163 Forwards LERW78-027/03L-0.
  BANKB,H.R. Caroline Power & Light Co. 78/11/11. lp. 94133:306.
- --7812140165 LERM78-027/03L-0 on 781109: w/reactor at full pur, instrair supplies to RHR flow controls vaives RHR-605 kRHR-738 were not isolated as require to deficiency in procedure 0P-38-C & misunderstanding by operator signing off procedure. BTARKEY.R.B. Caroline Power & Light Co. 78/12/11. 3pp. 9413-307.
- 7812270257 Forwards LER#78-029/01T-0. BANKS, H.R. Caroline Power & Light Co. 78/12/19. 1p. 94168:059.
- --7812270263 LER#78-029/017-0 on 781205; determined that 781128 Reactor Protec 8ye reley fellure was potential generic problem. Relay was stuck in energized position due to thermal deterioration of epoxy adhesive used in manufacture. STARKEY, R.B. Cerolina Power & Light Co. 78/12/19. 3pp. 94169:060.
- 7810310210 Forwards LER W78-024/03L-0.
  BANKS, H. R. Carolina Power & Light Co. 78/10/25. 1p. 94090: 323.

## V. Operator Examinations

- 7810170110 Senior Operator Lic#SDP-1426-4 for R.E.Morgan to direct the lic activities of lic operators & to manipulate all controls of subj facil, Lic#DPR-23.

  CQLLINB,P.F. Operator Licensing Branch. 78/11/16. 10.
- 7810180170 Operator Lic#OP-2866-4 for James I Murray to manipulate ell controls of subj facil.Lic#DPR-23 COLLING.P.F. Operator Licensing Branch. 78/11/16. ip. 94317:099.

- DOCKET 30-263 MONTICELLO NUCLEAR GENERATING PLANT
  F. Security, medical, margancy & fire protection plans
- 78:01:60122 Describes plan for isolation of reactor bidg fire suppression water for installation of new hose stations. Details corpensatory protec measures for the 10 hours the sys will be disabled MAYER.L.O. Northern States Power Co. 78/10/10. ip 94005:192
- 7811140194 Forwards responses to NRC Staff recommendations re-subj facil fire protec prog resulting from NRC inspet during week of 780731 & conteined in NRC itr of 780905 NBP intends to resolve all NRC concerns by 781231.

  MAYER, L.O. Northern States Power Co. 78/11/07 10pp 94384: 283
- 7812030045 Forwards fire protect info from 780731-780804 meeting, Incl
  list ofettendese.summery items NSP agreed to complete in
  response to NRC steff concerns.concerns discussed at meeting
  but not resolved & open items
  IPPOLITO. I A. Operating Resolves Branch 3 (Pre 790625). 78/11/24
  26pp. 94334-122

# Q. Adjudicatory correspondence

- 7810230337 Requests briefs from ell parties re issuance of e full-te ilc for subj fecil pending resolution of enticipated translents w/out screm(ATHB) design Briefs must be filed w/in 30 days of svc of this Order. LAZUR.M. Atomic Befety and Licensing Board Penel. 78/10/13. De 74167:043.
- 7811070284 Forwards memos re recent problems in pipe support base pl design. (ANO 7811020332, 7811020336. & 7811020343 ) LEWIS.8.H. Office of the Executive Legal Director. 78/10/24. 1p 94040: 326
- 7811130002 Forwards 780929 mamo re results of recent fire protect test conducted at Underwriters Lab (See ANO.87810030339, 97810050373) LEHIS.8.H. Office of the Executive Legal Director. 78/10/24 Ip
- 7812050050 NRC Steff request for extension of time re preparation of rept of staff views on implications of & requirements for protec against ATMS for operating nuc pur plants, KARMAN.H. Office of the General Counsel. 78/11/09. 3pp. 94334:211.
- 7812130149 Forwards 781017 memo re post-LOCA bydrogen production Promatis inside containment.

  KARMAN.M. Office of the Executive Legal Director. 78/11/22. 1p. 94299:063
- 7812260044 Request & Motion for Order Prohibiting the installation of Defective Spent Fuel Storage Recks in Violation of Provisional Oper Lic. Request to Institute a proc & Petition for Leave to Intervene Cert of Svc encl. STENSVAQ. J.M. OLSON. J.F. Minnesota Poliution Control Agency. 78/12/08. Dipp. 94021:001.
- --7812260037 Motion of MN Pollution Control Agency is granted & lic is ordered to ceese & deelst from further installation of any spant fuel storage rack at subj fecil pending further order.

  • Atomic Safety and Licensing Board Panel. 78/12/15. 3pp.

### H. General correspondence

- 7812270018 Responds to 781109 ltr expressing concern re fuel rack ewelling at subj facil.Forwards OE Topics: Rept NEDD-24076. W/o encl. iPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/010
- ---7812270023 Expresses concern over fuel rack swelling at subj faci Requests OF Rept NEDO-24076 & NRC SER. QARDEBRING, S. B. Affiliation Unknown, 78/12/09, ip. 94159: 13

#### I. Financial information

7810300156 Forwerds 1977 Annual Rept & schedule showing 1977 actual Cash Flow to comply with Reg Guide 9. 4. Net income by dividents declared inetead of dividends paid has been reduced to get retained earnings figure.

CARLEON, L. R. Northern States Power Co. 78/10/23. 2pp. 94034: 1

- 7810170099 Responds to 780807 NRC request for surveillance & info re Reactor Protec Sie Per Supply Design Final details on any facil or spec mod will be submitted by 79020) when studies are complete MAYER, L. D. Northern States Power Co. 78/10/12, 3pp. 94270:089.
- --7810170262 States that 781012 util response to NRC re Reactor Protec Bys Pur Supply contains no restricted or defense theo. WACHTER, L. J. Northern States Power Co. 70/10/12. 1p. 94270:092.
- 78:0230076 Notifies that starting about 78:20: Co will begin to use shipping cask CNST 14-193H(UBA/7094/A) MAYER, L. O. Northern States Power Co. 78/10/12. 1p.
- 7810200078 Mark I Containment Prog--Gen Elec Rept "NEDE-21685-P.Merk I Downcomer Reduced Bubmergence-Functional Assessment Rept' has been transmitted to NRC by Gen Elec via L.U. Sabon's ltr to V. Stello 703802. Rept deals w/tech bases re use 3 ft min. MAYER.L. D. Northern Stetse Power Co. 78/10/13. 1p. 9436:341.
- --7010200080 Forwards ltr which covers submittal of info requested by NRC recontainment design of Mark 1. Request contains no restricted or other defense info.

  WACHTER, L. J. Northern States Power Co. 78/10/13. 19. 94366:342.
- 7810300145 Notifies NRC of high leakage rates for reactor water cleanup sys isolation valves during local leak rate testing on 761020,781021, & 781022, tauee for which is under investigation. ELIASON, L. R. Northern Statue Power Co. 78/10/23. 1p. 94035:126.
- 7811130335 Summary of 780914 meating w/GE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance 11st & agenda(RD-9-A-Mark), Standards.) GRINES, C. Plant Systems Branch (Prs 791030), 78/10/26. 67pp.
- 7811220138 Forwards Amend#36 to Provisional Operating Lic#OPR-22. which changes Tech Space re limiting conditions for oper & surveillance reg for suppraesson pool water level. 1PPCLITO.T.A. Operating Reactors Branch 3 (Pre 790623). 78/10/30. 8pp. 94074: 225.
- --7Bi1920140 Amend#36 to Provisional Operating Lic#DPR-92, which changes Tech Bpecs re limiting conditions for oper k surveilisate req for suppression pool water level. W/encl rev Tech Bpsc. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/30. 94074: 227. lBpp.
- ---7811220143 Safety Eval Rept Supporting Arend#36 to Lic#DPR-22. States that issuance of amend will not be inimical to the common defense & sacurity or to pub health & eafsty.

  # Office of Nuclear Reactor Regulation, Director. 78/10/30. 4pp. 94074: 245.
- -- 7811220144 Notice of Issuance of Amend#36 to Provisional Operating Lic Operating Reactors Branch 3 (Pre 790625). 78/10/30. IPPOLITO, T. A. 2pp. 94074:249.
- 7811270100 Forwards Amend#37 to Provisional Lic#DPR-92.changing Tach Base to improve simmer margin of sefety/relief valves. Operating Reactors Branch 3 (Pre 790625). 78/11/06. IPPOLITO, T. A. 94240: 339.
- --7811270103 Amende37 to Provisional Oper LiceDPR-92, changing Tech Specto Improve simmer margin of safety/relief valves.

  ORIMES. B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/06, 33pp. 94223:249.
- --7811270106 Safety Eval supporting Amend#37 to Provisional Oper Lic #DPR-22, Concludes issuence of emend will not be inimical to nation or people. # Office of Nuclear Reactor Regulation, Director. 78/11/06. 10pp. 94223: 202.
- --7811270:10 Notice of Issuance of Amand&37 to Provisional Oper Lic &DPR-22 changing Tach Spec to improve simmer margin of efety/reliaf valves. IPPOLITO\_T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/06. 2pp. 94223:292.

- 7811210307 States that Sechtal has discovered a problem in the s analysis computer prog that analysed subj facil piping bys. Recommends adding one & modifying two restraints on the RHR section piping.
  - Northern States Power Co. 78/11/13. Ip. 94488 ELJABON, L. R.
- 7812130135 Notice of workshope re implementation of training & q requirements contained in Append B of 10CFR73 Requeste pre-workshop registration of attendess to facilitate sending out math W/ench Registration Form & List of Locations. HILLER, J. R. Assistant Director for Site & Safeguards (Pre 791-78/11/15. 5pp. 94212:179.
- 7812180275 Forwards RevM1 "Draft Radiological Effluent Tach Spec-BWR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Pur Plents" (NUREG-0133).

  ORIMEB.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/13. App. 94336:332.
- 7811210334 Notifies that 780707 ltr schedule can not be met. Antithat field verification & insurance review of completed design for turbine lube oil reservoir deluge sys extension will be completed by 790131.
  MAYER, L. O. Northern States Power Co. 78/11/16. 1p. 94484:31
- 7811280338 Completion of replacement of existing CR 120A contect retainsrs will be finished by 790131. Also, replacement of enubbar springs will be decided upon after discussions w/ vendorioriginal replacement springs found befective. HACHTER,L. J. Northern States Power Co. 78/11/16. ip. 94395:
- 7811290367 Requests addl info on 780315 util proposal re Insvo le Testing Prog. Questions cover pump testing prog.velve testing prog & reactor recirculation eye.

  IPPOLITO.T.A. Deersting Reactore Branch 3 (Pre 790625). 78/11 94180: 029.
- 7812010215 Announces installation of 1 add1 restreint & mod of 2 suction piping rastraints. Because analysis indicates RHR suction line & supports would have functioned during design besie earthquake, the prob is not an RO.RD hereby retracted ELIABON, L. R. Northern States Power Co. 78/11/22. 1p. 94409:
- 7812130200 Concludes that the affects evaluated re-post-LOCA game of hydrogen in both BWR & PWR pressure suppression type containments do not leed to new eignificant eafsty concerns w/encl supporting conclusion. MATTBON, R. J. Division of Bystems Safety. 78/10/17. 48pp. 94289: 0AD
- 7812050371 Forwards corrected replacement page#157A for subj faci Specific douncomera to suppraisation pool. IPPOLITOLTA. A Operating Reactors Branch 3 (Pra 790625). 78/11 3pp. 94408:096.
- 7812110021 Discusses possible dangers of LOCA in containment purg during normal plant open Requests either commitment purg during normal plant open Requests either commitment to limit purging or justification for continuing. M/ancl ANO: 87812080207.

  BPD.170.7. Operating Reactors Branch 2 (Pra 790625). 78/11/1 Rpp. 94339:295.
- 7812070221 Forwards appl for change of Tech Spece, Append A. of Ops MAYER, L. D. Northern States Power Co. 78/12/01, 1p. 03555: Of
- -- 7812070222 Appl for change of Tech Spece. Append A. of Open Lithi
- re reduction of minimum specified Low Pressurs Coolant Injection delivery capability by 10% to provide reasonable marpin between performence & minimum, W/att Exhibits A.E & C. WACHTER.L.J. Northern Stabes Power Co. 78/12/01. 7pp. 03555: OB3.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meeting & provising task-by-task activity summary for the month. BDBON.L.J. General Electric Co. 78/12/04. 11pp.
- 7812280017 Emphasizes importance of sumbitting accurate & complat to NRC by licensees & applicants, Info submitted must be substantiated by data & calculations.Licenses must notify NRC of any inscruracies or anforcesent action will result. DAVIS.J. D. Office of Inspection & Enforcement, Office of the Director. 78/12/06. Spp. 94131:034.

ressel mat! surveillance prog. Due to a delay by Gen Elec in assembling this info.util requests extension of time to strovide info.

(AVER.L. D. Northern States Power Co. 78/12/11. ip 94133:341.

.2260323 Forwards 781204 NRC itr rs mod & installation of defective spent fuel rocks at facil pleading served on the Comm by the NR Pollution Control Agency rs this issue.Cert of Box encl. ITENSVA00. J. Minnesota. Btate of. 78/12/13. 2pp. 94160:116.

'B12260328 Responds to 781109 ltr re fuel rack swelling. Forwards QE Topical Rest, NEDG-2407, W/o encl rest. W/encl Cert of Bvc. GARDEBRING, 8. Minnesote, Btate of. 78/12/04. 4pp.

2210190 During surveillance test on 781014 one of four ATWB-Recirc ump Trip reactor high pressure intetru channel sensor elaye(Agsetat ModelMOPBC 750 w/#CF0095 socket/Pailed to hergize due to socket contact being disengaged.

LI/GON.L. R. Northern States Power Co. 78/12/15. 1p. 94279.025.

2080318 Notifies NRC that co will use model CNB-1600 shipping cash o transport radioactive math. Also confirms understanding of A requirements of 10CFR71 governing shipments.

AVER.L.O. Northern States Power Co. 77/12/27. 1p. 94332:039.

1210367 Forwards add1 info re multiple consecutive safety/relisf alve actuation of Mark I containment program.
0BOW.L.J. General Electric Co. 78/11/13. 3pp.

Inspection reports, IE Bulletins & correspondence

1300398 Forwards IE Inspec Rept#50-263/78-12 on 780828-30 during hich no items of noncompliance were noted. AVIBNA B. Region 3. Chicago, Fuel Facility & Materials Safety ranch. 78/09/29. Spp. 94136:324.

31:30040: IE Inspec Rept#50-263/78-12 on 780928-30 during which no items of noncompliance were noted. Major eress inspected incl:anviron protects confirmatory messurements. JANUSHA. G., OESTHANN, M.J. Region 3, Chicago, Office of the Diractor. 78/09/26. Spp. 94:36:326.

)230338 Forwards IE Circular#78-17. (800 ANO:7810230221:Docket 1-313.781013) IPPLER.J. G. Region 3. Chicago, Dffice of the Director. 78/10/13. .. 94167:041.

t070074 Forwards IE Inspec Rept#50-263/78-14 on 781012-13 during ith no items of noncompliance were noted. ORELLI.0. Region 3. Chicago. Resctor Operations Nuclear Support anch. 78/10/30. 2pp. 94347:343.

112070078 IE Inspec Rept#30-263/78-14 on 781012-13 during which no items of noncomplience were noted Major areas inspected inclinitial training, replacement training & retraining of itcereed & noniticensed personnel & operators.

WRIGHT, O. C., LITTLE, M. B., Region 3, Chicago, Office of the Director. 78/10/30, 3pp. 94342:345.

140010 Forwards IE Inspec Rept#80-263/78-13 on 780925-29 & Notice Violetion.
ORELLI.9. Region 3, Chicego, Reactor Operations Nuclear Support anch. 78/10/31, 2pp. 94119:337.

12140012 Notice of Violation from inspec on 780925-29. % Region 3. Chicago. Dffice of the Director. 78/10/31. ip.

12140016 IE Inepec Rept#80-263/78-13 on 780925-29 during which I item of noncompliance was noted; quality engr did not review & approve the resolution of discrepancies identified during escalpt of purchase orders.

ARRETER, T. L., WARNICK, F. Region 3, Chicago, Office of the Director, 78/10/30, 7pp, 94119:340.

.50004 Forwards IE Circular 78-18. PLER.J. G. Region J. Chicago. Office of the Director. 78/11/06. 94112:183. incl:preparation for refueling outage, prefuel handling activities. & fuel handling activities. WRIGHT, O.C., LITTLE.H.B. Region 3, Chicago, Office of the Director. 79/11/15. Spp. 94159.034.

78:2050278 Forwards IE Bullstin#78-12A. suppl to IE Bullstin 78-12. W/encl ANO:78:1300055 KEPPLER.J.O. Region 3. Chicago. Office of the Director. 78/11/24 ip. 94202:165

7812260308 Ack receipt of 781121 itr informing NRC of steps taken to correct violations noted in 781031 NRC itr. FIORELLIO. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/12/14. jp. 94160:080

7812290065 Forwards IE Bulletin 78-14. KEPPLER.J. O. Region 3. Chicago. Office of the Director. 78/12/19. 19. 03554:384.

R Pariodic operating reports & related correspondence

7810120030 Forwards monthly Oper Rept for Bept 1978.

HAYER, L.D. Northern States Power Co. 78/10/09. 1p. 94471: 335.

--7810120032 Manthly Open Rept for Bept 1978. MYRABO.A.L. Northern States Power Co. 78/10/05. 4pp. 94471:30

7611150116 Forwards Monthly Oper Rept for Oct 1978.
MAYER, L. D. Northern States Power Co. 78/11/13. 1p. 94135:166.

--7811160117 Monthly Oper Rept for Oct 1978.
MYRABD.A.L. Northern States Pawer Co. 78/11/03. 5pp. 94135:10

7812110136 Forwards Monthly Oper Rept for Nov 1978.
MAYER, L. C. Northern States Power Co. 78/12/08. ip. 94393:237.

--7812110140 Monthly Oper Rept for Nov 1978 MYRAED: A.L. Northern States Power Co. 78/12/06. 4pp. 94393: 2:

9. Reportable occurrences, LERs & related correspondence

7810110160 Forward's LERS78-016/03L-0.
MAYER, L. D. Northern States Power Co. 76/10/06. 1p. 94069: 115.

--7810110183 LERETB-016/03L-0 on 780908: trip of essential MCC BB3A s breaker 52-304 resulted in oper in degraded mode parmitted by various limiting conditions for oper Cause unknown. SMITH. 0. R. Northern States Power Co. 78/10/06. ip. 94413: 336

7810240117 Notifies NRC that 2 valves leaked in excess of criteria f local leak tests established in Tech Specs. ELIABON, L. R. Northern States Power Co. 78/10/16, 1p.

781:240162 LERB78-018/00L-0 on 781002: during routine sorvellance te HPCI isoletion temp switch Model 17023-5 failed to trip, due to loose wire inside switch. Redundent switches tested satisfatorily.

HILL-W. J. Northern States Power Co. 78/10/19. 1p. 94456: 301.

7810300191 Forwards LER878-01B 03L-0.
MAYER, L. G. Northern States Power Co. 78/10/25. 1p. 94033:351.

--7810300196 LER#78-018/03L-0 on 781002:2 primary containment legist valves.1 in RCIC sys & 1 in RMCU sys.were made inoper due to personnel error.
FEARBON.8.L. Northern States Power Co. 78/10/19. ip. 94033:3

7811240124 Forwards LER#78-017/03L-0.
MAYER.L. O. Northern States Power Co. 78/10/25, 1p. 94478:282.

--7811240125 LERH78-017/Q3L-0 on 781001: two primary containment teol. valvas(RCIC & RWCU Bys)were rendered incorreble for 2 minutes due to control document identification error. Isolation valve Tech 8psc requirement amphasized. PEARBON. S.L. Northern States Rower Co. 78/10/23, 1p. 94478: 28

- 7811280234 Forwards LERN78-019/017-0. N78-023/017-0. N78-025/017-0. N78-025/017-0
- --7811280239 LERB78-019/017-0 on 781014: while performing local leek rate test. "D" outboard MSIV.AO-2-86D was lesting in excess of Tack Spec 4, 7 A. 2. f. Caused by scratch on main seat Seats lapped & valve retested satisfactory TOBIN.P. A. Northern States Power Co. 78/11/22 ip. (... 94012.147.
- --7811280244 LERF/8-023/017-0 on 781014 while performing local leek rete teet "A" outboard MBIV.AD-2-86A was leeling in excess of T.S. 4.7. A 2.f Caused by bent value sten & worn lower guide rib Valve stem replaced & lower guide rib rebuilt TCBIN.P.A. Northern States Power Co. 78/11/22 pp. 94012-148
- --7811280249 LER#78-024/017-0 on 781020:during local isst rate test HPCI-9.turbine exhaust line check valve was lesting in excess of T.S. 4.7.A.2. Caused by accumulated dist on easting surfaces Seats cleaned lapped & retested estisfactorily PEDERSEN, D.E. Northern States Power Co 78/11/22 ip. 94012.149
- --7811280253 LERM78-025/OLT-0 on 781021:during local test rate test.RCIC-9.RCIC turbine exhaust line check velve was lacking in excase of T S. 4.7.A 2.7 Caused by accomplated dirt on seating surfaces 8eets cleaned & retested estisfactorily. HAMMER.S.J. Northern States Power Co. 78/11/22. 1p. 94012:150.
- --7811280256 LERM78-026/01T-0 on 781022: during local lest rete test.M0-2397 & M0-2398, resector citanup isolation velves were lesking in excess of T.S. 4.7. A. 2.6. Caused by successive pecking gland leakage. & improper torque/limit switch settings.
  NCLAN.L. L. Northern States Power Co. 78/11/22 [p. 94012:15].
- 7812200283 Forwards LER#78-021/03L-0.
  MAYER-L.O. Northern States Power Co. 78/12/14. ip. 94207:180.
- --78i2200287 LERM78-021/03L-0 on 78iii4: during refueling outege while testing RHR 6W sue, a pinhols leek was discovered in CV-1729. RHR 6W differential pressure control valvs. Caused by corresion & erosion of upper valve body OVERLID. T. W. Northern States Power Co. 78/12/14. ip.
- 7812200211 Forwards LER #78-022/03L-0.
  MAYER, L. 0 Northern States Power Co. 78/12/15, ip. 94162:285.
- --7812200215 LER878-022/03L-0 on 781117, stem leek was discovered in A in WYE Strainer, Y8-4002, on the main steam equalizer drain line. Usek caused by a defective casting & dev after two days of syc.
  TOBIN.P. A. Northern States Power Co. 78/12/15. ip. 94162:286.
- 7812060193 Recortable occurrence on 781218 MA-2-944 recirc discharge
- 7812260193 Reportable occurrence on 781218:MD-2-94A recirc dischargs bypass valve would not close, recirc eye mod Valve to be repaired.
  ELIAGON, L. R. Northern States Power Co. 78/12/19. ip. 94159:196
- 7612260256 Forwards LERN78-028/03L-0.
  MAYER, L.O. Northern States Power Co. 78/12/19. 1p. 94159:356.
- --7812260258 LER#78-028/03L-0 on 781124: during normel oper, small steem leak was discovered in weld of 45 degree albow on HPCI steam supply line i inch drain line to mein condenser dus to corrossion. Held repair mede at leek. Awaiting perts. PEDERBEN.D. E. Northern States Power Co. 78/12/19. lp. 74159: 357.
- 761 2270232 Forward # LER878-029/01T-0.
  MAYER, L. D. Northern States Power Co. 78/12/21. 1p. 94017:141.
- --7812270237 LERM78-029/01T-0 on 781214: High pressure instrument channel relay failed to amergize due to disengaged AOASTAT#CR0095 relay socket contact that failed to make contect w/AOASTAT #FP8750 relay contact. Contacts were resngaged.

  HAMMER.M.E. Northern States Power Co. 78/12/21, 1g.
- 7812270241 Forwards LERW78-020/03L-0.
  MAYER, L. O. Northern States Power Co. 78/12/21. 1p. 94017:150.
- --78:2270245 LERW78-020/03L-0 on 78:21:during normal pur increess, both indicating lights for MC-2014, LPCI A loop admission valva were out due to blown control pur fuse. Fuse had opened on slight over load for extended time period k was replaced.

  OVERLID. T. W. Northern States Power Co. 78/12/2: 1p. 94017:151.

- --7812270251 LERW78-027/03L-0 on 781121: during normal oper a steam was found in tee downstream of MD-1197 on the 2" HP Turbing "U" bend drain line to condensar, probably due to flow of steam & water from restricting orifice into tee TILLY, D. D. Northern States Power Co. 78/12/21 ip. 94017
- DOCKET 50-264 DON CHEMICAL CO.
- F. Becurity, medical, smergency & fire protection plans
- 7810300037 Forwards Dow's rev "Security Plan for Subj Facil" Botto available in Central Files only. LANORER.R.R. MCOHANNY.O.L. Dow Chemical Co. 78/10/20. ip-
- J. Insurance & indemnity information
- 78:01:10098 Forwards signed copy of Amend #9 to Indemnity Agreement #8-34 COALMELL.T.N Dow Chemical Co. 78/10/05. ip 94066:347.
- --78i0110101 Amend #9 to indemnity Apresment #8-34,00ding Article payment of premiums SALTZMAN, J. Antitrust & indemnity Group. 78/10/05. 2pp. 74066:348.
- DOCKET 50-265 QUAD-CITIEB STATION. UNIT 2
- A. Application/construction stage documents & correspondence
- 7812150228 Ciassifies lic emend for proposed fuel pool mod se Cias 1V & I not Ciasses II & 1. Requires add1 charge of 98300 for sech of the two applits be paid w/in 15 days.
  MILLER.W.D. License Fee Hanggement Branch. 78/12/ii. Qpp.
- F. Becurity, medical, emergency & fire protection plans
- 78:01:20080 Forwards analysis of Electrical Cable Penetration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 5 detailed drawings sesociated w/test.

  NAUGHTON, M. F. Commonwealth Edison Co. 78/09/29. 44p.
- 781:020349 Responds to 780929 ltr requesting NRC agreement to resp ta requests in case of offsite emergency. Under Interagency Agreement DDE Chicago Oper Ofc coordinates requests in ares. KEPPLER.J. Q. Region D. Chicago. Office of the Director. 78/10/ 1p. 94241:087.
- --7811020375 Requests NRC assistance in event of sergency at subj KALIVIANAKISIN. Commonwealth Edison Co. 78/09/29. 1p. 94241:088.
- 7812120195 Informs NRC name of fire protec consulting firm hired to CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Controls & GA" will be submitted 790201.

  NAUGHTON, H. F. Commonwealth Edison Co. 78/11/30. 2pp.
- G. Adjudicatory correspondence
- 7811090259 Ed grents request by Citizene for a Better Environ & Ne Resources Defense Council for parmission to file response to answers opposing their patitions to intervene by 781103.

  MILPOLLIN. O. L. Atomic Safety and Licensing Board Penel. 78/11/1p.
- 7811160021 Orante request by liceness CEIL to have until 781107 to respond to 781013 Order of ABLB permitting NRDC & Citizens for a Better Environ to file response to enswere opposing thair patitions to intervene in proceedings re subj facile. MILHOLLIN, O.L. Atomic Befety and Licensing Board Penel. 78/11/1 ip.
- 7812110284 Cantels epecial prehearing conference scheduled for 781; Conference shall be held on 790111 in Tax Courtroom of US Courthouse & Fad Bldg. Chicago, IL. Parties & petitioner must rept to Board by 781215 to progress of negotiations.

  MILHOLLIN. C. L. Atomic Safety and Licensing Sourd Panel. 78/12/(2nn.
- 7810190131 Answer by CEIL to Patition to intervene filed by Atty of of IL on 780920. Agrees that Atty Gen has standing but asserts there are no genuine issues to be heard at hearing. Requests that Atty Gen request for EIS be denied.

BAN, A. Z. Naturei Resources Defense Council. 78/10/10 4pp.

200324 NRC Staff Answere to Council for Citizens for Better viron & Natural Resources Defense Council's Petition for type to Intervene Staff opposes granting patition.w/Cert

DARD, R. J. Office of the Esecutive Legal Director. 78/10/10

310223 Staff Answer to State of 1L patition for Leave to Intervene off does not appose admission of 1L se party to proc. DARD.R.J. Diffice of the Esecutive Legal Director 78/10/10.

010063 Petition for leave to intervene & for hearing filed by Diou63 Patition for Isave to Intervene & For hearing filed by titens for Better Environ & Natural Resources Defense uncil Request for leave to file response to answers posing patition is granted. HOLLIN, G. L. Atomic Bafety and Licensing Board Penel. 78/10/13.

130223 "Netural Resources Defense Council Response to Commenuealth son's & Staff's Answers to Patition for Leeve to tervens. "intervenor urgss Bd to establish a schedule for lefing challenges to contentions. [BMAN, A. Z. Netural Resources Defense Council 78/10/23. 16pp.

130214 NRC request to file response to NRDC response to Comm Ed & Canswers to patition for leave to intervene dtd 781023.
grented.repiy will be served by 78100, Cent of Svc enci.
pDARD.R. J. Office of the Executive Legel Director 78/10/24

200070 Request by Comm Ed for leave to file a response to NRDC ief which argues that organizations may show standing to relicipate in NRC proceedings merely by alleging that they present anonymous members. Cart of Svc encl. EPTGE, P. P. Isham, Lincoln & Beele. 78/10/30. 2pp.

220010 NRC Staff's Response to NRDC's Response to Answers to ther's Patition for leave to intervens. NRC asserts that ther's Patition for leave to intervens. NRC asserts that DC has not demonstrated its stending to intervens settler of right. Cert of Svc enci.

DDARD, R. J. Office of the Executive Legal Director. 78/11/03

200003 Special Prehearing Conference in proceedings re subj factio ll be held on 781215 in Rock leland. N. All parties to och all petitioners to intervens must attend & ould be prepared to discuss all issues. LFOLLIN. G. L. Atomic Sefety and Licensing Noard Panei. 78/11/09.

130122 Gives notice that A Bielawski enters an appearance on behalf applicant CEIL in proceedings re subj fecile. Cert of Svc ci.

ELANSki.A.P. Isham, Lincoin & Beals. 78/11/21. 2pp.

270230 Proposed stipulation re NRDC & CBE's representation of named members in Dresden-Qued Cities treneshipment is not ceptable to NRC.NRC position on NRDC's petition to tervens remains so stated in 781103 pleading.
DDARD.R. J. Office of the Esscutive Legal Director. 78/12/06. ip.

280271 Forwards"Stipulation" of NRDC.CBE & Commonwealth Edison Co-identification of members of NRDC & CBE to prove they ve interests that may be affected No agreement w/Reg Staff s been reached. 1944N.A.Z. Netural Resources Defense Council. 78/12/08. ip.

12280280 Partiss agree that NRDC & CBE have adequately indentified at less one member whose interest may be edversely affected by the proposed action, Auth to represent these interested members has not been agreed upon.

270133 Special Prehearing Conf Scheduled for 790111 is postponed til 790201. Parties & petitione ere excused from quirement to rept to Bd by 781215 re negotiations ograss.
LHOLLIN. Q. B. Atomic Bafaty and Licensing Board Panel. 78/12/13. transfer & storage between facils. W/o encl. GODDARD, R. J. Office of the Esecutive Legal Director 78/11/17. 1p.

# J. Insurance & indemnity information

7812190109 Requests refund of 86 per mut in sites indemity fee paid for LiceOPR-2. #DPR-19. #DPR-25. #DPR-29. #DPR-30. #DPR-39. #DPR-48 POOLE, R. D. Commonweelth Edison Co. 78/12/13. 1p

# P. Operating license stage documents & correspondence

7812080026 FOIA request for all records incl:quantity of radioactive matl disposed of from former Manhetten proj in It, known as Chicago PilesM1.2 & 3 Matl disposed of in It by Lindsay Cos at Horris Pacil & Dresden Pecil.
HANGELL, D illingis, State of 78/11/06 2pp.

7812080149 Requests edd) info within 60 days re 761104 & 780221 submittels on instru setpoints.

IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/05 3pp. 94104:351.

7812110001 Discusses possible dengers of LOCA in containment purging during normal plant open. Requests either consistent to limit purging or justification for continuing. W/sacci ANO: #7812080207

IPPOLITO T. Descript Resectore Branch 2 (Pre 770625). 78/11/29. 8pp. 94339:089.

7810100027 Forwards evaluation of resttor protect sys pur supplies proposing over-voltage aiarm in control room of subj facils TURBAK.M.S. Commonwealth Edison Co. 78/10/04. Spp.

7Bi0140i12 Resvaluation of Lic emend fees for Inter-station spent fuel transfer for subj facils as requested by 780817 its shows that the class i & 3 fees paid for each estation are correct.
MillER.W O. License Fee Management Branch. 78/10/10. Ip.

7811130335 Summary of 780914 meeting w/QE representatives & Mark 1 Owners Group re-progress of Long Term Prog w/ettendance list & agands (RD-9-A-Marki, Standards. ) CRIMES, C. Plent Systems Branch (Pre-791030), 78/10/26 676p.

7811020322 Request to amend Section 6.6. B. I. O of Append A to Tech βρεσε to facil aper lic re reporting req for resctivity anomalies is ω/drawn.as Reg Guids"interpretation"by ARC on 780701 does not req rept for resctivity increses of less than 5 secs.

DEFIG. Communicate Education 70/10/12 200 REED C. Commonweelth Edison Co. 78/10/26. 2pp.

7811030161 Forwards proposed Amend changing Tech Spece w/regard to updating station organizational charts. Changes have received onsite & offsite approvel. REED.C. Commonwealth Edison Co. 78/10/26 9pp.

7811140105 Responds to 780516 NRC ltr requesting addl info re reactor vessel metal surveillance specimen fluence values at time of withdrewel, w/projections based on dosimetry results of previously tested cepsules & BOX cepacity fector. W/a encl. TURBAKIM. 8. Commonwealth Edison Co. 78/11/03. 2pp.

7811140002 Notifies applicant of 781128 NRC-sponsered seminar re Model Radiological Effluent Tach Space for Nuc Pur Plants w/encl Seminar Info Sheetito be completed & returned by 78117) & Proposed Agenda. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/07. 6pp.

7811300058 Forwards Amend#39.#37.#48 & #47 for Lice DPR-19.DPR-25. DPR-19 & DPR-30 respectively. Amends revies Tech Specs re operating temp & pressure limits. Also forwards Bafety Evel & Fed Register Natice. IPPOLITO, T. A. Operating Reactors Branch 3 (Fre 790625). 78/11/13.

~~7811300073 Amend#47 to the Operating Lic rev Tech Spece re operating temp & pressure limits.

IPPOLITO, T. A. Operating Reacture Branch 3 (Pre 790625). 78/11/13. Вор.

--7Bi1300077 Sefety Evel Rept in support of Amend#39,#37,#48 & #47 to Oper Lics DPR-19,DPR-25,DPR-27 & DPR-30, respectively. # Office of Nuclear Resctor Regulation, Director. 78/11/13. App.



- --7811300089 Notice of Issuance of Amend#39. #37. #48 & #47 to Oper Lics DPR-19.DPR-25.DPR-29 & DPR-30.respectively.

  IPPOLITO.TA. Operating Reactors Granch 3 (Pre 790625) 70/11/13
- 7812180044 Notice of wortshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-wortshop registration of attendees to facilitate sending out mati Wienc) Registration Form & List of Locations.
  Miller, J. R. Assistant Director for Site & Safeguards (Pre 791030) 78/11/15 5pp 94133 049
- 78:2:180266 Forwards Rev8: "Draft Radiological Effluent Tech Specs" for BLR 'sINUREG-04731 & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Planes" (NUREG-0133) ORITES. B. A. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp. 94365:349
- 7812050107 Forwards ray page to Topical Rept CE-1-A: "Oual Assurance Prog.Rav 6. "Rev reflects Rep Guidel 28 & 1 33 rev TURBAK.M 8 Commonwealth Edison Co 78/11/17 Ppp
- 7811280213 Forwards current lic status list for subj facils REED.C Commonwealth Edison Co 78/11/20 9pp
- 78ii 280246 Forwards "Projected Fluence Values at Withdraus) for the Capsules Designated to Meet the Requirements of IOCFR50 Append H " Table I to be attached to 78lio3 ltr to ippolito TURBAN-H B Commonwealth Edison Co 78/ii/20 2pp
- 7812060166 Informs NRC that response to 781118 NRC Itr relic amend appl & ownership for subj facil will be made by Commonwealth MILLER.R D. 10ws-111inois Gas & Electric 78/11/24 1p 94371.260.
- 7812140176 Forwards Oct 1978 Prog Activity Raview listing meetings held & providing task-by-task activity summary for the month BOBON.L J General Electric Co 78/12/04 11pp.
- 7812280129 Emphasizes importance of submitting accorate & complete info to NRC by licensees & applicants info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J. Q Office of Inspection & Enforcement, Office of Director. 78/12/06. 2pp. Office of Inspection & Enforcement, Office of the
- 7812190097 Accepts topical rept@CE-1-A RevM6."Comm Edison Co Quality Assurance Prog Por Nuc Generating Stations." Requests submittal of 36 copies. HAABB. W. P. Quelity Assurance Branch. 78/12/13. Ip.
- 7812270225 Provides addl info re gaseous releases described in 781030 itr.Cause of increase in off-gas activity is believed to be fuel leaters & corrective action for high gaseous activity is to maintain minimum leelage by close surveillance KALIVIANAKISIN. Commonwealth Edison Co. 78/12/13. 2pp 94017:139.
- G. Inspection reports, iE Bulletins & correspondence
- 7812040033 Forwards IE inapec Repts#50-254/78-21 & #50-265/78-22 on 780821-25, 780831, 780901, 780906-07, 780913-14, 781003-04 \$ Notice of Deviation. FIDRELLI, Q Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/31. Epp. 94129:092
- ~-7812040038 Notice of Deviation from inspec on 780821-25. \* Region 3. Chicago, Office of the Director. 78/10/31. ip. 94129:094.
- --78:2040046 IE Inepec Repts#50-2543/78-21 & #50-265/78-22 on 78082:-25 during which i item of deviation wee noted sercesive amounts of oil stored near vital cabling smoking in No Smoking Area.

  JACKEW.I.N. BROWN.C.H., KNOP.R.C. Region 3, Chicago, Office of the Director. 78/10/30. App.
- 7811010067 Forwards 1E Inspec Repts N50-254/78-19 & N50-265/78-20 on 780713-14, 780719-20,780726-27,780802-03, & 780810-11,during which no items of noncomplaince were noted. FIDRELLI.O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/19. 2pp. 94290:103.
- --7811010076 IE Inspec Repts#50-254/78-19 & #50-265/78-20 on 780713-14 780719-20.780726-27.780802-03. & 780810-11.during which no items of noncompliance were noted. Major areas inspected included: plant oper & out-of-svc activities.

  JACKIW, 1. N. , KNOP.R.C. Region 3. Chicago. Office of the Director.
  78/09/18. 6pp. 94290:105.

- 7811080077 Forwards IE Inspec Repts#90-254/78-20 & #50-265/78-21 on 780822-25, 29, 0901 during which no Items of honcompliance were noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch. 78/10/02 2pp. 94271 124
- --7811080080 IE inspec Repts#50-254/78-20 & #50-265/78-21 on 780822-25. 29.0901 during which no items of noncompliance were noted Major areas inspected included radioactive waste sys. effluent releases & effluent control instru HUETER.L J. FISHER.M.L. Region 3. Chicago. Fuel Facility & Materials Bafety Branch 78/10/02 lipp
- 7810110293 Act receipt of 780901 itr informing NRC of steps taten to correct violations noted in 780810 NRC 1tr
  KEPPLER,J O Region 3, Chicago. Office of the Director 78/10/03
  Ppp 03556 074
- 7811070002 Ack receipt of 781006 itr informing NRC of steps taken to correct violations noted in 780920 Notice of Violation. HIND, J.A. Region 3, Chicago, Bafaguards Branch 94037-072
- 7812050011 Forwards IE Inspec Repts#50-010/78-27.50-237.-254.-295.-304/78-25.50-249/78-27 & 50-265/78-26 on 781002 during which no items on noncompliance were noted KEPFLER. J G Region 3, Chicago. Office of the Director. 78/10/30 epp.
- 7812060223 Forwards IE inspec Repts#30-254/78-24 & 50-265/78-23 on 781004-06 during which no items of noncampliance were notesu HEISHMAN.R F Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 78/10/31. 2pp 94382:174.
- --7812060230 IE inspec Repts#80-254/78-24 & #80-265/78-25 on 781004-06 during which no items of noncompliance were noted Major areas inspected incl. IE Bulletins & Circular followup relative to quel of elec equip. HWDHES.J. - BPEBBARD.R.L. Region 3. Chicago. Dffice of the Director. 7B/10/31. 6pp 94382:176
- 7811150063 Forwards 1E Circular 78-18 KEPPLER. J Q. Region 3. Chicago, Office of the Director. 78/11/06. in.
- 7812060020 Responds to 781031 NRC itr ra violations noted in inspec Repts#50-254/78-21 & #50-265/78-22 Corrective actions areas req housekeeping were cleaned, no smoking rules enforced. procedure GAP 200-13 is being rev.
  REED.C. Commonwealth Edison Co. 78/11/RO 2pp. 94415:333.
- 78:2050207 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-12 W/enc1 AND:78:1300055 KEPPLER. J G Region 3. Chicago, Office of the Director 78/11/24
- 7812260292 Ack receipt of 781120 itr informing NRC of steps telen to correct violations noted in 781031 NRC ltr.
  FIORELLI.9 Ragion 3. Chicago, Reactor Operations Nuclear Support
  Branch. 78/12/14 lp. 94160-045
- 7812290026 Forwards JE Bulletin 78-14. KEPPLER, J O Region 3. Chicago, Office of the Director. 78/12/19. ip.
- R. Pariodic operating reports & related correspondence
- 7810250111 Nonthly performance rept for Sept 1978 Includes meint summary average daily unit pur level, refueling info request & LEF's. 78/09/30. 23pp. 94368-332.
- 7811220031 Forwards Monthly Operating Rept for Oct 1978 KALIVIANAKIS N Commonwealth Edison Co. 78/11/09 1p. 94309:010
- --7811220033 Monthly Operating Rept for Oct 1978, # Commonwealth Edison Co. 78/10/30. 30pp. 94309:011.
- 7812200235 Forwards Honthly Oper Rept for Aug. Sept. Oct 1978.correcting mistakes made in Aug & Sept Average Daily Unit Pur Level Rept & in the Sept & Oct Operating Data Repts. KALIVIANAKIS.N. Commonwealth Edison Co. 78/11/28. 1p. 94162:325.
- --7812200241 Monthly Oper Rept for Aug. Sept. Oct 1978. Corrections are circled in red.
  HANNUM.D. Commonwealth Edison Co. 78/11/09. 4pp. 94162:326

7812200188 Monthly Bear Rept for Nov 1978
• Towa-1111nois Gas & Electric 78/11/30 26pp 94145.314.

# B Reportable occurrences. LERs & related correspondence

- 7810170198 Forwards LER#78-030/03L-0 KALIVIANAK 15.N Commonwealth Edison Co 78/09/26. 1p 94411 258
- --7810170202 LER#78-030/031-0 on 780831. Main Steam Line Radiat Monitor 2-1705-20. failed in a downacele condition. Caused by instru drift enhanced by an elsysted chassis ambient oper temp a Commonwealth Edison Co 70/09/26 3pp 94411 259
- 7810170172 Forwards LERM78-031/03L-0 NALIVINVANIB.N Commonwealth Editeon Co. 78/09/29 1p 94270 032
- --7810170180 LER#7B-031/03L-0 on 780910 during test the 2-203-3cHBIV failed to give a half scram in reactor protec sys channel "B" due to equip failure inspec & adjusted actuator arm CLARK, B. Commonwealth Edison Co. 78/09/29. 3pp. 94270.033
- 7811240222 Forwards LERM78-032/03L-0 KALIVIANAKIB.N Commonwealth Edison Co 78/10/20 ip 9445B 219
- --7811240224 LERM7B-032/03L-0 on 780927: Unit 2 Main Steam Targst Rock Pressure Relief Valve#2-203-3A failed to open while performing test Caused by broken air line to valve's manual sir operator RED.M Commonwealth Edison Co 78/10/20 3pp 94450: 220
- 7811240192 Forwards LER#78-033/03L-0 MALIVIANAK18.N. Commonwealth Edison Co. 78/10/26 1p. 94458 312.
- --7811240193 LERe78-033/03L-0 on 780930 during routing snubber surveillance inspec. 2 snubbers were found to be inoperable. Both Mark 183 & Mark 175 snubbers failed due to hydraulto leakage thru hardened O-rings. KOPACZ Commonwealth Edison Co. 78/10/26. 2pp. 94456:313
- 781107011B Notifies NRC that average release rate for radioactive matls w/helf-lives greater than 8 days between 700701 & 700930 was 2 03 times Tech Spec 3.8.0.3 (11)design objective. Eval of slaveted main chimney release rate has started KALIVIANAKIS.N. Commonwealth Edison Cq. 78/10/30 2pp. 94043 319
- 7811240203 Forwards LER#78-034/03L-0 KALIVIANAK1B,N Commonwealth Edison Co. 78/10/30 1p. 9445B:346
- --7811240204 LER#78-034/03L-0 on 781002 while performing procedure GTB 130-4, Control Rod Brivs Scen Timing control rod N-10180-39) failed to acree upon receiving a test signal from panel 702-16 Caused by fellure of 118 screm solenoid valve TIETZ.0 Commonweelth Edison Co 78/10/30. 2pp. 94458-347
- 7811240239 Forwards LERW78-035/03L-0.
  KALIVIANAKIB-N Commonwealth Edison Co. 78/11/01 lp 94458.246
- --7811240241 LERW78-039/D3L-0 on 781004.Unit 2A resector vent radiat monitor & 2A refueling floor radiat monitor started spuriously spiling Caused by faulty pur supply common to both 2A monitors. Fur supply replaced w/spare monitor.
  HILLEMSEN.B. Commonwealth Edison Co 78/11/01. 3pp. 94438:247.
- 7811240100 Forwards LER#78-036/03L-0.
  KALIVIANAKIB.N Commonweelth Edison Co. 78/11/03 lp. 94436.200
- --7811240156 LER#78-036/03L-0 on 781016: NI core spray low-low level initation switch failed to trip at proper setpoint, caused by instru drift.

  8WALES.J. Commonwealth Editon Co. 78/11/03 3pp. 94486-286
- DOCKET 30-266 POINT BEACH NUCLEAR PLANT, UNIT 1
  F. Becurity, medical, emergency & fire protection plans
- 7811120167 Forwards copies of RevMB to Emergency Plan Manual BURBIEIN, B. Wisconsin Electric Power Co. 78/11/06. Ppp. 94223-001.
- --7811150173 Rev#8 to Emergency Plan Manual covering reporting of radiat incidents & emergencies to Reg. agencies, med. assistence, minor radiat incidents, major radiat emergencies & gen health physics procedures.

   Wisconsin Electric Power Go. 78/09/15. 222pp. 94223:003.

- 7812220169 Forwards Raway to Emergency Plan Hanuat For subj twitto replace outdated pages of Manual BURBTEIN B Hisconsin Electric Power Co 78/12/14 Spp 94159.294
- --78:2260172 Revw9 to Emergency Plan Manuel for subj facil replacing outdated pages of Manuel 
  > Wisconsin Electric Power Co. 78/12/14 9np 94139 296

## O Adjudicatory correspondence

- 7810110017 Interrogetories propounded to Applicant re environ & safety aspects of proposed facti

   Affiliation Unknown 78/09/27 12pp
- 7810110018 NRC Staff first set of interrogetories to & Request for the production of documents from St of WI Cass involves arend to LickDPR-24 & 27 re incressed spent fuel storage capacity BERBON. B A Office of the Executive Legal Director 78/09/29 13ms
- 7810110023 NRC Interrogetaries to & request for production of documents from intervenor Leteshare Citizens for Bafe Energy Admitted contentions also submitted.

  BERSON-8 A Office of the Executive Legal Director 78/09/29

  39pp 94063:091
- 7810110072 NRC Staff interrogatories to & request for the production of documents from applicant per 10CFR2 7406 rs amend to 11c HDPR-24 & DPR-27 Admitted contentions also submitted. BERSON, D. A. Office of the Elecutive Legal Birector 78/09/29 14pp 94061, 116
- 7810120225 Submission of interrogatories by applicant MIEP to intervenor Lakeshore Citizens for Safe Energy Interrogatories addressed to contentions contained in intervenor's amended contentions
  TROMORIBGE 0 F Shew, Pittmen, Patts & Troubridge 78/10/02. App 74001 345
- 7810190093 Interrogs asked of NRC Biaff by Bt of HI Interrogs partain to staff's position related merit of sach intervenor Lakeshore Citizens for Bafe Energy's admitted contentions LAFOLLETIE.B.C. HALBH.P. Hisconsin. State of 78/10/02 3pp 94006-319
- --7810190008 Interrogs ested of applicant WMPC by 81 of WI pertaining t maint of spent fuel pool; in particular, dengar from radiat amission & exposure WM.841.P Wisconsin, State of 78/10/02 10pp
- 7810200326 Applicant. HI Elec Pur. objections to interrogs submitted by Intervenor. Lakeshore citizens for safe snergy, are stated. Objections based on interrog's reliance on contentions that were rejected by ABLB or are still being argued. TROWN100E.0 F Shew. Pittmen. Potts & Trowbridge 70/10/12. 669 94190 179
- 7B10260222 NRC advises NABLB that issuance of SER 4 environ essessment will be delayed until Dec 1778 due to reordering of NRC tech staff's priorities wirespect to review efforts on pending apple Oeley has been discussed wiapplicant's representative EERCON.B. A. Office of the Executive Legal Director 7B/10/17. 1p 74005 185
- 7811200275 "Lakeshore Citizens for Bafe Energy Responses to the NRC Btaff's First Bet of Interrops " Urges evaluation of Alrborne smissions which edd to existing background radiat Cent of Svc encl.

  BCHAEFER. H. Lakeshore Citizens for Bafe Energy. 78/10/25 22pp. 94250 288
- 7811200268 "Lebeshore Citizens for Bafa Energy Responses to the WI Electronic First Set of Interrogs." Defines "increased worker activity" re spent fuel pool ectivities EBIED, J. Lekeshore Citizens for Bafe Energy. 78/10/86 App 94250, 271.
- 7811180262 "Applicant's Answers to Interrogs Propounded by Intervenor on 780927." Cert of Suc encl.
  NEWION:8. A. Wisconsin Electric Power Co. 78/10/27. Alpp. 94273:167.
- 78iii50089 Answer by NRC Staff to interrogs of 8t of WI re contentions of Lakeshore Citizens for Sefe Energy who oppose amends to lice for suby facil concerning increase in spant fuel storage capacity. Affidavita & Cert of Svc encl.
  BEREON B. A. Office of the Executive Legal Director 78/11/01.
  55pp. 74113:208.

- on 781002 re amend to lics for subj facils to increase spant fuel storage capacity Supporting documentation & Cert of Svc encl.
  NEHTON.R.A. Hisconsin Electric Power Co. 78/11/01. 39pp. 94449:201.
- 7812040344 Forwards Affidavits of CM Trammell & FM Altmeter of NRC Staff.
  BEREON, B.A. Office of the Executive Legal Director. 78/11/08. 4pp. 94131:015.
- 7812030049 Applicant's answers to 780929 NRC interrops to amend to LiceOPR-24 t MDR-27. Increasing Spant Fuel Biorage Capacity. W/list of names, background & professional quals of witnesses t answers ta potential incremental airborns releases. NEWTON, R. A., Wisconsin Electric Power Co. 78/11/08. 23pp. 94.334: 168
- 7812140359 Bwaars that lieted persons have been authorized by intervenore LACSE to respond to interrogs submitted by NRC Staff & epplicant WIEP re LACSE contentions.

  BAST.S.A. Lakeshora Citizens for Safe Energy. 78/11/13. 1p. 03557. 233.
- 7812270050 St of WI's Answers to NRC Steff's first est of interrogs & request for production of documents. St has not yet located qualified whitnesses as admitted contentions. Cert of Svc encl
  MALBH-P Wisconsin. State of. 78/11/14. 3pp. 94160.261.
- 7812040183 Dismisses Contention#4 of Intervenors sustains objections raised by applicant MIEP to intervenors' Contention#9.0 be intervenors' intervenors intervenors rether Contention#9. Contention#9 concern security plens & health care plens.
  HILLER.M.E. Atomic Befety and Licensing Board Panel. 78/11/17.
  4pp. 94457-081.
- 7812080173 Gives notice that effective 781122.8 Berson withdraws ee NRC representative in proceeding raleuby facil. Certificate of Bvc snc1

  BERSON.9.A. Office of the Executive Legal Director. 78/11/17. 3pp. 94107:255.
- 7812270452 intervenors request NASLS for leave to w/draw Intervenor. MEPCO.NRC staff & St of WI move NASLS to enter order to approve w/drawel of Intervenor as party & enter Order dismissing proc. Agreement & Cert of Svc enci. BAST.S.A. Lakeshore Citizens for Safe Energy. BARTH.C.A. Office of the Executive Lagel Director. CHURCHILL.S.M. Hieconein Electric Power Co. 78/12/13. 9ps. 94016:008

## H. Gameral correspondance

- 7812140368 Requests copies of NUREQ-0410 & NUREQ-0471. BUBT.B.A. Lakeshore Citizens for Bafe Energy, 78/11/13. ip. 03557:204.
- P. Operating licenea etege documents & correspondence
- 7810250016 Request for add1 info re expension of spent fuel pool atorage capacity, which will req on-eite neutron ettenuetion tasting of boron plates that are to be in pool, removal of which will req epecial rept to NRC.

  BCHMENCER, A. Operating Resctors Branch 1 (Pre 790625). 78/10/03.

  3pp.
- 7810170193 Responde to 780913 itr requesting schad for submittel of rev ECCS cooling performence analysis Submittal of completed ECCS analysis to NRC will be on an before 790112 Analysis will use new Westinghouse ECCS sval model.

  BURSTEIN-S. Wisconsin Elactric Power Co. 78/10/10. ip. 94236:088.
- 7810230272 Forwards responses to requeste for add1 info re epent fuel etorage aspansion plans for sub; fecil. Discusses fuel loading limit, radiat does in Sprafler piate, thickness of stainless starl inner centfuel region dimension.

  BURSTEIN. 8. Wisconsin Electric Power Co. 78/10/10. 44pp.
  94167:136.
- 78:0190130 Forwards copy of 7805:0 ltr from subj fecil to Univ of W1. COLLINS.P.F. Operator Licensing Branch. 78/10/21. ip. 94414:077.
- ---78:0190193 Requests copy of 78:0510 ltr be sent to Univ of HJ. Ack 780609 ltr to WI Elsc has been placed in Univ of WI.

  JACOBBON, N. Affiliation Untrown. 78:09/25, tp. 94414:028.

- Requal Prog. Nine ataminations were regraded IAH conversations of 780420 & 21. Results of the regrading are attached. Regraded scores will be used as record scores REED, Q.A. Wisconsin Electric Power Co. 78/05/10 opp. 74414:029.
- 7810190101 Outlines agreement reached re proposed use of rod banks swap measurement technique to confirm adequate reactor shutdown capability. Technique to be used for subj facil only: further use must obtain NRC generic approval.

  BCHENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/12. 4pp. 94413:272.
- 7810310016 Summarizes meeting on 780929 to Westinghouse rod ben's swap measurement prog. ROBENTHAL J.E. Reactor Safety Branch (Pro 791030). 78/10/13. 4pp. 94094:326.
- 78:1170297 Forwards rough draft workingpapers on subj facil amended Becurity Plen, intended solely for use of JR Barggren. Comments withheld from public disclosure pursuant to 2.790. RDSE.D.G. Los A)emos Scientific Laboratory. 78/11/01. 3pp. 02765:230
- 7811130203 Forwards Tach Spec change Request 56 to DPR-24 & DPR-27. Tech Spec 15 3.15 "Gyerpræssure Mitigeting Sye Oper." encl outlining functional requiraments & limiting conditions for oper ra presentier pur operated raisef valve.
  BURGYEIN, 8. Wisconsin Electric Power Co. 78/11/02. 16pp. 03554:001.
- 78:ii40:24 Forwards reactor meths surveillance capsula test repts for subj facils. Conservation in the curves used to predict the change in transition temp as a function of fluence is clearly demonstrated by the results.

  SURSTEIN, 8. Wisconsin Electric Power Co. 78/ii/OB. 3pp. 94380:113
- --7Biii40iJi "Anaiysie of Capeuia T from WI Elec Pur Co Facility Reactor Vessel Radiation Surveillance Program." DAVIDBON.J.A., ANDERBON.S.L., BNOGAN.R.P. Westinghouse Electric Corp. McAP-9331. 78/08/Ji. 57pp. 94383:117.
- --78:1140133 "Analysis of Capsula R from Wi Eisc Pur Co Facility Resctor Vessel Radistion Burveillance Program." YANICHKO, B. E., ANGERSON, B. L. Hestinghouse Eisctric Corp. NCAP-9357, 78/08/31, 62pp. 94383:176.
- 78:2130203 Notice of workshope re implementation of training & quel requirements contained in Append B of 100FR73. Requests pre-workshop registration of attendees to facilitate sending out met). Wienci Registration Form & List of Locations. MILLER. J. R. Assistant Director for Site & Sefeguerds (Pre 791030). 78/11/15. 5pp.
- 7812190060 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for PMR's(NUREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NUREQ-0133). GRIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94215:095.
- 78:2010225 Requaste amend to Facil Oper Lic to Incorp changes to Tech Space. Changes consist of rev to reactor coolant sus heatup to cooldown limitation curves for oper of subj facil. W/check for \$4.400.00.

  BURSTEIN. 9. Hisconsin Electric Fower Co. 78/11/16. 6Pp. 94409:326.
- 7611280229 Withdraws unnecessary requests for relief ra Residual Heet Removal Pumps. Containment Spray Pumps. Turbina Drivan Auxiliary Feedwater Pumps. Elec Auxiliary Feedwater Pumps. Forwards ray pages of periodic pump & valve test plan. BURSTEIN, S. Wisconsin Elactric Power Co. 78/11/20. 9pp. 94012:050.
- 7812130008 Discuseee possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing. W/encl ANO e7812080207. SCHENCER: A. Operating Reactors Branch i (Pre 790623). 78/11/28. App. 94209:R30.
- 7812000101 Forwards results of startup physics testing at subj facil, in particular rod worth data. Data shows that the ecceptance criterion was mat. Preliminary repts indicating that 2 raview criteria were exceeded are incorrect.

  HILBON.T.R. Wisconsin Electric Power Co. 78/11/30. 19pp. 94333: 288.

- 7812210320 Forwards request for add1 info re subj Fect1 expansion of Spent Fuel Storage capacity SCHENCER, A. Operating Reactors Branch i (Pre 790625). 78/12/06. 3pp. 03556.104
- 7812270389 Responds to 781113 request & encl "Generic Task Problem Descriptions"(NVREO-0471)& "NRC Prog for Resolution of Generic Issues Related to Nuc Pur Plants"(NVREO-0410).

  BARTH. C. A. Opplice of the Esecutive Legal Director 78/12/06 ip.
- 7812280060 Emphasizes importence of submitting accurate & complate info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcament action will result. DAVIB.J. 9. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp 94085.360.
- 7812290110 Ack receipt of 781116 appl for amend to LicamDPR-24 & 27 Requests addl %3600 lic fee 01908.R H Licansa Fae Menagamant Branch. 78/12/20 Ip 94191.358
- G. Inspection reports, IE Bulletine & correspondence
- 7810130054 Ack receipt of 780911 ltr informing NRC of steps taken to correct violations noted in itr of 780822 re noncompliance & rev of adaquacy of the weld repeir KEPPLER.J. O. Region 3. Chicago. Office of the Director 78/10/05. ip. 94421 026
- 7810190079 Forwards 1E Inspec Repts #50-266/78-14 & #50-301/78-18 on 780822-25. Notice of Violation w/held purawant to 10CFR2-790 HIND.J.A. Region 3. Chicago, Safeguarda Branch. 78/10/10. 2pp. 94007-023
- 7810230302 Forwards 1E Circular#78-17 (8ss AND: 7810230221, Docket 50-313, 781013)
  KEPPLER, J. Q. Ragion 3. Chicego, Office of the Director 78/10/43. 1p. 94181: 335.
- 7811210413 Forwards IE Inspec Rspts#50~266/78~15.#50~301/78~20 on 780911~15 during which no Items of noncomplience were noted FIBRELLI.O. Region 3."Chicago. Reactor Operations Nuclear Support Brench. 78/10/16 2pp. 94483:132.
- --7811210436 IE Inspec Repts#30-266/78-15,#30-301/78-20 on 780911-15 dwring which no items of noncompilance were noted Major areas inapacted included plant oper-procurement nonroutine avent to safety injection reset procedures CHOULER, N. C., HUOMEB, J., WARNICK, R. F., Region 3, Chicago, Office of the Director, 78/10/16 11pp. 94483, 134.
- 7811290333 Forwards IE Inspec Rept#50-266/78-17 on 781003-05 during which no Itama of noncompilancs were noted. FIDRELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. 2p. 94193:324.
- --78i1290336 IE Inspac Rapt#50-266/78-17 on 781003-05 during which no items of noncompilence were noted. Mejor areas inspected inci-preparation for refueling outage, prefuel handling activities, fuel handling ectivities.

  MENNING, J.E. Region 3. Chicago, Office of the Director. 78/10/23 45p. 94i93:326.
- 7811070374 Responds to 1E Bulletin#78-12 dtd 780929 re etypical waid matl in Reactor Pressure Vessel weids. Vessels in subj. facil entedata the etypical matl. an the metter does not apply. BURSTEIN. 8. Wisconsin Electric Power Co. 78/10/26. opp. 94043 265.
- 78:10:0072 Notice of Violetion-failure to rept a significant fish kill-appended to 780612 itr is retrected. Thirty eix fish killed is not significant to warrant a rept.
  KEPPLER, J. O. Ragion 3, Chicago, Office of the Director. 78/10/31.
  1p. 94423:334.
- 7812060174 Forwards IE Inspec Rept#50-266/78-19 on 781002-04 during which no items of noncompliance were noted. HEIBHAM.R.F. Region J. Chicago, Reactor Construction & Engineering Support Brench. 78/10/21. 2pp. 94382:085.
- --7812040178 IE Inspec Rept#50-246/78-19 on 781002-04 during which no items of noncomplience were noted. Hajor areas inspected incl: GA/GC prog: implementing procedures: work activities & records relative to steam generator tube inspec. WARD.K.D., DAMELEON, D.H. Region 3. Chicago, Diffice of the Director. 78/10/31. 9pp. 94302:087.

- 78iii150071 Forwards IE Circular 78-18 KEFPLER, J O Region 3. Chicago. Office of the Director 78/ii/06 ip 94ii2 272
- 70:2140141 Forwards IB Inspec Rept#50-266/78-20 on 78:013-14 during which no items of noncompliance were noted FIDRELLI,O Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94:03-105.
- --7812140147 lE Inspec Rept850-266/78-20 on 781013-14 during which no items of noncompliance were noted Major eraes inspected inclineasurement of controlsbenk worth by boron dilution & of control & shutdown bank worths.

  KDHLER, J. E. CHDW.E.T., GTREETER, J. F. Region 3, Chicago, Reactor Operations Nuclear Support Brench. 78/11/13. 3pp. 94103:107.
- 7812210120 Forwards 1E Inspec Repth30-266/78-16 on 781012-19 during which no Itams of noncomplience were noted IEIGHMANS F. Region 3. Chicagn. Reactor Construction & Engineering Bupport Branch 78/11/17. 2pp. 94269.302.
- --7812210131 IE Inspac Rept#50-266/78-16 on 781012-13 during which no items of noncompliance were noted Major eraes inspected incl:safety reloted pipe anubbars incl review of prog & procedures
  YIN 1 T. . DANIELBON.D.H. Region 3. Chicago. Dffice of the Director 78/11/16. App. 94269.304
- 7812290068 Forwards IE Inspec Repts #50-266/78-22 & #50-301/70-23 on 781017-20 during which no Items of noncompliance were noted FIDRELLI.Q. Region 3. Chicago. Reactor Operations Nuclear Bupport Branch 78/11/22 2pp 94190:047.
- 7812290074 IE Inspec Repts #30-266/78-22 & #50-301/78-23 on 781017-20 during which no items of noncomplience were noted. Hejor arees inspected incl: calibr & surveillence of safety related components end equip.
  STREETEN.JF., SMITH.J.D. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/20. Spp. 94190:049.
- 7Bi 205027i Forwards IE Bulletin#7B-i2A, suppl to 1E Bulletin 7B-i2 M/encl AND: 7Bii 300055. KEPPLER.J G Region 3, Chicago, Defice of the Director. 78/i1/24. 1p. 94202 2iB.
- 7B12290022 Forwards 1E Inspec Rept#50-266/7B-21 & #50-301/7B-22 on 7B1023-24 during which no items of noncompliance were noted. FIDRELLI, G. Rapion 3. Chicago, Reactor Operations Nuclear Support Branch. 7B/11/24. 2pp. 94207:332.
- --7812290032 IE inspec Repts#50-266/78-21 & #50-301/78-22 on 781023-26 during which no itams of noncompliance were noted. Helpin areas inspected incliquality assurance progrescords, nonroutine swant fallowup & noncompliance followup. CHOULEG.N.C., WARNICK,R.F. Region 3. Chicego, Reactor Genrations. Nuclear Support Branch. 78/11/21. 4pp. 94207:354.
- 7B12130101 Requests add1 info for review of 770520 request relating to insvc inspec prog. Requests response w/in 45 days BCHENCER, A Operating Reactors Branch i (Pre 790625) 78/12/04. 4pp. 94294: 329.
- 7B122B0036 Forwards IE Bullatin 7B-14. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 7D/12/19. 19. 94133:216
- R. Periodic operating reports & related correspondence
- 7810170171 Forwards Monthly Oper Rept for Capt 1978 BURETEIN, B. Hisconsin Electric Power Co. 78/10/09, ip. 94270.036
- --7810170173 Monthly Open Rept for Bept 1978 • Wisconsin Electric Power Co. 78/10/09. 9pp. 94270:037.
- 7811140174 Forwards Monthly Open Rept for Oct 1978.
  BURSTEIN, 9 Hisconsin Electric Power Co. 78/11/08. 1p. 94384:234.
- --7811140178 Monthly Oper Rapt for Oct 1978.

  \* Hisconsin Electric Power Cp. 78/11/03. 10pp. 94384:235.
- 7812120083 Forwards Monthly Oper Rept for Nov 1978.

  BURSTEIN, S. Hisconsin Electric Power Co. 78/12/08. 1p. 94874:181.
- --7812120087 Monthly Oper Rept for Nov 1978.

  \*\* Hisconsin Electric Power Co. 78/12/05. 9pp. 94274:182.

- 8 Reportable occurrences. LERs & related correspondence
- 7810180043 Forwardt LER#78-012/01X-0.
  BURBTEIN.B. Hisconsin Electric Power Co. 78/09/12. 1p. 94422:056.
- --7810180046 LERH78-012/01X-0 on 780627: during visual inspec of fire barrier penetration seals, horizontal seals found to be constructed differently than specified. Error due to change in constructed wings. No reportable item exists.

  BURBTEIN.S. Hisconsin Electric Power Co. 78/09/07. ip. 94422:057.
- 7810180038 Forwards LERAT8-014/01T-0.
  BURBTEIN, 8. Wisconsin Electric Power Co. 78/10/04. 1p 94422:050.
- --7810180040 LER#78-014/017-0 on 780920: primary-to-escondary leekage noted during normal oper Causad by 2 isaking tubes & 1 isaking plug on injet side of the "Ameteem generator Tubes will be plugged & plug will be weld repaired.
  BURSTEIN 8. Hisconsin Electric Power Co. 78/10/04. 2pp. 94422-051.
- 7811240149 LERB78-010/017-1 on 780528: indication of primary-tosucondary loak of 145 GPD in the "A" 80 was noted on 780324. Bource of leak due to failure of tubs at position R44C33. Tubs plugged & unit returned to svc. BURBIEIN-8. Misconsin Electric Power Co. 78/10/23. 2pp. 94454-250.
- 7811240135 Forwards LER#78-015/017-0 8URST£1N.8. Wisconsin Electric Power Co. 78/10/23. 1p. 94456:270.
- --TB11240158 LERMTB-015/01T-0 on 781009: snubbar on preservizar rellef line was found inoperable. Orinns! Model#HB-17-21/2 inch x 5 inch bore & strote enubbar felled for undetermined cause. Snubber replaced & surveillance prog expanded. BURSTEIN. 8. Hisconsin Electric Power Co. 78/10/23. 2pp. 9455-271.
- 7812110189 LERB78-016/01T-O on 781106; turbine runback resulted from sefeguards bus tie breaker trip, Wastinghouss Model CV-7 undervoltage relay on the breaker tripped causing breaker to open. No line voltage surges detected. BURSTEIN-8. Wisconsin Electric Power Co. 78/11/17. 2pp. 94408-040.
- 7812180217 LER#78-073/03L on 781121: failure to submit RO 50-366/78-55 w/in 30 days. Caused by Daviation Rept 2-78-79 not raceived by responsible dept head nor superintendent of Pient Engr Sycs. Personnel were raminded of procedures.

  OREENG.T.V. Georgia Power Co. 78/12/11. 2pp. 94365:076.
- 7811210393 LERM78-015/017-0 on 781009; snubbsr #3221 inoperable caused by Grinnell model #HM-17 bars & stroke snubbar not locking when spacified load rate was applied. Snubbar replaced & surveillance prog expanded.

  QRECHHODD. J. Hisconsin Blactric Power Co. 78/10/10. 1p. 94406:049.
- DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

  B. Utility Preliminary Safety Analysis Report, amends
- 7811240234 SAR re use of U Carbide (UC2) Fual Particles in Fort St Vrain Fuel Elemants. Topical rept re future reload fuel segments. \*\*General Atomic Co. (subs. of Guif Dil Co.). 78/09/30. 29pp.
- E. NRC Sefety Evaluation Report (SER), supple & correspondence
- 7811240226 Forwards Safety Rapt for instru control rad drive & orifice assemblies.
  MILLEN.C.K. Public Service Co. of Catorado. 78/11/17. 3pp. 9448:178.
- --7811240228 Safety analysis rept for installation of instru control rod drive & orfice assemblies during fuel outage in 790101.

  remaining in core until second refueling. Oversite drewings available in Central Files.

  \* Public Service Co. of Colorado. 78/11/17. 22pp. 94458:181.
- f. Security, medical, smergency & fire protection plans
- 7810170174 Fire protec prog rev in response to brench tech position 9.5-1. FULER.J.K. Public Service Co. of Colorado. 78/10/13. ip. 94226:022.

- 7811:00096 Forwards ray pages & Mac 4 for rept shiftled "Fire Protsc Prog Review Por Nuc Cenerating Station in Response to Branch Position 9 3-1." dtd 781013. FULLER.J.K. Public Service Co of Colorado. 78/11/13 BBpp. 94135:001.
- 7812220052 Forwards Appl for Amend to Append A of Facil Oper LiceOps-34 changing Tech Specs for Fire Protec in areas of Haion Fire Suppression Sys for Control Room-Smoke Detectors & Alaras & Fixed Meter Spray Sys HILLEN.C.X. Public Service Co. of Colorado. 78/12/11. 2pp. 94342:255.
- --7812220069 Appl for amend to Append A of Facil Oper LicutPR-34, thangin. Tach Space for Fire Protec Sys re Halon Fire Suppression Sys & Smoke Datactors & alarms for control room & cable areas & fixed water spray sys for equiliery electrom.

  MILLEN.C.K. Public Service Co. of Colorado. 78/12/11. 6pp. 94342:267.
- H. General correspondence
- 78122B0274 Forwards info re reactor & HTOR concept in gen requested for high school debating purposes in 78112B ltr.W/sncl summary of 781103-04 meetings re subj facil.HTOR lic criteria.& postulated accidents & sefety res needs.

  DENTON.H.R. Office of Nuclear Reactor Regulation. Director.
  78/12/18. 100pp. 94347:207
- ~-7812280277 Requests info on subj fecil & HTQR concept in gsn for high school disbate topic re energy independencs. QERLACH. D. Affiliation Unknown 78/11/28. 1p. 94347.209.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7811240232 Forwards copy of "Bafety Analysis Rep:Use of UC2 Fissle Fuel Particles in Fort St Vrein Fuel Elements."
  Requests review be completed by 790215.
  HEBBMAN.C.L. Openeral Atomic Co (subs. of Guif Dil Co ). 78/11/17.
  Zpp. 94461:360.
- D. Advisory Committee on Reactor Befaguards reports & correspondence
- 7810230382 Comments on 780804 NRC Staff presentation refacil cora PMR oscillations Surprised to find that little mora is known on the matter how them was known in Nov 1977 LIPINBKI,M.C. Afgonne National Laboratory. 78/08/14. 2pp. 94195:172.
- P. Operating license stage documents & correspondence
- 7810100005 Describes Post Irradiation Surveillance Prog for proposed tast & standard fuel elements of subj facil reactor. FULLER, J. N. Public Service Co. of Colorado. 78/06/20. 2pp. 94033:024.
- 7810100012 Etetement that "gemma scan to determine distribution of fission product & core power"was included by mistake in on-site exemination description for PIE Prog. The gemma scan will be conducted on a selective basis.
  FULLER.J.K. Public Service Co. of Colorado. 78/06/R3. 1P. 94003. 1020.
- 7810110136 Advises PBC wishes to discuss improving NRC response to matters re subj facil & proposed open meeting re lic matters in Denver area at 781011 meeting. Matt listing of correspondence re proposed mode to subj facil Tech Specs. FULLER.J.K. Public Service Co. of Coloredo. 78/10/03. App. 94064:333.
- 7810120063 Forwards Appl for Amend to Appendix A of Facil Dear LicKOPR-34. MILLEN.C.K. Public Service Co. of Colorado. 78/10/05. 1p. 94418-389
- --7810120064 Appl for emend to Appendix A of Facil Oper LiceDPR-34, changing Tech Spec to incorparate new fire water booster pumps installed to meet requirements of Sec 14, 4, 2, 1 of FBAR.
  MILLEN.C.K. Public Service Co. of Colorado. 78/10/05. Appl. 94418: 354.
- 7810180141 Beaks to indirectly implement limiting steam generator module helium injet temp variation by limiting allowable steam generator module outlet steam temp variations. Concerns fluctuation test at 70% of rated thermal pur. FULLERU, K. Public Bervice Co. of Coloredo. 78/10/05. 2pp. 94316:338.

- acceptable & does not require Tech Spec change or involve unreviewed selety question per 10CFR30.59.
  FULLER, J. K. Public Service Co. of Coloredo. 78/10/09. 3pp. 94236.011.
- 7810190014 Summary of meeting on 780929 w/Oen Atomic Co to discuss use of H-451 graphite in subj facil reactor/OAC's questions were resolved/walidation of computer codes used in enalysis of stress or chem reactions not regulated for review.

  Williams.P.M. Advanced Reactors Branch. 78/10/10. 4pp. 94322:355.
- 7810230165 in response to concerns re precautions which will be taken when primary sys is pressurized & reactor open, util forwards prerequisites to surveillance test.

  MARCHEUMF0, D. Public Service Co. of Colorado. 78/10/12. ip. 94164.7253.
- 7810310094 Response to 780828 NRC ltr.PSC will not propose any mode of current prog at subj facil since plant oper thru Dec 1978 has not provided basis for determining mode. Asserts that use of ASME Section XI Draft 2 rules would not be practical. FULLER.J.K. Public Service Co. of Colorado. 78/10/19. 3pp. 94091:878.
- 7811010207 Notice of Meeting on 781103 & 04 w/Pub Svc Co of Caloredo to discuss subj facil fluctuations oper & testing above 70% pur & related items.

  KUZHYCZ.Q. Division of Project Management. 78/10/19. 2pp.
- 7810250067 Submits responses to 8 NRC questions of 780818. This completes response to 811 NRC questions re reactor fluctuation testing at pur levels above to below 70% rated thermal pur. Requests release for oper by 781118.

  FULLER.J. K. Public Service Co. of Coloredo. 78/10/20. 42pp.
- 7810260205 Psr request in NRC ltr of 781004 forwards comments re BNL POX graphite test results. Concludes that results verify data base presently used to analyze extent & consequences of oxidation of core support blocks. FULLER-J.K. Public Service Co. of Coloredo. 78/10/20. 9pp. 94036:078.
- 7810310085 Forwards response to questions contained in 780922 NRC ltr re core inlet helium temp vs time transients generated by TAP code.
  FULLER-J.K. Public Service Co. of Coloredo. 78/10/25. 82pp. 94091-045.
- 7811130200 Forwards first part of OA's response to 780919 NRC questions re add1 indo on H-431 graphits. Responses to remaining questions will be submitted 781124.
  WESEMAN.Q. L. Qamerai Atomic Co. (subs. of Quif Qii Co.). 78/10/30.
  56pp. 94077:001.
- 78ili30001 Calibr & testing for all Ciass A.O & C instru has been completed. Instruments to be calibr &/or functionally tested prior to resuming oper after early Jan 1979 refueling outags.

  BEYFRIT.K. V. Region 4, Dallas, Office of the Director. 7B/11/01.
  299. 94077:005.
- 78iii60071 Forwards preliminary rept of scillation testing at subj facil. On 78ii04 during testing mode undor auspices of RT-500A limit(+/-30F)for steam generator module main steam temp was exceeded. Begusnes of events encl. MARCHBURGO, D. Public Bervice Co. of Calorado. 78/ii/09. 4pp. 94i30;144i.
- 781127021: Responds to 781025 ltr re review sched of H-451 graphite & thorium oxide fuel Graphite review will be completed in Jan 1979, subj to acceptable responses by 781131 to addi info request. Thorium review is in acceptance phase, to end 781131. GAMMILL, M.P. Assistant Director for Standard & Advanced Reactors, 78/11/13. ip. 94272:170.
- 7811270154 Forwards Startup Rept#8 for subj Facil covering the period 780522 to 780822. MARCHEOURG, D. Public Service Co. of Coloredo. 78/11/21. 1p. 94199:214.
- ~~7811270156 Startup Rept#8 covering period 780522 to 780822 re Feedwater Flow Control, circulator speed control main stream desugarheators, load change response & control rod calibr.

  \* Public Service Co. of Colorado. 78/08/22. 104pp. 94199: 215.

- opportunity to observe tech discussions & discuss PBC plans for fluctuation testing above 70% pur H/encl agenda KUZMCZ.O. Advanced Reactors Branch. 78/11/21 92pp 94390.162
- 7812070185 Presents ravised schedule to 781104 reactor refueling region outlet tamp fluctuations. & reflecting 781116 discussions w/NRC Region restraint device installation delay SAR should be ready by Jan 1979. FULLER, J K. Public Service Co. of Colorado. 78/11/27 3pp. 94375:04D.
- 7812080021 Notice of meeting w/PSC on 781214 to discuss data & conclusions re fluctuation test where steam temp limits were excessed KUZMYCZ.O. Advanced Reactors Granch 78/11/30. 2pp. 94103:361.
- 78:2110242 Summery of a 78:1116 meeting re fluctuations at facility.
  Description of sequence of events during fluctuations
  & preliminary data from 78:1104 events enci.
  KUZMYCZ.Q. Advanced Reactors Branch. 78:/11/30 Sapp 94337:156.
- 7812110292 Responds to 7804il request for elemption to 10CFR21 requirements, Suggests that 781019 commission amend to 10CFR21 may sliminate need for such exemption. DENTON.H.R. Defice of Nuclear Reactor Regulation. Director. 78/12/01. 1p. 94204:030.
- 7Bi2i30164 Establishes new sched for action pian for identifying the instructrip settings & the absolute limiting values originally set out in itr to NRC of 770920. Also details present status of prog.

  MILLEN.C. K. Public Bervice Co. of Colorado. 78/12/05. 10pp. 94305:122.
- 7Di 2280090 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants Info submitted must be substantiated by data & calculations. Licensee must notify NRG of any inaccuracies or enforcement action will result. DAVIB, J. Q. Opfice of Inspection & Enforcement, Office of the Director, 7B/12/06. 2pp. 03555:305.
- 78:2:8032: Responds to FOIA request re environ impect statements submitted by Atlas Minerals Uranium Mill & addi records of euby facil. Copies will be placed in PDR in Greeley.Co. FELTON.J.H. Division of Ruiss and Records. 78/12/11. 2pp. 94355:293.
- --7812180323 Requests add1 info re draft & fine1 environ impact statems for Atlas Minerals Uranium Mills & worker health & safety info.Also requests info re control of reactor temp pecillations & mech vibrations. PULB.M. Affiliation Unknown. 78/11/12 2pp. 94336:295.
- 7812200164 Forwards corrected pages to Bth startup rept inti Module Main Steem Temp Trim Control.Load Change Response.Feeduster Flow Control & Deserator Level Control. MARE/HBDURG.D. Public Service Co. of Colorado. 78/12/15 Spp. 94157:342
- 7812270177 Forwards responses to questions raised at 781104 meeting & description of Firswatsr Squester Pump installation, design & results of functional tests after installation, FULLER, J. K. Public Service Co. of Colorado. 78/12/18. 65pp. 01791:057.
- 78:2270182 Summary of 78:215 meeting of Tech Review Comm for Review of Temp Fluctuations in subj facil. Topics discussed incl comparison of displacement probe & nuc detector signals & info on core status. FRY.D. N. Dak Ridge Netional Laboratory. 78/12/19. 17pp. 94017:342.
- G. Inspection reports, iE Builetins & correspondence
- 7810110304 Forwards IE Inspec Rept #50-267/78-13 on 780807 & Notice of Violation.

  MADEEN, Q. L. Region 4, Dallas, Office of the Director. 78/08/18.

  2pp. 94061:001.
- --7810110306 Notice of Violation from inspec on 780807-11.

  \* Region 4. Dallas, Office of the Director. 78/08/18. ip. 94061:003.
- ---7810110308 IE Inspec Rept#50-267/78-13 on 780807-11 during which 1 is of noncompliance was noted: failure to follow procedures redisposal of combustible & maint of recording equip.
  DICKERSON.M.M. Region 4, Dellas, Office of the Director.
  78/09/18. 8pp. 94061:004.

- Branch. 78/09/19 1p 94068.244.
- --7810110264 Responds to 780818 NRC ltr re violation noted in Inspec Rept#50-267/78-13 Corrective actions:continuous monitoring of Admin Procedure requirements. MILLEN.C K. Public Service Co. of Colorado. 78/09/11. ip. 94322,361.
- 7810230350 Forwards 1E Circular#78-17. (See AND: 7810230221 Docket 50-133.781013)
  SEVFRIT.K. V. Region 4. Dellas. Office of the Director. 78/10/13
  1p. 94169:189.
- 7812180328 Forwards 1E Inepsc Reptm30-267/78-16 on 781016-20 during which no items of noncompliance were noted. MADEEN.Q.L. Region 4. Dellas, Reactor Operations Nuclear Support Dranch. 78/11/03. 2pp. 94357:320
- --7812180331 fE inspec Rept#50-267/78-16 on 781016-20 during which so items of noncomplience were noted Major areas inspected inclingenization & admin.64 progression.70X per level date review 80 review of startup rept & LER's DICKERBON.H.M. CUPP.E.A. Region 4, Dellas, Reactor Operations Nuclear Support Branch. 78/11/03. 7pp. 94357:322.
- 7011920121 Forwards IE Circular#78-18, "UL Firs Test." W/enc! AND:7811150002. GEYFRIT, K. V. Region 4, Dallas, Office of the Director. 78/11/06. 1p. 94074:208.
- 7812190187 Forwards IE Inspec Rept#50-267/78-15 on 781016-19 during which no items of noncompliance were noted. MADEEN, O.L. Region 4, Dallee, Resctor Operations Nuclear Support Branch. 78/81/08. 2pp. 94414:297.
- --7812190193 JE Inspec Rept#50-267/78-15 on 781016-19 during which no items of noncompliance were noted Mejor areas inspected incl: radwaste says incl liquid & gaseous radioactive effluent releases & record repts of effluents
  HURRAY, B. Region 4, Dalles, Office of the Director, 78/11/06, 7pp.
- 7812290239 Forwards IE Inspec Rept#50-267/78-18 on 781103007 during which no Items of noncompliance were noted. HADGEN.O.L. Region 4, Dailas. Reactor Operations Nuclear Support Branch. 78/11/28. 2pp. 94191:239.
- --7812290244 IE Inspec Rept#50-267/78-18 on 781105-07 during which no items of poncompliance were noted Hajor areas impacted incl: Emergency Planning Prog incl coordination w/offsite support agencies.

  HURRAY, B., HARRISON, H. G., DROWN, G. D. Region 4. Delias, Reactor Operations Nuclear Support Branch. 78/11/28. App. 94191:241.
- R. Periodic operating reports & related correspondence
- 7812180243 Forwards Monthly Open Rept for July 1978. 8WART-F.E. Public Service Co. of Colorado. 78/08/23. 1p. 94338:354.
- --7812180245 Monthly Oper Rept for July 1978. HILLYARD, H. M. Public Service Co. of Colorado. 78/07/31, Spp. 94389:335.
- 7810160103 Monthly Open Rept for Sept 1978.

  OAHM J.M. Public Bervice Co. of Colorado. 78/10/01. Spp.
- 7810160100 Forwards Monthly Oper Rept for Sept 1978
  MAREHBOURG. D. Public Service Co. of Colorado. 78/10/09. 2pp.
  94001: 336.
- 7811070234 Forwards Monthly Open Rept for Oct 1978.
  WAREHBURR, D. Public Bervice Co. of Colorado. 78/11/02. 1p.
  94039: 181
- --7B11070238 Montbly Oper Rept for Oct 1978. OAHN.J.M. Public Bayvice Co. of Colorado. 78/11/02. 5pp. 94039:182.
- 7812130163 Forwards Monthly Open Rept for Nov 1978.
  WAREMBOURG, D. Public Service Co. of Colorado. 78/12/04. ip. 94205:138.

- OAHM-J.W. Public Service Co. of Colorado. 78/12/01. 5pp. 94305.139.
- 8 Reportable occurrences, LERs & related correspondence
- 7810300164 Forwards LERM78-029/03L-0 MAREM80URQ, D. Public Service Co. of Colorado. 78/09/27. 1p 94094:194.
- --7810300186 LERR78-029/03L-0 on 780829 during routins check of LCO compilance,1 emergency generator diesel oil day tank was found to be below the 300 gallon level Cause was fuel oil pump transfer which does not start until 350 gallon level 84Mt,J.W. Public Service Co. of Calorado. 78/09/27. 359 94034:135.
- 7810300189 Forwards LER#78-018/03X-2.
  WARDMBOURG, D. Public Bervice Co. of Colorado 78/09/27. 1p.
- --7810300194 LER#78-018/03X-2 on 780713: during period 780713-780908.1 primery content exidents exceeded 10 0 vpm w/core average outlet tamp greater then 1,200 degrees F. Source of moisture ingrees is undertermined Reactor shut down. GANN.J. M. Public Bervice Co. of Colorado. 78/09/27. 10pp.
- 7810160131 Forwards LERM78-30/03L-0.
  WAREMBOURG, D. Public Service Co. of Colorado 78/10/05. 1p. 94005:306.
- 7810300179 Forwards LERW78-030/03L-0. WAREHBURG9,D Public Service Co. of Colorado. 78/10/05. 1p. 94034:225.
- --7810300180 LERA78-030/03L-0 on 780912:5 hydraulic anubbars were for inoper due to ampty oil reservoirs. Reservoirs were refilled & surveillence interval adjusted.

  QAMM\_J.W. Public Service Co. of Colorado. 78/10/05. 4pp. 94034: 226.
- 7810300309 Forwards LER#77-036/03L-1.
  MARPHBOURG, D. Public Sarvice Co. of Coloredo. 78/10/05. ip. 94271:115.
- --7810300313 LERM77-036/03L-1 ON 771115: during normal open the reactions open w/everage core outlet time greater than 12000 F to w/ the sum of water.CO t CO2 primery coolent impurities in excess of 10ppm/val.caused by operator error. QAMILJ.W. Public Service Co. of Colorado 78/10/05. SPP. 94271:116.
- 7810270228 Forwards LERW78-031/03L-0.
  WAREMBURG, D. Public Bervice Co. of Colorado. 78/10/24. ip. 94032-242
- --7810270232 LERB78-031/03L-0 on 780925: during routine testing, i of heating ventilation & air conditioning eys isolation dempera for 480 volt switchpser room would not shut-due to faulty O-ring in damper jamming open ectuating wheft. QAHHIJM. Public Service Co. of Colorado. 78/10/24. 4pp. 94053: 243.
- 7B10270276 Forwards LER#78-025/01-X-1.
  WARCHEOURG.D. Public Service Co. of Colorado. 7B/10/24. 1p. 94027: 327.
- --TB10270283 LERM78-025/01x-1 on 780703 w/lose of pur to one of two redundant pps logic sys.circulator seal malfunction (buffer-mid-bufsy) of a heium circulator was inhibited caused by logic design problem.

  GAMM.J.M., REDD.A. Public Service Co. of Colorado. 78/10/24.
  10pp. 94027:328.
- 7810310225 Forwards LER W78-032/03L-0.
  WARCHEOURG, D. Public Service Co. of Colorado. 78/10/27. 1p. 94090:347.
- --7810310230 LER #78-032/03L-0: on 780928, surveillance check of fixed flow alarm bistables for primary coolant dew point moisture monitors not performed. Later less that acceptable alarm setpoints discerned. Cause: requirements misinterpreted. GAPCH.J. W. Public Service Co. of Colorado. 78/10/27. 4pp. 94090:348.
- 7811280285 Forwards LER#78-016/03X-1, WAREHBOURD, D. Public Service Co. of Colorado. 78/11/22. 1p. 94395:236.

- --78/1280289 LERW/8-018/03x-1 on /80310 while oper at 40x per-moisture concentrations in PCRV exceeded limits of 4.2.11 Moisture was introduced during previous Loop 1 shutdown & collected in PCRV insulation OAHM, J. H. Public Bervice Co. of Colorado. 78/11/22. App. 94375; 227.
- 7811280312 Forwards LER#78-033/03L-0
  WARDMBOURD, D. Public Service Co. of Colorado. 78/11/22. lp.
- --7811280318 LERM78-033/03L-0 on 781027: during routing surveilisnce of steam pipe rupture detection system of three bietables for high temperature under PCRV did not trip, due to corroded cable terminal board at junction box. QAMLJ.W. Public Service Co. of Coloredo. 78/11/22. 4pp. 94395:311.
- 7812120089 On 781129 at 4:00 pm due to problem in helulm circulatory systhems was a minute raisess of radioactivity in reactor bids. No heserd to public. OASCHLER.J. A Public Service Co. of Coloredo. 78/12/05 ip. 94274:192.
- 7812/30273 Discusses minor release of activity at subj facil on 781129. Breach in aftercooler of "B" hellum buffer compressor let weter enter gas alde & circulate through buffer sys-which ultimetely opened relief valves.latting 1 curls gas escape. XUZNYCZ. a Advanced Resctors Brench. 78/12/05. 3pp. 9491:324.
- 7812130135 Forwards LER878-034/03L-0.

  MARDHBURG, D. Public Service Co. of Colorado. 78/12/06. 1p.
- --7812130141 LER#78-034/03L-0 on 781107: during normal open a release of reactor bldg sump effluent req cooling tower bloudoum flow to increase shove normal rate to 4.39 million gellons for the day dus to need to dilute sump effluent discharge. DAMALH. Public Service Co. of Coloredo. 79/12/05. 3PP. 94307:064.
- 7812130190 Forwards LERH78-018/03x-3.

  WARDHSUNG, D. Public Service Co. of Colorado. 78/12/06. 1p. 94306:024.
- --7812130192 LERB78-018/03X-3 on 781009.primery coolent oxidant concentration exceeded 10vpm w/core everage outlet temp graeter than 1200 degrees F. Caused by eccumulation of weter in PCRV insulation.

  OMMI.J W. Public Service Co. of Colorado. 78/12/04. Spp. 94306:025.
- 7812130172 LERM78-014/03L-0 on 781007: Control Rods 3 & 8 of Group 6 drapped at 0405 t 0413 respectively due to faulty normal pur supply fees. Faulty fuse has been replaced.
  WILBON-K. R. Duta Power Co. 78/12/07. 2pp. 94294: 353.
- 781R130176 Forwards LER#78-005/03x-1.
  WARPHBURGO,D. Public Service Co. of Colorado. 78/12/07. ip. 94305:171.
- --7B12130179 Suppl info to RD#50-267/78-05/03-X-1 on 7B1107: during oper at 13% thermal & O elsc pur one of three 1A circulator speed indication channels was at 0.due to bridge unbelence. Similar problem occurred 7 times since 780425 FERIS.M.J., GAMM.J.M., MAREMBOURGO.D. Public Service Co. of Colorado., 78/12/07. 6pp. 94305:172.
- --7812130185 LER#78-005/03X-1 on 781107:malfunctions in lA.1C & iD circulator speed measurement caused loss of high speed circulator signels on different dates due to size circult unbalance & signel cable resistence change in modifiers. OAMI, J. W. Public Service Co. of Colorado. 78/12/07. 7pp. 94305:178.
- 7812200209 Forwards LER#78-035/03L-0. WARCHEURGO, D. Public Service Co. of Colorado. 78/12/14. 1p. 94162:280.
- --7812200210 LER878-035/03L-0 on 781114:4 of 6 high pur Rod M/drawel Prohibit trip points were set too high. Accepted test procedure voltage range permitted RHP to be set higher than Tech Specs ailow. QAHM, J. W. Publit Service Co. of Colorado. 78/12/14. 4PP. 74162:281.
- 7812270201 Forwards LERM78-027/03x-1.
  WARDMOURD, D. Public Service Co. of Colorado. 78/12/20. ip. 94017:213.

- -7812270206 LERW78-027/03X-1 on 781204: ITT Barton Model 289 hellum circulation seel malfunction pressure differential switches failed to activate at trippoint due to dirt accumulation in switches. Trip sattings being thatked on monthly basis. GAM, J. H. Public Servica Co. of Colorade. 78/12/20 Spp. 94017-214
- U. Congressional/Executive Correspondence
- 7811220132 FOIA request for encl list of communications pertaining to subj facil.
  HASHELL, F. M. Benets. 78/11/01. 3pp. 94074-260
- 7811220128 Responds to 781101 FDIA request Forwards list of 23 documents related to subj facil.
  FELTON.J.M. Division of Ruiss and Records 78/11/15 3pp 94074:184
- DOCKET 30-269 OCONEC NUCLEAR STATION, UNIT I

  A Application/construction stage documents & correspondence
- 78:11:30133 Notice of stemption from provisions of 10CFR30.46 for Litense DPR-38. Although facility does not comply w/ requirements for ECCB. Tech Specs will provide protec against smell break LOCA BIELLO.V. Division of Operating Reactors 78/10/23. Spp 94272:272.
- E. NRC Sefety Evaluation Report (SER). supple & correspondence
- 7811020014 Bupplaments 780811 Bafety Eval of subj facil Found LPBN syspiping arrangement acceptabls. Deletes requirement to provide spers dedicated cables for LPBN syspump motors.

  REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/05. 2pp 94351:247.
- F. Security, medical, emergency & fire protection plans
- 7810180126 Forwards proprietary info consisting of Change#8 to RevM5 o subj fac;1 security plan. W/o proprietary info. PARKER, U. Dute Pawar Co. 78/10/06 32pp
- 781031000B Forwards Revision 2 of modified shanded security plan (MASP). Enci withheld (ref 100FR2, 790).
  PARKER, M. O. Duts Power Co. 78/10/19. 2pp. 94093: 360.
- 78:12:0032 Bummery of 78:1025 meeting to discuss quel of Station Health Physics at suby facil. NRC requested util to submit rev Tach Bpac. FARTILE, M. Operating Reactors Branch 4 (Pre 790623). 78/11/02. 2890. 94486:358
- 7812060019 Bunmary of a 781025 meeting re sub; facil Station Health Physicist. FAIRTILE.M. Operating Reactors Branch 4 (Pre 790625). 78/11/02. 3pp. 94415:330.
- Q. Adjudicatory correspondence
- 7812080225 Ack receipt of 781018 ltr re util proposel to transport sut facil spant nuc fuel. Ltr will be forwarded to ASLB in order to be considered as a written limited appearance statement. H/encl ANO: 7811130267 KETOHEN.E. O. Office of the Executive Legal Director. 78/11/20. 3pp. 74137:114.
- P. Operating license stage documents & correspondence
- 7810110025 Request for all info re rediet laskegs & safety problems event fectla.

  QRECON, M. J. Gordon, Walter J. 78/09/08. ip. 94063:124.
- 7810230158 Forwards check for \$8300 to cover eddl lic fees for NRC review of Cycle 5 rejected amend for subj facil. PARKER(M.Q. Duke Fower Co. 78/10/03. 2pp. 94164:260.
- 7810130136 Requests return to 1 gpm ellowable leekage rete for subj facil because 0.3 gpm leek rate results in severe hardship in leek detection resulting in extresive loss of election resulting in extresive loss of elec

PARKER. H D Duke Power Co 78/10/05 1p. 94003: 051.

- 7810260149 Notification of forthcoming meeting with Duke Pur Co on 781025 to discuss goels of Radiat Protes Manager FAIRTILE.N B. Operating Reactors Branch 4 (Pre 790625) 78/10/17. Ip 94055:336
- 7811080107 Responds to 703012 PRC request for info re amend to lic MERM-1773 for spent fuel shipment to McQuire Finds that refracting Ocones spent fuel pool is tech feesible as a possible future action, but requests processing of appl now PARKER, W.D. Dute Power Co. 78/10/18 6pp. 94399 141.
- 7810240147 Dus to Inaction on subj Facil 781007 proposal for Yach Hosc rev to incorporate staff position for voltage monitors that proposal is rescinded PARKER-N.O Duka Power Co. 78/10/19. Ip
- 7810250153 Rights 2 stram generator tube plugs which uses being installed during current refueling outage have not been located Startup with plugs unrecovered prasents no significant safety herard PARKER. H D. Duke Power Co 78/10/19 App
- 7810300182 Responds to 781010 NRC 1tr 5 remits fas for revisu of cycle 4 reload enend PARKERS U. Dute Power Co. 78/10/20 2pp 94030.159
- 7810250062 Confirms conversation w/M Fairtiis is advice that DOE funding of extended fuel burnup irrediat at subj facil does not commit DOE to fund any future such irrediats or restrict future alternatives for LMR fuel cycls LANG.P M. Energy. Dept of 78/10/23 lp.
- 7810270129 Provides info re sffacts of heat in a dry soviron on an unesplodes steam generator plug in response to question re BAR based test results Concludes that possibility of detonation of unasploded plug in dry soviron is negligible PARKER, U Duke Power Co 78/10/23 ip 94057:110
- 7811070013 Forwards Amends 65.65 & 62 to Licenses DPR-38.DPR-47 & DPR-55.respectivally-changing Tech Space is full rated pur Cycls 5 open after core rejoad ramovel orifice red assemblies from core & High Pressure injection Pump open. REID.R.H. Operating Reactors Dranch 4 (Pre 790625) 78/10/23. 3pp. 94036:290
- --7811070055 AmandWA5 to Facil Oper Lic4DPR-38.changing Tech Specs REID.R W. Operating Resolves Drench 4 (Pra 770625) 78/10/23 2Pp. 94036:293.
- --7811070057 Amend#65 to Facii Oper Lic#DPR-47 changing Tech Space. REID-R. W. Dearating Resetors Branch 4 (Pre 790625). 78/10/23 200. 94038:295
- --7811070060 Amand#62 to Facil Oper LiceDPR-55.changing Tach Space. RELD-R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23 25p. 94036:297.
- --7811070063 Exempts subj facil from iOCFR80.46(a)ra rasctor cooling until med is complete or until next refualing shutdown.

  8 TELLO-V. Division of Operating Reactors. 78/10/23. Spp. 94036;322.
- --7811070068 Safaty evolution & EIA supporting Amend 65 to Lic DPR-3B.
  Amend 63 to Lic DPR-47 & Amend 62 to Lic DPR-55. Concludes
  that it is accaptable for Cycle 5 oper to proceed & that
  EIA not raq.
   Office of Nuclear Reactor Regulation, Director. 78/10/23.
  1792 9 4036: 330.
- --7811070071 Notice of Issuance of Amsnd#65 & 62 to Facil Opsr Lic#DPR-38.0PR-47 & DPR-55, respectively, rev Tack Specs to support fuil rated pur oper during Cycls 6 after core reload adding High Pressure Injection Pump rays & fusl demonstration prog. REID, R. W. Operating Reactors Branch 4 (Pre 790625). 78/10/20. 29p. 94036:1349.
- 7911170324 Notice of Issuance of Amend#62 & 63 to Oper Lic#OPR-39,47 & 53. Amend rev Tech Specs allowing full rated per during Cycle 5 after core raload & permits use of 5 praviously burned fuel assemblies.
  REID.R.H. Operating Reactors Stanch 4 (Pre 790625). 78/10/23, 288.02766:243.

- PARKER, H. O Duke Power Co. 78/10/26. 2pp.
  - 7811020355 Notice of ray to Tech Spec 3.7 re Auxiliary Siec Sye Spec 3.7.1 is rev to clearly define onsite smergency transmission peths in 12000 Instr Control Bys-& rev 3.7.2 re elec sys degraded mode oper.
    PARKER.W.O. Duks Power Co. 78/10/31. 6pp. -94247:138.
  - 7811170029 Requests additinfo in order to complete review of submittals dtd 780714 to 781006 re permanent mode to High Pressure Coolent Injection Bys at subj facil Requests info in 20 days.

    REID.R W Deresting Reactors Branch 4 (Pre 790626). 78/10/31. 3pp. 74049, 182.
  - 78ill40ll4 Responds to 78i031 request for add1 info re mod of high pressure injection systepecifically small bresh ECCB mod. PARKERTH O Duke Power Co. 78/11/06. 4pp. 94425:155.
  - 7811140065 Confirms conversations or 780705 proposed open lic change repossible receipt of 4 fuel assembliss from FL Pur Corp.
    Requests withdrawsi of proposed lic amend & indemnity agraement(B-44) & refund of lic fee.
    PARKER/M O Duke Power Co. 78/11/07. 1p. 94133:121.
  - 7811160079 Rescinds 780523 request for NRC concurrence re proposed changs to respiratory protect sys.
    PARKER, U. Duts Power Co. 78/11/07. ip. 94123:175.
  - 7811160134 Responds to 781011 NRC comments on minimum qualifications of station Health Physicist Considers requirements in ANSI/ANS-3 1-1978 to be appropriate.
    PARKER, H. D. Duka Power Co. 78/11/07 ip. 94135: 235.
  - 7811270:18 Forwards 3 praviously omitted Tech Bpac pages 2 9-1, 2-3-3 b 2 3-111for Lic AmendW65, 65 & 62 covering limiting safety sys sattings 2 protect instru.
    REID.R.W. Operating Resoltors Branch 4 (Pre 790625). 78/11/08 5pp 94271:266.
  - 7811200421 Forwards results of measurements of radiosctive meth in NRC phantom on whole body counter. Encl i contains actual amount of such radionuclide present encl 2 gives ratio of measurements to DDE velues & encl 3 gives recommendations. BUTHERLAND. J. T. Region 2. Atlants. Fuel Facility & Meteriais Sefety Branch 78/11/09. 3pp. 94419:175.
  - 7811210292 Notifies util of 781205 seminar in Atlanta to discuss RBW Model Rod Effluent Tach Specs & encl seminar info sheet, ragistration form. & proposed agenda.
    D'REILLY, J. P. Region 2. Atlante, Office of the Director. 78/11/09. 5pp. 94488:126.
  - 78:1210306 Notifies util of 78:205 seminar in Atlante to discuss new Model Rod Effluent Tach Space & ancl seminar info chest, registration form. & proposed agenda.

    D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09. 389. 94488:091.
  - 7811300035 Forwards NRC staff paper, Policy Bession Itsm(8ECY-78-554) re licenses rag performance evalution. Three methods for evaluation ara: statistical trend analysis & regional survey method W/o enci. D'REILLY, J. P. Region S. Atlanta, Office of the Director. 78/11/15 2pp. 94070.351
  - 7812150123 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pra-workshop registration of attendess to facilitate sending out math. M/encl Registration Form & List of Locations.
    MILLER. J. R. Assistant Director for Site & Bafeguards (Fre 791030).
    78/11/13. Spp.
  - 7812190031 Forwards Ray#1 "Draft Madiologics) Effluent Tech Specs" for PWR's(NURED-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NURED-0133). W/p encl ANG: 7811270173 & 781127018.
    ORIMES.S.K. Assistant Director for Engineers & Projects (Pre 7906251. 78/1/1/15 App. 94814:033.
  - 78ii300379 Informs DPC that NRC has contracted w/Mountain Wast first oundertains a series of post-licensing studies of nur first stations. Studies will enalyre socioecon impacts which occurred during constr & post-constr periods of each plans. DEYOUNG.R.C. Division of Site Safety & Environmental Analysis. 78/11/20. 2pp. 94i36:252.

- THE COURT OF IT reg of HIOCFR part B1 Rule emended 781019 & provided relief reg or wall requested. DENTON: H. H. DF Office of Nuclear Reactor Requistion, Director.
- 7812000260 Response to 780905 ltr requesting esemptions from certain reg of BiOCFR Part 21 Rule amended 781019 & provided relief DENTON. H. R. Office of Nuclear Reactor Regulation, Director. 78/11/24. 2pp. 94371:337.
- --7812060272 Requests exemption from 10CFR21 re procurement of various standard stock items from Cutler Hammer. Inc. Procurement delays will affect constr sched. PARKER, W. O. Duke Power Co. 78/09/05. 3pp. 94371: 339.
- 7812060272 Requests exemption from IOCFR21 re procurement of various standard etock itsms from Cutter Hammer, Inc. Procurement dalays will affect constr ached.
  PARKER.H.O. Dute Power Co. 78/09/05. 3pp.
- 7812040231 Requests relief from reg of ASME Code Saction Xi.Article IMC 500 Request concerns sys pressure test found to be PARKER, M. D. Duke Power Co. 78/11/28. 7pp. 94325:348.
- 7812150083 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests wither commitment to limit purging or justification for continuing. W/sncl AND. 7812080207. Operating Reactors Branch 4 (Pra 790625). 78/11/29. App. REID. R. W 94210: 330.
- 7812180131 Expects that mod of high pressure injection sys at subj facils can be implemented for each unit during first available outage of eched duration sufficient to install PARKER, W. O. Dute Power Co. 78/12/04. 1p. 94364: 278.
- 7812280173 Emphasizs importance of aubmitting accurats & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations Licenses must notify NRC of any insecuracies or anforcement action will result. DAVIB-J.Q. Office of Inspaction & Enforcement, Dffice of the DAVIB, J. Q. Office of Inspection & Enfo Director. 78/12/06. 2pp. 94375:015
- 78:2:20:175 Provides preliminary results of recent refusing outage of subj facil; Some avidance of eresion or corrosion defect growth was present & is currently being systumeted. A final rept will be provided by 790:24.
  PARKER, H. D. Dubs Power Co. 78/:2/07. \$p. 94305:170.
- 78:226000: Accepts proposed design mod to High Pressure Injection (HPI) sys consisting of installing cross-current lines between discharge lines of HP1 sys W/Bsfety Eval. LAINAB.G. Plant Systems Branch (Pre 791030). 78/12/07. Ap. 44030:271.
- 7812260062 Porwards Befety Eval Rept for subj facil re mpd to high pressure injection sys. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/13. 2pp. 74021:271.
- --7912260064 SER "Mod to High Pressure Injection Bys. "Concludes design mod to HPIB will ansurs that for all postulated single failure conditions. HPIB will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths.

  a Operating Reactors Branch 4 (Prs 770625), 78/12/19, App. 74021: 273.
- 7812280238 Forwards Amend#55.55 % 63 revising Tack Space re subj facils control rod operability. Forwards Bafety Eval. Notice of Issuance, & Notice of Exemption.
  REID.R.W. Operating Reactors Branch A (Pre 790625). 78/19/18. 3pp. 94355:258.
- --7812280247 LiceDPR-38, DPR-47. & DPR-35 for Amende 66.66. & 63: Tach Specs proposed changes re control rod operability & support of United full rated pur during Cycle 4 after core reload & removal of prifice rod assemblies from core. REID.R.W. Operating Reactors Branch 4 (Pre 790628). 78/12/18. 36pp. 94288:261.
- --7812280261 Notice of Exemption of DPR-47 from 10CFR50.46(a)(1) requirement that ECCB performance be calculated in accordance w/celculation models per 10CFR80, App N. BIELLO, V. Division of Operating Reactors. 78/18/15. 9pp. 94195: 286.

- Amend 63 to DRR-55 Concludes that proposed Tach Spac changes do not involve a significant hazard-health or safety consideration. # Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp.
- 94355: 306.
- --7812280267 Notice of Issuance of Amend 66 to DPR-38.Amend 66 to DPR-& Amend 63 to DPR-35 revising common Tach Specs to support the oper of Unit82 full rated pur during Cucle 4. ZNET210.0.D. Operating Reactors Brench 4 (Pre 790625). 78/12/15.
- 7812270244 Forwards proposed rev to subj facil Tech Spacs. Proposed exception: 3.3.6(f):would allow insperability of one Reactor Bldg Spray Pump for up to 72 hours provided all Reactor Oldg Cooling Units are operable.Wattach affidavit. PARKER:W O. Duke Power Co. 78/12/22. 4pp 94017 155.
- Q. Inspection reports, IE Bullatine & correspondence
- 7810130056 Ack receipt of IE Imap Repts 50-269/78-17.50-270/78-17 & 50-287/78-18 on 780807. No proprietary info PARKER. M. O. Duks Power Co. 78/09/27 ip 94079-185.
- --7810130060 Forwards 16 Insp Rept 50-269/78-17.50-270/78-17 & 50-287/78-17 on 780807. No noncompliance noted. SUTHERLAND.J T. Region 2. Atlanta. Fuel Facility & Materials Branch. 78/09/20. 2pp 94079 186
- --7810130064 IE lnsp Rapts 50-269/78-17.50-270/78-17 & 50-287/78-19 or 780807. No noncompliants noted Hajor aress inspected: whole body counting practices & test count of NRC phantom 01860N.A F. Region 2. Atlante. Fuel Facility & Materials Gafety Branch. 78/09/20. 4pp. 94079:188.
- 7811030221 States that prog has been astablished to eddress IE Circula 78-08 Review of adequaty of qualifications of each place of equip will be completed by 790416.

  PARKER.M. Q. Duke Power Co. 78/09/29. 1p. 02724-250.
- 7810230287 Forwards 1E Circular#78-17. (Bas AND 7810230221. Docket 50-313.7810131 O'REILLY, J. P. Region P. Atlanta, Office of the Director. 78/10/13.
- 7811100103 Ack receipt of 781016 itr informing NRC of steps taken to correct violations noted during inspec#50-269/78-18. #50-270/78-18 #80-287/78-19. KENNA-W.B. Region 2, Atlants, Safaguards Branch. 78/10/26.

94173: 356.

- --7811100110 States info contained in 781016 itr is proprietary pursu to Section 2.790 & is to be withheld. PARKER, W. D. Dute Power Co. 78/10/16 1p. 94173:357.
- --78;11001;5 Responds to 780919 NRC ltr rs violation noted in Inspec Repts850-269/78-18,480-270/78-18 & \$50-287/78-19 Corrective action withheld (rsf 1QCFR2 790). PARKER, W. O. Duka Power Co. 78/10/06. ip. 94173:358.
- --7811100124 Forwards summary of IE Inspec Repts#30-269/78-18. #50-270/78-18 & #50-287/78-19 on 780815-17.Notice of Violation withheid pursuant to 2.790. KENNA.M. B. Region 2. Atlanta. Office of the Director. 78/09/19. 2pp. 94173: 359.
- --7811100130 IE inepac Repts#50-269/78-18.#50-270/78-18 & #80-287/78on 780815-17 during which 1 item of noncompliance was noted; tasting of alarms.
  BEBECKER,K.H. OLLESPIE.F.P. Region 2. Atlanta, Office of the Director. 78/09/18 ip. 94173:361.
- 7811180085 Forwards 1E Circular 78-18. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/02
- 7811280378 Ack receipt of 1E Inepet Repts#50-269/78-22, #50-270/78-22, #50-287/78-23 on 780918-22 Does not consider any info therein to be proprietery. PARKER, N. O. Duke Fower Co. 78/11/09. 1p. 94397:251.
- --7811280390 Forwards IE Inspec Rapta#50-269/78-22, #50-270/78-22 & #80-287/78-23 on 780918-22 during which no items of noncoapliance were noted. LONO,F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/18. 2pp. 94397:252.

- --78:1280398 IE Inspec Repts#50-269/78-22.#50-270/78-22 & #50-287/78-23 on 780918-22 during which no items of noncerptients were noted. Major areas inspected included unresolved items, special repts.action on IEC 78-08 LEMIS.R. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/18. App. 94397:254.
- 7812180320 Forwards IE Inepsc Repte#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of noncompilance were noted.

  LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94056:285.
- 7811220110 inspec Rept 50-269/78-23 insovertantly named Oconse Unit 3, should be Oconse Unit 1.

  LONG.F.J. Region 2, Atlente, Reactor Operations Nuclear Support Brench. 78/11/13. ip.
- 7812120033 Forwards reproductions of articles that appeared in June & Aug 1978 additions of Nuc Security Befaguerds Newsletter. KENNA, N.B. Region 2, Atlanta, Safeguards Branch. 78/11/17. 4pp. 94278:072.
- 7812050021 Ack receipt of 781120 ltr informing NRC of steps teken to correct violations nated during inappres850-269/78-15. #50-287/78-16. #50-287/78-15. #50-287/78-16. #SUTERENAND.J.T. Region 2. Atlanta, Fuel Fecility & Meterials Bafaty Stench. 78/11/20 1p. 94200:270
- --- 7812050025 Responde to 780929 NRC ltr rs vibiations noted in inspec Repta#50-269/78-15,#50-270/78-15 & #50-287/78-16.Corrective actions: entrances to interim wests fecil posted w/redist eigns & spent fusi cask reboited & retorqued for shipment. PARKER, W.O. Duka fower Co. 78/10/25. 4pp. 94200:271.
- --7812050029 Forwards IE Inspec Repts#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 & Notice of Violation.

  UMEILLY.J.P. Region 2. Atlanta, Office of the Director. 78/04/29. 2pp. 94200:275.
- --7812050030 Notice of Violation from Inspec on 780724-28 k 780901-04. \* Region 2. Atlanta. Office of the Director. 78/09/29. ip. 94200:277.
- --7812050031 1E inspec Repts#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 X 780801-04 during which 2 items of noncomplience were noted: fasions to properly peck cosk for shipment & to perform radiat surveys in interim waste bldg. HDBEY.C. M., JENKINB.G.R., QIBBUN.A.F. Region 2, Atlente, Fuel Facility & Materiale Bafety Brench. 78/09/28. iipp. 94200:278.
- 7812060320 Ack recaipt of IE Inspec Rept#50-269/78-23 on 780926-29. Does not consider any info therein to be proprietary. PARKER, U. D. Duke Power Co. 78/11/21. 19. 94332:040.
- --7812060329 Forwards IE Inspec Rept#50-269/78-23 on 780926-29 during which no items of noncompliance were noted. LCNQ,F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/21. 2pp. 94332:041.
- --7812060333 IE Inspec Rept#50-269/78-23 on 780926-29 during which no items of noncompliance were noted. Hajor areas inspected inclinational maintenance accomplished on safety-related equip incl procedures & plant work requests.

  JCHN80N.A.H. Region 2. Atlants, Office of the Director. 78/11/21.6pp. 94332:043.
- 7812040326 Act receipt of 781106-ltr informing NRC of eteps teken to correct violations noted during inspec#50-269/78-20, #50-270/78-20, #80-287/78-21.

  BUTHERLAND, J. T. Region 2, Atlants, Fuel Fecility & Meterials Safety Branch. 78/11/22. 1p. 94130:353.
- --7812040328 Responds to 781018 NRC ltr re violetions noted in Inspac Repts850-289/78-20, 850-270/78-20, 850-287/78-21, Corrective actions: door lock mod to prevent unlocking w/o key. PARKER.W.O. Duke Power Co. 78/11/06. 2pp. 94130:354.
- --7812040332 Forwards IE Inspec Repts#50-269/78-20, #50-270/78-20, #50-287/ 78-21 & Notice of Violetion. SUTHERLAND.J. T. Repion 2. Atlanta, Fuel Facility & Materials Sefety Stanch. 78/10/18. 2pp. 94130:356.
- --7812040335 Notice of Violation from Inspec on 780911-15.

   Region 2. Atlanta. Fuel Facility & Materials Sefety Branch.
  78/10/16. ip. 94160:358.

- --7812040339 IE Inspec Repts#50-269/78-20,#50-270/78-20,#50-287/78-21 on 780911-15 during which 1 item of noncompliance was noted: fallure to keep entrance to high radiat area locked. HOSEY, C. M., QIBBON, A. F. Region 2, Atlanta, Fuel Factlity & Materiale Sefety Branch. 78/10/18. App. 94130:339.
- 7812040363 Forwards IE Bullatin878-12A, suppl to IE Bullatin 78-12.

  W/encl ANO.7811300055.

  D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 78/11/24
  1p. 94127:166.
- 7812070317 Ack receipt of IE lines Repts 50-269/78-21 & 50-287/78-22 on an 780919-21 Does not consider any info therein to be proprietery.

  PARKER, H. O. Duke Power Co. 78/11/28. ip. 94084: 339.
- --7812070019 Forwards 1E lnsp Repts 50-269/78-21 & 50-287/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHY.C.E. Region 2. Atlants. Reactor Construction & Engineering Support Brench. 78/11/02. 2pp 94084:340.
- --7812070320 IE Inep Repts 50-269/78-21 & 50-287-22 on 780719-21 during which no items of noncompilence were noted Major areas inspected incl:Corrective action on praviously identified infraction 9287/78-14-01.
  CONLON.T.E., ECONOMOS.N. Region 2. Atlenta, Reactor Construction & Engineering Support Branch. 78/11/01. 7pp. 94084:342.
- 7812130306 Ack receipt of IE Inspec Repts#50-269/78-26.#50-270/78-25 & #50-287/78-26 on 781023-27. Dose not consider any info therein to be proprietary.
  PARKER.W. 0. Dute Power Co. 78/12/05. ip. 94159:278.
- --7812130311 Forwards IE Inspec Repts#30-269/78-26.#50-270/78-25 t #50-287/78-26 on 781023-27 during which no items of noncompliance were noted. LCNG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Brench. 78/11/21, 2pp. 94159/279.
- --7812130317 IE Inspec Repte#30-269/78-26, #30-270/78-25 & #30-297/78-26 on 781023-27 during which no items of noncompliance were noted. He for areas inspected inclineview of poet flow.pur & pur distrib anomalies.

  BURNETI, P.T. Region 2, Atlanta, Office of the Director.

  JULIAN.C.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch.

  BETTENHAUBEN.L. Region i, Philedelphia. Office of the Director. 78/11/20. 3pp. 74197:281.
- 7812140041 Ack receipt of 1E Inspec Reptem50-269/78-29, #50-270/78-21 & #50-287/78-29 on 781106-08. Does not consider any info to be proprietery.
  PARKER. M. D. Duke Power Co. 78/12/05. ip. 94127:267.
- ---7812140046 Forwards IE Inspec Repts#50-269/78-29,#50-270/78-21 & #50-287/78-29 on 781106-08 during which no items of noncomplience were noted.
  LCNO/F. J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/11/22. 2pp. 94127:268.
- --781214004B IE Inspec Repte#50-249/78-29, #50-270/78-21 & #50-287/78-29 on 781104-0B during which no items of noncompliance were noted Najor areas inspected inclipiant oper & restoration of sys following refueling outage.

  JAPE.F. LEWIS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch, 78/11/22, 6pp. 94127:270.
- 7812140033 Ack receipt of IE Inspec Repts#50-269/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03. Does not consider any info therein to be proprietary. PARKER, M.D. Duke Power Co. 78/12/05. ip. 94126:330.
- --7812140055 Forwards IE Inepec Repts#50-269/78-24, #50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 during which no items of noncompliance were noted.

  KENNA, M. B. Region 2: Atlanta, Safeguards Branch. 78/11/29. 2pp. 94126: 331.
- --7812140059 IE Inegec Repte#50-249/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 1101-03 during which no items of noncompliance were nated. Hejor areas inspected incl:facil organization, shipping & receiving & etorage.

  HCDGER, J. W., CLAY, E. L., WILLIAMS, O. H., Region 2, Atlanta, Bafeguarda Branch, 78/11/24, App. 94126:333.
- 7812290072 Forwards IR Sulletin 78-14.

  O'REILLY, J. P. Region D. Atlante, Office of the Director. 78/12/19.

  Rpp. 03675:189.

PARKER, W. O. Dute Power Co. 78/10/16 19 94366 343.

- --78102000B3 Monthly Oper Rept for Sept 1978 REAVIB. J. E. Dute Power Co 78/10/16 16pp. 94366 344.
- 7810240002 Forwards Quarterly 780601-780831 rept on Jocassee Area Seismic Activity.

  PARKER, D. Dute Power Co 78/10/16 1p
- --7810240077 Quarterly Selsmic Activity Rept. (6-1-78 to 8-31-78)
  Decreased Selsmicity in Jocasses area represents diminishing site end no of joints at greater depths.
  TALMANI, P., STEVENSON, D., BAUBER, J., Bouth Carolina, Univ. of 78/10/16. 19pp.
- 7812210157 Forwards Monthly Open Rept for Nov 1978.
  PARKER, N D Duke Power Co 78/12/15 1p. 94278:195
- --7812210160 Monthly Oper Rept for Nov 1978 REAVIS-J. Dute Power Co 78/12/15 16pp. 94278.186
- 8. Reportable occurrences, LERs & related correspondence
- 7810200162 Forwards LERH78-023/01T-0 PARKER, N. D. Dute Power Co. 78/10/04. 1p. 94412.008
- --7810200170 LERM78-023/01T-0 on 780919: during annual check on boreted water storage tent level instr one channel was found out of cellbration due to error in differentiel pressura transmitter, Components were recallibrated.
  MILSON.K.R. Duke Power Co. 78/10/04. 2pp. 94412:010
- 7811020359 RD 269/78-24: on 781012 during refueling shutdown DT36 tube was found to be plugged at one end only Cause unknown VELO D.J. Dyke Power Co. 78/10/12. 1p. 94253.351
- 7811220185 Forwards LER#78-024/01T-0.
  PARKER-H. D. Dute Power Co. 78/11/15. 3pp. 94074.217
- --7811220188 LERM78-024/017-0 on 781012: during refusling outage noted that 7 OTSQ tubes which should have been plugged during earlist outages were not plugged. Caused by placement of plugs in wrong tubes due to personnel errors MILSON.H. R. Duts Power Co. 78/11/13. 1p. 94074.220.
- 7812010244 Forwards LERN78-025/03L-0. PARKER-N. O. Dute Power Co. 78/11/27 1p. 94390:133.
- ~-7812010245 LER#78-025/03L-0 on 781026; during annual RPS recalibr, the RPS trip setpoint was found to be less conservative them ellowed by Tech Spec limits. Caused by effect of temp/ humidity changes from May 1978 pressure switch feilure. HILBON, K. R. Duie Power Co. 78/11/27. 2pp. 9430:134.
- 7812190127 Forwards LER478-026/03L-0.
  PARKER, H. D. Duke Power Co. 78/12/11. lp. 94340:394.
- ~-7812190130 LER#78-026/03L-0 on 781110: while attempting to put RBCU "c" fee into syc.damper-open indication not recieved in control room. Ceused by blown fuse in demper motor circuit.
  WILBON.K.R. Duke Power Co. 78/12/11, 2pp. 94340:336.
- COCKET 50-270 DODNEE NUCLEAR STATION, UNIT 2

  E. NRC Befety Evaluation Report (BER), supple & correspondence
- 7811020014 Supplements 7808il Sefety Eval of subj facil Found LPSW sysplping errangement acceptabls. Deletes requirement to provide apare dedicated cebles for LPSW syspump motors.
  REID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/10/05. app. 94351:247.
- F. Security, medical, emergency & fire protection plans
- 7810180126 Forwards proprietary info consisting of ChangewB to RevM5 of subj facil security plen. W/o proprietary info. PARKER: N. O. Oute Power Co. 78/10/06. 32pp.
- 7810310008 Forwards Revision 2 of modified emended security plan (MASP). Encl withheld (ref 10CFR2.790). PARKER.W. O. Duke Power Go. 78/10/19. 2pp. 94093:360.

7812050019 Summary of a 781025 meeting re sub; facil Station Health Physicist. FAIRTILE.M. Operating Reactors Branch 4 (Pre 790625) 78/11/02 3pp. 94415.330

#### O Adjudicatory correspondence

94482.338

7812080225 Ack receipt of 781018 itr re-util proposal to transport subfacil spant nuc fuel Ltr will be forwarded to ASLB in order to be considered as a written limited appearance statement. W/encl ANO.7811130267 KETCHEN.E 0 Office of the Executive Legal Director 78/11/20. 3pp. 94137 114

## P. Operating license stage documents & correspondence

- 7811170029 Requests edd1 info in order to complete review of submittal dtd 780714 & 781006 is permanent mode to High Pressure Coolant Injection Sys et subj facil Requests info in 20 days REID.R W. Decrating Reactors Branch 4 (Pre 790625). 78/10/31 3pp 94048:182.
- 7810110025 Request for all info re radiat leakage & safety problems at subj fecils
  ODRDON,W J. Gordon, Welter J. 78/09/08 lp. 94063:131.
- 7810200102 Act receipt of 780825 response to 780801 NRC request for add1 info re substitute surveillance tendon Requests add1 info re solution to stress corrosion surveillance & lift-off test problem w/in 30 days.

  REID.R.M. Dperating Reactors Branch 4 (Pre 790625). 78/10/02 ip. 94367 333
- 7810230138 Forwards check for \$8300 to cover add1 lir fees for NRC review of Cycle 3 released emend for subj fac11, PARKER,H O. Duke Power Co. 78/10/03. 2pp 94164:260.
- 7810130174 Analysis of smell break LDCA dtd 780515 & the proposed modwhich requires an open to position switches to open 2 elocmotor-open valves. Actions are consistent w/stapp position on this metter. PARKER, M. O. Duke Power Co. 78/10/06. ip 94003:051
- 7810250149 Notification of forthcoming meeting with Duke Pur Co on 781025 to discuss goals of Rediat Protec Meneger. FAIRTILE.N.B. Operating Reactors Branch 4 (Pre 790625). 78/10/17. ip. 94055:336.
- 7811090107 Responds to 781012 NRC request for info re amend to lic MBNM-1773 for spent fuel shipment to McGuire Finde that rerecking Doonee spent fuel pool is tech feesible as a possible future action, but requests processing of appl now PARKER-M.O. Duke Power Co. 78/10/18. 6pp. 74397.141.
- 7810240147 Dus to Inection on subj Fecil 781007 proposel for Yech Spectory to incorporate staff position for valtage monitors, the proposel is rescinded. PARKER, M.O. Duke Power Co. 78/10/19. 1p
- 7811070013 Forwards Amends 65.63 % 62 to Licenses DPR-3D.DPR-47 & DPR-35.rsepectively, changing Tech Specs re full rated pur Cycle 5 oper after core reloed removal orifice rod assemblies from core & High Pressure Injection Pump oper. REID.R.M. Deprating Reactors Brenth 4 (Pre 790625). 78/10/23. 3pt 94036:290.
- --7811070055 Amend#65 to Fecil Oper Lic#DPR-38 changing Tech Epecs. REID.R.W Opereting Reactors Brench 4 (Pre 790625). 78/10/23 2pp. 94036:293.
- --7811070057 Amend#65 to Fecil Oper Lic#DPR-47.changing Toch Specs. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23. 2pp. 94036:295.
- --7811070060 Amend#62 to Fac11 Oper Lic#DPR-35.changing Tech Specs REID.R.W. Operating Reactors Branch 4 (Pro 790623). 78/10/23 25pp. 94036:297.
- --7811070063 Exempts subj facil from 10CFR50.46(a)re reactor cooling until mod is complete or until next refusing shutdown. STELLD,V. Division of Operating Reactors. 78/10/23 Spp. 94036:322.

- --7811070068 BePety evaluation & EIA supporting Amend 65 to Lic DPR-38. Abend 65 to Lic DPR-47 & Amend 62 to Lic DPR-55 Concludes that it is acceptable for Cycle 5 oper to proceed & that EIA not req. a Office of Nuclear Reactor Regulation Director. 78/10/23. 159p. 94026:330.
- --7811070071 Notice of Issuance of Amend#65 & 62 to Facil Oper Lic#DPR-3B. DPR-47 & DPR-55, respectively, rev Tech Specs to support full rated pur oper during Cycle 5 after core reload, adding High Pressure Injection Pump reqs & fuel demonstration prog. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23. 2pp. 94036: 349.
- 781:1170324 Notice of Issuance of Amend#62 & 65 to Oper Lic\*DPR-38.47 & 55. Amend ray Tech Specs allowing full rated pur during Cycle 5 after core reload & parmits use of 5 previously burned fuel assamblies.

  REID.R.M. Operating Reactors Branch 4 (Pre 790628). 78/10/23. Spp. 02766:245.
- 7811010104 Requests rapid NRC approval of Standby Shutdown Sys concept proposed ra station escurity & fire protect of subj facil. Must have NRC assurance that BBS concept meets NRC requirement before committing to these mode.

  PARKER.W.O. Duts Power Co 78/10/26. 2pp.
- 78i1020235 Notice of rev to Tuch Spac 3.7 re Auxiliary Elec Sys. Spec 3.7.1 is rev to clearly define onsite sampancy transmission pable in 125VDC instr Control Sys.& rev 3.7.2 re slet sys degraded mode oper.
  PARKER, W. O. Duke Power Co. 78/10/31. 6pp. 94247: 138.
- 7811070214 Ack receipt of NRC info to staff revisuing 780918 submittel of lic amend supporting subj facil through Cycla 4. Confirms 780922 & 780926 lit to NRC responding to staff questions reproposed physics testing of cycla 5. PARKER. H. D. Duks Power Co. 78/11/01. ip. 94039:121.
- 78III40114 Responds to 781031 request for addi info re mod of high pressure injection systematically smell break ECCS mod. PARKER. H. O. Duke Power Co. 78/11/06. App. 94425:135.
- 7811150179 Responds to 781002 NRC ltr re total # surveillance tendons prescribed & substitution of surveillance tendon for tendon 2D28 Ballisves tendon 2D28 nead not be replaced or tensioned & should be available for mail degradation test.

  PARKER.W.O. Dute Power Co. 78/11/06. 2pp. 94242:359.
- 7811160065 Confirms conversations or 780705 proposed oper lic change repossible receipt of 4 fuel assemblies from FL Pur Corp. Requests withdrawal of proposed lic amend & indemnity agreement(3-44) & refund of lic fee.
  PARKER, M. O. Dute Power Co. 78/11/07 ip. 94103:121.
- 7811160079 Rescinds 780823 request for NRC concurrence re proposed change to respiratory protect eye.
  PARKER, M.D. Dute Power Co. 78/11/07. ip. 94133:175.
- 7811160134 Raeponds to 781011 NRC comments on minimum qualifications of atation Haalth Physicist Considers requirements in ANBI/ANB-3. i-1978 to be appropriate. PARKER.M.D. Dute Power Co. 78/11/07. ip. 94135:235.
- 7811270118 Forwards 3 proviously emitted Tech Spec pages(2.3-1,2.3-3 & 2.3-11)for Lic Amand863.675 &62.covering limiting sefety systettings & protect instru.
  REIO.R.W. Operating Reactors Branch 4 (Pre 790623). 78/II/OB. 5pp. 9471:266.
- 7811200421 Forwards results of measurements of radioactivs matl in NRC phantom on whole body counter. Enci I contains actual amount of each radionucilde present enci 2 gives ratio of measurements to DOE values & encl 3 gives recommendations. BUTHERLAND. J. T. Region D. Atlanta. Fuel Facility & Materiale Bafety Branch, 78/11/09. 5pp. 94419:175.
- 7611210298 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & ancl seminar info sheet, registration form, & proposed agenda.

  O'REILLY, J.P. Ragion 2. Atlanta, Office of the Director. 78/11/09. 5pp. 74488:126.
- 7811210306 Notifies util of 781205 esminar in Atients to discuss new Model Rod Efficent Tech Specs 4 encl seminar info sheet, registration form, 4 proposed agends. O'REILLY, J. P. Region 2. Atlante, Office of the Director, 78/11/09. Spp. 94488:091.

- 78:1300035 Forwards NRC staff paper.Policy Bession Item(8ECY-78-554) r. licensee reg performance evaluation. Three methods for evaluation are: statistical, trend analysis & regional survey method. H/o encl.

  O'REILLY, U.P. Region 2. Atlante. Office of the Director. 78/11/25.
  2na. 94072:331.
- 7812150123 Notice of workshops or implementation of training & qual requirements contained in Append B of 10CFR79. Requests pre-workshop registration of attenders to facilitate sending out mati. W/morl Registration Form & List of Locations. MILLER, J. R. Assistant Director for Bite & Bafeguards (Pre 791030), 78/11/19. 5pp.
- 78:2190031 Forwards Rav#1 "Draft Radiological Effluent Tech Specs" for PWR's (NUREQ-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Pwr Plants" (NUREQ-0133), U/o encl ANC: 78:1270173 & 78:127018. GRIMED.8.K. Assistant Director for Engineers & Projects (Pre 790&25), 78/11/15. 6pp. 94214:333.
- 78Ii300379 Informe DPC that NRC has contracted w/Mountein Hest Res Inc to undertake a earlies of post-licensing studies of nuc pur stations. Studies will analyze socioecon impacts which occurred during constr & post-constr periods of each plant, DEYOLNO, R. C. Division of Site Bafsty & Environmental Analysis, 78/11/20, 2pp. 94i36:252.
- 7812060260 Response to 780905 ltr requesting exemptions from certain reg of 810CFR Part 21.Rule amended 781019 & provided relief requested.

  DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 78/11/24. 2pp. 94371:337.
- --7812060272 Requests examption from 10CFR21 re procurement of various standard stock items from Cutler Hammer, Inc. Procurement delays will affect constructed. PARKER, H. D. Duke Power Co. 78/09/05. 3pp. 94371: 339.
- 7812040231 Requeste reiief from rsg of ABME Cods Section XI, Article 3M 300. Request concerns sye pressure test found to be impractices.

  PARKER, M. D. Duke Power Co. 78/11/28. 7pp. 94325: 348.
- 78121500B2 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/enci ANO: 7812080207.
  REID.R. W. Operating Reactors Branch 4 (Pre 79062B). 78/11/29. 6pp 94210:330.
- 7812180131 Expecte that mod of high pressure injection sys at subjectle can be implemented for each unit during first available outage of sched duration aufficient to install mod.
  PARKER.N.O. Duke Power Co. 78/12/04. 1p. 94364:278.
- 7812280173 Emphasizes importance of submitting accurate & complete inf to NRC by licenees & applicante. Info submitted must be substantiated by data & calculations. Liceness must notify NRC of any inaccuracies or anforcement action will result. DAVIB.J.Q. Office of Inapection & Enforcement, Office of the Director. 78/12/06. 2pp. 94376:015.
- 7812260001 Accepts proposed dasign mod to High Pressure Injection (HPI sys consisting of installing cross-current lines between discharge lines of HPI sys. W/Bafety Eval.

  LAINMS.G. Plant Systems Branch (Pre 791030). 78/12/07. 6p. 94020:271.
- 7812260062 Forwards Safety Eval Rept for subj fecil re mod to high pressure injection sys.
  REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/12/13. 291 94021:271.
- --7812260064 SER "Mod to High Pressure Injection Sys. "Concludes designed to HPIS will ensure that for all postulated eingle failure conditions. HPIS will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths.

  \* Operating Reactors Branch 4 (Pre 790625). 78/12/13. App. 94021:273.
- 7812280238 Forwards Amend#66,66 % 63 ravising Tech Speca re subj facilicontrol rod operability. Forwards Bafety Eval. Notice of Issuance. & Notice of Eteaption.
  REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/18. 3pt 94355:258.

- REID.R. W. Operating Reactors Branch 4 (Pre 790625). 78/12/18. 36pp. 94355:261.
- --7812280251 Notice of Exemption of DPR-47 from iOCFR50 46(a)(i) requirement that ECCB performance be calculated in accordance w/celculation models per iOCFR50 App K. STELLD.V. Division of Operating Reactors. 78/12/15 9pp. 94195.286.
- --7812280264 EER supporting Amand 66 to DPR-3B. Amend 66 to DPR-47.& Amend 63 to DPR-35. Concludes that proposed Tech Spec changes do not involve a significant hazard, health or safety consideration.

   Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp. 9435:306.
- --7812280267 Notice of Issuance of Amend 66 to DPR-30.Amend 66 to DPR-47. & Amend 63 to DPR-55 revising common Tuch Spoce to support the oper of Unitw2 full rated pur during Cyclo 4 ZMETZIGO G B. Operating Reactors Branch 4 (Pre 790625) 78/12/15.
- 7612270244 Forwards proposed rev to subj facil Tech Specs.Proposed exception: 3 3 6(f), would allow inoperability of one Reactor Bldg Bpray Pump for up to 72 hours provided all Reactor Bldg Cooling Units are operable. W
- 7810300182 Responds to 781010 NRC ltr & remits fee for review of cycle 4 reload amend.
  PARKER.H.O. Dute Power Co. 78/10/20 2pp. 94030:159
- Q. inspection reports, IE Builetine & correspondence
- 7811100103 Ack receipt of 781016 itr informing NRC of steps taken to correct violations noted during Inspec#30-289/78-18, #50-270/78-18 & #50-287/78-19.
  KENNA.W.S. Region 2. Atlanta. Safeguards Granch. 78/10/26. ip. 94173
- --7811100110 States info contained in 781016 itr is proprietary pursuant to Section 2,790 & is to be withheld.
  PARKER, H. G. Oute Power Co. 78/10/16 ip. 94173:357
- --78[11001]5 Responds to 780919 NRC itr re violation noted in inspec Repts850-289778-18, 850-270778-18 & 850-287778-19. Corrective action withheld (ref lOCFR2, 790). PARKER, M. O. Duke Power Co. 78/10/06. ip. 94173:358.
- --7811100124 Forwards summary of IE Inspec Repte#50-269/78-18, #50-270/78-18 & #50-287/78-19 on 780815-17. Notice of Violation withheld pursuant to 2, 790. KENNA, M. B. Region 2, Atlanta, Office of the Director. 78/09/19. 2pp. 94173:339.
- ~~7811100130 IE Inspec Repts#50-269/78-19, #50-270/78-19 to #50-287/78-19 on 780815-17 during which i item of noncompliance was noted: testing of alarms.

  BESECKER. K. H., OILLESPIE, F. P. Region 2, Atlanta, Office of the Director. 78/09/18. 1p. 94173:361.
- 7810130056 Ack receipt of IE insp Repts 50-269/78-17,50-270/78-17 & 50-297/78-18 on 780807. No proprietery info.
  PARKER.M.O. Duke Power Co. 78/09/27. ip. 94079:183.
- --7810130060 Forwards IE Insp Rept 50-269/78-17, 50-270/78-17 & 50-287/78-17 on 780807. No noncompliance noted. SUMERLAND. J. T. Region 2. Atlanta. Fuel Factility & Materials Safety Branch. 78/09/20. 2pp. 94079:186.
- ~-7810130064 IE Insp Repts 80-269/78-17, 50-270/78-17 & 50-287/78-18 on 780807. No noncompliance noted, Major areas inspected; whole body counting practices & test count of NRC phentom.
  OIBSON.A.F. Region 2. Atlanta, Fuel Facility & Meterials Bafety Branch. 78/09/20. App. 94079: 188.
- 7811030221 States that prog has been established to address IE Circular 7B-08. Review of adequacy of qualifications of each piece of equip will be completed by 790416.
  PARKER-M.O. Duke Power Co. 78/09/29. 1p. 02724:250.
- 7810230287 Forwards IE Circular#78-17. (See ANG: 7810230221. Docket 50-313, 781013)
  D'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/10/13. 1p. 74165:005.

- 7811200378 Ack receipt of 16 Inspec Repts#50-289/78-22.450-270/78-22. & #50-287/78-23 on 780918-22 Days not consider any info therein to be proprietery PARKER.W. 0 Dais Power Co. 78/11/09. pp. 94397-251
- --7811280390 Forwards IE Inspec Repts#50-269/78-22, #50-270/78-22 & #50-287/78-23 on 780918-22 during which no items of noncompliance were noted LDVS.F.J. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/10/18 2pp 94:397 252
- --78i1280398 IE Inspec Repts#50-269/78-22.#50-270/78-22 & #50-287/78-23 on 780918-22 dering which no items of noncompliance were noted Major areas inspected included unresolved items, special repts.action on IEC 78-08 LEHIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 78/10/18 dep. 94397 294.
- 7812120053 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Nawsletter KENNA.H B. Region 2. Atlanta. Befoguards Branch 78/11/17 4pp 94278:072
- 78:205002: Ack receipt of 78:120 itr informing NRC of steps taken to correct violations noted during inspecs#50-269/78-15. #50-270/78-15 & #50-297/78-16 BUTHERLANO.J T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/11/20 1p. 94200:270
- --7812050025 Reaponds to 780929 NRC itr re violations noted in Inspet Repts#50-269/70-15,#50-270/78-15 & #50-287/78-16. Corrective actions: entrances to interin weste Pacil posted u/radiat signs & spont fuel cash rebolted & retorqued for enigment. PARKER: N. O. Dute Power Co. 78/10/25 App. 94200:271.
- --7812050029 Forwards IE Inspec Repts#50-269/78-15.#50-270/78-15 & #50-207/78-16 on 780726-28 & 780801-04 & Notice of Violation.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director 78/09/29. 2pp. 94200:275.
- --7812050030 Notice of Violation from Inspec on 780726-28 & 780901-04. \* Region 2. Atlanta. Diffice of the Director, 78709/29 ip. 94200:277.
- --7812050031 IE Inspec Repts#50-269/78-15,#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 during which 2 items of noncompliance were noted: failure to properly pack cask for shipment & to perform radiat surveys in interim waste bldg. HDEEY.C. M., JENMINB.O.R., OIDSON.A.F. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/07/20. 11pp 94200:270.
- 7812040326 Ack receipt of 781106 itr informing NRC of steps taken to correct violations noted during inspec#50-269/78-20. #50-270/78-20. #50-287/78-21. BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/22. 1p. 94130:353.
- --7812040328 Responds to 781010 NRC ltr re violations noted in Inspec Repts#50-269/78-20, #50-270/78-20, #50-287/78-21. Corrective actions: door lock mod to prevent unlocking w/o koy. PARKER.W. O. Duke Power Co. 78/11/06 2pp. 74130: 334.
- --7812040332 Forwards IE inspec Repts#50-269/78-20,#50-270/78-20,#50-26 78-21 & Notice of Violation. BUTHERLAND, J. T. Repion 2. Atlenta, Fuel Facility & Matorials Befety Branch. 78/10/18. 2pp. 94130 396
- --7812040335 Notice of Violation from Inspec on 780911-19.
  # Region 2, Atlanta: Fuel Facility & Materiale Safety Branch.
  78/10/18. 1p. 94130:358.
- --7812040039 IE Inspec Repta#50-269/78-20,#50-270/78-20,#50-287/78-21 |
  780911-15 during which 1 item of noncompliance was noted:
  failure to keep entrance to high radiat area locked.
  HOBEY, C. M., 91880N.A.F. Region 2, Atlanta, Fuel Facility &
  Materials Bafety Branch. 78/10/18. App. 94130:359.
- 7812040363 Forwards IE Bulletin#78-12A. suppl to IE Bullstin 78-12. W/encl ANG:7811300055. D'REILLY-J.P. Region 2. Atlants. Office of the Director. 78/11/24. lp. 94127:166.

- 7012130306 Ack receipt of IE Inspec Repts#50-269/78-26,#30-270/78-25 & #30-287/78-26 on 781023-27. Does not consider any info therein to be proprietary.
  PARKER, W C Duke Power Co 78/12/05 ip. 94139 278
- --7812130311 Forwards IE Inspec Repts#50-269/78-26.#50-270/78-25 & 650-289/78-26 on 781023-27 during which no items of nuncompliance were noted.

  LCNO,F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/21. 2pp. 94159:279
- --7812130317 IE Inspec Repts#30-269/78-26,#30-270/78-25 t #30-287/78-26 on 781023-27 during which no items of mondmpliance were noted Major areas inspected incl. review of past flow.pwr & pwr distrib dnomalies.

  BURNETT. P T. Region 2. Atlanta. Office of the Director JULIAN.C.A. Region 2. Atlanta. Resctor Operations Nuclear Support Branch BETTENHAUSEN.L. Region i, Philadelphia. Office of the Director 78/11/20 5pp 94139:201
- 7812140041 Ack receipt of 1E Inspec Repts#50-269/78-29,#50-270/78-21 & #30-287/78-29 on 781106-08 Does not consider any info to be proprietably.
  PARKER: W 0 Duke Power Co. 78/12/05. 1p. 94127: 267.
- --7812140046 Forwards IE Inspec Repts#50-269/78-29,#50-270/78-21 & #50-287/78-29 on 781106-08 during which no itsms of noncompliance were noted.
  LCNG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/22 2pp. 94127:268.
- --781214004B iE inspsc ReptsH50-269/78-29, H50-270/78-21 & H50-287/78-29 on 781106-08 during which no items of noncontlance were noted Major areas inspected incl plant oper & restoration of sys fallowing refueling outage.

  JAPE.F., LEMIS.R.C. Region 2, Atlants. Reactor Operations Nuclear Support Branch. 78/11/22 6pp. 94127:270.
- 7012140053 Ack receipt of 1E inspec RepteM50-269/78-24.W50-270/78-23 & W50-287/78-24 on 781017-20 & 781101-03 Does not consider any info therein to be proprietary. PARKER.W.O Duke Fower Co 78/12/05 ip. 94126:330.
- --7812140053 Forwards IE Inspsc Repts#50-269/78-24, #50-270/78-23 & #50-287/78-26 on 781017-20 & 781101-03 during which no items of noncompilance were noted.

  KENNA-H. D. Region 2. Atlanta, Safeguards Branch 78/11/29, 2pp. 94126:331
- --7812i40039 JE Inspec Rapts#30-269/78-24,#20-270/78-23 & #50-287/78-24 on 78i017-20 & 110i-03 during which no items of noncompliance wers noted Major areas inspected incl:facili organization, shipping & receiving & storags HCDCES.J.W. CLAY.E.L., WILLIAMB.O.H Ragion 2, Atlanta, Bafeguer ds Branch. 78/11/24. 4pp. 94126:333.
- 7812290092 Forwards 18 Bulletin 78-14.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/12/19.

  2pp. 03698:189.
- R. Parlodic operating raports & related correspondence
- 7810200082 Forwards Monthly Open Rept for Sept 1978. PARKER, M. O. Duke Power Co. 78/10/16. \$p. 94366:343.
- --7810200083 Monthly Oper Rept for 8spt 1978. REAVIS. J E. Bule Power Co. 78/10/16. 16pp. 94366:344.
- 7810240002 Forwards Quarterly 780601-780831 rept on Jocssee Area Selenic Activity PARKENIC Dute Power Co. 78/10/16. lp.
- --7810240077 Quarterly Beismic Activity Rept.(6-1-78 to 8-31-78).

  Decreased Beismicity in Jocasses area represents diminishing size and no. of joints at greater depths.

  TALWANI.P., BTEVENSON.D. SAUBER.J. South Caroline, Univ. of. 78/10/16. 19pp.
- 7812210137 Forwards Monthly Open Rept for Nov 1978.
  PARKER: N. O. Duke Power Co. 78/12/15. 1p. 94278; 185.
- --7812210160 Monthly Oper Rept For Nov 1978. REAVIB. J. Duke Power Co. 78/12/15. 16pp. 94278:186.

- --7811080141 LERW78-010/03L-0 on 781004: control rod 7 g to be inoper due to short in CRD stator. Short cause moisture-induced corrosion. Will replace shorted staduring upcoming refueling outage.
  WILSON, K. R. Duke Power Co. 78/11/01. 3pp.
- 7811300172 Forwards LERN78-011/03L-0 PARKER-W. O. Duks Power Co. 78/11/22 ip 94073 10
- --7811300174 LERM78-011/03L-0 on 781023:ES Analog Chann Range Prassure Transmitter found to be out-of-callb excessive temp/hunidity in penetration room. Actions minimize effects of excessive conditions. WILSON:X R. Duka Powar Co 78/11/22 2pp 94073
- 7812180188 Forwards LERW78-012/01T-0. PARKER-W O. Dute Power Co. 78/12/05. 1p. 94366:08
- --7812180196 LERN78-012/017-0 on 781105:valve 2HP-127.R thetr valve was in closed position during HPI cher functional test Caused by personnel error. HILSON.K.R Duks Power Co 78/12/05 2PP. 94366
- OOCKET 50-271 VERMONT YANKEE NUCLEAR POMER STATION

  E NRC Sefety Evaluation Report (BER1, Supple & corresp
- 781:1290392 Rasponds to 78:018 request for copies of ref from Safety Eval to Amand#47 for Subj facis lic & raq for info rapposible fuel loading arror.Forwards refe NRC found no loading error.H/enci ANO:78:10240145. STELLO.V Division of Operating Reactors. 78/11/id. 94:18::178.
- F. Sacurity, medical, amergency & fire protection plans
- 7810200090 Proposes to provide 2 fire drills per year foperating shift fire brigade. Asserts that NRC insists 4 drills for each brigade year per year is arbitrary unnacessary MOODY.0 E. Vermont Yenkae Nuclear Power Corp. 78/10 94367-000
- 7812050130 Forwards latest ray of mod amend ascurity pl facil to must 780621 NRC comments. Encl w/held from pu disclosura pursuent to 2.770. OROCE.R H. Vermont Yankas Nuclear Power Corp. 78/12 94335 051.
- 7812270276 Forwards addl info re fire protec sys hose s
- 7812270276 Forwards add1 info re fira protec sys hose s dasign. MODDV.D.E. Vermont Yankae Nuclear Power Corp. 78/12 94229: 287.
- H. Constai correspondence
- 7811090166 Requests change of address for correspondent ORDCE.R.H. Vermont Yankas Nuclear Power Corp. 78/11 94038:148
- K. Utility Final Barety Analysis Report (FBAR) & amends
- 7810240008 Ack receipt of rev Emergency Plan as Amend @ Requests submission of rev emergency plan IAN Reg Out 1.101. IPPCL110, T. A. Operating Reactors Branch 3 (Pra 79062 200.
- P. Operating license stage documents & correspondence
- 7810200151 Natice of Issuance of Amend to Facil Oper Li. Declaration, NRC has issued Amend 46 to Facil Oper Lic which revises Tach Space for oper of Subj Facil, Amend increase in pH of water discharged from cooling tower IPPLITG.T.A. Operating Reactors Brench 3 (Pre 79062 2pp. 94401:189
- 7810190043 Reload 5 Licensing submitted for subj facil dtd 780621 is being reviewed. Requests addl info telecto YAE on 780927. 1PPGLITO.T.A. Obstating Reactors Branch 3 (Pre 79062)
- 1PPCL1TG, T.A. Operating Reactors Branch 3 (Pre 79062 3pp. 94325:355.

# **DOCKETED ITEMS**

- --7810230043 Amend #47 to Facil Oper LicHDPR-28, changing Tech Spac re-Cycle 6 oper. 1970L1TQ.T.A. Operating Reactors Branch 3 (Pre 790525). 78/10/10 32pp. 94414:227.
- --7810230044 Bafety Evaluation supporting Amend#47 to Facil Oper Lic BPR-2B. Concludes that amend does not decrease safety Amgin. • Operating Reactors Branch 3 (Pre 790625). 78/10/10. Spp. 94414-259.
- --7810230048 Notice of Issuence of Amend#47 to Fec11 Oper Lic#DPR-28, changing Tech specific 6 open. IPPDLITO,T.A. Operating Resolves Branch 3 (Pra 790625). 78/10/10. 2pp. 94414:267.
- 7810160135 Comments on Reactor Protec Sys pur supply. Ref is made to LiceOPR-2Q for sub; facil & NRC 780807 ltr to sub; facil. Combination of events as described has low probability of occurring & does not present need for sys mod. VANDKNBURGH, D. Vermont Yantes Nuclear Power Corp. 78/10/11. 2pp. DADOM's LiceOpt.
- 7811020066 Forwards Amend 48 to License DPR-28.safety evaluation & notice of issuence.
  1PPGLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/13.
  4pp. 94351:264.
- --781102007i Amend448 to Facil Oper Lic#DPR-28 rev Tech Specs re:oper plent during Oct 13-May 15 in the helper-cycle mode w/discharge temp restrictions & oper in closed-cycle during May 16-Oct 14. Also removes limit on thermal plume.

  IPPOLITO.T.A. Operating Resectors Branch 3 (Pra 790525). 78/10/13.
  59p. 94331:288.
- --7811020081 Environ Impact Appraisel supporting Amende48 to Facil Oper LieBPR-28 concluding that there will be no significent environ Impact attributable to proposed action other then what has been described in FES. • Office of Nuclear Reactor Regulation, Director. 78/10/13. 3pp. 94331:273.
- --7811020086 Notice of Issuence of Amend#48 to Facil Oper Lic#DPR-28 on 781013.

  IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/13.

  Opp. 94351:276.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendancs list & agenda (RD-9-A-Mark), Standards. ) GRIMESIC. Plant Systems Brench (Pre 791030). 78/10/26. 67pp.
- 7810240143 Requests copies of ref#5 & #7 to Amend#47 which provide plant-specific data used in transient & accident analysis.
  Asks if NRC Falt subj facil committed fuel load error during previous refueling.
  8COTT. D.M. Vermont, State of, 78/10/18, ip.
- 7811010104 Requests repid NRC approval of Standby Shutdown Sys concept proposed reletation security & fire protect of subj facil.

  Must have NRC assurence that SSS concept meets NRC requirement before committing to these mode.

  PARMER.N.D. Duke Power Co. 78/10/26. 2pp.
- 7811140224 States 781016 NRC ltr requests rewriting of metl sent for life purposes only. Suggests need may exlet for review of steff activities to confirm they are consistent w/priorities established by senior mgt.
  VANDEMBURGH.D. Vermont Yankes Nuclear Power Corp. 78/11/07. 3pp. 94400.059.
- 7812150167 Natice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out set! Wenc! Registration Form & List of Locations.
  HILLEN-J.R. Assistant Director for Bits & Bafeguards (Pre 791030). 78/11/15. 3pp.
- 7812180262 Forwards Rev81 "Draft Radiological Effluent Teth Specs" for BMR's(NUREQ-0473) & "Preparation of Radiological Effluent Teth Specs for Nuc Pur Plants" (NUREQ-0433). 9R1MESB.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94365.328.
- 7811270130 Forwards rept re"Primery Containment Leak Rate Tasting, 1974-1978."
  9ROCE, R. H. Vermont Yankee Nuclear Power Corp. 78/11/17. 1p. 94224; 221.

- --7811270134 "Vermont Yankee Primary Containment Leakage Rate Tetting 1974-1978. "Describes all reactor containment testing parformed subsequent to the Oct 1974 Type A test & Up to & Incl e Type A test performed in Aug 1978 EICHENHOLZ, H. Vermont Yankee Nuclear Power Corp 78/11/17. 45p 94224:222.
- 7812070141 Notice of seminar on 781208 on new Model Radiological Efficient Tach Space for nuc per plants. Requests advance submission of seminar specific questions. Wanci Seminar Info Sheet-Proposed Agenda & maps. ORIER. B.H. Region 1. Philadelphia. Office of the Director. 78/11/21. Spp. 94375:284.
- 7812110002 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wantl ANO: #7812080207 19PCLITO.T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 94339-159.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings be & providing task-by-task activity summary for the month. BOSCN-L.J. General Electric Co. 78/12/04. 11pp.
- 7812280121 Emphasizes importance of submitting accurate & complete in to NRC by licensees & applicants. Info submitted must be substantiated by data & taltulations. Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIB. J. Office of inspection & Enforcement, Office of the Director, 78/12/06. 2pp. 94310:249.
- 7811210367 Forwards add1 info rs multiple consecutive safety/relief valve activation of Mark I containment program.
  8080N-L-U. General Electric Co. 76/11/13. 3pp.
- G. Inspection reports, 1E Bulletins & correspondence
- 7811080236 Forwards 16 inspec Rept#50-271/78-19 on 780822-24 during which no items of noncompliance were noted. MARTIN.N.Q. Region 1. Philadelphia. Safeguerds Branch. 78/09/25. 2pp. 94406:064.
- --7811080245 1E inspec Rept#50-271/78-19 on 780822-24 during which no items of noncompliance were noted Major arese inspected included:physical security.access contrals.detection aids. iOCFR2.790 info available in Central Files ROBERS, M., MCKEOWN.L. Region 1. Philadelphie, Safoguards Branch. 78/09/25. 1p. 94405:066.
- 7810170023 Forwards IE Bullstin#78-12: "Atypical Held Material in Reactor Pressure Vasest Helds" requesting action w/in 60 days. & list of IE Bullstine leaved in 1978. (see ANO 7810040233) GRIER. B. H. Region i. Philadelphia. Office of the Director. 78/09/29. App. 94241; 334.
- 7811020170 Ack receipt of 780928 ltr informing NRC of steps taken to correct violations noted during laspec 30-271778-18.

  8MITH. Q. H. Region I. Philadelphia, Reactor Operations Nuclear Support Brench. 78/10/13. 1p. 94335:108.
- --7811020175 Responds to 780911 NRC ltr re violation noted in inspec Rept#80-271/78-18. Corrective actions, personnel reminded to perform preliminary survey of subj samples, follow handling reg & written plant procedures.

  MCDUY, D. E. Vermont Yenkes Nuclear Power Corp. 78/09/28 2pp. 94355; 109.
- ~~7811020179 Forwards IE inepsc Rept#50-271/78-18 dtd 780901 & Notice Violation. CROCKER, H. W. Region i, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/09/05. 2pp. 94355:113.
- --7811020183 Notice of Violation from inspec on 780815-17.
  CROCKER, H. W. Region 1. Philadelphia. Office of the Director. 78/09/01. 10.
- --7811020188 IE Inspec Rept 50-271/78-18 on 780813-17 during which a items of noncompliance were noted Disregard of Procedure DP 0640/Neter Chemistry Procedure DP 0641, Results of Chem yess! Procedure 0P 2611, Qassous Radwasts.
  BTDHR.J.P. Region i, Philadelphia, Office of the Director.
  KUTTAN.J.J. NRC Regional Offices. 78/09/01. 9p. 94353:114.
- 7811040178 Forwards 1E Circular#78-17. (See AND: 7810230221, Docket #50-133, 781013.)

- 7812020344 Forwards IE Inspec Repts#50-271/78-21 on 780919-22 & 1005-06 during which no items of noncompliance were noted. CARLSONR T Region t. Philadelphie: Rector Construction & Engineering Support Branch. 78/10/23 2pp 94382 257.
- --7812060346 IE inspec Rept#30-271/78-21 on 780919-22 & 1005-06 during which no items of noncompliance were noted. Hajor areas inspected incl. insvc inspec prog & implementation during current refueling outage SANDERS. W F. Region 1. Philadelphia. Reactor Construction & Engineering Support Grench 78/10/19 4pp. 94392 259
- 7811290145 Forwards 1E Circular #78-18. "UL Fire Test. "H/ancl AND 7811150002 ORIER: 8 H Region i, Philadelphie: Office of the Director. 78/11/06. ip 94239: 323.
- 7812290051 Forwards 1E Inspec Rept#50-271/78-24 on 781025-26 during which no items of noncompliance were noted.

  BRUNNER E J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94190:005
- --7812290033 IE Inspec Rept#50-271/78-24 on 781025-26 during which no items of noncomplience were noted Major areas inspected incl: status of previously indentified items NAPUDA.D., KIETER.M. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/11/09. 3pp. 94190 007
- 7812180030 Forcerds 16 Bulletin#78-12A.Bupp1 to 16 Bulletin 78-12 W/snc1 AND-7811300035 GRIEN B R Region 1. Philadelphis. Office of the Director 78/11/24 p 94133 004
- R Periodic operating reports & related correspondence
- 7810170192 Forwards Monthly Open Rept for Sept 1978 MODDY.D E. Vermont Yankes Nuclear Power Corp. 78/10/10 1p 94233:289.
- --7810170193 Monthly Oper Rept for Sept 1978 B.OOREN.R M Vernant Yankes Nuclear Power Corp. 78/10/12. App. 94235.290
- 7811140125 Forwerde Monthly Open Rept for Oct 1978.
  MODDY D E Vermont Yankes Nuclear Power Corp. 78/11/10 ip.
- --7811140127 Monthly Oper Rept for Oct 1978. S.OOREN. R M. Vermont Yankee Nuclear Power Corp. 78/11/10. Bpp. 9422-223.
- 7812130290 Forwards Honthly Oper Rept for Nov 1978.
  MODDY D. E. Vermont Yantes Nuclear Power Corp. 78/12/11. ip.
- --7812150292 Monthly Oper Rept for Nov 1978. S.DOREN.R M. Vermont Yenkee Nuclear Power Corp. 78/12/11. 6pp. 94409:207.
- 8 Reportable occurrences. LERs & related correspondence

94409: 206

- 7812180173 Forwards LER878-021/03L-0, CDNAY, H. F. Varmont Yantee Nuclear Power Corp. 78/07/24. ip. 94399; 397.
- --7812180176 LERM78-021/03L-0 on 780612 during steady state oper, noted that drywell atmospheric tamp recorder TR-1-149 was inopereble. Recorder feiled due to failed idler essembly. CONMAY, M. F. Vermont Yankes Nuclear Power Corp. 78/07/24, 2pp. 94399, 338.
- 7812180193 Forwards LERB78-017/03L-0. CDNHAY-H.F. Varmont Yankee Nuclear Power Corp. 78/07/24. 1p. 94366:097.
- --7812180199 LERM78-017/O3L-O on 780626: during reactor pur increase noted that local critical pur ratio in 4 symmetrically located fuel bundles use lower than Tech Spec levels. Caused by pur increasing senon trensient.

  CONIAY, M. F. Vermont Yenkes Nuclear Power Corp. 78/07/24. 2pp. 94366:098
- 7812180213 Forwards LER878-016/03L-0. CONNAY.W.F. Vermont Yantee Nuclear Power Corp. 78/07/24. 1p. 94363:072.

- --7812180216 LER#78-016/03L-0 on 780625: during steady state Oper, hoted that drywell atmospheric temp recorder IR-1-149 was inogenable. Caused by recorder failure due to broken cord on chart drive mechanism CONHAY,N F Vermont Yantes Nuclear Power Corp 78/07/24. 2pp 94365.073
- 7812180190 Forwards LERM78-019/03L-0 CONWAY.W F Vermont Yankes Nuclear Power Corp 78/07/25. 1p. 94366:090
- --7812180194 LERW78-019/03L-0 on 780629 during steady state oper Motor Control Ctr 893 lost voitage because "D" Uninterruptible Pur Supply (UP5) tripped due to blown inverter leg Puse Failed componente replaced & operablity test performed.
  CONNAY, M.F. Vermont Yankes Nuclear Power Corp. 78/07/25. 2pp 94366 091
- 7812180237 Forwards LERW78-017/03L-1
  CONWAY.W F Vermont Yentee Nuclear Power Corp. 78/08/10 1p. 94359:332
- --7812180241 LER#78-017/031.-1 on 780626.during increase of reactor for noted that critical per retio in 4 symmetrically lideated fuel bundles was below Tech Spec values Caused by per increasing senon transient CCNMAY.H F. Vermont Yankes Nuclear Power Corp. 78/08/10. 2pp. 94359.333
- CONMY, M. F. Vermont Yenkee Nuclear Power Corp. 78/10/26 1p. 94091.328 --7810310248 LERW78-030/03L-O pn 780926 small amount of radiolodine we

7810310244 Forwards LER#78-030/03L-0

- released during third quarter-screeding Tech Spec Level. due to feulty fuel cladding Amount released is small fraction of maximum release sliqued. & there was no hazard to pub. CCNMAY. H. F. Vermont Yankes Nuclear Power Corp. 78/10/26. 29p. 94091.329
- 7811160102 Forwards LER#78-031/03L-0. CONHAY;H.F. Vermont Yankes Nuclear Power Corp. 78/11/13. 1p. 94130:102.
- --7811160103 LERM78-031/03L-0 on 781016. weekly review of completes surveillance test following plant exartup noted that monthly hydrogen detector functional test was not performed due to personnel error.

  CDNHAY. W.F. Vermont Yankee Nuclear Power Corp. 78/11/13. Ppp 94135.103
- 7811160128 Forwards LERM78-032/03L-0 CONMAY.W F. Vermont Yenkee Nuclear Power Corp. 78/11/13. 1p. 94135:226.
- --7811160130 LER#78-032/03L-0 on 781014: during surveillance test of Maleteen Isolution Valves-V2-86C closed in 2.6 seconds rather than 3-5 seconds req in Tech Spec 4.7. D. L. a.i. Caused by closing speed control valve coming loose from actuator CONHAY-H.F. Varmont Yankee Nuclear Power Corp. 78/11/13. 2pp. 94132:227.
- 7812180219 Forwards LERW7B-033/03L-0. CDNAY; W. F. Vermont Yantee Nucleer Power Corp. 78/12/13. 1p. 94398: 339.
- --7812180222 LER878-033/03L-Q on 781113: during weekly surveillance re radiological environ prog. sir pump motor was found inoper. Time meter indicated pump had operated only 0.4 hours. Air pump raplaced & new weekly sir sample initiated. CCNNAY, N. F. Varmont Yankee Nuclear Power Corp. 78/12/13. 2pp. 94358-340
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT \$
  F. Security, medical, emergency & fire protection plans
- 7811300022 Forwards findings of steff review of subj facil 780803 security plan. Enciwi lists areas NRC considers unresolved, w/held from pub disclosure IAN 10CFR2. 790 Enciw2 is Review Guideline re plant protec from sabotage by inelders. BCHENCER, A. Operating Resectors Branch 1 (Pre 790623). 78/11/16. 4pp. 94070: 337.
- 7812040224 Requests add1 info re subj facil Security Plan. Forwards list of Unresolved issues (withheld from disclosure) & Review Outdeline "Protec of Nuc Pur Plants Against Industrial Sabotage by the Insider."

  SCHWENCER.A. Operating Reactors Brench 1 (Pre 790625). 78/11/15.

2340225 Review Guideline#23 "Protec of Nuc Pwr Plants Against adustrial Babotage by the Insider " Refers to security sasures that place controls on access to vital areas. ARK.R. A Reactor Bafeguards Licensing Branch (Pre 791030). 311/06. 3pp.

.0206 Responds to 7Blli6 request for info on security plan waste incl detailed study to determine Type I & ll vital se is unnecessary & requests response to issues reised in ltr re "ineider" control procedures [IZZI.F P. Public Bervice Electric & Gas Co. of New Jarsey 2/14. 2pp. 94279 096

210210 Appraises Reactor sefeguards Licensing Brench Review ideline#23 "Protec of Nuc Per Plants Against Industrial working by the Insider" re-compartmentalization, two-men ites, personnal reliability.

EWEN. J. E. KMC. Inc. 78/11/28 Spp. 94279:098

# udicatory correspondence

O322 NRC Steff requested to inform ASI.0 & concerned parties of date upon which Steff will complete safety eval & ron enelyeis re subj facti
DLLIN.0 L. Atomic Safety and Licensing Board Panel 78/10/12.
94195:185.

O337 NRC Steff response to ASLB Order of 78:012 requesting infoublication of Staff documents NRC Staff asserts that it not be able to publish these documents before Jan 1979 to unevailability of key tach reviewer.

4.8.H Office of the Elecutive Legal Director. 78/10/24 App.

0259 Notion by Pub Advocate of St of NJ on behalf of intervenors ed & Elsenor Coleman to convene ARLB to receive publimony. Notion besed on principles reflected in R2.715. Cert of Svc enci.

ER.R.B. New Jersey, State of 70/11/09. Upp 94417:129

J351 Licensee's opposition to motion of intervenore A & E Colsman choses the 8d to receive pub testimony. Urges deniel of sats. Fesle Pub Advocate is invoking nanexistent liege & should become a full party If truly interested. ERHAHN.M J. Conner, Moore & Corber. 78/11/22 Opp. 94131:016

1227 NRC Btaff's response in apposition to Motion by Intervenore I Colemen to convene ASLD to receive pub testimony Staff veet testing of evidence from persons making a limited stance. Cert of Svc enci.

4. B. H. Office of the Executive Legal Director. 78/11/29. Bpp. 1-348

1027 Forwards 780523 ltr for file & requests ack of receipt. 14895 concern re pending appl to modify existing permite suc fuel storage at outs site 187.H.D. New Jersey, State of 78/12/09. 1p. 94159:240

x301 Licensee's Objections to certain of Mr & Mrs AC Coleman. Jre'. Set of Interrog to the Licensee. Licensee moves for corder that objectionable discovery not be hed. W/encl-ctive order, contentions & Cert of Svc.
RMANN.M.J. Conner, Moore & Corber. 78/12/11. 18pp. ::157.

046 Response by licenses PSEO to intervenore A & E Colemans' set of interroge dated 781121. Interroge concern inter epent fuel reprocessing & radiat levels in spent fuel Cert of Svc encl.

NG.R. Public Bervice Electric & Gas Co. of New Jerssy.

/ii. 32pp. 74082:321.

#### rence & Indemnity information

159 Forwards 8 certified copies of captioned endorsement for f 1978 premium. Advenced premiums & stendard premium seement encl.
EY. T. F. Nucleer Insurence Consultente 78/11/02. 2pp. 1300

275 Forwards Amende5 to Indemnity Apreement#8-74. Copy has been d by all licensees.

1HS-R. Public Service Electric & Gas Co. of New Jereey.

/21. 1p. 94096:214.

80276 Amend#5 to Indemnity Agraement#8-74.effective 781004. stituting replacement lic numbers. ITMAN.J. Antitrust & Indemnity Oroup. 78/11/21. lp.

# rev of 1978 premium HARTLEY, T F Nuclear Insurance Consultants 78/11/28 2pp

- P. Operating license stage documents & correspondence
- 7812020004 Forwarde Licenses Performance Eval Questions for subj facil in response to 771123 request Feels it is possible that devof statistical methodology for such eval may not justify the effort. Qualitative eval may be as good Urges i-year test QRIEM.B H Region i. Philadelphia. Office of the Director. 77/12/13 12pp

7812040223 Forwards insurance Endorsement #24 to MAELU Policy HMF90 fo

- 7810110091 Responds to 780913 NRC request for schedule for submittel or rev ECCB analysis w/corrected tirconlum-water heat generation caliculations Results will be available by November 1978
  LIBRIZILF P. Public Service Electric & Ges Co. of New Jersey 78/09/26 1p. 94065-349
- 7810180092 Forcerds tebies re total amount of water diverted from well each month & chioride analysis of woter from Walis #1, 2, 3, & 5 for 780701-780930 MIDWA-H J. Public Service Electric & Gas Co. of New Jersey. 78/10/10 3pp 94401-025
- 7810170132 Forwards Amend#44 to Lic Appl for subj facil.consisting of eddi financial info as requested by 780417 NRC ltr MITTL-R L. Public Service Electric & Qas Co. of New Jersey 78/10/11. ip
- --7Bi0170133 Forwarde Amend#44 to Lic Appl for subj fecil,pertoining t generel & financiel info. NAFIN.7 J. Public Bervice Electric & Ges Co. of New Jersey 78/10/11 App.
- --7810170135 Amend#44 to Lic Appl for subj facil Contains addl financi. info. \* Public Bervice Electric & Gas Co. of New Jersey. 78/10/11. 1764pp.
- 7810250118 Add1 info submitted in support of appl to incress epent fuel etorage capacity Covere procedures used to insure fuel etorage racks are lest tight & summary of matl properties used in rack.
  LIBRIZZI.F P Public Bervice Electric & Gas Co. of New Jersey.
  78/10/13. jipp 9439: 265
- 7810240083 Forwards request for amend to Fecil Oper LickDPR-70 rechange in reporting responds by fitty of Station GA Engineer. LiBRIZZI,F P Public Service Electric & Gas Co of New Jersey. 78/10/17. 9pp
- 7811270006 Discusses daily staff notes for 781023 re CElL's intention to replace recirculation iniet northe eafe ends.failure of Reactor Coolant Pump at PBEO fecil & 15.000 gsi of water leaking into containment & inventory at Nuc Fuel Bycs.

  # Office of the Esecutive Director for Operatione 78/10/24, ip. 94272:261.
- 7811060089 Responds to 780831 ltr requesting info re pulsation dampers to other mech devices utilized to eliminate excessive positive displacement charging purp vibration. Repts no pulsation dampers used at positive displacement pump. LIBRIZZI,F.P. Public Service Electric & Ges Co of New Jersey, 78/10/27, 3pp. 94424-102.
- 7811060091 Submite add1 info to support appl to increase spent fuel storage capacity at sub; facil: Neutron Abearber Spent Fuel Cell Corrosion Swelling Teet.Fuel Sundle Recovery from Bulged Fuel Cell. Fuel Storage Rack Inspec. Test. Surveillance LIBRIZZI, F.P. Public Service Electric & Oes Co. of New Jersey, 78/10/31. 24pp. 94424:118.
- 7811220259 Summary of 781003 meeting re PSESO's proposed spent fuel pool mod. Items distuesed incl:2.05 linear elastic limit for faulted congition.ablility of new racke to withstand accidental drop & reck struc enalyses.

  ZECH.0.0. Degrating Reactors Branch 1 (Pre 7906R5). 78/11/07. 7p 94379:335.
- 7811270288 Responde to 781106 request for info concerning licensee reperformence such for Region 1 plents by NRC.Provides details.

  ORIER.S. H. Region 1, Philadelphia, Office of the Director.
  78/11/09. 9pp.

- 7812150212 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CRF23. Requests pre-workshop registration of attendees to facilitats sending out math. Wencl Registration Form & List of Locations MILLER-J R Assistant Director for Site & Safeguards (Pre 791030) 78/11/15. 5pp.
- 7812180283 Forwards Revai "Orete Radiological Effluent Tech Specs" for PHR's (NURED-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

  ORIFES.8 K Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 4pp 94365-117.
- 7811240219 Forwards add1 info in support of subj util's appl to increase the spent fuel storage capacity at subj facil LIBRIZIJ.F P Public Service Electric & Gas Co. of New Jersey. 78/11/20 3pp 94458-214.
- 7812070191 Notice of seminar on 781208 on New model Reciological Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions W/encl Seminar Info Sheet.Proposed Agenda & maps ORICE, BH Region i. Philadelphia. Office of the Director 78/11/21. Gpp. 94375.057
- 78:12:40:332 Discusses possible dangers of LOCA in containment purging durling normal plant oper. Requests either commitment to limit purging or justification for continuing Wienci AND 478:2080:207.

  8CH-ENCER. A Operating Reactors Branch 1 (Pre 7906251. 78/11/28. 6pp. 03:537:046
- 7812080039 Forwards proprietary & non-proprietary rept\*Dynamic Analysis of the Reactor Coolant Sys for Loss of Coolant Accidents: Salem Nuc Generating Stations ) & 17, " effidavit for Withholding & Appl For
- --7812080043 "Dynamic Analysis of the Reactor Coolant Bys for LQCAs."

   Westinghouse Electric Corp. 78/12/01. 160pp.
- 7812260045 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants. Info subcitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIG.J O. Dffice of inspection & Enforcement. Dffice of the Director. 78/12/06. 2pp. 94133:220.
- 7812050012 Requests views of Regional Directors on Licensee performance eval of supj facils. Forwards questions to be answered by 771209.

  THORNBURGO. H Division of Reactor Construction Inspection. 77/11/23, 200
- 7812290240 Requests that PBEO reexamine 780628 & 780731 itr requests after review of enclosed NRC Amend to 10CFR21 that was issued on 781019.

  DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/12/18 4pp. 94191:247.
- 7812290101 Responds to 781128 for & requests extension to 790201 to complete review of containment purging during normal plant oper. Extension will not adversely affect plant safety.
  LIBRI221.F.P. Public Bervice Electric & Oas Co. of New Jersey. 78/12/21. ip. 94190:333.
- G. Inepection reports, IE Bulletins & correspondence
- 7811300293 Forwards 1E inepec Repts#30-272/78-23.50-311/78-27 on 780812-0916 during which no items of noncompliance were noted.

  BRUNNER,E. J. Region I, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/10/10. 2pp. 94075:149.
- --7811300298 IE Inspec Repts#50-272/78-23.#50-311/78-27 on 780812-0916 during which no Items of noncompliance were noted. Major areas inspected incliroutine inspec of oper & construc. NCRR-DUH, L. J. Region 1. Philadelphia. Resctor Operations Nuclear Support Branch. 78/10/10. 13pp. 94075:151.
- 7811270397 Forwards IE Inspec ReptW50-272/78-24 on 781012-15 during which no iteme of noncompliance were noted. SRUNNER,E.J. Region 1, Philadelphia, Reactor Operatione Nuclear Support Branch. 78/10/12. 2pp. 94181:159.
- 7811060173 Forwards 15 Circular#78-17 (See AND:7810230221, Doctat #30-133/781013.)
  ORIEN.8.H. Region 1, Philadelphia, Office of the Director. 78/10/13. 1p. 94489:103.

- 7811290389 1E Inapec Rept#50-272/78-24 on 781012-15 during which no items of noncomplience were noted Major areas inspected incl:surveillance celibr of safety related components. CONTE.R.J. ZIMMERMAN.R.P. Region i. Philadelphia. Reactor Operations Nucleer Support Branch. 78/10/13. 12pp. 94181:161.
- 7811130115 Ack receipt of 780928 ltr in response to 780906 & 780612 NRC ltr informing NRC of steps taken to correct deviations noted in Inspec ReptM50-272/78-18 & 50-311/78-13. GRIER, B. H. Repion 1. Philadelphia. Office of the Director. 78/10/30. 1p. 94076:090.
- --7811130119 Responds to 780906 NRC 1tr re deviation noted in Inspec R #50-272/78-18. Util claims elleged violetion was not & did not represent noncompliance w/100FR50.59 since subtaired procedures are controlled by QA Prog to comply w/FBAR. SCHNEIDER, W.F. Public Bervice Electric & Gae Co. of New Jersey 78/09/29 2pp. 94076:091.
- 7812010345 Forwards licenees performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual sefety concern. GRIER, S. H. Region 1. Philadelphia, Office of the Director. 78/11/01. 4pp. 00002:259.
- 7811290193 Forwards IE Circular #78-18, "UL Fire Test. "W/encl AND: 7811190002.

  QRIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/06 ip. 94239: 284.
- 7812270417 Forwards 1E Inegec ReptsM50-311/78-35 & 50-272/78-25 on 780917-1014 during which no items of noncompliance were noted.

  BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94312:308.
- --7812270423 IE Inspec RapteM50-272/78-25 & 50-311/78-35 on 780917-101 during which no items of noncompliance were noted Mejor area inspected incit test prog controls log & record review. Emergency Drill, preoper plant personnel training. NORMOUNL, J. KEIMIGR. R. R. Region 1, Philedelphia, Reactor Operatione Nuclear Support Branch. 78/11/06. 15pp. 94312:310.
- 7812280009 Forwards IE Inepec Rept#50-272/78-25 & #50-311/78-35 on 780917-1014 during which no items of noncompliance were noted.

  8RUNNER, E. J. Region 1, Philadalphia, Reactor Operatione Nuclear Support Branch. 78/11/13. 2pp. 94130:149.
- ~-7812280012 IE Inspec RepteM50-272/78-25 & 450-311/78-35 on 780917-10 during which no Itams of noncompliance were noted Major areas inspected inclitours of faciliog & record reviews, observation of amergancy drill & review of racent LERS. NORRHOLM, L. J., KEIMIO, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/06. 15pp. 94130:151.
- 7812180022 Forwards IE Bulletin878-12A. Suppl to IE Bulletin 78-12. W/encl ANO:7811300055. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/24. 1p. 94133:286.
- 7812110150 Cladding Flaws detected May 1974 in Unit 1 Steem Generator 414 have been inspec w/ultrasound & TV. Interprets Tech Space as limiting TV inspecs to areas where results can be correlated w/ultrasound inspecs.
  LIBRIZZI.F. P. Public Barvice Electric & Ges Co. of New Jersay.
  78/11/77. 2pp. 94393:274.
- R. Pariodic operating raports & ralated correspondence
- 7810160084 Forwards Monthly Open Rapt for Bept 1978. MIDRA-H. J. Public Service Electric & Gas Co. of New Jersey. 78/10/10. 1p.
- --78/0160090 Monthly Oper Rept for Sept 1978.

  MILLER,L. K. Public Service Electric & Gas Co. of New Jersey.
  78/10/10. 15pp.
- 7810180128 Forwarde Waetawater Treatment Rept for Sept 1978 for sewag trastment plant at suby facil.

  MIDURAH, U., Public Bervice Electric & Cas Co. of New Jersey.

  78/10/10. 2pp. 94195: 296.
- 7810180144 Forwards Discharging Monitoring Repts for sub; fec11 for 84pt 1978. MIDURA:H.J. Public Service Electric & Gae Co. of New Jersey. 78/10/10. 19pp. 94316:328.

- 7810290103 Forwards "Impingement Monitoring Prog Rept #18" for Sept 1978 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 78170/18 ig 94392 276
- --7310250104 "Impingement Monitoring Prog Rept #18 for September, 1978"
  Impingement rate of weakfish is declining steadily
   Public Service Electric & Oas Co of New Jersey 78/10/18
  63pp 94370-268.
- 7812080113 Forwards tech rept "Sucmary Assessment of Healflish Ispingement Summer 1978" "SHIBIAS, J.A. Public Service Electric & Gas Co. of New Jersey. 78/11/06 299. 94108.123
- --7812080119 "Gummary Assessment of Weakfish Impingement Bummar 1978" Concludes available data on population size-number impinged & survival indicate that impingement did not significantly impact on 1978 year-class of weakfish public Service Electric & Oes Co of New Jersey 70/11/30 196pp 94108.129.
- 78/11/60074 Forwards Monthly Oper Rept for Oct 1978.
  MIDURA:H J. Public Service Electric & Qes Co. of New Jarsey.
  78/11/09 ip 94133-147.
- -78:116:0075 Monthly Oper Rept for Oct 1978. HILLER, L K Public Bervice Electric & Gas Co of New Jersey. 70/11/09 17pp. 94137:145.
- 78/31/2019) Honthly rept Oct 1970. HILLER/L W. Public Borvice Electric & Oas Co. of New Jersey. 78/31/09. 2pp. 94276;284.
- 78/11/20323 Forwards Hastewater Treatment Rept for Oct 1970. MIDURA.H J Public Bervice Electric & Oas Co of New Jersey 78/11/10 2pp 94485. 267.
- 7812080134 Forwards Rept #19 on "Impingement Monitoring Prog" for Oct 1978 L1881271.F P. Public Service Electric & Gas Co. of New Jersey 78/11/20. ip 94108 308.
- --7812080136 "Impingement Montoring Prog. Oct 1978," Repthip, On 781012 rector was taken out of six for month & only 1 pump was in six resulting in low impingement rates Before shutdown. Fish not found in all samples, showing they are leaving area \* Public Service Electric & Gas Co. of New Jersey. P77-54-19. 78/11/20 App. 94108: 309
- 7812150242 Forwards Monthly Oper Rept for Nov 1978.
  MIDRA-H J. Public Service Electric & Qas Co. of Naw Jersey.
  78/12/11 ip. 94213.274
- --7812150244 Monthly Open Rept for Nov 1978.
  MILLER, L. R. Public Service Electric & Ges Co. of New Jersey.
  78/12/11 13pp. 94213:275
- 7811210343 Forwards Discharge Monitoring Repts for Oct 1978. MIDURAH J. Public Service Electric & Gas Co. of New Jersey. 78/11/17. 10pp. 94484:342.
- S. Reportable occurrances, LERs & related correspondence
- 7810100028 Forwards LER#78-062/03L Lib#1221,F P. Public Service Electric & Ges Co. of New Jersey. 78/10/03 ip. 94033:039.
- --7810100033 LER#78-062/03L-0 on 780913: during normal open the #12 Resector Coolent Flow Channel 2 was not indicating due to failure of a Hagen Controls Bignal legistor.

  KAPPLE.A. U Public Bervice Electric & Gas Co. of New Jersey.
  78/10/03. 3pp.
- F810100037 Forwards LERN78-063/03L-0. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. 78/10/03. ip. 94039:074.
- --7810100041 LERM7B-063/D3L-D on 780910: during normal oper the fan coll water flow trouble alarm sounded for M13 Containment Fan Coll Unit. Unit was declared inoper due to all't buildup in low pressure sensing line.

  KAPPLE.A.M. Public Service Electric & Gas Co. of New Jersey.
  78/10/03. 3pp. 94039:075.
- \*Si0100097 Forwards LERB78-064/03L-0. LIBRIZZI,F.P. Public Service Electric & Oas Co. of New Jersey. 78/10/03. ip. 94033:174.

- --7810100089 LERW78-064/03L-0 on 780912 reactor trip setpoint greate than T/B limit during check of pressure protec channel 2 Caused by unstable quiput from comparator feeding trip bistable Comparator replaced KAPPLE.A W Public Bervice Electric & Gas Co of New Jersey 78/10/03. 3pp 94033.177
- 7810200119 Forwards LER#78-061/01x-1.
  LIBR1221.F P Public Bervice Electric & Qas Co of New Jersey.
  78/10/16 1p 94401 205
- --7810200125 LER#78-061/01x-1 on 780907 design defect which could all atrooms activity to be released from container to outside atmosphere noted Caused by design deficiency Change initiated in procedure KAPPLE.A in Public Bervice Electric & Qas Co. of New Jersey 78/10/16 Jpp. 94401 208
- 7810230243 Forwards LERM78-065/03L-0 LIBRIZZI,F.P. Public Service Electric & Oas Co. of New Jersey. 78/10/18 1p. 94032 283.
- --7810230249 LER#78-065/03L-0 on 780924 containment isolation valve to be electrically inoparable in closed direction. Normally closed auxiliary contacts in opening main contactor found to be open. Auxiliary contact assembly replaced KAPPLE.A. II Public Service Electric & Ose Co. of New Jersey 78/10/18 3pp. 94052-284
- 7810230252 Forwards LERM78-066/03L-0.
  LIBRIZZI.F P Public Service Electric & Oas Co of Now Jersey 78/10/18 1p. 94165-099
- --7810230255 LER#78-066/03L-0 on 780929 inner door of 100 foot eleva eir lock inner door erceeded merieum leak rate Caused by improper latch adjustent due to normal oper & maintenance weer Door letch readjusted. KAPPLE,A.W. Public Service Electric & Oas Co. of Neu Jersey 78/10/18 ip 94165 100
- 7810230295 Forwards LERW78-068/03L-0 LIBRIZZI.F.P. Public Service Electric & Qas Co. of New Jersey. 78/10/18. 1g 94164:188.
- --7810230304 LERW78-068/03L-0 on 781004 Personnel air lock inner dno exceeded mailmum leet rate Cause was improper latch adjustment caused by war. Roller latch readjusted & test reperformed to confirm operability.

  KAPPLE.A W Public Bervice Electric & Oas Co. of New Jersey 78710/18. 2pp. 94164-189.
- 78:03:01:07 Reportable Occurrence 78-70/01P: on 78:021. failure of MID reactor coolant pump shaft seals resulted in excessive leakage of primary coolant into containment Detailed rept will follow MIDURA: M.J. Public Bervice Electric & Oas Co. of New Jersey 78/10/23. pp. 74070: 159.
- 7811130266 RB 78-70/01P: on 781021.413 Reactor coolant pump shaft see failed, resulting in excessive leakage of primary coolant into container. Detailed RO Rept will be submitted HIDURA.H J. Public Service Electric Gas Co. of New Jersey. 78/10/23 ip. 94011:210.
- 7810310180 Confirms 781024 verbal rapt of RO Low pressure in control air sys caused operation of air operated delugs valves, necessitating operation of fire pumps in manual mode LER will follow.

  HIDMRAH.J. Public Service Electric & Gas Co. of New Jersey 70/10/24 in 94090: 238.
- 7811130263 Act 78:024 verbal rapt to L Norrholm advising of reportal accurance re oper of fire pumps in manual mode resulting from low pressure in the control air sys & caused by operation of deluge valves. RC rept will be submitted MIDMA, H.J. Public Bervice Electric & Qas Co. of New Jorsey 78/10/24. 1p. 94011: 208.
- 7810310254 Forwards LER#78-067/03L-0 L18RIZZ1,F.P. Public Service Electric & Qas Co. of New Jersey. 78/10/20. 1p. 94094: 284.
- --7810310260 LERW76-067/03L-0 on 780929: missing fire berrier in cab penetration identified. Caused by failure of admin controls to pinsure fire berrier installation. Cable penetration was immediately properly sealed. Others to be inspec by 781101 KAPPLE.A.W. Public Service Electric & Gas Co. of New Jersey. 78/10/26. 3pp. 94094: 285.

KAPPLE, A.W. Public Bervice Electric & Cas Co. of New Jersey. 78/11/01 3pp 94040:185.

- 7811070178 Forwards LER#78-070/01T-0 LIBRIZZI.F.P Public Service Electric & Oas Co. of New Jer##4. 78/11/02 1p 94044:181.
- --78:1070181 LER#78-070/017-0 on 78:1021: during Mode 4 aper.while heeting up to enter Mode 3.high flau thru #13 RCP seals & other alarms indicating RCS laskage observed. Ceuse uninounisuppl rept to be submitted when cause discerned. KAPPLE.A.M. Public Service Electric & Oas Co. of New Jersey. 78:11/02. 3pp 94044:162.
- 7811070265 Forwards LERH78-069/03L-0. L18R1271.F.P. Public Bervice Electric & Gas Co. of New Jersey. 78/11/02. 1p. 94040:193.
- --78:1070268 LERB78-059/03L-0 on 78:101): while investigating 18 Diesel Alarm.heater lesting chromated water into pre-lube pump motor was discerned Lest caused by corrolation of element sheeth of 2 of the 3 heater alemente.

  KAPPLE.A.M. Public Bervice Electric & Gae Co. of New Jersey.
  78/11/02. 3pp. 74040:194.
- 7811170181 Reportable OccurrenceM78-72/OIP: high estarnal radiat lavels in fan coil unit detector location would result in isoletion of eve water to fan coil units, would render them inoperable. Datellad rapt to follow.

  MIDURA, H. J. Public Barvice Electric & Gas Co. of New Jersey.
  78/11/07. jp. 94048:138
- 7811280460 Reportable Occurrence 78-72/01P on 781106: design deficiency re high rediat lavels in gen area of containment fan coil unit would be sufficient to cause monitors to alorm & perform isolation function. Engr dept to change design MIDURA; H J. Public Bervice Electric & Gas Co. of New Jursey. 78/11/07. 1p. 94376:327.
- 78:1220107 Forwards comments in the form of redraft of Commission paper re-proposed Fed Register Notice "Abnormal Occurrence Event. Loss of Containment Integrity" W/encl draft notice of Isavance.

  DENION.H.R. Office of Nuclear Reactor Regulation, Director. 78/11/11. 15pp. 94273:306.
- 7811200201 Forwards LER#78-043/03L-1.
  LIBRIZZI.F P Public Service Electric & Gas Co of New Jarsey.
  78/11/14. 3pp. 94232: 037.
- --7811200203 LER#78-043/03L-1 on 780DQB: as reactor pur was increased a deviation alarm would not clear & a QPT celculation showed a QPTR of 1.03%. Due to large load reduction Design change will delete the less than 30% pur alarm.

  KAPPLE.A.M. Public Bervice Electric & Ges Co. of New Jarsey. 78/11/14. 1p. 94232:040. (
- 7811240132 Forwards LERW78-072/01T-0. LIBRIZZI.F.P. Public Bervice Electric & Gee Co. of New Jersey. 78/11/20. 1p. 94457:001.
- --7811240137 LER#7B-072/01T-O on 781106:during Mode 5 aper.ell contellment fan coil units were found inoper due to tripped ever weter valves caused by design deficiency in detector installation.

  KAPPLE.A.M. Public Service Electric & Ges Co. of New Jersey, 78/11/20. 3pp. 94437:002
- 7811280304 Forwards LER078-043/03L-0. LIBRIZZI.F.P. Public Service Electric & Que Co. of New Jersey. 78/11/22. 1p. 94395:302.
- --7811280313 LER#78-043/03L-O on 780808: during normal oper, after 45% pur reduction to less than 30% for maintreactor pur increased to 51%. Deviation atarm would not clear & OPTR was 1.03% OPTR was not discovered sooner because of alarm indications. KAPPLE.A.M. Public Service Electric & Oas Co. of New Jerssy, 78/11/22, 1p. 94395:303

- LIBRIZZI, F. P. Public Bervice Electric & Gas Co. of New Jersey. 78/12/11. 1p. 94088:142
- --7812140169 LERB78-073/01T-0 on 781127:18 Vital Instru Bus wes lost causing reactor trip Bafety injection followed & 18 Diesel #11 Charging & #12 RHz pumps folied to start. Caused by bad output transformer in supply inverter.

  KAPPLE,A.W. Public Bervice Electric & Gas Co. of New Jarkey.
  78/12/11 4pp. 94088:143
- 7812220085 Farwards LER#78-075/03L-0. L18R1221,F. P. Public Service Electric & Gas Co. of New Jarsey. 78/12/18. ip. 94343:331.
- --7812220086 LERW78-075/O3L on 781130: during open w/conteinment entry in progress, inner door of sir lock 130 would not fully open-caused by failed cam roller on inner door operating mechanism. Air lock repaired, tested, returned to evc. KAPPLE, A.W. Public Service Electric & Gas Co. of New Jersey, 78/12/18. 2pp. 94343:332
- DOCKET 50-274 U B. QEOLOGICAL BURVEY REBEARCH REACTOR
  H. General correspondence
- 7812200230 Effective 790101.Administrator of the geological survey TRIGA restor will be AP Merrantino.
  CLESSCH.A. Interior,Dept. of, Geological Survey. 78/12/14. 19. 94162:337.
- P. Operating license stage documents & correspondence
- 7810230134 Repts alow droptime for translant rod in subj reactor.dup to faulty cylindar & seal. Repair completed by 780927. CLESSCH.A. Interior.Dent.of. 78/09/27. 2pp. 94271:180.
- 7811090063 Requests change to paragraph 2.8 of lic to read "to receive possess & use up to 5 kg U-235 for use in connection w/oper of resctor."
  CLESSCH.A. Interior.Dept. of. 78/10/11. 2pp. 94040:122.
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 78:0140114 Forwards matl in support of oper lic appl re snviron qualification of equip. Requests sck of receipt of Metl. CRANE, P. A. Pecific Ges & Electric Co. 78/09/21. 16pp. 94421:081.
- 7810120058 forwards responses to Informal questions posed by 780804 NRC memo on asismic qualifications. Submission is nonproprietary version, CRANE, P.A. Pacific Gas & Electric Co. 78/09/22. 44pp. 94081:184.
- 7810190071 In response to 780321 NRC request for add1 info on containment purging forwards ensuers to questions dreft tech Specs & rept on "Analysis of Off-Site Exposures due to LOCA coincident w/Conteinment Purging."

  CRANE,P.A. Pecific Que & Electric Co. 78/07/27, 106pp. 94923:001.
- 7810170179 Forwards response to 780728 ltr re reactor vessel mati properties noncompliance w/10CFR50. Appendix 9. Fracture taughness requirements. & 10CFR50. Appendix H. reactor vessel mati surveillence prog requirements.

  CRANE, P. A. Pacific Gas & Electric Co. 78/10/02. Spp. 94270:073.
- 7810310226 Forwards responses to 780728 NRC ltr re reactor vessel math properties noncompliance w/locrabo toughness & surveillance requirements. Requests act of receipt. CRANE, P. A. Pacific Oas & Electric Co. 78/10/02. 8pp. 94090:339.
- 7810170221 Bubmits info re "degraded grid voltage" as result of discussions w/Instrumentation & Control Sys Branch reviewer on 780929 as suppl to previous submittals on second lavel under/over voltage protect Dasign is acceptable by ICSB rev. CRANE, P. A. Pacific Ose & Electric Co. 78/10/04. 1p. 94236: 165.

- 230038 Ack receipt of 780906 ltr re subj facil. Provides info on .waic assessment of site.decomm astimate & waste mgt. tOXB.44.d. Office of the Executive Director for Operations. 10/06. 3pp. 94032:335.
- OP30042 Requests add1 info re issuence of constr permit. URTON, P. House of Rep. 78/09/06. ip. 94052:338.
- 90294 Frip rept:plant visit & mesting w/applicant on 780905 to cues remaining open issues to subj facil. W/summary of aining unresolved issues.

  ,P. T. Structural Engineering Branch. 78/10/06. 4gp. 94R39:847.
- 70205 Atteched Table 6.3-iO.which appeared in Amend 67.has been nged as indicated to reflect Staff's concerns to added was position & function. Change to be documented in ure amend Five copies of submitted sent to D. Allison. NE.P.A. Pacific Gas & Electric Co. 78/10/10. 2pp. 94235:337.
- 60118 Forwards amend fee per 780811 & 23 requests for extension of st completion dates of CPPR-69 & CPPR-39.

  NE.P.A. Pacific Ges & Electric Co. 78/10/11. 2pp. 94005:162.
- 70229 Summerizes discussion w/NRC, PGE. & GE on 780830 in Betheede. re electrical penetration qualification.

  E.P.A. Pacific Ges & Electric Co. 78/10/11. 4pp. 94235:173.
- 10206 Responds to requests of 780811 & 780823 by lesuing Order inding construction dates for subj facil. 2.J.F. Light Weter Reactors Branch 1. 78/10/13. 3pp. 12: 203.
- 250212 Order extending constr completion dates for subj facil to 10430 for Unit i & 781031 for Unit 2. Eval of Request for tension of Constr Permit encl. MD.R.B. Division of Project Management. 78/10/13, 2pp. 1372: 356.
- Q219 Forwards saismic design audite & lists squip qualified for TS SAVITOR. BDN, D. P. Light Water Reactors Branch i. 78/10/16. 34pp. 8:112
- 260225 Rept of seismic enelysis & struc design eval used in viewing turine padestals for response to postulated 7.5M agri asrthqueke. DOM, J. A. Pacific Ges & Electric Co. 78/09/15. 38pp.
- 0257 Forwards gen repair prog for arc strikes & wald spatter on Code Clase 1.2 & T pressure boundaries, in accordance w/ irements of ASME Code section XI, summer 1978 addendum. ancl. E.P.A. Pacific Gas & Electric Co. 78/10/16. 2pp.
- 3099 Bummery of 781012 meeting re saismic qual of alec equip. swed task results of else equip. Did not discuse review ach aspects of test involving type & saverity of ing. M/ant list of attendes & results of discussion. 30N. D. P. Light Water Reactore Branch 1. 78/10/18. 13pp. 7: 309.
- 1381 Summarizes 781005 meeting re out; facil raviou sched. Object seting to discuse statue of numerous specific items review & to identify items of most concern re meeting schedule.List of attendess encl. tON, D. P. Light Water Reacture Branch 1. 78/10/18. 15pp.
- NOTO Burmary of 781020 meeting re seismic qual of subj facil equip. 15 items found acceptable & 8 items needed mod. tems pertain to Instru/Control Bys. W/epci Branch Review :88 scope equip w/in Westinghouse qual prog. ON.D.P. Light Weter Reactors Branch 1. 78/10/25. 9pp. . 117
- um: Kererences comments in matter of cross-examination of litants to ACRS at licensing proc be decided as soon as ble Comm will consider the matter on a generic basis. Bd agress that it is a top-level policy question. Bi.E. B., Atomic Sefety and Licensing Soard Panel. 78/10/27. ip. 8:319. O21 References comments in matter of cross-examination of
- 040 Ack receipt of 781020 NRC 1tr. Repeats opposition to crossnation procedures of ACRB consultants in licensing P.A. Preific Oas & Electric Co. 78/10/27. in. 94398:114.

- 7811060005 Forwards 781026 Con Elec response to 780830 NRC questions re euby facil elec panetrations qual flore info is new. ALLIBON, D. Light Water Reactore Branch 1 78/10/30. 3pp 94397: 343.
- --7811080008 Responds to questions raised at 780820 meeting w/NRC raqualification of electronterion assemblies for eubj facil Addresses justification of qual by similarity.verification of repaired essembliss & OE knowledge of repair. CLEVELAND.J.W. Oeneral Electric Co. 78/10/16 14pp. 94397:346.
- 7811070271 Advices that cannister-type penetrations meet environ qual requirements consistent w/those found acceptable for Three Mile Island Also supplies date re rein line steen break analysis & use of diseal generator under test.

  CRANE, P. A. Petific Que & Electric Co. 78/11/02 2pp. 94040-284
- 7811200366 Forwards QE draft ltr re testing of penetrations-adequacy of repair. QE tested a leaking-unrepaired penetration to test epoxy seal & concluded that a repaired penetration should not act differently. LAINAB.G. Plant Systems Branch (Pre 791030). 79/11/09 lp. 94419: 211.
- --78112003B4 Responds to 780830 NRC ltr questioning qual of elec panetration assembliss supplied to subj facil Incl attachment on "Comparison of Connister & 100 Beries Psnetration Dasigns". CLEVELAND, J. W. General Electric Co. 78/10/26 13pp 94419: 212
- --78i1200392 Finel prototype test rept "Millstone 2 Elec Ponetration Poet-LOCA Prototype Test".Low voltage pur & control modules were subjected to 165F degree. 5 psig. 100% RM environ for 52 weeks.Leakage rate wes less than 1s10 to 8 pur cc He/6ec. LURIA.N Q. General Electric Co. 78/11/09, 4pp
- 78:12:10234 Forwards assistic qual summary forms for all ME valves identified in Tables 7-7 & 7-7A of "Hosgri Rept."
  ANDERSON.T.M. Westinghouse Electric Corp. 78/11/10. 33pp 94487: 149.
- 7811210318 Presents ACR8 conclusion from 781102-04 meeting that Dr Luco's concerns re seismic aval bases for aub; facils were considered in findings & recommendations in 780714 ACRB LAWROSKI.S. ACRS - Advisory Committee on Reactor Safeguards. 78/11/07. 1p. 94482:175
- 7812050083 Forwards Rav#1 Draft Redicities Effluent Tech Spec for Pwr's(NUREQ-0472) & "Preparation of Redicinglical Effluent Tech Spec for Nuc Pwr Plants"(NUREQ-0133). W/o sect ANO: 7611270173 & 7611270180. VABBALLOJD B. Assistant Director for Light Water Reactors. 78/11/16. 6pp. 94336:164.
- 7811220181 Forwards Amend#78 & Amend#73 to Oper Lic appl. CRANE, P. A. Pacific Gas & Electric Co. 78/11/20. 3pp. 94387:001.
- --7811220182 Amend#72 & Amend#73 to Oper Lic appl u/addl metl for Hoegri Batamic Evel & FBAR respectively.
  SCHACKLEFORD, B. Facific Gas & Electric Co. 78/11/15. 28app. 74387: 004.
- 7811300364 Informs PGE that NRC hass contracted w/Mountain West Res Inc minususes informs fee inst NRC hass contracted w/Nountein Hest R to undertake a series of post-licensing studies of nuc pur stations. Studies will analyze sociascon impacts which occurred during constr & sast-constr pariods of each plant. DEYOUNG.R.C. Division of Site Befaty & Environmental Analysis. 78/11/20. Spp. 94116:299.
- 7811300079 Forwards log of contacts from 780419-780305 by resident PG&E engr in Bethesde for lisison w/NRC.
  ALLIBON, D. P. Light Water Reactors Brench i. 78/11/Qi. 12pp.
- 78:2010010 Forwards staff eval of probabilistic seismic risk assessment covering: POE studies on probabilities of earthquakes & resulting ground acceleration at site. & probabilities of various consequences. BTQLZ, J. F. Light Water Reactors Branch 1, 78/11/21, 3pp. 94409: 128.
- --7812010014 Discusses PRE studies in 1977-78 on probabilistic evel of earthquake hazard. Various assumptions are questioned.

  STEPP, U.C. Geosciences Branch. 78/05/08. 4pp. 94409:131.
- -- 7812010019 Forwards staff eyal of Amend 92 to lic appl re Risk to Pub

- --7812010019 Clarifies certain points of eval of analysis of risk to pub from selsoic events contained in 780908 memo. Covers probability of Core mefedoum, & warthquake probabilities BUHL-A.R. Probabilistic Analysis Branch (Pre 791030). 78/11/06. 20p. 94409-144
- 7812210229 Forwards telsmic test procedure for subj facil 4160V Class 1E Buttchgear Gus Undervoltage Releya CRANE, P. A. Pacific Oas & Electric Co 78/11/29. ip 94279: 129.
- --7912210235 Beismic test procedure for 4160v Class IE Switchgear, Undervoltage Rolays demonstrates relays performance while being switched on & off during the shake, HERBST-J.E. NIELSEN.B. COLMELL-J H. Pacific Gas & Electric Co. 78/11/27. 31pp. 94279:130
- 7812120200 Requests add1 into re means of accomplishing quality inepec at sub; Pacil. STOLZ: J.F. Light Water Reactors Branch 1. 78/11/20. 3pp. 94275:061
- 7812210197 Forwards seisonet tast procedure for subj facil dissel generator control cabinet. CRANE.P.A. Pacific Oas & Electric Co. 78/11/30. ip. 94279:069.
- --7812210209 Seismic test procedura for diesel generator control cabinat.
  Teste wjl) demonstrate that relays are capable of changing
  state during a saismic event if nacessary.
  HERBST-J E , NIELBEN-D., COLWELL-J.W. Pacific Cas & Electric Co
  78/11/30. 9pp. 94279:069.
- 7B12210223 Forwards seismic test procedure for subj facil local starter LPF36. CRANE-P. A. Pacific Oas & Electric Co. 7B/12/01. ip. 94279:121.
- --7812210225 Seismic test procedure for local eterter LPF36. Tests will determine if LPF36 motor contacts main pur contacts change state during a seismic avent. YOUNG. R. A. NIELSEN. D. COLMELL. J. W. Pacific Gas & Electric Co. 78/12/01. 3PP. 94279:122.
- 7812120161 Forwards 8 requests for exemption from ASME Code Section 11 pump & valve testing requirements. Requests 1 thru 4 are continuations of attachments 7 & 9 to 771010 PGE 1tr recompliance u/Bection 50.534(g), 10CFR50.

  CRANE-P. A Pacific Ose & Electric Co. 78/12/06. 10pp. 94276: 343.
- 7812130389 Forwards 781101 ltr from Hilsy Labe re test mounting configurations for selemic qual testing of sic equip. This memo places mat! in file & the PDR & informs parties of info evallability.

  ALLISON. D. P. Light Water Reactors Branch 1. 78/12/06. 3pp. 94292:231.
- --7812130390 Clarifies questions raised at 781020 meeting re test prog for size equip. BHIPHAY, O. D. Affilietion Unknown. 78/11/01. 2pp. 94292: 234.
- 78:2150033 Forwards informal info "Investigation of A Seiche due to Design Spectra at Raw Weter Storage Reservoir, Subj Facil Nuc Proj" by CE Cecilio discussing potential for seiching in raw water reservoirs.

  ALLIBON. D. P. Light Water Reactors Branch 1. 78/12/06. 20pp. 020(6.000)
- 7812210193 Forwards selemic test procedure for 125 VDC switchgeer, distribution panel 6 mold case circuit breakers & test rept entitled "Belemic Testing of Bafety-Releted Elec Equip for PGE."

  CRANE.P. A. Pecific Ges & Electric Co. 78/12/06. 4pg. 94279:027.
- --7812210200 Seiemic test procedura for 125 volt DC switchgsar, distribution panel & moid case circuit breakers. PATTERSON.H., GOAD, L.F., BHIPHAY, G.D., Pacific Oas & Elsctric Co. 78/11/28. 34pp. 94279:031.
- 7812280075 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuraties or enforcement action will result. DAVIB. J. Q. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:311.
- 7812190143 Forwards rept presenting results of a large-breat lose-of-coolant(LDCA)eccident. New analysis incorp a correction to clad-water heat of reaction calculation & recent ECCS eval model improvements.

  CRANE.P. A. Pacific Gas & Electric Co. 78/12/07. 78pp. 94376:031.

- 7812190394 Forwards request for addl info re bolted connections in linear supports of subj facil support base plates Requests response schod. 87012.J.F. Light Water Reactors Branch 1. 78/12/08 5pp. 94357-275
- 7812260217 Requeste addi time to dev draft Appendix 1 Tech Spece. Proposes submittal by 790216. CRANE, P. A. Pacific Oss & Electric Co. 78/12/14. ip. 94162.098
- 7811210113 Forwards 781107 1tr to Chairman Handrie re ACRB raview of appl for parmits to oper subj facil. 8T0LZ.J.F. Light Water Reactore Granch 1. 78/11/14 3pp 94482:172.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7812070056 Forwards Suppl 8 to SER for subj facil. VASBALLO.D. B. Assistant Director for Light Hater Reactors. 78/11/15. ip 94462.032
- --7812070063 Forwards SuppleS to SER for subj Pacil. BTDL7.J.F. Light Water Reactors Branch 1. 78/11/14. 3pp. 94462:033.
- --7812070067 Suppl 8 to facility SER.

   Division of Project Management. 78/11/15. 110pp. 94462:001
- 7812050155 Forwards addl info to address Section? B.open item 3 of BER Suppl 7. re environ qual of Fen Cooler Pur Cables. Attachment B1 on Space. Tests & Installation of Wires & Cables at subj facil is not anci.

  CRANE. P. A. Pacific Gas & Electric Co. 78/11/27, 12pp. 94335:074.
- F. Security, medical, smergency & fire protection plans
- 7811290307 Bummary of 780214-15 meeting w/util ra subj facil fire protec prog. All mods will be made prior to fusl loading. HEARN, P. C. Auxiliary Systems Branch. 78/03/29. 33pp. 94181:306.
- 7811210164 Forwards rsv responses to NRC fire Protec Review questions 5.8.9.21.23.24.26.29.45.46 & 49-51 & rev rept "Supplementary Info for Fire Protec Review." Review question items incirconstr design, pire protec valves & automatic eprintiers. CRANE.P.A. Pacific Que & Electric Co. 78/11/13. 54pp. 94485-294.
- --7811210169 "Buppi Info for Fire Protection Review." 
  # Pacific Ges & Electric Go, 78/11/13. 138pp. 94486:001.
- 7811290400 Forwards suppl dateiled info related to subj facile seisald design audits & the fire protection review.W/31 drawings available in Central Files.
  ALLIBON.D.P. Light Water Reactors Branch 1. 78/11/21. 1029pp.
  94182-001.
- 7812290102 Review of Fire Protec safety eval rapt for subj facil has been completed. Concurs in NRC findings & in NRC conclusion that upon implementation of mode listed in rapt, fire protec prog will be acceptable.

  BEHN J.D. Oage-Babcock Associates, Inc. 78/11/29. ip. 94190:116.

#### Q. Adjudicatory correspondence

- 7810160155 Requests by intervenors for production of documents by NRC steff & applicants & enlargement of time to file interroge. Also submits interrogs to appl & requests that attached documents be explained.
  FLEISCHAKER, D., PHILLIPS. J. Center for Lew in the Public Interest. 78/07/27. 19pp. 94005:143.
- 78:0190207 Forwards various plaadings of Intervenors(Scenic Shoreline Preservation Conference, San Luis Obispo Mothers for Pasco, Ecology Action Club, S. A. Sliver, & J. J. Forster) re oper 16: FLEIBCHAKER, D. Fleischeter, D. S. 78/09/28. 3pp. 94032:017
- --7810190262 Intervenors(Scenic Shoreline Preservation Conference, stc).
  request for oral argument.
  FLEISCHAKER, D. Fleischeker, D. S. PHILLIPS, J. P., KRISTOVICH, S.
  Center for Lew in the Public Interest. 78/09/28. 3pp. 94052:020.
- --7810190267 Intervenors(Scenic Shoreline Preservation Conference, stc)
  request to reply to NRC & applicant response to intervenors
  request for issuance of ASLB subposans.
  FLEIBCHAKER, D. Fleischaker, D. B. PHILLIPB, J. P., RIBTOVICH, B.
  Center for Law in the Public Interest. 78/09/28. 2pp. 94052:023.

190269 Intervenors (Scenic Shareline Preservation Conference, etc) quest to reply to NRC & applicant response to intervenors quest for issuence of AGLS subpoenas.
EISCHAKER, D. Fleischater, D. B. PHILLIPB, J. P., KRIBTOVICH, S. nter for Law in the Public Interest. 78/09/28 32pp. 052:025

Olog Notice of reconstitution of ASLAB re OL proceeding.

liman, A Rosenthal & W Johnson will serve on board.

O.M.S. Atomic Safety and Licensing Appeal Panel. 78/10/03. ip.

O324 Suppl Memo in support of intervenor SLOM appeal from 780511 0705 Orders re qual of accurity experts SLOM now seeks of certification & qual only of D Comey as security of for discovery purposes. S.y.l., VALENTINE.P.C. Ban Luis Obispo Mothers for Peace. 0706. 22pp. 94389:275.

O126 Grente request by intervenor for extension to 781006 to ond to PGE motion to dismiss security contention.NRC P is also granted extension to 781006.per their request. RS E.S. Atomic Sefety and Licensing Board Panel 78/10/10. 94414:025.

O182 Denies request by Intervenors that Bd subpoens 13 persons as eases in avidentiary hearing. Denied because Bd remains nvinced that circumstances are exceptional & warrant ting the request.

RB:E B. Atomic Bapaty and Licensing Board Panel 78/10/10.
94392:254.

O-DOB Requests Ed stay lesuance of any order on Applicants motion ismiss accurity contention until Appeals Ed leaves its ng in repsones to Intervenors motion for direct lification, M/anci cert of evc.
NTINE P. C. Ban Luis Obispo Mothers for Peace. 78/10/10. 4pp. 4: 2i6.

OBSO Poke response to intervenor SLQM's Petition for direct ification & SLQM's appeal from ABLE Order of 780905. Poke rts that certification is not appropriate. Supporting mentation & Cert of Bvc encl.
ON.B., MDRRIBEEV.J.C., CRANE.P.A. Pscific Ges & Electric Co. O/10. 35pp. 94253:279.

O294 Intervenor's Request to Subposes Dr S Orshem to testify resertions that Applicant has falled to conduct thorough atigations of Hospri fault sys. Cart of Svc anci. SCHAKER: D. Fleischeter: D. S. PHILLIPS, J. P., KRISTOVICH: S. Listion Unknown. 78/10/16. 11pp. 94025:347.

O128 Advises Lic 8d of status of 6 independent experts subpossed equest of intervenors. GCHAKER, D. Fleischeker, D. 8. 78/10/16. 2pp. 94035:143.

ODIS NRC Staff Answer to Appl Motion to Dismiss Security ention. Staff suggests the 3d defer on a ruling while ryenor Sen Luis Oblego Mothers for Peece awaits ruling heir appeal re the escurity lesue.

NBERG.M.R. Office of the Executiva Legal Director. 78/10/16-9438(7-265.

OO82 Informe B6 that Steff will comply w/Intervanor's request documents & Interrogs to the Staff no leter then 781025 to error in mells. There will be the seme answering time limits anticipated by perties.
TELLOTTE, J. Hearings Division. 78/10/17. 2pp. 94035:096.

OO39 Replies of Subj Util to Intervenors' Interrogs dtd 780927. mes of Guel for Sefety Hearings & Cert of Svc encl. E-P.A., NORTON.E., FURBUSH.M.H. Pacific Ges & Electric Co. O/17. 93pp. 94290:008.

O314 Forwards subposes for signature of E Bowers, One will be ed upon Dr Stephen Orahemithe other E copies are for raference.

BCHAMER.D. Fleischaber, D. B. 78/10/23. 1p. 94087:042.

OOSS Notice of eddition of E J Bullivan to list of steff sees provided in Sept 1978 Davis ltr re redlological th & safety hearings.
TELLOTELJ. Office of the Exacutive Legal Director. 78/10/25, 94423:325.

0199 "NRC Braff Response to Intervenor's San Luis Obispo Mothers Peats Petition for Directed Cert & Appeal from Licensing rder of 780905." Urges Intervenors patition be denied. of Syc encl. NHERO, M.R. Office of the Executive Legal Director. 78/10/26. . 03533:342.

- 7811080185 Hemorandum & Order prenting the petition for directed certification vacating Bd's 780705 order & remanding the cause for immediate further consideration consistent w/this capinon in the oper licensing proc.

  DUFLD.M.E. Atomic Bafety and Licensing Appeal Panel. 78/10/27, 12pp. 94405;113.
- 78iii000i4 No objection to Intervenor's request of 70i016 to subpossa Dr Grehm for the upcoming evidentiary hearing TOURTELLOTTE.J. Office of the Executive Legal Director. 78/10/27. ip. 94i7a: 351.
- 7811080029 Forwards "Staff Commants on Generic Natter of Crose"
  Examination of ACRE Consultants in NRC Licensing
  Proceedings". Wyencl Cart of Svc.
  TRESV-S A. Office of the Executive Legal Director 70/10/30. 10pp.
  94398:067.
- 7811280498 Notice that PQE will take depositions of F 811ver.J Bruns & R Hubbard. Also encl is response of PQE to intervenoral request of 780927 for production of documents Documente sought are now available for inspec. Cert of 8vc encl CRANE.P. A. Pacific Oas & Electric Co 78/10/30. App 94414: 269
- 7811070358 Urges ACRB permit cross-exemination of consultants. Cross-exemination is sessential to accurate interpretation of opinion & determination of fectual bases of assumption. VALENTINE, P. C. Valentine, P. C. 78/10/31, 1p. 94043 196
- 78:1170007 "Reconsideration of Bd's Order of 780905." Petition of Gan Luis Objego Mothers for Peace to establish David Comey as an expert witness is denied.
  BOWERS.E. 8 Atomic Safety and Licensing Board Panel. 78/11/03.
  3790. 94:16:104.
- 7Bi1200042 Evidentiary hearing on 781204 will be held in Avila Beach. CA. First 2 days of hearing will be set asids for limited appearance statements of no longer than 5 minutes each. Written statements of any length may be submitted. BOWERS.E. 9. Atomic Sefety and Licensing Board Penel. 70/11/07. 2pp. 94215:324.
- 7812010178 Attorney RK Hosfling enters appearants in captional matter. Cart of Svc enci. HOEFLING, R.K. Office of the Executive Legal Director. 70/11/09. 3pp. 94409:205.
- 7812010048 Expresses view on gen policy question of subpossing ACNB consultants to require their attendence at evidentiary hearings before ABLD. Exceptiones informatences etandard should not be limited to direct knowledge witnesses. FLEBCHAKER, D. Center for Lew in the Public Interest. 78/11/14. 3pp. 94416:133.
- 7812040321 Testimony of N Neumerk re-earthquake resistence design criteria utilized in conetr of subj facile. "Retionals for Development of Design Spectra for Diablo Canyon Reactor Facil" & Cert of Byc encl.
  NEWMARK, N. M. N. M. Neumerk Consulting Engineering Services.
  78/11/15, 75pp. 94122:001.
- --7812040324 Testimony of CJ Stepp re subj facil seismic concerns addressed during construering the Cper Lic review. STEPP, J. C. Gensciences Branch. 78/11/15. 41pp. 94192:076.
- --7812040327 "Diablo Canyon Testimony of J Knos & F Rosa re Helsinic Go of Class IE Equip," discussion of seismic qual eval with criteria in Hefsty Evel Rept 3.10 & euppls. ROBA.F. Power Systam Branch, 78/11/15, 12pp. 94122:117.
- --7B12040D3D "Testimony of RB Hofmenn" re conservative value for groun acceleration from a 7.50 santhquake on the Hospri fault. HOMMANN, R. B. Dffice of Standards Development, Director. 7G/11/10 22pp. 94122:129.

--78120403' for Un (1967meat HALL

--78120405 (def1r etruct KNIOHT 94122;

7812130006 Reque...

- 7812110219 Asis whether seismic hearings will begin 781204 Believes facil should not be allowed to open for love of humanity in general.

  ROSENBERG, H. Affiliation Uninoum. 78/11/17. 1p. 94337:359
- 7812180324 Forwards testimony on behalf of intervenors re Contention i. Oeology & sets forth conclusions re through-poing continuity of the San Gregario-Hosgri fault zone. Resume. Study results & Cert of Bvc encl GRAHM.8. A. Affiliation Uninown. 78/11/17. 19pp. 94356:299.
- 7812180309 Petition for directed certification for review of "Reconsideration of Bd's Order of 780903" relating to qual of security expert Forwards Cert of Svc. VALENTINE, P.C. Sen Luls Objepo Mothers for Paece. 78/11/20. 40pp. 94336:190.
- 7812040179 Applicant ODE has until 781205 & NRC Staff until 781211 to respond to intervenor's Petition for directed certification to review ASL814 rejection of DD Comey as an expert witness on security matters.

  DUFLO.M E. Atomic Befety and Licensing Appeal Panel. 78/11/21.
  2pp 94457-073
- 7812020191 Megorandum ach receipt of intervenor's Patition for Directed Certification. Applicant's response is due 7812051 Staff's 781211. Ed will not favor requests to extend time.

  DUFLO, M.E. Atomic Safety and Licensing Appeal Penel. 78/11/21.

  20p. 94382 122
- 7812130146 Forwards list of publications & ray qualifications sheet omitted from 780927 Staff's response to intervanor's intervog KETOHENE Q Office of the Esecutive Legal Director 78/11/21, 22pp. 94289:064.
- 7812080004 Order granting permission to make opening statements prior to limited appearances. Each etatement limited to RO minutes. No change will be made from stated location. BOMERS.E 8. Atomic Sefety and Licensing Soard Penal. 78/11/27. 2pp. 94103.314
- 7812080024 Requests to meta appearance statement at 781204 hearing in 8an Luis Obiapo County.CA. RICEL. Apriliation Unknown. 78/11/27. 1p. 94104:002.
- 7812140346 Forwards list of publications of JF Devine & resume of FA McKBoom.

  KETCHEN,E Q. Office of the Executive Legal Director. 78/11/27.
  10pp 03957:175
- 7812140089 Suppl reply of POE to intervenors' interrage of 780927. Forestds names & quals of 4 addi witnesses POE intende to cell in the liceneing hearing the subj facils. Cert of Svc encl. CRANE.P.A., NORTON,B., MORRISBEY, J. C. Pectfic Gee & Electric Co. 78/11/28. 10pp. 94128:231.
- 7812140344 Gives notice that E Netchen entere on appearance on behalf of NRC in proc re subj fecils. Cert of Svc encl.
  KETCHEN.E. G. Office of the Executive Legal Olractor. 78/11/28. 3pp. 03557:168
- 7812140373 Confirms 781192 conversation re-status of 2 USOB witnesses appearing for NRC Both witnesses wrote USOB rept which is appeared to Suppl 4 of SER & will be at hearing to ensur questions.

  TOURTELLOTTE, J. Hearings Division, 78/11/29. ip. 03558; iiB.
- 7812180027 Forwards memo to subpose to ACRS consultants entitled "Interpretive Comm Statement on Amenability to Subposes of Consultants to ACRS under 10CFR2.720."

  80MRRS.E.S. Atomic Sefety and Literaing Soard Penel. 78/11/30.4pp. 94130:340.
- --7812180037 Forwards "Interpretive Comm Stetement on Amenability to Subpoens of Consultants to ACRS under 10CFR2.720." which now represents the Comm's views & which will be presented for formal vate at next Comm Affirmative Session.

  KELLEY.J.L. Office of the Esscutive Legal Director. 78/11/29. 19. 94130:341.
- 7812180416 NRC Staff's Response to Petition submitted by intervenor Sen Luis Obispo Mothers for Peace seeking revise k reversal of ABLB's upholding of denial of D Comey's quals. NRC urges that intervenor's petition be denied. Cert of Svc encl.

  STAENBERO, M R. Office of the Executive Legal Director. 78/12/01.

  3pp. 74336:338.

- 7812210521 "Suppl Reply of Jt Intervenors' to Applicant's If 780927 "Cart of Svc encl. HUBBARD.R. B. MHB Technical Associates. 78/12/01. 4pp.
- 7812270025 Urgsa epproval of plant oper as soon at possible; elec pur la vitaily needed. RUSGELLH.M. Affiliation Uninoun. 78/12/05. ip. 94159:
- 78:2140273 Forwards AmendWi to Constr Permit#CPPR-39 & Amend Constr Permit#CPPR-69 w/related correspondence. ODLOBERG, J. R. Office of the Executive Legal Director. 78 ip. 03357.289.
- --/812140278 Forwards Amend#1 to constr permit#CPPR-39 & Ameconstr permit#CPPR-69 & Fed Register Notice.
  BOYD.R.B. Division of Project Management. 78/12/05. 4
  0357:290
- --7Bi2i4027B AmensWi to Constr PermitMCPPR-39 edding antitruto Peregraph 2.D.
  BOYD.R.B. Division of Project Management. 78/12/05. 1
  03377.294.
- -- TBIR140279 Amended to Constr PermithCPPR-69, adding antitru to Paragraph 2.0 BCVD.R.B. Division of Project Hanagement. 78/12/06. 1 03597:304.
- --7812140283 Notice of leguance of Amendal to Conetr Permital Amenda4 to PermitaCPPR-49. Went! Evel of Amend by LMR41. STUL7.J.F. Light Weter Reactore Branch t. 78/12/06. 8 0357-314

## H. Ubharai correspondanca

- 7811180180 Expresses concern dwar role of nuclestery in UB of suggests more resident directed towards solar energy. Deplores Liquid Metel Breeder Reactor & the idea of elting plant on the James River near her home.
  NELEDN.E.B. Affiliation Unknown. 78/10/21. 3pp. 94272:
- 7811210312 Act receipt of 78D918 ltr & environ impact statem date & location of public hearing on subj fecil & submits questions of concern re subj fecil.

  MURRHYLE. Affiliation Unknown. 78/10/30. ip. 94488:098
- 7812180289 Forwards for Dept of Energy Respones, a memo re an G Burne Into who inspects the structural steel of the subj facil. LAGURARBINO, R. J House of Rep. 78/11/22, Spp. 94366: 142
- 7812:10040 Responds to 78:000 ltr re selemic design, conservé u/regard to elec losd projections & notice of hearing. BALLARO,R. L. Environmental Projects Branch I. 78/11/30, 94408:169.
- 7812270059 Strongly recommends putting subj Petil Into oper possible elice the energy is necessary. OEDROE, J. Affiliation Unknown. 78/12/07. lp. 94180:291
- 7811210413 Selleves nuc pur cennot be made sere & that const fecil should be stopped. STANLR.F. APFiliation Unknown. 78/11/13. ip. 74485: 12
- K. Utility Final Safety Analysis Report (FSAR) & amende
- 78iii40126 Forwards copy of Amende 70 & 71 to open lic appl facils. Amends incl add1 mat1 for Hosgri evel & FSAR. Cart of Bvc encl.
  CRAME.P.A. Pacific Ges & Electric Co. 78/ii/09. 2pp.
- --7811140145 Amenda 70 & 71 to Oper Lic appl for subj facila 4ddl meti for Hosgri Eval & FBAR, SHACKLEFORD.B. Pacific Ome & Electric Co. 78/11/09. 4
- O. Advisory Committee on Reactor Sefeguards reports & corres
- 7812150050 Comments transmitted in 780722 ltf from ACRS cons Luco re seismic eval bases were discussed at 781102-04 ACR seeting. These comments were considered in the findings & recommendations in ACRS rept of 780714. LAMPOSKI, S. ACRS - Advisory Committee on Reactor Safeguar 78/11/07. ip. 94210:253.

BON.D P. Light Weter Reactors Branch i 78/10/24. 3pp. 3: 144

010384 Forwards comments by Dr Luco re setamic design basis for ij facil.
(INLEY, J. C. ACRS - Advisory Committee on Reactor Bafeguards '10/13. 10 94388-167.

>10388 Comments on 780614 & 780707 acrs meetings re use of fective peak acceleration & undersetination of subj fect1 sponse to offenore fault resulting from use of large luction for teu-effect & small torsion excitation.

10, J.E. Californie, Univ. of. San Diego. 78/09/22. Spp. 188: 168.

# action reports. IE Bullstins & correspondence

1316 Forwards IE Circular#78-17. (8se ANO: 7810230221. Docket 3-781013) KEN-R H Region 5. San Francisco. Office of the Director 1/13 ip. 94166: 347.

263 Forwards IE inspec ReptsW50-275/78-14 & #50-323/78-14 on 1-30 during which no items of noncompliance were noted.

J.L. Region 5. San Francisco, Reactor Operations Nuclear to Branch. 78/10/17. 2pp. 94273:355

20267 IE Inspec Repts#50-275/78-14 & #50-323/78-14 on 780901-30 ing which no items of noncompliance were noted. Mejor as Inspected included; preoper testing, fuel storage, lawup on licenses event & IE Bulletin-Circular-testing.
RNBERG.D. M. Region 5, San Francisco, Resttor Operations Nuclear port Branch. YOUNG.T., STERNBERG.D.H. Region 2, Atlanta, ctor Operations Nuclear Support Branch. 78/10/16. 5pp. 73:357

111 Responds to 78:006 NRC itr re violation noted in Inspective actions: circuitry is being placed in conformence R peregraph 3.3. & implementing instruc will be issued 11:5.

•P.A. Pacific Gas & Electric Co. 78/11/02 2pp. 94043:348

DO7 Forwards IE Circular 78-18. 4EN.R.H Region 5. Sen Francisco, Defice of the Director 706. ip. 94112-301.

DO1 Forwards IE Inspec Repts#50-275/78-17 & 50-323/78-16 on I-31 during which no itsms of noncompliance were noted. J.L. Region 5. Ban Francisco, Reactor Operations Nuclear & Branch. 78/11/16. 2pp. 94207:190.

90004 IE Inspec Repte#50-275/78-17 & 50-323/78-16 on 781001-31 ing which no Items of noncompliance were noted Major se inspected incl:preoper testing fire protectplent tour, lien repts. IE bulletin followup & design thanges. 49-T. & STERNBERO. D. M. Region 5. Ban Franciero. Resctor ations Nuclear Support Branch. 78/11/15. 4pp. 94209:192.

#01 Forwards IE inspec Rept#50-275/78-16 on 781030-31 & 1101 | which no Items of noncompliance were noted. U.L. Region 5, Sen Francisco, Reactor Operations Nuclear to Branch. 78/11/17, 2pp. 94306:328.

HO314 IE Inspec Rept#50-275/78-16 on 781030-31 k 1101 during which tems of noncompliance were noted. Hajor ereas inspected : Conteinment Integrated Leek Tast.

KENBERRY, B. Region 5. Sen Francisco, Office of the Director.

ER,H.L., MILLER,L.P. Region 5. Ban Francisco, Reactor ations Nuclear Support Branch. 78/11/15. 3pp. 94306:330.

98 Forwards 1E Bulletin#78-12A suppl to 1E Bulletin 78-12. ANO: 7811300055 EN.R. H. Region 5. Ban Francisco, Office of the Director.

33 Forwards IE Bulletin 78-14. EN.R. H. Region 5. Sen Francisco. Defice of the Director. 19. 1p. 06911:001.

# table occurrences. LERs & related correspondence

BA Forwards add1 into re RO: defect in Unit 2 NEMA size#2 motor liers. Unit 1 inspec complete, inspec & replacement of ut springs for Unit 2 will be completed prior to onal test.

4070N. J. D Pacific Oas & Electric Co. 78/12/07. 1p. 294.

- 7812070227 Transcript of PGEE testimony on 781204 Testimony of RV Bettinger. PH Hamilton. RM Johns & SM Smith encl.

  Atomic Safety and Licensing Board Panel. 78/11/20 239pp. 94188: 016.
- --7812070237 Testimony of PQbE on 781204.

  \* Atomic Safety and Licensing Doard Panel. 78/11/20. 200pp 94188.278.
- --7812070242 Testimony of POSE on 781204.

  Atomic Safety and Licensing Board Panel 78/\$1/20. 107pp. 94189:162.
- 7812330056 Transcripte of 781204 heerings re subj Facils Pp 3758-3997. BDWERB.E. - MARTIN.W.E., BRIGHT.Q.O. Atomic Safety and Licensing Board Panel. 78/12/04. 239pp. 94211:030.
- 7812130064 Transcript of 781205 hearing re-subj faciliLimited Appserance Statemente In Avila Beech CA PP 3398-4249. BOHERS-E., HARTIN,N E. BRIGHT-0.O. Atomic Sefety and Licensing Roard Panel. 78/12/05. 251pp. 94296:012
- 7812200344 Transcript of hearing in Avile Beach.CA on 781207.
  Appearences on behalf of applicant B Norton.Mi Furbush, &
  P. Crens on behalf of joint intervenors: DB Fleishaker. B
  Whistovitch & for NRC E Wetchen.Pp 4486-4579.
  BOWERS.E., MARTIN.W.E., BRIGHT.O D. Atomic Sefety and Licensing
  Board Pansi 78/12/07 193pp 94124 is8.
- 7812200338 Transcript of hearing in Avila Beach.CA on 781208 Appearance on behalf of Pacific Ges & Elec:B Norton.MH Furbush.P Crans. on behalf of joint intervenors: DS Fleischater.S Kristovich & for NRC:M Staenberg Pp 4679-4682
  BOMERS.E., MARTIN.M.E., BRIGHT.Q O Atomic Sefaty and Licensing Board Panel. 78/12/08. 183pp. 94124:003.
- 7812270346 Transcript of hearing re subj fecil at Avila Desch.CA on 781213 Pp 5309-5806 BOWERB.E. Atomic Befety and Licensing Board Panel 78/12/13. 197pp. 94229:024.
- 7812220014 Transcript of 781214 hearing in Avile Beach, CA re subject 1. Pp 5507-5706
  80WER8.E., MARTIN.W.E., BRIGHT.O.O. Atomic Safety and Licensing Board Pansi. 78/12/14. 197pp. 94248:024.
- 7812290002 Transcript of a 781218 hearing in Avila Beach CA fe subj fecil.Pp 6102-6359. BOWERS.E., MARTIN.W.E., BRIGHT.G D. Atomic Sefety and Licensing Board Panel. 78/12/18. 257pp. 94208:050
- 7812290279 Transcript of a morning 781214 hearing at Avile Beach, CA resubj fecil. Pp 6360-6471.
  BOMERS, MARTIN, M.E. BRIGHT, O.O. Atomic Sefety and Licensing Board Penel 78/12/19. iiipp. 94192:001.
- 7812290280 Transcript of 781229 hearing on 781220 st Avila Beach.Cs. Pp6472-6689. BUMERS-E. MARTIN.H.E. BRIGHT.O.O. Atomic Safaty and Licensing Board Panel. 78/12/20 216pp. 94193:001.
- 7812290282 Transcript of 781221 hearing in Avila Deach CA re subjecti. Pp 6689-6862. 80HERS.E., MARTIN.H.E., BRIGHT.O.O. Atomic Befaty and Licensing Board Penel. 78/12/21. 173pp. 94194:001.
- 7812290283 Transcript of a morning 781222 hearing in Avile Seach CA resubj facil.pp8863-6949.
  80HRR8.E., MARTIN.H.E., BRIGHT.G.O. Atomic Sefety and Licensing Board Penel, 78/12/22. 86pp. 94195:001.

#### U. Congressional/Executive Correspondence

7811080032 Responds to encl 780831 & 780925 congressional correspondence w/ODE requesting info to ensure constituent's charges re not waste storage & location of subj facil near geologic fault.

DIRCKS.M.J. Office of the Executive Director for Operations. 78/10/30. 10pp. 94398:089.

- Q. Inspection reports, IE Bulletins & correspondence
- 7812010175 Forwards 16 Inspec Reptab50-160/78-04.450-276/78-02. W70-2797/78-04 & W70-386/78-04 on 780926-27 during which no items of nancompliance were noted. KENN-W.W. B. Region 2. Atlenta, Safeguards Branch. 78/10/20. 2pp. 94409:221.
- --7812010182 IE Inepsc Repts#50-160/78-04.#50-276/78-02.#50-297/78-04 & #70-0286/78-04 on 780926-27 during which no items of noncompliance were noted Major areas inspec inclinuc matl control & accounting procedures review.
  TODD.Q.A. WILLIAMS.Q.H. Region 2. Atlente, Sefeguerds Brench. 78/10/20. 3pp 94409.223.
- 7812210281 Forwards 16 Inspec Rept#50-276/78-03 on 781121 during which no Items of noncompliance were noted.
  KENNA-W.B. Ragion 2. Atlanta. Sefeguerds Branch. 78/12/13 Spp. 94167: 298.
- --7812210287 IE inepsc Rept#30-276/78-03 on 781621 during which no items of noncompliance were noted. Areas inspected; physical security pratec prog. Details of inspec w/held pursuant to 2.790.

  MODRE, D. E. , OILLESPIE, F. P. Region 2. Atlanta, Safeguards Branch, 78/12/13. 1p. 94167.300.
- DOCKET 50-277 PEACH BOTTOM ATOMIC POHER BIATION, UNIT 2 F. Becurity, medical, emergency & fire protection plens
- 7811290078 Forwards request for eddi info re fire protec at subj facil.

  Several NRC staff positions are encl re concern on this subj.

  IPPOLITO.T.A Operating Reactors Brench 3 (Pre 790625). 78/11/17.

  46pp. 94192-209.
- 7812260192 Responds to 781117 request for edd1 info rs Firs Protec Prog. Remainder of questions will be eddressed with 90 days.

  8ubj covered incl: cebles above control room celling, anclosed rooms win control room complex & seel quel prog.

  DALTROFF, S. L. Philedelphie Electric Co. 78/12/20. 33pp. 94199: 163.
- Q. Adjudicatory correspondence
- 7812130217 Memo & order re ALAB-509. Any party who disagrees w/ABLAB approach re radon emissions should file brief within 45 days.

  DUFLO, M. E. Atomic Sefety and Licensing Appeal Penel. 78/12/01.

  11pp. 94306:087.
- P. Operating license stags documents & correspondence
- 7810300169 Forwards analysis of Gen Elec turbine trip transient tests performed during Apr 1977.
  ROBZTOCZY, Z.R. Analysis Branch. 77/11/02. 1p. 94034:114.
- --7810300174 "Baffety Eval Rept on OE Transient Analysis Method in View of Peach Bottom Yests". Repts validity of OE transient amalysis methods & verifies plant transient behavior. Four possible interim positions are presented.

  ROBZTOCZY, Z. R. Analysis Branch. 77/04/11. 16pp. 94034:115.
- 7812050004 Forwards Licenses Performence Eval Questions for out; fecile in response to 771123 request. Feele it is possible that dev of statistical methodology for such evel may not justify the effort. Qualitative eval may be as good. Urges i-year test. CRIEN, B. H. Region i, Philadelphia, Office of the Director. 77/12/13, 12pp.
- 7812130198 Act receipt of 760604,70930,761130, & 761203 submittals. Forwards request for add into to be provided w/in 34 deys for cost-benefit analysis.

  LEAR. G. Descating Reactors Branch 3 (Prs 790623). 77/02/16. 3pp. 94306.054.
- 7810230035 Notice of Issuance of Amends 844 & 844 to Fecil Oper Lics MDRR-44 & DRR-56, Amends delete Environ Tech Specs Sections 6.1.b, 6.1.c & 6.1.d, re special study prog related to impingement entrainment & thermal tolerence of organisms. LEAR.0. Operating Reactors Branch 3 (Pre 790625). 78/07/26. 2pp. 94052:319.

- issued Amends#45 & #46 to Facil Oper Lice\*MPR-44 & DPR-56.
  Amends rev Tech Space to mod reactor coolant Sys thereal &
  pressurization limitations.
  1PPD\_170.T A. Operating Reactore Branch 3 (Pre 790625). 7B/08/64.
  20p. 94992-234.
- 7811010390 Forwards Amends#46 & 46 to Fatil Oper Lit#DPR-46 & DPR-56 ray Tech Specs as requested in 780711 ltr w/Safety Evaluation & Notice of Issuance.

  IPPCLITG.T.A. Operating Reactors Branch 3 (Pre 790425), 78/10/03 2pp. 94388:281.
- --7811010393 Amend#46 to Facil Oper Lic#DPR-44 ray Tech Spece resurveillance of suppression pool temp logging, controlled bypes heatup lins on HPCI stam supply & identification of valvas to raffect plant unique designation.

  IPPOLITO.T.A Operating Reactors Branch 3 (Pre 790625). 78/10/03 9pp. 94308:203.
- --7811010400 Amend#46 to Facil Oper Lic#DPR-56 rev Tech Space re: surveillence of suppression pool temp logging.controlled bypes haetup line on HPCI steem supply & identification of valves to reflect plant unique dealgnetten. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/03. 9pp.
- --7811010405 Sefety Evel Rept supporting Amenda446 & 46 to Fecil Oper LicmDPR-44 & DPR-56 concluding thet proposed mode & essoc Tech Spac changes heve no sefety or environ eignificance & are therefore eccapteble. # Operating Reactors Branch 3 (Pre 790625). 78/10/03. 3pp. P4388:301.
- --7810130232 Notice of Issuance of Amend#46 & 46 to Fecil Oper LiceDPR-44 & DPR-36 on 781003.
  IPPOLITU.T.A. Operating Rectors Branch 3 (Pre 790625). 78/10/03 2pp. 94081:340.
- 7B10110105 Responds to 7B0B07 Itr requesting svaluation of subj facil Protec Sys pur supply to determine whether there is potential for undetected single failures to adversely affect Reactor Protec Sys.

  OALTROFF.S.L. Philadelphia Electric Co. 78/10/05. 2pp. 94066:391
- 7810230011 Forwards Amend#47 to LicaDPR-44 & #47 to LicaDPR-56 for subj fecil-changing Tech Spec in response to 780526 & 780905 ltrs. [PPLLITO-I.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10.

emubbase.

IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10.

Ripp. 94169: 210.

- --7810230019 Amend#47 to Facil Oper Lic#DPR-56, changing Tech Spec fe fire protec & admin controls. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10. 24pp. 94169:231.
- --7810230024 Bafety Evaluation Supporting Amend#47 to Facil Lic#DPR-44 & Amend 47 to Lic#DPR-56. Concludes that amend will not decrease safety mergin.

  \*\* Operating Reactors Branch 3 (Fre 790625). 78/10/10. Spp. 94169: 255.
- --7810230028 Notice of Issuance of Amend#47 to Facil Oper LiceOPR-44 & Amend #47 to DPR # 56, rev Tech Spec re containment cooling sys controls, admin controls & anubasts. IPPOLITO, T. A. Operating Reactors Branch 3 (Pro 790625). 78/10/10. 2pp. 94169; 263.
- 7811060124 Forwards Amend#48 to Facil Oper LiceDPR-44 revising Tech Bases as requested in 781004 ltr w/Safety Evaluation & Notice of Issuance. IPPCLITG.T.A. Operating Reactors Branch 3 (Pre 770625). 78/10/16. 2pp. 74424:146.
- --7811040125 Amend#48 to Facil Oper Lic#DPR-44 revising Tech Spec re-oper of subj fecil w/new type reload fuel(8x8R)far cycle 4. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre-790423). 78/10/16. 36pp. 94424:148.
- --7811060128 Safety evaluation supporting Amend %48 to Facil Oper LiceOpp-44 concluding that design of SidR fuel, therealhydraulic stability of subj facil & proposed oper limit are acceptable & safety of pub will not be endangered. a Office of Nuclear Reactor Regulation, Director. 78/10/16. 10pp. 94424:184.

- )60130 Notice of Issuance of Amend#48 to Facil Oper LicHDPR-44 on 1016.

  \*\*OLITO.T.A Operating Reactors Branch 3 (Pre 790625). 78/10/16.

  \*\*Pp. 94424:194
- 1272 Provides results of test on facility et end of cycle 2 tions using proposed licensing basis ODYN Model.
  K. M. General Electric Co. 78/10/17. 20pp. 94203:174.
- iO274 Transmits calculational results & data related to steff's 'i qu of ODYN transient model. Info incl calculations formed to quanify effects of stuck rod on scram c tivity & series of figures as delta K versus X voids. K.s.K.W. General Electric Co. 78/10/17. 27pp. 94203:195.
- 10277 Forwards results of studies carried out in effort to Prmine reason behind epparent discrepancy between BNL & Wold reactivity feedback models.
  46.K.M. General Electric Co. 78/10/17. 7pp. 94203:222.
- 1 OB Response to 780927 NRC ltr re benchmarking Enc's PTSBWR/2 against present deta & verifiqing transient & stability . Data to be supplied in Dct 1979 will settlefy requests twin GE proprietary info must be provided.

  Y+ 0.F. Exxon Nucleer Co., inc. (subs. of Exxon Corp.).

  / 19. 2pp. 94059:300.
- 186 Forwards "Postoperational Rept#10 on the Ecology of 1 mgo Pond for the Period of 7801-7806". EV-M. 8. Philadelphia Electric Co. 78/10/24. 1p. 94034:073.
- 70188 "Postoperetional Rept#10 on the Ecology of Conowingo Pond Period Jan-June 1978". Philadelphie Electric Co. 78/10/31. 161pp. 94054:074.
- 335 Surmary of 750914 meeting w/QE representatives & Mark 1 % Group re progress of Long Term Prog w/attendance & agenda (RD-9-A-Markl, Standards. ) % C. Plant Systems Branch (Pre 791030). 78/10/26. 47pp.
- 288 Responde to 781106 request for info concerning licenses reg remance eval for Region 1 plants by NRC. Provides 1 t., .B. H. Region 1. Philadelphie. Office of the Director. /OP. 9pp. 94239:230.
- 130 Notice of workshops re implementation of training & qual rements contained in Append B of 10CFR73. Requests 3rkshop registration of attendees to fecilitate sending sti.Wencl Registration Form & List of Locations. R. J.R. Assistant Director for Bite & Befeguards (Pre 791030). 715. 3pp.
- 268 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for (NAUREO-0473) & "Preparation of Radiological Effluent Specs for Nuc Pur Plants" (NUREO-0133).
  3. B.K. Assistant Director for Engineers & Projects (Pre 53. 78/11/15. 6pp. 94364:324.
- )&& Responds to 78:116 telecon.Forwards copies of ANB meeting s which demonstrate attention to ALARA per RGB.B. s. J.C. Ebesco Services, Inc. (subs. of Enserch Corp.). '17. 1p.
- .0070 "Experience in Decontemination & Repair of Radwasta: mentrator at Hillatone Unit#1." Describes procedures. 4A.J. Northeast Nuclear Energy Co. (subs. of Northeast .i ties). 78/1/17. 19pp.
- OO74 "Peach Bottom 2 & Q.Regenerative Heet Exchangers Cham: :mainstion & Seel Ring Repairs." Describes work performed 777 & 1978. EER.H.B. Philadelphia Electric Co. 78/06/06. 22pp.
- OO77 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem nitamination & Golidification." Describes work performed 977. 'Y. O. E. Daw Chemical Co. 78/02/16. 38pp.
- IBS Informs PECO that NRC has contracted w/Mountain West Res Inc dentake a series of post-licensing studies of nuc pur res. Studies will analyze socioecon impacts which ed during constr & post-constr periods of each plant.

  G.R.C. Division of Site Sefety & Environmental Analysis.

- 7812070205 Notice of seminar on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions. W/oncl Seminar Info Sheet-Proposed Agende t meps GRIER. B. M. Region 1. Philadeiphia. Office of the Director. 78/11/21. 6pp. 94375:152.
- 7812110052 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wienci ANO: e7812080207 IPPLLITG.T. Operating Reactors Branch 3 (Pre 790625). 78/11/29. 8pp. 94408-227.
- 7812180104 Forwards Amanda#49 & #48 to Licenses DPR-44 & DPR-65, respectively.Tach Space by increasing total storage capacity of spent their pools from 2220 to 5632 fuel assemblies. Forwards EER,EIA & notice of leasence IPPCLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/30. 2pp. 94130:253.
- --7812180103 Amenda 449 & MAB to Lic DPR-44 & DPR-55, respectively, espansion of epent fuel pool storage capacity & related Tech Spece. Forwards supporting SER & EIA.
  GRIMBE, B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/30 12pp. 94130:255.
- --7812180107 Safety Evel supporting Amende#49 & 48 to Lics DPR-44 & DPR-56 respectively.

  Assistant Director for Engineers & Projects (Pre 790625).
  78/11/30. 11pp. 94130:267.
- --7812180112 Notice of issuence of Amende#49 & #48 to Facile Operating Lic #DPR-44 & DPR-56.respectively, & Negative Declaration. 1PPOLITO,T A. Operating Reactors Branch 3 (Pre 790625), 70/11/30. 3pp. 94130:300.
- --7812180108 EIA supporting Amends#49 & #48 to Lice #DPR-44 & DPR-56respectively.

  \* Assistent Director for Engineers & Projects (Pre 790625).
  78/11/30. 22pp. 94130:278
- 7812140176 Forwards Oct 1978 Prog Activity Review listing mestings held to providing tesk-by-tesk ectivity summary for the month. BUBON.L.J. General Electric Co. 78/12/04. 11pp.
- 7812280035 Emphesizes importence of submnitting occurate & complete info to NRC by licensess & epplicants. Info submitted must be substantiated by data & celculations. Licenses must notify NRC of any ineccuracies or enforcement action will result. DAVIS. J. G. Office of inspection & Enforcement, Office of the Director. 78/12/06 2pp. 94133:214.
- 7812030013 Requests views of Regional Directors on Licenses performance evel of subj facile Forwards questions to be ensured by 771209.

  THORNSURG, H. Division of Reactor Construction Inspection. 77/11/23 265.
- 7811210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program SOBON, L. J. General Electric Co. 78/11/13. 3pp.
- Q. Inspection reports: 1E Bulletins & correspondence
- 7811090053 Forwards IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780823 during which no items of noncompliance were noted. BRUNNER, E. J. Region 1. Philadelphia. Resector Operations Nuclear Support Branch. 78/09/21. 2pp. 94040:099.
- ~-7811090058 IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780823 durin which no items of noncomplience were noted Hejor areas inspected included review of Licenses's response to IE Circular 78-8 dtd 780531.

  ORGENMAN.E.O. MCCARE.E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/18. 6pp. 94040:101.
- 7810160208 Forwards IE Builetin#78-12: "Atypical Weld Heteriel in Reactor Pressure Vessel Welds" requesting action w/in 60 days. & list of 1E Builetins Jesued in 1978. (see AN087810040253) ORIER.B.H. Region I. Philadelphie, Office of the Director. 78/09/29. 6pp. 94006:353.

- 2pp. 943B1; 300.
- --78:1010095 Notice of Violation from inspec on 780814-16.

   Region 1, Philadelphia, Office of the Director, 78/09/14. ip. 94981:302
- --7811010099 IE Inspec Reptem30-277/78-21 &#30-278/78-26 on 780914-16 during which 1 item of noncompitance was noted: Amount of radioactive decay of Pu-R41 during periods ending 770331, 770930 & 780331 not reported on Form-742-Paragraph 7. BISBETT. P.H. Region 1, Philadelphia, Office of the Director. BHAUR.E. T. JOYNER, J.H. Region 1, Philadelphia, Safeguarde Branch. 78/09/14. 10pp. 94381:303.
- 7810200094 Second Images progress conducted during recent subj facil refueling outage. All 25 channels were cleesified acceptable for reuse in any reactor core location during subsequent oper cycles.

  COONEY.M. J. Philadelphia Electric Co. 78/10/13. ip. 94401:220.
- 78i1060203 Forwards IE Circuler#78-17. (8se ANG:78i0230221, Dockat #30-133, 78i013.)

  ORIER, 8. H. Region 1. Philadelphia, Office of the Director. 78/10/13. ip. 94489: 205.
- 78:2010345 Forwards licenses performance evaluation for Region 1.No operating reactor in Region 1 considered to heve either abnormal or unusual sefety concern. ORIER, B.H., Region i. Philadelphia, Office of the Director. 70/11/01. 4pp. 00002:259.
- 7811290160 Forwards IE Circuler #78-18, "UL Fire Test. "Myencl AND: 7811130002 ORIEN, 8. H. Region i. Philadelphia, Office of the Director, 78/11/06. ip. 94238: 052.
- 78:2010008 Ack receipt of 78:103 ltr informing NRC of steps taken to correct violations noted during lnspscm50-277/78-26. BRUNNER.E. J. Region i. Philadelphis. Reactor Operations Nuclear Bupport Branch. 78/11/15. 1p. 94409:114.
- --7812010012 Responds to 781020 NRC itr re violetione noted in Inspec Rept#90-277/78-26. Corrective actions: procedure req constent monitoring of fuel slement is being rev to ellow aper to observe all aspects. DALTROFF, B. L. Philadelphia Electric Co. 78/11/03. Jpp. 94409:115.
- ---7812010016 Forwards IE Inspec Rept#60-277/78-26 on 780919-22 & Notice of Violation.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nucleer Support Brench. 78/10/20. 2pp. 94409:118.
- --7812010025 Notice of Violation from inspec on 780919-22.

  \* Region i, Philadelphia, Reactor Operations Nuclear Support Branch, 78/10/20, 19, 94409:120.
- --7812010031 IE inspec Repth00-277/78-26 on 780919-22 during which 2 items of noncompliance were noted feilure to complete procedure precedure tree princedure to perferning procedure to failure to observe fuel bundle during movement. KALMAN. 9., OREENMAN. E., CAPHION.D. L. Region 1. Philedelphia, Office of the Director. 78/10/02. 7pp. 94409:121.
- 7811300217 Forwards rev Insvc Inspec Prog in response to 780910 NRC ltt.Table 5.4-1 of ISI prog has been rev to require leak rate testing of valves needed to perform pressure isolation function. List of alternate velves is in Att A.

  DALTROFF, B. L. Philedelphie Electric Co. 78/11/22, 3pp. 94070:001.
- --7811300220 Insvc Inspec Prog for subj facil. Rev prog is IAN 1974 ed of Section XI of ASME Code & upgrades prog for subj facil. New prop establishes rev requirements for Class 1.2 & 3 components of boiling water reactors.

  \* Philadelphia Electric Co. 78/11/30. 45pp. 94070:004.
- 7812180221 Responds to 780929 NRC lbr forwarding IE Bulletin 78-12 & requests add1 info re resector vessel weld matl & resector vessel fabrication. Sen Elec Co is providing this info which will be forwarded to NRC at a later date.

  DALTROFF, B. L. Philadelphia Electric Co. 78/11/22, 2pp. 94358:335.

CODNEY, M. J. Philadelphia Electric Co. 78/10/15. ip. 94169:293.

LIGHT HED

POPUATUR DUDENTU

- --7810230167 Monthly Oper Rept for Bept 1978. ALDEN.W.M. Philadelphia Electric Co. 78/10/15. 9pp. 94169:294.
- 7811140142 Forwards Monthly Open Rept for Oct 1978.
  COUNEY, M. J. Philadelphia Electric Co. 78/11/09. 1p. 94383:240.
- --7811140144 Monthly Oper Rept for Oct 1978. ALDEN, W. M. Philadelphia Electric Co. 78/11/15. 9pp. 94380:241.
- 7811160084 Forwards Monthly Oper Rept for Oct 1978. COONEY.M.J. Philadelphia Electric Co. 78/11/09. 1p. 94134:273.
- --7811160085 Monthly Oper Rept for Oct 1978.
  ALDEN,H. M. Philedeiphia Electric Co. 78/11/15. 9pp. 94134:274.
- 7811170130 Forwarde Thermal & Biological Monitoring ReptW60.covering period 780801 thru 780530 for subj facil. MILLSEY.W. B. Philadelphia Electric Co. 78/11/09. ip. 94469:034.
- ---781170131 Thermal & Bilogical Monitoring ReptW60.covering period 780501 thru 780630.for emby ferils. \* Philodelphia Electric Co. 78/11/09. 37pp. 94459:035.
- 7812080109 Forwarde Thermal Monitoring Repts #61 & #62.
  Willsey, W. B. Philadelphia Electric Co. 78/12/05. 1p. 94246:238.
- ~~7812080111 "Thermal & Biological Monitoring Prog for Unit #2 k3," & Monthly Rept #61 for Jul 1978. Presents deily summary of air temp data:deily generation at PBAPB in thermal megawatts hourly. Conouingo Pond temps & impact hours above July limit.

  # Philadelphia Electric Co. 78/07/31. 12pp. 94246:239.
- --7B120B0i12 "Thermel & Biological Monitoring Prog for Unit 2 & 3."

  Monthly Rept #62 for August 1978 Presents daily generation
  at PBAPB hourly Conomingo Fond & Impact hours above August
  confidence limits.

  \* Philadelphia Electric Co. 7B/0B/31. 12pp. 94246:250.
- 7812180134 Forwards Sept Thermel Monitoring Rept#63. Willsey, M. B. Philadelphia Electric Co. 78/12/12. ip. 94366:008.
- --7812180107 "Thermel & Biological Monitoring Progw63 for Bept 1978."

  Oper w/in applicable thermal criteria w/monthly meen delta tamp 1, 41F higher than mean of preoper experience.

  \* Philadeiphia Electric Co. 78/707/30.
- 781222006d Forwards Monthly Oper Rept for Nov 1978. CDDNEY,M.J. Philadelphia Electric Co. 78/12/14. ip. 94248:300.
- --7812220064 Monthly Oper Rept for Nov 1978. ALDEN.H.M. Philadelphia Electric Co. 78/12/12. 9pp. 94248:302.
- S. Reportable occurrences, LERs & related correspondence
- 7810100082 LER#78-037/03L-0 on 780901: while testing ADS subsys, timers on both loops were found outside the 115-125 second limit of tech specs due to setpoint drift of time delay releys.

  Timers were callbreted, retested & returned to svc.

  CODNEY.M.J. Philadelphia Electric Co. 78/09/26. 1p. 94032:191.
- 7810100101 LERM78-036/03L-0 on 780901: failure of auxiliery oil pump to start due to a ground in motor. Motor. Baidor Tupe 1040D, 7 1/2 H.P., 250V.D.C. was replaced & HPCI mys tested satisfactorily w/in 36 hours. ADB timere not w/in Tech Specs. COONEY.M.J. Philadelphia Electric Co. 78/09/26. ip. 94033:155.
- 7810100036 LERW7B-035/031-0 on 780830: E-3 dissel start time to reach rated voltage & frequency did not meet surveillance test requirement, probably caused by leaking check velve in the hydraulic aus asenc withe air booter relay.

  CDONEY, M. J. Philadelphia Electric Co. 78/09/29. ip.
- 7810130185 Forwards LER#78-039/09L-0. GDONEY,M.J. Philadelphia Electric Co. 78/10/04. 3pp. 94002:356.

430143 LERH78-039/03L-0 on 780904: backflow of redicactive liquid om radwaste demineralizers to evo air sys discovered on 0904 & 780921. Caused by leaking process valves & sociated check vlaves due to dirt deposite

ONEY, M. J. Philadelphia Electric Co. 78/10/04. ip. 94002: 359.

OO94 Rept Occurrence#2-78-41/1P: on 781010 during routine e 11ance test of Unit 2 4KV undervoltage relays setpoint U% sequence looding relays E-32 t E-42 were out of brodue to engr stror.

ICH.N.T. Philadelphia Electric Co. 78/10/11 2pp. 94399:079.

O164 LER#78-040/03L-0 on 780918: While teating stroking control received that when control rod was selected previously cted rod did not deselect. Caused by defactive relay hear subsequently replaced.

EY.M.J. Philadelphia Electric Co. 78/10/17. 1p.

O137 Forwards LERH78-041/01T-0 EY.M.J. Philadelphia Electric Co. 78/10/24. 2pp. 94042:316.

OPO141 LERB78-041/01T-0 on 781010:2 4KV emergency bus sequential adding releys found outside Tech Spec limits. Caused by ror in determining setpoint & calibr span of relays. Relays calib & testing procedures revised.

3NEY, M. J. Philadelphia Electric Co. 78/10/24. ip. 94042; 318.

0146 Forwards LERW78-020/01T-0.
EY.M.J. Philadelphia Electric Co. 78/11/01. 2pp. 94043.001.

O 90182 LERM78-020/017-0 on 781019: unit 3 combainment oxygen nc antration had increased to 0.1% above 4 percent limit of ch Spsc 3.7.A.5. Caused by open air back-up valves in operable instru nitrogen compressor.
ONEY.M.J. Philedshphia Electric Co. 78/11/01. ip. 94043:014.

OO95 LER878-042/03L-0 on 781019: during start-up, inboard mains a line drain legistion valve MD-2-74 would not close in onse to hand switch in control room, due to defective torque 8MB-000 torque switch on the valve.
EY, M.J. Philadeighie Electric Co. 78/11/08. lp. 94134:361.

D225 LERW7B-044/03L-0 on 7810R1: during startup.excessive oper of gland esel condensate pump was noted. Check valve
-131 was leaking which let condensate return to gland condensar. Valves were blocked to facilitate repair.
EY-M, J. Philadelphia Electric Co. 78/11/20. ip. 94474:239.

D210 Forwards revised util 781024 ltr containing LER 78-041/17-0. errative description, "Rated pur" was insperoprietally tituted for "rated voltage" in 2 instances. Revision rate & consistent w/Tech Space.
EY.M.J. Philadelphia Electric Co. 78/11/29. 1p. 03555:117.

OFORIS LERW78-041/01T-1 on 781010; 4V emergency bus sequential adding relays found to be outside Tech Spec calibr rengs at oerror in setpoint & calibr span determination. Four KV adding releys recalibr.

DNMEYH. J. Philadelphia Electric Co. 78/11/29. 2pp. 03555: 118.

D16D LERGTB-047/03L-0 on 781102: during third refueling outage, ed to remove neutron flux complex from reactor vessel, ed by administrative oversight. Eval of sample removal is in progress.

EV. M. J. Philadelphia Electric Co. 78/12/04. ip. 94305:121.

01:30 LER078-046/03L-0 on 78:117; output demand signal from RCIC Controller (Inst#HCQ213-115) read down scale, Cevsed by circuit in controller demand current loop.
EY.M.J. Philoselphia Electric Co. 78/18/06. 1p. 94307:213.

50-978 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 prity, medical, emergency & fire protection plans

1078 Forwards request for add1 info re fire protec at subj fac11. • m1 NRC staff positions are enc1 re concern on this

.X TD.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/17. 94192:209.

7812260192 Responds to 781117 request for add1 info re Fire Protec Prog. Remainder of questions will be addressed win 90 days. Subj covered incl: cables above control room ceiling, enclosed rooms win control room complex & seal quel prog. DALTROFF, B. L. Philadelphia Electric Co. 78/12/20. 33pp.

#### Q. Adjudicatory correspondence

7812130217 Memo & order to ALAB-509 Any party who disagrees w/ABLAB approach to radon emissions should file brief within 45 days.

DUFLO, M. E. Atomic Sefety and Licensing Appeal Panel. 78/12/01.
1199- 94306:087.

## P. Operating license stags documents & correspondence

7812110052 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. Whenci ANO: 87812080207.

IPPOLITO, T. Operating Reactors Branch 3 (Pre 790625). 78/11/29.

Bpp. 94408: 227.

7812180104 Forwards AmendsW49 & 448 to Licenses DRR-44 & DPR-55, respectively. Tech Epics by increasing total storage capacity of spent fuel pools from 2220 to 5532 fuel assemblies. Forwards SER, EIA & notics of lesuance. IPPOLITO, T. A. Operating Reactors Grench 3 (Pre 790625). 78/11/30. 269. 94130:233.

--7812180107 Befety Evel supporting Amende#49 & 48 to Lice DPR-44 & DPR-35-respectively.

A Assistent Director for Engineers & Projects (Pre 790623).
78/11/30. https://doi.org/10.1006/11.780.

--7812180108 EIA supporting Amends#49 & #48 to Lics #DPR-44 & DPR-56, respectively.

# Assistant Director for Englasers & Projects (Pre 790625).
78/11/30, 22pp. 94130:278.

7812080004 Forwards Licenses Parformance Eval Questions for sub; facils in response to 771123 request. Feels it is possible that day of statistical methodology for such eval may not justify the effort. Qualitative eval may be as good. Urges 1-year test. QRIER. B. H. Region i, Philadelphia, Office of the Director. 77/12/13. 12pp.

7812130198 Ack receipt of 760604,70930.761130, & 761203 submittels. Forwards request for add1 info to be provided w/in 34 days for cost-benefit analysis. LEAR.9. Operating Resotors Branch 3 (Pre 790685), 77/02/16. 3pp. 94306:054.

7810230035 Notice of Issuence of Amends #44 & #44 to Facil Oper Lice #DPR-44 & DPR-56, Amends delete Environ Tech Specs Sections 6.1.b.6.1.c & 6.1.d.re special study prog related to Impingement, satireinment & thermal tolsrance of organisms LEAR.9. Operating Reactors Branch 3 (Pre 790625). 78/07/26. 2pp. 94052-319.

781025019: Notice of Issuance of Amends to Facil Oper Lics.NRC has Issued Amends 45 & w46 to Facil Oper Lics\*DPR-44 & DPR-56. Amends rev Tsch Bapecs to mod reactor coolant Bys thermal & pressurization limitetions. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/08/04. 2pp. 94392:234.

7811010390 Forwards Amends#46 & 46 to Fecil Oper LicHDPR-44 & DPR-36 rev Tech Beecs as requested in 780711 ltr w/8efsty Evaluation & Notice of Issuance.
1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/03. 2pp. 94388:281.

--7811010393 Amend#46 to Fecil Oper Lic#DPR-44 rev Tech Specs re: surveillance of suppression pool temp logging.controlled bypes heatup line on HPCI steam supply & identification of valves to reflect plant unique designation. IMPOLITG.T.A. Destating Reactore Branch 3 (Pre 790625). 78/10/03. Tpp. 94388:263.

--7811010400 Amend#46 to Facil Oper Lic#DPR-56 ray Tach Spacs ra: surveillance of suppression pool temp logging.controlled bupess heatup line on HPCI steem supply & identification of valves to raflect plant unique designation. IPPOLITO.T.A. Operating Reacture Branch 3 (Pre 790625). 78/10/03.

- --7811010405 Safety Eval Rept supporting Amends#46 & 46 to Facil Oper Lic#DPR-44 & DPR-56 concluding that proposed mode & assoc Tech Spec changes have no safety or environ significance & are thorefore acceptable \* Operating Reactors Branch 3 (Pre 790625). 78/10/03 3pp 94308 301.
- --7810130232 Notice of Issuance of Amend#46 & 46 to Facil Oper L1c#DPR-44 & DPR-36 on 781003. IPPOLITO.I A Operating Reactors Branch 3 (Pre 790625) 78/10/03 2pp. 94001.340.
- 78:01:10105 Responds to 780807 itr requesting evaluation of subj facil Protec Sys pur supply to determine whether there is potential for undetected single failures to adversely affect Reactor Protec Sys DALIROFF, S.L. Philadelphia Electric Co. 78/10/05. 2pp. 94066: 351.
- 7810230011 Forwarde Amend#47 to LicHDPR-44 & #47 to LicHDPR-56 for eubj Pacil.changing Tech Spec in response to 780526 & 780905 ltrs. TPPOLITO, TA Operating Reactors Branch 3 (Pre 790625). 78/10/10 2pp. 94169:208
- --7810230019 AmendW47 to Fecil Oper LicMDPR-55, changing Tech Spet refire protec & admin controls
  IPPOLITO.T.A. Operating Reactors Brench 3 (Pre 790625) 78/10/10.
  24pp 94169.231
- --7810230024 Safety Evaluation Supporting Amand#47 to Facil Lic#OPR-44 & Amend 47 to Lic#OPR-56 Concludes that amend util not decrease safety margin.

  # Operating Reactore Branch 3 (Pre 790525) 78/10/10 Spp 94169:255
- --7810230028 Notice of issuance of Amend#47 to Facil Oper Lic#DPR-44 & Amend #47 to DPR # 56, rev Tech Spec re containment cooling sys controls admin controls & snubbers. iPPOLITO,T.A. Operating Reactors Brench 3 (Pre 790625) 78/10/10. 2pp. 94169:263.
- 7810270108 Response to 780927 NRC ltr re benchmarking Enc's PTBBWR/2 code against present data & verifying transient & etability tests. Data to be supplied in Oct 1979 will setiafy requests & certain GE proprietary Info must be provided.
  GUSLEY.O. F Exam Nuclear Co. Inc. (subs. of Exam Corp.) 78710719. 2pg. 94039-300.
- 7810270186 Forwards "Postoperstions Reptwio on the Ecology of Conceings Pond for the Period of 7801-7806". HILLSEY, M. B. Philadelphis Electric Co. 78/10/24. Ip. 94054-073
- --78i027018B "Postoparational Rept#10 on the Ecology of Conceinge Pond for Period Jan-June 1978".

   Philadelphie Electric Co. 78/10/31, 161pp. 94034:074.
- 78ili30335 Bummary of 7809i4 meeting w/05 representatives & Merk 1 Duners Group re-progress of Long Term Prog w/attendance list & agende(RD-9-A-Marki.Standarde ) GRIFEB.C. Plant Systems Branch (Prs 79i030). 78/10/26 67pp.
- 78:1270288 Responds to 78:106 request for info concerning licenese reg performance eval for Region i plants by NRC Providee details.

  GRIER, B. H. Region i, Philadelphia, Office of the Director 78/11/09. 9pp. 94239:230.
- 7812150130 Notice of workehope re implementation of training & qual requirements contained in Append B of 10CFR3.Requests pre-workshop registration of attenders to facilitate sending out meth. W/enc1 Registration Farm & List of Locations. MILLER. J. R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. 3pp.
- 7812180268 Forwarde Rev#1 "Oraft Rediological Effluent Tech Bpecs" for BWR's(NUREG-0473) & "Preparation of Rediological Effluent Tech Spece for Nuc Pwr Plante" (NUREQ-0133). GRIMES, D. M. Assistant Director for Engineers & Projecte (Pre 790623). 78/11/15. 6pp. 94364:324.
- 7812210066 Responds to 781116 telecon forwards copies of ANS masting papers which demonstrate attention to ALARA per ROB. B. D'HARA.J.C. Ebasco Services. Inc. (subs. of Enearch Corp.). 78/11/17. 1p.
- --7812210070 "Experience in Decontamination & Repair of Radwasts Concentrator at Hillstons Unit#1." Describes procedures. SUMMA.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/11/17. 19pp.

- --7812210074 "Peach Bottom 2 & 3 Regenerative Heat Eichangers Chem Contamination & Seal Ring Repairs " Describes work performed in 1977 & 1970 ROWER, M M Philadelphia Electric Co 78/06/06. 22pp.
- --7812210077 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem Decontemination & Solidification " Describes work performed in 1977 CASEY, O. E. Dow Chemical Co. 78/02/14 38pp
- 7811300383 Informs PECO that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations Studies will analyse socioecon impacts which accurred during constr & post-constr periods of each plant. DEVO/NO.R.C Division of Site Befort & Environmental Analysis 78/11/20 2pp 94136-264
- 7812070205 Notice of seminar on 781208 on new Model Radiological Efficient Tech Space for nuc pur plante Requests advance submission of seminar specific questions W/encl Beminar info Sheet-Proposed Agends & maps GRIER'S H. Region 1. Philadelphia. Office of the Director. 78/11/21. Dpp. 94375-152.
- 7812180105 Arends449 t M48 to Lic DPR-44 & DPR-56, respectively, expension of epent fuel pool etorage capacity & related Tech Specs. Forwards supporting SER & EIA GRICES. B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/30. 12pp 94130:255
- --7812180112 Notice of Issuance of Amende#49 & #48 to Facila Operating Lic MDPR-44 & DPR-56 respectively. & Nagative Declaration. IPPDLITO T A. Operating Reactore Branch 3 (Pre 790625) 78/11/30 3pp. 94130-300
- 7812140176 Faruarde Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. 808CN/L.J Ceneral Electric Co. 78/12/04 lipp.
- 7812280035 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracise or enforcement action will result. UAVIG.J.Q. Office of Inspection & Enforcement. Office of the Director. 78/12/06 2pp. 9413:214.
- 7812030013 Requests visus of Regional Directors on Licenses performance evel of subj facils. Forwards questions to be answered by 771209.
  THORNOURS, H. Division of Resettor Construction Inspection. 77/11/23 Rep.
- 7812180160 Forwards Appl for Amend of Fecil Operating Lic in order to temporarily modify subj Facil Tech Basec relating to the Reactor Core leolation Cooling Sys. Forwards \$4,000 appl Filing Fee BRAULEY, E. J. Philadeiphis Electric Co. 78/12/14. 8pp. 94366.021
- 78:12:0367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program BDBCN.L.J. General Electric Co. 78/i1/i3. 3pp.
- Q. Inspection reports, IE Bulistins & correspondence
- 7811090053 Faruerds IE Inepec Rept#50-277/78-23 & #50-278/78-28 on 780823 during which no items of noncompliance were noted. BRUNNERE J. Region i, Philosofthia. Resctor Operations Nuclear Support Branch. 78/09/21. 2pp. 94040:099
- --7811090058 IE Inspec Rept#50-277/78-23 % #50-278/78-28 on 760823 during which no items of noncomplience were noted Major areas inepected included review of Licenese's response to IE Circuler 78-B ato 780531.

  GREEMMAN. E. O., MCCABELE. C. Region i, Philadelphie, Reactor Operatione Nuclear Support Branch. 78/09/18. App. 94040:101.
- 7B10160238 Forwards IE Bulletin#7B-12: "Atypical Held Material in Reactor Pressure Vessel Helds" requesting action w/in 60 days. k liet of 16 Bulletins feeued in 1978.

  (\*\*SANOW7810040253)

  ORIER.S.H. Region 1. Philadelphia. Office of the Director. 78/09/29. 6pp. 94006:353
- 7811010085 Ack receipt of 781002 ltr informing NRC of Steps taken to correct violations noted during inspec #50-277/78-21 & #50-278/78-26.
  #ARTIN.N.O. Region t. Philadelphia. Safeguards Branch. 78/10/10. ip. 94381:297.

0089 Responds to 780918 NRC its re violations noted in Inspec #850-277/78-21 & #50-278/78-26 Corrective actions:mod uter analysie method to calculate incremental Pu-241. RDFF\_8.L. Philadelphia Electric Co 78/10/02 2pp. 1:298.

0093 Forwards IE Inspec ReptsM50-277/78-21 & #50-278/78-26 on 14-16 & Notice of Violetion. IN.H.O. Region 1. Philadelphia. Bafeguarda Branch. 78/09/18.

94381:300.

- 0095 Notice of Violation from inspec on 780814-16. agion i, Philadelphia, Offics of the Director 78/09/14. ip 1:302
- 0099 IE lnepsc Repte#50-277/78-21 &#50-278/78-26 on 780914-16 007Y 12 Inepsc Heptemou-27778-21 &#50-27878-26 on 780914-16 ng which i Item of noncompliance was noted: Amount of oscilve decay of Pu-241 during periode ending 770331.
  30 & 780331 not reported on Form-742-Paragraph 7.
  BETT, P. H. Region 1, Philadelphia, Office of the Director.
  B. E. T., JOYNER, J. H. Region i, Philadelphia, Sefeguards Brench.
  09/14, 10pp. 94381.303.
- 03 Forwarde IE Circular#78-17 (See ANO: 7810230221, Dockat 3.781013.) B.M. Region i, Philadelphia, Office of the Director.
- H3 Forwards licenses performence evaluation for Region 1 No lng reactor in Region 1 considered to have either at or unusual safety concern R.H. Region 1- Philadelphia, Dffice of the Director. 01. 4pp. 00002:259.
- 60 Forwards IE Circular 878-18. "UL Fire Teet. "W/ancl AND: 0002. B.H. Region i. Philadalphia. Office of the Director 06. 1p. 94238-052.
- 21 Responde to 780929 NRC ltr forwarding 1E Bullatin 78-12 ests addl info re reactor vessal weld matl & reactor fabrication. On Elec Co is providing this info which a forwarded to NRC at a later date.

  FF.B.L. Philadelphia Electric Co. 78/11/22. Opp. 94358:335.
- 55 Forwards IE Bullatin#70-12A, suppl to IE Bullatin#78-12. ANO:7811300055. 8 H. Ragion I. Philadelphia. Office of the Director. 24. 1p. 94212:220.
- dic operating reports & related correspondence
- 30 Forwards Thermal & Biologics1 Monitoring Rept#60,covering | 780601 thru 780630.for subj fac11. |Y.W.B. Philadelphia Electric Co. 78/11/09. 1p. 94469:034.
- 0131 Thermal & Bilogical Monitoring ReptW60.covering pariod 01 thru 780630.for aubj facila. hiladelphia Elactric Co. 78/11/09 37pp. 94469:035.
- 09 Forwards Thermal Monitoring Repts W61 % W62. Y.W.B. Philadelphia Electric Co. 78/12/05. 1p. 94246:238.
- 10111 "Thermal & Biological Monitoring Prog for Unit #2 &3." & hly Rept Môl for Jul 1978 Presents delly summery of tamp data: delly generation at PNAPS in thermal megawatte Ny.Conowingo Pond tamps & Impact hours above July 11mit. hliadsiphia Elactric Co. 78707/31. 12pp. 94246:239.
- 0112 "Thermal & Biological Monitoring Prog for Unit 2 & 3." hly Rept Ná2 for August 1978, Presents deily generation BAPS hourly Concuinge Pond & impact hours above August idence limite. hiladelphia Electric Co. 78/08/31, 12pp. 94246:250.
- 064 Monthly Oper Rept for Nov 1978. M.M. Philedelphia Electric Co. 78/12/12. 9pp. 94248:302.
- 84 Forwards Monthly Oper Rept for Oct 1978. 'M.J. Philadelphia Electric Co. 78/11/09. 1p. 94134:273.
- 0086 Monthly Oper Rept for Oct 1978. N.W.H. Philedelphia Electric Co. 78/11/15. 9pp. 94134:274.
- 34 Forwards Sapt Thormal Monitoring Rept#63. YeW. B. Philadelphia Electric Co. 78/12/12. ip. 94366:008.

- --7812180157 "Thermal & Biological Monitoring Prog#63 for Sept 1978."

  Deer w/in applicable thermal criteria w/monthly mean delta temp 1.41F higher than mean of preoper experience.

  « Philadelphia Electric Co. 78/09/30. 11pp 94366:009.
- 7812220063 Forwards Monthly Oper Rept for Nov 1978. COONEY.M.J. Philadelphia Electric Co. 78/12/14. 1p. 94248: 300.
- B. Reportable occurrences. LERs & related correspondence
- 7810100096 LERN78-016/03L-0 on 780904 during surveillance test Unit 3 "D"main steam radiat monitor failed to cause a half scram dus to defactive transistor Transistor was replaced & monitor returned to see in 6 hours. COONEY.M. J. Philadalphia Electric Co. 78/09/26. 1p. 94033: 159.
- 7810130155 Forwarde LER#78-039/03L-0. COONEY.M. J. Philadelphia Electric Co. 78/10/04. 3pp. 94002.356.
- --7810130163 LERN7B-039/03L-0 on 780904: backflow of radioactive liquid from reducate demineralizars to svc air sys discovered on 780904 k 780921. Caused by leaking process vaives & associated chack views due to dirt deposits. CODNEY. M. J. Philadelphia Electric Co. 78/10/04. 1p. 94002: 359.
- 78:1080094 Rept Occurrence#2-78-41/1P, on 78:1010 during routine surveillence test of Unit 2 4KV undervoltage relays, setpoint of bue sequence loading relays E-32 & E-42 were out of calibr.due to engr error.
  ULLRICH.W. T. Philadeiphie Electric Co. 78/10/11. 2pp. 94399:079.
- 7810270261 Forwards LERW78-019/01T-0. COONEY, M. J. Philadelphis Electric Co. 78/10/16. 2pp. 94029; 200.
- --7810270270 LERW78-019/017-0 on 780929: underestimated amount of activity in purge etreem of off-gae sample, resulting in 3 peaks exceeding Tach Basc limits. Purging of off-gas directly to went sys during off-gas process has been stopped.

  CODNEY, M. J. Philadelphia Electric Co. 78/10/16, 1P. 94029; 202.
- 7811140086 Reportable Occurrence#3-78-20/1P on 781019:while Unit 2 was being instead.Unit 3 drywell oxygen concentration exceeded Tech Spec limit by 0.1%. Drywell was depressiving & purged to bring oxygen concentration with limit.

  ULLRICH.H. T. Philadelphie Electric Co. 78/10/19. 2pp. 94425:059.
- 7811280470 Reportable Occurence#3-78-21/1P on 781106: HPCI tripped after delivering erretic flow to reactor vessel following a reactor screm, No cause estermined & investigation continues.
  ULLRICH, W. T. Philadelphia Electric Co. 78/11/07. 2pp. 94376: 361.
- 7811280227 Forwards LERW78-021/017-0. COONEY.H. J. Philadelphia Electric Co. 78/11/20 2pp. 94012: 045.
- --7811280230 LERM78-021/01T-0 on 781106: while at pur facdwater control eye failura resulted in reactor low lavel transient & acrem HPCI initiated but delivered unstable flow & soon tripped on overspaed Causa was HPC1 governor being out of callbr. CODNEY, M. J. Philadelphia Electric Co. 78/11/20. 1p.
- 7812210165 LER#78-022/03L-0 on 781116; during performance of RHR eurveillance test-motor operated valvaMHD-1348 use closed from control room & felled to reopen. B LCPI eye was declared inoper. Causs: looss drive sleave locknut on operator BMB-5. COCNEY, M. J. Philadelphia Electric Co. 78/12/15. 1p. 06911:001.
- 7812290198 LERM7B-023/03L-0 on 781127: "D" Reactor Bidg Aras Ethaust Radlat Monitor indicated downscale & was detarmined to be inoperable. Caused by defective idear diods in emplifier of OE eensor-converter unit-model@1948927011.

  COONEY-M. J. Philadalphia Electric Co. 78/12/20, pp. 94190: 334.
- DOCKET 50-279 BANTA MARIA DE GARONA NUCLEAR POMER PLANT H. General correspondence
- 7811210413 Believes nuc pur cannot be made safe & that constr of subj facil ehould be stopped. STAHL, R.F. Affiliation Unknown. 78/11/13. 1p. 94483:126.

- DOCKET 50-280 SURRY POWER STATION, UNII 1
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7812140180 "NRC draft SER re Burry steam generator repair program for use by ACRS Surry Subcommittee at 781028 meeting "
  SCHLENGER.A Operating Reactors Granch 1 (Pre 790625). 78/10/27.
  4200
- 7812280284 Forwards Safety Eval by NRR dtd 781215 8CH-ENCER.A Operating Reactors Branch 1 (Pre 790629). 78/12/15. 2pp. 44083.053
- --781228029: Safety Evaluation Rept supporting Steam Generator Repeir Prog of euby facil-concluding that health & safety of pub will not be andangered by the proposed steam generator rapair prog \*\* Office of Nuclear Reactor Regulation, Director. 78/12/15 57pp 94083.055
- F Becurity, medical, emergency & fire protection plans
- 7810300022 Forwards "Chapter 10-Special Security Measures During Constr Open" which is to be incorp as part of mod amended security plan for subj fecils Document available in Central Files unly STALLINDS, C M Virginio Electric & Power Co 78/10/25 ip 94031 092
- 7812120137 Forwarde reproductions of articles that eppeared in June & Aug 1978 editions of Nuclear Sacurity Safeguards Newslatter. KENNA, H.B. Region 2. Atlanta, Safeguards Oranch. 78/11/17. App 94276: 329
- M Antitrust correspondence
- 7810310360 Ack receipt of edd1 antitrust info on Old Dominion Elec Cooperetive transmitted by owner of subj facils. PARR. O.D. Light Water Reactore Branch 3 78/10/43. 7pp
- O. Advisory Committee on Reactor Bafaguards reports & correspondence
- 7812040389 Notice of ACRB Bubcommittee on Burry Power Plant 781028 open meeting at 8:30 em to discuss steam generator repair program HOYLE, J. C. Office of the Secretary of the Commission 78/10/10. 2pp. 94382-342
- 7812200296 Forwards 781214 memo containing info on condensar tubs matl requested by ACR8 during 223d ACR8 meeting. CROCKER.L.P. Division of Project Hanagement. 78/12/15 lp 94205: 348.
- --7812200307 Forwards list of condensarimet1 for operating PMR's as requested by ACRS NOONAN, V. 8 Engineering Branch (Pre 791030) 78/12/14. App. 94205: 349
- P Operating license stage documents & correspondence
- 7810230154 Order amending Facil Operating Lics#DPR-32 & DPR-37.Rev 770824 Order for Mod of Lic. STELLO.V. Division of Operating Reactors. 78/06/29 4pp. 94194: 331.
- 7810250232 Supplements 780817 response to 15 OutletinW78-01, "Bergen-Paterson Hydraulic Snubbers". Corrects typographical error. BTALL INGS C. M. Virginia Electric & Power Co 78/08/30. 1p. 94372 223.
- 7810120034 Forwards add1 info in response to 780612 NRC ltr re movement of heavy loads near spent fuel. Includes diagrams illustrating physical reletionship between reactor core, fuel transfer canal-spent fuel storage pool & movement of loads 87ALLINGS.C.M. Virginia Electric & Power Co. 78/10/09. 38pp. 94332:252.
- 7Bi0160139 Responds to NRC ltr of 780913 & states plans to comply with conditions of recently issued Exemption & Order for Mod of Lic for subj facil by Jan 1979. Also plans to submit sufficient analysis plus Tech Spec changes in compliance.

  8TALLINGS.C.M Virginia Electric & Power Co. 7B/10/11. ip.

- 7810160198 Forwards amend to Oper Lic for subj facil's proposed Tech Spec Change No 72 Amend is in response to Schwencer's 780828 ltr requesting dev of Tech Specs to ensure operability of the overpressure protoc sys STALLINGS.C.M. Virginia Electric & Power Co 78/10/12 14pp. 94052, 355.
- 7810250215 Ack receipt of 1tr dtd 780929 stating intention to perfora environ qual test Test prog found acceptable except for acceptance criterian "short term for safety sys initiation following accident "
  SCHENCER: A Operating Reactors Branch 1 (Prs 790625) 78/10/12
  3pp 94370 038
- 7810180119 Forwards "Subj Facil Cycle 5 Startup Physics Test Rept" THOMAS U.N. Virginie Electric & Power Co 78/10/13 ip 94368-388
- --7810180121 "Subj Facil Cycle 3 Startup Physics Test Rept"
  KKN81718.7 J. LEDERSHEIN.J.H. Virginia Electric & Power Co.
  78/09/30 78pp. 94368-212
- 7810270390 Dased on clarification of environ testing on Continental cable contained in 780929 ltr testing prog is now acceptable acceptable acceptable acceptable acceptable acceptable acceptable acceptable acceptable acc
- 7810300331 Ack recispt of 780726 ltr re inspec & maint of outside recirculation spray pumps & low head safety injection pump. Does not agree that candition of pumps efter 30 hours of oper is a sufficient test to assure long term oper EISCHUI, D. O. Assistant Director for Systems Engineering (Pre 7910301, 78/10/19, 3pp 94233 348
- 7810270174 Forwards copies of "Steam Generator Repair Prog" for subj facil Rev contains supplemental info requested by steff. STALLINGS.C.M. Virginia Electric & Power Co 78/10/29 2pp. 94055:288
- --7B10270223 "Bitmam Generator Repair Prog" for subj facil.Rev contains supplementel info requeeted by NRC Staff. " Virginie Electric & Power Co. 78/10/25 9pp. 94056:290.
- 7811060060 Forwards draft eefety eveluation re-steam generator prog-(AND.7812140180). & copy of "Radiological Assessment of Steam Owneretor Removal & Replecement (AND:7812140185) BCH-ENCER, A. Operating Reactors Brench 1 (Pre-790625). 78/10/27. 1p. 94423-328.
- 7811070130 Forwards new sched for submlesion of radiological effluent Tech Specs as requested in 780710 ltr by B D Vescello Delay has been caused by changes in Model Tech Spec & NUREO 0133 BTALLINGS.C.M. Virginia Electric & Power Co. 78/11/03 1p. 94038:335.
- 7811070190 Responds to 781019 1tr on JRS pumps, ORS pumps & LHSI pumps.

  Btales respective pumps will perform settsfactorily under accident conditions & encle design info & inspec & test results.

  BTALL INOS. C. M. Virginie Electric & Power Co 78/11/03 4pp-94036:351.
- 7811170082 Forwards rev page T80.4-7a of Tech Spec amend#44 & 43 transmitted in 780927 ltr. Due to administrative error.an incorrect copy of page was eant.

  BCH-ENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/06 3pp. 02786; 281.
- 7811290132 Forwards Amend#43 & #45 to Facil Oper Lic#DPR-32 & #DPR-37 rev Tach Space requested in 770316 appl w/Environ Impact Appraisal & Notice of Issuance/Negative Declaration. BCHENCER, A Operating Reactors Branch 1 (Pre 790625). 78/11/06 3pp. 94240-001.
- --7811290166 Amend#49 to Fec11 Oper Lic#DPR-32 rev Tech Spec re: deleting biological monitoring prog except for low-intensity fish sampling prog.

  8CHWENCER.A Operating Reactors Brench 1 (Pre 790625). 78/11/06 2pp. 94240:004.
- --7811290168 Amend#45 to Facil Oper Lic#DPR-37 rev Tech Spec to reduce prog for temp.selinity & Impingement monitoring w/Tech Specs encl.

  ECHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/06.

- --7811290172 Environ Impact Appraisal supporting Amand#49 & #45 to Facil Oper Lic#DPR-32 & #DPR-37--concluding that there will be no anviron impact from proposed action \* Operating Reactors Branch 1 (Pre 790625) 78/11/06 10pp 94240 017
- --7811290175 Notice of Issuance of Amend #45 & #45 to Facil Oper Lic #DPR-32 & #DPR-37 & Negative Declaration on 781106 SCHMENCER.A Operating Reactors Branch i (Pre 790625) 78/11/06 3pp 94240 027
- 7811240021 Notifies util of 781205 seminar in Atlanta to discuss hew Model Red Effluent Tech Spece & encl seminar info ehset. registration form & proposed agenda O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/11/09 5pp 74458-162
- 7811140128 Forwards Rev 8 replacement pages to document entitled "Steam Generator Repair Prog. Surry Pur Station Units #1 & #2 "
  STALLINGS C. M. Virginia Electric & Power Co. 78/11/10. Spp. 94425 233.
- 7811300057 Forwards NRC staff paper.Policy Session Item(SECY-78-954) re licenses reg performance evaluation. Three methods for evaluation are.statistical, trend analysis & regional survey method Wout encl D'REILLY, D. Region 2. Atlanta, Office of the Director 78/11/15 2pp. 94071.309.
- 7B12150205 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out mati H/encl Registration Form & List of Locations. MILLER.J. R Assistant Director for Site & Bakeguards (Pre 791030). 78/11/15 Spp.
- 78ii300036 informs VEPC that NRC has contracted w/Mountain Hest Res inc to undertake a series of post-licensing studies of nuc pur stations Betudies will analyze socioecon impacts which occurred during constr & post-constr pariods of each plent. DEYOLNO.R C Division of Bits Befety & Environmental Analysis 78/11/20 2pp. 94070:383.
- 7811280247 Forwards title page of "Steam Generator Repair Prog" for subj facili, which was forwarded on 780817. Page had been inadvertently pmitted.

  87ALL INGS. C. M. Virginia Eisctric & Power Co. 78/11/22 2pp. 94012:164.
- 7811300222 Forwards responses to NRC questions re-permenent solution of low-head sedesty injection & spray pump net positive suction head problems in response to 780131 NRC itr requesting addlined STALLINGS, C. M. Virginia Electric & Power Co. 78/11/22, 34pp. 94070-075.
- 7812150057 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/enci AND-7812080207.

  BCHMENCER: A. Opsrating Reactors Branch i (Pre 790625) 78/11/28. Opp. 49210:099.
- 7812110063 Responds to 780922 Itr requesting comments on Tech Spec changes to Sec4.4 Containment tests. Disapproves proposal that air locks be tested et 4 mo intervels w/o intermediate test should air locks be opened during such interval. STELLO.V. Division of Operating Reactors. 78/11/29. App 94338:179
- 7812200169 Notifies NRC that for 30 min on 781118, condenser cooling water outlet temp decreased by 3 5 degrees F with both units at steady pur. Cooling water through condensers was increased to temp dropped 3.5dsgrees F.No detriment to biote was found. BTALLINGS.C.M. Virginia Electric & Power Co. 78/11/29 ip. 74157: 359.
- 78:1110087 Responds to 780726 request for exemption from 10CFR21.Comm amend to 10CFR21 dtd 78:019 might eliminate need for such examption. W/encl FR notice of amend to 10CFR21. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 78/11/30. 4pp. 94338:305.
- 7812120054 Responds to 781103 ltr providing eddl info re low head safety injection pumps, outside plans for inspec & test & ached for providing addl info.
  EISENHUT.D.O. Assistent Director for Systems Engineering (Pre 791000). 78/12/01. 3pp. 94278:076.

- 7812120059 Ack receipt of 780919 rept VEP-FRD-23, "Reactor Core Thermal Hydraulic Analysis Mode) Using LYNX 1 & LYNX 2 Computer Codes." Requests submitted of references 9 & 12.which are omitted BCHMENCER. A Operating Reactors Branch 1 (Pre 790625) 78/12/04 2pp 94278-096
- 7812180433 Requests registration as user of CNSI-I.L-37-65, CNSI-LL-50-100, CNSI-14-195H, CNSI-IL-28-4, CNSI-4-45, CNSI-AL-33-90. & CNSI-8C-48-220.
  BTALLINGS, C M Virginia Electric & Power Co 78/12/04 lp 94357, 029
- 7812280131 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants info submitted must be substantiated by deta & calculations Licenses must notify NRC of any ineccuracies or enforcement action will result. DAVISI. 0 Office of Inspection & Enforcement, Office of the Director 78/12/06 2pp. 94310 283.
- 7812220006 Forwards repts on subj Facili net positive section head(NPSH) concerns on containment recirculation spray pumps & low head safety (njection pumps Requests an sval by 790101 of the repts re edequacy of available NPSH for subj pumps BUCKLEY, B. C. Plant Systems Branch (Pre 791030) 78/12/11. 2pp. 94248: 283
- 7812150282 Forwards proposed Amend to Oper Lic DPR-32 Proposed change is to sitend oper for edd) hins months from completion of upcoming steam generator inspec tycheck for \$4,000.00 STALLINOS.C M Virginia Electric & Power Co. 78/12/12 2pp 94409-156
- 7812190079 Forwards proposed Tech Spec to replace those submitted 781012. Proposed changes set reactor coolant sys temp limit of 390 degrees below which the sys must be snabled. Less dependence is put on operator surveillance STALLINGS.C.M. Virginia Electric & Power Co. 78/12/14 10pp 94342-337
- 7Bi21900BB Responds to 7Bi201 itr re iou head safety injection pumps & outside & inside recirculation spray pumps Will forward conclusions re extension of intervel between IRS pump tests following inspac BTALLINGS.C.M. Virginia Electric & Power Co. 7B/12/15 2pp 94343:027.
- 7812190090 Forwards proposed changes in form of an amend to Tech Specs of Oper Lics DRR-32 & DRR-37. Request does not involve any unrevisued safety question Check for payment of amend fees enc.).

  8TALLINGS.C.M. Virginia Electric & Power Co 78/12/13. 19pp. 94341:001.
- 7812190148 Forwards results of environ qualitasting on the Continental instrument Ceble in use at subj fectl Cable performance was win ecceptance criterie for both the simulated loss of contant & steam break accident conditions.

  8TALLINGS.C.M. Virginia Electric & Power Co. 70/12/15 ip. 94340-079.
- --7812190149 Environ testing of Instriction was conducted to conform w/requirements established by subjuctif. Cable subjected to thermal aging & rediet exposure prior to test simulating LOCA & MBLB eccident conditions. Cables function as intended. w Virginia Electric & Power Co. 78/11/29. 64pp. 94340:080.
- 7812220032 Forwards suppl rapts on subj facil containment recirculation appear pumps & low head safety injection pumps. Raquests assistance in reviewing & providing a safety sval of mass & energy release data submitted in early Jan 1979.

  87ELLOW, Division of Operating Reactors 78/12/16, 2pp. 94248:360.
- 7812260252 Suppl to 781212 VEPC ltr requesting emend to Oper Lic #DPR-32 Provides clarification of inspec prog. summery of initial inspec results & defines erads of additinates identified to dats. STALLINGS.C.M Virginia Electric & Power Co 78/12/20. App 94139: 351.
- 7812280132 Requests on amond to Oper Lic in form of changes to Tech Brace is Emergency Core Cooling Bys & Loss of Coolant Accident. Forwards check for \$4,400. 8TALLINGS.C.M. Virginia Electric & Power Co. 78/12/26. 35pp. 94310:285

- Q. Inspection reports. IE Bulletins & correspondence
- 7811010414 Ack receipt of 771207 ltr informing NRC of steps teken to correct violations noted during inspec#50-280/77-30 & #50-281/77-30.

  LDNG.F.J Region 2. Atlanta, Office of the Diractor. 77/12/16 lp. 94388:342
- --7811010415 Responds to 771114 NRC ltr re violation noted in Inspec Rept #50-280/77-30 & #50-281/77-30.
  BIALLINGS C.M. Virginia Electric & Power Co. 77/12/07. 1p. 94386.343
- --7811010423 Forwards JE Inspec ReptM50-280/77-30 & M50-281/77-30 on 771004-07 & Notice of Violation Notice of Violation is W/held from disclosure per 100FR2.790 LDNg.F.J. Region 2. Atlanta, Office of the Director. 77/11/14. 2pp. 94388:344.
- --7811010428 IE Inspec Rept#50-280/77-30 & #50-281/77-30 on 771004-07 during which I fee of noncompliance was noted improper security bedging Details whelf from disclosure per 10CFR2 790 ROSERS,R F & WHITENER,H. L. Region 2, Atlanta, Dffice of the Director 77/11/09. Spp.
- 7810250139 Forwards IE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted. LONO,F J Region 2, Atlente, Resctor Operations Nuclear Support Branch 78/09/14. 2pp.
- --7810230140 IE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted. Major areas inspected included; quality assurance records, procurement & follow-up to LER.
  BKDLDB.J.L. Repion 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/709/14. App.
- 7810310048 Forwards IE Inspec Repts #50-280/78-20 & 50-281/78-20 on 780811 during which no items of noncompilance were noted. BUTHERLAND.J.T. Region 2: Atlanta. Fuel Facility & Materiele Safety Branch. 78/09/21. 2pp. 94094:119.
- --7810310034 1E Inspec Repts #50-280/78-20 & #50-281/78-20 on 780811 during which no items of noncompliance were noted. Major areas inspected included: whole body counting practices & procedures: test count on NRC phantom on whole body counter QIBBON, A. F. Region 2. Atlenta, Office of the Director. 78/09/21. 4pp. 94094:121.
- 7810260015 Forwards IE Inspec RepteM50-280/78-23 & M50-281/78-23 on 780905-08 during which no items on noncompliance were noted. Inspec Rept w/held from pub disclosure pursuant to 2,790 KENNA-W.B. Region 2. Atlante. Safeguards Branch. 78/10/13. Epp. 94410:083.
- 7812050258 Forwards 1E Inspec Repts#50-280/78-24 & 50-281/78-24 on 780912-15 during which no items of noncompliance were noted. LONG.F.J. Region P. Atlante. Reactor Operations Nuclear Support Branch. 78/10/23. Pp. 94071:328.
- --7812060262 IE Inspec Repts#50-280/78-24 & #50-281/78-24 on 780912-15 during which no items of noncompliance were noted. Hajor areas inspected incliplant open lic systm repts. seefsty injection sys features & IE Circular followup.

  BURKE, O. J. , 9KOLDS. J. L. , LEWIS, R. C. Region 2, Atlanta, Office of the Director. 78/10/23. 7p. 94371:330.
- 7812110222 Forwards IE Inspec Repts#50-280/78-27 t 50-281/78-27 on 780925-29 during which no items of noncompliance were noted. BUTHERLAND.J.T. Region 2, Atlanta- Fuel Pacility & Materials Sefety Branch. 78/11/02. 2pp. 94338:013.
- ---7812110225 IE Inspec Repta#50-280/78-27 & 50-281/78-27 on 780925-29 during which no itams of noncompliance were noted Major areas inspected incligravious items, reactor coolant chem control, solid radwaste control & gaseous effluents.

  OIBBON.A.F. EMALD.8.C., JACKSON.L.L. Repion 2. Atlenta, Fuel Fecility & Materials Sefaty Branch. 78/i1/02. 13pp. 94338:015.
- 7812080006 Forwards IE Inspec Repts#50-280/78-25 & 50-281/78-25 on 780918-22 during which no items of noncompliance were noted. BUTHERLAND.J. T. Region 2. Atlanta. Fuel Facility & Meteriale Safety Branch. 78/11/03. 2pp. 94109:069.
- --7812080010 IE Insp Repts 50-280/78-25 & #50-281/78-25 on 780918-22.
  No items of noncompliance were noted Major areas inapected:
  rediological environ monitoring program inclingt control &

- 7811130110 Forwards IG Circular 78-18.
  D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/06
  to. 94113 311
- 7811200335 Forwards IE Inspec Repts#50-280/78-26 & #50-281/78-26 on 780724-29 & Notice of Violation which is withheld from public disclosure.
  KENNA-W. B. Region 2. Atlante- Safeguerds Branch. 78/11/07. 2pp. 9449-332
- 7812140151 Forwards IE Inspec Repts#50-280/78-29 & 50-281/78-29 on 781002-06 during which no lives of noncomplience were noted. LONG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/07. 2pp. 94478 350.
- --7812140136 IE Inspec Repts#50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted Mejor areas inspected inci-procedures. LER follow-up & action on previous trapec findings OUZ15. J. E. , KELLO30.P. J. Region 2. Atlanta. Resctor Operations Nuclear Support Branch 78/11/03. 3pp 94478 332
- 7811130237 Ack receipt of 781026 ltr informing NRC of Steps telen to correct violetions noted during inspec#50-280/78-22 & #50-281/78-22. UNO,F.J. Region 2, Atlante, Reactor Operations Nuclear Support Branch. 78/11/08 lp. 03534:318.
- --7811130238 Responds to 781003 NRC ltr re violations noted in inspec Rept#850-280/78-22 & #50-281/78-22 Corrective actions: special requel training course re stertup procedures & theory Emphasis on 880 & 80 retraining STALLINGS, C M. Virginie Electric & Power Co. 78/10/26. 32p.

03554: 319.

- --7811130239 Forwards IE inspec Repts#50-280/78-22 & #50-281/78-22 on 780821-24 & Notice of Violetion LOW-F J. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/03. 2pp 03554:322.
- --7811130240 Notice of Violation from inspec on 780821-24.

  \* Region 2: Atlante: Office of the Director. 78/10/03. lp.
  03584.324.
- --7811130241 IE Inapec RepteM50-280/78-22 & #50-281/78-22 on 780821-24 during which 2 lives of noncompliance were noted: fallure to follow procedures peragraphs & deficiency LER's not submitted to NRC W/In reg time.

  BURKE, D. J., ORADFORD, H. H. 8UZY, J. J. Region 2, Atlanta, Office of the Director. 78/10/03 lipp. 03554:325.
- 7811200127 Ack receipt of 781018 itr informing NRC of steps taken to correct violations noted during Inspect50-280/78-21 No violetions noted during inspect50-281/78-21. LONG.F.J. Region 2, Atlanta. Reactor Operations Nuclear Bupport Branch. 78/11/08. 1p 94220:347.
- --7811200133 Responde to 780927 NRC itr re violation noted in Inspec Rept#30-280/78-21. Corrective actions: procedures mod th Include apacific guidance on High Flux Trip Batpoint Reduction. GTALLINGB, C. M. Virginia Electric & Power Co. 78/10/18. 2pp. 94220:348.
- --7811200140 Forwards IE Inspec Repts#50-280/78-21 & #50-281/78-21 on 780815-18 & Notice of Violation re #50-280/78-21. LONG.F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/09/27. 2pp. 94220-350.
- --7811200210 Notice of Violation from inspec on 780815-18. LCNO.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/27, 1p. 94220:352.
- ~-7811200214 IE Inspec RepteM50-280/78-21.M50-281/78-21 on 780815-18 during which 1 Item of noncompilance was noted: trip syssetting was higher than the limiting sefety eye setting. BERNETI, P.T., MARTIN, R.D., Region 2. Atlanta, Resector Operations Nuclear Support Branch. 78/09/26. 5pp. 94220:353.
- 7812210108 Forwards IE Inspec Repts#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncompliance were noted.
  LONG-F.J. Region 2, Atlanta, Resctor Operations Nuclear Support Branch. 78/11/13. 2pp. 94269:276.
- --7812210113 IE Inspec Repts#50-280/78-30 & 30-281/78-30 on 781010-13 during which no items of noncompliance were noted Major areas inspected inclipiant oper-plant classifiness control. IE

- 78:2290082 Forwards IE Inspec Repts#50-280/78-28 & #50-281/78-28 on TBIO2-06 during which no items of noncompliance were noted to EulifeRLAND. J. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 78/11/17 2pp 94190.089
- --7812290088 [E Inspec Repts#50-280/78-28 & #50-281/78-28 on 781002-06 B12290080 [E Inspec Rapts#50-280/78-28 & #30-281/78-28 on 7810(
  during which no items of noncompliance were noted Major
  areas inspected incl. emergenty facilis equip, procedures, tosts
  6 of 113, environ sys & fire brigade topics
  PERDTI, D. J. HUFHAM, J. W. Region 2, Atlanta, Fuel Facility &
  Materials Safety Branch 78/11/17, 15pp 94190 091.
- 7812010261 Forwards results of staff measurements of radioactivo mati eraciones Forwards results or starr measurements or radioactive hati in an NRC phanton on the whole body counter taken during inspec on 78091! BUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Brench 78/11/20 Spp. 94417-143
- 7812040320 Forwards 1E Bulletin#78-12A. suppl to 1K Bulletin 78-12. D'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 70/11/24 lp. 94121 341
- 7812130381 Responds to IE Bulletin#78-12 re reactor pressure vessel weld metl Will give NRC sched of info availability as soon as arrangements w/vendor are finalized.

  STALLINGS.C.M. Virginia Electric & Power Co 78/11/28 ip. 94292 217
- 7812180332 Ack recipt of 781201 ltr informing NRC of stops taken to correct violations noted during inspect/90-280/78-26 & #90-281/78-26 Region 2. Atlanta, Safeguards Granch 78/12/11 ip. KENNA N D 94356: 062.
- --7812180398 Responds to 781107 NRC its re-violations noted in Inspec Repts#50-280/78-26 & #30-201/78<sub>1</sub>-26 Corrective actions withheld from pub disclosure pureuant to 2 790. BTALLINOS, C. H. Virginie Electric & Power Co 94356, 063,
- 7812290040 Farwards 1E Bulletin 78-14
  D'REILLY, J. P. Region 2. Atlante, Office of the Diroctor 78/12/19
  2pp 94189-336
- R Periodic operating reports & related correspondence
- 7810230184 Forwards Monthly Oper Rept for Sept 1978 BTALLINGS, C.M. Virginia Electric & Power Co. 78/10/13. Ip 94170-193
- --7810230187 Manthly Oper Rept for Bept 1978. STEMART, D. L. Virginia Electric & Power Co. 78/10/13 44pp 94170 194
- 7811170192 Monthly Oper Rept for Oct 1978 BTEWART, D. L. Virginia Electric & Power Co. 78/10/31
- 7811200194 Forwards Monthly Oper Rept for Oct 1978
  STALLINGS, C.M. Virginia Electric & Power Co. 78/11/14. 1p 94253.001
- --7811200198 Monthly Open Ropt for Oct 1970. STEWMARD, D.L. Virginia Electric & Power Co. 78/11/14. 43pp. 94253 002
- 7812200262 Monthly Oper Rept for Nov 1978
  KANE, 0 Virginia Electric & Power Co. 78/12/01. 38pp 74206.242
- 7812200260 Forwards Monthly Oper Rept For Nov 1978 BTALLINOS. C. M. Virginia Electric & Power Co 78/12/12.
- 9. Reportable occurrences. LERs & related correspondence

74205 261

- 7810100074 Forwards LER#78-004/03X-1 STALLINGS, C M. Virginia Electric & Power Co. 78/10/03 94032-241.
- --7810100079 LER#78-004/03x-1 on 780305 less of svc water flow through charging pump intermediate seal cooler was caused by corrosion be stem of discharge gate valves corrosion was galvanic (brass touching bronze); problem will be studied. RAUCOM, T.L. Virginia Electric & Power Co. 78/10/03. 3pp. 94032: 242.

- 7810110127 Forwards LERN78-028/03L-0 BTALLINOS.C M Virginia Electric & Puwer Co 78/10/06 94068 266
- --7810110132 LERH78-028/03L-0 on 780916 snubber not meeting inspec criteria caused by low oil level due to leakage at meting surface between bindy & and plate Holding builts were tightened & snubber was refilled Virginia Electric & Power Co. 78/10/09 2pp BAUCOM, T L. 94068: 267
- 7810200110 Forwards LER878-029/03L-0 STALLINGS.C M Virginia Electric & Power Co 78/10/17 Ip 74164 002
- --7810200110 LER#78-029/03L-0 on 780927 failure of Channel II Pressu oscillator amplifier module of the transmitter Amplifier replaced, tested & Channel II was returned to eve DAUCOM, T L. Virginia Electric & Power Co 78/10/17 2pp 94164 003
- 7811090177 Forwards LER#78-030/03L-0.#78-031/03L-0.#78-032/03L-0. #78-033/03L-0 Virginia Electric & Power Co 70/11/06. 1p STALLINGS, C. M. 94030:184
- --7811090210 LERH78-030/03L-O on 781009 w/unit at rated pur. Charging Component Cooling Water Pump "B"tripped Pump tripped an overcurrent Caused by corrosion damage to motor boarings
  Pump & motor rebuilt & roinstailed

  NAUCOM. T. L. Virginia Electric & Power Co. 761/11/09 2pp 94038, 185
- --7811090213 LERN78-031/03L-0 on 781011 Channol 1 Pressurizer Level (Protec), L-1-439, drifted high Event caused by drift of electronic zero adjustment in conjunction wileakage thru transmitter's bypass/equalizing valve Valve tightomed Virginia Electric & Power Co 70/11/05 2pp. DAUCOM, T L 94038. 107
- --7811090217 LER#78-032/03L-D on 781011 heat tracing circuit Paults occurred as a result of boric acid incursion Faults regained & circuit current verified BAUCOM. T i. Virginia Electric & Power Co 70/11/06. 3pp 94038 189
- --7811070219 LERRYB-033/03L-O on 781015 heat tracing circuit failed Caused by old boric acid buildup & ponotration of heat
- 1 eskage Virginia Electric & Power Co 7H/11/05 2pp DAUCDM, T. L. 94038-192
- 7811170183 Forwards LER#78-034/017-0. STALLINGS, C. M. Virginia Electric & Power Co. 78/11/14 1p 94136 048
- --7811170185 LER#78-034/01T-0 on 781101. during routing inspec on 78 It was noted that 17 spare process plping containment penetrations on Unit I & 23 on Unit 2 were not capped but inside ands seeled in Auxiliary Ridg, due to constructor prop BAUCOM, T.L. Virginia Electric & Powor Co. 70/11/14. Rep. 94136 049
- 7811280236 Forwards LERN78-035/01T-0. STALLINGS, C.M. Virginia Electric & Power Co. 78/11/21 16 94012 156
- --781120023B LERH78-035/01T-0 on 781109 study of colibr techniques that B1 Accumulators indicated level would be lower than actual level Discovered after rigorous review of factors affecting Instru Virginia Electric & Power Co 78/11/20 3pp. BAUCOM, T L
- 94012.157 7812040230 Forwards LERA78-040/03L-0 STALLINGS. C M Virginia Electric & Power Co. 78/11/27

94329: 207

- --7812040233 LERR78-040/03L-O on 781031 periodic test to inspec EDG during a refueling outage had not been completed for EDG's 1 & 3 Caused by admin error Admin guidelines have been rev BAUCOM.T.L. Virginia Electric & Power Co. 78/11/R9. Rpp. 94325-28A
- 7812050208 Forwards LERB78-034/03L-0.#70-037/03L-0 & 878-038/03L-0. 87ALLINGS.C.M. Virginia Electric & Power Co. 78/11/30. p. 94331:209

- --7812050209 LERH78-035/03L-0 on 781107 failure of heet tracing circuit 24D. Unitell due to boric acid damage Heat tracing tope replaced BANCON.T.L. Virginja Electric & Power Go 78/11/27. 2pp. 94331:210
- --7812050211 LERM78-037/03L-0 on 781107 procedure deviation found re Filling & venting Reactor Coolant 8ys on 770103. Procedure deviation was misrouted to records veult w/o review by ENSOC Deviation has now been submitted to SNSOC for review BAJCON, T. L. Virginia Electric & Power Co. 78/11/29. 2pp. 94331:212
- --7812050214 LER#78-038/03L-0 on 781108: quarterly calibr of Nuc Pur Renge Instr not performed due to sched error Reactor pur reduced as required & calibr completed IAN existing procedures. BAUCON.T.L. Virginia Electric & Power Co 78/11/29 2pp. 74331:214.
- 78:2340125 Forwards LERM78-039/03L-0.478-041/03L-0.6 878-042/03L-0. BTAULINGS, C.M. Virginis Electric & Power Co. 78/12/12 ip.
- --7812140126 LERM78-039/03L-0 on 781115 during norrel oper Channel I of Pressurizer Level Instrumentation L1-1-459 drifted low Causs Unknown at this time. Transmitter receibir BAUCON, T. L. Virginia Electric & Power Co 78/12/11 2pp 94127,002
- --7812140129 LER#78-041/03L-0 on 781121, snubber 1-HAPD-HSS-1418 observed wizero fluid level in reservoir Caused by leakage thru faulty reservoir cause.

  BAUCON.T. L. Virginia Electric & Power Co 78/12/11. 2pp. 94127: Q04.
- --78:2140:31 LERH78-042/03L-O on 781:17: during normal pur oper.manual valves 1-80-B-18 420 closed in attempt to stop lesk in svc water line.resulting in termination of Plou thro bloudown radiat manitors Caused by operator error.

  BAUCON.T.L. Virginia Electric & Power Co. 78/12/13. 2pp. 94127:006.
- 7812200204 Forwards LER #78-034/01X-1 BTALLINGS. C.M. Virginia Electric & Power Co. 78/12/13 ip. 94162: 274.
- --7812200207 LER #78-034/01X-1 on 781101/noted that 17 spare process plaing penetrations on Unit #1 & 23 on Unit #2 were not capped in Auxiliary Bldg. Causad by failure to properly complete capping at end of constr.

  B#UCOM,T. L. Virginia Electric & Power Co. 78/12/13 3pp. 94162:279.
- 7812270290 Forwards LER#78-022/03x-1.
  BTALLINGS, C. M. Virginia Electric & Power Co 78/12/20. 1p. 94229: 341.

í

- --7812270294 LERW78-022/03X-1 on 780726: Hydro Test Pump falled to build up pressure during attempt to fill Safety injection Accumulators due to lifeting of its relief velve, Valve replaced & checked, Accumulator refilled.

  BAUCOH.T. L. Virginia Electric & Power Co. 78/12/18. 2pp. 9429-342.
- 7812270320 Forwards LER#78-044/03L-0. BTALLINGS: C M. Virginia Electric & Power Co 78/12/20. lp. 94230:360,
- --7812270324 LER#78-044/03L-O on 781204. during normal full pur oper, loss of flow was detected in charging pump intermediate seel cooler 1-581-E-18. Caused by fallure of cooler Intate gate valve becoming corroded.

  8NUCDM, T. L. Virginia Electric & Power Co 78/12/18. 2pp. 94230-361.
- T. Hearing transcripts on non-antitrust metters
- 78:11:0005: Transcript of 78:028 subcomm meeting in Hashington, DC resubj facil steam generator repair prop k whether ACRS should review the prog.
  CARBON, M. MOELLER, D., ETHERINGTON, H. ACRS Advisory Committee on Reactor Bafeguards. 78/10/28. 191pp. 94:175:245.

- DOCKET 50-201 SURRY POWER STATION, UNIT 2
- E. NRC Bafety Evaluation Report (BER1, supple & correspondence
- 7812140180 "NRC draft SER re Surry ethan generator repair programuse by ACRS Surry Subcommittee at 781028 meeting."

  8CHENCER: A Operating Reactors Brench i (Pre 790625) 78/10/1
- 7812280284 Forwards SePety Eval by NRR dtd 781215 SCHLENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/12/. 2pp 94083:053.
- --781228029: Bafety Evaluation Rept supporting Steam Generator Re Prog of subj facil, concluding that health & safety of pub will not be endangered by the proposed steam generator rapeir prog. • Office of Nuclear Reactor Regulation, Director 78/12/15 59p. 94083:055.
- F. Security, medical, emergency & fire protection plans
- 7812120157 Forwards reproductions of articles that appeared in Jul Aug 1978 editions of Nuclear Security Safeguards Newsletter KENNA-H B. Region 2. Atlanta, Bafeguards Branch. 78/11/17. 4; 94276-329.
- 7810300022 Forwards "Chapter 10-Special Security Measures During of Open" which is to be incorp as part of mod amended security plan for subj facils Document available in Central Files only STALLINOS, C.M. Virginia Electric & Power Co. 78/10/25. 1p. 94031.032
- Q. Adjudicatory correspondence
- 7810110043 Amend 44 to Facil Oper Lit OPR-37 revising Tech Spets changing date of next inspec of steam generator tubes. BTELLO.V. Division of Operating Reactors. 78/10/03. 3pp. 74062: 186.
- M. Antitrust correspondence
- 7810310360 Ack receipt of add1 antitrust info on Old Dominion Ele Cooperative transmitted by owner of subj facils. PARR.O.D. Light Water Reactors Branch 3. 78/10/23. 7pp.
- D. Advisory Committee on Reactor Safeguards reports & corresponde
- 7812060389 Notice of ACRS Subcommittee on Surry Power Plant 78102 open meeting at 8:30 am to discuse steam generator repair program HOYLE, J. C. Office of the Secretary of the Commission 78/10/1 2pp. 94382:342.
- 7812200296 Forwards 781214 memo containing info on condensar tube requested by ACR8 during 223d ACRS meeting. CROCKER-L. P. Division of Project Management. 78/12/15. 1p. 94205:348.
- --7812200307 Forwards list of condenser math for operating PWR's requested by ACRS. NCONAN, V. 8 Engineering Stanch (Pre 791030). 78/12/14. 4pp 94205:349
- P. Operating license stage documents & correspondence
- 78:1170082 Forwards rev page T89,4-7a of Tech Spec amend#44 & 43 transmitted in 780927 itr. Due to administrative error an incorract copy of page was sent.
  8CHWENCER, A. Operating Reactors Branch 1 iPre 790525). 78/11/3pp. 02756:281.
- 7812110063 Responds to 780922 ltr requesting comments on Tech Spechanges to Sec4.4 Containment tests. Disapproves proposal that sir locks be tasted at 4 mo intervals w/o intermediate test should air locks be opened during such interval. SIELLO.V. Division of Operating Resctors. 78/11/29. 4pp. 94336:179.
- 7B121100E7 Responds to 7B0726 request for exemption from 10CFR21.
  amend to 10CFR21 dtd 7B1019 might eliminate need for such
  exemption. W/enc1 FR notice of amend to 10CFR21.
  DENTON.H.R. Diffice of Nuclear Reactor Regulation. Director.
  78/11/30. 4pp. 94338:305.

**ういいいきょきひ ローロバック** 

- 7812120054 Responds to 781103 ltr providing addi info re low head select injection pumps outside plans for inspec & test & sched for providing addi info.
  EIECHUT.D.Q. Assistant Director for Systems Engineering (Pre 791030) 78/12/01. 3pp 94278:076
- 7812120059 Ack receipt of 780919 rept VEP-FRD-23, "Reactor Core Thernai Hydraulic Analysis Model Using LYNX i & LYNX 2 Computer Codes." Requests submittal of references 9 & 12.which are omitted.

Operating Reactors Bronch i (Pre 790525) 78/12/04 BCHLENCER. A. 2pp. 94278.096

- 7810230154 Order amending Facil Operating LicamDPR-32 & DPR-37 Rev 770824 Order for Mod of Lic. STELLO.V. Division of Operating Reactors. 78/05/89 4pp 94194:351
- 7810250222 Supplements 780817 response to 18 Bulletin#78-01, "Gergen-Paterson Hydraulic Snubbers". Corrects typographical error STALLINGS, C.M. Virginia Electric & Power Co. 76/08/30. 1p.
- 94372: 223
- 78:01:004i Forwards Amend 44 to License DPR-37. safety evaluation & notice of issuence & availability. BCHNENCER.A. Operating Reactors Branch i (Pre 790625) 70/10/03 2pp. 94063:184
- --7810110044 Notice of Issuance of Amend#44 to Facil Oper Lic#OPR-37 80HHENCER,A. Operating Reactors Branch 1 (Pre 790625) 78/10/0 3pp. 94063:189.
- --7810110048 Bafety evaluation supporting Amend 44 to License DPR-37. Plent may be operated for another six months & then shut down so steam generators can be reprobed to assess extent of tube denting.

  a Dffice of Nuclear Reactor Regulation. Director 78/10/03 5pp 94063:192.
- 7810160139 Responds to NRC ltr of 780913 & states plans to comply with conditions of recently lessed Exemption & Order for Mod of Lic for subj facil by Jan 1979. Also plans to submit sufficient analysis plus Tech Spac changes in compilance STALLINGS.C.M. Virginia Electric & Power Co. 78/10/11. ip.
- 7810160198 Forwards amend to Oper Lic for subj facil's proposed Tech Spec Change No. 72 Amend is in response to Schwencer's 780828 itr requesting deviof Tech Spocs to ensure operability of the overpressure protectsys.

  BTALLINGS, C.M. Virginia Electric & Powor Co. 78/10/12. 14pp. 94052: 355.

94005: 311.

- 7810250215 Ack receipt of 1tr dtd 780929 stating intention to porform environ qual test. Test prog found acceptable except for acceptance criterion "short term for safety sys initiation following accident."
- BCHMENCER, A. Operating Reactors Branch i (Pre 790625). 78/10/12. 3pp. 94370:038.
- 7810180119 Forwards "Subj Fac11 Cycle 5 Startup Physics Test Rept". THOMS.M.N. Virginia Cloctric & Power Co. 78/10/13. lp. 94368: 35B.
- --7810180121 "Bubj Facil Cycle 5 Startup Physics Tost Rept". KUNSIT18, T. J., LEBERBTEIN, J. H. Virginia Electric & Power Co 78/09/30. 78pp. 94368:212.
- 7810270380 Based on clarification of environ testing on Continental cable contained in 780929 itr testing prog is now SCHLENCER, A. Operating Reactors Branch i (Pre 790625). 78/10/18. 2pp. 94030: 162.
- 7810300331 Ack reciept of 780726 ltr re inspec & maint of outside Does not egree that condition of pumps after 30 hours of oper is a sufficient test to assure long term oper. Elemmur. D. Q. Assistent Director for Systems Engineering (Pre 791030). 78/10/19. 3pp. 44253:348.
- 7810270174 Forwards copies of "Bteam Generator Repair Prog" for subjectil Rev contains supplemental info requested by staff.
  BTALLINGS. C. M. Virginia Electric & Power Co. 78/10/25. 2pp. 94056: 288.
- --7810270223 "Btsam Generator Repair Prog" for subj facil. Rev contains aupplemental info requested by NRC Btaff.
  \* Virginia Eisctric & Pawer Co. 78/10/25. 9pp. 94056:290.

- 781:10:00:00 Forwards draft safety evaluation re steam generator prog (ANO 78:21:40:00). & copy of "Radiological Assessment of Steam Generator Removal & Replacement (ANO 7812140165) BCHIENCER, A Operating Reactors Branch i (Pre 290525). 79/10/27 1p. 94423.328
- 78i1070130 Forwards new sched for submission of radiological effluent Tech Space as requested in 780710 itr by 8 D Vascalio Delay has been caused by changes in Model Tech Space & NUREO 0133 BTALLINGS.C.M Virginia Electric & Power Co. 78/11/03. 1p. 94039: 355
- 7811070190 Responds to 781019 itr on 188 pumps, ORS pumps & LHSI pumps. States respective pumps will perform satisfactorily under accident conditions & encle design info & inspec & test results. STALLINGS C M Virginia Eisetric & Power Co. 78/11/03. App. 94036: 351.
- 78:1290152 Forwards Amend#45 & #45 to Facil Oper LicHDPR-32 & #DPR-37 rev Tech Specs requested in 770516 appl w/Environ Impact Appreisal & Notice of lasuance/Negative Declaration Operating Reactors Branch 1 (Pre 790625) 78/11/06. 3pp 94240.001
- --7811290166 Amend#45 to Facil Oper LicWDPR-32 ray Tech Barc re deleting biological monitoring progressor for low-intensity fish eampling prog.

  BCHMENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/06. BCHHENCER, A. Op 2pp. 94240:004.
- --7811290168 Amend#45 to Fac11 Oper L1c#DPR-37 rev Tech Spec to reduce prog for temp. salinity & impingement monitoring w/Tech Specs
- BOHWENCER. A Operating Reactors Branch | (Pre 790625) 78/11/06 2pp. 94240:006 --7811290172 Environ Impact Appraisal supporting Amend#45 & #45 to Fact:
  Open LiceDPR-32 & #DPR-37--concluding that there will be no

environ inpact from proposed action.

Operating Reacture Branch i (Pre 790625), 78/11/06, 10pp.

--7811290175 Notice of Issuence of Amend #45 & #45 to Facil Oper Lic WDPR-32 & WDPR-37 & Negative Declaration on 781106 Operating Reactors Branch i (Pre 790625) 78/11/06 SCHENCER. A.

94240: 017.

- 3pp. 94240 027. 78:1240021 Not1919s util of 78:205 seminer in Atlante to discuss new
- Model Rad Effluent Tech Specs benchmar in Atlante to discuss new Model Rad Effluent Tech Specs bench seminar info sheet, registration formak proposed agenda. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 78/11/09, 3pp. 94438.162.
- 78:1140128 Forwards Rev 8 replecement pages to document entitled "Steam Generator Repair Prog. Surry Pur Station. Units #1 & #2."
  87ALLINOS. C.M. Virginis Electric & Power Co 78/11/10. Spp. 94425: 233.
- 7811300057 Forwards NRC staff paper.Policy Bession Item(SECY-78-554) rs licenses rag performance evaluation. Three methods for evaluation are: statistical, trend analysis & regional survey method. W/out anci.
  G'REILLY, J. P. Region 2, Atlanta, Office of the Director 78/11/15. 2pp. 94071:309.
- 7812130205 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attenders to facilitate sending out meth. W/encl Registration Form & List of Locations MILLER.J.R. Assistant Director for Site & Bafeguards (Pre 791030). 78/11/15. Spp.
- 7812180288 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's (NNREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133). ORIMS-B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/13. Opp. 94365:136.
- 78ii]00036 Informs VEPC that NRC has contracted w/Mountain West Res Inc to undertake a series of past-licensing studies of hut pur stations. Studies will analyze socioecon impacts which accurred during constr & post-constr periods of each plant. DEYOUNG.R. C. Division of Sits Safety & Environmental Analysis. 78/11/20. 2pp. 94070:353.
- 7811280247 Forwards title page of "Steam Generator Repair Prog" for subjecti, which was forwarded on 780Bi7. Page had been inadvertantly emitted.

  BTALLINGS.C.M. Virginia Electric & Power Co. 78/11/22. 2pp.

- 7811300222 Forwards responses to NRC questions re permanent solution of low head safety imjection & spray pump net positive suction head problems in response to 780131 NRC itr requesting additing STALLINGS, C. M. Virginia Electric & Power Co. 78/11/22 34pp 94070.075
- 7812150059 Discusses possible dangers of LOCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing Wiencl ANO 7812080207
  BCHMENCER: A Operating Reactors Branch 1 (Pre 790625) 78/11/28. bpp 94210 099
- 7812200169 Notifies NRC that for 30 min on 781118 condenser cooling water dutiet term decreased by 3.5 degress F with both units et stady pur Cooling water through condensers was increased a temp dropped 3.5 degrees F No detriment to blota was found STALL NOS. C.M. Virginia Electric & Power Co. 78/11/29 1p. 94157-359.
- 7812180433 Requests registration as user of CNSI-LL-57-65. CNSI-LL-50-100. CNSI-14-195%, CNSI-LL-58-4. CNSI-4-45, CNSI-AL-33-90. & CNSI-6L-48-220 STALL INGS. C M Virginia Electric & Pousr Co. 78/12/04 19 94-337-009
- 7812280131 Emphasizes importance of submitting accurate & complate info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J Q Office of inspection & Enforcement. Office of the Director 78/12/06 Zpp. 94310.283
- 7812220006 Forwards repts on subj Facil net positive section head(NPSH) concerns on containment recirculation spray pumps & low head safety injection pumps Requests an eval by 790;01 of the repts re adequacy of available NPSH for subj pumps BUCKLEY. B C Plant Systems Branch (Pre 791030) 78/12/11. 2pp. 94248: 283
- 7812190079 Forwards proposed Tech Spec to rsplace those submitted 781012 Proposed Changes set reactor coolant sys temp limit of 330 degrees below which the sys must be enabled. Less dependance is put on operator surveillance BTALL INCS, C.M. Virginia Electric & Power Co. 78/12/14. 10pp. 94342-357.
- 781219008B Responds to 781201 ltr re low head safety injection pumps & outside & inside recirculation spray pumps Will forward conclusions re extension of Interval between IRB pump tests following inspec.

  STALLINOS. C. M. Virginia Electric & Power Co. 78/12/15 2pp 94342:077
- 7812190090 Forwards proposed changes in form of an amend to Tsch Specs of Oper Lics DPR-32 & CPR-37 Request does not involve any unreviewed safety question. Check for payment of amend fees encl
  8TALLINGS. C.M. Virginia Electric & Power Co 78/12/13. 19pp.
  94341.001
- 7812190148 Forwards results of environ qual testing on the Continental Instrument Cable in use at subj facil Cable performance was win acceptance criteria for both the almulated loss of coolant & steam break accident conditions
  STALLINGS. C. M. Virginia Electric & Power Co. 78/12/15. jp. 94340, 079
- --7812190149 Environ testing of instrictable was conducted to conform whrequirements established by subjustif. Cable subjected to thermal aging & radiat exposure prior to test simulating LOCA & MSLB accident conditions. Cables function as intended.
  Virginia Electric & Power Co. 78/11/29, 64pp. 94340:080.
- 7812220032 Forwards suppl repts on subj facil containment recirculation spray pumps & low head safety injection pumps. Requests assistance in reviewing & providing a safety sval of mass & energy release data submitted in early Jan 1979.
  BTELLO.V. Division of Operating Reactors. 78/12/16. 2pp. 94248.360
- 7812290132 Requests an amend to Oper Lic in form of changes to Tech Specs re Emergency Core Cooling Bys & Loss of Coolant Accident Forwards check for \$4,400. STALLINGS.C.M. Virginia Electric & Power Co. 78/12/2b. 35pp. 94310:235.

- O inspection reports. IE Bulletine & correspondence
- 7812010261 Forwards results of staff measurements of radioactive eati in an NRC phantom on the whole body counter taken during inspec on 780911
  8UTHERLAND, J. T. Region 2. Atlante, Fuel Facility & Materials Safety Branch. 78/11/20 Spp. 94417-143
- 7812080010 IE insp Repts 50-280/78-25 & #50-201/78-25 on 780918-22 No items of noncompliance were noted Major areas inspected rediological source monitoring program inclingt control & implementation of nonitoring programs PERRY.H.M., MACARTHUR,T C. HUFHAM.J H. Region 2. Atlanta, Fuel Ferlitty & Materials Safety Branch. 78/11/03 4pp. 74109.071
- 7812:10222 Forwards IE Inspat Repts#50-200/78-27 & 50-281/78-27 on 780925-29 during which no itsms of noncompliance were noted BUTHERLAND, J. T. Region 2. Atlante, Fuel Facility & Materials Safety Brench. 78/11/02. 2pp. 94338-013
- --7812110225 IE Inspec Repts#50-280/78-27 & 50-281/78-27 on 780925-29 during which no items of noncompliance were noted Major areas inspected incliprevious litems reactor coolant chem control solid radwaste control & gaseous efficients
  QIBSON.A.F., EMALD.S.C., JACKSON.L.L. Region 2, Atlanta, Fuel Facility & Meteriels Safety Branch. 78/11/02 13pp. 94338 015
- 7812140156 IE Inspec Repts#50-280/76-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted Major areas inspected incl. procedures. LER follow-up & action on previous inspec findings.

  OUZTB.J E., KELLOGO.P.J Region 2. Atlante. Reactor Operations, Nuclear Support Branch. 78/11/03. Spp. 94478-352
- 7812290040 Farwards IE Bulletin 78-14 O'REILLY, J. P. Region 2- Atlante, Office of the Director. 78/12/19 2pp 94189.336
- 7811010414 Ack receipt of 771207 1tr informing NRC of steps taken to correct violations noted during inspec#30-280/77-30 & #30-281/77-30.

  LCND.F.J. Region 2. Atlanta. DPPica of the Director 77/12/16 19 94:581-342
- --7811010415 Responds to 771114 NRC ltr re violation nated in Inspec Rept #50-280/77-30 & #50-281/77-30. BTALLINOS.C.M. Virginia Electric & Power Co. 77/12/07. ip 94388-343.
- --7811010423 Forwards 1E Inspsc Rept#50-280/77-30 & #50-201/77-30 on 771004-07 & Notice of Violation Notice of Violation is wheld from disclosure par 10CFR2.790 LONG-F. J. Region 2, Atlanta, Office of the Director. 77/11/14 2pp. 94388:344.
- --7811010428 IE Inagec Rept#50-280/77-30 b #50-281/77-30 on 771004-07 during which i item of nuncompliance was noted: Improper security badging. Details w/held from disclosure per 100FR2 790 RDERB.R.F., WHITENER.H.L. Region 2, Atlanta, Office of the Director, 77/11/09. Spp.
- 7810200139 Forwards IE Inspec Repts#50-280/78-19 & #50-281/78-19 cn 780802-04 during which no items of noncompliance were noted. LONO.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/14. 2pp.
- --- 7810250140 JE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted Major areas inspected included; quality assurance records, procurement & follow-up to LER.

  SKOLD8.J.L. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. dpp.
- 7810310048 Forwards IE Inspec Repts #30-280/78-20 & 50-281/78-20 on 780811 during which no items of noncompliance were noted. SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/09/21. 2pp. 94094:119.
- --7810310054 IE Inspec Repts #50-280/78-20 & #50-281/78-20 on 780811 during which no items of noncompliance were noted. Major erse inspected included; whole bady counting practices & procedures; test count on NRC phantom on whole bady counter. 01880N.A.F. Region 2, Atlanta, Office of the Director. 78/09/21. App. 74074:121.
- 7810260015 Forwards IE Inspec Repts#50-280/78-23 & #50-281/78-23 on 780905-08 during which no items on noncompliance were noted. Inspec Rept w/held from pub disclosure pursuant to 2,790. KENNA-M.B. Region 2, Atlante, Bafaguards Branch. 78/10/13. 3pp. 94410:003.

- 7812050258 Forwards IE Inspec Repts#50-280/78-24 & 50-281/78-24 on 780912-15 during which no items of noncompliance were noted. LONG, F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/23. 2pp. 94371:328
- --7812060262 IE Inspec Repte#30-280/78-24 & #50-281/78-24 on 780912-15 during which no items of noncampliance ware noted Major areas inspected inclipiant open-lic avent repts.safety injection sys features & IE Circuiar followup BURKE.D. J. BKOLDB. J. LEWIS.R.C. Region 2. Atlanta. Office of the Director. 78/10/23 7pp. 94371-330
- 7812080006 Forwards IE Inspec Repts#50-280/78-25 & 50-281/78-25 on 780918-22 during which no items of noncompliance were noted. 8UTHERLAND.J.T. Region C. Atiants. Fuel Facility & Materials Safety Branch. 78/11/02 2pp. 94109 069.
- 7811150110 Forwards IE Circular 78-18.

  O'REILLY J.P. Region 2. Atlenta. Office of the Director 78/11/06
  10.
- 7811200335 Forwards 1E Inspec Repts#30-280/78-26 & #50-281/78-26 on 780924-29 & Notice of Violation which is withheld from public disclosure.
  KENNAM, B. Region 2, Atlanta, Bafaguarde Branch. 78/11/07. 2pp. 94419:332.
- 7812140151 Forwards IE Inepac Rapta#50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted LDNG-F.J. Region 2. Atlanta. Raactor Operations Nuclear Bupport Branch. 78/11/07. 2pp. 94478:350.
- 7811130207 Ack receipt of 781026 itr informing NRC of Steps taken to correct violations noted during inepec#50-280/78-22 & #50-281/78-22. LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/08. 1p. 03534:318.
- --7811130238 Responds to 781003 NRC ltr re violations noted in Inspac Repts#30-280778-22 & #50-281778-22 Corrective actions: special requel training course are startup proceduras & theory. Emphasis on SRO & RO retraining. BTALLINOS.C.M. Virginia Electric & Power Co. 78/10/26. 3pp. 03548-319.
- --7811130239 Forwards Id Inspec RaptsW50~280/78-22 & W50-281/78-22 on 780821-24 & Notice of Violation. LONG.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/03. 2pp. 03554:322
- --7811130240 Notice of Violation from Inepec on 780821-24.

   Region 2- Atlanta- Office of the Director. 78/10/03. 1p. 03534-324.
- --7811130241 IE Inspec Repts#50-280/78-22 & #50-281/78-22 on 780821-24 during which 2 itams of noncompliance were noted:failure to follow procedures paragraphs & deficiency LER's not submitted to NRC w/in req time.

  BURKE, D. J., BRADFORD, H. H., BUZY, J. J. Region 2, Atlanta, Office of the Director. 78/10/03. 11pp. 03554:325.
- 7811200127 Ack receipt of 781018 ltr informing NRC of steps taken to correct violations noted during Inspect#30-280/78-21. No violations noted during inspec#50-281/78-21. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/08. 1p. 94220:347.
- --7811200133 Responds to 780727 NRC itr re violation noted in Inspec Rapt#80--280778-21. Corractive actions: procedures mod to include specific guidence on High Flux Trip Satpoint Reduction. BTALLINOS.C.M. Virginia Electric & Power Co. 78/10/18. 2pp. 74220: 348.
- --7811200140 Forwards IE Inspec Repts#50-280/78-21 & #50-281/78-21 on 780815-18 & Notice of Violation re #50-280/78-21. LUNG.F.J. Region 2, Atlants, Reactor Operations Nuclear Support Brench, 78/09/27, 2pp. 94220;350.
- --7811200210 Notice of Violation from inepac on 780815-18. LONG,F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/09/27, Ip. 94220:352.
- --7811200214 IE Inspec ReptsH50-280/78-21.H50-281/78-21 on 780815-18 during which i item of noncompliance was noted trip syssetting was higher than the limiting safety syssetting. BURNETT.P.T., MARTIN.R.D. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/09/26. 5pp. 94220:353.

- 7812210108 Forwards 1E Inspec Repts#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncompliance were noted.
  LNO.F J. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 76/11/13 2pp. 94269.276
- --7812210113 IE Inspec Rapte#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncampliance were noted Major areas inspected incl. plant oper. plant clashilness control. IE Butistine & Circulare & Followup on LER's EURKE, D. J. LEWIS, R. C. Region 2, Atlanta, Office of the Director. 70/11/13 bp. 94269:270
- 7812290082 Forwards IE Inspec Repts#50-280/78-28 & #50-281/78-28 on 781002-04 during which no items of noncompliance were noted. SUTHERLAND.J T Region 2. Atlants. Fuel Facility & Materials SePaty Branch. 78/11/17 2pp. 94190 089
- 7812040320 Forwards IE Bullstin#78-12A.suppl to IE Bullstin 78-12. H/encl AND 7811300055 O'REILLY,J. P. Region 2, Atlanta, Office of the Director. 78/11/24. 1p. 94121:341
- 7812130381 Responds to IE Bulletin#78-12 re reactor praesure vessel weld meth. Will give NRC eched of info aveilability as soon as errangements wivendor are finalized.
  BTALLINGS.C.M. Virginia Electric & Power Co 78/11/28, ip. 94272:217.
- 7812180352 Act recipt of 781201 itr informing NRC of staps taken to correct violations noted during inspec#50-280/78-26 t #50-281/78-26 KENNA, M.B. Region 2. Atlanta. Safeguards Branch. 78/12/11. 1p. 94356:062.
- --7812180358 Rasponds to 781107 NRC itr re-violations noted in Inspec Repts#50-280778-26 & #50-281778]-26 Corrective actions withheld from pub disclosura pursuant to 2.790. STALLINGB.C.H Virginia Electric & Power Co. 78/11/28. 1p. 94336:043
- R. Periodic operating raports & related correspondence
- 7811170192 Monthly Open Rept for Oct 1978. STEWART, D. L. Virginia Electric & Power Co. 78/10/31. 43pp.
- 7810230184 Forwards Monthly Open Rept for Sept 1978. 81ALLINOS.C.M. Virginia Electric & Power Co. 78/10/13 ip. 94170:193.
- --7810230187 Monthly Oper Rept for Sapt 1978. BIEHART.D L. Virginia Electric & Power Co. 78/10/13 44pp. 94170:194
- 7811200174 Forwards Monthly Oper Rept for Oct 1978. BTALLINGS.C.M. Virginia Electric & Power Co. 78/11/14. 1p. 74251:001.
- --7811200198 Monthly Oper Rept for Dct 1978.
  SIEWHARD.D.L. Virginia Electric & Power Co. 78/11/14. 43pp. 94252:002
- 7812200262 Manthly Oper Rept for Nov 1978

  KANE.Q. Virginie Electric & Power Co. 78/12/01. 38pp. 94206:262.
- 7812200260 Forwards Monthly Open Rept for Nov 1978. STALLINGS.C.M. Virginia Electric & Power Co. 78/12/12. 1p.
- S. Reportable occurrences. LERe & related correspondence
- 78i1170183 Forwards LER478-034/01T-0. BTALLINGS.C.M. Virginia Electric & Power Co. 78/11/14. 1p. 94136:048.
- --7811170185 LERW78-034/01T-0 on 781101: during routine inspec on 78102 it was noted that 17 spare process piping containment penetretions on Unit it & 23 on Unit 2 were not capped, but inside ends seeled in Auxiliary Bldg, due to constructor. BAUCOM.T.L. Virginia Electric & Power Co. 78/11/14. 2pp. 94134-049
- 7810100057 Forwards LER#78-011/03X-1. 87ALLINGS.C.M. Virginia Electric & Power Co. 78/10/03. ip. 74033: 094.

- --7810100065 LERMY8-011/03x-1 on 780305 During normal full pur approthers
  was no syc water flow thru charging puop intermediate seal
  coolor 2-SM-E-18, due to failure of the cooler's discharge
  gate value
  \* Virginia Electric & Power Co 78/10/03 Jpp 94033 095
- 7610230257 Forwards LER#78-032/03L-0 STALLINGS C M. Virginia Electric & Power Co 78/10/12 ip 94181.351
- --7810230262 LERM78-032/03\_-O on 78092) heat tracing circuit ranual boration/boric acid-to-blender failed Failure caused by boric acid penetration of the heat tracing tape circuits Heat tracing tape replaced BAUCOM.T L Virginia Electric & Power Co 78/10/12 3pp. 94181 332
- 7810200109 Forwards LERM78-033/03L-0 BIALLINGS C M. Virginie Electric & Power Co 78/10/17. 1p 94401 217
- --7810200112 LERN78-033/03L-O on 780926 Circulating water outlet valve MDV-CM-200D failed to close when operated elec Actuator cam for "shut"targue switch became wedged against a torgue switch Buitch mod by hold down screw locking hardware BAUCOM.7 L. Virginia Electric & Power Co. 78/10/17 2pp. 74401 218.
- 7811060211 Forwards LER#78-034/03L-0 & #78-035/03L-0 8FALL1NOS. C M Virginia Electric & Power Co 78/11/01. ip. 944889 229
- --7811060213 LERe78-034/03L-0 on 781006 w/unit at cold shutdown enubbers 2-RH-HIBB-20 & 2-RH-PD-HIBB-9 found inoper due to jou fluid level. Defective snubbers were dry bocause of leaking rad easts. Leak due to mech damage to seal. Shubbers replaced BAUCON. T L. Virginie Electric & Power Co. 78/10/31 2pp. 74489-230
- --781:0602:7 LER#78-033/03L-0 on 78:007: during cold shutdoum valve pit was flooded while draining circulating water bo: D Motor oper valve damaged by flood & could not accept vol of water being pumped from water bo: D.
  RAUCOM, 1 ... Virginia Electric & Power Co. 78/10/31 2pp 94489-232
- 7811090236 Forwards LER#78-036/03L-0 BTALLINGS, C M Virginia Electric & Power Co. 78/11/06 ip. 94042:083
- --7811070240 LERB78-036/03L-0 on 781015 compensatory surveiliance on RCP "cratator & hearing temp had not bean performed Caused by feilure of operating personnel to restore process computer trend block foilowing computer reinitialization.
  BAUCOM.I.L. Virginia Electric & Power Co. 78/11/03. 2pp. 94042:084
- 7811210259 Forwards LER#78-037/03L-0. 8TALLINGS.C M. Virginia Electric & Power Co. 78/11/14. lp.
- --7811210266 LERNTB-007/03L-0 on 781022 with unit at rated pur, panel indicator for Radist Monitor RM-213 monitoring "A" steam generator bluedown read "O". Caused by loose connector joining detector cable to electronic chassis
  BAUCON.T.L. Virginia Electric & Power Cd. 78/11/14. 1p
  03557:020.
- 7811280286 Forwards LERB78-038/03L-0 8FALLINGS C. M Virginie Electric & Power Co. 78/11/20 1p.
- --78112B0292 LERW7B-D3B/OOL-D on 781030.boric acid flow from boric acid teaks to blender was interrupted due to crystallized boron blockege at albow in line 1"-CH-335-132 Obstruction was removed & pipe flow returned to normal.

  BAUCDH.T t. Virginia Electric & Power Co. 78/11/17. 2pp. 94393:242.
- 7812140224 Forwards LER878-039/03L-0 & \$78-040/03L-0 STALLINOS.C.M Virginia Electric & Power Co. 78/12/12 1p. 94204:341.
- --7812140229 LER#78-039/03L-O on 781115 during normal oper-it was noted that "b" loop hot leg temp sensing element TI-2-422A was drifting low. Caused by packing leak which reduced resistance of the sunsing element.

  BAUCON-T. L. Virginia Electric & Power Co. 78/12/11. 2pp. 94204:342.

- --TEIZI 40234 LERM TO 400/QJL-U on /BILLS, Fourthe testing revealed failure of heat tracing circuit 4C Umit#2 Boron Injection Tank Top recirculation return Caused by boric acid damage to the heat tracing circuit BAUCON, T L. Virginia Electric & Power Co 7B/12/I1 2pp 94204:343
- 7012200204 Forwards LER #78-034/01X-1 BTALLINOS. C M Virginia Electric & Power Co. 78/12/13. ip 94162 274
- --7812200207 LER M78-034/01X-1 on 781101 noted that 17 spare process piping penetrations on Unit Wi & 23 on Unit M2 were not capped in Auxiliary Bidg Caused by Failure to properly complete capping et end of conetr.

  BAUCON, T L Virginia Electric & Power Co. 78/12/13 3pp. 94162: 275
- 7812270270 Forwards LER#78-041/03L-0. BTALLINGS.C H. Virginia Electric & Power Co 78/12/20 ip. 94272:039
- --7812270281 LER#78-041/031 on 781201 fellure of heet tracing circuit 54 (panel 10)Unit#2 Blander to charging pump suction due to uater damage of Heat Tracing Circuit Heet tracing tape replaced.

  BAUCOM, T L Virginia Electric & Power Co. 78/12/18. 2pp. 94232.040.

## T. Hearing transcripts on non-entitrust matters

- 781110051 Transcript of 781028 subcomm meeting in Nashington.DC resubs facilists am generator repair prog & whether ACRB should review the prog.

  CARBON.M., MRELLER.D., ETHERINGTON.H. ACRB Advisory Committee on Reactor Safeguerds. 78/10/28. 191pp. 94175.245.
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT i

  F. Security, medical, amergency & firs protection plans
- 7811140143 Forwards responses to 780913 &19 NRC ltrs re eddl info on fire protec prog equip.
  MAYERL D Northern States Power Co. 78/11/08. 16Pp. 94383 250.
- 7811290076 Summarizes progress of Fire Protec Review M/encl request for add1 info. staff positions. & evels. Requests meeting w/licenses 1 west after receipt of responses to latest staff positions.

  LAINAB.O. Plant Systems Urench iPrs 791030). 78/11/16. 27pp. 94192 182
- 7811290365 Requests addl info re fire protec prog & forwards NRC staff proposal & recommendations. Areas needing info include: equip req for achieving hot shutdown & fire brigade training. SCHENCER, A. Operating Reactors Branch I (Pre 790625). 78/11/21. 28pp. 94180:001.

#### 1. Financial information

- 7B10300156 Forwards 1977 Annual Rept & schedule showing 1977 actual Cesh Flow to comply with Reg Quide 9.4. Net intoms by dividends declered instead of dividends paid her been reduced to get reteined earnings figure.

  CARLSON, L. R. Northern States Power Co. 78/10/23 2pp. 94034:143.
- P. Operating license stage documents & correspondence
- 7810170220 Outlines schedules for correction of Zirconium-Water reaction inconsistency & dev of Upper Plenum Injection model & plant apacific celculations. Tentative completion date is April 1979.

  MAYER-L.O. Northern States Power Co. 78/10/12 2pp. 94236:163
- 7810300100 Notice of 781026 meeting w/ util to discuss besse for reactor coolant Tech spec in 780907 NRC ltr to util. GROTENHUIS.M. Operating Reactors Branch 1 (Pre 790625). 78/10/12. 2pp. 94035:064
- 7810300237 Evaluation of Overall Asymmetric LOCA Loads Notifies of decision to discontinue participation in utility task group's activities. Bubj util's plan is practical because of relatively recent design of reactor coolant sys piping. MAYER, L. D. Northern States Power Co. 78/10/25, 4p. 94034:034.

- SCHMENCER, A Operating Reactors Branch 1 (Pre 790623) 78/11/01-18pp 94049.037.
- --7811170265 GER for Amends#26 & 32 to subj facil oper lic. Concludes that Tach Bper changes related to heatup rets-reactor vessel pressure-temp oper limits, & part length rods does not involve a major hazards consideration. GCHJENCER. A Operating Reactors Branch 1 (Pre 790625). 78/11/01. 5pp. 94049.055.
- --7B1117026B Notice of fewance of Amend#32 & 26 to suby facil open lic SCHMENCER, A Operating Reactors Branch 1 (Pra 790625). 78/11/01. 2pp. 94049,060.
- 7811100338 Confirms upcoming 781116 meeting to discuss NRC's reg prog for protecting pub health & sefety. A tentative meeting agends is anciosed KEPPLER.J G Region 3. Chicago. Defice of the Director. 78/11/02. 3pp. 94007.305.
- 7811140022 Confirms upcoming 781116 meeting to discuss NRC's rag program for protecting pub health & safety. A tentative maeting agands is entlosed. KEPPLER.J. G. Region 3. Chicago, Diffice of the Director. 78/11/02. 2pp. 94419:024.
- 7811160191 Confirms telephone plans to meet & discuss pub health & safety protec grog as it relates to subj facil. Tantative agands for 781116 meeting encl KEPPLER.J G Region 3, Chicago. Office of the Director. 78/11/02. 3pp. 94136:039.
- 7811150115 Requests lic amend no later than 781215 rs Daletion of Reactor Trip on Turbina Trip Below 50% pur & encl requests for Tach Spac changes & sefety evaluation supporting changes.

  MAYER.L.D. Northern States Power Co. 78/11/03 34pp. 94113:340.
- 78iii30i47 Lic Amend request proposing change to reactor trip on turbine trip setpoint. Rev setpoint is justified on basis of NRC approved transient analysis methods amployed by Wastinghouse Corp.

  » License Fee Management Branch. 78/11/03. 1p. 94272:360.
- 78iii20157 Notifies applicant of 78ii28 NRC-sponsored saminer re Model Radiological Effluent Tech Space for Nuc Pur Plants. Enci w/Seminer info Sheatlto be completed & raturned by 78iii7) & Progresed Agenda.

  KEPPLER. J. O. Region 3. Chicago, Office of the Director. 78/11/07.

  App. 03553:293
- 7811210452 Confirms piens for 781116 meeting concerning reg prog for protec of pub heelth & safety re subj fecil. Tentetive agenda enci.
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 78/11/08.
  3pp. 94480:327.
- 7812010083 Confirms telephone discussion on 781107 rs 781116 meeting for local pub officials in vicinity of subj facil. Forwards tentative agends.
  KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/08. 3pp. 94417:137.
- 7811280403 Notice of Proposed Issuance of Amend to Fecil Oper Lic 40PR-42 % DPR-60, rev Tech Spec re use of Exxon fuel in Cycles 5 thru 8. 8CHMENCER.A. Operating Reactors Branch 1 (Pre 790525). 78/11/09. 4pp. 94397-317.
- 7811290010 Forwards "Notice of Proposed Issuance of Amendments to Facil Oper Lic." in response to 780908 amend appl re refueling of facil W/Exron Nuc Co Fuel for oper Cycles 5 thru B at each unit W/encl AND: 7811280403.

  BCH-MENCER.A. Operating Resctore Branch 1 (Pre 790625). 78/11/09.
  2pp. 74179:1120
- 78:2180050 Notice of workshops re implementation of training & qual raquirements contained in Append B of 10CFR73. Requeste pre-workshop registration of ettendese to facilitate sending out math. Myencl Registration Form & Liet of Locations.

  MILLER, J. R. Assistant Director for Site & Safeguerde (Prø 791030). 78/11/15. Spp. 94133:070.

- 7811280279 Request for emand to oper liceDPR-42 & DPR-60 to change Tech Specs re secondary coolant chemistry monitoring requirements Incl safety evel & minimum frequencies for sampling tests. Wichack for \$4,400. MAYER.L D. Northern States Power Co. 78/11/22. 5pp. 94395:222.
- 7812150061 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wiencl ANO: 7812080207
  BCHENCER. A Departing Reactore Branch 1 (Pre 790625). 78/11/20 6pp. 94210-122
- 7812060141 Forwards Environ Event Rept 78-11 on Cooling Towar Oper for Nov 1978. Slightly sleveted blowdown flow req for 3 days, during month to accomplete cooling aus preventative maint work.

  HARD.E.C. Northern States Pauer Co. 78/12/01. 1p 94372:251.
- 7812280017 Emphasizes importance of sumbitting accurate & complete inPd to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuraties or snforcament action will result DAVIS.J. O. Office of Inspection & Enforcament, Office of the Director. 78/12/06 2pp. 94131:034.
- 7812130215 Requests util help w/vital area analysis re sub; facil. Informs of sits visit on 790109-11 by Los Alemos Scien Lab representatives SCHMENCER, A Deprating Reactors Branch 1 (Pre 790625). 78/12/08.
- 2pp. 94304·085.
- 7812190154 Bummery of 781026 meeting to discuss tech space for secondary water cham, reactor coolent activity & secondary coolent activity.

  ORDIENHUIS.M. Operating Reactors Branch 1 (Pre 790625). 78/12/12

  Bpp. 94340:150.
- 7812290236 Forwards request for add1 info re Topical Rept XN-NF-78-30 in order to complete review of reload conditions. Req info should be submitted w/in 45 days.
  IPPOLITO, T. A. Operating Recetors Branch 3 (Pre 790623). 78/12/19.
  Opp. 94191:232.
- O. Inspection reports, IE Bulletins & correspondence
- 7810110199 Ack receipt of 780918 ltr informing NRC of etepe taken to correct violetione noted in 780829 NRC itr. FIORELLI,O. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/04. 1p. 94058:356.
- 7810230308 Forwards IE Circular#78-17. (See ANO.7810230221/Docket 50-313.781013)
  KEPHER, J. O. Ragion 3, Chicago Office of the Director. 78/10/13 19. 94147:041.
- 78i1130054 Forwards IE Circular 78-18.

  KEPPLER.J. G. Region 3: Chicago: Office of the Director. 78/11/06.

  ip. 94i12:183.
- 7812200091 Forwards IE Inspec RepteM50-282/78-12 & M50-306/78-13 on 780903-08.11-14.20-02 & 25-29 & Notice of Violation FIORELLI.Q. Region 3. Chicago, Reactor Operations Nuclear Support Stanch, 78/11/09, 2pp. 94184-335.
- --7812200095 Notice of Violation from inepsc on 780905-08,11-14,20-22 & 25-29.

  \* Region 3. Chicago, Office of the Director 78/11/09. ip 74155:337
- --7812200099 IE Inspec Repts#50-282/78-12 & #50-306/78-13 on 780905-08.
  11-14,20-22 & 25-29 during which 1 item of noncompliance was noted: fellure to follow an implementing procedure for approved GA prog.
  FELERABEND.C.D., WARNICK, R.F. Region 3. Chicago, Office of the Director. 78/11/06. 5pp. 94136:338.

- --7812210054 IE Inspec Repts#50-282/78-14 & #50-306/78-15 on 781016-20 during which 1 item of noncompliance was noted an employee was not wearing proper protective equipment. RIDEN.H D. LITTLE.H S. Region 3, Chicago, Reactor Operations Nuclear Bupport Grench. 78/11/14 4pp 94269.338
- 7812050278 Forwards 1E Bulletin#78-12A.suppl to 1E Bulletin 78-12. W/enrl AvB: 7811300555. KEPPLER, J. O. Region 3. Chicago. Office of the Director 78/11/24. 1p. 94202 165.
- 7812210036 Responds to 781107 NRC itr re-violations noted in inspec RepteM30-282/78-12 & #30-306/78-13 Corrective ections Design Charge Index Form(A)PINOPM340 rev to Incl date of completion of installation WACHTER: L. J. Northern States Power Co. 78/11/30 ip 94267 362
- 7812270028 Ack receipt of 781130 itr informing NRC of steps taken to correct violetions noted in 781109 NRC ltr. FIORGLLI, G. Ragion 3: Chicago, Reactor Operations Nuclear Support Branch. 78712714 1p. 94159-242.
- 7812260062 Forcerds 16 Dulletin 78-14.

  KEPPLER, J. O. Region 3. Chicago: Office of the Director. 78/12/19.

  1P. 03554:350
- R. Periodic operating reports & related correspondence
- 7810120029 Forwards Monthly Oper Rept for Sept 1978.
  MAYER.L. 0 Northern States Power Co. 78/10/09. 1p. 94421:174.
- --7810120031 Monthly Oper Rept for Bept 1978. HUNSTAD, A. A. Northern States Power Co. 78/09/30. 4pp. 9421:173.
- --7810120033 Monthly Oper Rept for Bept 1978 HUNSTAD, A. A. Northern Stetes Power Co. 78/09/30 App. 94081:305.
- 7811140115 Farwende Monthly Open Rept for Oct 1978.
  HAYER, L. O Northern States Power Co. 78/11/09. lp. 94425:159
- --78:1140:17 Monthly Oper Rept for Oct 1978. HUNBTAD, A.A. Northern States Power Co. 78/11/01. Bpp. 94425:169
- 7812120071 Forwards Honthly Open Rept for Nov 1978.
  MAYER, L. Q. Northern States Fower Co. 78/12/08, ip. 94274:195.
- --7812120094 Monthly Open Rept for Nov 1978 HUNGTAG. A. Northern States Power Co. 78/12/01. App. 94274:196.
- 8 Reportable occurrences. LERs & related correspondence
- 7810180012 Forwards LER#78-018/017-0.
  MAYER, L. O Northern States Power Co. 78/09/26. 1p. 94482:014.
- --7910180013 LER#78-019/01T-0 on 780912 Lightning etrike on trenemission line caused breeter 6H5 to open resulting in lose of 2 of the 3 sources of offsite pur Design change in transformer protect relaying 1s being pure
- 78:0170224 Environ Event Rept 78-09 re open of plant circulating water sys in partial recycle mode for Bept Except for 780921, sacess blowdown flow were needed for the month, everage delig blowdown flow rate was about 480cfs.

  MARD.E.C. Northern Bletts Power Co. 78/10/02. 1p. 94236:166.
- 781107021B Environ Event Rept 78-10 covering open of Pient circuleting water sys in pertial resucte mode w/deily average blowdown flow in axcess of 130 cfs.

  WARD.E.C. Northern States Power Co. 78/11/01, 1p. 94039:122.
- 78:11070247 Forwards LERN78-020/03L-0.
  MAYER-L. D. Northern States Pauer Co. 78/11/01. 1p. 94039:233.

- --7812260209 LERM78-023/03L-0 on 781130 during pur oper & relay test at refueling, Safeguards Bus 14 inadvertently was locked out of svc for about 2 minutes, caused by appl of elec jumper w/o groper review & approval.

  HKNSTAD-A A Northern Bitetes Power Co 78/12/20 ip. 94160,174
- DOCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR
  P. Operating license stage documents & correspondence
- 7811080035 Foruerds "Notice of Proposed Issuence of Amend to Facil Lice for AGN-201 rea reactor. Amend appl of 780810 requested Increase of meximum pur level from 100 MM to 5H REID.R. H. Operating Reactors Branch 4 (Pre 790625) 78/10/10 2pp. 94398:106
- --781108003B Notice of Proposed Leguance of Amend to Fecil Oper LiceR-iion 781010 REID.R H. Operating Reactors Branch 4 (Prø 790625) 78/10/10 Ann. 9409B:108
- 7811120330 Finds fecil Tech Spec not IAH current prectice Requests recipient to Mpd AGN-201 TS & resubmit ABAP H/snc1 Tech Spec.
  REID.R.H Operating Reactors Branch 4 (Pre 790625) 78/10/24, 53pp. 94087 156.
- --7811130333 Proposed "Standard for Admin Controls for Res Reactors."

  \* American Nuclear Society. 78/01/31. 15pp. 94087:211.
- 7812070202 Request on amond to 780810 itr to incorporate Tech Specs Amond forwarded 781024 per NRC request RAMESY,0. F. Ideho Bate Univ. 78/11/21. ip. 94375:101.
- --7812070204 Tech Spece of mode to ANSI N378-1974 & Reg Guide 2.2 guidence Tech Spece Incl definitions safety eye operation operation design feetures & edmin contols.

  4 Ideho State Univ. 78/11/15. 29pp. 94375:102.
- DOCKET 30-285 FORT CALHOUN STATION, UNIT 1
  F. Security, medical, emergency & Pire protection plens
- 7B10230197 NRC ofc of Controller has been given such to refund Class II amend fee of \$1.200 which was sent w/2B0713 appl. Weiver of fee for fire protec amend deered appropriate MILLER.W.O. License Fee Menagement Granch. 78/10/10. 1p.
- 7810230079 Informs NRC of criteria for instellation & testing of fire detectors in sefety related portions of fecil. Air flow patterns will be determined combustibles will be verified, struc considerations will be meds.

  8HORT, T.E. Omeha Public Power District. 78/10/19. 2pp.
- 7810220101 Info re penetration seels is provided. Penetration seal against utilizing silicons foem.eilicons slastomers & other related mates is currently being installed at subjecti. Quide spece prepared by Chemtral Corp on genetration seels encl. BHDRT.T.E. Omeha Public Power District, 78/10/18, 92pp. 94367:075.
- 7812030193 Bubmits rept pursuent to Tech Bpscs 2.19.4.a(11) & 5.9 3.1 re 781016 removal from evc of Elec Fire Pump FP-1A for "A" cell suction ecreening maint & circuleting water pump maint. Fire protect prog now fully operationel. SHORT.T.E Omeha Public Power District. 78/11/14. 2pp. 94317:272.
- H. Osmeral correspondence
- 7811280280 Requests ell future correspondence re subj fecil be eddressed to: TE Shart. Assistant Cenerel Heneger. Omeha Public Pur District. 1623 Henney Street. Omeha. Nebreske 68102. SHORT, Y. S. Omeha Public Power District. 78/11/20. 1p. 94395:227.

- 7810130151 Informs of planned action to support its for Gycle 5 open. Will supply documentation describing mech. thermal & nuc characteristics of the fuel & will describe fuel design Also plans to apply for increased plant pur level to 1500 SHORT. T E Omaha Public Power District 78/10/04 2pp 94003.036
- 7811290390 Informs NRC that OPPD has been unable to procure a proper temp detector sys, but will relocate radiat monitor RM-059 to companyate Gives reseases RM-0568 should be left as is, w/o replacement or mod. SMORT.T E Omena Public Power District 78/10/16 App. 94181 175
- 7810250060 Forwards Appl for Amend of Oper Lic to permit test of shock suppressors during oper LeBourf. Lemb. Leiby & MecRae. 78/10/24 2pp
- --7810250063 Appl for emend to oper lic DPR-40.changing Tech Specs to parmit test of shock suppressors during oper EHORT. T. E. Omaha Public Power District 78/10/24 Spp
- 7810300378 Notifies that ofc of controller has been auth to refund Class II emend fee for subj facilisent u/ appl dtd. MILLER, W.O. License Fee Menagement Branch 78/10/24. lp. 94197:358.
- 7811060079 Requests w/drawel of 771019 Appl for Amend for Operating Lic of subj facil The Cycle 4 operation has ended & peaking in fuel pine adjacent to flooded guide tubes was considered in Cycle 5 Core Reload Appl.

  SHORT.T.E. Omeha Public Power District 78/10/29. 1p. 94424 027
- 7811060099 Requests w/drewel of Request for Exemption Filed by epplicant Omeha Pub Pur District on 780714 Request is no longer necessary aince recent amend to 100FR21 Cert of svc encl.
  - enci. • LeBowuf, Lamb, Leiby & MacRae 70/10/30 2pp 94424:294.
- 7811070099 Forwards responses to first round of questions re subj facil Cycls 5 Rslood Appl dtd 780801 from Comm on 781005 SHORT.T.E. Dmahe Public Power District 78/10/31 3pp. 94038:288.
- 7811090iBO Forwards responses to second round questions re Cycle 3 Reload Appl of subj fecii BHORT.T.E. Omaha Public Power District 78/11/07. 10pp 94038:197.
- 7811140197 Forwards responses to questions posed in NRC itr of 770919 Responses qualitatively describe mods to be performed by DPPD to ensure that long term core cooling can be performed w/out boron pracipitation difficulties SHORT.T.E. Omeh Public Power District 78/11/08. 9pp. 94384:313
- 78iii50i32 Forwards add1 fee for amend to provide for Cycle 5 open of facility after core reload. SHORT.T.E. Omah Public Fower District. 78/11/09. 2pp. 94272:265.
- 7811170493 Forwards addl justification for OPPD request for amend of Facil Oper Lic for subj plant. Also forwards complete set of proposed Tech Spacs reflecting past amends.
  SHORT T. E. Dmaha Public Fower District. 78/11/09. BOpp. 94047:270
- 7811240087 Ack receipt of 781023 appl for amend to operating list to permit testing of shock suppressors. Because requested action is a Class 3 action, an addl fee of N2.800 should be sent in addition to the \$1.200 already received MILLER-W O. License Fee Manegement Branch. 78/11/13. 1p. 94458:074.
- 781219005: Forwards Rev#1 "Draft Radiological Effluent Tech Bpecs" for PWR's (NUREO-D473) & "Preparation of Radiological Effluent Tech Bpecs for Nuc Pwr Plants" (NUREO-0133).

  GRIVEB. B. K. Assistant Director for Engineers & Projects (Pre 790&25). 78/11/13. 6pp. 94215:057.
- 7812040161 Forwards responses to 780803 staff round 3 questions refecil Cycle 5 reload submittel.
  SHORT.T.E. Omaka Public Power District. 78/11/27 7pp 94456:135.
- 7812160072 Forwards Amend#41 to Facil Oper Lic#DPR-40.changing Tech Base for emergency pur sys. REID.R.H. Operating Reactors Granch 4 (Pre 790625). 78/11/27. 2pp 94(31:2AC)

- --701218000: Safety Eval supporting Amend#41 to Facil Oper Lic#DPR-40 Finds hazards will not increase significantly.

  \* Office of Nuclear Reactor Regulation. Director 78/11/27 6pg
- --7B12180083 Notice of Issuance of Amend#41 to Facil Lic#DPR-#0. REID-R.W. Operating Reactors Branch 4 (Pre 790623) 78/11/27 2ps. 94131 279.
- 7812130075 Discusses possible dangers of LOCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing Wencl AND. 7812080207
  REIDR.N. Operating Reactors Branch 4 (Pre 790625). 78/11/29 bpp

REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29 bpp 94210:352.

- 7812180376 Issues Arand 42 to Facil Operating LicHPDR-40 incorp site security plan info effective 790223 Forwards Amend 42 & Notice of Issuence.
  REID.R H. Operating Reactors Branch 4 (Pre 790625). 78/11/30 3pp
  - 94358 206.
- --7812180380 Amend 42 to Fecil Operating LiceDPR-40 re physical securiplen Becomes effective 790223. REID.R.W Operating Reactors Branch 4 (Pre 790625). 78/11/30. 2pp 94358 209.
- --78(2)80390 Natics of Issuance of Oper Lic#DPR-40 Amend 42 adding 11c condition to incl Comm approved physical security plan. REID.R.W. Operating Reactors Brench 4 (Pre 790625), 78/11/33 2pp. 94350 2i1
- 78:2130107 Forwards Amend#43 to Facil Oper LickDPR-40. REIO.R.W Operating Reactors Brench 4 (Pre 790625) 78/12/05. 2pp 94212-089.
- --781215014 Amend#43 to Fec11 Open LicMDPR-40, changing Tech Spec IAW Cycle 5 reload analysis & deleting Tech Specs permitting partial insertion of Control Element Assemblies REID.R.W Operating Reactors Branch 4 (Pre 790625). 78/12/05. 25pp. 94212:091.
- --7812150117 Safety Evel supporting Amend#43 to Facil Oper Lic#DPR-40. Concludes public will not be endangered e Office of Nuclear Reactor Regulation. Director 78/12/05 i9pp. 94212:116
- --78:2150119 Notice of Issuence of Amend#43 to Lic#DPR-40. REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/12/05. 299. 94212-135
- 7812280098 Emphasizes importance of submitting accurate & complete in to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations Licenses must notify NRC of any ineccuracies or enforcement action will result. DAVIS.J.O. Diffice of Inspection & Enforcement, Office of the Director. 78/12/06. Zpp. 03559:315
- 7812260203 Responds to 781113 ltr & encloses \$2800 check covering add amend fee for application for amend dtd 781023. Applicant seeks permit to test shock suppressors during open of subjecti.

  8HORIT, E. Omahe Public Power District 78/12/12 lp. 94160 138
- 7812290176 Provides info re insvc inspec & test of check valves SI-17 & 8I-176 in conteinment sprey sys. Valves will be added to inspec plen under Category C. Requests essention from stroking requirements since vessel must be sprayed down. SMORT-T.E. Deache Public Power District, 79/12/22 4pp. 94190-32
- G. Inspection reports, IE Bulletine & correspondence
- 7811030034 Forwards IE Inspec Rept#50-285/78-11 on 780821-25 during which no item of nancompliance was noted MADERNO L. Region 4. Dallas. Reactor Derations Nuclear Support Branch. 78/09/ii. 2pp. 02720.341.
- ---78ii030036 IE Inspec Rept#50-283/78-11 on 780B21-29 during which no term of noncompliance was noted Major dreas inspected included procurement prep for refueling plant oper safety injection sys reset proc & elec equip.

  JCHN80N. H. D. Region 4. Dallas, Reactor Operations Nuclear Suppor Branch. BOYTER.N.C., HADSEN.G.L. Region 4. Dallas, Reactor Construction & Engineering Support Branch. 78/09/07. 7pp. 02720: 343.

- 78:01:02:19 Ack receipt of 78:09:18 ltr informing NRC of steps taken to correct violations noted during inspec#30-285/78-10.

  MADSEN/C L. Region 4. Dallas, Reactor Operatione Nuclear Bupport Branch 78/09/27. 1p. 94062 164
- --7810110223 Responds to 780830 ARC ltm re violation noted in Inspec Rept #50-285/78-10. Corrective actions: Integrity of wall strengthened by covering transom u/metal grating. investigation of similar areas performed BICRT.T.E. Onahe Public Power District. 78/09/18. 2pp. 94062:165
- 7610160215 Forwards JE BulletinH78-32 (8ss AND: 7810040253)
  BEVFRIT.K. V Region 4. Dallas, Office of the Director. 78/09/29.
  1p. 94005.317.
- 7811220119 Forgards IE Circular#78-18, "UL Fire Teet." W/enc1 AND:7611150002. 8EYFRIT.K V. Ragion 4. Dallas, Office of the Director. 78/11/06 1p. 94074-194.
- 7811280059 Forwards IE Inspec Rept#50-285/78-12 on 780917-20 & Notice of Violation MADEN.4 L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 78/10/12 2pp. 94013 288.
- --7811280060 Notice of Violation from Inspec on 780917-20 9 Region 4, Dallas, Office of the Director. 78/10/12 ip. 94013:290.
- --7811280052 IE Inspec Rapth50-285/78-12 on 780917-20 during which 2 items of noncompitance were noted: failure to follow procedures re-records audits & failure to follow tech spece re-personnel qual audits. UCHSON, W.O., DOYTER, N.C., MADSEN, O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 78/10/12, 7pp. 94013:291.
- 7810230278 Forwards IE Circular#78-17. (Bss AND: 7810230221. Dacket 80-133/781013)
  BEYFRIT.K. V. Rasion 4. Dailes. Office of the Director. 78/10/13. 1p. 94179: 335.
- 7812060348 Forwards IE Inspec Rept#50-285/76-13 on 781010-13 & Notice of Violation.
  MADEEN.Q.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 78/10/31. 2pp. 94382:264.
- --7818060349 Notice of Violation from ineger on 781010-13. \*\* Region 4. Dallas Office of the Director. 78/10/31. ip. 94382:266.
- --7812060331 IE Inspec ReptsH50-285/78-13 on 781010-13 during which I ltm of noncompliance was noted: failure to adhere to plant procedures in response to Tech Spec & Design changes. JCHNBON, M. D. Region 4. Dallas, Office of the Director. 78/10/31. 6pp. 94302:267.
- 78:11:30:84 Response to requeste for info ra inext testing & inepec of check valves in the safety injection recirculation lines at subj facil.

  8HORT.T.E. Onabe Public Power District. 78/11/02. Spp. 03553:320.
- 781 1280257 Discovered that certain hydrotest requirement for Class 2 piping in ASPE XI. Burmer of 1975 Addenda to impractical w/in meaning of 10CFR50.35(a). Thus, rev to "insve inspec Prog Plan for the 1976-1980 period" for subj facil is and.
  BHORT. T. E. Omaha Public Power District, 78/11/20. 3pp. 02725:348.
- 7812050044 Ack receipt of 781106 ltr informing NRC of eteps taken to correct violations noted during inspec#50-285/78-12. MADEM.4L. Region 4, Dellas, Reactor Operations Nuclear Support Branch. 78/11/21. 1p. 94234:056.
- ~~781206004B Responds to 781112 NRC ltr rs violations noted in Inspec Rept%30-283/78-12.Corrective actions:approved sched of Internal & External Audits will be published at beginning of each year. BHORT.T.E. Omaha Public Power District. 78/11/06. 3pp. 94224-057.
- 7812060264 Forwards IE Bullstin#78-12A suppl to IE Bullstin#78-12. w/smc1 AND.7811300055.
  BEYFRIT.K. V. Region 4. Dailes. Dffice of the Director. 78/11/24. ip. 94371:348.
- 7812050R78 Ack receipt of 781121 itr informing NRC of steps taken to correct violations noted during Inspec#50-285/78-13. MADSEN.O.L. Region 4. Dalles. Reactor Operations Nuclear Support Branch. 78/11/29. ip. 94372:283.

- --7812060282 Responds to 781031 NRC ltr re-violation noted in Inspec Rep MSO-285/78-13. Corrective actions, all 1977 Fuel Mgt & Handling Records were examined in Oct & Nov 1977 & Inventories made of fuel assemblies SHORT. T. E. Onsha Public Power District, 78/11/21, 3pp. 94372: 284.
- 7812130111 Provides into re inspec of check valves 81-159 & 81-160. Beliaves test for valves is unnecessary & impractical, but during next refueling outage a flow test or removal & test will be performed.

  BHORT, T. E. Omaha Public Power District 78/12/08. 2p. 94294:349.
- R. Periodic operating reports & related correspondence
- 7810110189 Forwards Section IV of "Semi-Annual Rept for Tech Spec 5.9.4 & Append B 780101-780630 Inclusive." BHORT.T.E. Omaha Public Power District. 78/10/03 ip. 94068:043
- --7810110193 "Semi-Annual Rept for Tech Spec 5.9.4 & Append B.Jan-June 1978." " Omaha Public Power District. 78/10/03. 105pp. 94068:044.
  - \* Omaha Public Power District. 78/10/03. 103pp. 94088:044.
- 7810130125 Forwards Monthly Oper Rept for Sept 1978. 8HORT.T.E. Omena Public Power District. 78/10/09. ip. 94003:094.
- --70101301@6 Monthly Oper Rapt for Bept 1978. HICKLE.B.J. Omana Public Power District. 78/10/09. 9pp. 94003-095.
- 78:11:40:107 Forwards Monthly Oper Rept for Oct 1978. BHURT.T.E. Omaha Public Power District. 78/11/08. 1p. 94425:127.
- --7811140161 Monthly Open Rept for Oct 1978. HICKLE B. J. Omaha Public Power District. 78/10/31. App. 9429: 128
- 7812130178 Forwards Monthly Open Rept for Nov 1978.
  SHORT-T E. Omaha Public Power Dietrict. 78/12/08. ip. 94305:344.
- --7812130181 Monthly Open Rept for Nov 1978. HICKLE B.J. Omaha Public Power District. 78/12/08. 14pp. 9430:345.
- 8. Reportable occurrences. LERe & related correspondence
- 7810110113 Forwards LERW78-026/03L-1.
  ANDREMB.R.L. Omeha Public Power District, 78/09/21. 1p.
  74068.149.
- --7810110117 LER#78-026/03L-1 on 780830: "8"channel RP8 variable dvarpar trip reset damand alarm actuated & would not reset. Then, HI purt & thermal margin/low preseure trip units failed, both due to failure of Deveri9-601A, IBvolt pur supply.
  CDNNCLEY, J. Dmaha Public Power District. 78/09/15. 3pp. 94068: 130.
- 7810130100 Forwards LER#78-028/03L-0. ANDREMB.R.L. Omeha Public Power District. 78/09/29. 1p. 94066:340.
- --7810110103 LERM78-028/03L-0 on 780831: fellure of Tri-: weather towar' 100 mater Delta-T sensor sys to rept stability class info. Calibrations revised to ensure instruments datect subsequent sensor eys failures.
  OTTERSERG, J., PETERSON, 0 Gmaha Public Power District. 78/09/27. 3pp. 94066:341.
- 7810100010 Forwards LER#78-030/01T-0. ANDREMB.R. L. Omeha Public Power District. 78/10/03. ip. 74418:186.
- --7810100014 LERM78-030/01T-0 on 781003: During oper check on avxiliary steam driven feed pump, the steam inlet valve YCV-1045 did not open due to closed air supply.

  GATES, G. Omaha Public Power District. 78/10/03. 4pp. 94415:167.
- 7810110112 Forwards LER#78-029/03L=0. ANDREMB,R.L. Dmaha Public Power District. 78/10/06. 1p. 94053/019.
- ~-7810110114 LER#78-029/03L-O on 780908: Inedvertent radioactive gas release to atmosphere caused by leakage past thetk valve CH-28A: HQ-100 & relief valve HG-105. Valves will be inepacted & replaced or repaired during next refueling outage.

  GATES, G. Dmaha Public Power District. 78/10/06. App. 94053:020

iBO159 Forwards LERB78-031/03L-0. IBEENS.R.L. Omaha Public Power District. 78/10/11 ip. 317:017.

i0i80162 LERB78-031/03L-O on 780918 during normal steady state pur oper the hot leg temp indicator for "D"channel went to full ccale, due to unknown cause. CCHNCLLER, J. PETERBON, O. Omaha Public Power District. 78/10/11. 3pp. 94317:018.

\$1060204 LERS78-032/03L-0 on 781002 during performance of ST-EGF-5, timere SI-18 k CH-18 on sequence S2-2 Pailed to time out w/in prescribed limit due to a stuck open machanism. Timere were exercised to free mechanism.

ANDREMS R.L. Dmaha Public Power District. 78/10/31. 3pp. 94489.197.

210368 Forwards LER078-033/03L-0. DREMB.R.L. Omaha Public Power District. 78/11/08 ip 485:129.

H1210371 LERR78-033/03L-0 on 781014:Reactor coolant cold leg temp indicator B/122C feiled high off scale because of an open circuited Rosemount Hodel 104VC RTD. The RTD will be replaced during present refueling outage.

PETERBON.9. CONNOCLEY.J. Omaha Public Power District. 78/11/02.
3pp. 94485:130.

010238 Forwards LERM78-034/03L-0. DREMB.R.L. Omeha Public Power District. 78/11/25. ip. 1409:353.

it2010240 LERR78-034/03L-0 on 731026:repeated tripping of stack particulate process monitor. Caused by trip set in eccordence w/fech Specs Table 2-1 at 9.6x10-2:rather than more conservative release rates 2x10-3. KUBEXL I. T. Omaha Public Power District. 78/11/25. 2pp. 94409:354.

050173 Forwards LERW78-036/03L-0. UNREWS.R.L. Omeha Public Power District. 78/11/30. ip. 1325-128

312050179 LER#78-036/03L-0 on 781101: auxiliary feedwater check valve PH-164 found to be oriented in wrong position. Caused by missing valve disk plate which was subsequently located & recovered.

KUSEK/L.T. Omeha Public Power District. 78/11/27. App. 94335: 129.

2200264 Forwards LER#78-037/03L-0. UDREWS.R.L. Omeha Public Power District. 78/12/08. ip. 1207:103.

312200272 LERW78-037/03L-0 on 781116:during refueling.ell Limitorque Velves were inspec for proper staking of the lock nut on the motor pperstor. 30 of 65 velves exhibited unstaked lock nuts. Lock nuts were staked IAW manufacturer's instruc.
JONES D., ANDREWS, R. Omshe Public Power District. 78/12/05. 9pp. 49207:104.

2200267 LERB/28-038/017-0 on 781127: Dissel generatorM2 falled to autolious dato the busibreaker made switch contracts 27-27c siled to make contact. Caused by contact failure. 7807:114. PETERBDN. 0. Omaha Public Power District. 78/12/08. 3pp. 18207:114.

220027 Forwards LER#78-035/03L-0. UNREWS.R.L. Omaha Public Power District. 78/12/12. 1p. 4162:313.

Bi2200231 LERR78-035/03L-0 on 78iii3: during test of Ventilation labiation Actuation Bignel-lockout 885i/VIAB did not trip. Cause unidentified, eince relay retested & found to be operating normally, Relays will continue to be tested. CRE.M., PETERSON, 0. Omehe Public Power District, 78/12/12, 3p. 94i62; 314.

2270213 Forwards LER#78-037/03L-0. NDEWA, R. L. Omaha Public Power District. 78/12/22. 1p. 4146:094. --7812270217 LER878-039/03L-0 on 781122 nated that level transmiter for "C" channel (C/LT-901) for steam generator RC-2A level instrumentation not w/in specs. Caused by callbr drift of GEMAC Model 535 transmitter. CONNQLEY. J., PETERSON. G. Omaha Public Power District. 78/12/20 3pp 94168:097

7812270219 Forwards LER#78-031/03x-1 ANDEMB.R L. Omsha Public Power District 78/12/22. 1p. 94015.359.

--7812270224 LER678-031/03x-1 on 780918 during refueling outage."D" channel hot leg temp indication was investigated to deteraine cause of 780918 failure. Feilure caused by Rosemount Model 104VC RTD having water in the pothead CONNOLLEY.J., PETERBON.O Omaha Public Power Bistrict. 78/12/21. 3pp. 94015:359.

7812270258 Forwards LER#78-043/03L-0 ANDREWB.R. L Omaha Public Power District 78/12/22. 1p. 94166:063

--7812270262 LERR78-043/03L-0 on 781204 during improc of discharged fuel assemblias, a single fuel pin was observed to have failed, assoc w/manufacture & exposure of present day nuc fuel. DWQER, L.J. Qmaha Public Power District 78/12/22 3pp 94168-064.

7812270332 Forwards LERW78-044/03L-0.
ANDREWS.R. L. Dmaha Public Power District 78/12/22 ip. 94272-009

--7812270333 LERM78-044/03L-O on 781214 during 1978 refueling outage, certain surveilience tests req by Tech Spece could not be performed because of shutdoon condition facil Lic Chango #77-11 eubmitted to NRC on 781109 to delete requirements. KUEK.L. T. Oneka Public Power District. 78/12/19. 7pp. 94232:029

7812290225 Forwards LER#78-042/03L-0 ANDREWB.R L. Desha Public Power District. 78/12/22 ip. 94191:197.

--7812290228 LERW70-042/03L-0 on 781124: during shutdown cooling interlock test noted that PC-105D was not operating. Caused by valve closing relay 94-347/348 not being wired to PC-1058; inedvertently disconnected in 1977.

MEMAPREV. R. PRICERSON. O. Dmaha Public Power District. 78/12/22.

4pp. 94191:198.

7812200265 Forwards LERM78-038/017-0.
ANDREMS, R. L., Omaha Public Power District. 78/12/08. ip. 94007-112

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Bacurity, medical, emergency & Pire protection plans

7810260109 Responds to 780929 NRC 1tr requesting add1 info on Fire Protec Prop for subj facili 23 overeise drawings & Inventory sncli: copy drawings recd & sent to Br Chief. Orawings available in Central Files only.

EARLY,P. J. Power Authority of the State of New York 78/10/23.
3000.

7812270486 Requests additinfo on admin controls of fire protec prog by 790131.

BCHENCER, A. Operating Reactors Granch 1 (Pre 790625). 78/12/12.

7pp. 94015: 299.

#### 9. Adjudicatory correspondence

7811090188 Forwards recent NRC memos re problems w/pipe support beso piate design. Btaff will inform Bd of conclusions after study of add info from licenese. (See AND: 7811020332, 7811020336, & 7811020343.)

BNITH-B. H. Effice of the Executive Legal Director. 78/10/24, Rpp. 74031:078.

## H. General correspondence

7Bi2060113 Requests changes in distrib list for subj facil Replace Trotsen w/Bennett. EARLY,P.J. Power Authority of the State of New York. 78/10/24 ip. 94332:199.

- 7812190016 Forwards Rev#l "Draft Radiological Efficient Tech Specs" Por PWR's(NARCO-0473) & "Preparation of Radiological Efficient Tech Specs for Nuc Pur Plants" (NARCO-0133). GRIPES.G.N., Assistant Director for Engineers & Projects (Pre 790625). 78/11/15 6pp. 94214:286
- 7812050004 Forwards Licensee Performance Evel Questions for subj facils in response to 771123 request Feels it is possible that dev of statistical methodology for such eval may not justify the effort Qualitative eval may be as good. Urges 1-year test ORIEN. B. H. Region 1. Philadelphia. Office of the Director. 77/12/13 12pp.
- 7010110005 Responds to 700030 NRC itr u/questions on Diesel Generator Alam & Control Circuitry, Diesel control switch presently brings up safeguards equip locked open slarm when not in auto position. Circuit will be modified further BERRY. 0 T. Power Authority of the Blate of New York 78/09/29. 2pp. 94053, 358.
- 7810110094 In response to 780913 NGC ltr, etates that util submitted rev Emergency Core Cooling Bys calculation for subj facil on 780413 for ACRS rev EARLY, P. J. Power Authority of the State of New York, 78/10/02: 1p. 94063:359.
- 7BIO110160 Informs that info re lamellar tearing of steam generator & reactor coolant pump supports requested on 770914 & 771027 will be submitted by 7B1030.
  EARLYP. J. Power Authority of the State of New York. 78/10/02. 1p. 74069:244.
- 7810300061 Surmary of 781004 mosting re Environ Tech Spec on continuous monitoring of liquid effluent releases. Util was found to be in noncompliance w/ETS 2.4 i.e. b. remedial action was recommended pending util appeal. W/encl list of attendees. DLBHAN.L. Operating Reactors Branch i (Pre 790625). 78/10/12. App. 74004:286.
- 7010230191 Response to 700713 ACRB 1tr to NRC w/ltems of Concern re subj facil & to Auth's discussion w/NRC on 7009151discusses items re sys interaction; regulatory criteria & backfitting, instrumentation, shutdown & heat removal, & safety update. EARLY, P. J. Power Authority of the State of Naw York. 78/10/13. 2pp. 94052.275.
- 7810240100 Forwards data specified in Section 401 Certification for Bept Includes epecies code fist, grass elec output, circulating water temp.river water discharge, chem discharges L delly fish counts MONII. M. A. Consolidated Edison Co. of New York. 78/10/13 17pp
- 7810310240 Response to PAGN itr of 780802; forwards denial of PAGN's appl to extend period of interim oper using the installed once-thru cooling sys at sub; facil.

  DENTON,H.R. Défice of Nuclear Reactor Regulation, Director.

  78/10/13 3pp. 94091:322.
- --7810310243 Denial of PASN's appl for extension of period of interim oper using the installed once-thru cooling sys. Denial besed on NRC deference to EPA decision & NRC desire to evaluate that decision before taking action. GRLCARO.R.L. Environmental Projects Grench 1. 78/10/13. 3pp. 94091:325.
- 7811030102 Notice of denial of amend appl for lic#DPR-64,"Appl for an Extension of Period of Interim Oper Using Installed Oncerthrough Cooling Sys & Motion for Expedited Comm Consideration 780807". Comm must req compliance to EPA ached. BALLARD.R.L. Environmental Projects Branch 1, 78/10/13. 3pp. 02724:087.
- 7010300243 Forwards list of projects adddressed to the Hudson River estuary which NRC is conducting or in which it is participating as per ltr request of 760901.
  LEMIS B. H. Office of the Executive Legal Director. 78/10/17. 3pp. 48034:004.
- 7811080078 Responds to 780802 itr which included \$1,200 for extension of period of interim oper of facil using installed once-thru cooling eys. \$1,200 is being refunded pending legal estilement of request.

  MILLER.M. D. License Fee Hansgement Branch. 78/10/23. ip. 94271:107.

- oper & therefore milk sample is unobtainable Bamples of leafy green vegstables & milk from Shenandoah Farm will be taken. CAMILL-N J. Consolidated Edison Co. of New York. 78/10/30. 2pp. 74058:290.
- 7811070253 Forwards "Cyclo 2. Startup Physics Test Rept."
  BAYNE, J. P. Power Authority of the State of New York, 78/10/31. Ip.
  94003-00A.
- --7811070256 "Cycle 2. Startup Physics Test Rept".

  \*\* Power Authority of the State of New York. 78/10/31. 380pp
  94038 007
- 7811080110 Forwerds Summary Analysis of Periodic Type D & Type C Reactor Containment Bldg Leak Rate Test for subj facil. Leekegs during test occurred thru improperty positioned valve on #33 & 34 Containment Recirculation Fan EARLY-P. J Power Authority of the State of New York. 78/11/02. 3pp 94399-149.
- --7811080111 "Reactor Containment Bidg Integrated Leak Test-Summary Tech Rapt". Describes summar 1978 Periodic Type "B" & "C" tests at subj Pacil Measured leakage of all sys well within tech spsc. 4 Power Authority of the State of New York. 78/11/02. 62pp. 94399:132.
- 7811080183 Forwards"Appl for Amend to Oper Lic", \$1200 check for Class II fee not received. EARLY, P.J. Power Authority of the State of New York. 78/11/02. Rpp. 94405:103.
- ---7811080184 "Appl for Amend to Oper Lic". Three attachments incl Safety Eval.Environ Impact Assessment & proposed changes to Environ Tech Space.
  EARLY.P. J. Power Authority of the State of New York. 78/11/02.
  Bpp. 94405:105.
- 7811080123 Responds to 780828 itr & forwards "Appl for Amend to Operating Lic on Overpressure Protec Sys". Amend is class \$11 since it involves single safety issue.

  EARLY, P. J. Power Authority of the State of New York. 78/11/03.

  Rep. 94399: 231.
- --7811080127 Appl to amend operating liceDPR-64 Tech Spec contained in Appendix A. Proposed Changes are intended to desure safe Oper of Overpressure Protec Sys EARLY, P. J. Power Authority of the State of New York. 78/11/03. 26pp. 94299: 232.
- --781080129 Sefety eval of proposed Overpressure Protec Sye. Proposes to mod Tech Spec Section 3.1 to establish Limiting Conditions for Oper(LCO's) an Oper Companents of OPS. Changes will not increase accident probability. EARLY, J. Power Authority of the State of New York. 78/11/03. 2pp. 94399: 261.
- 7811210200 Forwards AmendM1B to Pecil Oper LicMDPR-64 for subj facil. Amend consists of changes to Tech Bpecs per 771102 appl. Also forwards Bafety Eval & Notice of Issuance. BCHLENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/06. 2pp. 9448B: 021.
- --7811210205 Amend to Facil Oper LiceDPR-64 Areas amended incl quadrant pur tilt ratio.heatup & conidown & cham & volume control sys.

  BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/06 36pp 94488:023.
- --7811210209 Bafety Eval supporting Amend#18 to Facil Oper Lic#DPR-64 for eubj facil. Changes incl reduction in maximum pressuriser heatup rete & change in definition of quadrant pur tilt ratio 
  # Office of Nuclear Reactor Regulation, Director. 78/11/06. 3pp. 94488:034.
- --7811210213 Notice of Issuance of Amend#18 to Facil Oper Lic#DPR-64 for oper of subj facil. Areas changed incl Tech Specs representier heatup & choldown rates & repting procedures resteam generator tube insvc Inspecs.

  BCHMENGER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/06. 37pp. 94488:037.
- 7811290208 Responds to 781106 request for info concerning licensee repperformence awal for Region i plants by NRC Provides details.

  ORIEH.B.H. Region 1. Philadelphia. Office of the Director.
  78/11/09. 9pp.

- 7811170160 Forwards data specified in Lection 401 Lectivitation for the aonth of October 1978 HONIL M.A. Consolidated Edison Co. of New York. 78/11/10. 16pp. 94048: 051
- 7811210274 Ack receipt of 781013 ltr responding to request for sateration of interim oper of subj Pacil using the installed once-thru cooling sys Believes hearing would be premature. EARLY, P. J. Power Authority of the Stets of New York. 78/11/13. 2pp. 94483 167.
- 7812150088 Notice of workshops to implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendess to facilitate sending out mat]. W/ancl Registration form & List of Locations. MILER.J.R. Assistant Director for Bits & Bafaguards (Pra 791030). 78/11/15. 5pp 94211:343.
- 7812190048 Forwards Revel "Draft Radiological Effluent Tech Space" for PHR's (NUREO-0473) & "Preparation of Radiological Effluent Tach Specs for Nur Pur Plants" (NURS-0-0133).

  ORINES-B. K. Assistant Director for Engineera & Projecta (Pra 79025). 78/11/15 6pp. 94215:045
- 7811290182 Forwards rept prepared by Wastinghouse in response to 771004 MRC itr re fracture toughness & potential for lemellar tearing of steem generator & reactor coolent pump support matl.Ript contains proprietary info.
  EARLY.P. J. Power Authority of the State of New York. 79/11/21. 2pp.
- 7812070200 Notice of seminar on 781208 on new Model Radiological Effluent Tach Space for nuc pur plants Requests advance submission of seminar apecific questions.W/encl Seminar Info Shast-Proposed Aganda & mapa. GRIER.B.M. Region i, Philadaiphia, Office of the Director. 78/11/21. Spp. 94375:093
- 7812140351 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. Whenci ANOS 7818080207.

  8CM-ENCER. A. Operating Reactors Branch i (Pre 790625). 78/11/28. 6pp. 03557:212.
- 78:2070180 Forwards application for smend to OLs.
  IARMAS.P. Consolidated Edison Co. of New York. 78/12/05. ip. TARAKAB, P. 94375: 030.
- --7812070182 Application for amend to OLs. Certificate of Svc enci.
  CAMILLA, J. Consolidated Edicon Co. of New York. 78/12/05. 12pp. 94375: 031.
- 7819280076 Emphasiss importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NAC of any inaccurative or anforcament action will result. DAVIS.J. G. Office of Inspection & Enforcament, Dffice of the Director 78/12/06. 2pp. 03035:31
- 7812050013 Requests views of Regional Directors on Liceness performance eval of subj facils. Forwards questions to be answered by 771209. THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23.
- 7812190182 Notice of 781218 meeting w/util to discuss NUREO-0133. "Preparation of Radiological Effluent Tach Spec for Nuc
- Pur Planta" as it applies to subj facil.

  OLSHAN-L. Operating Reactore Branch 1 (Pre 790625). 78/12/13. Spp. 94381:207.
- 7812190174 Forwards copies of "Appl for Amend to Oper Lic" which request emends to section 4.1.2a of Environ Tech Spec Requirements for subj facile. Amends would restructura present Aquetic Environ Nonitoring Prog. Cert of Byc snc1. CAMILLIM. J. Consolidated Edleon Co. of New York. 78/12/14. 3pp. 9334-000 94340:002
- --7812190180 Appl for emend to Licenses DPR-5, DPR-26 to DPR-64 requesting rev to Environ Tech Space Rev Tech Space to proposed mode are deeigned to provide a monitoring prog for continuous assessment of Hudgon River fish population. CMILL. N. J. BARLY, P. J. Consolidated Edison Co. of New York. 78/12/14. 46pp. 94340:005.
- 7812260014 Comments of PABN ra closed-cycle cooling conditions Asserts that lic condition should either be eliminated of delayed indefinitely. Cart of Bvc encl.
  TROSTEN.L.M., FIDELL, E. R., ANCARROW, M. R. LeBoeuf, Lemb, Leiby & MecRae. 78/12/15, 18pp. 94021:045.

- --/81559001A tormates abb; tot etteusion of installed once-thru cooling eys. pending final determination of permissibility of such systems. EARLY, P J Power Authority of the State of New York 78/08/02.
  - --7812260023 Appl for extension of period of interin oper using install once-thru cooling sys. Appl contains motion for expected railes Also encl is efficient of PJ Early of PASN in support of extension Power Authority of the State of New York 78/08/07 58pp 94021 065

APTIUU

- --7812260039 Notice of denial of amend appl seeking extension of period of interim oper using installed once-thru cooling sys Denial based on NRC legal reliance on EPA proc & decisions BALLARD, R. L. Environmental Projects Branch 1 78/10/13 Dpp. 94021 126
- 7812290170 Repts on Steam Generator Tube Plugging. Plant was placed but cold shutdown condition on 781207 as result of tube look in Steam GeneratorN31 Lesking tube was plugged explosively & excondary side hydrostatic test was performed BAYNE. J. P. Power Authority of the State of New York 78/12/20 2pp 74190 319.
- G. Inspaction reports. IE Bullatine & correspondence
- 7811080244 Forwards IE Inapec Rept#50-286/78-25 on 780815-17 during which no items of noncompliance were noted BRUNNER.E. J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch 78/09/19 2pp. 94405 349
- --7811080248 IE Inspet Rept#50-286/78-25 on 780815-17 during which no items of noncompliance were noted Major areas inspec inci-raviaw of pravious inapsc findings.oper actions on SIS reset features.CORE II startup preparations.
  REDELONSKI.Y Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/18. 7pp 94405-351.
- 7810160241 Forwards 1E Bullstin#78-12: "Atupical Wold Material in Reactor Pressure Vessal Haids" requesting action w/in 60 days & list of 1E Bullstins issued in 1978 (See AND #7810040253) ORIEN, 8 H. Region 1, Philadelphia, Office of the Director. 78/09/29. 6pp. 94007:007.
- 7810230134 Ack receipt of 780928 itr informing NRC of steps taken to correct violations noted during inspect#30-206/78-22 SMITH, 0. H. Region 1. Philadelphia, Fuel Facility & Materials Bofsty Branch. 70/10/12. 1p.
- --7810250135 Responds to 780906 NRC itr re violation noted in Inspec R #50-286/78-22 Corrective actions: establishment of inventory list for all health physics instru & control of human esposure to radiat.

  BAYNE, J. P. Power Authority of the State of Now York 78/09/20.
- --7810250136 Forwards 1E Inspec Rept#50-286/78-22 on 780717-21 & 780801-04 & Notice of Violation.
  CROCKER.H.W. Region 1. Philadelphia. Fuel Facility & Materials Sefety Branch. 78/09/06. 2pp.
- --7810250137 Notice of Violation from inapec on 780717-21 & 780801-04. Region 1. Philadalphia. Fuel Facility & Materials Safety Branch 78/09/04 Rpp.
- --7810250138 1E Inspec Rept#50-286/78-22 on 780717-21 & 780801-04 duri which 2 itams of noncompliance were noted: Pailure to adhere to radiat protec procedures & failure to control exposure w/in 10CFR20 101 limite. NEELY,D.R., HIGGINS,J.C. Ragion i, Philadelphia, Fuel Facility & Haterials Sacety Branch. 78/09/06. 19pp
- 7811060184 Forwards 16 Circular#78-17. (See ANO. 7810230221. Docket #50-133.781013. ) GRIER-B.H. Region i, Philadelphia, Office of the Director 78/10/13. ip. 94489:147.
- 7811100120 Ack receipt of 781005 ltr informing NRC of steps taken to correct violations noted during inspec#50-286/78-13. QRIER, B. H. Region 1. Philadelphia, Office of the Director. 78/10/20. jp. 94047:239.
- --7811100129 Responds to 780712 NRC ltr re violation noted in Inspec Rept#30-286/78-13 Repts current itr supersedes 780918 & 780921 itrs re-resolution of items from subj inspec. BANE, J. P. Power Authority of the State of New York. 78/10/05.

- --VBITUOUSLY Hepts Con Edison's corrective actions in response to requests by PABN re violations of ETS BAYNE.J P. Power Authority of the State of New York. 78/09/18 4pp.
- --7811100138 Responds to 780712 NRC itr re violations noted in inspec Rept#30-286/78-12 Rept# Con Edition conducts environ monitoring for PABN Corrective actions will be supplied subsequent to rely from Con Edition BAYNE.J P Power Authority of the State of New York 78/08/04 2pp 94047 201
- --7811100165 Forwards IE Inspec Rept#50-286/78-13 on 780516-18 & 22-23 & notice of violation GROCKER.H W. Region 1. Philadelphia. Fuel Facility & Matarials Safety Branch. 78/07/12 3pp. 94046 335
- --78iii00:72 Notice of Violation from Image: on 780516-18 & 22-23.

  \* Region 1, Philadelphia, Fuel Facility & Materials Safety Brench.
  78/07/10 3pp 94046 338
- --7811100161 1E Inspec Rept#50-286/78-13 on 780516-18 & 22-23 during which 6 items of noncompliance noted feature to submit anomalous measurements rept, feature to approve temp procedure changes in accord w/ETSR & other deficiencies. GCRESR J. 6704R.J.P. Region I. Philadelphia. Fuel Facility & Meteriale 8afety Granch 70/07/10 24pp. 94046.341.
- 78:2010047 Forwards IE inspec Repts#30-286/78-27 on 780911-12 during which no itams of noncompliance were noted.

  BRUNKER, J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/23 2pp. 94416-125
- --7812010062 IE Inepec Rept#50-286/78-27 on 780911-13 during which no item of noncompliance was noted Major areas inspected incl. response to IE Circular 78-08 "Environ Qualification of Safaty Related Elec Equip"
  REBECOMSAIL 7. KEIMIO.R. Region J. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/20 6pp. 94416:186.
- 78ii080082 Ack receipt of 78i0i0 ltr informing NRC of stepe taken to correct violations noted during inspec#50-286/78-26 BRUNKER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/10/27. ip. 94399.037.
- --7811080086 Responds to 780921 NRC ltr re violation noted in Inspec Rept #50-286/78-26 Corrective actions: procedures written describting admin of training w/documentation for Heintenence & I & C Dept personnel. BAYNE.J. P Power Authority of the Btate of New York. 78/10/10. ip. 94399-038
- --7811080090 Forwards 1E Inspec Rept#50-286/78-26 on 780822-24 & Notice of Violation.
  BRUNNER, E.J. Region i- Philadelphia, Reactor Operatione Nuclear Support Branch, 78/09/18, 2pp. 94399:039.
- --7811080097 Notice of Violation from Inspec on 780822-24.
  BRUNNER, E. J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/18 ip. 94399:041.
- --7811080097 IE Inspec Rept #50-286/78-26 on 780822-24 during which 1 item of noncompliance was noted; failure to establish documented retraining prog for craft & tech personnel. BECKMAN. D. A., RUMLMAN. W. A., KISTER, H. B., Region I, Philadelphia. Rector Operations Nuclear Bupport Branch. 78/09/07. Bpp. 94399:042
- 7812010345 Forwards licenses performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormal or unusual safety concern.

  ORIEN.B H. Region 1. Philadelphia. Office of the Director.

  78/11/01. 4pp. 00002:259.
- 7811290158 Furwards IE Circular #78-18, "UL Fire Test. "H/encl ANO: 7811150002 ORIER, B H Region i, Philadelphia. Office of the Director. 78/11/06. 1p. 94238: 044.
- 7812010033 Ack receipt of 781027 itr informing NRC of steps taken to correct violations noted during inspect50-286/78-21.

  8HiTM-0.H. Region i. Philadelphia. Fuel Facility & Materials Safety Brench. 78/11/09. ip. 94416:055.

actions which have been taken in light of inspecisteps take to avoid further items of noncompliance & date when compliance will be achieved SMITH.O H. Region i. Philadelphia. Fuel Facility & Materia Bafety Branch. 70/10/05. 2pp. 94416:097.

--7812010081 Request written statement of explanation incl cor

- --TBIR010085 Responds to 780816 NRC itr & Notice of Violation & Primisable discharge concentration should be everaged over a one year period in compliance w/ET8 section 2 4 i. a. therefore they are not in violation of Tech Specs BAYNE, J. P. Power Authority of the State of New York. 78/02pp 94416 059
- --7812010089 Forwarde 1E Inspec ReptH50-286/78-21 on 780712-14 & Notice of Violation. CROCKER: H W. Region I. Philadelphia, Fuel Facility & Mater Safety Branch 78/08/16 2pp 94416-061.
- --7812010092 Notice of Violation from Inspec on 780712-14 & 24-4 Region 1. Philadelphia: Fuel Facility & Materials Safety 78/08/14 1p 94416-063
- --7812010096 IE inspec Rept#50-286/78-21 on 780712-14 & 24-28 of which 02 items of noncompliance were noted feiture to callbr liquid redwaste monitor & improper setpoint on liquid redwaste monitor THONUS, L. H., RNAPP, P. J. Region i. Philadelphia, Fuel Facil Haterials 88fety Brench. 78708/14 bpp 94416-064
- 7812130138 Forwards 1E Bulletin#78-12A, suppl to 1E Bulletin#78-W/encl AND 7811300055. GRIER.B H Region i, Philadelphia, Deelce of the Director. 78/11/24. pp. 94212.225
- 70/11/24. [p. 74212.223
- 7812130168 Forwards "Inevo Inspec NIB-1 Data Rapt & Summary "refrom summer 1978 refueling outage including a summary rept of the Steam Generator Channel Head visual & Ultrasonic inspec EARLY, P. J. Power Authority of the State of Neu York. 78/12/
- --7812130171 "Inavo Inepec Rept for Bummer 1978 Refueling Duta; insvo examination of Class 1 piping & components & Class 2 strem generator items & reactor coolant pump flywheels \* Power Authority of the State of New York. 78/09/30. 99 94294:112
- 7812260130 Forwards info re inevc inepst on steam generatore83: Tubes inepsc by sddy current method of exam Exam incl inspec for tube wail degradation on outside surface of tubes & denting at tube sheet & tube support plates.

  BAYNE, J. P. Power Authority of the State of New York. 78/12/80pp 94027-216.
- R. Periodic operating raports & related correspondence
- 7812010206 Forwards corrected copy of Chem Diecharges sheet in A01 Cert Rept Por Oct 1978. MUNTI, H.A. Consolidated Edison Co. of New York. 78/8i/15. 74409: 265.
- 78:0130180 Monthly Oper Rept for Sept 1978.
  TAGLIAMONTE, M. Power Authority of the State of New York. 79
  6pp. 94003:039.
- 7810130167 Forwards Monthly Oper Rept for Sept 1978.
  BAYNE, J.P. Power Authority of the State of New York. 78/10.
  94003:039
- 78:0200064 Forwards tabulation of dealy record of fish collect: Bept 1978 including breekdown & total weight. CAHILL.H.J. Consolidated Edison Co. of New York. 7G/10/13. 74412:171.
- 7811140106 Monthly Oper Rept for Oct 1978.
  TAQLIAMONTE, M. Power Authority of the Stato of New York. 76 6pp. 94425; 119.
- 7811140104 Forwarde Monthly Oper Rept for Oct 1978.
  BAYNE, J. P. Power Authority of the State of New York. 78/11/74425:118.

- 7811220153 Forwards tabulation of daily record of fish callections for Oct 1978 w/daily species breakdown & total weight CARILLH J Consolidated Edison Co. of New York 78/11/16 App 94074-277.
- 7812160152 Forwards data specified in Section 401 Certification for Nov 1978 MCNTI, M.A. Commonwealth Edison Co. 78/12/10 17pp. 94366-056
- 7812150237 Forwerds Monthly Open Rept for Nov 1978
  BAYE.J P Power Authority of the State of New York 78/12/11 lp
- ---7812150241 Monthly Oper Rept for Nov 1978
  ZULA-B 8 Power Authority of the State of New York 78/11/30.
  6pp 94213-268
- 7812270188 Forwards rept of fish implingment & corrective action for Nov 1978
  CAHILL, W J Consolidated Edison Co. of New York 78/12/14. Spp. 94018 037
- B Reportable occurrences. LERs & related correspondence
- 7810100098 Forward: LERW78-031/03L-0

  BAYE., JP Power Authority of the State of New York. 78/10/03 Jp
  94033, 156
- --7810100100 LER#78-031/03L-0 on 780912 failure of hot leg RTD TE-410A Manifold stop valve 361A found to be leaking borated water onto cabling 8 junction bus of RTD Leak diverted by wrapping valve w/insulating cloth/RTD cable & box rinhed. OUTSLE,F.W. Pauer Authority of the glate of New York. 78/10/02 2pp. 94033.157.
- 7810120058 Forwards LERM78-030/O3L-0 8AYNE.J.P. Pawer Authority of the State of New York. 78/10/03 1p. 74471-359
- --7810120060 LERM78-030/03L-0 on 780908: during 99% plant oper the React Oper noted RCB leakage of 2.37ppm due to packing leaks on RTD manifold hat leg isolation velves M361A & 361B for loops M31 & 32. respectively. Leak insignificant & oper continued OMSLE.F. M. Power Authority of the State of New York 78/10/03. 2pp. 94471, 360
- 7811060210 Forwards LERW78-032/03L-0.
  BAYKE-J.P. Power Authority of the State of New York 78/10/30 1p 94489:226.
- --7811060215 LER#78-032/03L-0 on 781004 water coming out of ground at N and of Turbine Bidg caused by ruptured FM-1 valve located in fire protec loap. Ruptured valve replaced & sys returned to Teth Spec limits.

  GMBLE:F. M Power Authority of the State of New York. 78/10/30. 2pp. 94489: 227.
- 7811140247 Forwards LER#78-033/03L-0 BAYNE.J P. Power Authority of the State of New York. 78/11/09. 1p. 94400:103.
- --7811140250 LERAT8-033/03L-0 on 781014: radial tilt occurred caused by injection of barit acts when the axial offset was approaching its most negative value High flux setpoint was reduced b tilt condition eliminated.

  Power Authority of the State of New York. 78/11/09. 2pp. 74400: 104.
- 7811220189 Forwards LERW78-034/03L-0.

  BAYNE.J P. Power Authority of the State of New York 78/11/17. 1p 94071:299.
- --7811220192 LERM78-034/03L-0 on 781027 at 100X pwr.on increase in plant vent radio gas was monitored, due to leakage of M31 charging pump plunger, Plunger & packing for Union Pump GX-300 Guintuples were replaced.

  GAMBLE, F. M. Power Authority of the State of New York. 78/11/17.
  2Pp. 94071:300.
- 7812220095 Forwards LER#78-037/03L-0.
  BAYNE, J.P. Power Authority of the State of New York. 78/12/18. 1p 94343:340.
- --7812220098 LERW78-037/03L-0 on 781121: While open at 100% pur in steady state.chennel 3 pressurizer level indicator(LT-461)showed pressurizer level feiling. Caused by leekage of Edwards-Rockwell blowdown valve(3/8"plobs).

  OMBLE,F, N Power Authority of the State of New York. 78/12/18.

  19. 94340: 341.

- DOCKET 50-287 GCONEE NUCLEAR STATION. UNIT 3

  E NRC Safety Evaluation Report (SER). Supple & correspondence
- 78:1020014 Supplements 7808:1 Safety Eval of subj facil Found LPBW syspiping arrangement acceptable Deletes requirement to provide spare dedicated cables for LPBW syspump motors REID.R W Operating Reactors Brench 4 (Pre 790625) 78/10/05 2pp 94351 247
- F Becurity, medical, emergency & fire protection plans
- 78:0180:26 Forwards proprietary into consisting of Changek8 to Rev#3 of subj facil security plan W/o proprietary info PARKER, U.O. Duke Power Co. 78/10/06 32pp
- 7810310008 Forwards Revision 2 of modified amended security plan (MASP) Encl withheld (ref 100FR2 790). PARKER:N D Duke Power Co 78/10/19 2pp. 9409J: 360
- 78i1210032 Summary of 78i025 meeting to discuss qual of Station Mealth Physics at subj Pacil NRC requested util to submit rev Tach Base FAIRTILE.H. Operating Reactors Brench 4 (Pre 790625). 78/11/02 28pp 94482:338
- 7812060019 Summary of a 781025 meeting re-sub; facil Station Health Physicist FAIRTUE, M. Operating Reactors Grench 4 (Pra 7906257 78/11/02 3pp 94415 330
- P. Operating license stage documents & correspondence
- 7811170029 Requests addl info in order to complete review of submittals dtd 780714 & 781006 re permanent mods to High Pressure Coolant Injection Sys at subj facil. Requests info in 20 days REID.R W Operating Reactors Branch 4 (Pre 790629). 78/10/31. 3pp 94048:182
- 7810110025 Request for all info to radiat leakage & safety problems at sub\_facils.

  OURDON-W J. Oordon, Walter J 78/09/08 ip. 94063:131
- 7810110090 Forwards "Integrated Leak Rate Test of Reactor Containment Bldg."
  PARKER N D. Duke Power Co 78/09/29. 1p. 94066 289
- --7810110092 "Integrated Leak Rate Test of Reactor Containment Bidg." ROGERG.R. DAVENPORT.B.Q. Duta Power Co 78/09/29 30pp 94066:290.
- 7810230158 Forwards check for 98300 to cover add1 lic feet for NRC review of Cycle 5 released amend for subj facil. PARKERIN 0 Duke Power Co 78/10/03 29p. 94164:260
- 7810120174 Analysis of small break LUCA dtd 780015 & the proposed mpd which requires an oper to position switches to open 2 slec-motor-open valves Actions are consistent w/staff position on this matter.

  PARKER, H. D. Duke Power Co. 78/10/06 jp. 94003.051
- 7810260149 Notification of forthcoming meeting with Duke Per Co on 781025 to discuss goals of Rediet Protec Manager. FAIRTILE.N B. Operating Reactors Branch 4 (Pre 790625). 78/10/17. 1p. 94055.336.
- 7810270072 Forwards Startup Rept for sub.; feci; 781031 PARKER.W D. Duke Power Co 78/10/17. 1p. 94059: 149.
- --TB10270076 Startup Testing Summary for 781031. Summarites the zero pur pur escalation tests, & includes comparisons of measured & predicted values of important core parameters.

  \*\* Duke fower Co 78/10/17. 15pp. 94059:150
- 7810240147 Due to inection on subj Facii 781007 proposal for Yech Epec rev to incorporate staff position for voltage monitors, the proposal is rescinded. PARKER.W.O. Duke Power Co. 78/10/19. 1p.
- 7810300182 Responds to 781010 NRC 1tr & remits fee for review of cycle 4 reload amend.
  PARKER, N. O. Dute Power Co. 78/10/20. 2pp. 94030:159.

5pp. 94488: 091.

- 7811070013 Forwards Amends 65.65 & 62 to Licenses DPR-38.DPR-47 & DPR-55, respectively, changing Tech Spece re full retad pur Cycle 3 open after core reload removal orifice rod assemblies from core & High Pressure Injection Pump oper. REID.R. W. Operating Reactors Branch 4 (Pre 790625). 78. 94036-290 78/10/23 3pp.
- --7811070055 Amend#65 to Facil Oper Lic#DPR-38 changing Tsch 8pecs.
  REID.R W Operating Reactors Branch 4 (Pre 790625). 78/10/23. 2pp. 94036: 293
- ~~78:1070057 Amend#65 to Facil Oper LickDPR~47, changing Tach Specs.

  REID.R.W Operating Reactors Branch 4 (Pre 770625). 78/10/23
  2pp. 94036 293
- --7811070060 Amond#62 to Facil Oper LickDPR-93, changing fach Space REIO.R H. Operating Reactors Branch 4 (Pre 790623). 78/10/23. 25pp. 94036: 297
- --7811070063 Exempts subj facil from 10CFR50 46(a)re ranctor cooling until mod is complete or until next refueling shutdoun. STELLO.V. Division of Operating Reactors. 78/10/23. 8pp. 94036-322.
- --78:1070068 BaPaty evaluation & EIA supporting Amend 65 to Lic DPR-38, Amend 65 to Lic DPI-47 & Amend 62 to Lic DPR-55. Concludes that it is acceptable for Cycle 5 open to proceed & that EIA not req • Office of Nuclear Reactor Regulation, Director. 78/10/23 19pp. 94036.330.
- --7811070071 Notice of lesuance of Amend#45 & 62 to Facil Oper LickDPR-38. DPR-47 & DPR-55, respectively, rev Tech Spece to support full rated pur oper during Cycls 5 after core relaed adding High Pressure Injection Pump reqs & fuel demonstration prog. REID.R. W. Operating Reactors Branch 4 (Pre 790623). 78/10/23. 2pp 94036:349.
- 781:170324 Notice of Issuance of Amend#62 & 65 to Oper LiceDPR-38.47 & 55 Amend rov Tech Specs allowing full rated per during Cycls 5 after core reload & permits use of 5 previously burned fuel assemblies. . REID.R. W. Operating Reactors Branch 4 (Prs 790625), 78/10/23. 2pp. 02766:243.
- 7811020255 Natice of rev to Tech Spec 3.7 re Auxiliary Elsc Sys. Spec 3.7.1 is rev to clearly define chaits smargancy transmission paths in 12500C Instr Control Sys.& rev 3.7.2 rs elsc sys degraded mode oper. PARKER, H. O. Duke Power Co. 78/10/31. App. 94247: 138.
- 7811140114 Responds to 781031 request for add1 info ra mod of high pressure injection eye.epacifically.sms11 brssk ECC8 mod. PARKER.N.O. Duks Power Co. 78/11/06. 4pp. 94405:155.
- 78:11:60065 Confirms conversations or 780705 proposed open lic change of possible receipt of 4 fuel essemblies from FL Pur Corp. Requests withdrawel of proposed lic amend & indemnity agreement(8-44) & refund of lic fes.
  PARKER.W.O. Duke Power Co. 78/11/07. 1p. 94133:121.
- 7811160079 Rescinde 780523 request for NRC concurrence re proposed change to respiratory protec sys.
  PARKER, U.O. Duke Power Co. 78/11/07, ip. 94133, 175.
- 78:1160134 Responds to 78:01: NAC comments on minimum quelifications of station Health Physicist Considers requirements in ANBI/ANS-3, [-1978 to be appropriats. PARKER, N. O. Duke Power Co. 78/11/07. Ip. 94135: 235.
- 78:1270118 Forwards 3 previously omitted Tech Spsc pages (2.3-1, 2.3-3 & 2.3-illfor Lic Amendéd. 63 & 62. covering limiting safety sys sattings & protect instru.

  REID.R.M. Operating Resectors Branch 4 (Prs 790625), 78/11/08. Spp. 94271:266.
- 7811200421 Forwards results of measurements of radioactive matl in NRC phantom on whole body counter. Encl i contains actual amount of each radioauclide present encl 2 gives retio of measurements to DOE values & encl 3 gives recommendations.

  SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 78/11/09. Spp. 94419:175.
- 7811210278 Notifies util of 781205 seminer in Atlanta to discuss new Model Rod Effluent Tech Spess & encl seminer info sheet, registration form: & proposed agenda. O'REILLY,J.P. Region 2. Atlanta, Office of the Director. 78/11/09. 5pp. 94488: 126.

- 7811210306 Notifies util of 781205 seminar in Atlante to discuss new Mode) Rod Effluent Tech Speca & encl seminar info sheet, registration form. & proposed agenda.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09.
- 78:1300035 Forwards NRC staff paper.Policy Session Item(SECY-78-554) rs licenses reg performance evalution. Three methods for evaluation are: statistical, trend analysis & regions; survey
- msthod.H/o enct.
  O'REILLY-J.P. Region 2, Atlanta, Office of the Diractor. 78/11/15.
  2pp. 94070:351.
- 7812150123 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendars to facilitate sending out mati. Myenci Registration form & List of Location. MILLER, J.R. Assistant Director for Bits & Bafeguards (Pre 791030). 78/11/15. Opp.
- 7812190031 Forwards Rev#1 "Draft Rediclogical Effluent Tech Specs" for PHR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133), M/o encl ANO: 7811270173 & 781127018.

  ORIMES-B.K. Assistant Director for Engineers & Projects (Pra 790623). 78/11/15. 6pp. 94214:333.
- 7811300379 Informs DPC that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations Studies will analyss socioecon impacts which occurred during constr & post-constr psriods of sach plant. DEYOUNG, R. C. Division of Sits Bafaty & Environments! Analysis. 78/11/20. 2pp. 94136:252.
- 7812060260 Response to 780705 ltr requesting exemptions from certain reg of WiOCFR Part 21. Rule amended 781019 & provided relief Paquested. DENTON. H. R. Offics of Nuclear Reactor Regulation, Director. 78/11/24. 2pp. 94371:337.
- --7818060272 Requests examption from 10CFR21 ra procurement of various standard etock items from Cutler Hammer, Inc. Procurement delays will affect constructed.
  PARKER, M. O. Duke Power Co. 78/09/05. 3pp. 94371:339.
- 7812040147 Forwards updated replecement for 780216 copy of steam generator oper history. Includes all activities thru June 1978 refueling & ineyoc.
  PARKER.W. D. Dute Power Co. 78/11/28. 13pp. 94456:098.
- 7812150083 Discusses possible dangers of LDCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing. W/ancl AND: 7818080207. EID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp-94210:330. REID, R. W
- 78:2:80:31 Expects that mod of high pressure injection sys at subj facils can be implemented for each unit during first available outage of sched duration sufficient to install
- PARKER, H. O. Duks Power Co. 78/12/04. 1p. 94364: 278.
- 7819280173 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. Spp. 94075:015.
- 7812260001 Accapts proposed design mod to High Pressurs Injection (HPI) sys consisting of installing cross-current lines between discharge lines of HPI sys.W/Bafsty Eval. LAINMS-0. Plant Systems Branch (Pre 791030). 78/12/07. 6p. 94020:271.
- 7812260062 Forwards Safety Eval Rept for subj facil re mod to high pressure injection eye. REID.R.H. Dereting Reactors Branch 4 (Prs 790625). 78/12/13. Esp. 94021:271.
- --7812260064 BER "Mod to High Pressure Injection Sys. "Concludes sesign mod to HPIS will ensure that for all postulated single failure conditions. HPIS will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths. # Operating Reactors Branch 4 (Prs 790625). 78/12/13. App. 94021: 273.

- --7812280247 Lic#DPR-38. DPR-47. & DPR-55 for Amends 66. 66. & 63: Tech Specs proposed changes re control rod operability & support of United full rated pur during Cycle 4 after core reload & removal of orifice rod assemblies from core REID.R W. Operating Reactors Granch 4 (Pre 790625). 78. Operating Reactors Granch 4 (Pre 790525). 70/12/10 94355: 261
- --7812280264 SER supporting Amend 66 to DPR-3B, Amend 66 to DPR-47.& Amend 63 to DPR-55 Concludes that proposed Tech Spec changes do not involve a significant hezard health or safety consideration. Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp. 94355: 206
- --7812280267 Notice of Issuance of Amend 66 to DPR-38, Amend 66 to DPR-47.

  & Amend 63 to DPR-55 revising common Tech Bases to support
  the oper of Unit#2 full rated pur during Cycle 4.
  2187710, 9 8. Operating Reactors Branch 4 (Pre 790625). 78/12/15.
- 7813270244 Forwards proposed rev to subj facil Tech Specs Proposed exception 3 3.6(f).would allow inoperability of one Reactor Bidg Spray Pump for up to 72 hours provided all Reactor Bidg Cooling Units are operable Wattach affidavit.
  PARKER, N. D. Dute Power Co. 78/12/22 App. 94017.155.
- Q. Inspection reports. IE Bulletine & correspondence
- 7811100103 Ack receipt of 781016 Itr Informing NRC of steps taken to correct violations noted during inspec#50-269/78-18. #50-2270/78-19 & #50-287/78-19. KENNA. W.B. Region 2. Atlanta. Safeguards Branch. 78/10/26 1p. 94173: 356
- --7811100110 States info contained in 781016 ftr is proprietary pursuant to Section 2.790 & is to be withheld.

  PARKER, H. O. Duke Power Co. 78/10/16. ip. 94173:357.
- --7811100115 Responds to 780919 NRC 1tr re violation noted in Inspec Reptem50-269/78-18,450-270/78-18 & #50-287/78-19. Corrective action withheld (ref 10CFR2.790). PARKER, H. D. Duke Power Co. 78/10/06. 1p. 94173: 358.
- -7811100124 Forwards summary of 1E Inspec ReptsM50-269/78-18, #50-270/78-18 & #50-287/78-19 on 780815-17 Notice of Violation withheld pursuant to 2.790. KENNA.W. C. Region 2, Atlanta, Office of the Director, 78/09/19. 2pp. 94173:359.
- --7811100130 IE Inspet Repts#50-269/78-18,#50-270/78-18 & #50-287/78-19 on 780815-17 during which I item of noncompliance was noted; testing of alarms. BEBECKER.K.H., OILLEBPIE.F.P. Region Director. 78/09/18. 1p. 94173:361. Region 2. Atlanta, Office of the
- 7810130056 Atk receipt of IE lnsp Repts 50-269/78-17.50-270/78-17 & 50-297/78-18 on 760607. No proprietary info. PARKER.W. O. Duts Power Co. 78/09/27. 1p. 94079:185.
- --7810130060 Forwards IE Insp Rept 50-269/78-17.50-270/78-17 & 50-287/78-17 on 780807. No noncompliance noted. SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Barety Branch, 78/09/20. 2pp. 94079:186.
- --7810130064 IE Insp Repts 30-269/78-17, 50-270/78-17 & 30-287/78-18 on 780807, No noncompliance noted Major areas inspected: whole body counting practices & test count of NRC phantom. OIBBON A. F. Region 2, Atlanta, Fuel Facility & Meteriele Bafety Branch. 78/09/20. 4pp. 94079:18B.
- 78:10:30:221 States that prog has been established to address IE Circular 7B-08 Review of adequacy of qualifications of each piece of equip will be completed by 79:0416.
  PARKER, N. D. Duke Power Co. 78:709/29. ip. 02724:250.
- 7810230287 Forwards IE Circuler#78-17, [8ee ANO: 7810230221, Docket 50-313, 781 013) 0'REILLY, J. P. 1p. 74145: 005. Region 2, Atlanta, Office of the Director, 78/10/13.
- 7811150085 Forwards IE Circular 78-18. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/06.

- #50-287/78-23 on 780918-22 during which no items of noncompliance were noted
  - LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/10/18. 2pp. 94397:232.
- --7811280398 IE Inspec Repts#50-249/78-22.#50-270/78-22 t #50-287/78-23 on 780918-22 during which no items of noncompliance were noted. Major areas inspected included: unresolved items. special repta.action on IEC 78-08. LEMIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/18. App. 94397:254.
- 7612120033 Forwards reproductions of articles that a peared in June & Aug 1978 editions of Nuc Security Bafeguards Newsletter.
  KENNA.M. G. Region 2. Atlanto. Bafeguards Branch 78/11/17. 4pp 94278:072
- 7812050021 Ack receipt of 781120 itr informing NRC of steps taken to correct violations noted during inspecs#90-269/78-19. #50-270/78-15 & #50-207/78-16 BUTHERLAND, J T. Region 2. Atlanta, Fuel Facility & Materials Safety Brench. 78/11/20. 1p. 94200:270
- --7812030025 Responds to 780929 NRC Itr re violations noted in Inspec Repts#50-269/78-15,#30-270/78-15 & #50-287/78-15. Corrective actions: entrances to interim weste facil posted w/radist signs & spent fuel cask rebolted & retorqued for shipment PARKER,H. D. Duke Pawer Co. 78/10/25. 4pp 94200:271.
- --7812050029 Forwards IE Inspec Repts#50-267/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 & Notice of Violation Violation O'REILLY.J.P. Region 2. Atlanta, Office of the Director. 78/09/29, 2pp. 94200:275.
- --7812050030 Notice of Violation from Inspec on 780726-28 & 780901-04, \* Region 2, Atlente, Office of the Director. 78/09/29. 1p.
- --7812050031 IE inspec Repts450-269/78-15.450-270/78-15 & 450-287/78-16 on 780726-28 & 780801-04 during which 2 items of noncompliance were noted: failure to properly pack cast for shipment & to perform radiat surveys in interim wests bidg. HOSEY, C. M., JENKINB, Q. R., OIBSON, A. F. Region 2, Atlanta, Fuel Facility & Materials Safaty Branch. 78/09/28, 11pp. 94200:278.
- 7812040326 Ack receipt of 781106 itr informing NRC of steps taken to correct violetions noted during inspec450-269/78-20. #50-270/78-20, #50-287/78-21. BUTHERLAND. J. T. Region 2. Atlants, Fuel Facility & Majerials Safety Branch. 78/11/22. 1p. 94130:353
- --7812040328 Responds to 781018 NRC itr re violations noted in inspec Repts#50-269/78-20,#50-270/78-20,#50-287/78-21 Corrective actions: door lock mod to prevent unlocking w/o key. PARKER, W. Q. Duke Power Co. 78/11/06. 2pp. 94130: 354.
- --7812040332 Forwards IE Inspec Repts#50-269/78-20:#50-270/78-20:#50-287 78-21 & Notice of Violation. SUTHERLAND.J.T. Region 2, Atlanta, Fuel Factlity & Heteriele Befety Branch. 78/10/10. 2pp. 94130-336.
- --7812040335 Notice of Violation from Inspec on 760911-15. \* Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/10/18. 1p. 94130:358.
- --7912040339 IE Inspec Repts#50-269/78-20.#50-270/78-20.#50-287/78-21 or 780911-15 during which I item of noncompliance was noted: failure to keep entrance to high radiat area locked HOGEV.C.M. QIBSON.A.F. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/10/18. App. 94130: 359.
- 7812040363 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-12. W/encl AND: 7811300055. O'REILLY,J.P. Region 2. Atlants. Office of the Director. 78/11/24. 1p. 94127-166.
- 7812070317 Ack receipt of 1E Inep Repts 50-269/78-21 & 50-287/78-22 an on 780919-21. Does not consider any info therein to be proprietary.

  PARKER: H. O. Duke Power Co. 78/11/88. ip. 94084: 339.

- --7812070319 Forwards IE Insp Repts 50-269/78-21 & 50-287/78-22 on 780919-21 during which no items of noncompliance were noted MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch 78/11/02. 2pp 94084:340.
- --7812070320 IE Inap Repts 30-269/78-21 & 50-287-22 on 780919-21 during which no items of noncompliance were noted Major areas inspected incl. Corrective action on previously identified infraction #8237/70-14-01.
  CDNLDN-T.E., ECONOMOB, N. Region 2. Atlanta. Reactor Construction & Engineering Guppart Branch 78/11/01. 7pp 94084:342.
- 7812130306 Act receipt of iE Inspec Repts#50-269/78-26,#50-270/78-25 & #50-287/78-26 on 781023-27 Does not consider any info therein to be proprietary PARKELM, O Duke Power Co. 78/12/05. ip 94159-278
- --7812130311 Forwards IE Inspec Repts#30-269/78-26, #50-270/78-25 & #50-287/78-26 bn 781023-27 during which no items of noncompliance were noted.

  LDNO.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 78/11/21 2pp. 94139 279.
- --7812130317 IE Inspec ReptsM50-269/78-26.850-270/78-25 & #50-287/78-26 on 781023-27 during which no itsms of noncompliance were noted. He por erms inspected inclination of past flow.pur & pur distrib enomalies.

  BURNETT.P T. Region 2. Atlanta. Diffice of the Director. JULIAN.C A. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. BETTERMAUSEN.L Region 1. Philadelphia. Office of the Director 78/11/20. 3pp. 94159.281.
- 7812140041 Act receipt of IE Ineper Repts#50-269/78-29, #50-270/78-21 & #50-287/78-29 on 781106-08. Does not consider any info to be proprietary.
  PARKER, U. O. Dute Power Co. 78/12/05. 1p. 94127-267.
- --7812140046 Forwards iE Inspec Repts#30-269/78-29, #50-270/78-21 & #50-227/78-29 un 781106-08 during which no items of moncompilance were noted.
  LCNO.F. J. Region 2, Atlanta, Reactor Operatione Nuclear Bupport Branch, 78/11/22, 2pp. 94127:268
- --7812140048 IE Inepec Repts#90-269/78-29,#50-270/78-21 & #50-287/78-29 on 781104-08 during which no items of noncompliance were noted Major areas inspected inclipient oper & restoration of sys following refueling outage.

  JAPE.F., LEWIS.R.C. Region 2, Atlante, Reactor Operations Nuclear Bupport Branch. 78/11/22 App. 94127: 270.
- 7812140053 Ack receipt of 1E inspec Repts#50-267/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 Dose not consider any info therain to be proprietary. PARKELM. 0. Duke Power Co. 78/12/05. ip. 94126:330.
- --7812140053 Forwards 1E Inspec Repts#50-269/78-24.#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 during which no items of noncomplience were noted.

  KENNA, W B. Region 2, Atlanta, Bafeguards Branch. 78/11/29. 2pp. 94126.331.
- --7812140039 1E inspec Repts%30-269/78-24, w30-270/78-23 & w30-287/78-24 on 781017-20 & i101-03 during which no items of noncompilence were noted Hejor areas inspected incl:facil organization. shipping & receiving & storage. HCDOE9. J. M., CLAY. E. L., WILLIAMS. O. H., Replon 2, Atlanta, Bafeguards Branch 78/11/24, 4pp. 94126:333.
- 7812270092 Forwards IE Bulletin 78-14.

  O'REILLY, J. P. Region 2, Atlenta, Office of the Director. 78/12/19.

  2pp. 03695:189.
- R. Periodic operating reports & related correspondence
- 7810200082 Forwards Monthly Oper Rept for Bept 1978 PARKER, M. O. Duke Power Co. 78/10/16. 1p. 94366:343.
- --7810200083 Monthly Open Rept for Sept 1978. REAVIS. J. E. Duke Power Co. 78/10/16. 16pp. 94366:344.
- 7810240002 Forwards Quarterly 780601-780831 rept on Jocassee Area Seismic Activity. PARKER, M. D. Duke Power Co. 78/10/16. ip.
- --7810240077 Guarterly Beismic Activity Rept, (6-1-78 to 8-31-78). Decreased Beismicity in Jocasses area represents diminishing size and no. of joints at greater depths. TALMANI, P., BIEVENSON, D., BAUSER, J. Bouth Caroline, Univ., of. 78/10/16. 197p.

- 7812210137 Forwards Monthly Oper Rept for Nov 1978. PARKER, H. O. Dute Power Co. 78/12/15. 1p. 94278: 185.
- --7812210160 Monthly Oper Rept For Nov 1978. REAVIS. J. Dute Power Co. 78/12/15 16pp. 94278-186.
- 8. Reportable occurrances. LERs & related correspondence
- 7812130169 Forwards LERM78-014/03L-0.
  PARKER, M. O. Dube Power Co. 78/12/07 ip. 94294:352.
- 7812190153 Forwards LERW78-015/03L-0.
  PARKER, M. D. Duke Power Co. 78/12/08. ip. 94340:158
- --7812170156 LER878-015/03L-0 on 780731:RPB Channel A.RC flow indication began reading high on 780729 & was valued out-of-avc on 780731 caused by leek in pressure transmitter impulse line. Leaking fittings were repaired.

  WILBON, X. R. Duta Power Co. 78/12/08 2pp. 94340:159.
- 7812290209 Forwards LERM78-016/03L-0.
  PARKER-W. D. Duke Power Co. 78/12/22. 1p. 94190:344.
- ---7812290214 RGM287/78-16 on 781123:EB Channel A Wide-range pressure indication drifted high & was manually tripped-dus to excessive moisture in penetration caused by lasking roof.

  \* Duke Powar Co. 78/12/22 2pp. 94190:345.
- --781229021B LER#78-016/03L-0 on 781123:EB Channel A wide-rangs pressure indication drifted high & was manually tripped due to excessive moisture in penetration caused by iesting roof. MILBON.K. R. Duse Power Co. 78/12/22
- DOCKET BO-288 REED COLLEGE REBEARCH REACTOR

  O. Inspection reports. IE Builetins & correspondence
- 7811060007 Forwards IE Inspec Rapt#50-288/78-03 on 78091i-13 during which no items of noncompilance were noted.

  800K.H.E. Region 5. Ben Francisco. Fuel Facility & Materials Befory Branch. 78/09/29. 2pp. 94422:211.
- --78:1060008 IE inspec Rept#80-288/78-03 on 780911-13 during which no itses of noncompliance were noted. Major areas inspec incl: radiat control. anviron monitoring & emergency planning. 800K-H. E., 8410p. J. B. Region 5, 8en Francisco, Fuel Facility & Meterials Bafety Branch. 78/09/29. 6pp. 94422:213.
- DOCKET 30-289 THREE MILE ISLAND NUCLEAR STATION, UNIT I
- F. Bacurity, medical, emergency & Pira protection plane
- 7810300137 Forwards fire svc water piping drawing for THI-i. Drawing available in Central Files only.
  HERBEIN.J. Q. Metropolitan Edison Co. 78/10/24. 1p. 94195:317.
- 7811070135 Notification of implementation of amoking prohibition in sefety-related areas of facility. Hose reals to be installed per 780612 itr & Item 3.1.2 of fire protection sefety availation in order to suppress relay roum cable tray fires. HERBEIN J. D. Metropolitan Edison Co. 78/10/31. ip. 94195:335.
- 7811070101 Forwards summary of fire loading for subj facility to satisfy Item 3.2.9 of fire protection safety evaluation rept.

  MERBEIN.J. O. Metropolitan Edison Co. 78/11/01. 14pp. 94195:321.
- 7811080204 Forwards table identifying fire hazard enalysis of fire doors which will be electrically locked & alarmed by 790215, those machanically locked closed when not in use, & those not unlocked or alarmed but kept closed when not in use, MERREIN.J. 0. Metropolitan Edison Co. 78/11/01. 3pp. 94198:339.
- 7811270155 Forwards Revision 4 to physical security plan Withhold (ref. 10CFR2, 790).
  MERBEIN.J. O. Metropolitan Edison Co. 78/11/17. 1p. 94253.352.
- 7812060168 Responds to 780919 fire protection safety evaluation raps.
  Documentation saarch completed re fire rating of TMI-1 fire
  doors. Porwards fire hazards analysis drawlings.
  HERMEIN.J. O. Metropolitan Edison Co. 78/12/01. 5pp. 94270:252.

- 7812190113 Responds to NRC 780817 ltr re fire protection program. No further elice protection messures needed in cable routs area between fuel pool & control bidg to ensure safe shutdown. HEREIN J. G. Kstropolitan Edison Co. 78/12/13. 6pp 94137: 331.
- H General correspondence
- 7810230199 Informs that 780830 Tech Spec Change Request 77 re-ring sirder surveillance test is subj to Class II amend fee. HILLER-H. D. License Fee Hanegement Branch. 78/10/11. ip. 94199-316
- 7810300148 Appointment of new licensing mgr for GPU Svc Corp.

  MALLACE.E. G. General Public Utilities GPU Service Corp. 78/10/23.

  1p. 94035:115.
- --78(000133 Informs of appointment of new licensing menager for General Public Utilities Buc Corp. WALACE, M. V. General Public Utilities OPU Bervice Corp. 78/10/23. ip. 94033:116.
- 7812110248 Requeste payment of Claes II fee for 780830 application re ring girder survsillance test. Amend classified by NRC 781011 ltr as Class II. MILLER.M. D. License Fee Management Brench. 78/11/89. ip. 94192:352.
- 7812080212 Ack receipt of 780823 application for amend to DPR-80 & fee payment. Finds action is Class III & requests payment of addless.
  MILLER.H.O. License Fee Menagement Branch. 78/11/30. ip. 94193.340.
- 7812280161 Emphasizes importance of submitting occurate & complete info to NRC. Info must be substantiated by data. NRC must be notified of inecuracise to evoid enforcement action. DAVIS.J.Q. Optice of Inspection & Enforcement. Office of the Director. 78/19/06. 2pp. 94311:350.
- 7812120092 Advises that Generation Licensing Section (Production Supervision) moved back to Pottsville Pike location on 781213. Forwards new telephone numbers.
  HERBEIN J. O. Metropolitan Edison Co. 78/12/12. ip. 94274: 204.
- P. Operating license etage documents & correspondence
- 78:03:049 Forwards hose stretch test results & recommendations Firsh hose reels will be added to room w/decay heat ave coolers at all elevations except 306 ft elevation of control room bldg & reactor bldg.

  HEREIN J. G. Metropoliten Edison Co. 78/10/05. 3pp. 94:137:322.
- 7811020228 Requests add1 info re consequences of creme failures when handling heavy loads in order to complete review for fecfility. Also requests submittel within 45 days of amend to Tech Spec Change Request 38.
  REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/16. 3pp. 74195:318.
- 78:0240:19 Forwards NPDES Noncompliance Notification 78-22 rewests filter sys discharge sample with pM in excess of peratt limitation. TROFFER.O.J. Matropolitan Edison Co. 78/10/17. 2pp. 00001:235.
- 7811010246 Notification of 781026 meeting w/util re aircraft crash data for THI-2.
  BILVER.H. Light Water Reactors Branch 4. 78/10/19. ip. 00001:251.
- 781:140:03 Advises of discharge of 1,100 gellons of weter which bypessed industrial weste treatment sys. Caused by increase in flow to facility tubine bldg sump. TROFFER.9. J. Metropolitan Edison Co. 78/11/03. 2pp.
- 781:160143 Forwards NPDEB Noncompliance Notification 78-23:on 781026, sample from industrial wests filter ays discharge had pH of 9.4. Caused by rise of pH during test while pH monitors were malfunctioning.

  TROFFER. O. J. Netropolitan Edison Co. 78/11/06. 2pp. 94271:008.
- 78:1280389 Forwards request for add1 info re 780313 application to asend DRR-50 by increasing frequency for checking calibracturects of power range nuclear instrumentation.
  REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/06. 3pp. 94137:319.

- 78:2150109 Notification of workshops for training & qualification of personnel per 10CFR73.App B Requests advence registration of attenders Registration form & list of locations encl.
  MILLER.U.R Assistant Director for Site & Sefeguerds (Pro 791030).
  78/11/15 5pp.
- 7812190099 Forwards NUREO-0473, Revision 1. 'Draft Radiological Effluent Tech Space for PMRs" & NUREO-0133. "Preparation of Radiological Effluent Tech Opeca for Nuclear Power Plants." W/o encl. GRIMEB.D.K. Assistant Director for Engineers & Projects (Pre 790429). 78/11/15 dop. 94137 325.
- 7811290343 Natification of 781122 meeting w/util to discuss proposed mode to sliminate need for prompt action in responding to small break LDCA worst single feliume.
  ZMETTIG.0.8. Operating Reactors Branch 4 (Pre 790625) 78/11/17. 2pp 94193:331
- 7811300037 Informs that NRC has contracted to undertake a series of post-licensing studies to enalyze socioeconomic impacts of nuclear plant const.
  DEYCUNO.R C Division of Site Safety & Environmental Analysis.
  78/11/20. 2pp. 00002:234.
- 7811240110 Forwards proposed small breek LDCA lpng-term cod. NRC 780926 ltr did not respond to 780924 util proposel & util belisves proposel meets NRC requirements HERBEIN.J. Q. Hetropolitan Edison Co 78/11/21. 6pp. 94496. 275
- 7811280243 Informs NRC that Met Ed will implement 879 for TMJ-1 midcycle instead of at end of 1979 refueling outage. Lists reasons, advantages & disadvantages HERDEIN.J. Q. Metropolitan Edison Co. 70/11/21. 2pp 94137: 317.
- 7812070194 Notice of seminar on 781208 on new model redicingical efficient Tach Opeca for nuclear plants Requests advance submitesion of seminar-specific questions ORIER, B.H. Region i. Philadelphie. Diffice of the Director 78/11/21. Opp. 94375:069.
- 7BIRI80045 Forwards Amend 46 to DPR-50.safety evaluation & notice of [sevance. REID.R.H. Dperating Reactors Branch 4 (Pre 790625) 78/11/22 2pp 74271:023.
- --7812180047 Amend 46 to DPR-80. revising Tech Spece by increasing frequency at which heat balance checks are performed to verify colibr of power range nuclear instrumentation REID.R.W. Opereting Reactors Branch 4 (Pre 790625), 78/11/92, 7pp. 94133:056.
- --7812180049 Safaty evaluation supporting Amend 45 to DPR-50.

  \* Dffice of Nuclear Reactor Regulation, Director. 78/11/22, Epp. 94133:043.
- --7812180051 Notice of issuence of Amend 46 to DPR-80. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/92. 2pp. 94133:068.
- 7812150097 Discusses possible dangers of LOCA in containment purging during normal pient operation. Requests either commitment but limit or justification for continuing purging forwards SRP Bection 6.2.4: Ravision i.re containment purging. REID.R.H. Operating Reactors Branch 4 (Pre 7906R5), 78/11/29. Spp. 94270:278.
- 7812030098 Responds to NRC 781016 itr re consequences of crens failures when handling heavy loads. Based on anguers to NRC questions no amend to Tech Base Change Request 38 considered necessary.

  HERBEIN.J. Ø. Metropolitan Edison Co. 78/12/01. 3pp. 94270: 246.
- 7812060161 Responds to NRC 781011 ltr & contends that Tech Spec Change Request 77 clearly simplifies facility Tech Specs. No further review by NRC of ring girder insp program required. HERBEIN.J. Q. Metropolitan Edison Co. 78/18/01. Qpp. 94970: Q49,
- 7812080090 Forwards Tech Blac Change Request 85 to DPR-50 to deletion of enubbers from Table 3.16.1.Certificate of 8vc & Class II amend fee encl.
  HERBEINJ. 0, Matropolitan Edison Co. 78/12/04. 13pp. 94270: P40.
- 7812180281 Responds to 781121 ltr & requests addl info ro achedule for implementing mod to eliminate relience of facility on operator action following small break LOCA.

- 7812280049 Summary of 781122 meeting w/util in Betheads.HD re-util revised proposed mod to sliminate relience on apprator action following small break LOCA List of attendees & proposed mechanical mods entl.
  2WETZIO.0. B. Operating Reactors Brench 4 (Pre 790625). 78/12/12.10pp 00008:042
- 7812290129 Forwards NPDES Noncompliance Notification 78-25. TRDFFER.Q. J. Metropolitan Edison Co. 78/12/19. 2pp.
- 7812290086 Forwards responses to NRC 781208 itr re installation of long-term solution to small break LOCA problem Prodent time for Installing mod is during 1980 TMI-1 refueling outage. HERDEIN, J. G. Metropolitan Edison Co. 78/12/21. 3pp.
- Q. Inspaction reports, IE Bulletins & correspondence
- 7810160250 Forwards IE Bulletin 78-12, "Atupical Weld Metl in Reactur Pressure Vessel Welds." Licenses action required. M/o encl. GRIER. B.H. Region i. Philadelphia. Dffics of the Director. 78/09/29. 6pp. 94471:302.
- 7810200228 Natification of meeting on 781012-13 w/Mst Ed re TMI-1 inastrolce insp program per 10CFR50.55a(g) & to discuss 14censes submitted & responses to questions. ZWETZIQ.Q.B. Operating Reactors Branch 4 (Pre 790625). 78/10/05.20p
- 7810230196 Notification of meeting w/Met Ed, rescheduled for 781018-19, to discuss TMI-1 inservice inep program per 10CFR50. 55a(g) & to discuss licenses submittel & responses to questions. ZWETZ10.0.0. Deprating Reactors Branch 4 (Pre 790625). 78/10/05. ip. 94137:314.
- 7811040186 Forwards IE Circular 78-17.470 encl.
  GRIER, B.H. Region 1. Philadelphia, Office of the Director.
  78/10/19. 1p. 00001:265.
- 7812010345 Forwards licenses performence evaluation for Region i.No operating reactor in Region 1 considered to have either abnormed or unusual safety contern. GRIER, 8. H. Region i. Philadaiphia, Office of the Director. 78/11/01. 4pp. 00002:259.
- 7811290199 Forwards IE Circular 78-18, "UL Fire Test." ORIER, S.H. Ragion 1, Philadaiphia, Office of the Director. 70/11/06. 1p. 00002:226.
- 7812010000 Repts on status of raviaw of 770817 & 770930 aubmittals reinservice insp & testing. Forwards raquest for add1 info & minutes of 781018-19 meatings. Requests raply within 14 days. REID. R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/20. 1209. 94271: 011.
- 7812010140 Bummary of 781018 & 17 mesting re 770817 & 0930 licanses submittals on inservice insp & testing of pumps valvaes component prassure bounder(es.conflicts between code & safety requirements & concerning pressure isolation valvas. ZWETZ19, 0. B. Operating Reactors Branch 4 (Pre 790625). 78/11/20. 7pp. 74195:333.
- 7812270047 Forwards 12 Insp Rept 30-289/78-18 & 50-320/78-31 on 781006, 10-12 & 17-19 & notice of violation.

  SHITH, G.H. Region 1, Philadelphia, Fuel Facility & Materiale Befory Branch, 78/11/21, 3pp. 00007:362.
- --7812270051 Natica of violation from insp on 781006:10-12 & 17-19.

  \* Region 1: Philadelphia: Office of the Director. 78/11/21. 2pp. 00007;002.
- --78:2270057 IE Insp Rept 50-289/78-18 & 50-320/78-31 on 78:006.10-12 & 17-19. Noncompliance noted: feiture to barriceds high radiation area or maintain records of affluent eampling. PLUMLEE, K. E., SERABIAN, J. A. Region 1, Philadelphia, Office of the Director. 78/11/15. 12pp. 00008:004.
- 7812150144 Forwards 16 Bulletin 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds."
  ORIER, B.H. Region 1, Philadelphia, Office of the Director, 78/11/24, 1p. 94212:202.
- 7812200171 Forwards answers to NRC 781120 questions re inservice insp t testing program Prepering revision program submitted util 770817 & 0930 HERBEIN.J. Q. Metropolitan Edison Co. 78/12/13. 17pp. 94271:025.

- R. Periodic operating reports & related correspondence
- 7811210184 Forwards monthly operating rept for Oct 1978.
  HERBEIN, J. O. Metropolitan Edison Co. 78/11/15. ip 94488.077.
- --7811210185 Monthly operating rept for Oct 1978. HITCHELL.D.O. Metropolitan Edison Co 78/11/09. 5pp. 94488-078.
- 7612190166 Forwards monthly operating rept for Nov 1978. HERBEIN.J. G. Metropolitan Edison Co. 78/12/13 1p. 94137:337.
- --7812190170 Monthly operating rept for Nov 1978. MITCHELL, D. O. Metropolitan Edison Co. 78/12/13. 4pp. 94137:338
- B. Reportable occurrences, LERs & related correspondence
- 7810100090 Forwards LER 78-029/01T-0. HERDEIN, J. Q. Metropolitan Edison Co. 78/09/28. ip. 94271:007.
- --7010100099 LER 78-029/017-0: on 780914, temp sensor for A emergency diesel generating room found to be inoperable & fire watch not established within i-h. Caused by personnel arror. Procedural guidance will prevent recurrence.

  MITCHELL, D. O. Matropolitan Edison Co. 78/09/28. 2pp. 94033.170.
- 7810310184 Forwards LER 78-30/03L-0.
  HERBEIN, J. O. Metropolitan Edison Co. 78/10/20 ipp. 94137-315.
- --7810310192 LER 78-30/03L-0: on 780923, borated water found in heater terminal box due to cladding rupture Caused by hot spot from evaporator tank crud buildup.
  BTANLEY, M. 8. Hetropolitan Edison Co. 78/10/20. ip. 94137: 316.
- 7811070191 Forwards LER 78-027/01T-0.W/o encl. HERBEIN, J. Q. Matropolitan Edison Co. 78/10/27. 1p. 94195:336
- 7B12110146 RO 7B-31/4P:rivar water temp change axcaadad Tech Speciamita.Causad by low inlet temp & high ambiant tamp & raistive humidity, resulting in inability of machanical draft cooling towers to cool discharge water properly.

  BEELINGER, J. L. Metropolitan Edison Co. 78/12/05, 1p. 94195:351.
- 7812260191 Forwards LER 78-031/04T-0. HERBEIN, J. O. Metropolitan Edison Co. 78/12/15. 1p. 94270:344.
- --7812260194 LER 78-031/04T-0: on 781204, station river water discharge delta temp limit of 12 F was acceeded by 2 F. Ceused by heating of station river discharge by mechanical draft cooling towars.

  NIELGEN, E. 8. Matropolitan Edison Co. 78/12/15. 2pp. 94159:161.
- V. Operator Examinations
- 7811130145 Forwards applications for senior operator licenses for JB Logen, CE Hartman, RW Zechman, HB Shipman & ED Hemmile. MILLER, Q. P. Metropolitan Edison Co. 78/09/14. 2pp.
- DOCKET 50-290 PROOF TEST FACILITY

  F. Sacurity, madical, emergency & fire protection plans
- 7810310076 Forwards ray to copies 6 thru iO of sub; facil security plan dtd 780926, Rays reflect letest changes in proposed security ays & procedures. Rays are proprietary (ref iOCFR2, 790). GILLELAND, J.E. Tennesses Vailey Authority. 78/10/25. 79pp. 94094:315.
- Q. Inspection reports. 1E Bullatins & correspondence
- 7812030037 1E Inspec Repts#50-289/78-21,#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted. Major areas inspected incl:reportable occurrences & followup on TE bulistins & circulars.

  SULLIVAN, R. F. Region P. Atlanta, Office of the Director. 78/10/28.10/29.
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1
  F. Security, medical, amergancy & fire protection plans
- 7811130168 Forwards suppl info re mode to security plan dtd 781005, which is withheld pursuant to 2.790.
  ANDOONINI, Q. C. Boston Edison Co. 78/11/06. 1p. 94271:223.

- 7812290230 Ack receipt of 78:005 & 78:106 ltrs re changes to security plan Concurs withe finding that these changes do not dettease the effectiveness of the plan ippolito. T.A. Operating Reactors Branch 3 (Pre 790825). 78/12/21. 206 94191:204
- 1. Financial information
- 7810230205 Foruerde tebular deta on sarninge for Aug 1978. BUTLER.R.M. Boston Edison Co 78/10/16 3pp. 94195 188
- 7812050228 Forwards BECD 1977 Annual Rapt & BECD Form 10-G for quarter anding 780930 as filled w/REC. 1979 Cash Flow Forecast & narrative statement of curtailment of capital expanditures also encl. available in CF & PDR anily.

  KELPON.R.M. Boston Edison Co. 78/11/29. 43pp. 94201 201.
- K Utility Final Sefety Analysis Report (FSAR) & amands
- 7811140132 Forwards suppl info to proposed lic amend of 781016 re changes perteining to receipt possession & use of hyproduct, source & special nuc meth. Encl is rev to FSAR updating source inventory to comply w/Reg Quide 1.70 3 ANDOGNINI.Q.C. Boston Edison Co. 78/11/02. 3pp. 94428:247
- 7812260218 Forwards Revel to Emergency Plan & Amend#38 to FBAR.
  ANDCONING Q.C Boston Edison Co. 78/12/18. 2pp 94162:099
- --7812260223 Rsv 1 to Emergency Plan. Amend 38 to FBAR Majority of revised pages correct typographical errors. ANDONNINI.0.C. Boston Edison Co. 78/12/18 77pp. 94162:101.
- P. Operating license stage documents & correspondence
- 7810170136 Responds to 780807 NRC request for evaluation of reactor protectings pur supply. Believes that continued safe oper of subjecti is justified One Electuii rept on failure modes af affects by mid-Nov. Public health & safety not effected.

  ANDOONINI. Q C Boston Edison Co. 78/10/05. 3pp. 94236:008
- 7810180113 Informs NRC that info requests or seffects of sievated temp on sefety relief valve discharge loads will be submitted by 781115 instead of 781001 due to delay in completting trensient enalyses.

  ANCOGNINIS O C. Boston Edison Co. 78/10/10. 19
- 78:02:00:107 Requests amond to facil operating LichDPR-35 pertaining to receipt possession & use of byproduct source & special nucleat! Amond may produce more fisability in plant oper by generalizing approach to lic.
  FELCHANN.H.J. Soston Edison Co. 78/10/16. App.
- 7811030001 Natice of 781018 meeting w/Bostan Edison in Bethesda.MQ to discuss BECD proposal to provide augmented dissel generator for startup wil dissel generator inoper. HANNON.J N. Operating Reactors Branch 3 iPre 790625). 78/10/18. 2pp. 02720.216.
- 7810270105 Responds to 780915 itr request for proposal of corrective measures as recommended by NRC Staff re Emergency dissel generator control & alarm circuitry. Response is considered acceptable for the stated conditions for each criteria.

  ANDOGNINI. Q. C. Boston Edison Co. 78/10/20. 3pp. 94059: 292.
- 7811130335 Summery of 78091A meeting w/GE representatives & Mart 1 Owners Group re prograss of Long Term Prog w/attendance list & sgende(RD-9-A-Merk).Standerde.) GRIMES.C. Plent Systems Brench (Pre 791030). 78/10/26 67pp.
- 7811070185 Forwards memb summarizing operating history of the "B" distal generator & 3 unique situations that resulted in abnormal atresses. Concludes that feilure of "D" generator stator were not generator problems, but unique to the "B" unit, ANDONINI. G. C. Boston Editon Co. 78/10/31. 2pp. 94044:191.
- 7811290288 Responds to 781106 request for info concerning licensee reg performance eval for Region i plants by NRC. Provides details. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/09.
- 78:2150139 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attenders to facilitate sending out matl. W/sncl Registration Form & List of Locations. MILLER.J.R. Assistant Director for Bite & Bereguards (Pre 791030). 78/11/15. Spp.

- 7812180239 Forwards Rev81 "Draft Radiological Effluent Teth Specs" for SMR's(NUREO-0473) & "Preparation of Radiological Effluent Teth Specs for Nuc Per Plants" (NUREO-0133). GRIFEE, B. M. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp 94365 316
- 78:1270:63 Responds to 77:12:12 request for info & forwards detailed analysis of suppression pool temp transients & monitoring. Concludes that inadvertent opening of safety relief valve will have no adverse effect in pool or resctor vessel.

  ANDOGNINI. O. C. Boston Edison Co. 78/11/20. 35pp. 94386.169.
- 7812060223 Registers intent to utilize peckeging (UBA/9122/A. model#i8-450) for shipment of Type A & lerge quantities of radioactive mati. Licensed packaging user of record is Chem-Nuc Bye, Inc.
  ANDOMINI, Q.C. Boston Edison Co. 78/11/21 | p. 94382.165.
- 78:2070135 Notice of seminer on 78:208 on new Model Rediological Effluent Tech Space for nuc pur plants. Requests advants submission of seminer specific questions W/encl Seminer Info Sheet-Proposed Agands & meps ORIER-8 H Region i, Philadelphia, Offics of the Director. 78/11/21. Spp. 94373-208
- 7812050272 Ack receipt of 780227 ltr re need for feedweter pump trip or reactor high water lavel. Finds proposed sched for instaliation acceptebls. IPPOLITO.T.A. Operating Reactors Branch 3 (Prs. 270625) 78/11/28. 20p. 94202, 223.
- 7812110058 Discusses possible dengers of LOCA in contensment purging during narmal plant oper Requests either commitment to limit purging or justification for continuing, Wienci AND: #7812080207 IPPOLITO, T. Operating Reactors Branch 3 (Pre 790625). 78/11/29. 8pp 94337, 142.
- 78:2110:66 Advises that Mark I Containment Prog QE Rept, "NEDE-23898-f Analytical Model for Computing Mater Rise In a Sefety/Relief Valve Discherge Line Following Velve Closure" has been transmitted to MRC Should be included on subj facil dkt. ANDOGNING-0. C. Boston Edison Co 78/11/30. ip. 94337:085
- 78:2140:76 Forwards Oct 1978 Prog Activity Review Listing meetings he & providing tesk-by-tesk scrivity summary for the month 808ON-L.J General Electric Co. 78/12/04. hipp.
- 7812210238 Responds to Quelity Assurance requirements published in 770804 Fed Register Suby Facil's prog was approved in 751112 NRC ltr.but Facil will extend the scope of that prog to the lic shipping casts now used. ANDONINI.O.C. Boston Edison Co. 78/12/06 2pp. 94162:353.
- 7812280138 Emphasizes importance of submitting accurate & complete init to NRC by licensess & applicants Info submitted must be substantisted by dete & calculations. Licenses must notify NRC of any inaccuracies or enfortement action will result. DAVIB. J. Q. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:348.
- 7811210367 Forwards addl info re multiple consecutive sefety/relief valve actuation of Mark I containment progrem. 8080N.L.J. Ogneral Electric Co. 78/11/13, 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7811100008 forwards iE Inspec Rept#50-273/78-22.on 780905-08 during which no items of noncompliance were noted.

  BRUNNER.E. J. Region i. Philadelphia. Office of the Director.

  78/09/27. 2pp. 94179:258.
- --7811100012 1E inspec Rept#50-293/78-22 on 780905-08 during which no items of noncompliance were noted. He or areas inspected included; pient opers. IE Circuler 78-08, IE Sullatin 78-03 & LER review.

  \* Region 1. Philadelphia, Office of the Director. 78/09/26. 9p
- 7610160080 Forwerds Rept on Mgt HestingNSO-293/78-23 hald at subj fac on 780928.
  BRUNNER.C. J. Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/28. 2pp. 94003:229.
- --7810160082 IE Mgt Mesting Rept#30-293/78-23 on 780928 re recent ins findings to provide licenses w/info on inspec program. ARCHITZEL.R.E., MCCABE.E.C. Region 1. Philadelphia. Resctor Operations Nuclear Support Branch. 78/09/28. 3pp. 94003:231,

- 7810170027 Forwards IE Bulletin#78-12 "Atypical Held Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days. List of JE Bulletins issued in 1978. (see AND 7810040253)
  GRIER.B. H. Region I. Philadelphia. Office of the Director. 78/09/29. 6pp 94241:360
- ORIER B # Region 1. Philadelphia. Office of the Director 78/10/13. ip. 94489 117
- 7011270210 Forwards IE Circular #78-18. "UL Fire Test "W/enci AND: 7811150002 GRIER, B H. Ragion 1. Philadelphia. Office of the Director 78/11/06 ip 94207. 341
- 78:2260300 Forwards IE Inspec Repta50-293/78-24 on 78:1003-06 during which no items of noncompliance were noted. MARTIN.W Q. Region 1. Philadelphia, Sefeguerds Branch. 78/11/08. 3pp. 94349-356
- --7812200309 1E Inspec Rept#50-293/78-24 on 781003-06 during which no liters of noncompliance were noted. Mejor ereas inspected inci.physical protec inspec, implementation of accepted Becurity Pian & sections of 10CFR73 55.

  MADDEN. H., LADUN. R., DEVLIN, J. Region 1, Philadelphia, Office of the Director. 78/11/07, ip. 94349 358
- 7B12000185 Responde to 7B0929 NRC itr & 1E Dulletin#78-12 requesting info re reactor welds. Requests extension to 7B1231 for responses as contractor QE needs time for compilation ANDCONTRI, Q Q Boston Edizen Co 7B/11/14 [p. 94109:205.
- 7812150121 Forwards IE Bulletine78-12A.suppl to IE Bulletine78-12 W/enci AND: 7811300055 ORICR.D H Region I. Philadelphia. Office of the Director. 78/11/24. ip 94212.155.
- R. Periodic operating reports & related correspondence
- 7010100130 Forwards Monthly Open Rept for Bept 1970 HCGUIRE, P. J. Boston Edison Co., 78/10/01 1p 94413.002
- --7810180131 Monthly Oper Rept for Bept 1978 \* Daston Edison Co. 78/10/12 6pp 94413:003
- 7011210263 Forwarde Monthly Open Rept for Oct 1978 MCOUIRE, P. J. Boston Edieon Co. 70/11/01 1p 94405:350
- --7811210269 Monthly Oper Rept for Oct 1978. \* Boston Edison Co 78/11/01. 7pp. 94485 287
- 7812200183 Forwards Monthly Open Rept of Nov 1978, MCOUIRE, P. J. Boston Edison Co. 78/12/01 1p. 94158:351.
- --7812200185 Monthly Oper Rept for Nov 1978. QAFFNEY, C. Boston Edison Co. 78/12/11. 6pp. 94158:352.
- 8 Reportable occurrences. LERs & related correspondence
- 7B10310158 Forwards LERH78-045/03L-0. HCOUIRE,P J Boston Edison Co. 78/10/24. 1p. 94090:214.
- --7810310163 LERM78-045/03L-O on 780926 indicator needle for TI-5047 water temp gage snapped off from dusting since the needle had been exposed by a broken protec covering. HATHIBLC. J. Boston Edison Co. 78/10/24. 1p. 94090-215.
- 7011080152 Forwards LERW78-047/03L-0. MCCUIRE, P. J. Boston Edison Co. 78/11/02. 1p. 94399:321.
- --7811080186 LER#78-047/03L-0 on 781002:Position of Chief Radiol Engr was incorp into PMP8 organization which assumed responsibilities of Health Physics Organization. Caused by efforte to improve quality of Health Physics Prop.

  MATHIS, C. J. Boston Edison Co. 78/11/03. 1p. 94399:322.
- 7811090161 Forwards LERW78-046/03L-0. HCOUIRE, P. J. Boston Edison Co. 78/11/02. 1p 94043:031.
- --7811090168 LERM78-046/03L-0 on 761006: oxygen analyser valves CV-5065-12, CV-5065-16 & CV-5065-25 appeared inoperable but local observation showed valves working properly, Caused by switch misslignment. LERM inconsistent w/LERM in cover ltm. MATHUR. C. I. Deather Fotion Co. 78/11/02 2na 94043-04.

- 7811140207 Forwards LER#78-048/03L-0 MCQUIRE, P. J Boston Edison Co 78/11/07 Ip 94384-345.
- --781ii402;2 LER 78-048/03L-0 on 781009 reactor strammed on a load rejection causing generator lockout relay trip. Cause was excessive pilot seat leakage keeping second stage & main valve open. Relief/safety valve replaced MATHIB.C J. Boston Edison Co. 78/11/07. 1p. 94304: 346
- 7811140183 Forwards LERW78-049/03L-0 HCQUIRE,P. J. Boston Edison Co. 78/11/10 2pp. 94384:2%
- --7811140188 LER 78-049/03L-0. on 781011. while performing eurveillence testing on diesel generator B. generator output breaker tripped due to short from one coil to stator Ceused by loose laminations. Coils replaced & test re-run satisfactorily.

  MATHIB.C J. Boston Edison Co. 78/11/10. 2pp. 94384:257.
- 7811210341 Forwards LERW78-050/04T-0.
  MAGUIRE, P. J. Boston Edison Co 70/11/14. ip. 94484: 338.
- --7811210345 LERM78-050/04T-0 on 781106: Yankse environ lab indicated that 63901/kg of C8-60 existed in sample mussel must This exceeds by 10 tinse the concentration measured at Marshfield control station Resulted from new enalysis technique
  MATHIG. C J Doston Edison Co 78/11/14 IP 94484: 339
- 7811280333 Forwards LERW78-051/01X-0 MCOUIRE, F J Boston Edison Co 78/J1/22. 1p 94395:351.
- --7811280333 LERRY8-031/01X-0 on 781030 # of operable SRM's Les raduced below minimum req when SRM "A" was jumpered to eliminate problems w/downscale rod block Caused by inadvertent jumpering of entire "A" SRM trip logic Procedures being rev a Boston Edison Co. 78/11/22 ip. 94393:332.
- 7812040173 Forwards LERM78-052/03L-0 MCGUIRE, P. J Doston Edison Co 78/11/27. 1p 94455: 232
- --7912040176 LERW78-052/ODL-O on 781028:BUAE offgee rediat monitor readings were low caused by shut block valve to FCV-118. Valve was opened Proper flow rate established Valve will be properly identified in future by personnel. MATHIS.C. J. Boston Edison Co. 78/11/27. 1p. 94456:203
- 7012050185 Forwards LERM78-053/01T-1.
  MCQUIRE,P J Boston Edison Co. 78/11/29. 1p. 94335:173.
- --7812030192 LERW70-053/01T-0 on 701116 during repair of fire hydrent facing condenser retube bldg, shut-off valve blew off line causing local flooding & removal of fire suppression from Bvc.Cause was improper reinstallation at retube bidg constr. MATHIB, C. J. Boeton Edison Co. 78/11/29 ip 94335:174.
- 7812120135 Forwarde LER 78-051/01T-0 HCGUIRE, P. J. Boston Edison Co 78/12/05 1p. 94276: 180.
- --7812120141 LER 78-051/017-0:on 781121, noted that on 781030 number of operable source range monitors reduced below Tech Spec minimium when monitor A was jumpered to eliminets problems widownscale rod block. Caused by personnel & maint error. MATHIS.C. J. Boeton Edison Co. 78/12/05. 3pp. 94276:181.
- 7812180168 Forwards LERM78-054/03L-0.
  MCGUIRE, P. J. Boston Edison Co. 78/12/08. 1p. 94366:037.
- --7812180172 LERM78-054/03L-0 on 781115; during test of reactor weter level, level switches LI8-263-57AL8 observed to trip at values greater than specified in Tech Specs, Caused by minor setpoint drift.

  MATHIB, C. J. Boston Edison Co. 78/12/08. 1p. 94366:038.
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
- 7811240200 Forwards LER#78-091/03L-0. WANDKE,N.E. Commonwealth Edieon Co. 78/10/13 ip. 94458:344.
- F. Security, medical, emergency & fire protection plans
- 78101200B0 Forwards analysis of Electrical Cable Penstration Fire Barrier Test conducted on 780619, Also forwards 3rd party observer rapt of test & 5 detailed drawings associated witest.

  NAUGHTON, H. F. Commonwealth Edison Co. 78/09/29. 44p.

# **DOCKETED ITEMS**

- 7812120193 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plent Fire Protec Functional Rasponeibilities Admin Controls & OA" will be submitted 770201 NADMION.H.F. Commonwealth Edison Co 78/11/30 2pp.
- 7812270365 Forwards correction of item 3 2 5 of fire protec SER Requests delay in advising licenses of acceptability until there is a response to smc1 2 of 780626 ltr LAIMS.Q. Plent Systems Branch (Pre 791030) 78/12/07 ip 04277:016

# g Adjudicatory correspondence

- 7811130202 "Agreed Motion for Special Prehearing Conference & to Set Sched for Further Proc" on 781120.21 or 22 to heer oval arguments & rule on motions to dismiss & to allow citizens to enter linited epsearances.
  STEPICE.P. Commonwealth Edleon Co. SCHELL.S. Illinois, State of 78/10/24. 3pp. 03553:355.
- 7811240022 Amended contentions of St of IL re emends to Oper Lice MDPR-39 & A8 to Increese spent fuel storage capacity at subjectles. Asserts that to approve amend would be contrary to NRC polity position Cert of Svc & affidavit encl.

  8EXULER, 8 N Illinois. State of 78/11/01. 9pp 94458:167
- 7811170012 "Order for Special Prahesring Conference." The 781024 joint motion of Patitioner, Applicant & Reg Steff for special prahearing conference is greated & set for 781120 LUTON.E. Atomic Sefety and Licensing Board Penel. 78/11/02. 2pp. 94116.123
- 7811200423 Notice of eppearance by Q Cunningham in proceedings re subj facils on behalf of NRC.Cert of Buc anci. CUNNINGHAM, Q.H. Office of the Executive Legal Director. 78/11/02. 2pp 94419:185.
- 7812040311 Commonweelth Edison Co Motion to strike contentions & supporting mamp submitted by IL Atty General on 781101 Requests that Amended Contentions#2.#6D & Wió be stricken ROME-J W. STEPTOE.P.P. lahem, Lincoln & Beale. 78/11/09 17pp. 94129:188.
- 7812050047 Motion to amend Contention 6A of Intervenor's amended Contentions filed 781:01 by stating that there has been insufficient dev of all credible eccident scenarios in subject SEMULER, B. N. 111:nois, State of 78/
- --7812050051 Memorandum in support of amend contentions Believes staff & Applicant should not be allowed to use the special prehearing conference as means to circumvent the summary disposition process. Myenci Cert of Byc.

  SEXULER, S.N. Illinols, Beats of, 78/11/09, 14pp. 94334:162
- 7812050054 NRC Staff brief in apposition to the admission of Illinois' proposed contentions 2.6A.6D. & 16 re proposed mod of spent fusl pool. Staff visus cover non-contrainty literating of storage facilis, contention wording, vagueness & irrelevance QDDARD, R. J. Office of the General Councel. 78711/09. 7pp. 94334:231.
- 7812120211 Submits typographical corrections to "Memo in Support of Cartein Amended Contentions" filed on 781109 by State of IL. W/Cert of Svc. SEKULER, B. N. Illinois, State of. 78/11/13. 2pp. 94276:066
- 7812120223 Notice of appearance by A Bielewski as counsel for util in proceedings resulty facils. Cert of Suc encl.
  BIELAWSKI, A. P. Ishem, Lincoln & Osale. 78/11/16. 2pp. 94277:127.
- 7812270335 Opposes Commonwealth Edison request to increase spent fuel storage at subj facil. Fears it will become a parameter dump. ROBERTER. M. Affiliation Untroden. 78/11/20. 1p. 94230-286.
- 7819270371 Notification that respondent has been added to see lists for legal & tech branch documents re Spent Fuel Pool Mod proc for selly facilis as of 781127 & previous papers in Formal File ste ancl. (w/o sncl).
  9000MRD.R.J. Office of the Executive Legal Director. 78/12/05. 1p. 9429-05

# J. Insurance & indemnity information

7812190109 Requests refund of \$6 per mut in excess indemity fee paid

- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 7812060394 Notice of ACRS Subcommittee on Plant Arrangements 781026 open meeting at 8:30 AM in Washington.DC to review MRC Generic Issue. Sys. Interaction in Noc Pur Plants. Task A-17 & Zion Station Sys Interaction Study IMPLE. J C Office of the Secretary of the Commission 78/09/25 20p. 94382:351.
- P. Operating license stage documents & correspondence
- 7812080026 FOLA request for all records inci quentity of radioactive matl disposed of from former Manhatten proj in IL known as Chicago Pilesal, 2 to 3 Matl disposed of in IL by Lindsay Cos at Morte facil & Oresden facil
  HANGELLO 1111nois, State of 78/11/06 2pp
- 7810100025 Current schedule for submittal to NRC Staff of required res ECCS enalysis & associated Tech Spec changes is 780105 Me Bohadulad rev analysis for subj facil to begin late 781031 NAUGHTON.M F. Commonwealth Edison Co 78/10/03. 10. 94033:043
- 7810120098 Request for addi info on Startup Physics Testing Rept of 781015 BCHNENCER, A Operating Reactors Branch i (Pre 790625) 78/10/03. 3pp 94474-019
- 7010120036 L1(@DPR-39 & DPR-48 appl for amend to Tech Specs proposed incorporating ECCS flow requirements re a blow belance test & tamper-proof covers for manual throttle valves.

  REED.C. Godmonweelth Edison Co. 70/10/05. 7pp. 94332.299
- 7810180060 Forwards drawing: "Location & Dateils of Reactor Coolant Pur Trip Pans" for subj facil as fire protec response NAUGHTON.H.F. Commonwealth Edjann Co. 78/10/10. 1p.
- 7810200113 Responds to 780829 NRC request for overpressure protec Tech Spec. States that util will submit requested info by 781201 NAUGHTON-W F Commonwealth Edison Co 78/10/13 2pp. 94367:342
- 7810250102 Renewal of request to amend Pacil operating liceDPR-39 & DPR-4B.Proposed amend is a combined class i & class III Amend & does not require extensive environ impact rept. Tech Goet & Environ impact statement encl REED.C. Commonwealth Edison Co. 70/10/13. 17pp.
- 7810230194 Requests withdrawal of proposed amend to facil lice DPR-39 & DPR-4B originally submitted in ltr of 760720. Completion of mod re lake discharge tants necessitates proposed amend be cencelled NAUGHTON,H.F. Commo
- 7810300097 Forwards into in response to 780831 NRC 1tr re pipe cracks in them you control due to excessive charging pump
- NAUGHTON, H. F Commonwealth Edison Co. 78/10/24 2pp. 94035: 072
- 7811010069 Forwards additinfo re proposed expansion of spent fuel storage capacity of subj facti in response to 780926 NRC request. Responds to 27 NRC questions
  NAUGHTON.H F. Commonwealth Edison Co. 78/10/24 690p. 94302.285
- 781107014B Requests change to Oper LicMDPR-39 & DPR-4B Tech Bpectettending red tow panelty curve & EFPH clad collapse limite to incl higher region everage fuel burnups
  REED, C. Commonwealth Edison Co. 78/10/27, 7pp. 94044
- 7811140002 Notifies applicant of 781128 NRC-sponsored seminar re Modi Radiological Effluent Tech Specs for Nuc Pur Plants U/encl Beminar Info Sheet(to be completed & returned by 781117) & Proposed Aganda. KEPPLER, J. Q. Region 3, Chicago, Office of the Director, 78/11/07. App.
- 781:210410 Provides addi info in response to questions 13 & 15 in 781024 ltr re isskepe rate from spent fuel pool linar, surface dose rate as spent fuel pool potential impact of proposed spent fuel pool mad re quesous efficients.

  NAUCHTON.H.F. Commonwealth Edison Co. 78/11/08. 3pp. 94483.123
- 7811300147 Forwards "Licensing Rept for Sub; Facil Spent Fuel Rack Mod" in response to 780203 request.
  OODDARD.R.J. Office of the Esecutive Legal Director. 78/11/03. 94072:031.

- 7811270104 Summary of 781025 meeting w/Subcomm on Plant Arrangements of Advisory Comm on Reactor Safeguards of Sandia Labs presentation of Sys Interaction Methodology Appl in Nuc Pur Plants & subj facil sys interaction study.

  ANOLO.J. Division of Project Management. 78/11/13. 35pp. 94221:294.
- 78:2:8002: Notice of workshops rs implementation of training & qual requirements contained in Append B of iOCFR73.Requests pre-workshop registration of attendess to facilitate sending out metl. H/enci Registration Form & List of Locations. HILLER.U R. Assistant Director for Site & Bersguerds (Pre 79:000). 78:71:715 5pp. 74:103.281
- 7812190011 Forwards Rev#1 "Draft Radiological Effluent Tach Spece" for P#R's(NUREO-0473) & "Preparation of Radiological Effluent Tach Spece for Nuc P#R plenta" (NUREO-0133).
  ORINES.B. K. Assistant Director for Engineers & Projects (Pra 790525), 78/11/15. 6pp. 94214:274
- 7811270091 Forwards suppl to Facil Cycle 3 Startup Rept re Furthar Demonstration of Adequate Shutdown Hargin & responses to NRC questions re Cycle 3 Startup Rept. Subj facil completed Cycle 3 open on 760914.
  REED.C. Commo
- 78:20:00107 Forwards rsv pags to Topical Rspt CE-i-A: "Qual Assurance Prog.Rsv 6." Rev reflects Rsg Quidal 28 & 1.33 rsv TURBAKiM.S. Commonwealth Edison Co. 78/11/17, 2pp.
- 7811280213 Forwards current lic status list for subj facils. W/ancl. REED.C. Commonwealth Edison Co. 78/11/20. 9pp.
- 7811300042 Informs CEIL that NRC has contracted w/Mountain Wast Ras Inc to undartake a saries of post-licansing studies of nuc pur stations Bludies will analysi socioacon imparts which occurred during constr & post-constr pariods of each plant DEYOUND.R. C. Division of Bits Bafsty & Environmental Analysis. 78/11/20. 2pp. 94071:037.
- 7812270127 Forwards Commonwealth Edison "Add1 Info on Proposed Espansion of Spent Fuel Storage Capacity" dtd 781108. H/o encl.
  BIELAMBKI, A. P. Isham, Lincoln & Beals. 78/11/27. 1p. 94161:084.
- 7812180116 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either tommitment to limit purging or justification for continuing. H/ancl ANO 7812080207.

  BCHMENGER, A. Operating Reactors Branch 1 (Pre 790625), 78/11/28. 6pp. 94130: 317.
- 7812080095 Forwards CEIL's Proj Milepoate ached for subj facile fual pool mode. Also included are brief statements providing beens for these milepoats. Requests that NRC staff aspadite its review ached to mest 790201 & 790515 completion dates. REED.C. Commonwealth Edison Co. 78/11/29. App. 94107:292.
- 7812180236 Forwards Amend#40 to Oper Lic#DPR-39 & Amend#37 to Oper Lic #DPR-48, Aiso forwards Safaty Evai Rept & Notice of Leavance. BCH-ENCER.A. Operating Reactors Branch 1 (Prs 790625). 78/11/30. 2pp. 94365:001.
- ---7812180239 Amsnd#40 to Oper LiceDPR-39, Changes Tach Spect to allow boron concentration in pressuriser to be 200 ppm less than reactor coolent loop boron concentration, Corrections are made to Tech Specs, Changes to Tech Specs and.

  SCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/30. 6pp. 94365:003
- --7812180240 Amand#37 to Oper Lic#DPR-48. Changes Tech Space to Allow horsh concentration in pressurizer to be 200 ppm less than reactor coolant loop boron concentration. Corrections are made to Tech Space. Changes to Tech Space and:
  SCHWENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/30.6pp. 94365:009.
- --7812180242 Safety Evel Rept in Support of Amend840 to Oper Lic#39 & Amend837 to Oper Lic#48.
  SCHMENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/30.
  49p. 94265:015.
- --7812180244 Notice of Issuance of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#40, BG##ENCER.A. Operating Reactors Branch 1 (Pre 790525). 78/11/30. 2pp. 94365:019.
- 78:2070211 Responds to NRC 780828 itr requesting overpressure protection Tech Speca Requests extension to 790215 for authorston due to receipt of new info.
  NAUGHTON, M. F. Commonwealth Edison Co. 78/12/01. 2pp. 03555:115.

- 78:17280129 Emphasizes importance of submitting accurate & complete into NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or snforcement action will result. DAVIB.J.G. Optics of Inspection & Enforcement. Office of the Director. 78/12/Q6. 2pp.
- 7812030013 Requests views of Regional Directors on Licenses parformance aval of subj facile Forwards questions to be answered by 771209.

  THORNBURG. H. Division of Reactor Construction inspection 77/11/23
- 7812190097 Accepts topical reptMCE-1-A RevM6. "Come Edison Co Oustity Assurance Prog for Nuc Generating Stations." Requests submittel of 36 copies.
  HAA98. M.P. Guelity Assurance Branch. 78/12/13. 1p.
- 78:1280278 Discusses preparations for aub; facil Estended Eurnup Propincl fuel sipping test & fuel seasmblies exam prop. Reaffires request to NRC to expedite lic mod review & approve changes to higher region everage fuel burnup Tech Space by 78:1220 REED.C. Commonwealth Edison Co. 78:11/21. 3pp. 94395.219.
- G. Inspection reports, 15 Bullatine & correspondence
- 7811080066 Forwards IE Inspec Rapts#50-295/78-20 & #50-304/78-22 on 780809-11-16.17.23-25.30.31.0901-07 & 08 & Notice of Violation. FIDRELLI, Q. Ragion 3. Chicago, Reactor Operations Nuclear Bupport Branch. 78/10/04. 2pp. 94398:274.
- --7811080070 Notice of Violation from inaper on 780809-11, 16.17,23-25,30.
  31.0901.07.08.
  - Ragion 3, Chicago, Reactor Operations Nuclear Support Branch.
     78/10/04. 1p. 94398:276.
- --7811080074 to inspec Repte#50-295/78-20 & #50-304/78-22 on 780809-11.
  16-17, 23-25, 30-31, 0901, 07-08 during which 1 item of noncompliance was noted; preparation for refueling, BOYO. D. C., RIDEN, M. D., KNOP, R. C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 11pp. 94398:277.
- 7812050011 Forwards IE Inspsc Rapts#50-010/78-29,50-237,-254,-295,-304/78-25.50-249/78-27 t 50-255/78-26 on 781002 during which no Itams of noncompliance were noted.

  KEPPLER, J. O. Region 3, Chicago, Diffice of the Director. 78/10/30.
- --7812050027 IE Inspec Rapts for subj facile on 781002 during which no items of noncompliance were noted. Hagor erass inspected inclidiscussion of actions being taken by util to improve its reg parformence k tour of Zion station.

  KNDP.R.C. Rapion 3. Chicago, Reactor Operations Nuclear Busport Branch. 78/10/30. 3pp.
- 7812060231 Forwards IE Inapec Rapts#50-275/78-24 & #50-304/78-24 on 780913-15,780920-21,780927-29 % 781004-05 % Notice of Violation. FIDRELLI, 0. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/31. 2pp. 94382:184.
- --7812060234 Notice of Violation from Inspec on 780913-15,780920-21, 780927-28 & 781004-05, Region 3, Chicago, Office of the Director. 78/10/31. 1p. 94382;186.
- --7812060236 IE Inapac Rapts#50-295/78-24 & #50-304/78-24 on 780913-15.
  20-21.27-29 & 781004-05 during which i item of noncompliance
  was noted: failure to adhere to conditions of Nork Raquest
  Authorization.
  BUYD.D.C., BIDEN.M.D., KNOP.R.C. Region 3. Chicago. Office of the
  Director. 78/10/31. Spp. 94382:187.
- 7811150063 Forwards IE Circular 78-18.
  KEPPLER, J. G. Ragion 3, Chicago, Office of the Director. 78/11/06.
- 7812130329 Forwards IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliants wars noted. HEISHMAN,R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/07.
- --7812130338 IE Inapec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of honcompliance ware noted. Major areas inspected incl: IE Bulletin & Circular followup & qual of size equip & independent inspec. HUDHER, J. Region 3. Chicago, Office of the Director. 78/11/09. 6pp. 94307:049.

- 7812050287 Forwards IE Bullstin#78-12A. suppl to 1E Bullstin 78-12 W/snci ANO 7811300055 KEPRER, J. G. Region J. Chicago. Office of the Director. 78/11/24. ip
- 7812280002 Forwards IE Bullatin 78-14.
  KEPPLER, J. O. Region 3. Chicago. Office of the Director. 78/12/19.
  ip 94133 002
- A Periodic operating reports & related correspondence
- 7810100049 Monthly Oper Rept for September 1978.
  SCHEIDER, H. Commonwealth Edison Co. 78/10/03 13pp 94063.065.
- 78]101014] Forwards rapt entitled "Oper Environ Monitoring in Lake Michigan near subj facil-July 1977 thru June 1978, Vols 1-1V MANDKE,N. Commonwealth Edison Co. 78/10/24. ip 94095:002
- -7811010131 Annual rept entitled "Oper Environ Monitoring in Leie MI near subj facil-July 1977 thru June 1978" prepared by NALCO Environ Sciences • Commonwealth Edison Co. 78/11/01 1617pp 94095 003
- B Reportable occurrences. LERs & related correspondence
- 7810170184 Forwards LERM78-078/01L-0.
  WANDKE,N E Commonweelth Edison Co. 78/09/15. ip. 94270:052.
- --7810170189 LER#78-078/01L-0 on 780818 possible use of etypical wald metal discovered in 4-loop PMR Reactor Versels in subj facils. Interim RCS heatup & cooldown curves calculated & used to provide adequate conservation until issue resolved.

  SHANNON, R. E. Commonwealth Edizon Co. 78/09/15. 3pp. 94270:053
- 7810170181 Forwards LERN78-084/03L-0 MANDXE.N.E. Commonwealth Edison Co. 78/09/21 1p. 94270:081.
- -7810170187 LERB7B-094/03L-0 an 780822 Instru dept found amtr 1FT-446 failed at 103%. Percentage nonconservative for low RC flow Rx trip. Caused by failure of oscillator in transmitter (Fisher-Porter model 1082496) RQEERS. C L. Componwealth Edison Co. 78/09/21. 1p. 94270.082.
- 7810170207 Forwards LER#78-082/03L-0. WANDKE,N E. Commonwealth Edison Co. 78/09/22. 1p. 94235:339.
- ~-7810170212 LER#7B-082/03L-0 on 780802 during normal open daily surveillance for DRT-PR17 (radiat monitor for control room intake from turbine bidg) was amitted. Monitor was open prior to & after missed surveillance. No affety implications. OST.F. Commonwealth Edison Co. 78/09/22, jp. 94235:340.
- 7810180050 Forwards LERW78-083/031-0 MANDRE:N E. Commonwealth Edison Co. 78/09/22. 1p.
- 7810170219 Forwards LERS78-089/01T-0. WANDKE-N.E Commonwealth Edison Co. 78/09/25. ip. 94236;158.
- --7810170227 LERW78-089/01T-0 on 780911: during normal open 1C Svc Water Pump was removed for breaker inspec Other 2 pumps were not immediately verified as operable & their standby AC & DC pur supplies not checked Caused by personnel arror.

  \* Commonwealth Edison Co. 78/09/25. 4pp. 94236: 159.
- 7810170225 Forwards LERW78-085/03L-0. WANDKE,N.E. Commonwealth Edison Co. 78/09/26. 1p. 94236:167.
- --7810170228 LER#78-085/03L-O on 780827: discovered missing belt on unit 1 containment area post sampler blower. New belt installed. WANDKE, N. E. Commonwealth Edison Co. 78/09/26. 1p. 94236: 168.
- 7810170214 Forwards LERM78-086/03L-0. WANDXE.N.E. Commonweelth Edison Co. 78/09/29, 1p. 94236:151.
- --7810170223 LER#78-086/03L-0 on 780830: containment isolation valves IFCV-MD17A: IFCV-PR20A: and IFCV-PR24B failed during test. Valves failed dus to oil in instru air. HANDKE, N. E. Commonwealth Edison Co. 78/09/29. 1p. 74236: 152.
- 7810170241 Forwards LER#78-087/01T-0. MANDKE:N.E. Commonwealth Edison Co. 78/10/02. 1p. 94236:326.

- --7810170246 LERM78-087/01T-0 on 780702 while iA diesel generator was out of eve for testing. IB diesel failed to start due to improper staking of starting air distributor drive bushing causing shift in starting air timing. Bushing was restaked.
  ALINGER, N.A. Comeonwealth Edison Co. 78/10/02 2pp. 94236.327
- 7810170231 Forwards LER#78-088/03L-0 WANDME-N E. Commonwealth Edison Co. 78/10/06 1p 94236.177
- --7810170234 (ERM78-088/03L-O on 780908 During normal oper channel 1L-5 uas found reading higher than other 2 level channels on luop D by over 5% Caused by steam look on root valve on the reference line of XMTR RDSER.C L Commonwealth Edison Co. 78/10/06 lp. 94236:178.
- 7811240127 Forwards LERS78-092/03L-0 WANDKE,N E Commonwealth Edison Co. 78/10/13, 1p 94456: 352.
- --7B(1240129 LERRYB-092/03L-0 on 7B0914 an inadvertant BI occurred when 1A delest generator was started due to bent plunger apring causing failure of engine trip lockout solemoid valve (ASCO B320) Valves replaced & springs checked AINOER.K.A. Commonwealth Editon Co. 78/10/13 2pp 94456:353.
- 7811240197 Forwards LERW78-094/03L-0 WANDKEIN E. Commonwealth Edison Co. 78/10/13 1p. 94458-303.
- --7811240198 LERM78-094/03L-0 on 780914: on a phase A isolation, ifCV-PR2 & ifCV-HD17A failed to close placing containment isolation sys in degraded mode Caused by ASCO 8320 solenoid valve failing to close due to oil in Instru air UGOLINI, D. J. Commonwealth Edison Co. 78/10/13. 1p 94450:304
- 7811240201 LER#78-091/03L-0 on 780914 Damper switching sequence from normal to accident mode caused pressure differential in iE RCFC Pressure differential caused accident inlet damper blades to flex & bend Switching sequence to be changed JOHNSON.R. Commonwealth Edison Co. 78/10/13 Ip. 94458.345.
- 7811240212 Forwards LERM78-090/03L-0.
  WANDME:N.E. Commonwealth Edison Co. 78/10/13. ip. 94463:358.
- --7811240213 LERB78-090/03L-0 on 780914, channel 1L-538 read higher than IL-539, IL-538 was found to be out of tolerance & appropriate bistables were tripped Caused by steem lesk on root valve (3/4 inch manual globalon sensing line ROGERS.C.L. Commonwealth Edison Co. 78/10/13. 1p 94463; 359.
- 7811240221 Forwards LERM78-093/03L-0 WANDME:N E Commonwealth Edison Co. 78/10/13. 1p. 94438.217
- --7811240223 LERBYB-093/03L-O on 780914: Following Inadevertant SI.1CRCF falls to jou speed auto start due to dirty contacts in the low speed hand switch Operating surveillance rev to keep dirty contacts cleen.
  JUNNBONN R. Commonwealth Edison Co. 78/10/10. 1p. 94458:210
- 7B11240227 Forwards LERN7B-098/03L-0.
  HANDKE-N.E Commonwealth Edison Co. 70/10/27, 1p. 94458.201.
- --7811240229 LERM78-096/03L-0 on 780904: channel iL-337 higher than 2 redundant channels due to eteam leak on root valve (3/4", Hanual Olobe)on seneing line XMTR. Channel failed again on 780908 Root valve replaced.
  ROQERB.C. Commonwealth Edison Co. 78/10/27, ip 94438:202
- 7811240205 Forwards LER#78-097/03L-0.
  HANDKE,N.E. Commonwealth Edison Co. 78/11/03. ip. 94458:350.
- --7811240206 LERM78-097/03L-0 on 781004: Unit I component cooling radio monitor would not respond to check source Caused by water damaged detector in detector Hell & defective rate board. TRZYNA.O. Commonwealth Edison Co. 78/11/03. Rpp. 94430: 351.
- 7811240207 Forwards LERB78-102/03L-0.
  HANDKE:N E. Commonwealth Edison Co. 78/11/03. 1p. 74458:393.
- --7811240208 LER#78-102/03L-O on 781006: Westinghouse reported O 5% erro in APDMS limit calculations due to roundoff & addl apparent error totaled 1.5% creating potential for exceeding APDMS limits Caused by z. xzz format of APDMS calculations. PERDIKIS.O.C. Commonwealth Edison Co. 78/11/O3. 1p. 94458:354.
- 7908080684 Natification of deficiency found 780913 in valve cross

WANDKE, N E Commonwealth Edison Co. 78/11/17. 1p 94339.318

- -- 7812110129 LER#78-106/03L-0 on 781020: during refueling autage surveillence, noted that feed water flow Kmtr ILI-931 had shifted in excess of Toch Spec limits Caused by transmitter drift, kmtr recalibr & channel returned to normal. RODERB. C. L. Commonwealth Edison Co 70/11/17. 1p. 94339: 319.
- 7812180144 Forwards LER#78-100/03L-0.

  WANDME, N. E. Commonwealth Edison Co. 78/11/17. Ip 94393:267.
- --7812110147 LERN78-100/03L-0 on 781010. Containment air particulate monitor, IREODII blower continually tripped due to low flow. Caused by improper valve lineup of monitor HEYER, B. A. Commonwealth Edison Co. 70/11/17 lp 94393:288.
- 7812110157 Forwards LER#78-107/03L-0. WANDRE, N.E. Commonwealth Edison Co. 78/11/17. ip. 94337:075.
- --7812110159 LERW78-107/03L-0 an 781020 during refueling surveillance. noted that steam generator ID level channel 1L-548 had drifted above Tech Spec accuracy limit Caused by instru drift of transmitter Instru subsequently recelibr. HANSEN, P. W. Commonwealth Edison Co. 78/11/17. 1p. 94337:07b.
- 7612110161 Forwards LER878-109/03t-0
  WANDRE, N E Commonwealth Edison Co 78/11/17 1p 94337:001.
- --7812110163 LER#78-109/03L-0 on 781020: during refueling surveillance noted that steam generator 1D level channel IL-538 was 5% high exceeding 2% ipop tolerance Caused by blocked instru line leading to transmitter Line subsequently cleared HANDEN, P. W. Commonwealth Edison Co. 70/11/17. 1p. 94337:002.
- 7612110151 Forwards LERW7B-110/00L-0.
  WANDKE,N.E. Commanweelth Edison Co. 70/11/20. 1p. 94339:361.
- --7012110154 LERM78-110/03L-0 on 781021; surveillance level xmtre 950, 981 for accumulator A & 936.957 for accum D were found out of tolerance low Caused by instru drift CAMPBELL, J. Commonwealth Edison Co. 70/11/20 tp. 94339.362.
- 7812110175 Forwards LERR78-113/03L-0. HANDKE, N. E. Commonwealth Edison Co. 78/11/20. 1p.
- --7812110180 LERB70-113/00L-0 on 701021: trip point for reactor coolant flow comparator on channel IF-414 loop A drifted low by 2.62%.esreeding overall loop accuracy of 2% Caused by setpoint drift in channel comparator(Hagen Model#118). HANBEN, P. W. Commonweelth Edison Co. 78/11/20 1p 74337: 102.
- 7B12110160 Forwards LER#7B-120/03L-0. WANDKE-N. E. Commonwealth Edison Ca. 70/11/RP. 1p. 94337:077.
- --7812110164 LERW78-120/03L-0 on 781027:5 enubbers which had empty reserviors were proven importable when bench tested. Coused by hydraulic fluid leakage teahsage sources: reservior seals. leaking body jointe & adjustment screw thread seels.
  RICHARDBON.C K. Commonwealth Edison Co. 78/11/22. 3pp. 94337: 078.
- 7812110179 Forwards LERM78-118/99L-0. WANDME: N. E. Commonweelth Edison Co. 78/11/22, 1p. 94337: 098.
- --7812110182 LER#76-118/99L-0 on 780314; subj fac;1 did not possess Cert of Compliance for packages for 12 shipments of radiosctive matl.10CFR71.12 had been misinterpreted to apply to Hittman Nuclear packages. Registered W/NRC to use Hittman packages. REBCEK, F. Commonwealth Edison Co. 78/11/22 3pp 94337:099.
- 7812210203 Forwards LERW78-121/03L-0.
  HAND&/N.E. Commonwealth Edison Co. 78/12/01. 1p 94879:093.
- --7812210213 LER#78-121/03L-0 on 781101:M8IV 10 from Train A did not close when eignal wes removed caused by relay plunger MELNICOFF. M. A Commonwealth Edison Co. 78/12/01. 1p. 94279:094.
- 7812120121 Notification of deficiency found 780913 in valve cross assemblies, inlet & exhaust push assemblies of KBV Per Engine & corrective action to design roller pin & raplace hand flaring oper. BENDER, B. B. Cooper Industries, Inc. 78/11/03, Rpp. 94278: 389.
- 7812210214 Forwards LER#78-129/03L-0. WANDKE, N. E. Commonwealth Edison Co. 78/18/05. 1p. 94279; 118.

- was incorrectly valved indentification of personnel & cause IRTPROP of event could not be determined. Control room is being investigated.
- TRZYNA. Q. Cummonwealth Edison Co 78/12/04. 10 94279:113.
- 7812210227 Forwards LER#78-122/03L-0.
  HANDME-N.E Commonwealth Edison Co. 78/12/07 ip. 94279:127
- --7812210229 LER#78-122/03L-0 on 781107 Puel bldg area radiat monitor #CRECOOS alarmed high due to erroneous readings in control room & local readouts. Caused by failed GM tuberdetector MEYER, 8 A Commonwealth Edison Co. 78/12/07. 1p. 94279:128
- 7812210234 Forwards LERM78-095/99x-0. HANDKE, N. E. Commanwealth Edison Co. 78/12/11. 1p. 94279:181.
- --7812210239 LERW78-095/99X-0 on 780914: shortly after reactor trip an inadvertent safety injection occurred from a false delta P steam pressure signal, generated from shock of feedwater hammer No damage resulted from sefety injection. REIBB. J. F. Commonwealth Edison Co. 78/12/11. 3pp. 94279:162.
- T. Hearing transcripts on non-antitrust matters
- 7812040047 Transcript of 781120 hearing re subj facil spant fuel pool aspension: pp1-180 LUTON:E. REMICH:F. J. LITTLE:L. W. Atomic Safety and Licensing Board Panel. 78/11/80. 181pp. 01791:057
- 7812040045 Transcript of 781121 hearing re subj fecil spent fusl pool Panel. 78/11/21. 107pp. 94028:179. Atomic Safety and Licensing Board
- DOCKET 50-296 DROWNS FERRY NUCLEAR POWER STATION, UNIT 3
- 7810110107 Responds to 780029 itr indicating there have been no incidents of control rode failing to fully insert on demand at subj facile OitLELAND, J. E. Tennysees Valley Authority. 70/10/08. ip. 94066: 353.
- F. Becurity, medical, emergency & fire protection plans
- 7011200200 Forwards reve to Physical Security Plan of subj facils ra installation of samrgency lighting firtures Requests withholding from pub disclosure per 105FR2 790. GILLELAND. J. E. Tennessee Velley Authority. 70/11/15. 1p. 94252: 036
- H. General correspondence
- 7812210336 Comments on 780927 constituent itr to Lagomeraino ra validity of the Resctor Defety Study, the subj facil fire, a the operabling performance of commercial nuc pur plants. ODBSICH.L. V. Office of the Elecutive Director for Operations 78/12/12. 13pp. 74014:305.
- J. Insurance & indemnity information
- 7012010256 Forwards PolicyMMF-66. Endoresment#37 for sub; facil. Btates advance premium \$94768. B9, reserve premium \$71349. 36 & return premium #3125. 17. FIEDLER, J. Nuclear Insurance Consultants. 78/11/28. 2pp.
- 781 1090096 Advance premium & standard premium endorsement for 1978. BARRES, C. R. Nuclear Energy Liability Insurance Association. 78/10/11. 1p. 94042:141.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7812200244 Forwards Amenda67 which tov FGAR to reflect current plant configuration. Amend does not req revise & in evaluable in PDR. QILLELAND, J. E. Tannesses Valley Authority. 78/11/30. Bpp.
- ---7812200246 Amend#67 to FBAR. Vols i-7. This amend does not req review.
  it merely rev FBAR to reflect current plant configuration.
   Tennessee Velley Authority. 78/11/30. 9900pp.

- 7811170113 Reports that NRC will assist Los Alamos Scientific Lab team in performing vital area analysis at sub; facil during the west of 781126.
  Tennassee Valley Authority. 78/11/13. 1p. 94047:145
- 78:11:70215 Responds to NRC questions prompted by Gilleland's 7808:1 ltr requesting Tech Spsc changes change ensures reconfiguration of GRM's & IRM's & will be placed in non-coincidence trip mode. HILLE, L. M. Tennesses Valley Authority. 78/11/13. ip. 94136:122.
- 7811200080 Requests addi info for review of recirculation pump trip for use to mitigate Anticipated Turansient w/o Boram info due W/In 60 days. LEAR.Q. Operating Reactors Branch 3 (Pre 790625). 78/05/15. Spp.
- 7810200131 Notice of issuance of Amend#40 to Facil Operating Lice DPR-03.Amend#38 to Facil Operating LiceDPR-52 & Amend#14 to Facil Operating LiceDPR-68.rmv Tech Space for oper of subj facile.Amend# lower low water level setpoint.
  1PPLITO.T.A. Operating Reactors Branch 3 (Fre 790625). 78/08/02.
  2pp. 9441i:287.
- 7810230244 Forwards responses to verbal questions re proposed changes to Tech Specs of subj facil as submitted 780322.

  QILLELAND, J.E. Tennesses Velley Authority. 78/10/10. 6pp. 94170: 242.
- 7810270209 Requeste add1 info for review of reload for cycle 2 oper of subj facii. Requests partial responses to quastions as info le dev. & fuli responses w/in 30 days.

  1PPCLITO.Y.A. Operating Reactors Brench 3 (Pre 790625). 78/10/10. 3pp. 94029:218.
- 7810940153 Forwards add1 Info re proposed differential pressura control torus water level Tech Space for subj facile.

  OILLELAND, J. E. Tennessee Valley Authority. 78/10/18. 3pp.
- 7810240144 In response to 780807 ltr to N.E. Hughes, the recommended surveillence of reactor protec sys will continue. Request response date extension to 781215.
  GILLELAND. J. E. Tennesgee Valley Authority. 78/10/19. ip.
- 7810250080 Response to 781010 itr requesting add1 info to complete review of reload analysis for cycle 2 oper of subj facil. Info supplied we obvo licensing code, analysis of Limiting Pressure 2 Pur Increase transient, turbina trip, startup tast. GILLELAND, J. E. Tennessee Velley Authority. 78/10/20. 4pp.
- 7811120335 Summary of 780914 meeting w/OE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendence liet & egende(RD-9-A-Marki, Stendards.) ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/86. 67pp.
- 7811070132 Forwards hydrostatic pressure teeting prog for subj facil. OllELAND, J. E. Tennesse Vallay Authority. 78/11/03. 17pp.
- 7811200406 Forwards results of measurements of radiosctive matl in NRC phentos on whole body counter Encl i contains actual amount of sech radionuclide present encl 2 gives ratio of acasurement to DOE values t encl 3 gives recommendations.

  BUTHERLAND, J. T. Region 2. Atlants. Fuel Facility & Materials Bafety Brench. 78/11/09. 5pp. 94419:305.
- 7811210298 Notifies util of 78120b seminar in Atlanta to discuss new Model Rod Effluent Tach Spece & encl seminar info sheet, registration form & proposed agenda. O'REILLY, J. P. Region 2. Atlants. Office of the Director. 78/11/09 Region 2. Atlante, Office of the Director. 78/11/09. 3pp. 94485: 212.
- 7811300049 Forwards NRC staff paper.Policy Sassion Item(8ECY-78-554) re-licenses reg parformence evaluation. Three mathods for evaluation are:etetistic), trend enalysis & regional survey method. N/o encl. O'AERLLY-J.P. Region 2, Atlanta, Office of the Director. 78/11/15. 2pp. 74071:051
- 7813150148 Notice of workshops re implementation of training & qual requirements contained in Appand B of 10CFR73, Requests the mortishop registration of attendess to facilitate sending out sat), W/encl Registration Form & List of Locations.
  HILLER, R. Assistant Director for Site & Safaguarde (Pra 791030), 78/11/13. Spp.

- ORIHES, B. K. Assistant Director for Engineers & Projects (Pre 7906281. 78/11/15. 6pp. 94356:340.
- 7812050003 Ferwards Amends#44.40 & 17 to LicHDPR-33. DPR-52 & DPR-68 safety syal & Notice of lesuance.

  IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 3PP. 94200:021.
- --7812050009 Amend#44 to Oper Lic. Permits average pur range monitor sys to be inoperable in requel modespermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & cieriftee Tech Specs re:rod block monitor. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790525). 78/11/16 94200: 024. 2900.
- --7812050017 Amend#40 to Oper Lic.Permite average pur range monitor systobe inoperable in refuel mode/permits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clerifies Tech Bpacs rerod block monitor. 1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 29pp. 94200:055.
- --7812050022 Amende17 to Oper Lic Permits average pur range manitor eys to be operable in refuel modespermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Bpecs re:rod block monitor.

  M. Operating Reactors Branch 3 (Fre 790625). 78/11/14. 16pp. 94200: 0B4.
- --7812050023 Concludes amends do not involve eignificant hazards, health safety of public will not be endangered by open in proposed manner & activities in compliance w/regs. \* Office of Nuclear Reactor Regulation: Director. 78/11/16. 9pp. 94200:102.
- --7812050026 Notice of Issuance of Amend#44 to Lic#DPR-33 amend#40 to Lic#DPR-52 & amend#47 to Lic#DPR-68 which revise Tech Specs.

  IPPOLITO.T.A. Operating Resctors Branch 3 (Pre 790625). 78/11/16. 94200: 111.
- 7812050012 Forwards Amend#45.41 & 18 to Facil Oper Lic#DPR-33, DPR-52 & DPR-68 rev Tech Bpecs as requested in 780803 its w/8sfety Evaluation & Notice of Issuance. . IFPGL1TO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. 
  Rpp. 94200:188.
- --7812050016 Amend#45,41 & 18 to Facil Oper LicHDPR-33.DPR-52 & DPR-68 propule Amendmen, 41 % 10 to Facti Oper LiceDPR-33. DPR-58 & DPR-68 rev Tech Spece to incorp minor changes for leak testing containment isolation & check valves. Amendel8 changes limit of 2000 MMO/t fuel exposure.

  IPPDLITO.T.A. Deprating Resctore Branch 3 (Pre 790625). 78/11/18. 60pp. 94200:190.
- ---7812050019 Bafety Evaluation Rept supporting Amend#45.41 & 18 to Fati Oper LiceDPR-33 DPR-52 & DPR-68 concluding that proposed changes are acceptable & safety of pub will not be andangered by open in proposed manner.

  # Office of Nuclear Reactor Regulation, Director. 78/11/18.
  18pp. 94200:250.
- --7812050020 Notice of leavence of Amend#45.41 & 18 to Fecil Oper Lic
- 7811280255 Forwards ray to pump & valve tasting prog which suppl 780925 ltr.Ray are based on further raylaw of ABME Section XI raquirements.
- DILLELAND. J. E. Tennesses Valley Authority. 78/11/22, 13pp. 02725: 322.
- 7812110029 Discusses possible dengers of LOCA in containment purging during normal plant oper Raquests of their constraint to limit purping or justification for continuing. W/enci ANO: 87912080207.

  IPPOLITOR: Querating Reactors Branch 2 (Pre 790625). 78/11/29.
  - 1PPGL1TG, T. Gp. Bpp. 94408: 101.
- 7612030171 Responde to 781118 NRC itr issuing AmendWiB to Fecil Oper LiceDPR-68, Concludes NRC-approved MCPR oper limits are Tach Spec change approval by 790228.

  GILLLAND, J. E. Tennesses Valley Authority. 78/11/30. 2pp.
- 7812050189 Informe that due to delays complete response re suppression pool temp transients will be submitted by 780318.

  GILLELAND, J. E. Tennesses Valley Authority. 78/12/01. 1p. 94336; 123.

```
7612140176 Forwards Oct 1978 Prog Activity Review listing meetings held
     providing task-by-task activity summary for the month. OBCN-L. J. General Electric Co. 78/12/04 11pp
   BOBON, L. J.
```

- 7812200141 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations Licenses must notify NRC of any inacturaties or enforcement action will result DAVIB.J O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:354.
- 7812200194 Provides details of mod motor-generator set characteristics u/postulated M-O set oper modes for low-pressure content injection valve pur supply. Installation will be delayed until end of 2nd refueling outage of Unit 3 OILELAND. J E. Tennessee Valley Authority 78/12/13 App. 04400-194
- 7812200256 Responds to NRC ltr of 780807 re reactor protect sys pur supply at subj facil. TVA does not believe that concerns expressed by NRC are a problem Further surveillance of the reactor protect sys supplies is unwarranted.

  OILEELAND, J. E. Tennesses Vailey Authority 78/12/13 ip 38000 Cons.
- 7812270175 Due to incomplete resolution of insvc prog for Unit 1. submittel of rev Tech Bpecs has been postponed until after details of Unit 3 insvc Inspecc prog are resolved.

  OILLELAND. J.E. Tennessee Valley Authority. 78/12/19 1p.
- 7812290217 Responds to 781129 NRC itr re-containment purging during normal plant oper & request for info re design of all safety actuation signal circuits which incorp a manual feature Responses will be submitted by 790301.

  OILLELAND, J. E. Tennesses Valley Authority 78/12/21. 2pp. 94171: 188.

7811210367 Forwards addl info re multiple consecutive eafaty/relief

- valve actuation of Mark 1 containment program. BOBON, L. J. General Electric Co. 78/11/13. 3pp.
- O Inspection reports. IE Bullatins & correspondence

94017:341

initiated.

- 7D:1090198 Ack recaipt of 7B1016 ltr Informing NRC of staps taken to correct violations noted during inspec#50-259/78-18, #50-260/78-19 & #50-296/78-17. KENNA, W B. Region 2. Atlanta: Office of the Diractor. 78/10/26 1p. 9403B: 260.
- ~-7811090204 Responds to 780825 NRC ltr ra violations noted in Inspec Reptem50-239/78-18. #50-250/78-19 % #50-276/78-17. Corrective actions are exempt from disclosure IAM 10CFR2 790. GILLELAND. J. E. Tannesses Valley Authority 78/10/16. ip. 74038; 261.
- torract violations noted during inspet#50-259/78-17, 50-250/78-19 % 50-296/78-16. SUTERLANG.J. T. Region 2. Atlanta: Fuel Facility & Materials Sarety Branch. 78/10/31. 1p. 94075:275.
- 94077: 012.
- --7811120018 Forwards IE Inspec Repts#50-259/78-17.#30-260/78-18 & #50-276/78-16 on 780725-28 & Notice of Violation. BUTHERLAND. J. T. Region 2. Atlanta, Fuel Facility & Meterials Sefety Branch. 78/09/15. 2pp. 94075:278
- --7811130022 Notice of Violation from inspec on 780725-98.
  \* Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/10. ip. 94075; 280.
- --7811130049 IE Inspec Repts#50-259/78-17, #50-260/78-18 t #50-296/78-16 on 780725-28 during which i item of noncompliance was noted: release of radicactive affluents above limits.
  TROUP, O. L., GIESON.A.F. Region 2, Atlanta, Fuel Facility t Haterials Safety Branch. 78/09/15, 8pp 94075: 282.
- Aug 1978 editions of Nuc Becurity Sefequerds Newsletter. KENNA M. B. Region 2. Atlanta, Sefequerds Branch. 78/11/17. 4PP.

- 7810310060 Ack receipt of 780127 ltr informing NRC of statement violations noted during Inspec #30-289/77-26. #30-260/77-26 & #50-276/77-26 to The Translate Reactor Operations Nuclea Branch 78/03/01 1p 94094:129
- --7810310064 Responde to 780103 NRC itr re violations not Repts #30-259/77-26, #30-260/77-26 & 50-296/77-26 Corrective actions are esempt from disclosurs due to security into contained in response
  OllLELAND, J. E. Tennessee Valley Authority. 78/01/2: 94094 130
- --7810310069 Forwards IE Inspec Repts #30-259/77-26, #50-296/77-26 on 771213-16 & w/o Notice of Violation.
  - Wheld pursuant to 2.790. LENO.F J. Region 2. Atlanta. Reactor Operations Nuc. Branch. 78/01/03. 200 94094:131.
- --7Bi0310074 lE Inspec Repts #50-239/77-26. #90-260/77-26 on 771213-16 during which I item of noncompliance was vital green area gate was open & unattended. BRADFORD. W H. Ragion 2. Atlanta: Office of the Direct ALDERGON. C.C. Region 2. Atlanta: Reactor Operations Support Branch 78/01/03. 5pp. 94094:133

- 7811130006 Ack receipt of 781010 ltr informing NRC of steps taken to
- --781i130013 Responds to 780915 NRC ltr re violations noted in inspec Repts#50-259/78-17.#50-260/78-18 %#80-296/78-16. Corrective actions: 18 & 3A RHR heat exchanges inspected & task test
- GILLELAND, J. E. Tennesses Vallag Authority. 78/10/10 2pp.

- 7812120051 Forwards reproductions of articles that appeared in June &

- 78:01:0265 Forwards 1E Inspec Rapts#50-259/78-15,#50-260, 296/78-14 on 780625 during which no items of noncomplic wara noted. SUTIERLAND, J. T. Ragion 2. Atlanta. Fuel Fatility & Ma Branch. 78/00/31. 2pp 94079.142
- --7810120004 IE laspec Repts#50-259/78-15.#50-240/78-16. on 780626. during which no items of noncompliance wern Major area inspected: whole body counting practices & procedures & test count of NRC phentom HLLEAP.H J Region 2. Atlanta, Fusi Facility & Matterials. 70/08/30 4pp.
- 78:01:0283 Forwards IE Inspec Rapts#50-259/78-i9.#50-260 /78-i8 on 760720-21 during which no items of noncompli-BUTHERLAND, J. T. Region 2. Atlanta, Furi Facility & Ma Branch. 78/09/01. 2pp. 03555:076
- --7010110206 IE Inspec Repts#50-259/78-198#30-260/78-20, on 780720-21 during which no items of noncompilance noted, Major areas inspected included emergency plann simulated emergency conditions.
  PERROTTI.O. J. Region 2. Atlanta. Fuel Facility & Ma Branch. 78/08/31. 4pp. 94079:144.
- 7811010249 Forwards IE Inspac Repts#50-259/78-20. #50-260 #50-296/78-19 on 780807-10.during which no items of
- noncompliance ware noted.
  LONG.F.J. Region 9, Atlanta Reactor Operations Nucla
  Branch. 78/09/13. 2pp 94392:160
- --7811010280 1E Insp Repts 50-259/78-20,50-260/78-21 & 3 on 780807-10, during which no items of noncompliance noted, Me jor erees inspected; plant operations, reports occurrances & alectrical mods.
  EULIVAN.R.F. Region 2, Atlanta, Office of the Dira 78/09/12. Spp.
- 7810110006 Forwards 1E Inspec Rapt 50-209/78-24.50-260/7 50-296/78-23. O'REILLY, J. P. Region 2. Atlanta. Office of the Direct 200. 94069:246
- --7810110059 IE Inspec Rept 50-259/78-24.60-260/78-27 & 760915. Heating held re TVA security program & manage
- changes being implemented. OILLESPIE.F.P. Region R. Atlanta. Sefeguards Branch 3pp. 94063: 248.
- 7810230024 Ack receipt of 780922 ltr re corrective steps items of noncompliance found in inspec as notified by 1tr of 780825 O'REILLY, J. P. 1p. 94165:093.
- - --7810230227 Responds to 780825 NRC 1tr re violations no Rept#50-259/78-18, #50-260/78-19, #50-296/78-17. OILLELAND J.E. Tennessee Valley Authority. 78/09/3
  - --7810230230 Forwards IE Inspec Repts\$50-259/78-18.450-1 78-17 on 780726-28. O'REILLY, J. P. Region 2. Atlenta. Office of the Dir-78/08/25. 3p. 94165:095.

74145: 094.

Region 2. Atlanta, Office of the Direct

- 7810230300 Forwards IE Circuler#78-17. (Sae AND 7810230221. Docket 50-313. 781013) O'REILLY.J.P. Region 2. Atlante. Office of the Director. 78/10/13 ip 94164: 883
- 7812050169 Forwards IE Inspec Rept#50-296/78-27 on 781017 during which no items of noncompliance were noted MURPHY.C. E. Region 2. Atlanta. Resector Construction & Engineering Support Branch. 78/10/25 ip 94408 299
- --7812050172 IE Inspec ReptW50-296/78-27 on 781017 during which no items of noncomplience ware noted. Mejor eress inspected incl: ultresonic examination of recirculation notable. ECONOMOS, N. CONLON.T.E. Region 2. Attents. Reactor Construction & Engineering Support Brench. 78/10/20 App 94408.300
- 7812050033 Forwards 1E Inspec ReptsN50-259/78-21.M50-260/78-23 & #50-276/78-20 on 780828-0901 during which no items of noncomplience were noted.

  LONG.F.J. Region 2: Atlanta. Resector Operations Nuclear Support Branch. 78/10/27. 2pp. 94034:218.
- --7812050057 1E Inspec Repta%50-259/78-21, #50-260/78-23 % #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted Major arses inspected incl: reportable occurrences % followup on 1E bulletins & circulars.
  BULLIVAN.R.F. 00278.J.E. Region 2. Atlanta. Offics of the Director. 78/10/26 10pp. 94334 220.
- 7811150073 Forwards IE Circular 78-18.

  O'REILLY, J. P. Region 2, Atlants, Office of the Director. 78/11/06.

  ip. 94112:288.
- 7812210355 Forwards IE Inspec Repts#50-259/78-26,#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted.

  KENNA, M. B. Region 2, Atlante, Safeguards Brench. 78/11/08. Rep. 94014:353
- --7812210363 IE Inspec Repts#50-259/78-26.#50-260/78-29 & #50-296/78-25 during which no itame of noncompliance were noted. Major areas inspected incl:physical security requirements previous items:elarm, access.communications.

  BEBECKER:K.H.: 01LLE8F1E.F.P. Region 2. Atlante. Befaguards Branch 78/11/08. 4pp. 94014:355.
- 7812180320 Forwards IE Inspec Repts#50-259/78-25,#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of nontompliance were noted.

  LONG P.J. Region 2: Atlenta: Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94336:285.
- --7812180325 IE Inepsc Repte#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 789725-27 during which no items of noncomplience were noted Mejor erses inaperted incl:refueling plant oper & LER & IE Circulare/Bullatine review.
  BLLIVAN.R.F., DANCE.H.C. Region 2, Atlanta, Resctor Operations Nuclear Bupport Brench. 78/11/09. 6pp. 94356: 287.
- 7812130372 Forwards emended response to IE Bulletin#78-09.describing steps telen to effect a good seal between drywell head & containment flags.
  OILLELAND, J. E. Tennessee Valley Authority. 78/11/13. 2pp. 94272:25.
- 7812040369 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/sec1 AND: 7811300085. G'REILLY, J.P. Region 2, Atlenta, Diffice of the Director. 78/11/24. ip. 94127:177.
- 7812050015 Ack receipt of 781122 itr informing NRC of steps taken to correct violations noted during inspsc#30-259/78-22. #50-260/78-25 & #50-296/78-21. #SUHERAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/28. 1p. 94418:338.
- ~~7812060021 Responds to 781027 NRC ltr re violations noted in Inspec Rept#50-229778-22.850-28078-25 & #50-276778-22 Corrective actions: survaillance instruc sched change to reflect is month testing reg. QILLELAND.J.E. Tennessas Velley Authority. 78/11/22. 3pp. 74418:339.
- --7812060026 Forwards IE Inspec Rept#50-239/78-22, #50-260/78-25 & #50-296/78-21 on 780911-14 & Notice of Violation. BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Befety Branch. 78/10/27. 2pp. 94415:312.

- --7812060033 IE Inspec Rept#50-259/78-22. #50-260/78-25 & #50-296/78-25 on 7809ii-i4 during which i item of noncompliance was noted surveillence testing of ein cleaning eye TROUP, 0. L. JACKBON. L. + 01880N.A.F. Region 2. Atlanta, Office of the Director. 78/10/27 9pp 94415.315
- 7812100248 Forwards requests for relief from ABME Section XI exam requirements that would be conducted per subj facil insectines or a few insectines of reflecting util position will be submitted pending completion of prog
- 7812260014 Forwards IE Bulletin 78-14.
  O'REILLY, J. P. Ragion 2. Atlanta. Office of the Director 78/12/19
  2PP. 94131.032
- R. Pariodic operating reports & related correspondence
- 7810160106 Forwards Monthly Oper Rept for Sept 1978
  DEWEASE, J. G. Tennasses Valley Authority. 78/10/10. 1p. 94004:201
- --7810160109 Monthly Oper Rept for Bept 1978. DEMEASS.J.O. Tennssse Velley Authority. 78/09/30. 34pp. 94002:087
- 7810170161 Monthly Oper Rept for Sept 1978.
  DEWEASE, J 0 Tennesses Valley Authority. 78/10/31. 3lpp. 94236.097.
- 7810300103 Filss fish impingement rept for subj facil for 3rd quarter 1978 OILLELAND J. E. Tennessee Valley Authority. 78/10/19. 14pp. 94035-048
- 7811140137 Forwerds Monthly Oper Rept for Oct 1978, DEWEASE, J. G. Tannessee Valley Authority. 78/11/09. 1p. 94425:275.
- --7811140140 Monthly Oper Rept for Oct 1978 OREEN.D. Tennessee Valley Authority. 78/11/02. 33pp. 94425:276.
- 7812190161 Forwards Monthly Oper Rept for Nov 1978.
  DEWEASE, J. Q. Tennesses Valley Authority, 78/12/02, tp. 94040:180
- --7812190162 Monthly Oper Rept for Nov 1978.

  DEMEASE, J. Q. Tennessee Velley Authority, 78/12/02. 29pp.
  94340: 181.
- B. Reportable occurrences, LERs & related correspondence
- 7810100002 Fowerds LERM78-024/03L-0 FDX-H.S. Tennesses Valley Authority. 78/09/29. ip. 94007:302
- --7810100006 LERM78-024/03L-0 on 78091i: during refueling while performs surveillence instru 81-428-31 2 broken wire was found on signel lawd for RCIC turbine high steam flow switch PDIS-71-19 which provides RCIC isolation. Loose connection repaired. PITTMAN.J.R. Tennesse Valisy Authority. 78/09/29. #pp.
- 7810100042 Forwards LERW78-025/01T-0. FDX:H.8. Tennesse Valley Authority, 78/09/29, ip. 94033:072.
- --TB10100047 LERM78-025/017-0 on 780917: during refueling.4 MBTV's exceeded leakage limits. Defective valves will be repaired & retested.

  \* Tennessee Velley Authority. 78/09/29. 2pp. 94033:073.
- 7810240146 Forwards LERN78-026/03L-0. FOX.H.S. Tennesse Valley Authority. 78/10/20. 1p.
- --7810240151 LERM78-026/03L-0 on 780924: during refusling outage, smoke detector X8-39-9388 slarmed w/o proper cause & could not be classed, due to normal aging.

  \* Tennesse Vallay Authority. 78/10/17. 2pp.
- 7811140165 Supplementary Reportable Occurence Rept SFRO-50-296/7822: on 780822 during stertup at 3 percent thermal pur.MSRV 1-4 opened & did not completely closs resulting in excessive cooldown rate. Caused by excessive pilot lesiege.
  FOX.M. 8. Tennesses Valley Authority. 78/11/08. 3pp. 94383:317.
- 7811140168 Supplementary Reportable Occurrence Rept#BFRO-50-296/7801

--70:1140195 LERM7B-027/03L-0 on 78:012 during refusiting outage panel 3-25-327 wee inoperable placing 2 smoke detector zones out of svc Caused by a contact on power transfer relay which felled to close efter short power interruption

4 Tennessee Valley Authority 78/:1/08 2pp 94384 273

7811140201 Forwards LERW78-028/03L-0 FOX.N 8 Termesser Valley Authority 78/11/08 1p 94384:333

--7611140205 LERN7B-028/03L-0 on 781014 during refust outage 1 amoke detector XB-39-1087E in mach equip room on elevation 617 caused false alam that would not clear. Caused by normal natural aging of detector

\* Tennesses Valley Authority. 76/11/06 2pp. 94384.034.

7811160099 Forwards RON50-296/7822.
FOX:H 8 Tennesses Velley Authority. 78/11/09. 1p 94135:094.

--781(160104 ROM50-296/7822 on 780822 during stertup at 3% thermal pur-MSRV 1-4 opened & did not reclose completely, resulting in sicessive vassel cooldown reta-due apparently to sicessive pilot & second-stage leekege in the velves. • Tenns asse Valley Authority, 78/11/09, ip 94135 095.

7811280294 Forcerée LERM7D-029/03L-0 FDX.H.B Tennesses Valley Authority 78/31/21. ip. 94395: 254.

--7811280298 LERM78-029/03L-0 on 781029; during refueling while reloading fuel in vessal w/ell rode inserted.2 IRM channels were inoperable in seme trip sys IRM F signal cebls were sheered by CRD repeir platform IRM H eignal cable disconnected.

\* Tennesses Velisy Authority 78/11/15. 2pp 94395; 255

7812050199 Furwards LER878-030/03L-0 FDX-H 8. Tennesses Volley Authority 78/11/27 Ip

--7812050201 LER#78-030/03L-0 on 781031 evidence of greeke in 6 enubbers located in core agrey.main stamm & residual heat removal age Bnubbers regisced. Recurrence control action incl replacement of greeke fittings w/those incompetible w/guns. a Tennesse Valley Authority 78/11/27. 3pp. 9433:007.

7812110160 RD-50-296/782: Bendix connectors used inside primery containment which feiled post-aging environ test were modified by potting plug & receptedle portion of connectors & pessed in year quelifyling tests.

FDX:H 8 Tennesses Valley Authority, 78/12/06. 2pp. 94937:006

7812190110 Forwards LERR70-031/01T-0 F0X:H 8. Tennesses Valley Authority. 78/12/11. 1p. 94381:198.

--7812190111 LERW78-031/017-0 on 781128 during CRD scram timing & associated LPRM connect on verification noted that all LPRMs had been connected in reverse order. Caused by lack of explanation in documents describing connection procedure.

b Tennesses Valley Authority. 78/12/11. 2pp. 94381:199.

7812190119 Forwards LERB78-033/03L-0. F0X:H.8 Tennesses Velley Authority. 78/12/13 ip 94376:278.

--7812190122 LERB7B-033/03L-0 on 781114: leekage from 35 isolation valves which terminete below suppression pool water level exceeded inventory restriction of 20781 cubic feet per 30 days. Caused by wearing of seats on velves.

\* Tennesses Valley Authority. 78/12/13. ip. 94376:279.

DDCRET 50-297 NORTH CARDLINA STATE UNIV. PULSTAR REACTOR

G. Inspection reports, IE Duiletins & correspondence

7812010182 IE Inspec Rapte#50-160/78-04.#50-276/78-02.#50-297/78-04 & #70-0386/78-04 on 780926-27 during which no items of noncompliance were noted. Major ereas inspec inclinut matl control & accounting procedures review TODD. 0.4. WILLIAMS.0.H. Region 2. Atlante, Sefeguards Branch. 78/10/20. 3pp. 94409:223.

7810140037 Forwards Inspec Rept 50-297/78-3 on 780817 during which no item of honocompliance was noted.

KENNA-M.B. Region 2, Atlanta- Befeguerds Branch. 78/10/02. Rpp. 74413:034.

HENNEGSEY, R J. OILLESPIE, F. P. Region 2. Atlanta. Safeguarda Branch 78/10/02 5pp 94413:035

DOCKET 50-298 COOPER NUCLEAR STATION

CECUPITU PIAN

E. NRC Barety Evoluation Report (SER), supple & correspondence

7811270041 Review of augmented main eteam isolation valve rept has determined that midcucle MSLIV leak testing is no longer required. IPPOLITO. A Operating Reactors Branch 3 (Pre 790625). 78/11/01. 2pp 94253:337.

--7811270043 "Bafety Eval Rept of Main Stream lepletion Valve Test Results." Util request for continuing CNB in present fuel cycle for add1 mid-cycle MBLTV leak test is approved. \*\* Operating Reacture Branch 3 (Pre 790625). 78/11/01. 2pp 94233-359

## F. Becurity, medical, amergency & fire protection piens

781122024D Presents results of 781013 meeting re-fire protec. W/anci attender list, staff review positions egreed to by licenses treview positions licenses agreed to consider further. IFPRLITO. T. A. Dereting Reactors Branch 3 (Pre 790825). 78/11/01. 1208

7812130166 Submits data requested in 781120 NRC ltr re fire inspec review. Subj incl:self conteined breething apparetus, fire senergency radio communication, manual foam suppression & conduit risers in battery room.
PILMNT.J.M. Nebreska Public Power District. 78/12/11. 232p. 94303-144.

P. Operating license stage documents & correspondence

7010130233 Notice of Issuence of Amend#52 to Facil Oper LicwDPR-46 on 780929.

IPPOLITO.T.A. Operating Resctors Branch 3 (Pre 790625). 78/09/29.

ZPP 94081 342

7810130266 Forwards Amend #52 to Facil Open Lic #DPR-46, as requested in 770722 ltr.Bafety Evaluation & Notice of Issuence. IPPOLITO T. A. Operating Reseture Branch 3 (Pre 790625). 78/09/29.

--7010140015 Amend 852 to Feril Oper Lic WOPR-46 revising tech space fs: increase in storage capacity of spent fuel pool from 740 to 2366 fuel essemblies. QRINES, O.K. Assistant Director for Engineers & Projects (Fre 7906251: 747/07/29, 4pp. 94003:171.

--7810140018 Safety Evaluation Rept supporting Amend #52 to Fecil Oper Lit #DPR-46 concludes that installation & use of new Pest recks can be accompished safety & health & sefety of pub Will not be endangered. # Office of Nuclear Reactor Regulation, Director. 78/09/29. https://doi.org/175.

--7810140021 Environ impact Appraisal for Amend#52 to Facil Oper Lic# DPR-46 concludes that increase in storage capecity for east fuel pool will not effect quality of human environ.

- Office of Nuclear Reactor Regulation, Director. 78/09/29, 32pp. 94003;169.

--7B10140024 Notice of Issuence of Amend #52 to Facil Open Lic #DPR-46 & Negetive Occianation. IPPOLITO, T. A. Openating Reactors Branch 3 (Pre 790625). 78/09/29. 22pp. 94322:306.

7B10170152 Responds to 7B0807 NRC ltr re subj facil reactor protec syspur supply. Possibility is remote for undetected or seismic releted failures. Probability & possible effects are still under enalysis. No facil mode are proposed at this time. PILANT.J. N. Nebraska Public Power District. 7B/10/06. 2pp. 94235: 089.

7810120037 Requeste revision of radiological Tech Specs change primary containment & reactor vessel isolation tables amergency plan drills & organization chart Changes are Class 2 amend. PILMI-J.M. Nebraska Public Power Oistrict. 78/10/09. Bpp. 94332:306.

- 7811130335 Summary of 780914 meating w/GE representatives & Mark 1 Owners Group re propress of Long Term Prog u/attendance list & agenda(RD-9-A-Marti).Standards. 1 GRIMEB.C. Plant Systems Branch (Pre 7910301. 78/10/26 67pp
- 7811020253 Forwards add1 info re exemptions from requirements previously unacceptable covering personnel atriock-bellows lestages & water testing for feedwater check valves M/ oversize drawings PILMT-J M Nebraska Public Power District. 78/10/30 lipp 94247 126.
- 7811140130 Responds to 780918 itr requesting add1 info re Quality Assurance Prog. Add1 info will be submitted by 790115 re exceptions which licenses will take relative to requirementa contained in the "Orange Book."
  PILMIT.J.M. Nabraské Public Power Olstrict 78/11/09 8pp. 94425: 239
- 7811200115 Forwards new proposed Tech Specs, amplified because of new 10CFR30 44 Asis NRC to disregard earlier proposed. Changes gertain to Atmospheric Containment Atmosphere Dilution (ACAD)sys for subj facil. PILANT.J. M. Nebraska Public Power Oistrict. 78/11/14. i3pp 94220:233
- 7812010122 Forwards analysis in support of functional form used in the canterlins temp rise relationships for the thermal plumas. Also attached are canterline temp rise plots showing actual field data points from past monitoring years.

  PAILY-P.P. Hazelton Environmental Briences Corp 78/11/15. 10pp. 94418 027.
- 7812150139 Notice of workshops is implementation of training & qual requirements contained in Append B of 100FR73. Requests pre-workshop registration of attendees to facilitate sending out matt. Wienci Registration Form & List of Locations MILLER-J. R. Assistant Director for Bits & Bafaguards (Pre 791030), 78/11/15 Spp.
- 7812180271 Forwards Rev#l "Oraft Radiological Effluent Tsch Bpacs" for BMR's(NMREO-0473) & "Preparation of Radiological Effluent Tsch Spacs for Nuc Pur Plants" (NMREO-0133), GRIMER, B.K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15 6pp. 94366:079.
- 7812040196 Requests that the rept NEDE-23898-P. "Analytical Model for Computing Water Riss in a Bafaty/Relief valve Discharge Line Following Valve Closure." be utilized in containment eval prograe.
  PILANT.J.M Nebraska Public Power District. 78/11/27. ip. 94457:128
- 7812060148 Requests Radiological Tech Space be rev to incl proposed changes re primary containment surveilience instrureactivity control testable penetrations w/double O-ring
  seels & safety related Hydraulic Shock Byppressors.
  PILANI.J.M. Nebraske Public Power Oistrict. 78/11/29. iipp.
  94382.056.
- 7812110018 Discusses possible dangers of LUCA in containment purging during normal plant oper Requests either commitment to purging or justification for continuing Wiencl ANG: e7812080207

  IPPOLITO.T. Operating Reactors Branch 2 (Pre 790625) 78/11/29. 6pp. 94339:265.
- 7812140174 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. SOSON,L.J. General Electric Co. 78/12/04, 11pp.
- 7812110197 Forwards request for add1 info re 781109 submittal of quality assurance prog for subj facil. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/05. 3pp. 94408:055.
- 7812280105 Emphasizes importante of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses—must notify NRC of any inaccuracies or enforcement action will result. DAVIS, J. Q. Office of Inspection & Enforcement. Dffice of the Director. 78/12/05. 2pp. 03555:321.
- 7812260031 Forwards request for add1 info re suppression pool temp transients in order to complete review of topical rept NEDE 21072P "Test Results Employed by GE for BMR Containment & Verticel Vent Loads."

  DAVIS.O.K. Operating Reactors Branch 2 (Pre 790625). 78/12/13. 4pp. 94020:357.

- 7812270328 Responds to 781205 itr requesting addl info re Guality Assurance prog for subj facili PILANT.J.M Nebraska Public Power District 78/12/21 App. 94232 021
- 7011210367 Forwards edd1 info re multiple consecutive safety/relisf valve actuation of Hark 1 containment program.
  8080N-L J General Electric Co 78/11/13 3pp.
- Q Inspection reports. IE Bulletins & correspondence
- 7810140132 Forwards IE Inspec Rept#50-298/78-14 on 780818 during which no items of noncompliance were noted.

  MADEEN.O L. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/08/22 2pp. 94422 084.
- --7010140133 IE Inspec Rept#50-298/78-14 on 760818 during which no items of noncompliance were noticed Major areas inspec included ray of IE inspec prog.licensee's snforcement history, assessment of ilcansee's performance & implementation of security plan. SEYFRIT.K V. AMDSEN.C.L. JOHNSUN.E.H. Region 4, Dellas, Office of the Director. 78/08/22 2pp 94422 086
- 7810120012 Forwards IE Inspec Rept#50-298/78-13 on 780815-18 & Notics of Violation MADES.Not. Region 4. Oallas. Reactor Operations Nuclear Bupport Branch. 78/08/29. 2pp. 94421:195.
- --7810120014 Notice of Violation from inspec on 780815-18 \* Region 4, Dallas, Vendor Inspection Branch, 78/08/29, 2pp. 7442:197
- --7810120016 IE inspec Rept#50-298/78-13 on 780815-18 during which 4 ltems of noncompliance were noted activities in Tech Spec 6 2 8 4 not rev by Bafety Rev & Audit Board & lic procedures not adhered to for rev of design changes.
  JCHNSON, E H , KELLEY, O. L. , MADER, O L. Region 4. Dallas, Vendor Inspection Branch. 78/08/29 12pp 94421-196
- 7811060051 Forwards 1E Inspec Rept#90-278/78-19 on 780928-30 & notice of deviation MDERN, O.L. Region 4. Oallas, Reactor Operations Nuclear Support Branch, 78/09/12 2pp. 94423,306.
- --7011060053 Notice of Deviation from inapec on 760828-30

  \* Region 4, Delias, Reactor Operations Nuclear Support Branch.
  78/09/12 ip. 94423:308
- --7811060055 IE Inspec Rept#50-298/78-15 on 780828-30 during which I ltd of noncompliance was noted: Pallura to maintain 2 fire doors in an operable status as req by Natl Fire Code.

  JCHNSQN,E H., VERDUZCO.O H., MADBEN.O L. Region 4. Dallas, Reactor Operations Nuclear Bupport Branch. 78/09/12. 6pp. 94423:309.
- 7B10110011 Forwards IE Bulletin #78-12 requiring action by util. 8EYFRIT.K. V. Region 4. Oalles. Diffice of the Director. 7B/09/29.
- 7810230209 Ack receipt of 780919 itr informing NRC of Steps taken to correct deviations noted in Inspsc Rept#30-298/78-13.

  HADEN.Q L. Region 4. Oallas, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94488:336.
- --7810230213 Responds to 780829 NRC ltr re violations noted in Inspec Rspt#80-298/78-13. Corrective actions: document control test of valves AR-153AV & AR-154AV PILANT.U, M Nebreske Public Power District. 78/09/19. 6pp. 94888 338
- 7810200276 Forwards IE Circular#78-17. (Bas AND. 7810230221 Docket 50-133.781013)
  8EYFRIT.K. V. Region 4. Dallas, Office of the Director. 78/10/13. 1p. 74174:355
- 7811200325 Forwards IE Inspec Rept#50-298/78-16 on 780927-29 & Notice of Violation which is withheld from public disclosure.
  MADEN/O.L. Region 4. Delias, Reactor Operations Nuclear Support Branch. 78/10/18. 2pp. 94251
- --7811200330 IE Inspec Rept#50-278/78-16 on 780927-29 during which a noncompliance was noted in the area of Physical Barriers.

  Details are withhald from public disclosure.

  HATD, J. J., CALDMELL, R. A. EVANS, E. A. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/10/19. 1p. 94251:025.
- 7811080106 Ack receipt of 781003 itr informing NRC of steps taken to correct deviations noted in Inspec Rept#30-278/78-15.

  MADSEN.O.L. Region 4, Dalles, Reactor Operations Nuclear Support Branch. 78/10/25. 1p. 94099: 138.

- #30-298/78-15. Corrective ections: hose removed from do PILANT. J M. Nebrasia Public Power District. 78/10/03. 2pp.
- 7812160348 Forwards IE Inspec Repts#50-298/78-17 on 781002-05 during which no items of noncompliance were noted. MADEEN, G. L. Region 4, Dalles, Reactor Operations Nuclear Support Branch. 78110/30. 2pp. 74336.043
- --7812180350 Notice of Violation from inspec on 781002-05 » Rapion 4. Deltas. Reactor Operations Nuclear Support Branch 78/11/27. ip. 94356:045.
- --7812180356 IE Inspec Repts#50-298/78-17 on 781002-05 during which 2 items of noncompliance uses noted:failure to follow procedure for control of valves in liquid control sys & to sched requal lectures for ic operators. JCNNSON, E. H. Region 4, Dallas. Resctor Operations Nuclear Support Branch. 78/10/27. 8pp. 94356:046.
- 7811130079 Ack receipt of 781031 itr informing NRC of steps taken to correct violations noted during inspected0-298/78-16.
  MADEEN.Q.L. Region 4. Dallas, Reactor Operations Nuclear Support
  Branch. 78/11/03. 1p. 94076: 324.
- 7811220124 Forwards IE Circulare78-18. "UL Fire Test. " W/enc1 AND:7811130002 BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 78/11/06. 1p. 06911:001.
- 7811270123 Ack receipt of 780918 & 781025 ltrs informing NRC of steps taken to correct violations noted during inspec 450-298/78-13. MADEEN.Q L. Region 4. Dalies, Reector Operations Nuclear Support Branch. 78/11/13. tp. 94271:285.
- --7811270129 Responds to 780829 NRC itr re violation noted in Inspec Rept \$50-298/78-10. Corrective actions: QC procedures will be written. QC prog objectives, responsibilities & requirements clarified. Pilant, J. M. Nebraska Public Power District. 78/10/25. 2pp. 94271: 284
- 7812210180 Forwards IE Inspec Rept#50-298/78-18 on 781030-1102 during which no items of noncompliance were noted.
  MADBEN.G.L. Region 4, Dallas. Reactor Operations Nuclear Support Branch. 78/11/17. 2pp. 94278:323.
- --7812210184 IE Inspec Rept#50-298/78 on 781030-1102 during which no items of noncomplience were noted Major areas inspected inclinations, follow-up on IE Bulistins, Circulars, open items. unresolved items & prior deviations.
  JONNBON.E.H., CUPP.E.A. MADEN.O.L. Region 4, Dellas. Reattor Operations Nuclear Support Branch. 78/11/17. 7pp. 942/8:025.
- 7812060261 Forwards (E Bulletin#78-12e.suppl to IE Bulistin#78-12. w/encl AND: 781100055. ## Ancl AND: 781100055. SEYFRIT, K. V. Region 4. Deiles. Office of the Director. 78/11/24. 1p. 94371: 342.
- 7812060049 Ack receipt of 781120 ltr informing NRC of steps teten to correct violations noted during inspection-298/78-17.

  HADREN G. L. Region 4. Dallas; Resctor Operations Nuclear Support
  Branch. 78/11/29. 1p. 94234:061.
- --7812060052 Responds to 781030 NRC ltr re vibietions noted in Inspec Rept850-298/78-17. Corrective action: seeled open valve SLC-10 was closed per surveillance procedure & the seel removed & not replaced. PILANT, J. M. Nebraska Public Power District. 78/11/20. 2pp. 94234: 062.
- R. Pariadic operating reports & related correspondence
- 7810170268 Forwards Monthly Oper Rept for Sept 1978. LEBSOR, L. C. Nebresta Public Power District. 78/10/05. 1p. 94242:194.
- ---7810170299 Monthly Open Rept for Best 1978.
  BORER, P. J. Nebraska Public Power District. 78/10/05. App. 94242: 195
- 7811160113 Forwards Monthly Oper Rept for Oct 1978. LEBBOR.L.C. Nebraska Public Power District. 78/11/03. ip. 94135:140.

Negraska Public Power District. /8/11/03

7812130158 Forwards Monthly Open Rept for Nov 1978
LEBEOR.L.C Nebraska Public Power District. 78/12/06. 1p. 94305 115

HINEK, P.J.

94135: 161.

- --7812130160 Monthly Oper Rept for Nov 1978. BCRER, P. J. Nebraske Public Power District. 78/12/06. 4pp. 94303 116.
- B. Reportable occurrences, LERs & related correspondence
- 7812120121 Notification of deficiency found 780913 in valve cross assemblies, inlet & exhaust push assemblies of KSV Pur Engine & corrective action to design roller pin & replace hand flaring oper. BENDER. B. B Cooper Industries. Inc. 78/11/03. 2pp. 94275:329.
- 7810300173 Forwards LERM78-030/03L-0. LESBOR, L. C. Nebraska Public Power District. 78/09/12. 2pp. 94034: 236
- 7810300201 Forwards LER#78-029/03L-0. LESSOR, L. G. Nebraska Public Power District. 78/09/12. 200. 94033: 319.
- --7810300229 LERW78-029/03L-0 on 780814: Core Spray Time Delay Reley did not operate win req time limits Caused by typs of relay usedirelay does not operate property after periods of inactivity Design change baing prepared to replace relag-PHILLIPS, D. L. Nabraska Public Power District. 78/09/12. ip. 94033, 321.
- 781R090166 Forwards LER#78-031/03L-0. LEB#0R.L.C. Nebraska Pubilc Power District. 78/09/28 2pp. 94335: 115.
- --7812050170 LER#78-031/03L-0 on 780912: Cooper-Bessemer dissel sagins type KSV-16-T main bearing overheated Main hearing#10 was damaged dua to minimel oil flow during engine coestdown. Caused by foreign particles in oil. BEDNAR.L.F. Nebraska Public Power District. 78/09/28. 1s. 94035: 117.
- 7810300177 LERATS-030/03L-0 on 780815:13 primary containment genetrations were identified which were not leak tested. Panetrations were not identified in preoper testing. Penetrations added to Test Spec Table 3.7.2 will be tested. PHILLIPS.D.L. Nebraska Public Power District. 78/09/12. Ip. 94034: 238.
- 7812050135 Forwards LER#78-032/03L-0. LEBBOR.L.C. Nebraska Public Power District. 78/10/13. 299. 94335-D57
- --7812050138 LER#78-032/03L-0 on 780918: during normal oper.efter cooling down the torus. RHR Heat Exchanger 1B BypassBRHR-MO-66B failed to open due to loose set screw on yoke of Limiterque 849-3 operator BARNUS, C. Nebraska Public Power District. 78/10/13. 19-94335:09-
- 7812030144 Forwards LERR78-033/03L-0. LEBBORLL.C. Nebraska Public Power District. 78/11/13. 2pp. 94334: 352.
- --7812030145 LER#78-033/03L-0 on 781016: cable HP58.Dlv 1, was found route thru Div II riser under panel 9-3. Caused by personnel error during constr. Redundant sys were operable. BEDNAR, L. F. Nebraska Public Power District. 78/11/13. 19. 94334-354.
- 78:2200259 Initial Notification of Reportable Occurrence 50-298-78-25 DIRECTORY Initial Notification of Reportable Occurrence 20-278 on 781124. Recirculation MO Bet 8 was tripped, then a fuse was publisd for exam, allowing MO Bet 8 to ramp up in speed, causing fast per increase. Due to personnel error. LEBOOR. L. C. Nebraska Public Power District. 78/11/29. 2pp. 42004-000 94204: 002.
- 7812290197 Forwards LER#78-034/03L-0. LESBOR:L.C. Nebraska Public Power District. 78/12/07. 25p. 94190: 185.

Control Red Upersolity's Control Foo Soul was very uncoupled from its control red drive. Cause cannot be determined until control rod drive is removed & examined. BALLINGER.P. Nebraeka Public Power District. 78/12/07. ip. 94190 187.

- 7812200271 Farwards LER#78-039/01T-0 LESSOR,L C. Nabraeta Public Power District. 78/12/08 2pp
- --7812200274 (ER#78-035/017-0 on 781124 while checking RR MO Bet 10 speed control.) amp fuse(F2) in drive amplifier circuit was pulled out & checked Caused rapid increase in pur level, tripping RR MO Set 10 BEDNER, L. F. Nebraska Public Power Dietrict. 78/12/08. Ip 04077 149

OCCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 7811150167 Forwards copies of RevAB to Energency Plan Manual. 8URGTEIN.8 Wisconsin Electric Power Co 78/11/06. 2pp. 94223.001.
- --7811150173 Rev#8 to Emergency Plan Menual covering reporting of radiat incidents & amergencies to Reg agencies med assistence, minor radiat incidents major radiat emergencies & gen health physics procedures before the physics procedures 2 Histories Teatric Power Co 78/09/13 222pp. 94223-003.
- 7812260169 Forwarde RevM9 to Emergency Pian Manual for subj Pacil to to replace outdated pages of Manual.
  BURSTEIN.8. Wisconsin Electric Power Co. 78/12/14 2pp. 94159:294
- --7912260172 Rev#9 to Emergency Pien Manual for eubj fecil replacing outdated pages of Menual.

   Historian Electric Power Co 78/12/14 9pp. 94139: 296
- G. Adjudicatory correspondence
- 7812040183 Diemisses Contention#4 of intervenors; susteine objections raised by applicant MIEP to intervenors' Contention#10 & intervenors' intervenors at their Contention#9 Contentions concern security plane & haeith care plans.
  MILLER.M E Atomic Bafety and Licensing Board Panel 79/11/17
  4pp. 94457.081.
- 7812080173 Divae notice that effective 781122.8 Berson withdraws as NRC representative in proceeding re subj facil Certificate of 8vc enci.
  8ERSON.B.A. Office of the Executive Legal Director. 78/11/17. 3pp. 94107:255.
- 7810110017 interrogetories propounded to Applicant re environ & safety espects of proposed facil.
- espects of proposed facil.

  Affiliation Unknown. 78/09/27. 12pp
- 7810110018 NRC Staff first eet of interrogatories to & Request for the production of documents from St of Wi. Case involves amand to LittNOPR-24 & 27 re increesed epent fuel storage capacity BERBON.9. A. Office of the Executiva Legal Director 78/09/29 130s
- 7810110023 NRC interrogetories to & request for production of documents from intervenor Lakeshore Citizens for Safe Energy. Admitted contentions also submitted BERSON.B.A. Office of the Executive Lagal Director. 78/09/29 39pp. 94063:091.
- 7810110072 NRC Staff Interrogetories to & request for the production of documents from applicant per IOCFR2.7406 re amend to lic #DPR-24 & DPR-27. Admitted contentions also submitted DERSON S.A. Office of the Executive Legal Director. 78/09/29. 14pp. 94061:116.
- 7810130225 Bubmission of interrogatories by applicant WIEP to intervenor Lakeshore Citizens for Bafe Energy. Interrogatories addressed to contentions contained in intervenor's amended contentions.
  TROMBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge. 78/10/02. 6pp. 94081:345.

Lakashors Citizens for Bafe Energy's admitted contentions LAFQ.LETTE.8 C. WALSH.P. Wisconsin. State of. 78/10/02 3pp. 94005-319.

stark a corretor to their matter of bath intorvation

- --7810190088 Interrogs asked of applicant WMPC by St of WI pertaining maint of spent fuel pool in particular danger from radiat emission & asposure.

  WALSH P Wisconsin. State of 78/10/02. 10pp.
- 7810230326 Applicant.HI Elac Pur.objections to interrogs submitted by Intervenor.Lakeshore citizens for safe energy, are stetad. Objectione based on Interrog's relience on contentions that were rejected by ASLB or are still being argued.
  TROUGRIDGE.O.F. Shaw. Pittman. Potts & Troubridge 78/10/12 6pp 74194-179
- 7810260222 NRC advises NASL8 that issuence of SER & environ assessment will be delayed until Dec 1978 due to reordering of NRC tech staff's priorities wirespect to review efforts on pending epple. Delay has been discussed wiapplicant's representative BERBON.B A. Office of the Executive Legal Director 78/10/17 ip 94058: 183.
- 7811200275 "Lakeshore Citizens for Safe Energy Responses to the NRC Staff's First Sat of Interroge." Urgee evaluation of airborne emissions which add to existing background radiet Cert of Svc anci SCHAEFER.H. Lakeshore Citizens for Safe Energy. 78/10/25. 22pp. 94250: 280
- 781120026B "Lekeshore Citizens for Safe Energy Responses to the WI Elec Pur Co's First Est of interrogs " Definee "increased worker activity" re spent fuel pool activities ESTES, J. Lekeshore Citizens for Safe Energy 78/10/26 4pp. 94250:271
- 78i1i50262 "Applicent's Anguars to interrogs Propounded by Intervenor on 780927" Cert of Svc encl NEWTON,R A Wisconsin Electric Power Co. 78/10/27, 6ipp 94273, i67
- 78:ii:30089 Answer by NRC Staff to interrogs of 8t of WI re contentions of Lakeshore Citizene for Sefs Energy who oppose amends to lice for subj facil concerning increase in spant fuel storage cepacity Affidavite & Cart of Svc enci.

  BEREON-B A Office of the Executive Lagel Director 78/11/01 550p. 94113.200
- 7811240119 Applicant HIEP's answere to interogs propounded by 8t of HI on 781002 re amend to lice for subj facile to increase spent fuel storage cepecity. Supporting documentation & Cert of Svc anci NEWTON,R A. Hieconein Electric Power Co. 78/11/01 39pp. 94449 201.
- 7812040344 Forwards Affidavits of CM Trammell & FM Altmeter of NRC Staff.
  BER80N.B.A. Office of the Executive Legal Director 78/11/08 4pp 94131.011.
- 7812050049 Applicant's answers to 780929 NRC interrogs related to LickOPR-24 & MDPR-27. Increasing Spent Fuel Storage Capacity. W/list of names baciground & professional quals of witnesses & answers related incremental eirborns releases. NEWTON.R.A. Wieconsin Electric Power Co. 78/11/08. 23pp. 94374:188
- 7812140359 Sweare that lieted persons have been authorized by intervenors LACSE to respond to interruge submitted by ARC Breff & applicant WIEP re LACSE contentione BABT.8.A Lekeshore Citizens for Bafe Energy. 78/11/13. ip 03557:203.
- 7812270050 St of WI's Answers to NRC Staff's first set of interroge & request for production of documents. St has not yet located qualified uitnesses re edmitted contentions. Cert of Svc enci.
  WALDI, P. Wisconsin, State of 78/11/14 3pp 94160:261.
- 7812270452 Intervenors request NASLB for leave to w/draw.intervenor, WEPCO.NGC etaff & St of WI move NASLB to enter order to approve w/drawel of Intervenor as party & enter Order dismissing proc. Agreement & Cert of Svc encl.
  BABLS.A. Lakeshore Citizens for Befe Energy. DARTH.C.A. Office of the Executive Legal Diractor. CHRCHILL.B.W. Wieconsin Electric Power Co. 78/12/13. 9pp. 94016:008.

#### H. General correspondence

- 7B1214036B Requests copies of NUREG-0410 & NUREG-0471. BUBT.B.A Laignhore Citizens for Safe Energy. 7B/11/13. ip. 03557:244.
- P. Operating license stage documents & correspondence
- 78iii40i33 "Anelysis of Capsule R from HI Elec Pwr Co Fecility Reactor Vessel Radiation Survetliance Progrem." YANICHKO, S. E., ANDERSON-B.L. Hestinghouse Electric Corp. WCAP-9357. 78/08/31. 62pp. 94383:176.
- 78ii170297 Forwards rough dreft workingsepers on subj facil emended Security Plan, intended eciely for use of UR Berggren. Commente withheld from public disclosure pursuant to 2,790. ROBE D. 9. Los Alemos Scientific Laboratory. 78/ii/01. 3pp. 02766:230.
- 78:2010225 Requests amend to Fecil Oper Lic to incorp changes to Tech Bpecs. Changes consist of rev to reactor coolent sye heatup & cooldown limitation curves for oper of subj fecil. M/check for 44.400.00.

  BURBTEIN B. Wieconsin Electric Power Co. 78/11/16. 6pp. 94409-326
- 7810220016 Request for additinfo re expension of spant fuel pool storage capacity, which will req on-site neutron attenuation testing of boron plates that are to be in pool, removal of which will raq spacial rept to NRC SCHENCER, A. Operating Reactors Brench i (Pre 790620). 78/10/03. 360.
- 7810170153 Responds to 780913 ltr requesting sched for submittel of rev ECCB cooling performence enalysis Submittel of completed ECCB analysis to NRC will be on or before 790112 Analysis will use new Hestinghouse ECCB swal model.

  BURSTEIN, B. Wieconsin Electric Power Co. 78/10/10. 1p. 94236:08B.
- 7810230272 Forwards responses to requests for edd1 info re spent fuel storage expansion plans for subj fecti. Discusses fuel loading limits radiet dose in Borafles piste, thickness of stainless steel inner can fuel region dimension.
  BURBIEIN 8. Hisconein Electric Fower Co. 78/10/10. 44pp. 94167: 136.
- 7810190130 Forwarde copy of 780510 ltr from eubj facil to Univ of WI. COLLING.P.F. Operator Licensing Branch. 78/10/11. ip. 94414:027.
- --7810190133 Requeste copy of 780510 ltr be sent to Univ of MI. Ack 780609 it to MI Eisc hes been pieced in Univ of MI. JACOBBON. N. Affiliation Unknown. 78/09/23. ip. 94414:028.
- --7810190136 Responde to 780413 NRC ltr re admin of licensed Oper Requal Prog. Nine examinations were regraded IAW conversations of 780420 & 21.Results of the regrading ere attached. Regraded scores will be used as record scores. REED. 9.A. Wisconein Electric Power Co. 78/05/10. épp. 74414:029.
- 7810190101 Dutlines egraement reached re proposed use of rod benke ewap measurement technique to confirm adequate reactor shutdown capability. Technique to be used for subj facil only further use must obtain NRC generic approval.

  SCHMENCER.A. Depreting Reactors Branch 1 (Pre 790625), 78/10/12, 4pp. 94413: 272
- 7810310016 Bummarizes meeting on 780929 re Westinghouse rod bank ewap measurement prog.
  ROBENTHAL. J. E. Reector Sefety Branch (Pre 791030). 78/10/13. App. 94094: 326.
- 7811130203 Forwards Tech Spec change Request 54 to DPR-24 & DPR-27. Tech Spec 15.3.15 "Giverpressure Mitigating Sye Oper." entl outlining functional requirements & limiting conditions for oper re-pressurizer pur operated relief valve.
  BURSTEIN S. Misconsin Electric Power Co. 78/11/02. 14pp. 03554:001.
- 7811140124 Forwards reactor matte surveillance capsule test repte for subj facils. Conservatism in the curves used to predict the change in transition temp as a function of fluence is clearly demonstrated by the results.

  BURBIEIN 8. Wieconsin Electric Power Co. 78/11/08. 3pp. 7438(; 113.

- 7812150203 Notice of workshops to implementation of training & qual requirements contained in Append 8 of iOCFR73. Requests pre-workshop registration of attendess to facilitate sending out math. H/anci Registration Form & List of Locations. HILLER. J. R. Assistant Director for Site & Bafeguards (Pre 791030). 78/11/15. 5pp.
- 7812190060 Forwards Rev81 "Draft Radiological Effluent Tech Space" for PMR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Space for Nur Pur Plante" (NUREG-0133).

  ORINES-8.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94215:095
- 7812050188 Request to amend Facil Oper Lic to incorp changes to Tech Black retesting of containment legistion valves valve & pump teeting code requirements, mein steam stop valve periodic testing & auxiliary feedweter pumps testing. BURSTEIN-9. Misconsin Electric Power Co. 78/11/27. 11pp. 94336-112.
- 7812150008 Discusses presible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. M/encJ ANO 97812080207.
  8CHMENCER, A. Operating Resctors Branch 1 (Pre 790625). 78/11/28. 6pp. 94209:230.
- 7812210320 Forwards request for add1 info re out; Facil expension of Spent Fusl Storage capacity.

  8CH-ENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/06.
  5pp. 03556: 104.
- 7812270389 Responds to 781113 request t encl "Generic Task Problem Descriptione" (NUREG-0471)t "NRC Prog for Resolution of Generic Issue Related to Nuc Pur Plants" (NUREG-0410). W/a encl.

  8ARTH-C.A. Office of the Executive Legal Director. 78/12/06. 1p. 94227: 286.
- 7812280060 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicents. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any ineccuracise or enforcement action will result. DAVIS.J. Q. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94085:360.
- 7812290110 Ack receipt of 781116 app1 for amend to Lics#DPR-24 & 27. Requests addi 93600 lic fee. DIOGSR, M. License Fee Hanegement Branch. 78/12/20. lp. 94491-358
- Q. Inspection reports, IE Bullstins & correspondence
- 7810270371 Forwards 1E Inspec Rept #50-301/78-19 on 780907-08 during which no items of noncomplience were noted. FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Brench. 78/09/20. 2pp. 94030:178.
- --7810270376 IE Inepec Rept 50-30i/78-19 on 780907-D8 during which no iteme of noncompliance were noted. Hajor arese inspected included reactor physics test performed prior to full pwr oper for Cycle 5.
  KGLER, J. E., STREETER, J. F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/19. App. 94030:180.
- 7810130054 Ack receipt of 780911 ltr informing NRC of eteps taten to correct violations noted in itr of 780822 re noncompliance to rev of ladequecy of the weld repair.

  KEPPLER J. G. Region S. Chicago. Defice of the Director. 78/10/05. ip. 94421:026.
- 7810190079 Forwards IE Inspec Repts #50-266/78-14 & #50-301/78-18 on 780822-25. Notice of Violetion w/held pursuent to 10CFR2.790. HIND, J. A. Region 3, Chicago, Safeguards Branch. 78/10/10. 2pp. 94007:023.
- 7810230332 Forwards 1E Circular#78-17. (Sas AND: 7810230821, Docket 50-313.781013)
  KEPPLER, J. O. Region 3, Chicago, Office of the Director. 78/10/13. ip. 94181;355.
- 7811210415 Forwards IE Inspec Repts850-266/78-15,#50-301/78-20 on 780911-15 during which no items of noncompliance were noted. FIORELLI,Q. Region 3. Chicago, Reactor Operations Nuclear Support Brench. 78/10/16. 2pp. 94483:132.

-- TOURS AND A MANAGEMENT OF COMMING TO SHAPE BY CLASS CO. Provide Barreto

- -- 7811210436 IE Inspec Rapts#50-266/78-15,#50-301/78-20 on 780911-15 suring which no items of noncompliance were noted. Major areas inepected included: plant oper, procurement, nonroutine event & safety injection reset procedures. CHOWLES, M. C., HUGHES, J. WARNICK, R. F. Region 3, Chicago, Office of the Director. 78/10/14. lipp. 94483:134.
- 7811070374 Responds to IE Bulletin#78-12 dtd 780929 re atypical weld eatl in Reactor Pressure Vessel welds Vessels in out / facil antidate the atypical matis of the matter does not apply. BURSTEIN, B. Hisconsin Electric Power Co. 78/10/26. 6pp. 94043: 265.
- 7811060072 Notice of Violation-failure to rept a eighificent fish kill-appended to 780612 itr is retracted. Thirty six fish killed is not significent to warrant a rapt. KEPPLER, J. G. Region J. Chicago, Office of the Director. 78/10/31. 19. 94423:354.
- 78:11:5007: Forwards IE Circular 78-18.

  KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/11/06.

  1p. 94112:272.
- 7812290068 Forwards IE Inspec Repts #50-266/78-22 & #50-301/78-23 on 78/017-20 during which no flees of noncompliance were noted.
  FIORELLI, 9. Region 3. Chicago, Reactor Operations Nuclear Support
  Branch. 78/11/22. 2pp. 94190: 047.
- 7812290074 JE Inspec Repts #50-266/78-22 & #50-301/78-23 on 781017-20 during which no items of noncompliance were noted. Major areas inspected incl: Celibr & surveillance of safety related components and equip. BIRETER, J. F., BMITH, J. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/20. Spp. 94190:049.
- 781200027) Forwards IE Sulletin#78-12A. suppl to IE Sulletin 78-12. W/ancl AND: 7811300058-KEPPLER. J. G. R 1p. 94202: 218. Region 3. Chicago, Office of the Director. 78/11/24.
- 7812290022 Forwards 15 Inepac Rept#50-266/78-21 & #50-301/78-22 on 781023-26 during which no items of noncompliance were noted.
  FIORELLI, 9. Region 3. Chicago, Reactor Operations Nuclear Support Brench. 78/11/24. 2pp. 94207:352.
- -7812290032 1E Inspec Repts#50-266/78-21 & #50-301/78-22 on 781023-26 during which no items of noncompliance were noted. Major average which no items or noncompliants were noted. Rejoi areas inspected incliquality assurence progrescords, noncotine event followup & noncompliance followup.

  CHOULEB, N. C., HARNICK, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/21. 6pp. 94207:334.
- 7812280036 Forwards 1E Sullstin 78-14.
  KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/12/19. 1P. 94133:216.
- R. Pariodic operating reports & rejeted correspondence
- 7812120085 Forwarde Monthly Open Rept for Nov 1978. SURSTEIN-8. Wieconsin Electric Power Co. 78/12/08. 1p. 94274:181.
- -7812120087 Monthly Oper Rapt for Nov 1979. \* Wisconsin Electric Power Co. 78/12/05, 9pp. 94274; 182,
- 7810180099 Forwards summary Tach Rapt: "Reactor Containment Bldg integrated Lastage Rate Test for March 1978."

  BURSTEIN.8. Wisconsin Electric Power Co. 78/10/05. ip.
- --7810180102 Bummary rept: "Reactor Containment Bldg Integrated Leakage Rata test for March, 1978" Finds that overall leakage rate is 0.0757 plue 0.07574% per day. Test type: Second pariodic type BRUCKNER, Q. E. Historian Electric Power Co. 78/10/05. 216pp.
- 7810170171 Forwards Monthly Open Rept for Sept 1978. BURSTEIN.S. Misconsin Electric Power Co. 78/10/09. 1p. 94270:036.
- ---7810170173 Monthly Open Rept for Bept 1978.

  \* Wiscanein Electric Power Co. 78/10/05. 9pp. 94270:037.
- B. Reportable occurrences. LERs & related correspondence
- 7810180043 Forwards LER#78-012/01X-0.

  8URSTEIN, 8. Hisconsin Electric Power Co. 78/09/12. 1p. 94422:036.

- --7810180046 LER#78-012/01X-0 on 780627: during visual inspec of Pire barrier penetration seals horizontal seals found to be constructed differently than specified. Error due to change in Constr drawings No reportable item asists. BURSTEIN. B. Wisconsin Electric Power Co. 78/09/07. ip. 94492-097
- 7811210349 LER#78-010/17-0 on 780928: reactor coolant sys pressure: dropped. Rate in decrease reached 25 psig per minute. Pressure decrease caused by failed elec-to-air signal Converter. QREENWOOD, J. Wisconsin Electric Power Co. 78/09/29. 200. 94484: 355.
- 7811240130 Forwards LER#78-010/01T-0.

  BURBTEIN, 8. Wisconsin Electric Power Co. 78/10/12. 19. 94436:355.
- --7811240136 LERG78-010/01T-0 on 780928: reactor coolant eye pressure bagen dropping at 25 psi per minutel pressurizer epray value 4318 found partially open deepite shut signal dus to 0 est point drift caused by heat degradation in transducers SURBTEIN. B. Wisconsin Electric Power Co. 78/10/12. 2pp. 94456: 356.
- 7811240131 Forwards LER#78-009/03L-0. BURSTEIN, B. Wieconein Electric Power Co. 78/10/13. 1p. 94456:359.
- --7811240134 LERM78-009/03L-0 on 780913: on 2 occasions, 2 of 3 charging pumps were isolated 2 3/4" croeby relief valvas lasked through causing temporary loss of charging flow. Charging gump relief valva replaced & A pump returned to Svc. BURSTEIN, B Wisconsin Electric Pawer Co. 78/10/13. 2pp. 94456: 359.
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3 F. Becurity, medical, emergency & fire protection plans
- 7810200160 Confirms 781006 rept re potential problem in use of Duct Basi campound used in facil cable spreading room. Util 1s evaluating the mati & will rept in 14 days.

  BEATTY, Q.P. Florida Power Corp. 78/10/10. ip. 94412:012.
- 7811170103 Forwards Rev 8 to Security Plan for subj Pacii Rav attempts to respond to difficiencies identified by NRC Security Review Team Bince plan contains proprietely info. FFC requests that it be withheld from public disclosure pursuent to 2.790. BTEWART. H. P. Florida Power Corp. 78/11/10. ip. 02765; 266.
- 7811280382 Request for addl info re fire protec prog as described in 770622 submittal. W/encl questionneire. NRC Staff Positions & request for drawings covering fire hazard analysis, instru REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/14. 20pp. 94397: 265.
- 7812210453 Forwards request for add1 info re fire protec prog. Suppl 781114 NRC request resulting from review of 780530 fecil submittal on administrative controls.
  REID,R.W. Operating Reactors Branch 4 (Pra 790625). 78/11/21. 5pp. 94168:020. REID, R. W.
- 7812140127 Requests titls changes to Bacurity Plan Reve#6.7. & 8 to "Mod Amended Bacurity Plan" (780202). "Rav#1" to the MABP (780317), & "Rev#2" to the MABP (781010) respectively, H/enc1 new cover sheets, Amend w/heid pursuant 2, 790.
  BTEHART, M. P. Floride Power Corp. 78/12/11. 4pp. 94123:328.
- H. Gameral correspondence
- 7812270168 Requests piecement on distribution list for correspondence t repts dealing w/oper status for subj facils.
  SHREVE, J. Florids, State of. 78/12/18. 1p. 94018:090.
- J. Insurance & indemnity information
- 7811160123 Forwards copy of Amend #5 to Indemnity Group Agreement #8-54 which edds new Article VIII re premium payments & financial statements. PAPALOS, F. A. Florida Power Corp. 78/11/09. 4pp. 94135:185.
- P. Operating license stage documents & correspondence
- 7B10250211 Notice of Issuance of Amend#15 to Facil Oper Lic#OPR-72 & Negative Daclaration. REID.R.W. Operating Reactors Branch 4 (Pre 790525). 78/07/24. 3pp 94368:349.

- worst case atruct rod BASH did not notify FPC of problem acisting in other units. STEHART.N. P Florids Power Carp. 78/10/03 2pp. 94069:360.
- 7810130130 Re 780926 NRC ltr FPL intends to pursue ned proposed in ltr of 780721 Flow balance analyses currently being performed are due to be completed on or about 781027. Since no new mod is proposed no submittal sched needed.

  STEWART.W P. Florida Power Corp. 78/10/09 3pp. 94003.091
- 7810270165 Util Production Engr & CR#3 Plant Staff have initiated review of safety related says that contain embbers to determine if there are any snubbers that should be added to Tables 3.7-3 of Tach Specs.
  SIEWART.W P. Fjorida Power Corp. 78/10/23 2pp. 94036.259.
- 7811080165 Forwards Tech Spec Change Requests 27 & 34-requesting amend to App A of Licanse DPR-72. Changes concern reactor coolent pump power monitors & revisions to heatup.cooldown & inastruice leak & hydrostatic pressure-temp curves

  BTEWART.W.P Fiorida Power Corp. 78/10/31. 25pp. 94405:078.
- 78i1200394 Forwards request for add1 info rs parmenent solution to ECCS small break analysis problem per 780727 submittal.
  REIG.R.U. Operating Reactors Branch 4 (Pre 790625). 78/11/02. 3pp. 94419:237.
- 7811130181 Refere to 780926 NRC it & requests prompt notification of review of proposed mod to Engineered Sefsguard Sys to mitigate Condition 3 event(small LOCA) Analysis of High Pressures Injection Sys will be completed & sant by 781130. STEMART. In P. Florida Power Corp. 78/11/07. 3pp. 03553:314
- 7811200422 Forwards results of measurements of radioactive meth in NRC phantom on whole body counter Encil 1 contains actual amount of each radionucide present encil 2 gives ratio of measurements to DDE values & ancil 3 gives recommendations. BUTHERLAND. J T Region 2. Atlants. Fuel Facility & Materials Safety Branch. 76/11/09. 3pp 94419.180.
- 7811210270 Notification of 781205 saminar in Atlanta, QA to discuss naw model rod effluent Tech Specs Forwards saminar info sheat, registration form & proposed agenda. O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 78/11/09, 5pp. 94485:276
- 78:11:40:109 Forwards list of anubbers to be added to Table 3.7-3 of Tach Spaces. FPC is currently preparing a Tech Spac change request which will include these enubbers. Request will be submitted w/matt litense emend.

  BTEWART.W P. Florida Power Corp. 78/11/10, 5pp. 94425:136.
- 7811300033 Forwards SECY-78-554, "Policy Session Item." dtd 781025 w/
  "Licenses Regulatory Performance Evaluation." W/o encl.

  O'REILLY, J. P. Region R. Atlants, Office of the Director. 78/11/15.
  2pp. 94070:348.
- 7812130120 Notice of workshops re implementation of training & qual requirements contained in Append 5 of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out meth. W/enci Registration Form & List of Locations. MILLER. J. R. Assistant Director for Bite & Safeguards (Prs 791030). 78/11/15. Spp.
- 7812190033 Forwards Ravel "Draft Radiological Effluent Tach Space" for PHR's (NUREO-0473) & "Praparation of Radiological Effluent Tach Space for Nuc Pur Plants" (NUREO-0133), H/o anci ANO: 7811270173 & 781127018.

  GRIMESIS N. Assistant Director for Engineers & Projects (Pra 790425), 78/11/15 6pp. 94213:001.
- 7811240216 Responds to 781102 request & forwards add1 info re proposed solution to ECCS small break analysis problem.
  STSWART.M P. Florida Power Corp. 78/11/17. App. 94466:344.
- 7811300358 Informs FPC that NRC has contracted w/Mountain Hest Res Inc to Undertake a series of post-litensing studies of nuc pur stations. Btudies will smally:a socioston impacts which occurred during constr & post-constr pariods ofesch plant. DEYGUNO. R. C. Division of Site Safaty & Environmental Analysis. 78/11/20. 2pp. 94116:240.
- 7812040199 Forwards resubmittal of Tech Spec Change Request 27 for amend to App A of License DPR-72 Replaces 781031 request entirely. New submittal deletes time dalay relay & clarifies response time in safety analysis. Certificate of Sec encl. BTEWART. W. P. Florida Power Corp. 78/11/29. 1699. 94457:135.

- during normal plant oper Requests either commitment to limit purging or justification for continuing Forwards most Tech Spece SRP Bection 6.2.4 w/encl Branch tachnical position. REID.R.U. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 8pp 74211:274.
- 7812280172 Emphasizes importance of submitting accurate & complete info to NRC by liceness & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or anforcement action will result. DAVIS. J Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94375:013.
- 7812270489 Notification of forthcoming masting on 781219 w/util to discuss content & achedule of submittals re pur increase to be proposed.
  NELEON.C. Operating Reactors Brench 4 (Pre 790625). 78/12/12 2pp 74015:293
- G. Inspection reports. 1E Sullatine & Correspondence
- 7810250116 Forwards IE Inspec Rapt#50-302/78-19 on 780726-29 during which no items of noncompilance were noted. LONG-F.J. Rapion 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. 2pp.
- --7810250154 IE Inspac Rept#50-302/78-19 on 780726-29 during which no items of noncompliance were noted. Major areas inspacted included: fuel handling activities, review of annual rept & a plant tour.

  DANCE.H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. 11pp.
- 7811010299 Forwards suppl info to Item of Noncompliance 478-17-02 radesignation & control of temporary auth vahicles & to Unresolved Item 478-17-08 racontrol of all vahicles.Full compliance will be achieved by 790223.

  BTEMART.W.P. Florida Power Corp. 78/10/05. ip. 94389: 132.
- 7811130409 Forwards IE Inspec Rept#50-302/78-20 on 780810-11 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/05. 2pp. 94008:332.
- --7811130412 IE inspec Rept#30-302/78-20 on 780810-11 during which no items of noncompliance were noted. Major areas inspected included; surveillance activities, testing & safety related piping support & reatraint sys.

  MARTIN.R. D. Region 2, Atlanta, Office of the Director. 78/10/03
  708. 94008:334.
- 7810230290 Forwards 1E Circular#78-17. (Sae ANO: 7810230221, Docket 50-133, 781013) D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/13. lp. 94165; 008.
- 7811010299 Ack receipt of 781005 ltr informing NRC of steps taken to correct violations noted during inspec#50-302/78-17.
  KENNA-M-B. Region 2: Atlanta: Safeguerds Branch. 78/10/17. lp. 94399:131.
- 7811100017 Ack receipt of 781024 ltr informing NRC of steps taken to correct violations noted during inspec#50-302/78-21. LONG-F.J. Ragion 2. Atlanta: Rasctor Operations Nuclear Support Branch. 78/11/01. jp. 94176:295.
- --7811100021 Responds to 780929 NRC ltr re violation noted in Inspec Rept#50-302/78-21 Corrective actions: admin procedures rev to make the master mechanic responsible for assuring cleanliness of fuel transfer canel. BIEMART.M.P. Florida Power Corp. 78/10/24. ip. 94176: 296.
- --7811100023 Forwards IE Inspec Rept#50-302/78-21 on 780814-18 & Notice of Viglation. LCNO.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Brench. 78/09/29. 2pp. 94176:297.
- --7811100026 Notice of Violation from inspec on 780814-19.

  # Region 2, Atlanta: Reactor Operations Nuclear Support Branch.
  78/09/29.

  1p. 74176;299.
- --7811100030 IE Inspec Rept#50-302/78-21 on 780814-18 during which I itam of noncompliance was noted: failure to follow procedures re facil cleanliness.
  DNCE.H.C., QUICK.D.R. Region 2, Atlants, Reactor Operations Nuclear Support Branch. 78/09/29. 15pp. 94178:300.

- 7811150098 Forwards IE Circular 78-19.

  O'REILLY J. P. Region 2. Atlanta. Diffice of the Director. 78/11/06.
  13. 94113-285
- 7812180312 Forwards IS Inspec Rept#50-302/78-24 on 781002-06 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/11/08 2pp. 94396:261
- --7812180317 18 inspec Rept#50-302/78-24 on 781002-06 during which no items of noncompliance were noted Hajor areas inspected inclipiant oper/followup on previous noncompliance items to unresolved items.

  GUICK, D. R., TAYLOR, P. A. Region 2. Atlanta, Resctor Operations Nuclear Support Branch. 78/11/08. 12pp. 94336-263
- 7812180308 Forwards IE Inspec Rept#50-302/78-28 on 781011-13 during which no itams of noncompliance were noted. LONG.F.J Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94356:184.
- --7812180311 1E Inapac Rapt#30-302/78-28 on 781011-13 during which no items of noncomplianca ware noted. Hajor ereas inapacted incl:zaro-pwr-physics tests to pur ascalation tests.
  BURNETT.P. T. Rapion 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. App. 94336:186
- 78ii240071 Ack receipt of 78i030 itr informing NRC of steps taken to correct violetions noted during inepec#50-302/78-22.

  8UTHERLAND.J T. Region 2- Atlanta- Fuel Facility & Meterials Safaty Branch. 78/11/14. 1p. 94456.311.
- --7811240074 Rasponds to 781114 NRC itr re violation noted in Inspec Rept #50-302/78-22. Corrective actions: rev survey sched divided over 4 dey period; posting of redist erees once a weekinew ing book. BTEMATI-W.P. Floride Power Corp. 78/10/30. 2pp.
- --7811240077 Forwards IE Inspec Rept#50-302/78-R2 on 780905-08 % Notice of Violation.

  SUTHERLAND.J.T. Ragion 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/10/16. 2pp. 94456:314.
- --7811240079 Notice of Violation from inspec on 780905-08.

  Region 2, Atlanta, Fuel Facility & Meterials Sefety Branch. 78/107/16. 1p. 94456: 316.
- --781iR400B1 iE Inspec Rapte50-302/78-22 on 780905-0B during which 3 items of noncomplience were noted: failure to post high radiat area & failure to post two radiat areas. EMALD.8. C., ZAVADDSKI,R.W. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/10/13 ilpp. 94456:317.
- 7812120197 Forwards reproductions of articias that appeared in June & Aug 1978 editions of Nuclear Becurity Bafeguards Newslatter, in suggest of IE Circular 78-17. KENNA H.B. Region 2, Atlants, Bafeguards Branch. 78/11/17. 4pp. 9427:101.
- 7812040306 Forwards IE Bullatin#78-12A/suppl to IE Bullatin 78-12. W/srci AND:7811300055. U'ABILLY,J.P. Region 9. Atlanta, Office of the Director. 78/11/24. 1p. 94127:094.
- 7812050043 Ack receipt of 781115 itr informing NRC of steps taken to correct violations noted during inspace800-302/78-23. LONG,F.J. Region 2. Atlanta, Resctor Operations Nuclear Support Branch. 78/11/24. 1p. 94334:324.
- --7812050067 Responds to 781023 NRC ltr re violations noted in Inspec Restet50-302/78-23 Corrective ections:personnel instructed, plant heatup oper reviewed. BTENART, M. P. Floride Power Corp. 78/11/15. 2pp. 94334:325.
- --7812050070 Forwards 1E Inspec Rept#80-302/78-23 on 780830-0901 & Notice of Violation.
  LQNG.F.J. Region 2, Atlante, Reactor Operations Nuclear Support Branch, 78/10/23, 2pp. 94334:327.
- ~-7812050072 Notice of Violation from inspac on 780830-0901.

   Region D. Atlanta: Reactor Operations Nuclear Support Branch. 78/10/23. 1p. 94334:329.
- --7812050076 JE Inspec Rept#50-302/78-23 on 780830-0901 during which i item of noncompliance was noted:completion & verification of procedures during review of sys realignments.

  GUICK, D. R., DONATT. J., DANCE, N. C. Ragion 2, Atlanta, Reactor Operatione Nuclear Support Branch. 78/10/20. 8pp. 94334:330.

- 7812210333 Ack receipt of 781130 itr informing NRC of steps taken to correct violations noted during inspect50-302/78-25 LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/12/08 ip. 94014:289.
- --7812210337 Responds to 781109 NRC ltr re violations noted in inspec Rept#50-302778-25 Corrective actions formal qual training guide was rev.upgraded & distrib for implementation STEWART.F.P. Florida Power Corp. 78711730
- --7812210344 Forwards IE inspec Rept#50-302/78-25 on 781016-19 & Notic of Violation LCN2:F.J Region 2. Atlanta. Resector Operations Nuclear Support Branch. 78/11/09 2pp. 94014:292.
- --7812210346 Notice of Violation from inspec on 781016-19.

  \* Region 2, Atlanta Reactor Operations Nuclear Support Branch.
  78/11/09. ip. 94014-294
- --7812210350 IE Inspac Rept#50-302/78-25 on 781016-19 during which is of noncompliance was noted failura to implement treining & retraining for nuc susiliery operators & sesistant nuc auxiliary operators.

  8RAPFORD M. H., TAYLOR. P. A., KELLOGO, P. J., Region 2. Atlants.
  Resctor Descriptions Nuclear Support Branch. 78/11/09. Spp. 94014-295.
- 7812290096 Ack receipt of itr informing NRC of staps taken to correct violations noted during inspec#50-302/78-27 Response is incomplete. Requests eddl info w/in 10 days.

  MENNA-N.B. Region 2, Atlanta, Safeguards Branch. 78/12/18. 1p. 94190:117
- --7812290101 Forwards IE Inspac ReptW50-302/78-27 on 781018-19 & Noticely Violation.

  KENNALW B. Ragion 2. Atienta, Befeguards Branch. 78/11/15. 2pp. 94190-118.
- --7812290107 Notice of Violetion from inspec on 781018-19. \* Region 2, Atlanta, Safaguards Branch 78/11/15. 1p. 94190.120.
- --7812290112 IE inspec Rept#50-302/78-27 on 781018-19 during which 2 items of noncompilance were noted: response procedures & vehicle control Details withheld from pub disclosure Per 2.790.

  2.190.

  2.190.

  2.190.

  2.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.

  3.190.
- 7812280025 Forwards 16 Bulletin 78-14. O'REILLLy P. Ragion 2. Attents, Office of the Director. 78/12/19 1P. 94121:058.

### R. Pariodic operating reports & related correspondence

- 78:0:60094 Monthly operating rept for Sapt 1978
  SARRETT, J. E. Florida Power Corp. 78/10/05. 5pp. 94003:224.
- 78:0:6008: Forwards Monthly Oper Rept for Bept 1978. BTEWART, N. P. Florida Power Corp. 78/10/09. ip. 94003: 223.
- 7811200184 Forwards Monthly Oper Rept for Oct 1978. 81EWAR1, W.P. Florida Power Corp. 78/11/15. ip. 94202:304.
- --7811200187 Monthly operating rept for Oct 1978. SARRETT, J. E. Florids Power Corp. 78/11/15. Spp. 94252:305.
- 7811280268 Forwards revision to monthly operating rept for Oct 1978. BTEWART, M. P. Florida Power Corp. 78/11/20, 1p. 94395:208.
- --7811280271 Revision to monthly operating rept for Oct 1978.
  BARRETT, J. E. Florida Power Corp. 78/11/01. 1p. 94395:209.
- 7812200176 Forwards Monthly Oper Rept for Nov 1978. STEWART, W. P. Florida Power Corp. 78/12/11. 1P. 94158:337.
- --7812200179 Monthly Oper Rapt for Nov 1978. BARRETT, J. E. Florida Powar Corp. 78/12/01. 3pp. 94158:339.
- 8. Reportable occurrences. LERs & related correspondence
- 7810200132 Forwards LER 78-021/047-0.
  BTEWART.N.P. Florida Power Corp. 78/08/09. ip. 94401:186.

#### COKETED HEIVIS

- --7810200158 LER 78-021/04T-0. on 780729, spent fuel casts were recaived w/ removable radioactive contamination in excess of 22,000 DPM legistion & decontamination started Cause unknown CCOPER, J. Fiorida Power Corp. 78/07/31. 2pp. 94401.187
- 7810130151 Forwards LER#70-045/031-0 STEWART, W. P. Floride Power Corp 78/10/02 1p. 94065:346.
- --7810110152 LERR78-045/031-0 on 780907 closed indication not recaived for Control Complex air supply damper D-1 after closed commend was issued Causad by mech binding of air supply dampar Preventive maint will provide corrective action COOPER. J Fiorida Power Corp. 78/09/27, 2pp 94065-347.
- 7810110116 Forwards LER 78-044/03L-0 BTEWART.W P. Floride Power Corp 78/10/03 lp 94069:147.
- --7810110120 LER 78-044/03L-0.on 780907, during performance of 8P-417, closed position indication not received after CFV-15, core flood 8 vent to gas decay systems given command to close. Caused by feulty torque awitth. Torque awitth renewed CCOPER. J. Floride Power Corp. 78/09/29, 2pp. 94057:334
- 7810110170 Forwards LER 78-023/04X-1. STEWART-W. P. Florido Power Corp. 78/10/03. 1p 94069:093
- --7810110173 LER 78-023/04x-1 (supplementary info): (discovered 780914) during Jul-Aug 1978, environ eamples not eneigned u/methods providing LLD's equal to or less than Tach Spec requirements # Florida Power Corp. 78/09/29. 2pp. 94069:096.
- 7810170249 Forwards LER 78-025/04T-0. SIEWART.W P Florida Power Corp. 78/10/11 lp. 94236:331.
- --7810170232 LER 78-025/04T-0: on 781001; unplanned radioactive gas release occurred when attempting to place Miscalleneous Maste Evaporator in svc. Coused by procedure inadequecies which have been revised.

  CCOPER. J. Florida Power Corg. 78/10/09. 2pp. 74236-332.
- 7810180105 Forwarda LERN7B-048/03L-0. 81EWART.W.P. Floride Power Corp. 78/10/12 1p. 94421:279.
- --7810180107 LERW78-048/03L-0 on 780918: Quadrant pwr tilt exceeded transient limit but not meximum limit recorded. Caused by uncoupling of grp 5.Rod 1. Control Rod Drop Test Procedura has been ray CCOPER. J. Florida Power Corp. 78/10/10. 2pp. 94421:297
- 7810180147 Forwards LER 78-047/03L-0.
  61EWART-W P. Floride Power Corp. 78/10/12. ip. 94316:342.
- --7810180182 LER 78-047/03L-0: on 780918-in Mode Lubils performing RCS total ges Burvelllance Procedure BP-710, gas chromatograph found inoperablé. Caused by failure of separation column.

  # Florida Pawar Corp. 78/10/10. 2pp. 94316:343.
- 7810180153 Forwards LER 78-049/03L-0. BIEWART, W. P. Fiorida Power Corp. 78/10/12. 1p. 94317:001.
- --7810180185 LER 78-049/03L-0: on 780915, relative position indication for Orong 7, Rod 8 found inoperable. Ceused by improper termination of reactimater to relative position indicator module for Group 7, Rod 1. Procedure will be revised... COOPER, J. Floride Power Corp. 78/10/09. 2pp. 94317: 002.
- 7810180110 Forwards LER 78-046/03L-0. STEWART.N P. Florida Power Corp. 78/10/13. 1p. 94195:201.
- --7810180111 LER 78-046/03L-0: on 780914, sutiliary bldg ventilation sthaust radiat monitor interlock on RMA-2 failed to respond during performence of BP-335. Caused by shorted surge suppressor which inhibited interlock function.

  CCOPER. W P. Florida Power Corp. 78/10/06. 1p. 94195: RO2.
- 7B1024011B Forwards LER 7B-050/01T-0. BTEHART, H. P. Florida Power Corp. 78/10/17. 1p.
- --7810240124 LER 78-050/01T-0: on 781006, duct seal compound which supports combustion was used around penetrations in CR-3 cable spreading room. Duct seal compound used in qualifying cable spreading room for halon sus but not as fire barrier. COOPER. J. Florida Power Corp. 78/10/12. 2pp.

- --7810240162 LER 78-051/02L-0: on 780920, reactor bidg air sampling monitor inoperable & in low flow alarm. Caused by meladjustment of a flow controller which was subsequently readjusted. CDOPER. J. Florida Power Corp. 78/10/17. 2pp.
- 7810310136 Forwards LER W78-027/1T-1. 8TEWART.H.P. Florida Power Corp. 78/10/23. 1p. 94090:156.
- --7810310141 LER 78-027/01T-1: on 780511.1tr received from B&W on 780508 re uncertainties associated w/incore instrumentation found to apply to CR-3. Ceused by insufficient data from prototype incore instrument studies. Quadrant power tilt revised. COOPER.J. Florida Power Corp. 78/10/17. 2pp. 94090:157.
- 7810310164 Forwards LER 78-052/03L-0.
  BTEHART.H. P. Florida Power Corp. 78/10/23. ip. 94090: 222.
- --7010310169 LER 78-052/03L-0.on 780928.operating range lavel transmitter for once-through ateam generator 8 found out of calibr.
  Normal maint restored operability through calibr.
  CCOPER.J. Florida Power Corp. 78/10/20. 2pp. 94090:223
- 7811070136 Forwards emended LER 78-023/04X-2 Supplementary info sheet only encl. 8TEMART.M.P. Florida Power Corp. 78/11/01. 1p. 94040:131.
- --7811070139 LER 78-023/04x-2:(discovered 780914), during Jul & Aug 1978, environ samples not analyzed using procedures which would provide LLD's per ETS. Apparently caused by inadequate sample count time. (Bupplementary info sheat).

  \*\*Fioride Power Corp. 78/10/26. 2pp. 94040:132
- 7811070204 Forwards LER 78-054/03L-0.
  STEWART, H. P. Florida Power Corp. 78/11/01. 1p. 94039; 080.
- --7811070208 LER 78-054/03L-0: on 781004, in cable spreading room, saverel penatretions to control room were found to lack fire barriar mati. Caused by inadequets installation & insp. 8TEMART, W. P. Florida Power Corp. 78/11/01. 2pp. 94039:081.
- 7811070925 Forwerds LER 78-083/031-0. BTEMART.H.P. Florids Power Corp. 78/11/01. 1p. 94039:153.
- --7811070235 LER 78-053/03L-0:on 781004 during ECCB pump operation procedure 8P-340A valve DHV-110 found incapable of controling required flow Caused by flow controller DH-43-F18 not being valved in. CCOPER, J. Florida Power Corp. 78/10/25. 2pp. 94039:154.
- 7811160136 Forwards LER 78-055/03L-0. 8TEWART.W.P. Florida Power Corp. 78/11/06. 1p. 94135:241.
- --781160140 LER 78-055/03L-0: on 781014, during routine aperation, lubs oil beckup pump MVP-3C lost indication & would not start. Caused by two blown fuses in indication & control power circuit in DPPD 39 switch 4. Circuits checked & fuses renewed. COOPER. J. Florida Power Corp. 78/11/06. 2pp. 74135:242.
- 7811280303 Forwards LER 78-055/03L-0. BTENART.M.P. Florida Powar Corp. 78/11/20. 1p. 94395:299.
- --7811280307 LER 78-056/03L-0:on 781027.during mateorological monitoring instrumentation calibr, differential temp & wind indications found out of tolerance.Formar caused by defective temp probasilatter by worn sensor bearing.Units recalibr. COOPER.J. Fiorida Power Corp. 78/11/17. 2pp. 94395:300.
- 7812010246 Forwards LER 78-057/03L-0. 8TEWART, N. P. Florida Power Corp. 78/11/24, ip. 94390:156.
- --7812010247 LER 78-037/03L-0: on 781030, during routine plant insp,both concentrated boric acid storage tank discharge valves CAV-38 & 43 were closed. Caused by improper valve alignment during restoration of sys from recirculation to normal modes. CODPER.J. Florida Power Corp. 78/11/24. 2pp. 94390: 157.
- 7612180150 Forwards LER 78-060/03L-0. STEWART.H. P. Florida Power Corp. 78/12/11. 1p. 94365:251.
- --7812180155 LER 78-060/03L-0: on 781115, conteinment radiation sonitor RM-1 found in purge mode while reactor bldg purge was in progress, preventing att sampling. Causad by personnal error. COOPER.J. Florida Power Corp. 78/12/07. 2pp. 94365: 252.

7812200178 Forwards LEG 78-058/031-0

# **DOCKETED ITEMS**

- -7812200181 LER 78-058/03L-0: on 781112, feeder breaker was open & disrupting ac power supply. Caused by personnel opening untaried ac power feeder breaker. Breaker will be identified & labeled CODER. J. Florida Power Corp. 78/12/05 2pp. 94158.342
- 7812200270 Forwards LER 78-059/03L-0 STEWART.W P. Florids Power Corp. 78/12/11. 1p 94207-140
- --7812200273 LER 78-059/03L-0: on 781113, control complex atmospheric radiation monitor RMA-5 went to high flow alarm, preventing ectuation of interlocks which route control room air through emergency ventilation sys. Caused by vacuum pump saizing COPER.J. Floride Power Corp. 78/12/06. 2pp. 94207. 141.
- 7812200284 Forwards LER 78-051/03L-0. STEWART, W. P. Fiorida Power Corp. 78/12/13 ip. 94207.212.
- 7812220081 Forwards LER 78-063/03L-0. 81EHART N P. Florida Power Corp. 78/12/15. ip. 94343:326.
- --7812220084 LER 78-063/03L-0:on 781123.stert-up transformer disabled, causing loss of power in cable tunnel sump pumps. Operability restored shortly. Engineering evaluation of power sys initiated. COPER.J. Florida Power Corp. 78/12/13. 2pp. 94343:327.
- 7812220102 Forwards LER 78-062/03L-0. 8TEWART, U.P. Floride Power Corp. 78/12/15. 1p. 94343:355.
- --781220105 LER 78-062/O3L-0: on 781121, during control rod exercise procedure 8P-333, ebeciute position indication for Rod 4 Group 3 not observed as rod was moved. Caused by sticking reed switch COOPER, J. Floride Power Corp. 76/12/13. 2pp 94343.356.
- 7812270239 Forwards LER 78-064/03L-0. 8TEWART.W. P. Florida Power Corp. 78/12/19. 1p. 94017:146.
- --7812270243 LER 78-064/03L-0: on 781125-during routins operation of air handling fans AHF-14A&C-low flow condition was indicated. Cause was suction shroud breefing loose & carrying into fan ilade essembly Broken bledes AHF-14C replaced & rebelanced. COPER, J. Florida Power Corp. 78/12/14. 2pp. 94017:147.
- 7812270291 Forwards LERR78-065/01T-0. BTEWRT.N.P. Florida Power Corp. 78/12/21. 1p. 94229:344.
- --7812270293 LERW78-065/01T-0 on 781218: during routine open discovered that AHF-14C was overladed & was secured to attempt to belence air flow ANF-14C was tripped during restart & cause was ettributed to not allowing sufficient time for restart. COOPER, J. Floride Power Corp. 78/12/19. 2pp. 94229: 345.
- U. Congressional/Executive Correspondence
- 7812080210 Responds to 781030 itr requesting info for GF Danlelson. Forwards Bub; Fattl Sami-Beala Annual Radioactive Effluent Repts re gaseous: liquid & solid radioactive metl released during 1977 & First helf of 1970.

  DIROKS.H.J. Office of the Executive Director for Operations. 78/11/28. 2pp. 94137:048.
- --7812080211 Forwards Danleison 781020 request for info re facility nuclear waste disposal program & controls on Sr-90 solssions. Requests NRC comments & views.

  CHILEB.L. Senate. 78/10/30. 2pp. 94137:050.
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
- F. Becurity, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Electrical Cable Penatration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test.

  NAUGHTON: W. F. Commonwealth Edison Co. 78/09/29. 44p.
- 7812120195 Informs NRC name of fire protec consulting firm hired by CEIL to Pulfill requirements of "Fire Protec Organization of Nuc Plent Fire Protec Functional Responsibilities Admin Controls & OA" will be submitted 790201.
  NAUCHTON, W. F. Commonwealth Edison Co. 78/11/30. 2pp.

- 7812270365 Forwards correction of item 3.2.5 of fire protec SER. Requests delay in advising licenses of acceptability until there is a response to encl 2 of 780626 ltr LAINAB.O. Plant Bystams Branch (Pre 791030) 78/12/07. ip. 94229:016.
- O Adjudicatory correspondence
- 781:130202 "Agreed Motion for Special Prehearing Conference & to Sat Sthad for Further Proc" on 781:20.21 or 22 to hear orel arguments & rule on motions to dismiss & to ellow citizens to enter limited appearances
  BTEPTOB-P. Commanuelth Edison Co. SCHELL.8 111:nois, State of 78:10:24. 3pp. 03533:335.
- 78:11:70012 "Order for Special Preheering Conference." The 78:024 joi motion of Petitioner Applicant & Reg Staff for special prehasting conference is granted & set for 78:120.
  LUTON.E. Atomic Safety and Licensing Board Panel 78/:1/02. 2pp 94:16.123
- 7812120211 Submits typographical corrections to "Memo in Support of Certain Amended Contentions" filed on 781109 by State of IL W/Cert of Svc. BEKULER.S.N 1111nois. State of 78/11/13 2pp. 94276 066
- 7811240022 Amended contentions of 8t of IL re amends to Oper Lics #DPR-39 & 48 to increase spent fuel storage capacity at subj facils. Asserts that to approve amend would be contrary to NRC policy position. Cert of 8vc & efficient encl BEKULER. 8. N Illinois. State of 78/11/01 9pp. 94458-167.
- 7811200423 Notice of appearance by 0 Cunningham in proceedings re su facile on behalf of NRC.Cert of Svc encl.
  CUNNINGHAM, Q H Office of the Executive Legal Director 78/11/02
  2pp. 94419:185
- 7812040311 Commanwealth Edison Co Motion to strike contentions & supporting memo submitted by IL Atty Censrel on 781101.
  Requests that Amended ContentionsW2. #6D & W16 by stricken.
  ROME\_J.W. STEPTOE.P.P. leham, Lincoln & Esels 78/11/09. 17pp.
  94129:18B
- 7812030047 Motion to emend Contention AA of Intervenor's emended Contentions filled 781101 by stating that there has been insufficient dev of all credible accident econorios in subj proc.

  8EKULER.S.N. 1111nois. State of. 78/11/09 3pp. 94334:159.
- --7812050051 Memorandum in support of smand contentions Believes ata Applicant should not be allowed to use the special prehability conference as means to circumvent the summary disposition process. Wiencl Cert of Byc. SEMULER, B. N. 111 incis. State of . 78/11/09. 14pp. 94334:162.
- 7812050054 NRC Staff brisf in opposition to the admission of lilino: proposed contentions 2.6A.6D. & 16 re proposed nod of spent fuel pool. Staff views cover non-emergency litensing of storags facils, contention wording, vagueness & irrelevance. QODDARD.R. J. Diffics of the General Counsel. 78/11/09. 7pp. 94334; 231.
- 7812120223 Notice of appearance by A Bielewski as counsel for util proceedings re subjectis. Cart of Buc end.
  BIELAMBAI.A.P. Ishem. Lincoln & Beals. 78/11/16. 2pp. 94277-11
- 7812270335 Opposes Commonweelth Edison request to increese spent fu storage at subj facil. Fears it will become a permanent dump. ROBERTS.M. Affiliation Unknown. 78/11/20. ip. 94230: 296.
- 7819270371 Notification that respondent has been added to svc iists legal & tech branch documents re Spent Fuel Pool Mod proc for sub; facile as of 781127 & previous papers in Fornal File are enti. (w/o entl).
  ODDDARD.R. J. Office of the Executive Legal Director. 78/12/05. 94229:023.
- J. Insurance & indemnity information
- 78:2190109 Requests refund of 65 per mwt in excess indamity fee pai for LiceDPR-2, MDPR-19, MDPR-25, MDPR-29, MDPR-30, MDPR-39, MDPR-49. POOLE, R. D. Commonwealth Edison Co. 76/12/13. 1p.

DOURE LED HER

## D. Advisory Committee on Reactor Safaguards reports & correspondence

- 7812060394 Notice of ACRS Subcommittes on Plant Arrangements 781026 open meating at 8:30 AM in Washington.DC to review NRC Generic Issue.Sky interaction in Nuc Pur Plants.Task A-17 k Zion Station Sys Interaction Study.

  HOYLE, J. C. Office of the Secretary of the Commission. 78/09/25 2pp. 94382:331.
- P. Operating license stege documents & correspondence
- 7812080026 FOIA request for all records incl:quantity of radioactive meth disposed of from former Manhetten proj in \$L thoun as Chicago Pilsswi.2 & J.Math disposed of in IL by Lindsay Cos at Morris facil & Drasden facil.

  HANGELL.D. Illinois, State of. 78/11/06. 3pp.
- 7812080095 Forwards CEIL's Proj Mileposts schod for subj facils fuel pool mods. Also included are brief statements providing besss for these mileposts. Requests that NRC steff expedite its review sched to mast 790201 & 790315 completion dates. REED C. Commonwealth Edison Co. 78/11/29. App. 94107:292.
- 7812180239 Amend#40 to Oper Lic#DPR-39. Changes Tach Space to silow boron concentration in pressuriser to be 200 ppm less than reactor coolant loop boron concentration. Carrections are made to Tach Space. Changes to Tech Space anci. SCHENGER, A. Operating Reactors Branch 1 (Pre 790625), 78/11/30. dpp. 94365:003.
- --7812180242 Bafaty Eval Rapt in Bupport of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#48. GCHWENCER.A. Operating Reactors Branch 1 (Pra 790625). 78/11/30. 4pp. 94365:015.
- 7810100025 Current schedule for submittel to NRC Staff of required rev ECCS enelysts & associeted Tech Spec changes is 780105. We Scheduled rev enelysis for subj fecil to begin late 781031. NAUGHTON.M.F. Commonweith Edison Co. 78/10/03. 1p. 94033:043.
- 7810120036 Lic#DPR-39 & DPR-48 sppi for amend to Tech Speca proposed incorporating ECCS flow requirements is a blow belance test & tamper-proof covers for manual throttle velvs.
  REED.C. Commonwealth Edison Co. 78/10/05. 7pp. 94332:299
- 78:01:00:00 Forwards drawing: "Location & Datelle of Reactor Coolant Pump Trip Pane" for subj fecil as fire protec response. NAUGHTDN:W.F. Commonwealth Edison Co. 78/10/10. 1p.
- 7810200113 Responds to 780829 NRC request for overpressura protec Tach Spec. Stetse that util will submit requested info by 781201. NAUGHTON, H. F. Commonwealth Edison Co. 78/10/13. 2pp. 94367: 342.
- 7810230102 Ranswel of request to amend facil operating liceDPR-39 & DPR-48. Proposed amend is a combined class I & class III Amend & does not raquire extansive environ impact rapt. Tech Base & Environ impact statement encl.

  REED. C. Commonwealth & dison Co. 78/10/13. 17pp.
- 7810230194 Requests withdrawai of proposed amend to facil lite DPR-G9 % DPR-48 originally submitted in ltr of 760720. Completion of moe re lake discharge tanks necessitetes proposed amend be cancelled. NAUGHTON.W.F. Communeeth Edison Co. 78/10/17. ip. 94052:277.
- 7810300097 Forwards into in response to 780931 NRC itr re pipe cracke in chem vol control due to excessive charging pump vibrations.
  NAUGHTON N. F. Commonwealth Edison Co. 78/10/24, 2pp. 94035:072.
- 7811010069 Forwards add3 info re proposed expension of epent fuel storage capacity of subj facil in response to 780726 NRC request. Responds to 27 NRC questione.
  NAUGHTON.M.F. Communuesith Edison Co. 78/10/24. 69pp. 94302:283.
- 7811070168 Requests chenge to Oper LiceDPR-37 & DPR-48 Tach Spec, axtending rod bow paneity curve & EFPH clad collapse limits to incl higher region everage fuel burnups. REED.C. Commonwealth Edison Co. 76/10/27. 7pp. 94044:150.
- 7811140002 Notifies applicent of 781126 NRC-sponsered seminar re Hodel Radiological Effluent Tach Specs for Nuc Pur Plante w/encl Seminer Info Sketkito be completed & returned by 781117) & Proposed Agenda. KEPPLER. J. Q. Region D. Chicago, Office of the Director. 78/11/07, Spp.

- 7811210410 Provides add1 info in response to questione 13 % 15 in 781028 itr re leakage rate from spent fuel pool liner, surface dose rate are spent fuel pool, potential impact of proposed spent fuel pool mod re gaseous effluents NAUGHTON, W.F. Commonwealth Edican Ca. 78/11/08. 3pp. 94483:123
- 7811300147 Forwards "Licensing Rept for Subj Facii Spent Fuel Ract Mod" in response to 780203 reguset.

  ODDDARD.R. J. Office of the Executive Legal Director. 78/11/03. 19. 94072:031.
- 7811270104 Summary of 781025 meating w/Subcomm on Plant Arrangements of Advisory Comm on Reactor Sabaguards to Sandia Lebs presentation of Sys Interaction Methodology Appl in Nuc Pur Plants & subj fecil aga interaction study.
  ANGELO J. Division of Project Management. 78/11/13. 36pp. 94223:294.
- 7812180021 Notice of workshops re implementation of training 4 qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out metl. W/enc) Registration Form & List of Locations.
  MILLER-J.R. Assistant Director for Bite & Bafaguards (Pre 791030), 78/11/10. 5pp. 94103:281.
- 7812190011 Forwards Rav#1 "Draft Radiological Effluent Tech Space" for PWR's (NUREQ-0473) & "Preparation of Radiological Effluent Tech Space for Nur Pwr Plants" (NURED-0133).

  GRIMEBLE, K. Assistant Director for Engineers & Projecte (Pre 790@5). 78/11/15. 6pp. 94214:274.
- 7812030107 Forwards ray page to Topical Rept CE-1-A: "Qual Assurance Prog.Ray 6." Rev reflects Reg Quidel.28 & 1.33 ray.
  TURBAK-M.B. Commonwealth Edison Co. 78/11/17. 2pp.
- 7B112B0213 Forwards current lic status list for subj facils. W/entl. REED.C. Commonweeith Edison Co. 78/11/20. 9pp.
- 7811300042 Informs CEIL that NRC has contracted w/Mountain West Res
  Int to undertake a series of poet-licensing studies of nuc
  pur stetions. Btudies will analyze socioscon impacts which
  occurred during constr & poet-constr periods of sech plant.
  DEYQUNO.R. C. Division of Site Bafety & Environmental Analysis.
  78/11/20. 2pp. 94071:037.
- 7812270127 Forwards Commonwasth Edison "Addl Info on Proposed Expansion of Spant Fuel Storage Capacity" dtd 781108. W/o encl. BIELMBKI: A. P. 18ham. Lincoln & Basle. 78/11/27. 1p. 94161:084.
- 7612180ii6 Discusses possible dangere of LOCA in containment purging during normal plent oper. Requests either commitment to limit purging or justification for continuing, W/ancl AND 7812080207.

  BCHENCER, A. Uperating Reactore Branch 1 (Pra 790625). 78/11/28.

6pp. 94130:317.

- 7812180236 Forwards Amend#40 to Oper Lic#DPR-39 & Amend#37 to Oper Lic #DPR-48. Also forwards Safety Eval Rept & Notice of Issuance. BCHMENCER.A. Operating Reactors Branch 1 (Pra 790625). 78/11/30. 2pp. 94365:001.
- --7812180244 Notice of Issuence of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#48.
  80%ENGER.A. Operating Resectors Branch 1 (Pre 790625). 78/11/30.
  82pp. 94365:019.
- 7812070211 Responds to NRC 780828 itr requesting overpressure protection Tach Spece, Requests extension to 790215 for submission due to receipt of new linfo.

  NAUGHTON.H.F. Commonwealth Edison Co. 78/12/01. 2pp. 03555:115.
- 78:2280:29 Emphasizee Importance of submitting accurate & complete info to NRC by licenees & applicante, Info aubmitted must be substantiated by data & calculations. Licensee must notify NRC of any inscruracies or entorcement action will result. DAVIB. J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp.
- 7812030013 Requests visus of Regional Directors on Licenses performance aval of subj facils. Forwards questions to be answered by 771209.

  THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23.
- 7812190097 Accepts topical rept#CE-1-A Rev#6."Comm Edison Co Guslity Assurance Prog for Nuc Generating Stations. " Requests submittel of 36 copies.
  HAABG,M.P. Guslity Assurance Branch. 78/12/13. 1p.

incl fuel sipping test & fuel assemblies exam prog. Rasffirms request to NRC to expedite its mod review & approve changes to higher region average fuel burnup Tech Specs by 781220. REED.C. Commonwealth Edison Co. 78/11/21. 3pp. 94393:219.

## Q Inspection reports. 1E Bulletins & correspondence

- 7811080066 Forwards 1E Inspec Repts#50~295/78~20 & #50~304/78~22 on 780809~11, 16,17,23~25,30,31,0901,07 & 08 & Notice of Violation. FIORELLI, O. Region 3, Chicego, Reactor Operations Nuclear Support Branch. 78/10/04 2pp. 94398-274.
- --7811080070 Notice of Violation from inspec on 780809-11.16.17.23-25.30. 31.0901.07.08. e Region 3. Chicago. Reector Operations Nutlear Support Branch. 78/10/04. 1p. 94398:276.
- --7811080074 IE Inspec Repts#50-295/78-20 & #50-304/78-22 on 780809-11.
  16-17.23-25.30-31.0901.07-08 during which 1 item of noncompliance was noted:preparation for refueling BUYD.D.C., RiDEN.H.D., KNUP.R.C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 11pp. 94396:277.
- 7812050011 Forwards IE Inspec Repts#50-010/78-29,50-237,-254,-295,-304/78-25,50-249/78-27 & 50-265/78-26 on 781002 during which no items of noncomplience were noted. XEPPLER, J Q. Region 3. Chicago. Office of the Director. 78/10/30 2pp.
- --7812050027 IE Inspec Repts for subj facile on 781002 during which no items of noncompilence were noted. Major sreas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station KNDP,R C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/30. Spp.
- 7812060231 Forwards 1E Ineppt Rept##50-295/78-24 & #50-304/78-24 on 780913-15.780920-21.780927-29 & 781004-05 & Notice of Violetion. FIDRELLI.9. Region 3. Chicago. Reactor Operations Nuclear Support Branch 78/10/31. 2pp. 94382:184.
- --7812060234 Notice of Violation from inspec on 780913-15,780920-21, 760927-28 & 781004-05.
  Region 3, Chicago, Office of the Director. 76/10/31. ip. 94082-186.
- --7812040234 IE Inspec RepteM30-295/78-24 & M50-304/78-24 on 780913-15, 20-21,27-29 & 781004-05 during which I item of noncompliance was noted; faiture to adhere to conditions of Work Request Authorization.
  BOYO, D. C., BIDEN, M. D., KNOP, R. C. Region 3, Chicago, Office of the Director. 78/10/31. 5pp. 94382:187.
- 78:1120063 Forwards 1E Circuler 78-19.

  KEPPLER, J. 9. Region 3. Chicago, Office of the Director 78/11/06
  1p.
- 78:2130329 Forwards IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 78:012-13 during which no items of noncompliance were noted. HEISHMAN,R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/09. 2pp. 94307:047.
- --7812130338 IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliance were noted Hejor eres inspected incl.1E Bulletin & Circular followup & qual of slec squip & Independent inspec.

  HUDHES, J. Region 3, Chicago, Office of the Director. 78/11/09. 65p. 94307:049.
- 7812050287 Forwards IE Bullstin#78-12A, suppl to 1E Bulletin 78-12. W/encl ANO: 7811300055. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 78/11/24. 1p.
- 7812280002 Forwards IE Bullstin 78-14.
  KEPRER.J. 0. Region 3. Chicago. Office of the Director. 78/12/19.
  19. 94133:002.
- R. Periodic operating reports & related correspondence
- 7810180049 Manthly Oper Rept for September 1978. SCHNEIDER, H. L. Commonweelth Edison Co. 78/10/03. 13pp. 94063:065.

- Michigan near sub; facil-July 1977 thru June 1978 Vols 1-1V " WANDKE:N Commonwealth Edison Co. 78/10/24. 1p 94099:002.
- --7811010131 Annual rept entitled "Oper Environ Menitoring in Lake MI near subj facil"-July 1977 thru June 1978" prepared by NALCO Environ Sciences

  a Commonwealth Edison Co. 78/11/01. 1617pp. 94090:003.
- 8 Reportable occurrences. LERs & related correspondence
- 7812120121 Notification of deficiency found 780913 in valve cross assemblies inlet & eshaust push assemblies of KBV Pur Engine & corrective action to design roller pin & replace hand flaring oper.

  BENDER, 8, 8. Cooper Industries, Inc. 78/11/03. 2pp. 94275: 329.
- 7810170208 Forwards LERM78-057/031-0.
  WANDKE-N E. Commonwealth Edison Co. 78/09/08. 1p 94236: 131.
- --7810170211 LERM78-057/03L-0 on 780811 Unit 2 Containment Particulate Ventilation Rad Monitor-2RE0011.eshibited spurious elemes. & detector would not respond to source check due to loose signal wire on "oper"selector switch in control room TR2YNA, 0. Commonwealth Edison Co. 78/09/08. 1p. 94236:132.
- 7810170184 Forwards LER#78-078/01L-0 WANDKE-N E. Commonwealth Edison Co. 78/09/15 Ip. 94270: 052.
- --7B10170189 LERW7B-078/01L-0 on 7B0B1B.possible use of atypical weld metal discovered in 4-loop PWR Reactor Vessele in subj fecils interim RCB heatup & cooldown curves calculated & used to provide adequate conservatism until issue resolved BHANNON, R. E. Commonwealth Edison Co 78/09/15. 3pp 94270.053
- 7810170251 Forwards LERN78-060/03L-0 HANDME:N.E. Commonwealth Edison Co 78/09/25 ip. 94236: 338.
- --7810170253 LER#78-060/03L-O on 780826: Unit 2 Air Ejector rod monitor ERTPR26 #11ed and would not reset. Event resulted from failure of Roots-connersville blower. Pump was replaced and returned to service.

  WANDKE.N. E. Commonwealth Edison Co 78/09/25. 1p. 94236.339
- 7810170218 Forwards LERM78-061/03L-0. WANDKE-N.E. Commonwealth Edison Co. 78/10/05. 1p. 94236:156.
- ---7810170222 LERW78-061/03L-0 on 780905 during testing MCC tripped due to a cracked Limitorque case caused by Jamming Rodundant VLV was operable to insure containment integrity Motor case, handwheel & bracket replaced & VLV returned to eve. REIBB.J. Commonwealth Edison Co. 78/10/05. 1p. 94236:157.
- 7810170239 Forwards LER878-062/03L-0.

  MANDKE-N.E. Commonweelth Edison Co. 78/10/06. 1p. 94236-324.
- --7810170242 LER#78-062/031-0 on 780906: During testing, RWST to charging PP suction vaive, 2mov-vcii2s, failed to open remotely degrading eye per T. S. J. S. L. B. Limitorque model GMB00 valve operator torqued out, valve stroked 3 times.
  RE188, J. Commonwealth Edison Co. 78/10/06. 1p. 94236:325.
- 7811240218 Forwards LERM78-064/03L-0. WANDKE,N.E. Commonwealth Edison Co. 78/10/13. 1p. 94466-350.
- --7811240220 LER#78-064/03L-0 on 780913: during normal open-received a channel deviation alarm. Pur range channel N42 was reading 93% instead of 100% Caused by defective 25 volt pur supply in N42 pur range drawer.
  PIECK-T. A. Commonwealth Edison Co. 78/10/13. 1p. 94466: 351.
- 7811240145 Forwards LER#78-065/09L-0.
  WANDKE,N.E. Commonwealth Edison Co. 78/10/19. 1p. 94456:248.
- 7811240147 LERM78-065/03L-0 on 780919: during normal oper-channel PL-8 had failed high & asoc bistables were tripped due to faulty XMTR(level.mode 1302495W): XMTR replaced w/spare & channel recalibr.
  ROOCRE, C.L. Commonwealth Edison Co. 78/10/19. ip. 74456:249.
- 7811240195 Forwards LERM78-066/03L-0. WANDKE, N. E. Commonwealth Edison Co. 78/10/25. 1p. 94458:342.

- --7811240196 LER#78-066/03L-0 on 780925; pressurizer level 2LT-459 was found to be 6% louer that the other 2 channels, No cause was found for failure.

  HNNEEN.P Co-conwealth Edison Co. 78/10/25. Ip. 94458:343.
- 7811240139 LERB78-067/03L-O on781008:8/Q level channel 2 LI-538 was found to be indicating 6% higher than the other 2 channels. Caused by dirt in XMTR sensing lines & a XMTR oscillator PN803827U01 being out of tune.

  GAMPBELL, J. Commanuealth Edison Co. 78/11/04. lp. 94456:362.
- 7811240135 Forwards LERK78-067/03L-0.

  HANDKE,N.E. Commonwealth Edison Co. 78/11/06. Ip. 94456:361.
- 7811240176 Forwards LERW78-069/03L-0. WANDME:N E. Commonwealth Edison Co. 78/11/14. ip. 94458:271.
- --7811240179 LERRY8-049/03L-0 on 781015:20 MSIV feiled to close from the control room Caused by feilure of both DC solenoid valves & AC adjanoid valve. AC solenoid valve replaced.
  MELNICOFF, M.A. Commonweith Edison Co. 78/11/14. 3pp. 94459:272
- 7812210217 Forwards LER#78-071/03L-0.
  WANDKE N. E. Commonwealth Edison Co. 78/12/08. Ip. 94279:117.
- --7812210221 LERP78-071/03L-0 on 781108: during monthing performance test on containment agrey pump 2C.a cooling water hose on dissel angine broke. Caused by a defective cooling water hose on dissel angine.

  KRANCZAK.A.T. Commonweith Edison Co. 78/12/08. ip. 94279: 118.

### T. Hearing transcripts on non-antitrust metters

- 7812040045 Trenscript of 781121 hearing to subj facil spent fuel pool sysansion, pp. 181-287.
  LUTCN.E. REMJCK.F. J., LITTLE, L. W. Atomic Before and Licensing Board Panel. 78/11/21. 107pp. 94325:179.
- 7812040047 Transcript of 781120 hearing rs subj facil spent fuel pool expension, ppi-180.

  LUTON E., REMICK,F.J., LITTLE.L.W. Atomic Safety and Licensing Board Panel. 78/11/20. 181pp. 01791:057.
- DOCKET 50-305 KEHAUNEE NUCLEAR POWER PLANT
- F. Security. medicel. emergency & fire protection plans
- 7810300116 Sumary of 780928 & 29 meeting re fire protec open items. Util agreed to implement some parts of the "Fire Sefety Protec Eva)" by 800101 & present further rept es to why other recommendations need not be met. MLYNCZAN, M. M. Operating Reactors Branch i (Pre 790625). 78/09/29. 4pp. 94035:189.
- 78:03:30:10 Request for add1 info on firs protec w/edd1 steff position re fire rating of barriers separating dissel generator rooms from corridor to screenhouse.

  BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/06.
- 7810300105 Forwards responses to 781006 NRC request for addi info re fire grotec: "Responses to Request for Addi Info", "Analysis of Circulating Heter Pump Dil Fire", "Analysis of Relay Room Fire".
  - JAMES: E. M. Wisconein Public Service Corp. 78/10/25. 14pp. 94035:026.
- 7812210194 Forwards rev to Industrial Security Menual of subj facil. Requests w/holding from public disclosure. JAMES E. M. Wisconsin Public Service Corp. 78/12/18. ip. 94279: 066

#### Q. Adjudicatory correspondence

- 78:0169017 Expresses concern re-adequets & ratioble elec pur supply. Requests limited epprerance in support of util in subj lic renewal processings.

  MOFPHAN.R.P. Green Bay Packing, Inc. 78/09/29. Ip. 94004:339.
- 7B1G170040 Requests limited appearance in support of HI Pub Svc in increesed apent fuel storage matter. PEARSON.T. N. Affiliation Unknown. 7B/10/02. ip. 94235:335.

- 7811210471 Issuence date for principal documents has been deferred to 781127.
  LAWRENCE, J. F. Office of the Executive Legal Director. 78/10/31.
  19. 03058: 220.
- 7812010079 Requests info re making appearance at pub hearing re subj facti. 8CHMIDT.T.M. Wisconsin Paper Council 78/10/31. ip. 94416.225.
- 7812040141 Farwards NRC Staff's interrogs to Citizens for Sefe Energy/ Bafe Haven, Ltd. Response must be served on or before 781129. LAWRENCE, J. F. Office of the Executive Legal Director. 78/11/09. ip. 94456:087
- --7812040144 NRC Staff interroge to,& request for production of documents from intervenors Citizene for Bafe Energy/Safe Mayer Ltd.
  Interroge concern testimons to be presented, admitted contentions & ASLB questions.
  LARRENCE, J.F. Office of the Executive Legal Director. 78/11/09, 79p. 94456.088.
- 7812040285 Forwards Staff Interrog to Citizens for Safe Energy/Sals Heven Ltd. Response must be served by 781128. LAMRENCE, J. F. Office of the Executive Legal Director. 78/11/09, 1p. 94379-342
- --7812040288 NRC Steff Interrogs to & Request for the Production of Documents from Intervenors Lakeshors Citizens for Bafe Energy/Bafe Haven Ltd LAMRENCE, J.F. Office of the Executive Legal Director. 78/11/09, 900.
- 7812050245 Forwards Staff Interops to State of WI.Response requested by 781128.
  LAWRENCE, J. F. Diffice of the Executive Legal Director. 78/11/09.
  19. 94202:068.
- --7812050252 NRC request for production of documents from & interrogs to Blate of NI re plenned testimony & witnesses.

  LARRENCE, J. F. Diffice of the Executive Legal Director. 78/11/09. 3pp. 94202:069.
- 7812110305 Interrogs submitted by intervenor LACSE to applicant WMSC re LACSE contentions on such topics as radiosctive emissions, experiments on deterioration of neutron obsorber plates & removal of redioactive westes. Certificate of Svc enci. BABI.S.A. Leteshore Citizens for Sefe Energy. 78/11/11. 4pp. 94204:090.
- 7811290273 Notice of w/drawel by J Lawrence as counsel representing NRC in proc re increase spent fuel storage capacity at subj facil. Future correspondence should be eddressed to W Climsteed Cart of Svc enci.
  LAWRENCE.J.F. Office of the Executive Legal Director. 78/11/13. 3pp. 94237:036
- 7812130220 Licensee Hi Pub Byc first set of interrogs to & request for production of documents from intervenors LACE & Bt of MI. Interrogs concern inter aliasidentification of intervenors contentions & presentation of evidence.

  BAKER.D. A., KEANE.S. E. Wisconsin Public Service Corp. 78/11/20. 3pp. 94243.049.
- 7812180267 Response by intervenore 8 Best & H Schaefer to NRC Steff's first set of interrogs. Cert of Svc enci. BAST 8.A. SCHAEFER W. Affiliation Unknown. 78/11/28. 9pp. 94365:335.
- 7812210006 "intervenors Responses to Licensess" First Est of Interrogs" A Thermo-Inversion eround the pient sites may cause a higher level of radiat to be present. Thermo-Inversion prevents emissions escaping to higher atmosphere. Cert of Byc encl. CGROARG. M. M. Affiliation Unknown. 78/11/28. 7pp. 94249:291.
- 7812220027 Interrogs propounded by St of WI to applicants MIPS, HI Per à Light à Madison gas & Elec re appl to mod apant fuel pool. Interrogs concern Contentions#2 & #13.
  WALSH,P. Wisconsin, State of. 78/11/30. 4pp. 94248:322.
- --7812220029 Interrags propounded by 8t of WI to NRC Steff. Interregs concern Steff's position re tech merit of each of intervenor's admitted contentions.
  WH.SH.P. Wisconsin. State of. 78/11/30. 4pp. 94248:326.
- --7812220001 Bt of MI's answers to NRC Staff's first set of interfess to request for production of documents. St does not anticipate utilizing in its crose-exem any documents not already listed by Staff to applicant MIPS. Cart of Svc encl.
  WALSH.P. Misconsin, State of. 78/12/01. 3pp. 94248:330.

- 7819270037 Notifies intervenor that they failed to address section "c" of "Interrogatories Relating to Bd Questions" of 781109, which must be enswered in timely writing. EVAND, D. J. Office of the Executive Legal Director. 78/12/05. 3pp. 94160:207.
- p. Operating license stags documents & correspondence
- 7812130386 "Fire Protec in Oper Nuc Pur Stations-Kawaunee Safety Evai Rapt Raview" lists sycaptions to fire protec prod rappresenting a differing engr point of view which should be eval by NRC incl turbine bldg.control valvesteir compressor. HALLR.E. Brookhaven National Laboratory. 7812130386. 78/09/06. 6pp. 94292:222.
- 78:01:00:00 Qualification of Reactor Physics Methods for appl to subject Addresses reactor model description qualification & quantification of reliability factors & apple to opens & reliable sefety eveluations of subject.

  e Wisconsin Public Service Corp. 78/09/29, 188pp. 94065:001.
- 7810120041 Forwards non-proprietary & proprietary copies of "dusiffication of Resector Physics Methods for Appl to KewkunserWydserciption of neutronic calculation methodology for NRC rev. H/o encl repts.

  JAMES. E. W. Wisconsin Public Service Corp. 78/10/05. 2pp. 9432: 315.
- --7810120042 States that some mati in the rept"Qualification of Reactor Physics Methods for Appl to Kewaunes"is proprietery t should be withheld from public.
  FIBHER, J. R. Nuclear Associates International Corp. (subs. of Control Data Corp.). 78/09/28, 6pp. 94332:317.
- 7810110093 Responds to 780913 NRC request for schedule for submittel of rev ECCB analysis w/corrected tirconium-water heat generation calculations. Earliest submittal data is Jan, 1974 JAMEB. E. M. Hisconsin Public Service Corp. 78/10/06. ip. 94065-352.
- 7810310016 Summarizes meeting on 780929 re Westinghouse rad bank swap meeturement prog.
  RDSBTHAL, J.E. Reactor Safety Brench (Pre 791030). 78/10/13. 4pp. 94094;326.
- 7811080339 Notice of 781101 meeting w/util re reactor physics methods qualification. MLYNCZAW, H. M. Operating Reactors Branch 1 (Pre 790625), 78/10/23, 291. 74406:305.
- 7810270139 Forwards copies of proposed Amend#35 to subj facil Tech Bpscs. Proposed change responds to NRC request dtd 780828 re Overpressure Protection Tech Specs on mods installed in subj facil. JANED.E.W. Misconsin Public Service Corp. 78/10/24, Spp. 94060:037.
- 7811200373 Bummerizes meeting of 781101 w/representatives of WPSC.NAI & Eizen re NRC review of WPSC topical rept. "Qual of Resctor Physics Nethods for Appl to Kewaunee" of 781005. NRC will issue forms! request for add1 info. Attendence list encl. MLYNCZAK.M. M. Operating Resctors Branch i (Pre 790625). 78/11/06. 3pp. 74419: 224
- 78iii30i4i Notifies applicant of 78ii28 NRC-epumspred seminer re Model Rediological Effluent Tech Specs for Nuc Per Plants, Enci w/Sminer Info Sheet(to be completed & returned by 78iii7) & Proposed Agenda. KEPR-ER.J. 9. Region 3. Chicego. Office of the Director. 78/11/07. 6pp. 79087:325.
- 781ii40195 Forwards proposed Amend#35 to sub; facil Tech Spec, changing definition of rated pur, updating safety related shock suppressor listing & correcting error in listing of firm datectors. Also forwards check for fes.

   Wisconsin Public Service Corp. 78/11/10. 18pp. 94384;295.
- 78ii280079 Forwards request for add1 info after reviewing topical rapt. "Qualification of Reactor Physics Methods for Appl to Kswaunes." Response requested by 78ii30. 8CH-ENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/15. 3pp. 03554:262.
- 7811280359 Forwards copy of TB 3.10-1 which was issued w/Amendel6 to Fecil Oper LiceDPR-43 on 770325. This page was inadvertently satisfied from some Tach Spec copies.

  8th-RNCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/15.
  3pp. 94397:219.

- 7812150198 Notice of workshops re implementation of training & qual requirements contained in Append B of IOCFR73. Requests pre-workshop registration of attendees to facilitate sending out mall. Myenci Registration Form & List of Locations. MILLER.J.R. Assistant Director for Bite & Bafeguerds (Pre 791030) 78/11/15. Spp.
- 7812190062 Forwards RevNi "Dreft Radiological Effluent Tech Spece" for PHR's(NAREO-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Per Plants" (NUREO-0133).

  GRITES-B. K. Assistant Director for Engineere & Projects (Pre 790623). 78/11/15. 6pp. 94215:101.
- 7812150006 Discusses possible dangers of LGCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. Whenci AND #7812080207.

  BCHMENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. App. 94209:206.
- 78:2080198 Forwards Bafety Eval & Environ impact Appraisal dtd 78:201 re suth to incresse spent fuel storage pool capacity at subj facil.

  8CHENCER.A. Operating Reactors Branch i (Pre 790625). 78/12/01 2pp. 94:09:230.
- --7812080190 Sefety Eval re Mod of spent fuel storage pool of subj facil Concludes such expension will not be inimical to pub health or security. • Office of Nuclear Reactor Regulation, Director. 78/12/01. 13pp. 94109:232.
- --7812080193 Environ Impact Appraisel re mod to epent fuel storage pool. Finds proposed lic amend will not significantly affect quality of human environ, so environ impact statement need not be prepared.

  a Office of Nuclear Reactor Regulation, Director, 78/12/01, 20pp. 94109:246.
- 7812080108 Responds to 781115 request for add1 info re "Qual Reactor Physics Methods for Appl to Keweunes." Add1 info describing methodology & procedures to evel key physics parameters to determine if reanalysis of accidents is request for 790115.

  JAMES E. W. Histonein Public Service Corp. 78/12/05. 22pp. 74107:314.
- 7812280119 Emphasizes importance of submitting occurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracise or enforcement action will result. DAVIS.J.O. Office of Inspection & Enforcement. Office of the Diractor, 78/12/06. Spp. 74310:215.
- 78122800ii Forwards Amend#23 to Facil Oper Lic#DPR-43--revising tech specs as requested in 781025 ltr w/BaPety Eval & Notice of leeuance.

  8CHMENCER, A. Operating Reactors Branch i (Pre 790625). 78/12/12.
  2pp. 94130: 193
- --7812280015 Amend#23 to Facil Oper Lic#DPR-43 revising Tech Bpecs re completion of facil mods for fire protec. SCHWENCER, A. Operating Reactors Branch i (Pre 790625), 78/12/12. 2pp. 94130:195.
- --7812280016 Safety Evel Rept supporting Amend#23 to Oper LicMDPR-43 concluding that proposed mods are acceptable re improvements in fire protec prog & continued sefe oper of facil-panding resolution of incomplete items.

  Office of Nuclear Reactor Regulation, Director. 78/19/12. 53pp. 74130:197.
- --7812280018 Notice of Issuence of Amend#23 to Facil Oper Lic#DPR-43 on 781212. 8CHMENCER, A. Operating Reactors Branch i (Pre 790625). 78/12/12. 2pp. 94130:251.
- 7812270171 Responds to 770926 itr re baron dilution eccidents. Re-eval of potential for such accidents concludes no single failure could result in reactor coolent boron dilution by contents of caustic spray additive standpips.

  JAMES. R. W. Hisconsin Public Service Corp. 78/12/20. 2pp. 94018:092.
- Q. Inspection reports, IE Bulletins & correspondence
- 78:01:01:02:P forwards IE Inspec Rept#50-305/78-15 on 780807-11 during which no items of noncompliance wave noted. FIORELLI, 9. Region 3, Chicago, Diffice of the Director. 78/09/06. 2pp. 94069:117.

- 7810190026 Forwards IE Inspec Rept#50-303/78-14 on 780731-0802 during which no items of noncompliance were noted.

  HEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 78/09/12 2pp. 94329:353
- --7810190029 1E Inspec Rept#50-305/78-14 on 780731-0802 during which no items of honcompliance were noted Mejor areas inspected included: followup of unresolved items identified in IE Rept #50-305/78-08 & matls for snubber seels.

  DANIELBON.D. H. Region 3. Chicego. Resctor Construction & Engineering Support Branch. 78/09/12. 3pp 94329:353.
- 7812010065 Forwards IE Inspec Rapt#50-305/78-16 on 780711-13 during which no items of moncomplience were nated. DAVIEA B. Region 3. Chicago. Fuel Fecility 6 Materiels Safety Branch. 78/09/29. 2pp. 94416:190.
- --7812010070 IE inspet Rept#50-305/78-16 on 780911-13 during which no items of noncomplience were noted. Hejor aress inspected incl:quelity control of analytical measurements of rediol effluents, internal audits.

  AXELSON, H. L., ESSIO. T. H. Region 3, Chicego, Office of the Director. 78/09/29. 9pp. 94416:192.
- 7810230337 Forwards IE Circular#78-17. (See ANO:7810230221 Docket 50-133.781013)

  XEPPLER.J. Q. Region 3. Chicago. Office of the Director. 78/10/13. 1p. 74166:360.
- 7811070227 Responds to 78090B request for edd1 info re IE Inspec Rept#50-303/78-10 item of noncomplience:contention that record keeping of ultrasonic test couplant meth did not conform to Tech Specs. JAMEB.E.W. Wisconein Public Service Corp. 78/10/13. 2pp. 74079-196.
- 7812060124 Forwards IE inspec Rept#50-305/78-17 on 781002-06 during which no items of noncomplience were noted. FIORELIA. O. Region 3. Chicago, Resctor Operations Nuclear Support Branch. 78/10/27. Rpp. 94332:231.
- --7812060128 IE Inepsc Reptw50-303/78-17 on 781002-06 during which no litems of noncomplience were noted. He jor erese inspected inclidesign changes, procurementariscords, nonroutine followup & IE Bulletin followup.

  CHOULES, N. C., WARNICK, R. F., Region 3, Chicego, Office of the Director. 78/10/27. App. 94332:233.
- 78:1130351 Ack receipt of 78:013 Itr Informing NRC of steps telen to correct violations noted in 78:0708 NRC Itr.Bletes thet recordiseping is licensee's responsibility.

  KEPPLER, J. O. Region 3. Chicago, Diffice of the Director. 78/11/05.

  ip. 94:007:3325
- 7811150072 Forwards IE Circular 78-18.
  KEPPLER.J. Q Region 3. Chicago, Office of the Director. 78/11/06.
  1p. 94112:280.
- 7812120225 Forwards IE Inspec Rept#50-305/78-19 on 781016-17 during which no items of noncomplience were noted, #IDRELLI.9. Region 3, Chicago, Resctor Operations Nuclear Support Brench. 78/11/06. 2pp. 94277:135.
- --7812120231 IE Inspec Rapt#50-305/78-19 on 781016-17 during which no items of honcompliance were noted Mejor erest inspected inclitating & requal prog. fire protec & prayention prog. MASSE,R.E. Region 3, Chicago, Office of the Director. 78/11/02. Spp. 94277:137.
- 7812050267 Forwards IE BullstinN78-12A, suppl to IE Bullstin 78-12. W/encl AND: 7811300055. KIPPLER.J. Q. Region 3, Chicago, Office of the Director. 78/11/24. lp. 94202:213.
- 7812290009 Forwards IE Inspec Rept#50-305/78-21 on 781025-26 & Notice of Violation.
  FIORELLI, G. Region 2. Atlanta, Reactor Operations Nuclear Support Brench. 78/11/24. 2pp. 74207:330.
- --7812290011 Notice of Violation from inspec on 781025-26.

  \* Region 3. Chicago, Office of the Director. 78/11/24. ip. 94207:332.

- --7812290014 IE Inspec Rept#50-305/78-21 on 781025-25 during which 1 it of noncompliance was noted failure to fully implement on acceptable inevoltesting prog for pumps & valves.

  SMITH.J. D., STREETER.J.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/21. 3pp. 94207:333.
- 7812280053 Forwards IE Bulletin 78-14. KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/12/19 1P. 03554:358.
- R. Periodic operating raports & related correspondence
- 7810170156 Forwards Monthly Open Rept for Sept 1978.

  JAMES.E. W. Misconsin Public Service Corp. 78/10/10. 1p. 94236-091.
- --7810170139 Monthly Oper Rept for Bept 1978.
  WALLACE, J. J. Wisconsin Public Bervice Corp. 78/10/04, 4pp. 94236:092.
- 7811140116 Forwards Monthly Open Rept for Oct 1978.

  JAMES, E. H. Hisconeln Public Service Corp. 78/11/08. ip. 94425: 177.
- --7811140118 Monthly Open Rept for Oct 1978. WALLACE, J. J. Hisconsin Public Service Corp. 78/11/03 6pp. 94425-178
- 8. Reportable occurrances, LERs & related correspondence
- 7810100035 Forwards LERW78-030/03L-0.

  JAMES.E.M. Misconein Public Service Corp. 78/10/02. 1p. 94415:161.
- --7810100062 LERM78-030/03L-0 on 781002:during steedy full pur oper one 8H pump failed due to excessive undercutting of the encl tube for tool relief at internal end threads during mfg. RUITER.O. H. Hisconsin Public Service Corp. 78/10/02. ip. 94415:162.
- 7810130149 Forwards LER#78-024/03X-3.

  JAMEB.E.W. Wisconsin Public Service Corp. 78/10/09. 1p. 74002.334.
- 7810230247 Forwards LERW78-024/03X-0.

  JAMES, E. W. Wisconsin Public Service Corp. 78/10/09. 1p. 74164-081.
- --7810230251 LERB78-024/03X-3 on 780905: supply breaker to MCC 1-62f opened 17 times on 9 experats dates. Breaker trip coil does receive 2 spurious elec trip signel w/out overload condition present.
  RUITER, 9. H. Wisconsin Public Service Corp. 78/10/09. 1p. 94164-082
- 7810240128 Forwards LERM78-031/03L-o.

  JAMES, E. W. Wisconsin Public Bervice Corp. 78/10/18. lp.
- --7810240138 LER078-031/03L-0 on 780918: smell leak was discovered on the discherge of coolent cherging pump IC while CCP IB was out of SVC & for meint Creck in CCP IC was caused by oper stress & vibration loading.

  RVITER. 9. H. Wisconsin Public Service Corp. 78/10/18. 1p.
- 7811220196 Forwards LER#78-032/03L-0.

  JANES: S. W. Hisconsin Public Barvice Corp. 78/11/17. 1p. 74074:251.
- --7811920199 LER#78-032/03L-0 on 781019; whils performing monthly 4-hour full load 6/9 SP load, D/0 1A drifted low & could not be raised until load was decreased to less than 2100 KH. Caused by meladjustment of cam in upper load limit switch. RUITER. O.H. Wisconsin Public Service Corp. 78/11/17. ip. 94074:232.
- 7811280299 Forwards LER078-033/04L-0 & 78-034/03L-0.

  JAMES E. W. Wisconsin Public Service Corp. 78/11/22. 1p. 94395-294.
- --7811280305 LERW78-033/04L-0 on 781024: "Saults of PH enelysis of grab sample from water suftening unit regeneration waste water were not recorded on log sheet. Lab personnel failed to record PH sample results.

  RUITER.O. H. Wisconsin Public Service Corp. 78/11/22. ip. 74395:295.

- --7811280310 LER#78-034/03L-0 on 781025: trein B reactor trip breater would not open immediately when a trip signal was applied. Adjustable reset lever on breaher undervoltage trip attechment would not reset due to normal wear RUITER, C. H. Wisconsin Public Service Corp. 78/11/22. 1p.
- 7812150232 Forwards LER#78-035/00L-0 JAMES E.W. Hisconsin Public Service Corp. 78/12/11. 1p. 94213.156.
- --7812150234 LER878-035/03L-O on 781111: improper switching sequence course bus 1-5 to trip. Caused by add1 switching procedure step edded in wrong place. Procedure corrected & tasted while plant was shutdown.

  BUITER. G. H. Wisconsin Public Service Corp. 78/12/11. 1p. 2012/157.
- DOCKET 30-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2
  F. Security, medical, smergency & fire protection plans
- 78iii40143 Forwards responses to 780913 &i9 NRC ltrs re eddl info on fire protec prog squip.
  MAYER.L.O. Northern States Power Co. 78/11/08. 16pp. 94383:250.
- 7811290076 Summerizee progress of Fire Protec Review M/shc1 request for add1 info, steff positions. A svels. Requests meating w/license i week efter racsipt of responses to latest staff positions.

  LAIMS, 0. Plant Systems Brench (Pre 791030). 78/11/16. 27pp. 94192:182.
- 7811290365 Requests addl info re fire protec prog & forwards NRC staff project & racommandations. Areas needing info include: equip ret for echieving hot shutdown & fire brigede training. 8CHERNER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/21. 28pp. 94180:001.

#### 1. Financial information

- 78:03:00:156 Forwards 1977 Annuel Rept & schedule showing 1977 actual Cash Flow to comply with Reg Guide 9. 4. Nat income by dividends declared instead of dividends peid has been reduced to get reteined earnings Figure.

  CARLSON.L.R. Northern States Power Co. 78/10/23. 2pp. 94034:143.
- P. Operating license stage documents & correspondence
- 78iii:00ii5 Requests lic emend no later then 78i2i5 re Deletion of Resetor Trip on Turbine Trip Below 50% pur & encl requests for Tests Bost changes & safety evaluation supporting changes.
  MAYER-L.O. Northern States Power Co. 78/ii/03. 34pp. 94ii3:340.
- 7811170255 Forwards Amend#32 & 26 to out; fecil oper lic re pressurized heetup rete reactor vessel pressure-temperature oper limits. Also forwards BER, Notice of Issuance, Tech Specs & Table of contents releted to Amend#32 & 26.

  BCHEMCER, A. Operating Reactors Stanch 1 (Pre 790625). 78/11/01.
  2pp. 94049:035.
- --T8iii70259 AmendeQ2 & 26 to open lid chenging Tech Specs related to heatup rate, reactor vastel pressure-temperature open limits, and the pert length rods.

  SCHENCER.A. Operating Reactors Branch 1 (Pre 790625), 78/ii/0i. 18pp. 94049:037.
- --7811170265 SER for Amends#26 & 32 to subj facil oper lic. Concludes that Tach Spec changes releted to heatup rate-reactor vessi pressurg-temp oper limits. & part length rods does not involve a major hazerds consideration. SONMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/01. 5pp. 94047-055.
- --7811170268 Notice of Issuence of Amend#32 & 26 to subj fecil oper lic. SCHENCER, A. Operating Reactors Branch 1 (Pre 7906R3), 78/11/01. 2pp. 94049:060.
- 7811280403 Natice of Proposed Issuence of Amend to Pacil Oper Lic 4DPR-42 & DPR-60, rev Tach Spec re use of Exxon fuel in Cycles 5 thru 8.
  8CMENCER.A. Operating Reactors Branch i (Pra 790825). 78/11/09.
  4pp. 94397:317.

- 7812010083 Confirms telephone discussion on 781107 re 781116 meating for local pub officials in vicinity of subj facil Forwards tentative agenda.
  KEPPLER, J. O. Region 3. Chicago, Office of the Director 78/11/08 3pp. 94417:137
- 7812190047 Forwards Revell "Dreft Radiological Effluent Tech Specs" for PUR's(NUREO-0473) & "Preperetion of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

  ORINES, B.K. Assistent Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94215:039
- 78i0170220 Outlines schedules for correction of Zirconium-Heter reaction inconsistency & dev of Upper Plenum Injection model & plent specific celculations Tentative completion date is April 1979.

  MAYER, L. D. Northern Stetes Power Co. 78/10/12 2pp. 94236-163
- 7810300100 Natice of 781026 meeting w/ util to discuse bases for reactor coolent Tech spec in 780907 NRC ltr to util 9R0TENHUIB.M. Operating Reactors Brench i (Pre 790625). 78/10/12. 2pp. 94035:066.
- 7810300237 Evaluation of Overell Asymmetric LOCA Loads Notifies of decision to discontinue perticipation in utility task group's ectivities. Buby util's plan is practicel because of relatively recent design of reector coolant sys piping MAYER, L. D. Northern Stetes Power Co. 78/10/25 4p. 94034:034.
- 7011130338 Confirms upcoming 781116 meeting to discuss hRC's reg prog for protecting pub heeith & safety. A tentetive neeting agenda is enclosed KEPPLER.J.Q. Region 3: Chicago, Office of the Director. 78/11/02. 3pp. 94007.305.
- 78:1140022 Confirms uptoming 78:116 neating to discuss NRC's reg program for protecting pub heelth 5 safety A tentative meeting agende is enclosed.
  KEPPLER.J.Q. Region 3: Chicago, Office of the Director. 78/11/02 2pp. 94419:024.
- 7811160191 Confirms telephone plens to mest & discuss pub heelth & safety protec prog es it relates to subj fecil. Tentative agenda for 781116 masting encl.
  KEPPLER.J. O. Region D. Chicago. Office of the Director. 78/11/02.
  3pp. 94136:059.
- 7811150147 Lic Amend request proposing changs to reactor trip on turbine trip setpoint. Rev setpoint is justified on basis of NRC approved transient energies asthods employed by Westinghouse Corp.

  \* Litense Fee Menegement Branch, 78/11/03, ip. 94272:360.
- 7811130137 Notifies epplicent of 781128 NRC-sponsored seminer re Model Radiologicel Effluent Tech Specs for Nuc Pur Plents Encl W/Seminer info Sheet(to be completed & returned by 781117) & Proposed Agenda. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 78/11/07. App. 00353: 293.
- 7811210482 Confirms plens for 781116 meeting concerning reg prog for protect of pub heelth & sefety re subj facil. Tentative agenda and L. KEPPLER, J. O. Region 3, Chicago, Office of the Director. 78/11/08. 3pp. 94480; 327.
- 78i1290010 Forwerds "Notice of Proposed Issuence of Amsadments to Facish Oper Lic," in response to 780908 amsnd applies refusing of facil w/Exxon Nuc Co Fvel for oper Cucles 5 thru 8 at each unit. H/encl AND: 78i1280403.

  BCHMENCER.A. Operating Reactors Brench 1 (Pra 790625). 78/11/09.

  2pp. 94179:112
- 7812180050 Natice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to fecilitate sending out meth. W/encl Registration Form & List of Locations. MILLER, J.R. Assistant Director for Site & Sefequards (Pre 791030). 78/11/15. 5pp. 94133:070.
- 7811280195 Forwards lic emend fee for lic#DPR-42 & DPR-60, Lic amend request involves a single safety issue.

  \* Northern Stetes Power Ca. 78/11/22. ip. 94013:253.
- 7811280277 Request for emend to open lic#DPR-42 & DPR-50 to change Tech Specs re escondary coolant chamistry monitoring requirements. Incl safety eval & minimum fraquencies for sampling tests. Hycheck for \$4,400. MAYER.L.O. Northern States Power Co. 78/11/22. 3pg 94299:222

- 7812150061 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Myenci AND.
  7012080207.
  8004EMCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/28 dpp. 94210:122
- 7812060141 Forwards Environ Event Rept 78-11 on Cooling Tower Open for Nov 1978. Blightly elevated blowdown flow req for 3 days, during month to accomplete cooling sys preventative maint work
  MARD. E. C. Northern States Payer Co. 78/12/01 ip. 94372-251.
- 7812080135 Forwards 780216 rept "Analysis of Capsule V from NSP prairie Island#2 Reactor Vessel Radiat Burveillance Prog. "MCAP-9212 to replace those forwarded 780216 k lost in transit MAYERL D Northern States Power Co 78/12/06 ip. 94104 255.
- --7812080138 Forwards "Analysis of Capsule V From NSP subj facii Unit#2 Reactor Vessel Radiat Burvelllanca Prog." MCAP-9212 HAYER.L. Q Northern States Power Co 78/02/16 1p 94104.256.
- --7B:2080142 'Analysis of Capsule V from NSP subj facil Unit#2 Reactor Vessel Radiat Gurvelllance Prog." Repts effects of neutron irrediation on reactor pressure vessel matl under operating conditions
  DAVIDSON.JA. YANICH
- 78:2220017 Emphasizes importance of subditting accorate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J. O. Office of inspection & Enforcement, Office of the Director 70/12/06. 2pp. 94:31:034.
- 7812/130215 Requests util help w/vital area analysis re subj facil. Informs of site visit on 790109-ii by Los Alamos Scien Leb representatives. BCHMENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/12/08 2pp. 94306:081
- 78:2190154 Summary of 78:026 meeting to discuse tech specs for secondary water chem.reactor coolent activity & secondary coolent activity.

  OROTENBUS.M. Operating Reactors Branch i (Pre 790625). 78/12/12 Bps. 94340 150.
- 7812290236 Forwards request for additinfo re Topicel Rept XN-NF-78-30 in order to complete review of relied conditions Req info should be submitted with 45 days.

  IPPOLITO, T.A. Operating Reactors Brench 3 (Pre 790625). 78/12/19

  dop. 94191 232

## Q. Inspection reports, IE Bulletins & correspondence

- 7810110199 Ack receipt of 780918 itr informing NRC of steps taken to correct violations noted in 780829 NRC itr. F10RELL.O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04 ip. 94068:336.
- 7810230338 Forwards TE Circular#78-17. (See AND. 7810230PR1. Docket 50-313.781013)
  KEPPLER, J. Q. Region 3. Chicago, Offics of the Director. 78/19/13. ip. 94167:041
- 78iii50054 Forwards IE Circular 78-18. KEPPLER.J. Q. Repion 3. Chicego. Office of the Director. 78/11/06. 1p. 94ii2:183
- 781220091 Forwards IE Inspec Repte#50-282/78-12 & #50-306/78-13 on 780905-06, 11-14-20-22 & 25-29 & Notice of Violation. FIORELLI Q. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94136:335.
- --7812200095 Notice of Violation from Inspec on 780905-08.11-14.20-22 & 25-29.

  \*\*Region 3. Chicago. Office of the Director 78/11/09. | 1p. 94184.337
- --7812200099 IE Inspec Rept#850-282/78-12 & #30-306/78-13 on 780905-08, 11-14,20-12 & 25-29 during which I item of noncompliance was noted:failure to follow an implementing procedure for approved GA prog. FEIERABEND.C.O., MARNICK, R.F. Region 3, Chicago, Office of the Director, 78/11/04. Spp. 94136:338.

- 7812210046 Forwards LE Inspec ReptsM50-282/78-14 & M50-306/78-15 on 781016-20 & Notice of Violation. FIDRELI, O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/14. 2pp. 94268:335.
- --7812210049 Notice of Violation from Inspec on 781016-20.
   Region 3: Chicago: Reactor Operations Nuclear Support Branch 78/11/14. 1p. 94260:337
- --7812210034 1E Inspec Repts#50-282/78-14 & #50-306/78-15 on 781016-20 during which I Item of noncompilance was noted an employee was not warring proper protective equipment.

  RIDEN.M D. LITTLE.M.B. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/14 4pp. 94268 338
- 7812050278 Forwards 16 Dulletin#78-12A, suppl to 16 Builetin 78-12. W/encl ANO.7811300035 REPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/24 ip 94202:165
- 7812210036 Responds to 781109 NRC itr re violations noted in Inspec Rept#80-282/78-12 & #30-306/78-13 Corrective actions:Design Change Index Form(A)PINOP#340 rev to incl date of completion of installation. #ACHTER.L.J. Northern States Power Co 78/11/30. ip. 94267.362
- 7812270028 Ack receipt of 781130 itr informing NRC of steps taken to correct violations noted in 781109 NRC itr. FIDRELLIO Region 3. Chicago, Resctor Operations Nuclear Support Branch. 78/12/14. ip. 94159:242.
- 78:220062 Forwards IE Bulletin 78-14. REPPLER J O Region 3. Chicago Office of the Director. 78/12/19. 19. 03364:330.
- R Periodic operating reports & related correspondence
- 7811140117 Monthly Oper Rept for Oct 1978.

  Northern States Power Co. 78/11/01. 8pp 94425:169
- 7812120091 Forwards Monthly Oper Rept For Nov 1978
  MAYER, L.O. Northern States Power Co. 78/12/08. ip. 94274-195
- --7812120094 Monthly Oper Rept for Nov 1978. HLWSTAD.A A. Northern States Power Co. 78/12/01. Bpp. 94274, 196.
- 7810120029 Forwards Monthly Oper Rept for Sept 1978. MAYER-L.O. Northern States Power Co. 78/10/09. ip. 94421-174
- --7810120033 Monthly Open Rept for Sept 1978. HLM91AD.A.A. Northern States Power Co. 78/09/30. 4pp. 94081;305.
- 7811140113 Forwards Monthly Oper Rept for Oct 1978.
  MAYER, L. O. Northern States Power Co. 78/11/09. 1p. 94423 139.
- 8 Reportable occurrences, LERs & related correspondence
- 7810180034 Forwards LERN78-017/03L-0.
  MAYER, L. Q. Northern States Power Co 78/09/12. ip. 94195:199.
- --7Bi0iB0036 LER#7B-017/03L-0 on 7B0Bi5: During surveillance test. Channel of low pressurizer pressure tripped below iBi5 paig limit & 1 channel of 10/10 steem line pressure tripped below 300 paig limit. Caused by instru
- 78:0170224 Environ Event Rept 78-09 re open of plant circulating eater eye in partial recycle mode for Sept. Except for 780921, excess bloudown flow was needed. For the month, average daily bloudown flow rate was about 480cfs. WARD.E.C. Northern States Power Co. 78/10/02. 1p. 94236:166.
- 7810180021 Forwards LERN78-019/03L-0.
  MAYER.L.Q. Northern States Power Co. 78/10/12. 1p. 94195:191.
- --7810180025 LERW78-019/03L-0 on 780915: during course of investigative maint on NIB pur range channel 2N41, channel failed.

  Channel taken out of eve w/in 3 minutes. Caused by failure of -23V pur supply. Pur supply replaced.

  HNBTAD, A. A. Northern States Power Co. 78/10/12. 1p. 94193:192

- 70213 Environ Event Rept 78-10 covering oper of Plant circulating props in partial recycle code u/daily average blowdown prin excess of 150 cfs b.E.C. Northern States Power Co 78/11/01. ip 94039-122
- XXXXX Reportable Occurrence 4P-RD-78-21 on 781128 during local interest at Unit 2 refueling penetration 258. Samment Purgs Supply exhibited leakage in excess of Tech
- iimite Northern States Power Co 78/11/30 1p 94335 136. MEY. F P
- 10159 Forwards LER#78-021/01T-0 R.L.O. Northern States Power Co 78/12/12 1p 94133:331
- 2:40:6: LERA78-02:/017-0 on 78:1:20 during refueling local leak rate ising revealed lesiege in excess of Tech Sport limits thru lives in penetrations/23A & 23B Cause & Corrective action
- lli be given in Updets Rept. NSTAD. A. A. Northern States Power Co. 78/12/12. ip
- 0222 Forwards LER#78-022/03L-0. Northern States Power Co 78/12/20 1p 94159.305 38. L G
- 2260237 LERN78-022/03L-0 on 781128: during surveillance test, valvo icing leakege from CV-31239.4822 RHR Heet Exchanger Outlet live use about 7 gal/hr.due to deterioreted valve pecking NSTAD.A.A. Horthern States Power Co. 78/12/20 ip. 94139:306
- 50-309 MAINE YANKEE ATOMIC POWER PLANT eraj correspondence
- 0099 Ack receipt of ltr describing training prog underwey for irs Lehoullier & Rescorl Prog appears adequate & NRC eccept util certification when the applicants complete program successfully. .1NS.P. F. Operator Licensing Dranch. 78/10/04 ip 94422.069
- 0101 Comments on 780919 Oper training program submitted by util.
- n interim basis MOLT.D J. Assistant Director for Quality Assurance & Operations. 10/04 2pp. 94422: 067
- urance & indomnity information
- 20066 Responds to 780922 NRC ltr by encl liability insurance resembnts N21-30,33-38 to Policy NNF-194 & Endorsements N4.26-35 to Policy NNF-00 Endorsements N36,37 & 38 to O have not yet been received TREE, R. A. Maine Yankee Atomic Power Co. 78/10/04. 62pp.
- 17. 151.
- 0137 In response to 700922 request, forwards Endorsements 21 thru 10 NF-194 & Endorsements I thru 24-26 thru 33 to MF-60; 7 & 38 to MF-60 have not been received by util yet. IREE.R. A. Hains Vanise Atomic Power Co. 78/10/04 ip. 7. 184
- rating license stegs documents & correspondence
- 0171 Forwards check for \$2800 for licensing rev fee for proposed 199 N.S. deleting lic conditions for weter quality limits are lience requirements felling under EPA. Fee submitted in protect pending determination of legality of fee. E.S.H. Heine Yankse Atomic Power Co. 78/10/02. 2pp. 9:098
- 0036 Forwards supplementary rept.CEN-93(M)-P. Amend 1-P: "ME Yankee # 3 Ouide Tube Inspec & Analysis", prepared by Combustion inc. Contains proprietary into & is w/held from public. lities continued reactor oper. H/out encl E.R.H. Maine Yenkee Atomic Power Co. 78/10/06. 2pp.
- 0153 Forwards check for \$8300 for lic review fee for Class IV 0033 Forwards check for BEJUU for lic review rea for cler ECCS Evaluation Hodel for LicHDPR-36. Beliaves NRC fee dule is illegal & makes payment under protest & reserves t to recover all or part thereof. RDS.D. H. Haine Yankee Atomic Power Co. 78/10/11. 2pp.
- 0137 Confirms accomplishment of Item 3.1.2a of Table 3.i in 1tr 80424 from NRC to R. Groce. Notites on hose stations
- that to control room replaced w/norries suitable for use lec equip areas Y.D.E. Maine Yantee Atomic Power Co. 78/10/12. ip. 94400:355.

- 7811080043 Confirms sched of Corp mgt meeting for 781027 to discuss NRC inspec findings re util radiet protec prog ORIER.8 H Region I. Philadelphia. Office of the Director. 78/10/19 ip 94398 134.
- 7810270077 Describes lube oil sys & proposed mod to reduce potential lube oil leakage from reactor coolant pump Lube oil sys Oversized drawing encl.
  MORDY, D.E. Maine Yanksm Atomic Power Co. 78/10/23. 3pp. 94059 192
- 7811290317 Forwards Amend#42 to Facil Oper Lic#DPR-35 rev Tach Specs as requested in 771107 & 771201 ltrs W/appraisal of changes in monitoring prog & Notice of Issuance REID.R.W. Dpereting Reactors Branch 4 (Pre 770625). 78/11/08 3pp. 74193-264
- ~-7811290318 AmendM42 to Facil Oper LigHDPR-36 rev Tech Space re reddialogical & thermal effluent monitoring Changes involve environ surveillance prog. air particulate charcoal gamma monitoring & estuary water temp monitoring REIDLR W Operating Reactors Branch 4 (Pre 770625) 78/11/08 Thm. OALDS 202 10pp 94193 267.
- -- 7811290319 Notice of lesuance of AmendW42 to Fecil Oper LicMDPR-36 on 781100 Amend rev Tech Specs to require single continuously composited radiological sample at plant inteke REID.R W Operating Reactors Branch 4 (Pre 790625) 78/11/08 2pp 94193 277
- 7811190091 Forwards "HYAP Reactor Open w/mod CEA Quide Tubes" & Amend 1-P "MYAP Cycle III Quide Tube Inspec & Analysis "
  ORDCE.R H. Hains Yankee Atomic Power Co. 78/11/09 1p 94114 D12
- --7811150099 "MYAP Reactor or Oper w/Modified CEA Guide Tubes, "Definee guide tube wear observed in C-E reactors & describes modifications which will prevent further wear during Cycle
  - \* C-E Power Systems. CEN-093(M)-NP. 78/11/09. 86pp 94114 013
- 7811270086 Forwards Startup Teet Rept prior to Open of Cycle 4. W/enci Cycle 4 celculational model changes & CEA drop teet results ORGCE, R H Maine Yankee Atomic Power Co. 78/11/15 25pp.
- 7812130113 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out met. Whenci Registration form & List of Locations MillER. J. R. Assistant Director for Bite & Sefeguards (Pre 791030). 78/11/15. 5pp
- 7812190042 Forwards Rev#1 "Dreft Rediological Effluent Tech Specs" for PMR 's (NUREQ-0473) & "Preparation of Rediological Effluent Tech Specs for Nuc Per Plants" (NUREQ-0133) GRITES-B.K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15, 6pp. 94215:023.
- 7812070212 Notice of seminer on 781208 on new Hodel Rediclogical SECURE NOTICE OF STAINER ON PERIOD ON NEW HOUSE REGISTING EFFIVENT TECH OPERS FOR NUC PUT Plants. Requests advence submission of seminer specific questions W/encl Seminar Info Sheet Proposed Agends & meps.

  GRIER.B.H. Region 1. Philedelphie, Office of the Director.
  78/11/21. Spp. 03555 107.
- 7811290243 Informs NRC of newly dev spent fuel storage concept to increese spent fuel storage capebility of existing storage racks et environ & economic cost below any known alternetive involves compaction & storage. Wenci eval VANDENBURGH, D. Heine Yenkee Atomic Power Co. 78/11/22. 25pp. 94237: 272.
- 7812140040 Finds Yankee Pur Spike Model (YAEC-1140)accepteble. Forwards eval & suppl REID.R.W Descriting Reactors Branch 4 (Pre 790525). 78/11/27. 2pp.
- --7812140042 Bafety Eval Rept for Yenkee Pur Spike Model, Finds model acceptable. W/encl SER Supplei dtd Aug 1978.

  4 Operating Reactors Branch 4 (Pre 790625). 78/11/27. 15pp 94126 315
- 7812180373 Notification of 781212 meeting re proposed deletion of environ monitoring requirements. NELDON.C.C. Operating Reactors Branch 4 (Pre 790625). 78/11/28. 2pp. 94358:198.

- 7812150098 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing Wienel ANO: 7812080207.

  REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp.
  - REID R.W. Operating Reactors Branch 4 (Pre 790525). 78/11/29. 6 94212:010.
- 7812140383 Requests w/in 60 days specs which provide adequate assurance that containment purge valves & all hatches leading from containment are closed before radioactivity is released to environ
  RESD.R.U. Operating Reactors Brench 4 (Pre 790625). 78/11/30 2pp. 03590.112.
- 78:2180012 Notice of postponed 78:213 meeting in Betheade to discuss ME Yankee Atomic Pur's proposal to store fuel in mod "compact" fuel bundle in spent fuel storage pool. Heating date to be detarmined NELSON(C. Operating Reacture Brench 4 (Pre 790625). 78/12/04. 3pp. 94:33:248.
- 7812200220 Forwards non-proprietary version of rapt antitled "Cladding Damage Analysis of Bubj Faci) Cora II Burnable Poison Rods."

  QROCE, R. H. Maine Yankes Atomic Power Co. 78/12/14. ip. 94145: 247.
- --7812200223 "Cladding Demage Analysis of Core II Burnable Poison Rods." # Co-bustion Engineering, Inc. CEN-077(M)-NP. 78/10/30. 3ipp. 94445:240.
- G. Inspection reports, 1% Sulletins & correspondence
- 7B1016024B Forwards JE Bullstin#7B-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting ection w/in 60 days & list of IE Builetine lesued in 1978 ORIER. B. H. Region 1. Philadaiphia. Office of the Director. 7B/09/29. 6pp. 94471: 308.
- 70:10:60:192 Forwards IE Circular#78-17. (See AND: 78:10:230:221. Doctat #50-133, 78:10:13 )
  ORIER.B. H. Region 1, Philadelphia. Office of the Director. 78:/10/13. ip. 94409: L68.
- 7811120092 Act receipt of 781003 ltr informing NRC of steps taken to correct violations noted furing Inspect30-309/78-16.

  BRUNNER,E. J. Region 1, Palladelphia, Reactor Operatione Nuclear Support Branch. 78/11/03. 1p. 94114:099.
- --7811150095 Responds to 780912 NRC ltr re violations noted in Inspec Rept#80-309/78-16.Corrective actions: opers have been reminded of importance to maintain accurate complete chronological history of plant oper events. MCDDY, D. E. Mains Yanksa Atomit Power Co. 78/10/03. Rpp. 94114-100
- --7811150100 Forwards 1E Inspec Rapt#50-309/78-16 on 780821-23 & Notice of Violation.

  BRUNNER, E. J. Ragion 1, Philadeiphia, Reactor Operations Nuclear Support Branch. 78/09/12, 2gp. 94114:102.
- --7811150102 Notice of Violation from inspec on 780821-23.

  \* Ragion 1. Philadalphia, Reactor Operations Nuclear Support Branch, 78/09/12, 1p. 94114:104.
- --781150105 IE Inapec Rept#50-309/78-16 on 780821-23 during which i item of noncompliance was noted: failure to log datails of a fuel headling problem.

  LAZARUS. M. J. Ragion i. Philadelphia, Office of the Director. STAVELY. J. M., KEINIG.R.R. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78709707. 7pp. 94114:105.
- 7811270205 Forwards 1E Circular #78-18, "UL Fire Tast, "W/snc1 ANO; 7811150002.

  GRIER, D. M. Region 1. Philadelphia, Office of the Director, 78/11/06. 1p. 94237; 254.
- 7812010090 Ack receipt of 781020 itr informing NRC of steps teken to correct violations noted during inspace30-309/78-17.

  BRUNNER, E. J. Region i. Philadelphia, Reactor Gereations Nuclear Support Branch. 78/11/17. 1p. 94416:230.
- ---TB12010093 Responds to 760929 NRC ltr re violations noted in Inspet Rept#50-309/78-17. Corrective actions: during future requal proge quizzes will be admin & "Tygon H2o Menometer" celibr. Buggests Item C be withdrawn. MCDDY, D. E. Maine Yankee Atomic Power Co. 78/10/20. 4pp. 94416: 231.

- --7812010097 Forwards IE Inspec Reptw50-309/78-17 on 780903-08 t Natics of Violation.
  BRUNNER.E.J. Ragion is Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/29. 2pp. 94416. 235.
- --7812010099 Notice of Violation from inspec on 780905-08.

   Region 1. Philausiphia Reactor Operations Nuclear Support Branch. 78709/29. 2pp. 94416:237.
- --7812010103 IE Inspec Rept#50-309/78-17 on 780905-08 during which 3 items of noncompliance were noted: feilure to correct condition adverse to quality, to conduct requel prog quittes to se of menometer w/o documented calibr.

  MARKOMSKI,R.S., RUMLMAN.M., KISTER,M. Region 1. Philadelphia, Resctor Operations Nuclear Support Branch. 78/09/29. 21pp 94416-230
- 7812130140 Forwards IE Bullatin#78-12A.suppl to IE Bulistin#78-12. W/encl ANO:7811300055. ORIEN.B.H. Region i. Philadalphia. Office of the Director. 78/11/24. | p. 94212.191
- 7812010214 Forwards MYAP Inspec Rapt for 780129-780828. covaring i978 refusing outage, includes abstract of examinations parformed w/conditions observed & corrective measures taken. OROCE, R. H. Haine Yankes Atomic Power Co. 78/11/27. ip. 94409:286.
- --7812010216 Inservice inservant from 780129-780828 covering 1978 refueling outage inservalent of examinations performed by Nuclear Engineering Bucs & NDT Engineering Personnes.

  \* Maine Yantee Atomic Power Co. 78/11/27
- A. Periodic operating reports & related correspondence
- 7810170150 Forwards Monthly Oper Rapt for Sept 1978. H00DV.D.E. Maine Yenkes Atomic Power Co. 78/10/10. ip. 94236:082.
- --78i0170:51 Monthly Oper Rept For Bept 1978. BUDGREN, R. M. Heine Yentse Atomic Power Co. 78/10/i0. 4pp. 94236:083.
- 7811140112 Forwards Honthly Open Rapt for Oct 1978. MODDY.D.E. Mains Vankes Atomic Power Co. 78/11/10. ip. 94425:149.
- --7811140166 Monthly Oper Rept for Oct 1978. BUDGREN.R.M. Maine Venkee Atomic Power Co. 78/11/10. Spp. 9422: 150
- 7812150355 Porwards Monthly Open Rept for Nov 1978.
  MODDY-D.E. Maine Yankes Atomic Power Co. 78/12/ii. ip. 94418:152.
- --7812150357 Monthly Oper Rept for Nov 1978. BJOGREN.R.M. Maine Yantea Atomic Power Co. 78/12/11. 4pp. 9418:183.
- B. Reportable occurrences. LERs & related correspondence
- 78i1030i37 Forwards LER#78-023/03L-0.
  W00D, E.C. Maina Yankea Atomic Power Co. 78/09/29. 1p. 02723:308
- --78ii030i40 LER#78-023/03L-0 on 780925: Emergancy Diesel Generator D0-18 was found insperdue to introduction of air into fuel lines.

  ANDER80N.P.L. Maine Yenkee Atomic Power Co. 78/09/28. 2pp. 02723:3no
- 78:1030131 Forwards LER678-024/03L-0.
  WDDD E.C. Mains Yankes Atomic Power Co. 78/10/25, ip. 02723:296.
- --781030135 LER#78-024/03L-0 on 781017: after temporary 25% autput reduction, RCB chem samples for isotopic analysis of iodina whre not taken between 2 & 6 hours, due to personnel error. ANDERBON, P. L. Haine Yankee Atomic Power Co. 78/10/25. 2pp. 02723: 297.
- 7611220213 Forwards LER#78-022/03L-1.
  WOOD, E. C. Haine Yankee Atomic Power Co. 78/11/01. 1p. 03668:359.
- --7811220217 LER#78-022/03L-0 on 780907: rev of original LER. Further investigation revealed low RWST boron concentration was dus to dilution effects of draining a loop at a lower boron concentration to the RWST plus add

- STREVIOUR LENGTH-023/03L-0 on 781031: channel D Bafety Injection Actuation Signal Bigma meter drifted to lower setpoint than permitted Caused by instru drift.
  ANDERSON P. L. Heine Yankee Atomic Power Co. 78/11/08. 2pp. 03675.276 11220202 LER#78-023/03L-0 on 781031: channel D Bafety Injection
- 200213 Forwards LER#78-027/03L-0 DD. E. C. Maine Yankee Atomic Power Co 78/12/13. 1p. 94162:289.
- DIRECULARY LERBY B-027/03L-0 on 781007: noted that a staim general space activity sample result had not been recorded. Caused by personnel fallure to record all data.
  ANDERSON, P. L. Maine Yankee Atomic Power Co. 78/12/13. 1p. 94162.290. 112200217 LER#78-027/03L-0 on 781007: noted that a steam generator
- 200252 Forwards LER#78-028/03L-0. 100. E C Maine Ventee Atomic Power Co 78/12/13. 1p. 94206:259.
- 812200254 LER#78-020/03L-O on 781206 noted that a Procedure Change Rept had not been reviewed by the PDRC w/in 14 days of being generated Caused by personnel oversight.
- ANDERSON.P.L. Haine Yanker Atomic Power Co. 78/12/13. iP. 94206.260
- ET 30-311 BALEM NUCLEAR GENERATING STATION, UNIT 2 application/construction stage documents & correspondence
- 2080039 Forwards propristory & non-propristory rept"Dynamic relations of the Reactor Coolent Bys for Loss of Coolent cidents: Salem Nuc Generating Stations 1 & 11." affidevit per Hithholding & Appl for Hithholding UDERBON.T.M. Hestinghouse Electric Corp. 78/12/01. 2pp.
- 312080043 "Dynamic Analysis of the Reactor Codiant Bys for LOCAs." Westinghouse Electric Corp. 78/12/01. 160pp.
- 130233 P860 has filed appl for special nuc matl re subj facii on shelf of P860. Pepco, Delmarve Pewer & Light & Atlantic City lec Co. P860 is euthorized to ect on behalf of other utils. PWEIDER, F. M. Public Service Electric & Das Co. of New Jersey. 3/09/22 ip. 03534:160.
- 0130134 Responds to 780418 & 780508 NRC itrs requesting addi info re AR Info will be become part of FBAR in future amend to lic ppl Includes reactor vessel metl properites & maxium inner sil and of liferwelds. ITR.R.L. Public Service Electric & Gas Co. of New Jersey. 8/10/05. 23pp. 94079:274.
- 0170132 Forwards Amend#44 to Lic Appl for subj facil.consisting of 661 financial info as requested by 780419 NRC ltr. 17Tw.R.L. Public Service Electric & Gas Co. of New Jersey. 8/10/11. jp.
- B10170133 Forwards Amend#44 to Lic Appl for subj facil.pertaining to
- general & financial info. MARTIN.T J. Public Service Electric & Ose Co. of New Jersey. 78/10/11. 2pp.
- Bi0170134 Requests eddl financial info for review of subj facil lic appl by 780707.
  PARRIO D. Light Weter Reactors Branch D. 78/04/19. App.
- 810170135 Amend#44 to Lic Appl for subj facil. Contains addl financial info. • Public Estrice Electric & Ges Co. of New Jersey. 78/10/11. 1764pp.
- 0250002 Notice of meeting on 781018 to discuss residual heat enough as it relates to cold shutdown at subj facil. ROMERICK, A. Light Weter Reactors Branch 3. 78/10/12. 2pp.
- 0240149 Responds to requests for edd1 info which will incorporated DEMOTARY Responds to requests for each into which wise into FBAR as amend to appl. Disusses mpt responsible for QA org review, measures taken IAW Reg Guides, LOCA analysis, & hiron qual for equip.

  ITIL.R.L. Public Service Electric & Gas Co. of New Jersey 8/10/20. 82pp.
- Public Bervice Electric & Gas Co. of New Jersey.
- 0200069 Submits responses to remaining NRC requests for addl info ated 780327, 0418, 0302, 0508, 0518, 0907, 0921, 1004 Info is to

- 78:1080034 Summery of 78:018 meeting re residual heat removal sys & its relation to cold shutdown of subj facil. Applicant will demonstrate by oper test that almospheric steam dump valves will shuffly procedure documentation by 78:106 DROMERICA. A Light Water Reactors Branch 3 78/10/23. 4pp. 94398-099
- 78;1270006 Discusses delly staff notes for 78:023 re CELL's intention to replace recirculation inlet nozzle safe ands.failure of Reactor Coolant Pump at PSEG facil & 15,000 gal of water leaking into containment & inventory at Nuc Fuel Syce. 
  - Office of the Executive Director for Operations 78/10/24 ip 94272: 261
- 7811080102 Responds to 781024-25 request for add1 info on elec pur sys re reliability criterie, stebility analysis expected steady-state voitage conditions intentional disconnection of transmission during sys disturbances & reserve definitions.
  MITTLR L. Public Bervice Electric & Gas Co. of New Jerssy.
  78/11/06. 49pp. 94399:088.
- 7811080227 Forwards response to NRC requests for add1 info re Guality Assurance Prog.unich will be incorporated into facil FBAR. HiTL.R.L. Public Bervice Electric & Gas Co. of New Jersey. 78/11/06. 41pp. 94405:308.
- 78:1090084 Forwards util response to NRC request for add1 info re ECCS Analysis Question 3.65 & RNR Sys Question 9.61 Encl info will be Incorp into Salem FSAR in amend to appl. MITTL.R L. Public Service Electric & Qas Co. of New Jersey 78/11/08. BOpp. 94041.293.
- 7811220261 Notlfication of 781119 mesting in Bethesda w/PSEO to discuss OA prog for subj fecil. DROMERICK.A. Light Weter Reactors Branch 3. 78/11/09. Jpp. 94379: 133.
- 78ii290288 Responds to 78ii06 request for info concerning licensee reg performance eval for Region i plants by NRC Provides ORIER, B.H. Region 1. Philadeiphia. Office of the Director. 78/11/09. 9pp.
- 7811200132 Forwards response to request for add1 info re Ovality Assurance Prog. Covers overall approach & ecope-PBEO corporate OA Prog. Mestinghouse Pur Sys Div OA Prog. United Engr & Constructors GA Prog & Operational OA Prog. MITN.R.L. Public Service Electric & Gas Co. of New Jersey 78/11/16. 90pp. 94420:133.
- 7811280125 Forwards Rev#1"Draft Red|ological Effluent Tech 8pec for PHR's" (NUREG-0472) & "Preparation of Rediological Effluent Tech 8pec for Nuc Fur Plents" (NUREG-0133), W/enci ANO: 7811270173 & 7811270180.

  VASSALLD. D. 8. Assistant Director for Light Water Resctors, 78/11/16. 5pp. 94013:025.
- 7811290354 Summary of meeting on 781115 on quality assurance prog for sub; facil. Applicant will change QA prog IAW NRC recommendations. DROMERICK, A. W. Light Water Reactors Branch 3. 78/11/17. 3pp. 94194: 288.
- 78:124014; Forwards responses to NRC questions. Will be incorp in Final Safety Analysis Rept as en emend. MITTL.R.L. Public Bervice Electric & Gas Co. of New Jersey 78/11/20. ip. 94457:007.
- --7811240142 Answers NRC questions 5, 62, 5, 63, 5, 82, 5, 83, 5, 84 & 5, 85 re analyses of main steam lines break within conteinment of unisolated steem in mein steam line & turbine plant.

  # Public Service Electric & Oas Co. of New Jersey. 78/11/50.

  449p. 94457:008.
- 7811240225 Forwards Tables 3a.3b & 3c in support of response to 780418 NRC questions 5.62 & 5.82 assoc w/subj facii. Requests that subsitted info be withheld form pub disclosure pursuant to 10CFR2.790.

  MITTL.R.L. Public Service Electric & Cas Co. of New Jersey. 78/11/20. 2pp. 94458:176.
- 7812070156 Notice of seminer on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants. Requests advance submission of seminer specific questions. Wenci Seminar info Sheet Proposed Agends & maps. ORIER, B. H. Region I. Philadelphia, Office of the Director.

- 7812120039 Forwards request for add1 info for review of facil FBAR. PARR.O D. Light Water Reactors Branch 3. 78/11/30. 13pp. 94278:079.
- 7812130367 Requests add1 info re facil initial test prog to complete review of FBAR.
  PARR.O.D. Light Water Reactors Brench 3. 78/12/05. 4pp. 94307:107
- 7812120370 Requests commente by 781218 on Tech Spece. Areas incl:pur distrib limit & curves reactor trip & ESF setpoints. Post Accident Instru. Overpressure Protac Sys. ECCB prassures & flows. Elec Equip test & Protec Device tables.
  PARR. G. D. Light Water Reactors Branch 3. 78/12/06. 1p. 94292: 123.
- 7812180260 Forwards request for eddl info on instru & control for review of FBAR.
  PARR.O.D. Light Water Reactors Brench 3. 78/12/06. Spp. 94365: 322.
- 7812190175 Notice of 781215 meeting to discuss open items to subj fecil.
  DROMERICK, A. W. Light Water Reactors Brench 3. 78/19/07. 2pp. 44740.082
- 78/12/20072 Forwards responses to NRC requests for addi info %1.48.5, %6, 5.110 % 14.28 for FBAR review.Responses cover salamic catagorius, safety releted plant dasign & singr asfety factures.

  MITTL.R.L. Public Service Electric & Qas Co. of New Jerasy. 78/12/10. 10pp. 94413:246.
- 7812220143 Forwards reaponss to request for add1 info which will be incorp into FDAR in an amend to appl. Bub; incl:floor response spectra. Class 1 alec equip & instrumentation, & setamic qual for safety-releted equip.

  HITTL. R.L. Public Bervice Electric & Cas Co. of New Jersay.

  78/12/21. 23pp. 03506.001.
- F. Becurity, medical, emergency & fire protection plens
- 78:10280083 Forwards Emergency Pien & amends to Finel Bafety Analysia Rept in response NRC request for edd! info. The info will be incorporated in sub. Facil FBAR in an amend to eppl. MiTU-R.L. Public Barvice Electric & Ges Co. of Naw Jarsey, 78/10/24. 106pp. 94370:160.
- 7811300022 Forwards findings of staff review of subj facil 780803 sacurity plan. Encist fists areas NRC considers unresolved, w/held from pub disciosure IAM 100FR2. 790. Encist is Review Quidstine re-plant protec from sebotage by insiders. BCHMENCER. A. Operating Reactors Brench 1 (Prs 790625). 78/11/16. 4pp. 94070:337.
- 7812040224 Requests addi info re subj facil Security Plan. Forwards list of Unresolved issues (withheld from disclosure) & Review Quideline 'Protet of Nuc Fuer Planta Against Industrial Babatege by the Insider."

  BCHMENCER. A Operating Receture Branch 1 (Pre 790625). 78/11/16.
- --7812040225 Review Guidelina#23: "Protec of Nuc Per Planta Against Industrial Sabotege by the inelder." Refers to security measures that place controls on access to vital areas. CLARK-R. A. Reactor Safeguarda Licensing Branch (Pre 791030). 78/11/06. 3pp.
- 7812210206 Responds to 781116 request for info on security plan.
  Comments Inci deteiled attudy to determine Tupe I & II vital
  areas is unnecessary & requests response to issues reised in
  KMC itr re "insider" control procedures.
  LIBRIZZI,F. P. Public Barvice Electric & Gas Co, of Naw Jerssy,
  78/12/14. 2pp. 94279:096.
- --7812210210 Appraises Reactor safeguards Licensing Branch Review Guideline823. "Protec of Nuc Per Plants Against Industrial Sebotage by the Insider" re compertmentalization, two-men rules, personnal reliability.

  MCEMEN, J. R. KMC, Inc. 78/11/28. 5pp. 94279:098.
- 7812290027 Forwards request for add1 info refacil Fire Protec Prog for FBAR raviaw.w/anc1 questionnaire. PARR.O.D. Light Weter Reactors Branch 3. 78/12/15, 20pp. 94208:020.

# J. Insurance & indemnity information

94044: 130.

- 7811070159 Forwards G certified copies of captioned endorsement for ray of 1978 premium. Advanced premiums & stendard premium endorsement encl.

  HARILEY T. F. Nuclear Insurance Consultants. 78/11/02, 20d.
- 7812040223 Porwards insurance Endorsement #24 to MAELU Policy #MF90 for rev of 1978 premium.
  HARTLEV.T.F. Nuclear Insurance Consultants. 78/11/28. 2pp.
- R. Utility Final Sefety Analysis Report (FBAR) & amenda
- 7810140040 Forwards request for add1 info for ray of subj fac11 F8AR. PARR.O.D. Light Water Reschors Branch 3. 78/10/06. 6pp. 94389:803.
- 78ii030ii9 Forwerds responses to NRC request for addi info re:component coolent weter supply to reector coolent pumperrev response re containment negative pressure. & rav FBAR pages re Radist Monitoring Bys & mod to conteinment struc integrity tast.
  MITDLR.L. Public Bervice Electric & Ges Co. of New Jersey, 78/11/01. ip. 02723:140.
- --7811030120 Gusations & Answers for FBAR Amend 43 re:containment repative pressure & component cooling sys. Public Bervice Electric & Que Co. of New Jarsay. 78/11/01. R2pp. 02723:141.
- --78:1030124 Ray peges for Amand#43 to FBAR for subjfecil re:Rediat Monitoring Bys & Containment struc integrity test.

   Public Bervice Electric & Gey Co. of Naw Jarsay. 78/11/01. 26pp.
- P. Operating license stage documents & correspondence
- 781023009B Summary of 781004 meeting re the environ qual of sefety related instrumentation tellar equip.
  DROMERICK.A.W. Light Water Reactors Branch 3. 78/10/12. 3pp.
- 7819280045 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants, info submitted must be substantisted by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. 9. Diffice of Inspection & Enforcement, Diffice of the Director. 78/18/06. Pp. 94193:220.
- G. Inspection reports, IE Bullatine & correspondence
- 7810280048 Forwards IE Inspec Rept#80-311/78-29 on 780822-24 during which no items of noncompliance ware noted. BRUNNER, E. J. Region 1, Philadalphia, Reactor Operations Nuclear Bupgort Branch. 78/09/11. 2pp.
- --TBICE50052 IE Inspec Rapt#50-311/78-29 on 780822-24 during which no items of noncompliance were noted Major areas inspected included: Containment lask rate testing, pips support & restraint aux & presvc tasting.

  CAPHTON, D. L., HIGOING, J. C. Ragion 1, Philadalphia, Reactor Operations Nuclear Support Branch, 78/09/11, 70p.
- 7810270284 Forwards IE Inspec Rept#50-311/78-28 on 780821-24 during which no items of noncompliance were noted. CARLSON R. T. Region 1, Philadelphia: Reactor Construction Engineering Support Branch. 78/09/12, 2pp. 94025:331.
- --7810270288 IE Inspec Rapt#80-311/78-28.on 780821-24 during which no items of noncompliance were noted. Hajor areas inspected included; elec cable installation, termination & documentation diesel generator installation & records.

  FINKEL.A.E., EBNETER,B.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/07. App. 94025-333.
- 7511080R90 Forwards IX Inspac Rept#80-311/78-30 on 780828-31 during which no items of noncompilance were noted. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/19, 2pp. 94406:203.

- --7811080292 IE Inspec Rept#50-311/78-30 on 780828-31 during which no items of noncompliance were noted. Major areas inspec incl: overall preoper test prop. e preparations for Integrated Hot Functional Yest Procedure.
  NCHOLAB.H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/15. opp. 94406:205.
- 7811100099 Forwards IE Inspec Rept#80-311/78-32 on 780913-18 during which no items of noncompliance were noted.

  BRUNCE, E. J. Region 1, Philadelphia, Resctor Operations Nuclear Support Branch. 78/09/26. 2pp. 94179:291.
- --7811100102 IE Inspac Rept#50-311/78-32 on 780913-15 during which no itses of nonceapliance were noted. Hejor areas inspected included: prepar test prog. interpated but functional test prog. I followup of previous open items.
  NICMCAB.M. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/26. 7pp. 94179:293.
- 7811100157 Forwards 1E Imagec Rept#50-311/78-34 on 780920-22 during which no items of noncompliance were noted. BRUNNER,E. J. Region 1, Philadsiphia, Reactor Operations Nuclear Support Branch. 78/10/02. 2pp. 94047.192.
- ---7811100164 IE Inspec Rept#50-311778-34 on 780920-32 during which no items of noncompliance ware noted. Major drama inspec incl; integrated hot functional test prog status, preoper test prog status, preoper test procedures for review plant tour. NICKCAS.H. Region i, Fhiladeiphia. Office of the Director. 78/09/29. 1p. 94047:194.
- 7811140037 Forwards 1E Inspec Rept#50-311/78-36 on 780927-28 during which no items of noncompilancs were noted. SRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94420:305.
- -- 7811140043 IE inepsc Rept#50-311/78-34 on 7809R7-28 during which no item of noncompliance were noted. Hajor areas inspected included integrated hot functional test prog status-failumup on previously unresolved liems & control room tour.
  NICHOLAB, M., MCNATI, T., CAPHION, D. L. Region i, Philadelphia, Office of the Director. 78/10/04. 7pp. 944R0:307.
- 78:11:00:142 Forwards 1E Inspec Rept#50-3:11/78-33 on 780920-92 during which no itams of noncompliance were noted. BRUNEERE J. Region 1: Philadelphia. Reactor Operations Nuclsar Support Branch. 78/10/05. Spp. 94047:148.
- --7811100148 1E Inspec Rapt#50-311/78-33 on 780920-22 during which no lives of noncompliance were noted. Major areas inepected included; matl storage, test & measurement equip control, conduct of GA audits & surveiliances.

  BECKMAN, D., NAPUDA, Q., MARKONSKI, R. Region 1, Philadelphia, Office of the Director. 78/10/05. 10pp. 94047:150.
- 7811170295 Forwards IE Inspec Rept#50-311/78-31 on 780911-15 during which no Items of noncompliance were noted. CARLEBORR T. Region 1, Philedelphia. Reactor Construction & Engineering Support Branch, 78/10/06. Spp. 02766: RI3.
- --7811170299 IE Inspec Rept#50-311/78-31 on 780911-15 during which no items of nencompliance were noted. Major areas inspected included: structural integrity, piping. & cable installation & quality varification records.

  TOTH:A.O., DURR.J.P., PAOLINA,R.J. Region i. Philadsiphia. Reactor Construction & Engineering Support Branch. 78/10/06. 14pp.

  02746:215.
- 7811300295 Forwards 1E Inspec Repts#50-272/78-23,50-311/78-27 on 780612-0916 during which no items of noncompliance ware noted.

  BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Brench. 78/10/10. 2pp. 94075:149.
- --7811300298 IE Inspec Reptem50-272/78-23,#80-311/78-27 on 780812-0916 during which no items of noncompliance were noted Major areas inspected inclinatine Inspec of oper & construction, NORRHOLM.L.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/10. 13pp. 94075:151.
- 7812040353 Forwards IE Inspec Rept#50-311/78-38 on 781010-12 during which no items of noncompliance were noted. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/25. Spp. 94382:279.
- --7812060355 IE Inspec Rept#50-311/78-38 on 781010-12 during which no items of noncompliance were noted. Major areas inspected inclipreoper test prog implementation & integrated hot functional test prog status.
  NICHOLAS: M. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/85. 7pp. 74382:281.

- 7811130115 Ack receipt of 780928 ltr in response to 780906 & 78061P NRC ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#50-272/78-18 & 50-311/78-13.

  GRIER. B. H. Region 1, Philadelphia, Office of the Director.
  78/10/30. ip. 94076:090
- --7811130119 Responds to 780906 NRC ltr re deviation noted in Inspec R. #50-2727/8-18. UE11 claims alleged violation was not & 410 not represent noncomplyance w/10CrR50. 99 since subteired procedures are controlled by GA Prog to comply u/FBAR BCNEIDER.W.F. Public Service Electric & Ges Co. of New Jersey. 78/09/29. 2pp. 94076:091.
- 78;2010345 Forwards licenses performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormed or unusual earety concern. GRIER, 8. H. Region 1, Philadelphia, Office of the Director 78/11/01. 4pp. 00002:259.
- 7811140271 Ack receipt of 781018 itr informing NRC of steps taken to correct violations noted during inspects0-211/78-26 CARLBON.R. T. Region 1. Philedeiphia. Reactor Construction & Engineering Support Dranch. 78/11/02.
- --7B11149274 Responds to 7B0912 NRC ltr re violation noted in lineace Rept#80--311/78-26. Corrective ections: pressure testing of welds review of mechanical arrangement drawings & rev of procedures.

  MARTIN.T. J. Public Service Electric & Gas Co. of New Jersey.
  78/10/19. 3pp. 94400:192.
- --7811140277 Forwards IE inspec Rept#80-311/78-26 on 780814-16 & Notic of Violation.
  CARLBON, R. T. Region i. Philedelphia. Reactor Construction & Engineering Support Branch. 78/09/12. 2pp. 94400:195.
- --7811140278 Notice of Violation from inspec on 780814-18 CARLBON, R. T. Region i. Philadelphia. Office of the Director. 78/09/12. ip. 94400:197.
  - --7811140280 IE Inspec Rept#50-311/78-26 on 780814-19 during which I i of noncompliance wee noted: feiture to provide Q: I length ratio on socket weld.

    TUTH.A.D. Region I, Philadelphia, Office of the Director.
    FABAND.A.N., MCREARTY.R.A. Region I, Philadelphia, Resctor Construction & Engineering Support Branch. 78/09/12. 13pp. 74400: 198.
- 78:1290222 Forwards 1E Circular 878-18, "UL Fire Test, "M/encl AND: 781:180002.

  GRIER: 8.H. Region i, Philadelphia, Diffice of the Director. 78/11/06. 1p. 94237;304.
- 7812270417 Forwards IE Inspet Repts850-311/78-35 & 50-272/78-25 on 780917-1014 during which no items of noncompliance were noted.

  BRUNNER.E. J. Region 1. Philadsiphie. Reactor Operations Nuclear Support Branch. 78/11/13. App. 94312:308.
- --7812270423 IK Inspec Repts#50-278/78-25 & 50-311/78-35 on 780917-101 during which no items of noncompilance were noted. Major areas inspected inci: test prog controls, ing & record review. Emergency Drill, prepper plent personnel training. NORRHOLM.L.J., KEIMIO,R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/05. 15pp. 94212:310.
- 7819280007 Forwards IS Inspac Rept#50-979/78-25 t #50-311/78-35 on 780917-1014 during which no litems of noncompliance were noted.

  8RUNNER.S.J. Region 1, Philadelphia, Resctor Operations Nuclear Support Branch. 78/11/13. 2pp. 94130:149.
- --7812280012 IE Inspec Repts#80-279/78-25 & #50-311/78-35 on 780917-10 during which no itsms of noncompliance were noted. Major areas inspected incl: tours of facil, log & record raviews, observation of emergency drill & review of recent LERB. NORRHOLH, L. J., KEINIQ.R.R. Region 1. Philadalphia: Reactor Operations Nuclear Support Branch. 78/11/06. 15pp. 94130: 151.
- 7812290042 Forwards IE Inspec Rept#80-311/78-37 on 781025-37 during which no Items of noncompilance were noted.
  BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/11/13. 2pp. 94189:349.
- --7812270044 IE Inspec Rept#50-311/78-37 on 781025-27 during which no items of noncompliance ware noted. Major areas inspected inclicoverall prespec test prog. followup on unresolved items & plant tour.
  NICHOLAS.M., CAPHION.D.L. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/13. Opp. 94189:331.

- 7812150042 Forwards IE Builetin#78-12A, suppl to IE Builetin 78-12 W/amcl ANO 7811300035.

  GREER, B. H. Region i. Philadelphia. Office of the Director 78/11/24. p. 94210: 225.
- 7812280210 Ack receipt of 781109 ltr informing NRC of steps teken to correct violations mated during Inspects00-311/78-26 CARLBON.R.T. Region i. Philadelphia, Reactor Construction & Engineering Support Branch. 78/12/00. ip. 94373:190.
- --7812280215 Provides add1 infa re violations noted in Inspec Rept#50-3|1/70-26 Corrective actions: 75 welds properly reworked & accepted & 3 welds will be properly reworked prior to Core Lood. MARTIN.T J. Public Service Electric & Qas Co. of New Jersey. 78/11/09 2pp. 94373:191
- R. Periodic operating reports & related correspondence
- 7810180120 Forwards Hastewater freetment Rept for Sept 1978 for sewage treatment plant at subj facil MIDURA.H.J Public Bervice Electric & Oas Co. of New Jersey. 78/10/10, 2pp. 94190: 296.
- 7810100144 Forwards Discharging Monitoring Repts for Subj facil for Espt 1978. MIDURAH, J. Public Service Electric & Gas Co. of New Jersey. 78/10/10. 17pp. 94316:328
- 7811210323 Forwards Hastewetsr Treatment Rept for Oct 1978. MIDURA-H, J. Public Bervice Elsctric & Ges Co. of New Jersey. 70/11/10, 2pp. 94485:267.
- 78:112:10343 Forwards Olscharge Monitoring Repts for Oct 1978. MIDURA:H. J. Public Bervice Electric & Oas Co. of New Jersey. 78/11/17. 10pp. 94484:342.
- DOCKET 90-312 RANGIO BECO NUCLEAR GENERATING STATION

  F. Security, medical, energency & fire protection plans
- 7810230099 Bubmits design details for two items identified by NRC as requiring approval tone item where util proposes mod differing from one described in fire protection safety evaluation in response to request for additinfo, MATIMOS, J. J. Bacramento Municipal Utility District. 78/10/17. 5pp. 94052:212.
- 7812010344 Forwards Amend 24 to License DPR-54, sefety evaluation, & notice of issuance & availability.
  REID.R.H. Operating Reactors Dranch 4 (Pre 790625). 78/11/14. 2pp. 94410:227
- --7012010397 Amend 24 to License DPR-54, revising edministrative controls portion of Tach Opecs in response to 780221 application. Reflects revised facility organization structure & clarified raview requirements for security & emergency plans. REID-R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/14. 19pp. 94418:229.
- --7812010398 Befsty evoluation supporting Amend 24 to License DPR-54 concluding that proposed changes in plent arg see admin in nature 8 preserve intent of Tech Space. Mods to Security & Emergency Plans are also ecceptable.

  \*\* Office of Nuclear Reactor Regulation, Director. 78/11/14. 4pp. 94418: 240.
- --78:2010362 Notice of issuance & availability of Amend 24 to License DRR-54.
  REID:R.W. Operating Reactors Branch 4 (Pra 790688). 78/11/14.
  Rpp. 94416:252.
- 7812050146 Application for Amend 61 to License DPR-54-reflecting changes to Table 3.1 of fire protection safety evaluation. MATTIMOS, J. J. Sacramento Hunicipal Utility District. 78/12/01. 3pp. 94298:359.
- 7012180159 Proposes elternate mod of Paragraphs 3.1.34(2) & 5.17.6(2) of fire protection SER attached to Amend 19 of License DPR-94, Mould relocate transformer 250 ft seet of current location.

  MATTIMOS.J.J. Secremento Municipal Utility District. 78/12/12. 1p. 94366.020.

- 7812270116 Approves supplemental info re Section 3 of fire protection EER.including installation of thormal insulation on Channel A.C.& D conduits, and of lube oil pump control circuits associated w/HP18 & procedures for dissel generators. REID.R.W. Operating Reactors Dranch 4 (Pre 790825). 78/12/14 5pp. 74161:064.
- 7811210261 Forwards Amend#4 to Mod Amend security plan for subj facil.
  Requests withholding from pub disclosure (ref 10CFR2.790).
  M/out encl.
  MATTIMOE.J.J. Secremento Municipal Utility District. 78/11/17. ip.
  944881-854

#### O. Adjudicatory correspondence

- 7812140142 Forwards for approval of simination of add1 insp of 1TT Orinnel units per 781130 ltr. Fee peid under protest per lawsuit filed in U.B. Court of Appeal for 5th Circuit. HATTIMOS, J. J. Bacramento Municipal Utility District. 78/12/06. App. 94478:346.
- P. Operating license stage documents & correspondence
- 7811020084 Forwards Amend#23 to Facil Oper Lic#DPR-54.changing Tech Spec for pient surveillance times. REID.R.M. Operating Reactors Branch 4 (Pra 790625) 78/10/01 299 94331:027.
- --7811020087 Amend#23 to Fecil Open LicMDPR-54, changing Teth Spec for plant surveillance times. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/03. 7pp. 94051:029
- --7811020093 Befety Evaluation Supporting Amend#23 to Facil of Lic #DRR-54. Concludes that no increase or hazard will ensue. \*\* Operating Reactors Branch & (Pre 790625). 78/10/03. 3pp. 94351:036
- --7811020098 Notice of issuance & availability of Amend 23 to License DPR-64.
  REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/03.
  2pp. 94051:039.
- 7810120027 Presents into re proposed and to assure high pressure injection flow to reactor core following a small break as requested by NRC 780726 ltr.
  MATIMOG. J. J. Bacamento Municipal Utility Dietrict. 78/10/09. 20p. 94470:346.
- 7810230160 Forwards check for \$12.300 in payment for application for Amend 60 to License DPR-54. MATHIMOS, J. J. Sacramento Municipal Utility District. 78/10/13. 2pp. 94164:258.
- 7B11070201 Notifies that util cannot obtain NRC approval perform celculations & purchase new aguipment for installation of second level of voltage protection by 1978 refusiling outage. Proposes and completion by end of 1979-80 refusiling outage. MATTIMOE. J. J. Secramento Municipal Utility District. 7B/10/31. 1p. 94039:083
- 7811200404 Notifies that mode proposed in 780927 ltr.enhancing capebility to detect reactor coalant leekaga in reactor bidg shrough radiation monitor use, acceptable in concept. Mode to be functionally acceptable, upon approval of equipment. REID, R. W. Operating Reactors Branch 4 (Pre 790623). 78/11/04. 2pp. 94419-316
- 781120346 Responds to 780913 request to emend Tech Specs to psralt operation w/fuel loading plenned for Cycle 3. Forwards request for additing. Reply required by 781117.

  REID.R.H. Operating Reactore Branch 4 (Pre 790623). 78/11/07. 999. 94420:108.
- 7Bili7Gil7 Responds to NRC 7BG921 rejection of design criteria for instellation of ionization detectors in areas containing both combustibles & equipment/cables required for safe shuldown Requests approval of schedule to make related mode. MATTIMES.J. Becramento Municipal Utility District. 7B/11/14. Epp. 94047:146.

109 Insiste out; facil ECCS is acceptable & in conformance w/ 10 46 but in response to staff request util applies for tion to 10CFR30,46 & for lic to oper et 2772 MHt for on of Cycle 3. Hill provide datails of mod. രം. പ Sacramento Municipal Utility District. 78/11/22. 94013: 278

02 Discusses possible dangers of LOCA in containment purging normal plant uper. Requests either commitment to limit or or justification for continuing.

LM. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp. 2:062.

16 Discusses failures of Bargen-Paterson anubbers during 1978 -r test program. W/54 tested 10 failed in sema mode: or test program myor terterity railing in sema pad spring damaging sent aurfaces. Engineer lesizes that failures due to abusive handling IDE.J. J. - Secramento Municipal Utility Distri Secramento Municipal Utility District. 78/11/30. 94333: 284.

94 Forwards eddl info re mods eliminating requirement for oction subsequent to small breek per 781122 raquest seption from 100FR30.46, supplementing 781122 info tel.

10E. J. J. Secremento Municipal Utility District. 78/12/04. 94109:001.

07 Notifies that fae for review of util 781130 ltr to NRC | 781206 to ensure that NRC concurrance not to insp | 17-0rinne]|-manufacturad enubbars will be issued by | .Request for concurrence determined to by Category II. | | 1805-J. J. | | Bacremento Municipal Utility District. | 78/12/06. | ip. 1992 1:337.

33 Emphasizas importance of submitting eccurata & complate info 133 Emphasizes importance or summitting economic a compa-ity liceneses & applicants info submitted must be initiated by deta & calculations.Licenese must notify any inaccuracies or enforcement action will result J.O. Office of inspection & Enforcement. Office of the for. 78/12/06. 2pp. 943i1:3i0.

191 Responds to 781130 ltr re hydraulic enubber surveillenca M. Couse of Bergen-Patarson enubber failure dua to dling during installation. L.W. Operating Resctors Br

Operating Reectors Brench 4 (Pre 790525). 78/12/08. App. : 07B.

.39 Proposes to store spai plate in current position for one upl cycle.eliowing eveluation of design permitting is of spel plate rigidly above present location.
1881 probability of rupture of primery cooling loop.
1881 probability of Municipal Utility District. 78/12/14. ip.
1835

ction reports, 15 Bullistins & correspondence

: 335.

P1 Forwards IE Circular#78-17. (800 AND: 7810230221, Docket . 781013).

EN.A.H. Region 5. Ban Frencisco, Office of the Director. 13. lp. 94170:160.

redicactive matt properly labeled & radiat level of rooms Posted. MATTIMOE, J. J. Bacramento Municipal Utility District. 79/11/07. 2pp. 94260.35B.

- --7811270097 Ack receipt of 781107 Itr informing NRC of eteps taken to correct deviations noted in Inspec Rapt#50-312/78-15.
  BOOK-M.E. Region 5. San Francisco. Fuel Facility & Materials Safety Branch. 78/11/17. 1p. 94260: 360.
- 7811270056 Forwards Inspet Rept #50-312/78-17 on 781011. Requests notification if any metl is propriatory.

  BPENCER, Q B Region 5. Ben Francisco. Reactor Construction & Engineering Bupport Branch. 78/10/24. 2pp. 74246.273.
- --7811270058 IE Inspec Rept M50-312/78-17 on 781011: insec inspec meating at which licenses discussed governing codes & specs. perticipating organizations, nature & extent of prog for insvc inspec during Pail 1978 Puel outage.
  VCRDERBRUEGGEN, NARBUT,P.P., MAYNES,R.C. Region 5, Sen Francisco,
  Office of the Director. 78/10/24. 3pp. 94246:275.
- 7811210244 Forwards Summary of IE Inspec Rept#50-312/78-16 on 781016-19 Inspec Rapt & Notice of Violation withhald per 10CFR2, 790. NORDERHAUG, L. R. Region 5. Ban Frencieco, Bafeguerda Branch. 78/11/03. Spp. 94408:010.
- 78:1150012 Forwards IE Circular 78-19. ENGELKEN,R.H Ragion 3, San Francisco, Office of the Director. 78/11/06. ip. 941:1:178.
- 7812140037 Forwards IE Inspec Rept#50-312/78-18 on 761023-25 during which no items of noncompliance were noted. CREWS.J.L. Region 5. Ben Francisco. Reactor Operations Nuclear Support Brench. 78/11/14. 2pp. 94127:215.
- --7812140039 if Inspec Rept 50-312/78-18 on 781023-25 during which no items of noncompliance were noted. Major areas inepected incl: open surveitiance cleenliness, refueling preparetion & IE Bulletin/Circular followup. JOHNSON, A. D. Region 5, San Francisco, Office of the Director.

  WOEBSHER, J. D., FAULKENBERRY, B. Region 5, San Francisco, Reactor
  Operations Nuclear Support Branch. 78/11/14. 5pp. 94126:308.
- 7811300092 Forwards 1E Bulletin #78-12A, suppl to IE Bulletin 78-12. W/ancl AND: 7811300055. ENGELERN, R. H. Region 5. San Francisco, Office of the Director. 78/11/24. ip. 94073:054.
- 7812060202 Ack receipt of 781124 ltr informing NRC of staps teken to correct violetione noted during inspec.

  NORDERHAUG,L.R. Region 5. Ben Francisco: Safequerds Branch.
  78/12/01. ip. 94382:147.
- 7812290094 Forwards IE Bulletin 78-14. ENGELKEN, R. H. Region 5, Ban Francisco, Office of the Director. 78/12/19. 1p. 03669:361.
- R. Periodic operating reports & related correspondence
- 7810110126 Monthly Oper Rept for Bept 1978. COLOMBO, R. M. Bacramento Municipal Utility District. 78/10/03. 6pp. 94067: 352.

u

- RODRIGUEZ, R. J. Bacramento Municipal Utility District. 78/11/07, 1p. 94133:165
- --7811160078 Monthly Oper Rept for Oct 1978. CO.0H90.R.W. Secramento Municipal Utility District. 78/10/31. 7pp 94133.166
- 7812200194 Forwards Hontbly Open Rept for Nov 1978 RODRIOUEZ: R.J. Sacramento Hunicipal Utility District. 78/12/12. 1p. 94162-242
- --7812200197 Monthly Open Rept For Nov 1978. COLOMBD, R. M. Sacramento Municipal Utility District. 78/11/30. Opp 94162:243.
- B. Reportable occurrences. LERs & related correspondence
- 7810100050 Forwarde LER 78-006/03L-0. MATTHMES.J.J. Barramento Hunicipal Utility District. 78/07/05. 2pp. 94032:173
- ~-7810100056 LER 70-006/03L-0. on 780611 during normal operation, increased leakage noticed, between 1.1-1.7 gallone/min Caused by leaking pressure sefect valves & block valve on slactromatic relief valve Valves replaced or resurked.

  CILOMDO.R W. Sacremento Municipal Utility District. 78/07/05.
  19. 94032:175
- 7810100073 Forwards LERH7B-003/03L~1.
  MATTIMOE, J. J. Bacramento Municipal Utility District. 78/07/17.
  2pp. 94033 075.
- --7010:00077 LERM78-003/03L-1 on 7807:0: Maintenance on safety sys hydraulic snubber previously found to have low fluid accumulator level revealed 2 dateriorated orrings made w polyurathene seals instead of ethylene-propulene seals. CCLOMBO.R W Bacramento Municipal Utility District. 78/07/10. 1p. 94033:077.
- 7810100016 Forwards LER 78-004/017, MATTIMOE.J. J. Sacramento Municipal Utility District. 78/07/20. 1p. 94003:016
- --7830100021 LER 78-004/01T-i: on 780414, small break analysis determined to be at RC pump discharge. Analysis identified & evaluated solutions. Facility has incorporated procedural changes & initiated design changes. CQL0M20. R.W. Bacramento Municipal Utility District. 78/07/20. 1p. 94033:017.
- 7810100061 Forwards LERM78-008/02T-0. MATTIMES, J. Secremento Municipal Utility District. 78/08/15. 2pp. 94033:088
- --7810100069 LER 78-00B/02T-0: on 780B04, analysis showed atypical weld filler wire w/high silicon k low nickel contents in archive weldments. Wire mixed by euppliar w/enipment of Mn-Mo-Ni filler wire. Caused by inadequate GA. CQLOMBO. R.M. Bacramento Municipal Utility District. 78/0B/15. ip. 94033: 090.
- 7810250184 Reportable Occurance#78-10: Tach Spst 3, 14, 5, 2 on 780914 rsq inoperable fire hose stations to have add1 operable hose w/in I hour not satisfied w/in time rsq.
  AUBRG.R.P. Bacramento Hunicipal Utility District. 78/09/22 1p. 94392: 249.
- 7811030149 Forwards LER878-010/017-0.
  MATTIMOR.J. J. Sacramento Hunicipal Utility District. 78/09/28. ip.
  02723:351.
- --781i030152 LERW7B-0i0/017-0 on 7807i4: During normal oper 1t was found that Fire Hydrantia hose cabinet had not been relocated W/hydrant. Upon discovery of discrepancy hose cabinet was relocated.

  GCL0/80. R.W. Bacramento Hunicipal Utility District. 78/09/2b. ip. 02723:352.
- 7811030153 Forwards LER#78-011/017-0.

  MATTIMEE.J. J. Bacremento Municipal Utility District. 78/09/27. ip. 05037:295.

- 7810130131 Forwards LER 78-013/03L-0.
  MATTIMDE.J. J. Sacramento Municipal Utility District. 78/10/05
  2pp. 94003:032
- --7810130135 LER 78-013/03L-0:on 780925.HP1 Loop A flow transmitter FT-23007 found inoperable during surveillance procedure 200.14 Caused by broken ballows in flow transmitter. Failed bellows replaced. COLOMBQ, R.W. Bacramento Municipal Utility District. 78/10/05. 1p. 94003:054.
- 7810130178 Forwards LER 78-009/03L-0.
  MATTIMOE.J. J. Bacramento Municipal Utility District. 78/10/03.
  2pp. 94415:102
- 7810170199 Forwards LERW78-012/03L-0.
  MATTHOE.J. J. Becamento Municipal Utility District. 78/10/05.
  2pp. 94053:024
- --781017020; LER 78-012/03L-0: on 780927, header failed to discharge during routine testing of CO2 sys. Caused by defective micro switch on a solenoid which operates a pliot valve integral w/controller of main isolation valve.FV 99809.
  CCLOMBO. R. W. Bacramento Municipal Utility District. 78/10/05, 19. 94236:336.
- 7810200104 Forwards LERM78-003/04T-0. MATTHMOG. J. Bacramento Municipal Utility District. 78/10/16. 2pp 94195:224.
- ---7810200106 LER 78-003/04T-0:on 780913 during steady state operation dissolved oxygen concentration downstream of confluence of Hadselville & Clay Creek was less than minimum of 5mg/liter typical of stagnant water. Location is beyond util property. CCL.0H80. R. W. Bacramento Hunicipal Utility District. 78/10/16. ip 94195:826.
- 7810230277 Forwards LER 78-014/017-0 MATTHODE, J.J. Bacramento Municipal Utility District. 78/10/17, 2pp. 94166:358.
- --- TBIQGOODED LER 78-014/DJT-0 on 78J004: during oper w/8 diess] generator out of succuse of A generator temporarily lost. Reactor Shutdown commenced until dissel generator oper. Shutdown stopped spray of fuel oil Packing gland tightened. CCLOMD.R.W. Sacramento Municipal Utility District. 78/10/17. ip 94166.175.
- 7810310087 RQ-18-16. on 781024. while B generator was out of evc for maint. Voltage regulator circuit for A generator maifunction occurred b shut down A generator. Cold shutdown of reactor commenced. A generator raturned to evc. Full rept to follow. OUREC.R.P. Sacramento Hunicipal Utility District. 78/10/25. Ip. 74071:165.
- 7811140230 Forwards LER 78-016/017-0.
  MATTIMOE.J.J. Becramento Municipal Utility District. 78/11/06
  2pp. 94400:087.
- --7811140274 LER 78-016/01T-0: on 781024, operability of A dissal generator lost due to failure of primary fuses on the voltage regulator's control power circuit. Fuses replaced: A generator tested than returned to svc. CLOMBO, R.W. Bacramanto Municipal Utility District. 78/11/06. 1p. 94400: 089.
- 7812120147 RO: on 781023, welder entered filter room to remove three inlet & outlet lines w/oryacstylene cutting torch During process, welder oversappead when head, arms & upper torso extended bayond protective shield to obtain batter position. MATTIMOS. J. J. Sacremento Huniclpal Utility District. 78/11/13. Spp. 74276:271
- 7812110170 Forwirds LER 78-015/017-0.
  MATTINGE.J. J. Bacramanto Municipal Utility District. 78/12/04.
  Rpp. 94337:091
- ~~7B12110173 LER 7B-015/017-0:on 7B1120, failure of 9 Bargan-Patterson snubbers. Baven of 9 failures caused by abusive handling during reinstallation following 1977 testing. Other two failures isolated cases. Failed units repaired. CLQMBO.R.W. Bacramento Municipal Utility District. 7B/12/04 2pp. 94037:093.

- DOCKET 50-313 ARKANBAB NUCLEAR DNE. UNIT 1 F. Beturity, medical, emergancy & fire protection plans
- 7810700099 Discusses facility emergency plan Amends 54.55 & 56 subsitted on 780426 & 0630. Annual emergency drills, communications links & Pire brigade drills amended. Changes acceptable & meet NRC 771205 position REID.R.H. Operating Resoctors Branch 4 (Pre 790625) 78/10/02 2pp. 94367:351.
- 7811170065 Forwards coples#1.2.3.4 & 5 of 781030 amend to proposed industrial Security Piem 4td 780510.which responds to 780428 NRC itm Requests withholding of document from public disclosure pursuant to 2.770 WILLIAMS. D. H Arkansas Power & Light Co. 78/10/30 2pp. 94046 322.
- 7811090170 Forwards Amend#37 to facil Emergency Plantrav pages for intertion into FBAR). WILLIAMS D. H. Arkenses Power & Light Co. 78/11/06. 19pp 94039.154
- J insurance & indomnity information
- 7810230200 Forwards Endorsements #30.31.32.33.34 to Liability Policy eNF-210 & Endorsaments #25, 26, 27, 28, 29, 30 to Liability
  Policy &MF-74.as requested in 780922 NRC ltr
  WILLIAMS.D.H Arkansas Power & Light Co. 78/10/11. 13pp. 94164: 087
- K. Utility Final Bafety Analysis Report (FBAR) & amands
- 7812280125 Forwards annotated ray pages for AND-1 FBAR re possession & use of Krypton 83 source according current limits of OL-suppressing previous 760816 ray pages. MILLIAMS.D.H. Arkansas Power & Light Co. 78/12/06. 7pp. 94310: 255.
- P. Operating license stage documents & correspondence
- 7810100081 Forwards proposed changes to Tach Spece & Environ Tach Spece Listing new job titles & organizational duties.

  CAVANAWHAW Arkaness Power & Light Co. 78/09/22. Spp. 94032:192.
- 7810230271 Forwards Amand 36 to License DPR-51, safety svaluation & notics of issuance & evailability. REIDR.W. Operating Reactors Branch & (Pre 790525). 78/10/05. Spp. 94187:123
- --7810030273 Amend 36 to License DPR-51, changing Tech Space to parmit headling of 25 ton shielded shipping cask on one-time basis to remove & ship irradiated B4C test rods stored in facility full storage pool. REID-R. H. Operating Reactors Branch 4 (Pre 790625). 78/10/05. 4pp. 94167: 126.
- -7810230279 Safety evaluation supporting Amend 36 to License DPR-51. . Office of Nuclear Reactor Regulation, Director. 78/10/05. App. 94167, 130.
- -7810230281 Notice of Issuence of Amend 36 to License DPR-31. REID.R.H. Dparating Reactors Branch 4 (Pre 790625). 78/10/05 2pp. 94167:134.
- 7810240001 Raylaw of appl for Oper Lic. Documents efforts by city of faragould. An, to participate  $\omega/2X$  interest in AP & L planmed facile, w/encl supporting correspondence. HAMILTON,D.B. Cathey, Goodwin & Hamilton, 78/10/12. I3pp.
- /810240098 Supplaments info in 780922 request for proposed changes to Tech Space & Environ Tach Spaces to implement proposed reorganization of plant staff. Describes functions of major positions established by reorganization.
  HILLIAMS, D. H. Artaness Power & Light Co. 78/10/17. 4pp.
- '810250098 In response to 780428 NRC ltr.enalysis of ECCS small break was discussed in ltrs from J.H. Taylor (B&H) to S. A. Varga dtd 780718 & 780811. WILLIAMS, D. H. Arkanses Power & Light Co. 78/10/17. 1p.
- 911010363 Responds to util 770617,0705 & 1206 proposed Tech Specs 3.3 & 4.1 for reactor bldg spray sys. Changes accaptable provided sedium hydroxide contentration is 18% weight & computer simulator data verified within 21 days.

  REID.R.W. Depreting Reactors Branch 4 (Pre 770625). 78/10/17. 3pp. 94396.299.

- 7610260076 Advise; that 780719 application to amend OL considered G1 4 action & remaining fee balance should be submmitted MILLER.W.O. License Fee Management Branch. 78/10/19 1p 94392.313
- 7811060075 Documents verbal commitment between author & O Vissing ma 781024 re Sequencing Elec Loads on Start Up Transformer "Milistone Mods" still under review er schad for implamentation 790301 6 oversize drawings aveilabl in CF. HILLIAMS, D.H. Arkansas Power & Light Co. 78/10/25. Bpp 94423 360
- 7Bi102009: Reviews Sub, Facil SER on voltage degradation at Class 1E 480-volt buses Such dagradation could jappardize some fuses in ECCS control circuits Licensee mod is acceptable. LAINAS. 0 Plant Systems Branch (Pre 791030) 94351.066 78/10/27. 1p.
- --7811020096 SER ra potentially serious degradation of off-site pur Bys Mod usuid change loads from being block started to being sequentially started Concludes that nod is acceptable LAINAS.O. Plant Systems Branch (Pre 791030) 78/10/27 94351 067
- 78i1030106 Bupplements 78i025 ltr re Sequencing Eisc Loads on Startu Transformst Hill raq 5 calendar days to implement mod after NRC approval Tast of completed sys will req only simple wiring changes. WILLIAMS.D.H. Arkansas Power & Light Co. 78/10/27. 1p. 02723 3.
- 7811030139 Forwards proposed mod to high pressure injection sys Mod meats staff position expressed in NRC 780916 ltr because no oper action util req & it is consistent w/all assumptions of 781017 ECCs 8mall Breaks Analysis
  HILLIAMS, D. H. Arkansas Power & Light Co. 78/10/27 3pp.
- 7811080136 Responds to NRC concerns re sequencing siec loads on startransformer to alleviata possible undervoltage situation Proposad mode uili be implemented by 781031. WILLIAMS.D.H. Arkeness Power & Light Co. 78/10/27. 2pp.

02724: 004

- 7811130284 Requests registration as user of Cham-Nuc Bys#CNB1 14-195 shipping cash. WILLIAMB.O.H. Arkansas Power & Light Co. 78/10/27. ip 94011.2
- 78iii50032 Notice of mod to Licenca DPR-51 to alleviate undervoltage condition which would be created in startup transformers which would in turn provide degraded voltage.

  BTELLO, V Division of Operating Reactors. 78/10/27. App. 94112:171.
- 78ii130190 Request raview of enti description of Phase 3 installatio for cooling battery/charger rooms Submittal completes followup action re RD 30-313/77-19. Forwards oversite drawings M/o drawings.
  HILLIAMS. D.H. Arkenses Pawer & Light Co. 78/10/31. 3pp. 00390-103 03550: 333
- 7811160062 Forwards proposed change supporting Topical Rept Tach Spers parameter changes nacessary for cycle 4 open Datermines change to be Class 4 amend & encloses fee. Requests approved by Mar 1979
  CAVAMAUGH. M. Arkenses Power & Light Co. 78/11/09. 24pp. 94132: 288
- --7811160064 "Cycle 4 Reload Report." \* Arkanese Power & Light Co. BAW-1504, 78/10/31. 54pp. 74132-312
- 7811160129 Responds to 781019 NRC itr requesting \$8,300 to allow use NAC-1 Cask This figure represents the difference in few determination between util 780017 itr & NRC 780816 ltr. Util contests NRC determination & will not remit difference. WILLIAMB, D. H. Arkansas Power & Light Co. 78/11/09 2pp. 94135: 229.
- 7812010370 Forwards Amend 37 to License DPR-51. Amend 5 to License NPF-6-sefety evaluation & notice of issuance & evaluability. REID.R.W. Operating Reactors Branch 4 (Prs 790625). STOLZ.J.F. Light Water Reactors Branch 1. 78/11/13 2pp. 94409:061.
- --7812010374 Amend 37 to Licensa DPR-51, changing Tech Specs dealing administrative controls, plant organization & revising ETS to make them current w/Unit 2.
  REID, R. W. Opereting Reactors Branch 4 (Pre 790625). 78/11/13.
  RSpp. 94409:063.

- --7812010377 Amend 5 to License NPF-6.chenging Tech Specs dealing w/ edministrative controls & plant organization BTOLT.U.F. Light Water Reactors Branch 1. 78/11/13. 19pp 94409 09:
- --7812010380 Safaty evaluation supporting Amend 37 to License DPR-51 & Amend 5 to License NPF-6.

   Office of Nuclear Reactor Regulation. Director 78/11/13. 2pp. 94409:110.
- --7812010081 Notice of issuance of Amend 37 to License DPR-51 & Amend 5 to License NPF-6. REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/11/13. 200. 94409-112
- 7812130118 Notice of wortshops is implementation of training & qual requirements contained in Appaid B of 10CRF73. Requests pre-workshop registration of attendess to facilitate sending out meth. H/enci Registration Form & List of Locations. MILLER, J. R. Assistant Director for Site & Sefequents (Pre 791030). 78/11/15. 3pp
- 7812190002 Forwards RevMi "Draft Radiological Effluent Tach Space" for PWR's (NUREO-0472)& "Preparation of Radiological Effluent Tach Space for Nuc Pwr Plents" (NUREO-0133). GRIMES, B.K. Assistant Director for Engineers & Projects (Pra 790625). 78/11/13. 6pp. 94214:248.
- 7811200350 Forwards order for Hod of lic which smands Facil Oper Lic eDPR-51. Implementation of caratin mods to also pur sys must begin by 781031 Allows oper of ANO-1 until mods are complete.
  REID.R.M. Operating Reactors Branch 4 (Pra 790625). 78/11/17. 2pp. 94451:001
- --781:200356 "Notice of Order for Mod of LicHDPR-51." Mod involves connection of load sequence circuitry used for loading flees I generators such that they will also sequence sefety loads onto stertup transformere.

  STELLO.V. Division of Operating Reactors. 78/ii/17. 6pp. 74451:003.
- 78:1300045 Discusses Mountain Wast Research Inc forthcoming contracted study on regional socioeconomic impacts during facility const and post-const pariods. J Chalmers will brise util restudy objectives & dasign & type of info required. DEYDNOR.R.C. Division of Site Bafety & Environmental Analysis. 78/11/70. 2pp. 94071:047.
- 78:2040236 Forwards results of impingement monitoring at subj facilintake during Oct 78 pursuant to Environ Tack Spec 4.1.2.a. (2). HILLIAMB.D.H. Arkenses Power & Light Co. 78/11/28. 2pp. 94328:023.
- 7812150084 Discusses possible dangers of LOCA in containment purging during normal plent oper Requests alther commitment to limit purging or justification for continuing Wencl AND: 7812080207.
  REID-R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp. 94211:318.
- 7812140124 Requests raviaw & approval of alternets method of obtaining reference stress intensity factors which allow continued etud tensioning et minimum temp of 70 degrees F during upcoming refueling outege.
  WILLIAMS.D.H. Artenses Power & Light Co 78/12/06. 3pp. 94133:325.
- 7812280146 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any insecuracies or enforcement action will result. DAVIB.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94311:278.
- 7812180120 Provides requested verification by computer simulation of sys ra Tech Space change to delete sodium thiosulfate from Reactor Slidg Byray Bys. Raquests expeditions review of attach drawdown tast deta. W/att comparison of tests.
  WILLIAMS.D.M. Arkenses Power & Light Co. 78/12/13. 6pp. 94344: 335.
- O. Inspection reports, IE Bulletins & correspondence
- 7B10130045 Forwards 1E Inspec Repts 50-313/78-12 & 50-368/78-20 on 7B0710-14 & 7B0725-28 & notice of violation. MADEN.6.L. Region 4, Deltas, Reactor Operations Nuclear Support Brench, 78/08/11, 2pp. 94001:179.

- --7810130049 Notice of Violation from inspec on 780710-14.

   Region 4, Dallas, Reactor Operations Nuclear Support Brench.
  78/08/11 2pp. 94001-181
- --7810130053 IE Inspec Rept#50-313/78-12 & #50-368/78-20 on 780710-14 & 25-28 during which 3 items of noncompliance were noted: no audits conducted since 770728 under BRC, no demonstration of nonsupervised circuits, unplugged rod wermer.

  MADSEN, O. L., WESTERMAN, T.F., KELLY, D. L. Region 4, Dalles, Rector Operations Nuclear Support Branch. 78/08/10, 12pp. 94001:183.
- 7810140089 Forwards IE inspec Repte#50-313/78-13 & #50-368/78-21 on 780801-04 & 780808-10 during which no items of noncompliance were noted.

  MADEN. G. L. Region 4. Delias. Reactor Operations Nuclear Support Dranch. 78/08/22. 2pp. 94421:001.
- --7810140092 IE Inspac Repts#50-313/78-13 & #50-368/78-21 on 780801-04 & 780808-10 during which no items of noncompliance were noted.

  Hejor erass inspec included: Tech Spec calibr & surveill & items re Oper Lic issuence & Constr Deflancy Repts.

  HESTERMAN.T.F., BOYTER.N.C., MADBEN.O.L. Region 4. Dailes, Office of the Director 78/08/22, Spp. 94421:003
- 7811210114 Forwerds IE Inspec Rept#50-313/78-14 on 780814-18 & Notice of Violation.
  MADEEN.O.L. Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/09/14. 2pp. 94482:176.
- --7811210115 Notice of Violation from Inspec on 780814-18. \* Region 4. Dallas. Reactor Operations Nuclear Support Stanch. 78/09/14. 2pp. 94482:178.
- --7811210121 IE Inspec Rept#30-313/78-14 on 780814-18 during which 4 itsms of noncompliance were noted: failure to control high radiat areas. Improper radioactive shipment & feiture to label metls.

  MRRAY.B., URDWN.Q.D. Region 4. Dalles, Reactor Operations Nucleer Support Brench. 78/09/13. 11pp. 94482:180.
- --781i210i25 Responds to 7809i4 NRC ltr re violations noted in Inspec Rept#50-313/78-i4. Corrective actions: door to high radist area posted w/high radist area signs. Expended filters double checked for dewetering. WILLIAMS.D.H. Arkenses Power & Light Co. 78/10/09. 2pp. 94482:191.
- --78:12:10:128 Ack receipt of 78:1009 itr informing NRC of steps taken to correct violations noted during imapsc#50-313/78-14.

  HADBEN.G.L. Region 4. Dallas, Reactor Operations Nuclear Support Brench. 78/10/31. 1p. 94482:193.
- 7B10110276 Ack receipt of 7B0918 ltr informing NRC of steps talen to correct violations noted during IE Insp 50-313/7B-10.

  MADEEN.G.L. Region 4. Delias, Reactor Operations Nuclear Support Brench. 7B/09/25. ip. 94068:343.
- --7810110301 Responds to 780911 NRC ltr re violation noted in Insp Rept 50-313/78-10. Corrective ections: agrees w/definition of "annuel" per NRC interpretation for annual operator requalification exams.
  WILLIAMS.D.H. Arranses Power & Light Co. 78/09/18. 1p. 94088:344.
- 7810140131 Forwards 1E Bulletin#78-12 requiring action re reactor fecil w/oper lic or constr permit. (See AND:7810004233)
  BEYRRITK, V. Gefice of Inspection & Enforcement. Office of the Director. 78/09/29. 1p. 94413:048.
- 78112104B0 Forwards IE Inspec Repts#50-313/78-15.#50-348/78-23 & Notics of Violation.
  MADEEN.G.L. Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 03058: 228.
- --7811210487 Notice of Violation from inspec on 780822-25,780828-31, 780705-08. • Region 4, Dallas, Reector Operations Nucleer Support Branch. 78/10/04. 2pp. 03558:230.
- --78:1210301 IE Inaper Repta#30-313/78-15 & #50-348/78-23 on 780822-0913 during which 2 items of noncompilance were noted: verification of operability of main steam isolation velves & non-functional panetration fire berrier. #EBIERMAN, T. F., JOHNBON, M. D., DICKERSON, M. M. Region 4, Dalles, Office of the Director. 78/10/03. 23pp. 03558:232.
- 78:1220117 Forwards IE Circular#78-18, "UL Fire Tast." W/encl AND:78:11:150002. SEYFRIT.K.V. Region 4, Dellas, Office of the Director. 78/11/06. ip. 94071:286.

T.K.V. Region 4: Dalles: Office of the Director. 78/10/13. 4169:173.

153 Forwards IE Inspec ReptsW50-313/78-16 & W50-368/78-24 on -1022 & notice of violation.

10.L. Region 4, Delles, Reactor Operations Nuclear Support 78/10/31. 2pp. 94215:066

0088 Notice of Violetion from inspec on 780925-1022. egion 4. Dallas. Reactor Operations Nuclear Support Branch. 0/31. pp. 74215-048

006: IE Inspec RepteM50-313/78-16 & M50-36B/78-24 on 780925-1022 ng which I item of honcompliance was noted: bypesses were properly verified upon removel.

ERMAN.Y.F., SPANGLER.R.Q., MADSEN.Q.L. Region 4, Deliastor Operations Nuclear Support Branch. 78/10/31. 6pp.
5:069

13 Act receipt of 781024 ltr Informing NRC of steps teken to twioletions during inspec#50-313/78-15 & 3/78-23.

9.L. Region 4, Dallas, Reactor Operations Nuclear Support 78/11/03. 2pp. 94087:053

M27 Responds to 78:004 NRC ltr rs violations noted in Inspection-368/78-23. Corrective ections: use of sign-off steps sturn HPSI pump hend switches to normal install "fire" ion fire doors.
AMB.D.H. Arkanses Power & Light Co. 78/10/24. 2pp. 1:054.

77 Forwards 1E Inspec Rept#50-313/78-18 on 781003-04 during in items of noncomplience were noted. Wh.M. Region 3: Chicago: Bafeguards Brench. 78/11/09. Rpp. 20.

7 Forwards Inspec Rept 50-313/78-20 & 50-368/78-27 on 781026 ing w/ pub officials of London & Russellville.AR ing subj Facil.
9 L. Region 4, Delles, Reactor Operations Nuclear Support 78/11/09. 2pp. 94159:245.

ORO Inspec Rapt#50-313/78-20 & #50-368/78-27 on 781026 during NRC officials discussed w/local officials lines of nication w/NRC, the status of subjecti, & community rhs.

RMAN, T.F., MADBEN, Q.L., WIBNER, C.E. Region 4, Dellas, Reactor tions Nuclear Support Branch. 78/11/08. 3pp. 94159: 247.

9 Forwards IE Bulletin #78-12A.suppl to IE Bulletin#78-12. ANO: 7811300055.
K. V. Region 4. Deltes, Office of the Director. 78/11/24, 371:357.

 Ack receipt of 781121 Itr informing NRC of steps taken to violetions noted in Inspec Rept#50-313/78-17.
 L. Region 4. Delles. Reactor Operations Nuclear Support 78/12/07. ip. 94307:007.

321 Responds to 781026 NRC ltr re violations noted in Inspec 30-319/78-17. Corrective actions: procedures used For 1 bldg purges & deteiled instructions For hand lating values have been corrected.
449.D.H. Arkenses Power & Light Co. 78/11/21. 2pp. 008.

127 Forwards IE Inspec Rept#50-313/78-17 on 781002-06 & Notice letion.

1. G. L. Region 4. Dellas, Reactor Operations Nuclear Support 78/10/26. 2pp. 94307:010.

32 Notice of Violation from inspec on 781002-06. ion 4. Dallas, Office of the Director. 78/10/26. ip.

36 IE Inspec Rept#50~313/78-17 on 781002-06 during which 1 f noncompliance was noted:geneous effluent release exceeded.
E. J. BROWN, Q. D. Region 4. Dellas. Fuel Fecility & Materials Brench. 78/10/25. 7pp. 94307:013.

Ack receipt of 781122 itr informing NRC of steps teken to violations noted during inepsc#50-213/78-16.
L. Region 4, Dellas, Reactor Operations Nuclear Support 78/12/11. 1p. 94279:115.

in Junger & Bypas Log were removed & memo issued to staff to meintain compliance.

HILLIAMS.D.H. Arkensee Power & Light Co. 79/11/22. ip. 94279:116.

- 7812210135 Forwards responses to items of insec Inspec Programmer not resolved during 781115-16 meetings, 12 related oversized piping 4 instrumentation disgrams retained by Ching Chang HTLLIAMS, D. H. Arkenses Power & Light Co. 78/12/15. 3ipp 94266:283.
- R. Periodic operating reports & related correspondence
- 7810200067 Farwards Monthly Oper Rept for Sept 1978.

  HILLIAMS, D. H. Arkenses Power & Light Co. 78/10/10. 1p. 94412: 176.
- --7810200070 Monthly Oper Rept for Sept 1978. BHIVELY: C.N. Artenses Power & Light Co 78/10/11. Spp. 94412: 177
- 78103i0119 Forwards fish impingement monitoring results for Sept 1978. WILLIAMS.D.H. Arkansas Power & Light Co. 78/10/24. 2pp. 94.090:017
- 7811030151 Forwards third querter Netl Poliutent Discherge Elimination Bys Rept for NPDES Permit#AR0001392 WILLIAMS, D. H. Arkenses Power & Light Co. 78/10/31. 2pp. 02723:353.
- 78121R0138 Forwards Monthly Oper Rept for Nov 1978.
  WILLIAMS.D H. Arkeness Power & Light Co. 78/12/07. 1p. 94276: R90.
- --7812120142 Monthly Oper Rept for Nov 1978. BMIVELY.C.N. Arkenses Power & Light Co. 78/11/30. Spp. 94276:251.
- 7812280127 Forwards intels impingement monitoring data for subs fecil for Nov 1978.
  WILLIAMS,D.H. Arkansas Power & Light Co. 78/12/21. 20pp.
- S. Reportable occurrences. LERs & related correspondence
- 7810170143 Forwards LER#78-023/017-0 & 78-024/03L-0.

  MSLLIAMB.O.H. Arkenses Power & Light Co. 78/10/06. 19. 94236:066.
- --78:0170:146 LER#78-023/01T-0: on 780925, during surveillence test. Control Rod Driveline Braeter A felled to trip on first attempt. Caused by trip mechanism mechanical arm being out of adjustment, Arm adjustment corrected. Breeker meets epacs. SHIVELY, C. N. Arkenses Power & Light Co. 78/10/06. App. 94236: 067
- --7810170149 LER078-024/00L-0; on 780916, Control Rod Driveline Breeker A failed to trip upon reactor trip. Ceuse not given. Breaker tripped manuelly. Minor adjustments mede to breaker. Breaker subsequently tested successfully.

  8HIVELY, C. N. Arkanses Power & Light Co. 78/10/06. ip. 94236: 071.
- 7811060175 Forwards LERM78-025/03L-0.LERM78-026/03L-0 & LERM78-027/03L-0.

  MILLIAMS.D.H. Arkenses Power & Light Co. 78/10/13. 1p. 94489:113.
- --7811060180 LER#78-025/03L-0: on 780917, control red index reached restricted ione w/worst case condition at 171 X withdrawn at 90 X power. Caused by miscalculated boron addition to RCS. Acceptable rod positions obtained within 2-b. BHIVELY.C.N. Arkenses Power & Light Co. 78/10/13. lp. 94489: 114.
- --7811060183 LERW78-026/03L-0: on 780926, normal borated water storage tank chamical sample showed boron concentration below Tech Specs limit. Cause not given. Concentration raised to Tach Specs requirements.

  BMIVELY: C.N. 'Arkenses Power & Light Co. 78/10/13. 1p. 94487: 115.
- --7811060189 LER#78-027/03L-0; on 780926, condensate storage tank level dropped below min Tech Space level. Caused by ehrormelly high condensate demand due to simultaneous rinsing of polisher & makeup plant plus makeup to hotwell.

  BHIVELY. C.N. Arkenses Power & Light Co. 78/10/13. ip. 94489: 116.

1060154 Forwards LER#78-028/03L-0.
1LLIAM8, D. H. Arkansas Power & Light Co. 78/10/27. 1p. 94489: 072.

HillO6015B LERN78-028/03L-0: on 780929 leak developed in casing drain line from discharge of Makeup Pump P36C upstream of Velve ABD-9C. Caused by crack in pige nipple threaded into pump Casing due to apparent overstressing in installation. BHIVELY, C.N. Arkenses Power & Light Co. 78/10/27 1p. 94489: 073.

1200175 Forwards LER#78-029/03L-0. ILLIAMS, D. H. Artenses Power & Light Co. 78/11/06 1p. 94252: 293.

8i1200180 LERW78-029/03L-0:on 78i017, during surveillance test. Control Red Driveline A breaker felied to immediately trip on trip aignal. Cause not identified Breaker replaced. SHIVELY, C.N. Arkenese Power & Light Co. 78/11/06. 1p. 94252: 294.

1170055 Summerizes 780916 event & recommends it be inpt as Abnormal courtener; during pur oper Unit 1 tripped due to Pailure of ne main steem inclation vaive & shut down. Resulting eisc ransient etertad Unit 2 diesel generature, causing floading. AIMSB.0. Plenb Systems Brench (Pre 791030). 78/11/07. 2pp. 4046:253.

2120131 Forwards Addenda A to "Resetor Bidg Conteinment Integrated ask Test Rept." JLL1AM9,D.H. Arteness Power & Light Co. 78/11/30, ip. 94276:160.

812120137 "Reactor Containment Bldg Integrated Leakage Rate Teet Rept, Addenda A.Lacal Leek Rete Testing."

+ Arkeness Power & Light Co. 78/10/08. 15pp. 94276:184.

2270247 Forwards LERM78-030/03L-0. ILLIAMS.D.H. Artensas Power & Light Co. 78/12/19. ip. 94017:161.

812270249 LERM78-030/03L-0:an 781191.borated water storage tenk boron concentration fell balow Tech Specs limit. Caused by open Condensets Valve CB-3B. Veive closed increesing boron concentration. SHIVELY, C. N. Artensae Power & Light Co. 78/12/19. 1p. 94017: 162.

KET 80-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1 Security, modical, emergency & fire protection plans

1170204 Reports on investigation of isoletion of deluge valves to rumming room & new fuel receiving area: closing valves wee accessary to prevent epurious oper of eprintler sye during epairs to broken fire header outside bldg from 781027-31. HALLER D. V. Indiana & Michigen Power Co. 78/11/09. 2pp. 4048: 295

2210354 Responds to 781122 request for change in commitment ra inding replacement portable air sempla for emergency use. Iccapts rev pien. EPPLER.J. G. Ragion 3, Chicago, Fuel Facility & Materiels Safety Iranch. 78/12/13. 2pp. 94014:351.

Gameral correspondence

1100154 Notice of meeting on 781101 w/AEP to discuse AEP plane for use plant & related metters. W/att agenda. IILVER.H. Light Water Reactors Branch 4. 78/10/30. 2pp. 44047:185.

Utility Final Befety Analysis Report (FBAR) & amends

.1250247 Forwerde Amendé82 to FSAR. ILLINOHABT.J. indiene & Michigan Power Co. 78/11/27. 4pp. 14237:203.

2260198 Remits add1 far for processing Amend#81 to FBAR for subj acils.purusent to discussions w/NRC. ILLINOHAST.J. Indiana & Michigan Power Co. 78/18/12. 2pp. 4141:330.

P. Operating license stags documents & correspondence

7810110080 Describes abnormal environ occurrence of 780923 when chloring residuals showed greater than 0.10 PPM due to increase in chloring feed rate resulting from clutch slipping in chlorinator. Tension on clutch adjusted.
BHALLER, D. U. Indiana & Michigan Power Co. 78/10/02. 2pp. 94063: 348.

7811010204 Notice of 781031 assting u/American Elec Pur Bvc Corp to discuss proposed mod of spent fuel pool.

MLYNCXAM.M. Depreting Resettors Branch 1 (Pre 790625). 78/10/12. 2pp. 94391: 345.

78:1030103 Forwards 2 copies of Startup Tast Rept For Cycle 3 of subj facil Encl available in CF only. TILLINGHABT, J. Indiana & Michigan Power Co. 78/10/24. 2pp. 02721: 184.

7810310090 Response to 1tr që 780913 from A Schwencer, presents sches for submittal of rev EECS analysie for subj facil.
Hestinghouse hes airedy performed reshalysis for Unit 2 Unit 1 will be removed from area of concern addressed in ltr.
TILLINGHAST. J. Indiana & Michigen Power Co. 78/10/25. 2pp. 94091: 167.

7810310204 Requests extension in responding to 780828 1tr from Schwencer ra overpressure protec Tech Specs Needed info will not be received & In-house reviews will not be completed in time Extension sought is to 781128.
TILLINGHABT.J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94090: 314.

7811130164 Notifies applicant of 781128 NRC-sponsored eminer re Model Radiological Effluent Tech Specs for Nuc Pur Plants Encl w/8minar Info Sheatito be completed & returned by 7811177 & Proposed Agends.

KEPPLER.J.Q. Region 3. Chicago. Office of the Director. 78/11/07. 6pp. 03553: 275.

7611280344 Forwards request for add1 info re containment sump tests.
Inter alia, seeks info re NPSH margin & containment sump vent destan. BCHWENCER. A. Operating Reactors Branch 1 (Prs 790625). 78/11/07. 3pp. 94397: 184.

7811270018 Forwards Amend#26 & S to fec11 Open Lic#DPR-58 & DPR-74. Amend consists of changes to Append B Environ Tech Spec in response to 780301 appl. SCHEENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 3pp. 94081:058.

--7811270019 Amend#26 to Lic#DPR-58 re delcing measurements. Water chemietry in plant sys.chemical discharges, thermal discharge surveillance, groundwater monitoring & termination of biote monitoring. BCHWENCER, A. Operating Reactors Branch 1 (Prs 790625). 78/11/08 2pp. 94081:061.

--7811270020 Amend#8 to LiceDPR-74 to deling measurements, weter chemistry in plant sys, chemical discharges, thermal discharge surveillance, groundwater monitioring & termination of biote monitoring. SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/08 60pp. 940B1:063.

--7811270021 Environ Impact Appraisal & safety aval supporting Assideb & 98 to facil oper lic #DPR-74.

8CHHENCER, A. Derating Reactors Brench 1 (Pre 790625), 78/11/08. 12pp. 94081: 124.

--7811270023 Notice of issuance of amend to facil open lic & negative or issuence of amend to facil oper its angular declaration relating to delicing mesour-ments-wester chamistry inplant sys, chemical discharges, thermal discharge survaillance, graindwater monitoring.

SCHHENCER.A. Operating Reactors Brench I (Pre 790625). 78/11/08.

Jpp. 74081:142.

7811210260 Forwards "Reactor Containment Bldg Integrated Leah Rate Test" rept for subj facil conducted 780527-29.
TILLINGHABT, J. Indiana & Michigan Power Co. 78/11/14. 29p. 94486: 052.

--7811210265 "Reactor Containment Bldg Integrated Leak Rate Test, 780527-29" Covers acceptence criteria, iLRT test results, test conduct, instr & equip containment model & leak rate calculations, iLRTES prog printout & analysis.

4 indiana & Michigan Power Co. 78/11/14, 98pp. 94486:054.

781 P

781

781

EH 7813 . .

781

CI ML 7812 7E 80

He tr of Br 7812 to SU NR

Di 7812 8u

--78

7812 He

in Til 7812 64

7 I I 76122 fai

HAL 941

45 Notice of workshops re implementation of training & qual seatts contained in Append B of 10CFR73. Requests riskop registration of attendess to facilitate sending th. Wrenci Registration form & List of Locations.

J. R. Assistant Director for Site & Safeguards (Pre 791030).
15. 5pp.

O Informe IMPR that NRC has contracted w/Mountain Weet Resundertake a series of post-licensing studies of nuctions. Studies will analyze socioecon impacts which during constr & post-constr periods of each plant. vR.C. Division of Site Safety & Environmental Analysis. O. 2pp. 94071:053.

i Lic #OPR-58 & #DPR-74 Appl for Amend to increase spent fuel capacity from 500 to 2.050 fuel assemblies. W/sncl ption & Bafety Analysis for the Fuel Storage Capacity on Prog."

.9. P. Indisns & Michigan Power Co. 78/11/22. Aipp.

5 Sunmary of 781031 meeting re spent fuel pool espansion at cil.Licenees outlined preferred lic sched & will rerack appl on 781115 & 781211.NRR itc review to be ad by 780413.

4.M. Operating Reactors Branch 1 (Pre 790625). 78/11/22.
4416:311

3 Discusses possible dengers of LOCA in containment purging normal plant oper Requests either commitment to limit or justification for continuing Wanci AND: 207.

IR.A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. 1130:311.

) Forwards results of 780328 strontium split samples, 780328 itself waste enalysis, 780907 nonacidified split & 781019 acidified split samples, D. V. Indiana & Michigan Power Co. 78/11/29. 7pp.

Reports loss of documentation from 780216 Ice Basket. All final weights, data analysis & weight standard lity are available, so it is fait that requirements Space are eatisfied.

D. V. Indiana & Michigan Power Co. 78/11/29. 2pp.

Emphasizes importance of submitting accurate & complete infog licenesse & applicants. Info submitted must be lated by data & calculations. Licenesse must notify ny inaccuracies or antorcement action will result.

9. Office of inspaction & Enforcement, Office of the 78/12/06. Rpp. 94311:302.

Forwards rapt entitled "Hydraulic Model investigation of g & Bwiri within a Reactor Containment Recirculation td 780930. ABT.J. Indiana & Michigan Power Co. 78/12/20. 2pp.

81 "Hydraulic Model Investigation of Vortexing & Swirl Within A r Containment Recirculation Sump" rept. Teste concluded all sump design should be modified to reduce exceesive in suction pipes under certain blockage conditions.
48 HAN.M. Indiena & Michigan Power Co. 108-78/Mi78PF.
30. 67pp.

Provides preliminary info re plans for next refueling outage Pacil. Current operating cycle should end in late early April 1979; stertup of next cycle is expected 179. No Tech Spec changes foreseen.

18T. J. Indiana & Michigan Power Co. 78/12/20. 20p.

Forwards \$12700 check for processing of spent fuel storage expension submittels. Will submit thermal enalysis it struc enalysis by 780220, i37.J. Indians & Michigan Power Co. 78/12/21, 2pp.

Requests changes to Append "A" Tech Space of subj facil & proposed changes w/appropriate ray pages. Also has el.200 fes.

.P. Indiana & Michigan Power Co. 78/12/22. Ppp.

--7812290185 Proposed revs to Append "A" Tech Space of subj facil. Contains 16 changes w/appropriate rev pages reifire detacinstrutflow rates for boron injec system additive system Space, applicability of Tech Space, applicability of Tech Space, applicability of Tech Space, applicability of Tech Space, & editorial changes.

• Indiana & Michigan Power Co. 78/12/22. 56pp. 94190:124.

## G. Inspection reports, IE Bulletins & correspondence

7810240032 Forwards IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15, 20-21 during which no items of noncompliance were noted. HIND, J.A. Region 3, Chicago, Bafeguards Branch. 78/01/19. 2pp.

--7810240033 IE Inspec Repts#50-319/77-26 & #50-316/77-37 on 771114-16 & 1214-15.20-21 during which no items of noncompliance were noted Major areas inspected included: security organization. physical berriprs.eccese controle.detection aids. CRLEON, D. M. J. MADEDAT, J. J. HIND, J. A. Region J. Chicego. Sefeguards Branch. 78/01/18. 1p.

7810270395 Forwards IE Inspec Repts#50-313/78-23 & #50-316/78-23 on 780710:12:14:17:19-21:24. & 26-28:780809-10:14:16-18 & \*Notice of Violetion.
FIORELLI, Q. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94033:296.

--7810270388 Notice of Violation from inspec on 780710,12.14.17,19-21,24, 26-28 & 780807-10.14,16-18. \* Region 3, Chicago, Reactor Operations Nuclsar Support Branch. 78/09/21. ip. 94033;298.

--7810270398 IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710 during which I item of noncompliance was noted procedure for equip control was not implemented as raquired-allowing unplenned release of partial contents of 2 gas docay tanks. BAKER.K.R. Region 3. Chicago, Reactor Operatione Nuclear Support Branch. 78/09/20. 9pp. 94033:299.

7810300375 Forwards IE Inspec Rept #30-318/78-26 & 50-316/78-25 on 780906-07 during which no items of noncomplainte were noted. DAVIS, A. B. Region 3, Chicago, Bareguards Branch. 78/09/22. 2pp. 34150-345

--7810300383 IE Inspec Repts #50-315/78-26, 50-316/78-25 on 780906-07 during which no items of noncomplience were noted. Major areas inspected included: special confirmatory measurements inspec & semple analyses.

OREER.R.J. Region 3. Chicago, Befaguards Dranch. 78/09/21, App. 94197:345.

7811020111 IE Inspec Repts#80-315/78-23 & #50-316/78-21 on 780905-06 during which no items of noncompliance were noted Major areas inspected included:action on previously identified items re operability of safety related snubbers.

YIN.1. DANIEL80N.D.H. Region 3. Chicago, Office of the Director. 78/09/25. 3pp. 94351:082.

7811020106 Forwards IE Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-06 during which no items of noncompliance were noted. HEISHMAN.R.F. Region 3, Chicago, Resctor Construction & Engineering Support Branch. 78/09/27. 2pp. 94351:081.

7811080101 Forwards IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no items of noncompliance were noted. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/10/02. 2pp. 94399:084.

--7811080104 IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no litems of noncomplience were noted. Major ares inspected included: eubj fecil operating performance. FIORELLI, G., KEPPLER, J. G. Region 3, Chicego, Reactor Operations Nuclear Support Branch. 78/09/14. 2pp. 94399: 086.

7810110297 Ack receipt of 780911 ltr informing NRC of atess teken to correct violetions noted in 780817 NRC ltr. FIDRELLIA. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/03. 1p. 03556:083.

7811090182 Forwards IE Inspec Repts#50~315/78-24 & #50-316/78-22 on 780829-0901 & Notice of Violation. FIGMELLI-Q. Region 3, Chicago: Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94038:208.

--7811090185 Notice of Violetton from inspec on 780829-01. # Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94038:210.

- --7811090189 IE Inspec Rept#30-315/78-24 & #50-316/78-22 on 780829-0901 during which 4 items of noncompliance were noted: failure to process off sits safety review comm minutes & failure to implement acceptable inavc pump test prop.

  REVER.L. A. MASSE.R. E. JABLONSKI.F. J. Region 3. Chicago, Office of the Director. 78/10/04 Spp. 94038-212
- 78:1140183 Forwards IE Inspec Repts#50-315/78-28 & #50-316/78-28 on 780912-15 during which no items of noncompliance were noted. DAVIB.A B. Region 3. Chitego, Fuel Facility & Meterials Bafety Branch. 78/10/11. 2pp. 94384:263
- --7811140189 IE Inspec Repts#50-315/78-28 & 50-316/78-28 on 780912-15 during which no items of noncompliance were noted Major areas inspected included: radioactive waste systeffluent raisages, records & rapts of effluents.

  SCHUMACHER,M.C. Region 3, Chicego, Fusi Pecility & Materials Safety Branch, 78/10/10. 7pp. 94384:265.
- 7810230356 Forwards JE Circuler#78-17. (800 AND: 7810230221 Docket 50-133.781013)
  KEPPLER, J. G. Region 3, Chicego, Office of the Director. 78/10/13. ip. 94147:001.
- 7811020160 Forwards replacement cover page for Insp Repts 30-315/78-30 5 50-316/70-28, on which signatures had been inedvertently omitted. KEPPLER, J. O. Region 3, Chicago, Office of the Oirector. 78/10/13-2pp 94394:349.
- 7811080138 Responds to 780921 NRC itr re-violation noted in Inspec Reptw850-315/78-25 & 50-316/78-23 Corgective ection: the Mod Indiceted in 780822 itr will be compiled by 781031 DDLAN-J.E. American Electric Power Co., Inc. 78/10/16. 2pp. 94399: 283.
- 7812060388 Forwards 1E Inspec Rept#50-315/78-29 & #50-316/78-27 on 780925-29 & Notice of Violation Notice of Violation w/held per 100FR2.790(d).
  HIND.J.A. Region 3, Chitago, Bafeguerds Branch. 78/10/29. 2pp. 94382.344
- --7812060391 IE Inspec Repts#50-315/78-29 & #50-316/78-27 on 780925-29 during which 4 itses of noncompliance were noted; security organization, communications control detection aids & testing & maintenance.

  CREED, J. R., MADEDA, T. J., HIND, J. A. Region 3, Chicago, Befaguards Brench, 78/10/20, Epp. 94382-346.
- 7811210446 Responds to 781004 NRC 1tr re-violations noted in Inspec RepteR30-315/78-24 & 850-316/78-22 Corrective actions: proceduras rev to include requirements of Tech Spec 4.0.5 & 4.5.2.f. i, new procedure 12THP 4030, BTP, 022 setablished, DOLAN.J.E. American Electric Power Co., inc. 78/10/27. App. 94480; 196.
- 7811150061 Forwards IE Circular 78-18.
  MEPPLER. J. O. Region 3. Chicago, Office of the Director. 78/11/06.
  1p. 94112:222.
- 7811200045 Ack receipt of 781016 itr informing NRC of steps taken to correct violations noted during inspec. FIDRELLI.G. Region 3. Chicago, Resector Operations Nuclear Support Branch. 78/11/09. 1p. 94213/327.
- 7812130035 Forwards IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780828-31, 780901, II-15, I8, 20-22, 25-29, 1002 & 1004-06 & Notice of Violetion.
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/09. 2pp. 94307: 215.
- --7812130037 Notice of Violetian from Inspec on 780828-31,0901,0911-15,0918,09210-22,0925-29,1002 & 1004-06.

  W. Region D. Chicego, Office of the Director. 78/11/09. 2pp. 94307:217.
- --7812130045 IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780828-31 during which 2 items of noncompliance were noted:Unit 2 RMET piping for low temp alarm was blocked w/o epproval & condition repts not promptly initiated for RO's.

  SAKER, M. R. MASSE, R. E. , WARNICK!, R. R. R. (and C. Chicago, Office of the Director. 78/11/09. 13p. 94307:218.
- 7812130206 Forwards IE Inspec Rept#50-315/78-31 & 450-316/78-29 on 781010 during which no items of noncompliance were noted. HEIBHAN.R.F. Repion 3. Chicago, Office of the Director. 78/11/09. 2pp. 94306:066.

- --7812130209 IE Inspec Rept#50-315/78-31 & #30-316/78-29 on 781010 durie; which no items of noncompliance were noted. Major areas inspected inclicionnee action on IE Circular#78-08.
  LARLONGHI.F.J. Region 3. Chicago. Office of the Director. 78/11/09. Spp. 94306:068.
- 7812050311 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/encl AND:7011300055 KEPPLER.J. O Region 3. Chicago: Défice of the Director. 78/11/24. ip. 94203-073.
- 7812050260 Forwards IE Bulletin#78-12e.suppl to IE Bulletin 78-12. U/encl AND 7811300055. PAPPAB-H. Region 3. Chicago, Office of the Director. 78/11/27. 2pp. 94202:142.
- 7813280047 Forwards 1E Bulletin 78-14.
  KEPPLER, J. G. Region 3: Chicago: Office of the Director. 78/12/19
  1P. 94084-323.
- R. Periodic operating raports & related correspondence
- 7811210383 Forwards Monthly Open Rept for Oct 1978.

  BHALLER, D. V. Indiana & Michigan Power Co. 78/11/14. 1p. 94464:291.
- --7811210391 Monthly Dper Rept For Dct 1978.
  OllLETT, M. T. Indiana & Michigan Power Co. 78/11/01. Spp. 9484:292.
- 7812110137 Forwards monthly repts for July, Aug & Sept 1978 re fish Implingement at subj. facil. SHALLER, D. V. Indiana & Michigan Power Co. 78/12/05. 16pp. 94393:242.
- 7812200173 Forwards Monthly Oper Rept for Nov 1978. BHALLER.D.V. Indians & Michigan Power Co. 78/12/14. 1p. 94183;325.
- --7812200174 Monthly Oper Rept for Nov 1978.
  OILLETT. M. T. Indiana & Michigan Power Co. 78/12/04. 6pp.
  94158:326.
- 8. Reportable occurrences, LERs & related correspondence
- 7810180106 Forwards LERW78-051/03L-0 & LERW78-052/03L-0. 8HALLER, D. V. Indiana & Michigan Power Co. 78/09/27. ip. 94421:301.
- --7810180109 LERR7B-051/03L-0 on 780828: axial flux difference went outside terget band during rapid load reduction. Caused by repairs to valvee resulting in loss of steam to condenser air ejectors.

  RNDOLPH.J.M. Indians & Michigan Power Co. 78/09/27. 19.
- --7810180158 LERN78-052/03L-0 on 780828: Steam generator loop level found to have exceeded minimum set point limit. Caused by bad solder joint on resistor.causing input resistance to vary. Bolder joint reformed.

  BEILMAN, T. P. Indiana & Michigan Power Co. 78/09/27. 19. 7442: 303.
- 7810100024 Describes abnormal environ occurrence of 780923, when chloring residuals taken of condenser outlet showed greater then 0.10PPM, due to site of clutch on feed rate control motor, Clutch tension has been adjusted.

  8HALLER.D. V. Indiana & Michigan Power Co. 78/10/02. 2pp. 94033;044.
- 7810110154 Forwards LERW78-053/03L-0 & LERW78-054/03L-0. SHALLER, D. V. Indiana & Hichigan Power Co. 78/10/03. 1p. 94413: 338.
- --7810110192 LERW7B-053/03L-0 on 780907: containment atmosphere gaseous separticulate monitoring pump discovered inoperable. Failure attributed to obsolessence. Pump replaced w/improved model w
- --7810250117 LER878-054/03L-0 on 780906: during routine surveillants, its condenser inlet door monitoring sys was imagerable, due to short caused by water in instr having same breaters as inlet door monitoring sys.

  BEILMAN, T.P. Indiana & Michigan Power Co. 78/10/03. 3pp. 94058: 019.

rd & LERW78-055/03L-0. Indiana & Michigan Power Co. 78/10/18. ip.

#78-055/03L-O on 780924: source range channel N-31 became
111e withdrawing shutdown banks of control rods.
Caused arretic indication of channel.
Indiana & Michigan Power Co. 78/10/18 ip.

ad s LER#78-056/031-0.

#78-056/03L on 780923: after shutdown horon concentration which is below ignit due to reduction of boron sampling at 1% accumulator voi increase. Admin a rev to req level & boron verification.

Indiana & Michigan Power Co. 78/10/20. ip.

od a LER #78-056/031-0 Emidiana & Michigan Power Co. 78/10/20 Ip.

1030, it became nacassary to isolate deluge valves to Room & New Fuel Receiving Area as rasult of Bys headers. Follow up rept will be issued

Emdians & Hichigan Power Co. 78/10/30. ip.

^ds LER#78-057/03L-0,LER#78-058/03L-0 & ~O. Isrdians & Michigan Power Co. 78/11/10. ip.

3-057/03L-0 on 781002; result of study declared pump send by inconsistency of pump's shility to tend spead which was traced to pump spead now replaced.

Endians & Michigan Power Co. 78/11/01. 1p.

▶78-058/03L-0 on 78:003: rounding off of T(2) resulted in 373 Sing non-conservative in top of the cors.
to perform stairstap comparison to FZ limit in 3P core height.
Indiana & Michigan Power Co. 78/11/01. 2pp.

B7B-059/03L-0 on 7B1023:Pressurizer level channel 3 ater than 4% from other 2 channels. Caused by gas ad in sensing line.
Indiana & Michigan Power Co. 7B/ii/Oi. ip.

remnts rapt to Meteorological Sys inoperability. On & 100 ft wind direction instruction improperly will be leaving jumpers in during installation and conficel Sys Translators.

Indiana & Michigan Power Co. 78/11/03. 2pp.

r d's condition repts on 780830 & 780928. Imidiana & Michigan Powsr Co. 78/11/03. 7pp.

diftion rept: on 780830 both Meteorological Bys Translators diducto switching malfunction, calibr is returned 0728, both wind direction instructure observed erly switching. Bys were fully recalibr.

Indiana & Michigan Power Co. 78/10/02. 5pp.

rds LERW78-060/03L-0. Emdiana & Michigan Power Co. 78/11/15. 1p.

## 78-060/00L-0 on 781028:RCS leak discovered due to cking on a 314 valve in PZR safaty valve loop ime. Valve found to be i/B turn open. Valve amkage stopped. Indiana & Michigan Power Co. 78/11/15. 1p.

rds LERN7B-061/03L-0. Indiana & Michigan Power Co. 78/12/01. ip. --7812080007 LERM78-061/03L-0 on 780823: discovered that during past surveillance testing, allowable surveillance estimation had been exceeded for target flux difference surveillance test. Caused by personnel error.

BEILMAN, T. P. Indiana & Michigan Power Co. 78/12/01. 1p 94104, 324

7812120162 Forwards LER 78-062/03L-0. BHALLER. D. V. Indiana & Michigan Power Co 78/12/07. 1p 94276: 353

--7812120167 LER 78-062/03L-0. on 781107. Unit 1 AB dissel declared inoperable following inadvertent removal of circuit board card from dissel voltage regulator circuitry. Removal caused by technician enegging the board on clothing.

BEILMAN. T. P. Indiana & Michigan Power Co. 78/12/07. 1p. 74276: 354.

7812270220 Forwards LERM78-063/03L-0.
6HALLER, D. V. Indiana & Michigan Power Co. 78/12/20. [p. 94017-102

--7812270226 LERW78-063/00L-0 on 781128: aux faed throttla from MDAFF to M32/0 position indication was intermittentivelya would not close electrically. Caused by broken tead between terminal M43 & #57 on aux switch of limitorque GMB-0-25 operator. WIZNER, D. 0 Indiana & Michigan Power Co. 78/12/20. 1p. 94017:123.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT Q F. Security, medical, amergancy & fire protection plans

78:1170204 Reports on investigation of Isolation of deluge valves to drumming room & new fuel receiving area: closing valves was necessary to prevent spurious open of sprinkies sys during repairs to broken fire header outsids bldg from 78:1027-31.

SHALLER, D. V. indiane & Michigan Power Co 78:/11/09. 2pp. 94048: 225.

7811290136 Forwards Special Rept BI-01: "Safety Injection Actuation" dtd 780301 & Bacial Rept BI-02: "Safety Injection Actuation" dtd 780804. 8HALLER, D.V. Indiana & Michigan Power Co. 78/11/07. 5pp. 94238: 137.

7812210354 Responds to 781122 request for change in commitment refinding replacement portable air sample for emergency use. Accepts rev pian. KEPPLER, J. Q. Region 3. Chicago, Fuel Facility & Materiale Safety Branch. 78/12/13. 2pp. 94014:351.

H. Ganaral correspondence

7811100154 Notice of meating on 781101 w/AEP to discuss AEP plans for nuc plant k related matters. W/att agenda.

BILVER:H. Light Water Reactors Branch 4. 78/10/30. 2pp. 94047:185.

K. Utility Finel Befety Analysis Report (FSAR) & amends

7811290247 Forwards Amend#82 to FBAR.
TILLINGHABT J. Indiana k Michigan Power Co 78/11/27. 4pp. 94237: 203.

--7811290201 Amend#82 to F8AR: rev of response to F8AR Question 0. Append Q. Amend#77. & rev to F8AR sections 1. 7. Rev will allow plant to combine load rejection & turbine trip startup tests & perform only load rejection test.

\* Indiana & Michigan Power Co. 78/11/27. App. 94237:207.

7819260198 Ramits add1 fas for processing Amend#81 to FSAR for subj facils, purposent to discussions w/NRC.
TILLINGHAST, J. Indiana & Michigan Power Co. 78/12/12. 2pp. 94141: 330.

P. Operating license steps documents & correspondence

7811280344 Forwards request for add1 info re containment sump tests. Inter alie, seeks info re NPSH margin & containment sump vent design.

3CHNENCER, A. Dearating Reactors Branch 1 (Pre 790628). 78/11/07.

3pp. 94397:184.

- 7B12010365 Bummary of 7B1031 meeting re spent fuel pool expansion at subj facil Licensee outlined preferred lic sched & will submit reract appl on 7B1115 & 7B1211 NRR lic review to be completed by 7B0413 MLYNCZAK.H M Operating Reactors Branch i (Pre 790625) 7B/11/22 4pp 94418 311
- 7012190036 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for PWR's(NVREO-0473) & "Preparation of Radiological Effluent Tach Specs for Nuc Pwr Plants" (NVREO-0133).

  ORITEES. K. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp. 94215:015
- 7810120062 Forwards Startup Test Rept for subj facil Lic HDPR-74 on 780919.
  DOLAN, T.E. American Electric Power Co., Inc. 78/10/02. Rep 94403: 033.
- -- 7810120067 Startup Test Rept for subj facil describing startup/testing activities initial core loading, initial criticality, low pur physics testing & pur ascension testing completed thru 700001. BMARRELLA, E. A. American Electric Power Co., Inc. 78/09/19. 294pp. 94403: 035.
- 7811010204 Notice of 781031 meeting w/American Elec Pur Svc Corp to discuss proposed mod of spent fuel pool.

  MLYNCZAK, M. M. Dparating Reactors Granch 1 (Pre 790625) 70/10/13.

  2pp 94391:345
- 7810230242 Notification that rept entitled "Qual Test of Barton Pressure & Differential Pressure Transmitters"in both proprietary & nonproprietary vareions is being forwarded under esperate cover. TILLINGHABT.J. Indians & Michigan Power Co. 78/10/05. Rpp. 94194:323.
- 7810300006 Ack receipt of 780929 1tr in response to 780816 NRC 1tr. Ballavas corrective actions re dissal generator problems are adequate.

  MOBELEY, N. C. Division of Reactor Operations Inspections. 78/10/20.
  - MOBELEY, N. C. 0
- 7810310090 Response to itr of 780913 from A Schwencer, presente eched for submitts) of rev EECS analysis for 40bj facil.
  Mastinghouse has already performed reanalysis for Unit 1 will be removed from area of concern addressed in itr.
  TILLINGHAST.J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94091: 167.
- 7810310204 Requests extension in responding to 780828 ltr from Bithwencar re overpressure protec Tech Space. Needed info will not be received & in-house reviews will not be complated in time, Extension sought is to 781128 TILLINGHAST, J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94090: 314
- 7811130164 Notifies applicant of 781128 NRC-sponsored seminar re Hodel Radiological Effluent Tach Space for Nuc Pur Plants. Encl w/Seminar info Bhestito be completed & returned by 7811171 & Proposed Agende. MEPPLER.J. Q. Ragion J. Chicago, Office of the Director. 78/11/07.
- 6pp. 03553: 275.
- 7811270018 Forwards Amend#26 & 8 to facil Oper Lic#DPR-58 & DPR-74.
  Amend consists of changes to Append 8 Environ Tech Spec in response to VB0301 appl. BCHMENCER, A Operating Reactors Dranch i (Pre 790625). 78/11/0B. Spp. 94081; 008.
- --7811270019 Amend#26 to Lic#DPR-58 re detcing messurements.water chemietry in plant sys.chemical discharges.thermal discharge eurveillance, groundwater monitoring & termination of biota monitoring. BCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 2pp. 74081:061.
- --7811270020 AmendMB to LicMDPR-74 re descing measurements.weter chemistry in plant systchemical discharges, thermal discharge surveillance, groundwater monitioring & termination of biota monitoring. SCHWENCER, A. Operating Reactors Branch i (Pre 790525). 78/11/08. 60pp. 940B1:063.
- --7811270021 Environ Impact Appraisal & safety eval supporting Amend#26 & #8 to facil oper lic #DPR-74.
  BCHNENCER.A. Deparating Reactore Branch 1 (Pre 790625). 78/11/08. 12pp. 94081: 124.

- -- 7811270823 Notice of issuance of amend to facil oper lic & negative declaration relating to deiting measurements, water chamistry implant sys, chemical discharges, thermal discharge SUrveillance groinduater monitoring SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/08 3pp. 94081: 142.
- 7811300050 Informs IMPR that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations. Studies will analyse socioecon imports which
- 7811270171 Lic MDPR-50 & MDPR-74 Appl for Amend to increase spent fuel storage capacity from 500 to 2 050 fuel assemblies. H/ancl "Description & Befety Analysis for the Fuel Storage Capacity Expansion Prog \* MALONEY, Q. P. Indiana & Michigan Power Co. 78/11/82. 41pp. 94199: 109.
- 7812180113 Discusses possible dangers of LOCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.Wenci ANO. 7812080207. BCINENCER, A. Operating Reactors Branch 1 (Pre 790525). 78/11/28.
- 7812070216 Forwards results of 780320 strontium split samples, 780328 Cs-134 liquid wasts analysis, 700907 nonscidified split samples & 780197 scidified split samples. BHALLER, D. V. Indiana & Michigan Power Co 70/11/29 7pp. 03555: 094.

6pp. 94130:311

- 78:2200149 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVID.J.O. Diffice of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94311:302
- 7812200145 Ack 701218 rapt to KR Bakar ra R-i1 & R-12. Air Particulate Detector & Gassous Black Honitor that wars out of Svc in conjunction w/Containment Daw Point Recorders. A Pollowup rept will be submitted by 781231. BHALLER, D. V. Indiana & Michigan Power Co 78/12/18. 1p. 94310:350
- 7812270170 Forwards rept entitled "Hydraulic Model investigation of Vortaxing & Buirl within a Reactor Containment Retirculation Bump," dtd 780930. TILLINGHABT, J. Indiana & Michigan Power Co. 78/12/20. 2pp.
- --7012270101 "Hydraulic Model Investigation of Vortazing & Buirl Within A Reactor Containment Recirculation Bump" rept. Tests concluded original sump design should be modified to reduce sceesive ewirl in suction pipes under certain blockage conditions. PADMANABIIAN.M. Indiana & Michigan Power Co. 108-78/M178PF. 78/09/30. 67pp.
- 7812260242 Forwards \$12700 check for processing of spant fuel storage capacity expansion submittals Hill submit thermal analysis by 790103 & struc analysis by 780220. TILLINGHABT, J. Indiana & Michigan Power Co. 78/12/21. 2pp. 94159: 346.
- G. Inspection reports. IE Bulletins & correspondence
- 7B110901B2 Forwards IE Inepac Rapts#50-315/7B-24 & #50-316/7B-22 on 7B0E29-0901 & Notice of Violation. FIGRELLIA. Region J. Chicago, Reactor Operations Nuclear Bupport Branch. 7B/10/04. 2pp. 9403B:208.
- -- 7811090185 Notice of Violation from inspec on 780829-01. \* Region 3, Chicago, Reactor Operations Nuclear Support Branth. 78/10/04. 2pp. 94038:210.
- --7811090189 IE Inspec Rept#50-315/78-24 & #50-316/78-22 on 780829-0901 during which 4 items of noncompliance were noted failure to process off site safety raview comm minutes & feilure to implement acceptable inevc pump test prog. REVES,L.A.; MABER,R.E., JABLONSRIF,J. Region 3, Chicago, Office of the Director. 78/10/04. Bpp. 94038:212.
- 7810240032 Forwards IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 77114-16 & 1214-15.20-21 during which no items of noncompliance were noted. HIND, J.A. Ragion 3. Chicago, Bafeguards Branch. 78/01/19, 200.

94480: 198.

- --7810240035 IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15.20-21 during which no Items of noncompliance ware noted. Ha yor areas inspected included security organization. barriers, access controls, detection aids CARLSON, D. M., MADEDA, T. J., HIND, J. A. Region 3, Chicago, Bafeguards Branch. 78/01/18. 1p.
- 7810270385 Forwards IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710.12.14.17.19-21.24. & 26-28.780809-10.14.16-18 & Rotice of Violation. FIDELLI.9. Region 3. Chicago, Reactor Operations Nuclear Support Page 78/19/21 Brench. 78/09/21 2pp. 94033 296
- --7810270398 IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710 during which I item of noncompliance was noted procedure for squip control was not implemented as required. allowing unglanned release of pertial contents of 2 gas decay tenks. BAKER.K. R. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 70/09/20. 9pp. 94033:299.
- 7810300375 Forwards IE Inspec Rept #50-315/78-26 & 50-316/78-25 on 780908-07 during which no items of noncomplaince were noted. DAVIB.A B. Region 3. Chicago, Safeguards Branch. 78/09/22. 2pp. 94199-343.
- --7810300383 IE Inspec Repts #50-315/78-26, 50-316/78-25 on 780906-07 during which no items of noncompliance were noted. Major erees inepected included: special confirmatory massurements Inspec & sample enalyses GREER R J. Region 3: Chicago: Bafeguards Branch. 78/09/21. App. 94199- 345.
- 7811020111 1E Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-06 ouring which no items of noncompliance were noted Major areas inspected included: action on previously identified litems re aperability of safety related snubbers.

  YIN.I.T., DANIELGON.D.H. Region 3. Chicago, Office of the Director. 78/09/25. Spp. 94331:083.
- 7810310335 Forwards IE Inspec Rept#50-316/78-24 on 780824-25 during which no I tems of noncompliance were noted.

  FIDRELLI.Q. Region 3. Chicago, Reector Operations Nuclear Support Brench. 78/09/26. 2pp. 94089:109
- --7810310340 1E Inspec Rept#50-316/78-24 on 780824-25 during which no items of nancompliance were noted. Major areas inspected included preaper test involving initial rise to 70% & 100% KOILER, J. E. Region 3. Chicago, Office of the Director. 78/09/26. 4pp. 94089; 111.
- 7811020105 Forwards IE Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-05 during which no litems of noncompliance were noted. #EIDMAN.R.F. Region 3. Chicego, Reactor Construction & Engineering Support Branch. 78/09/27. 2pp. 94331:081.
- 7811080101 Forwards IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no items of noncompliance were noted. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/02. 200. 94399: 084.
- --7811080104 IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no I tems of noncomplience were noted. Major eres inspected included: subj Pacil operating performance. FIORELLI.G., KEPPLER.J.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/14. 2pp. 94399:086.
- 7810110297 Ack receipt of 780911 itr informing NRC of steps taken to correct violetions noted in 780817 NRC itr. FIGNELLIA, Region 3: Chicago, Reactor Operations Nuclear Support Brench. 78/10/03. Ip. 03586: 083.
- 7811140185 Forwards IE Inspec Repts#50-315/78-28 & #50-316/78-28 on 780912-15 during which no items of noncompliance were noted.
  DAVIB.A.B. Region G. Chicago, Fuel Facility & Meterials Bafety
  Branch. 78/10/11. 2pp. 94384:263.
- --7811140189 IE Inepec Repts#50-315/78-28 & 50-316/78-28 on 780912-13 during which no items of noncompliance were noted Mejor areas inspected included redioactive waste systeffluent releases records & repts of effluents.

  BCHUMACHER, M. C. Region 3. Chicago, Fuel Facility & Materials
  Bafety Branch. 78/10/10. 7pp. 94384:265.
- 7810230356 Forwards IE Circular#78-17. (Bee AND: 7810230221 Docket KEPRER, J. O. Region 3. Chicago, Office of the Director. 78/10/13. 1p. 94167:001.

- 7811020160 Forwards replecement cover page for Insp Repts 50-315/78-30 & 50-316/78-28, on which signatures had been inedvertently REPPLER.J. G Region 3, Chicago. Office of the Director 78/10/13 2pp. 94334 343
- 7811090138 Responds to 780921 NRC ltr re violetion noted in Inspet Repts#50-319/78-25 & 50-316/78-23 Corrective action. the mod indicated in 780822 ltr will be completed by 781031 DOLAN J E. American Electric Power Co., Inc. 78/10/16. 2pp. 94399: 283
- 7812060388 Forwards IE Inspec Rept#50-315/78-29 & #50-316/78-27 on 780925-29 & Notice of Violation Natice of Violation w/held per 10CFR2 790(d) HIND.J A. Rejion J. Chicago, Befeguards Brench 78/10/29. 2pp. 94382-344
- --7812060391 IE Inspec Rspts#50-315/78-29 & #50-316/78-27 on 780925-29 during which 4 items of noncompliance were noted security organization, communications control detection wide & testing & maintenance. CREED, J.R., MADEDA, T.J., HIND, J.A. Branch. 78/10/20. 2pp. 94382:346. Region 3. Chicago: Safeguerds
- 7811210446 Responds to 781004 NRC itr re violations noted in Inspec Repts#50-315/78-24 & #50-316/78-22 Corrective actions: procedures rev to include requirements of Toch Spec 4.0 3 & 4.5 2 f. Inset procedure 12THP 4030. 8TP. 022 established. DOLANJE. American Electric Pawer Co., Inc. 78/10/27 App. 94490-100
- 7811150061 Forwards IE Circuler 78-18.
  KECPLER, J. O. Region 3. Chicego, Office of the Director 78/11/06
  1p. 94112: 232
- 7811200045 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inepec.
  FIORELLI.O. Region 3. Chicego. Reactor Operations Nuclear Support
  Branch. 78/11/09. ip. 94219.327.
- 7812130035 Forwarde IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780828-31, 780901, 11-15, 18, 20-22, 25-29, 1002 & 1004-06 & Notice of Violation. Region 3. Chicego, Office of the Director. 78/11/09. KEPPLER J Q 200. 94307.215.
- --7812130037 Notice of Violation from inspec on 780828-31.0901.0911-15 0918,09210-22,0925-29,1002 & 1004-06. Region 3, Chicago, Office of the Director. 78/11/09. 2pp. 94307-217
- --7812130045 IE Inspec Repts#50-319/78-27 & #50-316/78-31 on 780828-31 during which 2 itses of noncompliance were noted:Unit 2 RMST piping for low temp elem was blocked w/o approved & condition repts not promptly initiated for RO's.
  BAKER, K. R., MASSE, R. E., WARNICK, R. F. Region 3, Chicego, Office of
  the Director. 78/11/09. ISpp. 94307:218.
- 7812130206 Forwards 1E Inspec Rept#50-315/78-31 & #50-316/78-29 on 781010 during which no items of noncomplience were noted.
  HEIBHMAN,R.F. Region 3, Chicego, Office of the Director. 78/11/09. 2pp. 94306.066.
- --7812130209 IE Inspec Rept#50-315/78-31 & #50-316/78-29 on 781010 dur which no items of noncompliance were noted Major areas inspected inclilicenses action on IE Circular 478-08. LABLONSKI,F. J. Region 3, Chicego, Office of the Director. 78/11/09. Spp. 94306:068.
- 7812050311 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl AND 7811300055.
  KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/24. 1p. 94203:073.
- 7812050260 Forwards IE Bulletin#78-12a. suppl to IE Bulletin 78-12. W/encl ANO: 7811300055. PAPPAB: H. Region 3. Chicago, Office of the Director. 78/11/27. 2pp. 94202:142.
- 7812280047 Forwards 1E Bulletin 78-14.
  KEPPLER, J.O. Region 3, Chicago, Office of the Director. 78/12/19. 1P. 94084: 323.
- R. Periodic operating reports & related correspondence
- 7812110137 Forwards monthly repts for July. Aug & Sept 1978 re fish

- 7810200053 Forwards Monthly Oper Rept for Sept 1978. SKALLER, D. V. Indiena & Michigen Power Co. 78/10/10. ip. 94412:214.
- --7810200036 Monthly Oper Rept for Sept 1978. OILLETT, N. T. Indiana & Michigen Pawer Co 78/10/03. 10pp. 9412:215
- 7811210437 Forwards Monthly Oper Rept for Oct 1976. SHALLER, D. V. Indiena & Mithigen Power Co. 78/11/14. ip. 94482:194.
- --7811210438 Monthly Oper Rept for Oct 1978
  OLLETY, M.T. Indiene & Michigan Power Co. 78/11/01. Spp.
  94482:195.
- 7812200203 Forwards Manthly Oper Rept for Nov 1978.
  8HALLER, D. V. Indiana & Michigan Power Co. 78/12/14. ip-
- --7812200205 Monthly Oper Rept for Nov 1978.
  OILLETT, U.T. Indiana & Michigan Power Co. 78/12/04. 129p.
  9162-262
- S. Reportable occurrences. LERs & releted correspondence
- 7810180016 Forwards LERe78-064/03L-0.
  SHALLER, D. V. Indiana & Mithigan Power Co. 78/09/27. ip. 94422:001.
- --7810180018 LERe78-044/OIL-O on 780905: rod position indication for Rod C-9 showed deviation of greater that 12 staps from demand position. Caused by drift of signal conditioning module. Hodula recalibrated. RIBCHLING. J. Indiana & Michigan Power Co. 78/09/27. 2pp. 94422: 002.
- 7810100044 Forwards LER#78-065/03L-0 & 78-066/03L-0.
  8MALLER,D V Indians & Michigan Power Co. 78/09/29. 1p.
- --7810100064 LERB78-066/03L-0 on 780905: interlock on 650 ft level containment eir lock feiled to function during test, as interlock cells was too loose to operate locking mechanism. Tension edjustment was added to maintenance prog. BROWN.M. 8. Indiane & Michigan Power Co. 78/09/29. 1p. 94415: L64.
- --781010006B LERB78-065/03L-0 on 780901:viscosity of dissel lube oil wes low during routine check due to fuel oil contemination: for fuel oil injection pumps & I fusi Injectors were replaced.

  BROWN.H.S. Indiana & Michigan Power Co. 78/09/29. lp. 94415:165.
- 7810310199 LER #78-071/03L-0 on 780926: during surveillence test on containment hydrogen skimmer recirculation for(2HV-CEQ-1),46 ice condenser lower inlet doors opened, due to jammed actuator.

  RIBORLING, J. L. Indiene & Michigen Power Co. 78/10/26. 2pp.
- 7810110188 Forwards LERM78-067/03L-0 & LERM78-068/03L-0 
  8MALLER.D V. Indiene & Michigan Power Co. 78/10/03. ip. 94089:142
- 78i0180002 Forwards LER#78-067/03L-0 & LER#78-0&8/03L-0.
  8HALLER:D V. Indiana & Michigan Power Co. 78/10/03. 1p.
- --7810180004 LER#78-067/03L-0 on 780903: While in Mode 1 open condensate storage lavel reduced below limit of 175,000 gel due to closing of velve during leetegs check Level was returned to minimum requirements w/in 15 min from Unit 2 storage sys LEASE.R. 8. Indians & Michigan Power Co. 78/10/03. ip.
- --7810180005 LER#78-068/03L-0 on 780705: It was discovered that APDMB rounds off the T(2) calculation using interperarithmetic rather than real arithmetic w/resulting F2 calculations being non-conservative in top core. Engr rayles underseq. RISCNLING. J. Indiena & Michigan Pawer Co. 78/10/03. 2pp.
- 7810180027 Forwards LERe78-049/03L-0. & LERe78-070/03L-0. 8MALLER, D. V. Indiene & Michigen Power Co. 78/10/11. ip. 94168:192

- --7810180030 LERM7B-069/03L-0 on 780913 While performing surveillence test on protec set 4 pressurizer pressure high-resctor trip bistebie feiled to trip on simulated high pressure signal due to bed triec. Bisteble was replaced.

  RIBCH\_INO.J.L. Indiana & Michigan Power Co. 78/10/11. 1p. 94148 1973
- 7810180032 LERBYS-070/03L-0 on 780911: Air start line of 2AS diesel was found to be hot during load test due to loose piston bolt latting combustion vapors in air sterting line. Check vaive was replaced & engine retested satisfactoriiu.

  BROWN M.S. Indiana & Michigan Power Co. 780/10/11. ip. 94168: 194.
- 7810230177 Forwards LER#78-063/03L-1 & #78-072/03L-0. SHALLER.D.V. Indiana & Mithigan Power Cq. 78/10/18. 1p.
- --7810230183 LERM7B-072/03L-0 on 780926: During rapid load raduction fr 100X to 20X pur pressuriser press raduced below Tach Spec. Recovery w/m elioued time. Cause was rapid pur raduction. Tech Spec allows pur incress translent not detresse. LEASE.R.S. Indiana & Michigan Power Co. 78/10/18. ip. 94167:091.
- --7810230185 LERM78-063/03L-1 on 780820: While test closing turbins vei at 90% puristeem flow use reduced ceusing reactor content temp to increase & pur to decrease, both inviolation of Tech Spec dus to testing valve at too high pur level. LEASE.R.S. Indiana & Michigan Power Co. 78/10/18. lp. 94167: 090
- 7810270309 Forwards LERW78-073/03L-0 & LERW78-074/03L-0. SHALLER D. U. Indians & Mithless Power Co. 78/10/20. 1P. 94089: 092.
- --7810270314 LERM78-073/03L-0 on 780922: Automatic Control adjustment experienced pressure reduction below Tech Spac 3.2: 56/2220 PSIA)dus to error in interpretation of calibr procedure. Operator closed valve. Pressure returned to normal. LEASE.R. S. Indiana & Michigan Power Co. 78/10/20. 2FP. 94089:093.
- --7810310155 LER078-074/03L-0 on 780921: bistables returned to normal fitting position w/o dynamics of lase-leg portion of unit being calibrated. Caused by improper communications.
  RIBCH\_ING, J. Indiana & Michigan Power Co. 78/10/20. 2pp. 74089: 095.
- 7810310190 Forwards LER #78-071/03L-0 & #78-075/03L-0. SHALLER, D. V. Indiana & Michigan Power Co. 78/10/26. ip. 94090: 277.
- 7811020252 On 781030, it become necessary to labeleta deluga valves to feel! Drumming Room & New Fuel Receiving Area as result of repair on Fire Sya headers. Follow up rept will be issued 781010.

  BHALLER, D. V. Indiana & Michigan Power Co. 78/10/30. 1p. 94247:125.
- 7811090151 Forwards LER#78-076/03L-0 & LER#78-077/03L-0, BHALLER.D. V. Indiana & Michigan Power Co. 78/11/01. 1p. 94045:011.
- --7811090103 LERW78-076/03L-0 on 781003; surveillance tests on train-8 solid at protec sue showed that several switch positions were bad. Cowed by bed universal logic card. Card repleced & sys returned to syc.
  RISCHLING. J. Indiana & Michigan Power Co. 78/11/01. ip. 94043-012.
- --7811090158 LERN78-077/03L-0 on 781005:main turbine stop valves "C" & "D" closure limit switches found inoperable. Caused by excessive vibration of stop valves due to poor design. RISCH\_INO, J. Indiana & Michigan Power Co. 78/11/01. 1p. 94043:013.
- 7811140210 Forwards LERW28-034/03X-2.W78-078/03L-0 & W78-079/03L-0. SHALLER, D. V. Indiene & Michigen Power Co. 78/11/08. Ip. 94441: 355
- --7811140218 LERM78-034/03X-2 on 780515: hydrogen stimmer recirculation fame starting times were found to be 10 minutes-6 seconds for 24V-0602 % 10 minutes-5 seconds for 2-V-0602 % 10 minutes-5 seconds for 2-V-0602 % 10 minutes-6 seconds for 2-V-0602 % 10 minutes-78 tolerance for Unit 2 % agestate ere of 0-60 minute range. RIBCHLING. J. Indiena & Michigan Power Co. 78/11/08. 2pp. 94384:352.

7226 LER 78-034/031-0: on 78:010. menual isolation valve in flow circuit of turbine driven aux feed pump found unlocked in. Instructions issued to keep a manual valve in test closed & locked except when testing i.R. 9. Indiana & Michigan Power Co. 78/11/08 2pp.

200 LER 78-079/00L-0: on 78:019, engine failed to start while upting to prove operability of 2AD Emergency dissal in to remove 2CD diesel from svc. Cause for apparent lack is a could not be determined.

33.0.0 indiene & Michigan Power Co 78/11/08. 1p. 8: 356.

77 Forwards LERW78-080/03L-0.LERW78-081/03L-0.LERW78-082/03L-0. '8-083/03L-0. I-D. V. Indiana & Michigan Power Co. 78/11/22. 1p.

2181 LERWTS-080/OSL-O on 781024; during test of salid at protection A.3 logic test positions tested unsatisfactorily.
In the pailure of a universal logic card & a test card.
Subsequently replaced.
ANNT.P. Indiana & Michigan Power Co. 78/11/22. ip.
3.100.

185 LERM78-081/O3L-O on 781023 beron injection tank boron intration found to exceed Tach Bpsc limit Caused by in lack of effective mixing from a previous boric acid tion addition or by faulty sampling methods.

LPH. J. M. Indiana & Michigan Power Co 78/11/22. 2pp. 3:101

DISS LERWTS-082/OSL-O on 781025: during lask rate tast on the 650 alsovation airlock doors, noted that laskage rate ided acceptable limits. Caused by inadequate seal of floor. Switch indicator subsequently readjusted.

AN.T.P. Indiana & Michigan Power Co. 78/11/22. 2pp.

0193 LER#78-083/03L-0 on 781023: noted that cycling times for a operability test after meintenence not recorded when as stroked Caused by defective document control for ing changes to instructions.
4.R.S. Indiana & Michigan Power Co. 78/11/22. 1p. 3: 105

10 Confirms 78:128 verbal rept. While investigating cause of coming from upper containment apray header, 2 lower when t apray check valves were found installed rds. Rept will be submitted 78:12:2.
3.D. V. indiana & Michigan Power Co. 78/11/28. ip. 304

43

61 Forwards LERM78-084/03L-0 & M78-085/03L-0. 8.D. V. Indiene & Michigen Power Co. 78/12/01. 1p.

OO68 LERW78-085/OOL-O on 781106: during routine surveillence test ins driven auxiliary Feadwater pump did not start. Caused ener dlode which had shorted at electronic overspeed tor, resulting in constant overspeed trip signal.

\*AN.T.P. indiana & Michigan Power Co. 78/12/01, 1p. 7:349

0070 LERN78-084/03L-0 on 781101; rod H-8 rod position remained at steps after control bank D position reduced from 220 to steps. Caused by drift for H-8 signal conditioning is. Was reset to correct position.
-LING.J.L. indiana & Michigan Power Co. 78/12/01, 1p. 7:350.

86 Forwards LER#78-086/03L-0. 4,D. V. Indians & Michigan Power Co. 78/12/04. 1p. 785

0089 LER#78-086/03L-0 on 7807R3; snubber#63 was found to be rtsd on its horizontal exis during inspec due to loose and locknut. Snubber removad, testad & reinstallad. N.M.S. Indiana & Michigan Power Co. 78/12/04. ip. 8: 356.

19 Forwards LERM7B-087/03L-0 & M7B-08B/03L-0. R,D. V. Indiana & Michigan Power Co. 78/12/06. ip. 323.

0120 LERB78-087/03L-0 on 78:110: Containment Integrity was broken issassembling an NESH check valve while reactor plant was odd 3. Early start of repair has been reviewed by onnel to prevent future mistate.
5.6.8. Indians & Michigan Power Co. 78/12/06. 1p. 6:324.

- --7812080122 LER#78-088/03L-0 on 781125: One RHR sub-sys made inoperable w/reactor in Mode 2.less than 5X pur. due to essumption that plant was still in Mode 1 at greater that 5X pur. New safety sys unit start-up instructions issued.

  LEASE.R 9 Indiane & Michigan Power Co 78/12/06 ip. 94106.325.
- 7812120178 Forwards LER#78-089/03L-0 BHALLER, D. V. Indiana & Michigan Power Co. 78/12/07 ip. 74276: 359.
- --7812120186 LER878-089/03L-0 on 781109 emergency load reduction resulted in axial flux difference outside target band. Caused by loss of all generator bus duct cooling.

  RANDOLPH.J.M. Indiana & Michigan Power Co. 78/12/07. 1p. 94276: 360
- 7812180207 Forwards LER#78-090/01T-0. BNALLER.D. V. Indiana & Michigan Power Co. 78/12/12. 19. 94363:094.
- --7812180212 LERM78-090/017-0 on 781121: \(\omega/RHR\) in open-leakage was noted from some upper containment spray nozzles-caused by check valves CT8-1276 & CT8-1274 being installed backwards.
  RISCHLING.J.L. Indiena & Michigan Power Co. 78/12/12 3pp. 94363.055.
- 7812270252 Forwards LER#78-091/03L-0: #78-092/03L-0/: #78-093/03L-0: #78-094/03L-0: #78-095/03L-0: #78-095/03L-
- --7812270235 LER#78-091/03L-0 on 781125: source range neutron flux channal N-G1 inoperable. Caused by unclean connectors on high voltage cable & signel cable at preamp.
  R18CH\_INGLUE. Indiane & Michigan Power Co. 78/12/20 Ip. 94017:17f.
- --7812270260 LERM7B-092/03L-0 on 781125:reactor coolant average tamp on 2 of 4 loops below Tech Spacs of 541p-resulting in P-12 parmissive being actuated. Caused by turbine test w/minimum atsem dump, increase steem flow caused tamp drop. RANDOLPH.J.M. indiana & Michigan Power Co. 78/12/20. 1p. 94017:172.
- --7812270264 LERW78-093/03L-0 on 781125: rod position indication(RPI) for control rod H-8 exceeded 12 step limit. Caused by H-8 drift. RISCHLING. J. L. indiana & Michigan Power Co. 78/12/20. 1p. 94017: 172
- --7812270268 LERM78-094/03L-O on 781202: haion sys Por cable spraading area was discharged & therafore inoperable Caused by operator error.

  SMITH, J.K. Indiana & Michigan Power Co. 78/12/20. 1p. 24/17/17/4
- --7812270272 LERM78-095/03L-0 on 781206: while decreasing turbina load, reactor coolant avarage tamp asceaded 576.2 F. Caused by faulty drain valves on 5-A heater, creating unstable feadwater control & turbine load.

  MURPHY.C.E. inclane & Michigan Power Co. 78/12/20. 1p. 94017:175.
- --7812270277 LERN78-096/03L-0 on 781209: during rapid load reduction from 100% to 88% axial flux difference went outside target bend. Alt lask on "A" condenser vecuum breeker caused increase in back pressure on mein condenser.

  a Indiana & Michigan Power Co. 78/12/20. 1p. 94017:176.
- --7812270282 LER#78-097/02L-0 on 781209: during rapid per reduction from 100% to 88%, per pressurizer pressure reduced below tach spac limit of 2220psts. Caused by rapid per reduction because of decreasing vacuum on main turbins/generator.

  KEITH.R.B. Indians & Michigan Power Co. 78/12/20. ip. 94017:177.
- --7812270286 LER#78-098/03L-0 on 781010: axial flux differenca(AFD) monitoring alarm point was discovered to be set at 103% vice 84%. Caused by AFD elem trip point being refeed for testing purposes & not returned to correct point.

  BEILMAN.T.P. Indiane & Michigan Power Co. 78/12/20. 2pp. 94017:178.
- 7812290083 Confirms 781224 varbal rept re brief inoperability of control room pressurisation fans.due to Fire Protec logic preventing fans from starting.Followup rapt will be submitted 780106.
  BHALLER.D.V. Indiana & Michigan Power Co. 78/12/27. 1p. 94190:107.

- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POMER PLANT, UNIT 1
  F. Becurity, medical, emergency & fire protection plans
- 7810310271 Forwards Suppl 1 to Rev of Celvert Cliffs Modified Amended security plan re temporary security arrangement during constr of new ave bldg. Encl withheld from public disclosure (ref 10CFR2 790).

  LUNDVALL, A.E. Baltimore Gas & Electric Co. 78/10/17. 3pp. 94088.238
- 7010230162 Forwards addition of the protect study in response to 780830 ltr. Covers trasient combustibles, design besit fire methodology-conduits & covered cable trays & determination of burning rates.
  LUND/ALL.A E. Baltimore Que & Electric Cd. 78/10/20. 39pp. 94164:208
- 7811130375 Notifies of completion of review of temporary security arrangements to be established during construct one avoided. Changes do not decreese security & no action is required.

  OAITANIB; M.J. Reactor Sefety Branch (Pre 791030). 78/10/30. 1p. 74008:077.
- 7011120105 Responds to 781031 NRC request re requirements for non-co personnel access to fecility. Encis outline training requirements for antry to controlled eres & escurity requirements for admittance.

  LUNDVALL, A E Beitimore Gas & Electric Co. 78/11/01. 7pp. 94270:167
- 7811150189 Forwards captes of Rev 4 of Mod Amend Security Plan, including additions verbally requested by MJ Opitense & reflecting impending organizational changes. Info withheld pursuent to 2.790.

  LUNDVALL, A. E. Baltimore Ose & Electric Co. 78/11/06. ip. 94242:398.
- 78:11:70:197 Announces enother review of NRC guidelines re facil Fire Protec Prog will be performed because review may have been misleading. Nest response will be submitted no leter than 78:1229.

  LUND/ALL.A.E. Beltimore Gas & Electric Co. 78/11/14. 1p. 94040:294.
- 781R180265 Notification of 781R21 meeting in Bethesda w/BQEE re-fire protec review & instru cable fire retendant properties. CONNER.E.L. Operating Reactors Branch 4 (Pre 7906R5). 78/12/07. 3pp. 94366:346.
- P. Operating license stage documents & correspondence
- 78:1270166 Forwards "Chesapseke Bay LNO OPLAN." Piens establish procedures to ensure sefe errival fransit & departure of vessele carrying liquefied natural gas on Chesapseke Bey. SCHLMACHER, K. B., THOMPBON. C. R. Coast Quard. Transportation. Dept. of. 78/03/09. 42pp. 94223:207.
- 78:0250:43 Notifies NRC per iOCFR71.125 of intent to use packegs AN-1008(UBA/78097A) supplied by Hittman Nuc Day Corp for shipment of radiosctive matls.

  LUNDVALL, A. E. Beltmore Ges & Electric Co. 78/10/05. 1p.
- 7811030079 Requests edd1 info re radiat doss to control room operature following postulated LDCA. Ameignis of postulated event finds add1 info is req.
  REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/10. 3pp. 02703-330
- 7811010233 Notifies util of 781018 meeting to implementation of inti-Atomic Energy Agency Sefequends Requirements pursuant to proposed "Agreement Between the UBA & Inti Atomic Energy Agency for Appl of Sefeguends in the USA." REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/13. Spp. 94372:074.
- 7810230148 Forwards suppl & corrected data to be included in rapt on test conducted re-reactor containment bidg integrated leak rate.

  LUNDVALL, A.E. Baltimore Gas & Electric Co. 78/10/16. 4pp. 94164: 295.
- 7810260202 Responds to 780502 NRC 1tr re add1 info to complete review of amend request dtd 780727. Also forwards rept on containment tendon surveillance lift-off acceptance criteria which is basis for several responses to NRC questions. LUNDVALL, A. E. Baltimore Que & Electric Co. 78/10/20. Bipp.

- 7811170121 Requests 1 change & 1 addition to Svc 11st. DLSON.R.C. Baltimore Gos & Electric Co. 78/11/09. 1p. 94048.277.
- 7011200206 Requests amend to open lic tech space re:limiting maximum boron concentration in SIT's & RWT's to 2200ppm.ellow lesser shutdown concling flow when reactor coolant loop partially dreined. & add loss of field trip to DO survaillance. LUNDMAL, A. E. Daltimore Das & Electric Co. 78/11/13. 30pp. 94282, 043.
- 7Bi1840214 Remits Lic amend fas for Class 4 & Class 1 emend involving 11 proposed changes to oper lic. OLBON-R.C. Baitimore Gas & Electric Co. 7D/11/15. 1p. 94463:360.
- 7B12150106 Notice of workshops re implementation of training & qual requirements contained in Appand B of 10CFR7D. Requests pre-workshop registration of attendess to facilitate sending out metl. W/encl Registration Form & List of Locations.

  MILLER.J. R. Assistant Director for Site & Rafeguards (Pre 791030). 78/11/15. 5pp.
- 7812190008 Forwards Rev#i "Dreft Radiological Effluent Tech Specs" for PRR's(NUREG-0472)& "Preparetion of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREG-0133).

  ORIMES B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. App. 94214:266.
- 7811240183 Forwards response to NRC request for edd1 info re enalysis of potential radioactive dose to control room operators following loss-of-coolant accident.

  LUNDVALL.A. E. Baitimore Gas & Electric Co. 78/11/20. PRpp. 94438: 279
- 7811300046 Informs BOE that NRC has contracted w/Mountain West Res Inc to undertate a series of post-licensing studies of nuc pur stations. Studies will analyse socioacon impacts which occurred during constr & post-constr periods of each plant. DEYQUNO, R. C. Division of Bite Bafety & Environmental Analysis, 78/11/20. 2pp. 94071:049.
- 7BipO70161 Notice of seminar on 7BipO9 on new Model Radiological Effluent Yech Opecs for nuc pur plants. Requests advance submission of samitars specific questions. H/encl Gaminer Info Sheet Proposed Agende & meps. QRIER, B.H. Region i. Philedelphia, Office of the Director. 7G/11/21. Opp. 74375:166.
- 7812140379 Forwards discussion tuples for meeting to be held on 781219. Purpose of meeting is to obtain lnfo for use in "Reactor Bafsky Study Methodology Apple Prog" res proj. REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/28 6pp. 03558:120.
- 7812130293 Aske util to reexamine 780725 request for exemption from 100FR21 in 11ght of 781019 amond to Part 21. DENTON, N.R. Office of Nuclear Reactor Regulation, Director, 78/11/29, 2pp. 94294: 360.
- 7B12150079 Discusses possible dengers of LOCA in conteinment surging during normal plant oper. Requests either commitment to limit purging or justification for continuing Wienci ANO: 7B100B0207.
  REID.R.H. Operating Reactors Branch 4 (Pre 790625). 7B/11/29. 689.

94211:295.

- 7B122B0140 Emphasizes importence of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substentiated by deta & calculations. Licensee must notify NRC of any ineccuracies or enforcement action will result. DAVIB, J. 9. Office of Inspection & Enforcement, Office of the Director. 78/12/04. Rpp. 94310:352.
- 7819270384 Forwards into re forthcoming 781920 meeting to discuss fuel demonstration prog related to subj facils' transitions to 18 month cycles.

  CONNER. E. L. Operating Reactors Branch 4 (Pre 790625). 78/12/12.

  2pp. 94228:292.
- 781109006: Responds to 78073: Itr on Liquid Natural Gas Contingenty Plant spent fuel storage capacity & shallow water draft trials of LNO tankers. Wranci let from Coast Quard that mansuvers near facil will not be allowed w/gas.

  REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/10/18. 3°P. 94040:119.
- G. Inspection reports, IE Bulletins & correspondence

- -78:1080095 IE Inspec Repts#50-317/78-23,#50-318/78-17 on 780822-25 dwing which no items of noncompliance were noted. Major areas inspected included monthly oper status repts facility ture & implementation of 10CFR21 requirements.

  JCHNSON, D. F., KEIMIG.R.R. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/18. Spp. 94399:074.
- 7810170026 Forwards IE Bulletin878-12: "Atypical Weld Material in Reactor Pressure Vessei Helde" requesting action w/in 60 days & list of IE Bulletins issued in 1978. GRIER.8.H. Region i, Philedelphia, Office of the Director. 78/09/27. 6pp. 94241:352.
- 78|1060|88 Forwards IE Circular#78-17. (8ee AND: 7810230221, Docket #50-133, 781013.) GRIER.8, M. Region i, Philadelphia, Office of the Director. 78/10/13. 1p. 94489: (58.
- 7811090025 Ack receipt of itr informing NRC of steps taken to correct violations noted during inspec#30-317778-22 & w50-319778-16.

  MITH, 0. H. Region 1. Philadelphia. Fuel Facility & Materials Safety Stanch. 78/10/26. 1p. 94040:029.
- --7811090030 Responds to 780813 NRC ltr re violations noted in Inspec Repts850-317/78-22 & 50-318/78-16. Corrective actions: Rad-Chem technicians properly reinstructed: CCT-607B rev by 781201: air supply maint procedures written by 781101. LUNDVALLA E. Baltimore Cas & Electric Co. 78/11/08. 3pp. 94040; 030.
- --7811090032 Forwards IE Inspec Rept#30-317/78-22 & #50-318/78-16 on 780808-18 & Notice of Violation.
  CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Befety Brench. 78/09/13. 2pp. 94040:031.
- --7811090034 Notice of Violation from Inspec on 780808-11. CROCKER.H. M. Region I. Philadelphia, Fuel Facility & Meterials Bafety Branch. 78/09/13. 2pp. 94040:033.
- --781109003B lE Inepsc Rept#50-317/78-22 & #50-318/78-16 on 78080B-11 during which 3 ltems of noncompliance were notedirediat protec procedures:Procedures CT-6078 not incorp into training:NUREO-0041.Baction 9. B procedures I pnored HHITE. J. R. SERABIAN. J. A. KNAPP.P. J. Region 1. Philadelphia. Fuel Facility & Materials Befety Grench. 78/09/12, 11pp. 94040:035.
- 78:1140045 Requests that util prepara enswers to encl questions on insvetest prog for meeting on 78:108-09 at Calvert Cliffe. NO & formally document responses by 78:127. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/31. Gpp. 94420:326.
- 7812010345 Forwards licenses performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormal or unusual eafesty concern.
  ORIER, 8. H. Region 1, Philadelphia, Office of the Director.
  78/11/01. 4pp. 00002:259.
- 7811150265 Ack receipt of 781017 ltr Informing NRC of eteps taken to correct violations noted during inspec450-318/78-26 & #50-318/78-20.

  8RUNKER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Busport Branch. 78/11/02. 1p. 94273:229.
- ---7811150269 Responds to 781006 NRC itr re violation noted in Inspec Rept 80-317/78-26 & #50-318/78-20. Corrective actions: informing control room operators of requisite procedures.

  LUNDVALL.A.E. Beltimore Oes & Electric Co. 78/10/17. 2pp. 94273;230.
- -7811150272 Forwards IE Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 & Notice of Violation.
  BRUNNER, E.U. Region I. Philadeiphia, Resctor Operations Nuclear Support Branch. 78/10/06. 2pp. 94273:232.
- --7Bili50274 Notice of Violation from inepec on 780912-15. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 1p. 94273:234.
- ~~7811150276 IE inegec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 during which i item of noncompliance was noted; failure to comply w/limiting conditions for open.
  JONBON, D. F. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 12pp. 94273.235.
- 7811290220 Forwards IE Circular #78-18, "UL Firs Test. "W/encl ANO: 7811150002.

  ORIER, S. H. Region i, Philadelphia. Office of the Director. 78/11/06. ip. 94237: 298.

- 7B12010291 Ack receipt of 7B1017 itr informing NRC of steps taken to correct violation noted during inspec#50-317/78-25 & #30-318/78-19
  BRUNNER.E. J. Region i. Philadeiphie. Office of the Director. 7B/11/06. ip. 94417:266.
- --7612010295 Responds to 760928 NRC ltr re violations noted in Inspec Reptse50-317/78-25 & 850-318/78-29. Corrective actions: 218 Befety Injection Tank drained to epoc level & personnel reprimended. LUNDVALL, A.E. Beltimore Ges & Electric Co. 78/10/17. 2pp. 94417:247.
- --7812010295 Forwards IE Inspec Repts#50-317/78-25.#50-310/78-19 on 780905-08 & Notice of Violation. BRUNNER.E.J. Region i. Philadelphia. Office of the Director. 78/09/28. 2pp. 94417:269.
- --7812010298 Notice of Violation from inepec on 780905-08. \*\* Region i. Philadelphia, Office of the Director. 78/09/28. ip 94417:271.
- --7812010303 (E Inspec Reptem50-317/78-25 & #50-318/78-19 on 780905-08 during which 2 items of noncompliance were noted: Failure to conduct Type B tests w/in 2 years, failure to follow approved procedure HIGGINS, J. C. . MRITH.T. H. . WONG, H. J. Region 1, Philadelphia, Defice of the Director. 78/09/28. 12pp. 94417:272.
- 7812290028 Forwards 1E Inspec Repts850-317/78-30 & 50-318/78-27 on 781023-26 during which no items of noncompliance were noted. BRUNNER.E. J. Region 1. Philedelphia. Reactor Operations Nuclear Gupport Branch. 78/11/13. 2pp. 94208:040.
- --7812290034 1E Inspec Repte#50-317/78-30 & #50-318/78-27 on 781023-26 during which no items of noncompliance were noted. Major areas inspected incl-shift logs & records & licenses followup actions concerning previous inspec findings.

  JOHNBON, D.F., KEIMIO.R.R. Repion 1. Philadelphia. Office of the Director. 78/11/09. App. 94200:042.
- 7812110105 Responds to 1E BullstinW78-iR re resetor pressure vessel welds. Requests permission to deal w/problems on a generic rather than a plant specific basis.
  LUNDVALLA, E. Daltimore Qua & Electric Co. 70/11/17, 2pp. 94339-042
- 7812080125 Responds to 781031 & 761124 NRC itre requesting add1 info r pump & valve testing ineva progs. H/ancl overeits drawings available in Central Files only LUNDVALLA.E. Beltimore Gas & Electric Co. 78/11/20. 9pp. 94106:336.
- 7812130125 Forwards 1E Bulletin#78-1RA, suppl to IE Bullstin#70-12. Westl AND: 7811300055. GRIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/24. jp. 94212:189.
- 7012060242 Forwards IE Inspec Repts#50-317/78-29 & #50-318/70-26 on 780410-3 during which no items of moncompliance were noted. SMITH.Q.H. Region I. Philadelphia. Fuol Facility & Materials Safety Drench. 78/11/25. 2pp. 74372:340.
- --7812060244 IE Inspec Repts#50-317/78-29 & #30-310/78-26 on 780410-3 during which no items of noncompliance were noted Major areas inspected incl:effluent sample. KGTKM.J.J.: STOKKJ.J.P. Region i. Philadelphia. Fuel Facility & Materiele Sefety Branch. 78/10/24. App. 94372:342.
- 7812080096 Discusses ASME Boiler & Preseurs Vescel Code Requirements for Insve inspec of Nuc Components. Requirement for aiging examination is burdensome because extra teams must be utilized who will be unnecessarily exposed to redist. LUNDVALL, A. E. Baltimore Gas & Electric Co. 78/12/05. 2pp. 94107:296.
- R. Periodic operating reports & releted correspondence
- 7810230178 Forwards Honthly Oper Rept for Bept 1978.
  HERSON.B.D. Beitimore Gas & Electric Co. 78/10/15. 1p. 94164:10
- --7810230182 Monthly Oper Rept for Sept 1978.

  a Baltimore Gas & Electric Co. 78/10/15, 20pp. 94164:105.
- 7811240215 Forwards Honthly Oper Rept for Oct 1978.
  MERBON, S. D. Baltimora Gas & Electric Co. 78/11/15. Ip. 94473:33

- --7811240217 Monthly Oper Rept for Oct 1978.
  MERSON, 8 D. Bailtimare Cas & Electric Co. 78/11/15. 18pp.
- 7812220076 Forwards Monthly Open Rept for Nov 1978
  MERSON, B D. Galtimore Cas & Electric Co. 78/12/13. ip 94343.880
- --7012220077 Monthly Oper Rept for Nov 1978. MERBON, B. D. Baltimore Gas & Electric Co. 78/12/15. 18pp. 94342:281
- 8. Asportable occurrences. LERs & related correspondence
- 7810100051 Forwards LER#78-043/04T-0.
  DBUQLASS, R rt. Baltimore gas & Electric Co. 78/09/26. ip. 74032:170.
- --78i010005B LERM78-043/04T-0 on 780912 approximately 6200 Manidia (Atlantic silversides) were collected between 0900 & 1000 hours from U-1 travelling screens. Studies after 1000 hours did not reveal any unusual numbers of impinged fish.

  Bestimore Gas & Electric Co. 78/09/26. 3pp. 94032:171.
- 7810110167 Forwards LERW78-023/03L-0
  0000 A88,R M Baltimora Gas & Elsctric Co. 78/10/04. ip.
  940.84 093
- --TBI0110174 LERM7B-023/03L-0 on 780906: failure of containment atmosphere particulate monitor due to moisture from confensation & some corrosion: caused by high ambient containment humidity & subsequent condensation inside detactor plg. CARROLL, J. T., MJERNICKI, M. J. Baltimore Gas & Electric Co. 78/10/06 lp 94059:094
- 7810130173 Forwards LER#78-046/04L-0.
  BOUQ.ASS,R M. Baltimora Gas & Electric Co. 78/10/09. lp.
  94003-032.
- --7810130176 LERB78-046/04L-0 on 780908: redicactive liquid weste release rate arcseded 1,25 Curies par quarter on 780900 Change has been submitted to change Tech Byscs Bection 4.6.2c to requirements in Eaction 2.3 A 7.
  CRIN10AN.P T. Baltimora Gas & Electric Co. 78/09/12. ip. 94003-023
- 7810270235 Forwards LERW78-045/03L-0.
  D0UQLABB.R.M. Daitimore Oas & Electric Co. 78/10/20. ip. 94057: 003
- --7810270240 LERM78-045/03L-0 on 780926: Voltage deviated greater than 1.0 volts for channel 70 from other channels caused by nonlinear isolation transformer 1-E/E-1013A w/excessive A/C ripple & output voitage .2V high.

  DAVIB, 8 M. MIERNICKI, M.J. Beltimore Gas & Electric Co. 78/10/20.

  Typ. 94039:004
- 7810310102 Forwards LER#78-047/03L-0. DDUGLABB,R.H. Bajtimore Gas & Electric Co. 78/10/20 ip. 94092:134.
- --7810310108 LER 78-047/031-0: on 781010:13KV Breeker 252-2104 tripped open-de-energizing #21 12KV svc bus. Caused by signal of unknown source.

  DAVIE: 8. M. ROPINEY K. M. Beltimore 9es & Electric Co. 78/10/20.
  10. 94092:135.
- 7810310197 Forwards LER#78-044/03L-0.
  DOUGLABB.R.M. Beltimore Cas & Electric Co. 78/10/20. 1p.
  94090: 305.
- --7810310200 LERR78-044/03L-0 on 7809R3: during past-maint test on spent fuel pool 12.exhaust for the flow rate was found to be less then requdue to discharge damper leakage.

  DAVIS, 8. M. HERNICKI, M. J. Baltimore Oes & Electric Co. 78/10/20.

  Rpp. 94090: 306.
- 781 1010113 Forwards LER878-048/03L-0.
  DQVQLASS.R.M. Baltimore Qua & Electric Co. 78/10/25. ip. 74/28: 053.
- --7811010116 LER#78-048/03L-0 on 781017: while moving group 5 CEAs to control ASI. CEAS 4 dropped into core from full-out position. caused by spike in the 15 voit pur supply. Design modfFCR78-72) is under raview to improve sys reliability.

  DAVIS, S. H., MERRNICKI, H. J. Beltimore Oas & Electric Co. 78/10/26. Ip. 94288-054.

- 7811030112 Forwards LER#78-050/04L-0.
  DDUCLASS.R.M. Daltimore Cas & Electric Co. 78/10/27. 1p. 09723:315
- --7811030117 LERW78-050/04L-0 on 781023 stressive release of redirective liquid effluents caused by clogged streiner which put Miscellaneous Maste Filters & Ton Exchangers out of svc. CRINIOAN, P. T. Baltimore Que & Electric Co. 78/10/27, 1p. 02720, 316.
- 7811210407 Forwards LERM78-049/03L-0. RUBELLL B. Baltimore Oes & Electric Co. 78/11/16. 1p. 94483:121.
- --7811210409 LERW78-049/03L-0 on 781020 pump for radiat monitors seized, parhaps due to graphite particles from pump being deposited in bearings. A normal and of life failure Code Pump Model&6. DAVIS.8 M., MIERNICKI.M J. Bettimore Ges & Electric Co. 78/11/16. 19. 94483:122.
- 7811300194 Forwards LERM78-051/03L-0. RUSBELL. B. Daltimore Cas & Electric Co 78/11/17. 1p. 94074.340.
- --78i1300199 LERW78-051/03L-0 on 78i031: solanoid valva 1-8V-4043 for agia steam isolation valve hydraulic accumulators was leaking dus to failure of 1 of 4 "o" ring seals. Cause of ring failure unknown. Ali 4 saels replaced & valva returned to svc. DW16.8 M., WATKING.K. 8 Galtimure Gas & Electric Co. 78/t1/17. ip. 94076:361.
- 7811290264 Forwards LER#78-052/03L-0 RUSSELL-L.B. Baltimore Gas & Electric Co. 78/11/94. ip. 94270:101.
- ~-7811290267 LERR78-052/03L-0 on 781103: in routine survailiance test, is auxiliary feed pump was tripped per procedure & oper was unable to reset throttle vaive due to binding. Assembly was freed upon lubrication of stem & nut DAV18.8.M., RDHNEY.K.M. Deltimore Cas & Electric Co. 78/11/24. 1p. 94270: 102.
- 7812:30189 Forwards LER#78-053/001-0. RUSEKLU.L.B. Saltimore Oas & Electric Co. 78/12/07. ip. 94308:022.
- --7812130194 LERA78-053/03L-0 on 781113; during normal oper the containment particulate radiosttivity monitor failed low at 1110. Caused by disconnection of signal cable to monitor. Cable connected & monitor returned to 8vc. GARROLL, J.T., MIERNICKI, M.J. Daltimora Cas & Electric Co. 78/12/07. 19. 94306: 023
- 781220026: LER#78-084/Oix-O on 78:213: reactor was made critical w/il component cooling hast exchanger out of exc to it seltwater sub-eys partially drained. Caused by parsonnel error. CARROLL J. T. Baltimore Gas & Electric Co. 78/12/14. 1p. 74207:093.
- DOCKET 30-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT & F. Security, medical, emergency & fire protection plans
- 7811170197 Announces another review of NRC guidelines re-facil firs Protec Prog will be parformed because review may have been misleading. Next response will be submitted no later than 781229. LUNDYALL, A. E. Deltimore Cas & Electric Co. 78/11/14. 1p. 94046:294.
- 78:03:027: Forwards Suppl i to Rsv of Celvert Cliffs Modified Amended escurity plan re temporary security arrangement during constr of new svc bldg. Encl withheld from public disclosure (ref 10CFR2, 790).

  LUNDVALL, A. E. Deltimore Cas & Electric Co. 78/10/17. 3pp. 74088: 239.
- 7810230162 Forwards add1 info re fire protec study in response to 780800 ltr. Covers traslent combustibles, design basis fire methodology, conduits & covered cable trays & determination of burning rates.
  LUNDYALL, A. E. Beltimore Oes & Electric Co. 78/10/20. 39pp-94164-208
- 7811130375 Notifies of completion of review of temporary security arrangements to be established during construct now evoluted. Changes do not decrease security & no action is required.

  QAITANIB.H.J. Resctor Safety Branch (Pre 791030). 78/10/30. 19-

- 7811130153 Responds to 781031 NRC request re requirements for non-copersonnel access to facility Encls outline training requirements for entry to controlled area & security requirements for admittance.

  LUNDVALL. A. E. Baltimore Gas & Electric Co. 78/11/01. 7pp. 94270:167.
- 7811170187 Forwards copies of Rev 4 of Mod Amend Security Planincluding additions verbally requested by MJ Gattanae & reflecting impansing organizational changes. Info withheld pursuant to 2.790. LUNDVALL-A. E. Beltimors Oas & Electric Co. 78/11/06. 1p. q4242:338.
- 7812180265 Notification of 781221 meeting in Betheade w/80%E re fire protec review & Instru cabls fire retardant properties. CONER.E.L. Operating Reactors Branch 4 (Pre 790625). 78/12/07. 3pp. 94365:346.
- P. Operating license stega documenta & correspondence
- 7811170121 Requests 1 change & 1 addition to Bvc list. OLSON.R.C. Baltimore Gee & Electric Co. 78/11/09. ip. 94048:277.
- 7811270166 Forwards "Chasapeeks Bay LNG OPLAN." Plans satablish procedures to ensure sefs errival transit & departure of vessels.carrying liquefied natural gas on Chasapeeks Bay. SCHMACHER.K B., THOMPSON.C.R Coast Guard, Transportation, Dapt. of, 78/03/09. 42pp. 94223:207.
- 7810250143 Notifies NRC per 10CFR71.12b of intent to use packags AN-1008(USA/9809/A)supplied by Hittmen Nuc Day Corp for ahigment of redicactive matis. LUNDALL, A. E. Beitimore Cas & Electric Co. 78/10/05. ip.
- 7810170162 Forwards non-proprietary responses to questions raised in itr from NRC of 780908 rs reload appl.

  ODREJ.M. Beltimora Oas & Electric Co. 78/10/06. ip. 94236:214.
- 7811030079 Requests edd1 info re radiet dose to control room operators following postuleted LOCA Analysis of postuleted event finds edd1 info is req. REID.R.M. Operating Reactors Brench 4 (Pre 790625). 78/10/10. 3pp. 02723:332.
- 781:010233 Notifies util of 78:018 meeting re implementation of Intl Atomic Energy Agency Safeguerds Requirements pursuent to proposed "Agreement Batween the USA & Intl Atomic Energy Agency for Appl of Befaguerds in the USA."
  REID.R.M. Operating Reactors Branch 4 (Pre 790625), 78/10/13, 2pp. 94392:074.
- 7810180073 Forwards supplementary into re Cycla 2 Reload Appl. Encl contains proprietery into & is w/held. LUNDYALL. A. E. Seltimore Ges & Electric Co. 78/10/16. 48pp.
- 7810230246 Enc1 suppl info & changes to reload appl requested in 781013 NRC ltr.
  LUNDVALL.A.E. Saltimore Gas & Electric Co. 78/10/17. 3pp.
- 7811030076 Forwards AmendWiB to Facil Open LicMDPR-69 revising Tach Space as requested in 780726 ltm w/Bafety Evaluation & Notice of Issuance. REID.R.W. Openating Reactors Branch 4 (Pre 790625). 78/10/21. 3pp. 02721:008.
- ~-7811030080 Amend#18 to Feril Oper Lic#OPR-69 revising Tech Specs re: Incorp changes resulting from enalyses of Cycls 2 reload fust, & authorizing removal of sli part length control element assemblies. REID.R.W. Operating Reacture Branch 4 (Pra 790625). 78/10/21, 58pp. 02721:011.
- --7811030085 Sefsty evaluation supporting Amend 18 to License DPR-69.

   Operating Reactors Branch 4 (Pre 790625). 78/10/21. 30pp.
- --7811030088 Notice of Issuance of Amend#18 to Facil Oper Lic#DPR-69 on 781021.
  REID.R. M. Operating Reactors Branch 4 (Pre 790625). 78/10/21.
  200.
- 7811200206 Requests amend to oper lic tech specs re: limiting maximum boron concentration in SIT's & RMT's to 2200ppm.sllow lesser shutdown cooling flow when reactor cooling loop pertially drained, & add loss of field trip to DG surveillance. LUNDVALLA. 5. Seltimore Gas & Electric Co. 76/11/13. 30pp. 74282-045.

- 7Bi12402i4 Remits Lic amend fee for Class 4 & Class 1 4mend involving 11 proposed changes to oper lic.
  GLEGN.RC Gattimore Gas & Ejectric Co. 78/11/15 1p. 94463:360.
- 7812150106 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFA73. Requests pre-workshop registration of attendees to facilitate sending out mati. H/enci Registration Form & List of Locations. HILLER.J.R. Assistent Director for Bite & Refeguards (Pre 791030). 78/11/15. 5pp.
- 7812190008 Forwards RsvM1 "Draft Radiological Effluent Tech Specs" for PMR's(NUREO-0472)& "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) GRIMES, R.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:266
- 7811240183 Forwards response to NRC request for add1 info re analysis of potential radioactive dose to control room operators following loss-of-coolent accident
  LUND/ALL, A.E. Baltimore Oes & Electric Co. 78/11/20. #2pp.
  94458: 279.
- 781:300046 Informs BGE that NRC has contracted w/Mountain Heat Res Inc to undertake a series of post-licensing studies of nuc pur stetions. Studies will analyse socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNG.R.C. Division of Sits Safety & Environmental Analysis. 78/11/20 2pp. 94071:049.
- 7812070161 Notice of seminar on 781208 on new Hodel Radiological Effluent Tach Space for nuc per plants. Raquasta advance submission of seminar specific questions. W/ancl Baminar Info Bheat. Proposed Aganda & maps GRIER, B. H. Ragion i. Philadeiphia, Office of the Director. 78/11/21 Spp. 94375:168.
- 7812140379 Forwards discussion topics for masting to be held on 781212. Purpose of meeting is to obtain info for use in "Reactor Bafaty Study Hothodology Apple Prog" rea proj. REID.R.M. Operating Reactors Granth 4 (Prs 790625). 78/11/28. 6pp. 03558:128.
- 7812130293 Asks util to restamine 780725 request for exemption from 10CFR21 in light of 781019 amend to Part 21. DENTON.H.R. Defice of Nuclear Reactor Regulation, Director. 78/11/29. 2pp. 94294:360.
- 7812150079 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either townitment to limit purging or justification for continuing. W/enc1 AND: 7812080207.
  REID.R.W Dperating Reactors Branch 4 (Pre 790625). 78/11/29. Spp. 94211:295.
- 7812280140 Emphasize importance of submitting accurate & complete infe to NRC by licensess & epplicents. Info submitted must be substentiated by deta & calculations. Licenses must notify NRC of any inaccuracise or snforcement action will result. DAVIB.U.Q. Defice of inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:332.
- 7812270354 Forwards into re forthcoming 781220 meeting to discuss fusl demonstration prog related to subj facile' transitions to 18 month cycles.

  CONER.E.L. Operating Reactors Branch 4 (Pre 790625). 78/12/12.

  2pp. 94228:292.
- 781109006: Responds to 78073: Itr on Liquid Natural Gas Contingancy Plan. spant fus! storage capacity & shallow water draft trials of LNQ tankara W/encl itr from Coast Quard that maneuvers neer facil will not be allowed w/ges.
  REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/10/18. 3PP 94040:119.
- Q. Inspection reports. IE Bulletins & correspondence
- 7812010291 Ack receipt of 781017 ltr informing NRC of steps taken to correct violation noted during inspec#50-317/78-25 & #50-019/78-19.
  BRUNNER,E.J. Region 1, Philadelphia, Office of the Director. 78/11/06. ip. 94417:266.
- --781201029A Forwards IE Inspec Repte#50-317/78-25,#50-318/78-19 on 780905-08 & Notice of Violation. BRUNNER,E.J. Region 1, Philadelphia, Office of the Director. 78/09/28. 2pp. 94417:269.
- --781201029B Notice of Violation from inspec on 780905-08.

  Region i, Philadelphia, Office of the Director. 78/09/28. ip. 94417:271.

- 761,0010303 IE Inspec Repts#50-317/78-25 & #30-318/78-19 on 780905-08 during which 2 items of noncompliance were noted failure to conduct Type B tests win 2 years failure to follow approved procedure #HIGGING, J.C. & MITH, T. H., WONG, H.J. Region 1. Philadelphia. Office of the Director. 78/09/20 12pp. 94417.272
- 7812080095 Discusses ASME Boiler & Pressure Vessel Code Requirements for Insve Inspec of Nuc Components Requirement for piping examination is burdensome because eithe teams must be utilized who will be unnecessantly exposed to radiat LUNDVALL.A E. Reltimore Gas & Electric Co. 78/12/05 2pp 94107 296
- 7812080125 Responds to 781031 & 761124 NRC ltrs requesting addl info re pump & valve tasting insvc progs. Wentl oversize drawings available in Central Files only LUNDVALL, A. E. Baltimore Gas & Electric Co. 78/11/20 9pp. 94106: 336
- 7812110105 Responds to IE Bulletin#78-12 ra reactor pressurs veses1 walds. Requests permission to deal w/problems on a generic rather than a plant epecific desis.

  LUNDYALL, A. E. Baltimore Gas & Electric Co 78/11/17. 2pp. 94339: 062.
- 7811090091 Forwards IE Inspec Repts#50-317/78-23.#50-318/78-17 on 780822-25 during which he items of noncompliance were noted.

  8RUNNER, E. J. Region is Philadelphia: Reactor Operations Nuclear

  Bupport Branch. 78/09/20 2pp 94399-072
- --7811080096 IE Inspec Reptem50-317/78-23.#50-318/78-17 on 780822-25 during which no items of nancompliance were noted. Major areas inspected included monthly open status repts/fecility tours & implementation of IOCFR21 requirements JOHNSON.D F., KCIMIO.R R. Region I. Philadalphia, Reactor Operations Nuclear Support Branch 78/09/18. 5pp. 94399:074.
- 7810170026 Forwards IE Bulletin#78-12. "Atypical Wald Material In Reactor Pressure Vassel Welds" requesting action with 60 days & list of IS Gullstine Issued in 1978. ORIER & H. Region 1. Philadelphia, Office of the Director. 78/09/29. 6pp. 94241 332
- 7811050188 Forwards 1E Circular#78~17. (8ss ANO: 7810230221, Docket #50-133, 781013 ) ORIEN, B. H. Ragion is Philadalphia, Office of the Director 70/10/13. 1p. 94489 158
- 7811090025 Ack receipt of itr informing NRC of steps taken to correct violations noted during Inspect30-317/78-22 & #50-318/78-16. BMITH. 0 H. Region I. Philadelphia. Fuel Facility & Materials Bafety Branch. 78/10/25 ip. 94040:029.
- --7811090030 Responds to 780813 NRC itr ra violations noted in Inspec Repts#50-317/78-22 & 50-318/78-16 Corrective actions: Red-Chem tachnicians properly reinstructed/CCI-6078 ray by 781201nair supply maint procedures written by 781101. LWNOVALL, A.E. Baltimore Gas & Electric Co. 78/11/08. 3pp. 94040: 030.
- --78:1090032 Forwards 1E Inspec Rept#50-317/78-22 & #50-318/78-16 on 780808-18 & Notice of Violation. CROCKER, H. W. Region I. Philadelphia. Fuel Facility & Hateriels Barety Branch. 78/09/13. 2pp. 94040:031.
- --7811090034 Notice of Viciation from inspec on 780808-il. CROCKER, H. M. Region I, Philadelphia. Fuel Facility & Materials Befety Branch. 78/09/13. 2pp. 94040:033.
- --781109003B IE Inspec Rept#50-317/78-22 & #50-318/78-16 on 78080B-11 during which 3 items of noncompliance were noted; radiat protec procedures: Procedure CCI-A078 not incorp into training: NUREQ-0041. Section 9.8 procedures ignored. WHITE, J. R., SERABIAN. J. A., KNAPP. P. J. Region 1. Philadelphia. Fuel Facility & Materials Sefety Branch. 78/09/12 11pp. 94040:035.
- 7811140045 Requests that util prepare ensuers to encl questions on insvc test prog for meeting on 781108-09 at Calvert Cliffs. MD & formally document responses by 781127. REID.R.H. Operating Reactors Branch 4 (Pre 790525). 78/10/31, Spp. 94420:326.
- 7812010345 Forwards licensee performance evaluation for Region 1. No operating reactor in Region 1 considered to here either abnormal or unusual safety concern. ORIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/01. 4pp. 00002:259.

correct violations noted during inspec#50-317/78-26 & #50-318/78-20 BRUNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/02. 1p. 94273:229.

7811150265 Act receipt of 781017 ltr informing NRC of

- --7811150269 Responds to 781006 NRC itr re violation noted in Inspec Rep #50-317/78-26 & #50-318/78-20. Corrective actions: informing control room operators of requisite procedures. LUNDVALL, A.E. Beltimore Gas & Electric Co. 78/10/17. 2pp. 94273: 230
- --781i150272 Forwards IE Inspec Rept#30-317/78-26 & #50-318/78-20 on 760912-16 & Notice of Violetion.
  BRUNNER,E J Region 1. Philadsiphia, Reactor Operations Nuclear Support Branch. 78/10/06. 2pp. 94273:232.
- --7811130274 Notice of Violation from inspec on 780912-15. BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/06. 1p. 94273:234.
- --7811150276 IE Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 during which I itam of noncompliance was noted; failure to comply w/limiting conditions for oper.
  JCHNSON, D. F. Region I. Philadelphie, Rector Operations Nuclear Support Branch 78/10/06, 12pp. 94273:205.
- 7811290220 Forwards JE Circular #78-18, "UL Fira Test. "W/encl ANO: 7811150002. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 78/11/06 1p. 94237: 298
- 7812280313 Forwards IE Inapec Rept#50-318/78-22 on 780925-29 & 1017-18 during which no itsms of noncompitance were noted. CARLBON, R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch, 78/11/09. 2pp. 94082:049.
- --7812280319 IE Inspec Rept#30-318/78-22 on 780925-29 & 1017-18 during which no itsms of noncompliance were noted. Major areas inspected incl:Steem Generator Inspec Prog & Inspec Inspec (IBI)Activities.
  MCBREARTY,R A , EBNETER, S.D. Ragion I. Philadelphia, Office of the Director 78/11/07. 8pp. 94082;031
- 7812290028 Forwards IE Inspec Rapts#50-317/78-30 & 50-318/78-27 on 781023-26 during which no Items of noncompliance were noted. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94208:040.
- --7812290034 IE Inspsc Repts#50-317/78-30 & #50-319/78-27 on 781023-26 during which no items of noncompliance were noted. Major areas inspected incl: shift logs & records & licenses followup actions concarning pravious inspec findings JOHNSON, D. F., KEIMIG, R. R. Region i, Philadelphie, Office of the Director 78/11/09. opp. 94208:042.
- 7812130125 Forwards IE Bulletin#78-12A. suppl to IE Bulletin#78-12. H/enc1 AND: 7811300055. GRIER. B H. Region 1. Philadelphia. Office of the Director. 78/11/24. ip. 94212:159.
- 7812060242 Forwards 1E Inspec Repts#50-317/78-29 & #50-318/78-26 on 780410-3 during which no ltems of noncompliance were noted. BMITH.9.H. Region I. Philadelphia. Fuel Facility & Materials Bafety Branch. 78/11/25. 2pp. 94372:340.
- --7812060244 IE Inspec Repts#50-317/78-29 & #50-318/78-26 on 780410-3 during which no Items of noncompliance were noted. Major areas inspected incl:affluent sample.
  KOTTAN, J. J., BIOHR, J. P. Region I. Philadelphia, fuel Facility & Materials Gafety Branch. 78/10/24. 4pp. 94372:342.
- R. Periodic operating reports & related correspondence
- 7810230178 Forwards Monthly Oper Rept for Sapt 1978.
  MERBON, B. D. Baltimora Gas & Electric Co. 78/10/15. 1p. 94164: 104.
- --7810230182 Monthly Oper Rept for Sept 1978.

  \* Baltimore 9as & Electric Co. 78/10/15. 20pp. 94164:105.
- 7812220076 Forwards Monthly Oper Rept for Nov 1978.
  MERBON, B. D. Beltimore Gas & Electric Co. 78/12/15. Ip. 94343:280.
- --7812220077 Monthly Oper Rept for Nov 1978.
  MERSON, 8, D. Beltimore Qas & Electric Co. 78/12/15. 18pp. 94343: 281.

- 8. Reportable occurrences, LERs & related correspondence
- 7810310209 Forwards LER878-033/03L-0. DOUGLASS R M. Baitimore Gas & Electric Co. 78/10/20. 1p. 94090:318
- --7810310216 LER 78-033/03L-0 on 780924: while filling refueling pool from refueling water tank an RAS actuated & tripped both LPSI pumps, dus to poor calibr of Sigma instr level indicator 2-L1-4143.

  CARROLL, J. T., ROMNEY, K. M. Baltimore Qas & Electric Co. 78/10/20.

  1p. 94090, 319.
- 7811130166 LERM78-036/01X-0 on 781023: during inspec of steam generator isolation signal logic.21 main steam isolation valves failed to shot when gives 8018A & 8018B signal. Cause undstarmined.

  DAVIS.8 M. Baltimors Gas & Electric Co. 78/10/24. Ip. 94087: 359.
- 78:10:60103 LER#78-038/01X-0 on 78:1025: containment air lock inner door ramained open for 4 days. Caused by misonderstanding between shift supervisor & maintenance personnes.

  CARROLLL J Baltimore Gas & Electric Co. 78/10/31. 2pp. 94424:203
- 7811060155 Forwards LERM78-035/01T-0.
  00UGLABS.R.M. Baltimore Gas & Electric Co. 78/10/31. 1p. 94499:074.
- --7811060161 LERB78-035/01T-0 on 781017: air binding of LPBI pumps resulted when air being used to transfer purification system is aked into the SDC Sys. Oper instruct ere being rev. CARROLL. J. T. Beltimore Gas & Electric Co. 78/10/31. ip. 94489: 075
- 7811130211 Forwards LERM78-034/03L-0. DDUCLABB.R.M. Baitimore Gas & Electric Co. 78/11/02. 1p. 03554:033.
- --781130214 LERR78-034/021-0 on 781023: in Mode 3 at 500F,12 main steam safety valve relief set points were outside tolerances of TB 4.7. Liell were adjusted & satpoints returned to spec. DAV16.8. M. MIERNICKI.M. J. Beltimore Ges & Electric Co. 78/11/02. ip. 03504:034.
- 7811140164 Forwards LER#78-036/01T-0 DOUGLABB,R.M. Baltimore Gas & Electric Co. 78/11/02. ip. 94380:314.
- --781140170 LERM78-036/01T-0 on 781023; during routine test of steam generator legation signal logic, 21 main steam isolation valve failed to shut upon 801BA & 801BB signal or hand switch in Control Room.due to atticking MSIV solenoid valves.

  DAVIS. B. M. J. WATKINB, K. B. Beltimore Gas & Electric Co. 78/11/02. 2pp. 74083; 315.
- 7811170165 Forwards LER#78-037/03L-0.
  RUSEKLI-L. B. Baitimore Gas & Electric Co. 78/11/10. 1p. 94047-353
- --7811170171 LERA78-037/03L-0 on 781025: during oper, reactor protect instruwide range logarithmic neutron flux monitor Channel A read 2 decades lower than other Channels, due to connector, for Channel A not being dried completely when recently cleaned, DAVIS, B. M. , ROMNEY, K. M. Beltimore Ges & Electric Co. 78/11/10. 200.
- 7811170179 Forwards LERW78-038/017-0.
  RUBEELL-L.B. Reltimore Oes & Electric Co. 78/11/13. ip. 94134:033.
- --7811170187 LEAW78-038/01t-0 on 781025:during LPPT in Mode 2, containment air lock was opened to repair failed opsi machanism & was kept ajar-dus to misunderstanding between supervisor & maintenance personnel All personnel have been reinstructed. CARROLL, J., ROMNEY, K. Baltimore Cas & Electric Co. 78/11/13. 2pp. 94048:135.
- 7811300211 Forwards LERW78-041/03L-0 RUBEELL-L.B. Baltimore Gas & Electric Co. 78/11/24. 1p. 94075-217.
- ---78:1300223 LER#78-041/03L-0 on 78:113:RWT level discovered to be at 455 inches. Caused by Rad-Chem technician's failure to fully close local sample vaive after drawing routine sample. Technician has been reinstructed in valve sampling. DWIB.S.M. Beltimore Oas & Electric Co. 78/11/24, 1p. 94075-218.

- 7812130170 Forwards LER#78-039/03L-0 RUBBELLL, B Baltimore Gas & Electric Co 78/12/07. 1p. 94294:335
- --7812130174 LERM78-039/03L-0 on 781113 during normal open periodic winventory balance indicated that unidentified reactor coolent leakage was i 72 gpm at 0500. Leak identified as crecked wsid.

  CARROLL, J.T., WATKINS.K. B. Baltimore Oas & Electric Co. 78/12/0 ip. 94294:336.
- 7812130183 Forwarde LER#78-043/03L-0
  RUSEELL B. Beitimore 9es & Electric Co. 78/12/07 ip. 94303 Asi
- --7812130187 LER 78-043/03L-0 on 781126 during monthly surveillance to CEA 3 dropped to bottom of core at 0049. Pur reduced to 70% per Tech Space until CEA 3 was restored to its group position at 0158.
  CARROLL, J. T., Miernicki, M. J. Baltimora Gas & Electric Co. 78/12/07. ip. 943081362.
- 7812260244 Forwards LERM78-040/03L-0 RUSELLL B. Baitimory Gas & Electric Co. 78/12/14. 1p 94197: 349
- --7812260248 LER#78-040/03L-0 on 781117:#5 halon sub-sys discharged w door to 22 inverter was open. Caused by thermal detactor being overly sensitive to rate of rise of temp. When door opened.internal eirflow disturbed.setting off detactor. CARROLL, 17., MIERNICKI.M.J. Baltimore Ges & Eiertric Co. 78/12/14. 19. 94159:330.
- DOCKET 50-320 THREE MILE IBLAND NUCLEAR STATION. UNIT 2
  F. Security, medical. emergency & fire protection plans
- 78ii270135 Forwards Revision 4 to physical security plan. Withheld (re 10CFR2.790). HERBEIN J. Q. Mstropolitan Edison Co. 78/11/17. 1p. 94253:339.
- Q. Adjudicatory correspondence
- 7810140104 Recommends that 781117 be set as new filling deadline, as a result of add inquiries posed in 780915 order. CHANDLER,L.J. Office of the Executive Legal Director. 78/10/04. lp. 94421:344.
- 7810200034 Requests extension until 781117 to file suppl testimony on aircresh probability analysis, due to difficulty in obtaining data & witness.

  TROMERIDGE, G. F. Bhaw, Pittman, Potts & Trowbridge, 78/10/04, 2pp 94367
- 7810240046 Extends time for the filling of prepared testimony on the airplane crash probability issue until 781117. DUFLO.M.E. Atomic Sefety and Licensing Appeal Pensi. 78/10/10 2pp. 00001:229.
- 7811010342 Forwards order for mod of license which amends DPR-73 & supersedes order for mod of license 6td 780526. VARQA, B.A. Light Hater Reactors Branch 4. 78/10/13. 3pp. 94391-072
- --7811010368 Order for mod of license amending DPR-73 & superseding 780526 order Adds provision limiting reactor core power level to 2772 MHt. BOYO.R. 8. Division of Project Hanagement. 78/10/13. App. 94391:080.
- 7812050090 Forwards recent NRC mamos re problems associated w/pips support base plate design which apply to facility.
  MCGURREN,H.J. Office of the Executive Legal Director. 79/11/14 9pp. 94335:292
- 7812040264 Motion for extension of time for filin 781130. Certificate of Svc enci. CHANDLER:L.J. Office of the Executive Legal Di App. 94129:332.
- 7812130375 Forwards portion of NRC testimony re d Carrier creshes & creek info for heavy military CHANDLER,L.J. Office of the Executive Legal Di 84pp. 94292:18B.

20D. 74436 167

- 7812130000 Act receipt of ASLAS 781121 order scheduling evidentiary hearing on aircraft crash probability lesus at 9:00am.Monday 781211
  - CHANDLER, L J Difice of the Esecutive Legal Director 78/11/22 94294: 284 ip.
- 7812210456 Act receipt of 781121 order scheduling evidentiary hearing on 781211 on plane cresh probability Both respondent & AJ Helaberd will represent applicants. TROUBRIDGE, Q.F. Shew, Pittman, Potts & Troubridge. 78/11/29. Ip. 94168-027
- 78:12270030 Forwards NRC testimony re aircraft creshes pertaining to facility Forwards tables re aircraft accidents
  CHANDLER, L. J. Office of the Esecutive Legal Director 78/11/30. 86pp. 00007.147.
- --7812270033 Forwards data requested for preparation of testimony before ABLAB re military aircraft Forwards info to C-5A aircraft be aircraft mishaps retes per 100,000 hours of flying. 78/08/02 6pp. 00007:232 NASH-E J Air Force-Dept. of
- --7912270040 NRC testimony ra US air carrier & military accident & 00007: 280
- --7812270052 Forwards testimony re aircraft crashes covering a real crash density at TMI-2 & off-runway creek probabilities MCORE.R., ABRAMSON,L. Office of Management and Program Analysis. 78/11/30. 16pp. 00007-324.
- -- 7812270056 Evaluation of aircraft cresh potential for nuclear power plants. EIBENHUT.O O 0 Q Assistant Birector for Systems Engineering (Pre 78/11/30. 21pp. 00007:341 7910301
- 7812130217 Meno & order re ALAB-309. Any party who disagrees w/ASLAB approach re radon emissions should file brief within 45 DUFLO.M.E. Atomic Safety and Licensing Appeal Panel. 78/12/01. 11pp. 94306: 087.
- 7812180307 Responds to 781121 ASLAB order & informs that NRC will be represented at forthcoming hearing on aircraft crash issue by SA Treby & RL Black. CHANDLER, L.J. Office of the Executive Legal Director. 78/12/01. ip. 94356:181.
- 7812220141 Notice of eppearance of AJ Weisbard on behalf of util. Certificate of Byc enci. HE169ARD, A. J. Shaw, Pittman, Potts & Trombridge. 78/12/05. 3pp. 94249:067.
- 7812270360 Forwards professional qualifications of NRC witnesses & "Table of Effective Aircraft impact Tanget Area" inavertently omitted from NRC testimony on 781130. CHANDLER, L. J. Office of the Elecutive Lagal Director. 78/12/05. CHANDLER, L. J. 04 2049. 94232:333.
- 7812270366 Forwards revised page to testimony of J Read, et a) on 781130. & errate sheet to testimony of R Moore & L Abramson. BLACK,R.L. Diffice of the Executive Legal Director. 78/12/06. 4pp. 94229:017.
- 7812270114 Notices of appearance for RL Black-SA Treby & JF Scinto on behalf of NRC. Certificate of Svc encl.
  BLACK,R.L. Office of the Essentive Legal Director. TREBY.S.A., SCINTO-J.F. Hearings Division. 78/12/08: 3pp. 00008:016.
- 7812280314 Forwards Table 4 Revision E. providing info re weather conditions prevailing at time of accident shown on Table 4, type of radar & causative factors. CHANDLER.L.J. Office of the Executive Lagal Director. 78/12/08. 20pp. 94082:039.
- H. General correspondence
- 78:2190112 Bosing has delivered forty 727-200s to THA: fourteen are of 191.000 1b gross text weight, witsheaff weight of 190.500 1b & landing weight of 154.500 1b.

  WHEELER.J. R. Bosing Co. 78/12/0b. 1p. 94381:201.

- 7812120092 Advises that Generation Licensing Section (Production Bupervision) moved back to Pottsville Pike location on 781213 Forwards new telephone numbers. HERBEIN, J. O. Metropolitan Edison Co. 78/12/12. 1p. 94274: 204.
- J. Insurance & indomnity information
- 7811060092 Forwards copy of Endorsement 1 to NELIA Binder E8-65.
  MDREAU.W.N. General Public Utilities GPU Service Corp. 78/10/30.
  2pp. 94424:142.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7811090048 Forwards Amend 66 to F8AR. Certificate of Byc encl. HERBEIN, J. Q. Metropolitan Edison Co. 78/11/08. 3pp. 00001: 276.
- --7811090054 Amend &6 to FBAR Metropolitan Edison Co. 78/11/08. 175pp. 00001:279.
- P. Operating license stage documents & correspondence
- 7810260147 Forwards C-141 & E-4A info re destroyed aircraft, flying hours sorties. & landings 1968-Jul 1978 in response to NRC 780920 1tr. Air Force, Dept. of. 78/10/02. 1p. 94055: 330. CREWBE. R. O
- 7810100046 Unit 2 will install feedweter sys mod prior to startup following plant first refueling outage Requests opportunity to meet u/NRC 781019. HERBEIN. J. G. Matropolitan Edison Co. 78/10/04. 1p. 94032:178.
- 7810180132 Responds to NRC 780804 questions re operability of containment purge valves in the event thay are open at the time of a LUCA.

  MERBEIN J. Q. Matropolitan Edison Co. 78/10/13. 2pp. 944 Matropolitan Edison Co. 78/10/13. 2pp. 94413:009.
- 7810310305 Notification of 781019 meeting w/util re details of steam BILVER.H. Light Weter Reactors Branch 4. 78/10/16. 1p. 94089:090.
- 7810240097 in response to 780918 phone call util will submit Tech Spac change request requiring implementation of interim corrective action for single suciliary transformer.
  HERBEIN.J. Q. Matropolitan Edison Co. 78/10/17. 2pp. 00001:233.
- 7810240119 Forwards NPDES Noncompliance Notification 78-22 re waste fifter sus discharge sample with pH in excess of permit limitation. TROFFER. Q. J. Metropolitan Edison Co. 78/10/17. 2pp. 00001:235.
- 7811010246 Notification of 781026 meeting w/util re aircraft crash data BILVER.H. Light Water Reactors Branch 4. 78/10/19. ip. 00001:251.
- 7810240120 In view of new Burns & Ros analysis, util will defeat automatic transfer feature when loading on 4160 volt buses exceeds 19 MW. Modifies 780929 commitment. HERBEIN, J. Q. Matropolitan Edison Co. 78/10/20, 2pp. 00001:937.
- 7810300157 Appointment of new licensing mgr for OPU Svc Corp.
  HALLACE,E. Q. general Public Utilities OPU Service Corp. 78/10/23.
  1p. 94035:117.
- 7811090114 Forwards responses to NRC 780508 ltr ra steem line break & anviron qualification of electrical components. FSAR pages & anviron qualification test repts ancl.
  HGRBEIN.J. G. Metropolitan Edison Co. 78/10/31. 600pp. 94042:291.
- 7811030174 Forwards data requested for preparation of testimony before ABLAS, info on gross weight of sircraft & active ruhway is unavailable.
  - NASH E.J. Air Force, Dept. of. 78/11/03. 2pp. 02784:072.
- 7811140172 Forwards Tech Spac Change Request 16. Certificate of Byc & affidavit. HERBEIN, J. C. Matropolitan Edison Co. 78/11/06. Spp. 94384: 229.
- 78) 1150161 Ramits fee for NRC review of Tech Spec Change Request 16 re auxiliary transformer operation.
  HERBEIN. J. Q. Metropolitan Edison Co. 78/11/09. 1p. 94273:002.

- 7811290343 Notification of 781122 meeting w/util to discuss proposed mods to eliminate need for prompt ection in responding to small break LCGA worst single failure.
  ZMSTZIO. 0. B. Operating Reactors Branch 4 (Pre 790623). 78/11/17
  - 94193: 351.
- 7811300037 Informs that NRC has contracted to undertake a series of post-licensing studies to analyze socioeconomic impacts of nuclear plent const. DEYQUNO.R.C. Division of Site Safety & Environmental Analysis. 78/11/20. 2pp. 00002:234.
- 7811240110 Forwards proposed small break LOCA long-term mod NRC 780926 ltr did not respond to 780724 util proposel & util believes proposal meets NRC requirements HERBEIN, J. Q. Metropolitan Edison Co. 78/11/21, 6pp. 94456:275.
- 7812070194 Notice of seminar on 781208 on new model radiological effluent Tech Spece for nuclear plents. Requests advance submission of saminer-specific questions.

  ORIER.B.H. Region 1. Philadelphia, Office of the Director.
- ORIER, B. H. Region 1, Phila 78/11/21 Spp 94375:069.
- 7812080244 Summery of a 781026 mosting re alreraft crash data at TMI-2 BILVER,H Light Hater Reactors Branch 4. 78/11/21. 5pp. 94137:168.
- 7812070203 Forwards summary of 781019 meeting on feedwater isolation HERBEIN, J. O. Metropolitan Edison Co. 78/12/04. 1p. 94375.131.
- --7812070206 Summary of 781019 meeting in Bethesde, MD to reach agreement on feedwater isoletion sys:conceptual design.design criteria & conformence to Condition C(3)1. # Metropolitan Edison Co 78/12/04. 20pp. 94379.132
- 7812130109 Summery of 781019 mapting w/util & Burns & Roe on steam line break fix Discussed conditions of TM1-2 license, feedwater isolation valves & Type C test.
  BILVER.H. Light Weter Reactors Branch 4. 78/12/04. 2ipp. 94295:309.
- 7812180187 Forwards Tech Spec Change Request 18 requesting amend rereactor coolent pumps HERBEIN, J. O. Metropolitan Edison Co. 78/12/11, App. 94366:002.
- 7812280049 Summary of 781122 meeting w/util in Sethesde.MD re util revised proposed mod to eliminate reliance on operator action following small breek LOCA List of attendage &
  - proposed mechanical mods encl.
    ZMETZIG.G.B. Operating Reactors Branch 4 (Pre 790625). 78/12/12. 10pp. 00008,042
- 7812190096 Forwards edd1 info re TM1-2 Tech Spec Changs Request 10. Amend 1. Changes involve restructuring format in RCB/flow reactor power level entries. HERBEIN.J. Q. Metropolitan Edison Co. 78/12/13. 5pp. 94376:318.
- 78:12290:31 Provides addi info re steam line break environ qualifications. W/revised pages containing environ test parameters for Aneconde Instrument cable & Test Rept F-C2933 HERBEIN, J. G. Metropoliten Edison Co. 78/12/14, 42pp. 94190:216.
- G. Inspection reports, IE Bulletine & correspondence
- 7811090284 Forwards IE Insp Rept 50-320/78-28 on 780905-07. No noncompliance noted.

  RRUNNER.E. J. Region 1. Philadelphia, Dffice of the Director.
  78/09/21. 2pp. 00002:131.
- --7811090290 IE Inep Rept 50-320/78-28 on 780905-07 No noncompliance noted. Major areas inspected; safety injection sys reset feature & LERs.
  HAVERKAMP, D. R. Region 1, Philadelphia, Office of the Director, 78/09/18. Spp. GOGO2:133.
- 7810160230 Forwards IE Bullstin 78-12, "Atypical Weld Matl in Reactor Pressure Vessel Walds." Licenses action required. W/o encl. QRIER. B. H. Region 1. Philadelphia. Office of the Director. 78/09/29. 6pp. 94471:302.
- 7810180221 Ack receipt of 780918 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/78-24. ORIER.8.H. Region i, Philadelphia, Office of the Director. 78/10/03. 1p. 94412:241.

- ~-7810190001 Responds to NRC 780824 ltr re-violations noted in 16 Insp. Rept 30-320/78-24 Corrective actions holding/storage oven repaired, weld rod returned to oven to remove addi hydrogen, HERBEIN, J. G. Metropolitan Edison Co. 78/09/18. 2pp. 94412: 242
- ~~7810190005 Forwards 1E Insp Rept 30-320/78-24 on 780718-21 & 0731-0803 & notice of violation. BRUNNER.E J. Region 2 BRUNNER, E.J. Region 2, Atlente, Reector Operations Nuclear Support Branch. 78/08/24 2pp. 94412:244
- ~-7810190006 Notice of violation from insp on 780718-21 & 0731-0803 HAVERNAMP, D.R. Region i. Philedelphia. Reactor Operations Nucleor Bupport Branch. FABANO.A.N. DURR. J.P. Region i. Philadelphia. Office of the Director. 78/08/24. 1. 94412:246.
- --7810190007 1E Insp Rept 50-320/78-24 on 780718-21 & 0731-0803 Noncompliance noted: failure to maintein weld rod storage oven et required temp. oven at required temp.

  AWYERKAMP, D.R. Region i, Philadelphia, Reactor Operations Nuclear Support Brench. FASANO, A.N., DURR, J. P. Region 1, Philadelphia, Office of the Director. 78/08/23. 22pp. 94412:247.
- 7811060185 Forwards IE Circular 78-17. Wo enci. ORIER.B.H. Region i. Philadelphia. Office of the Director. 78/10/13. 1p. 00001:265.
- 7812010280 Forwards 1E Inap Rept 50-320/78-29 on 780914-15 & 19-22. No noncompliance noted. BRUNNER.E.J. Region i, Philadelphie, Reactor Operations Nuclear Bupport Brench. 78/10/18. 2pp. 94417:232.
- --7812010282 IE lnsp Rept 50-320/78-29 on 780914-15,19-22. No noncompliance noted. Major arms inspected: preoperational & startup test results & power ascension test.

  HAVERKAMP, D.R., COLEMAN, H. E., BETTENHAUSEN, L. Region 1,

  Philadelphia, Office of the Director. 78/10/18. 15pp. 94417:234.
- 7812010336 Forwards IE lnap Rept 50-320/78-30 on 781004-06. No
- noncompliance noted. BRUNNER,E. J. Region 1, Philedelphia, Reactor Operations Nuclear Support Brench. 78/10/20 2pp. 94418: 184.
- --7812010338 1E 1mmp Rept 50-320/78-30 on 781004-06. No noncompliance noted. Major erees inspected: limiting conditions for operation & control of design changes. HAVERKAMP, D. R., KEHDE, D. V. Region 1. Philadelphia. Office of the Director. 78/10/19. Spp. 94418:186.
- 7811290324 Forwards 1E Inspec Rept#50-346/78-27 on 780905-05 during which no items of noncompliance were noted.
  FIDRELLIO. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/25. 2pp. 94193:300.
- --7811290326 1E Inspec Rept#50-346/78-27 on 780905-08 during which no Items of noncompliance were noted. Major arees inspected inci:inspec of selected stertup test performed during Cycls TB pur exceletion testing.
  CRESHELL, J. 8, Region 3, Chicego, Dffice of the Director.
  78/10/24. 5pp. 94193:302.
- 7812010345 Forwards licenses performence evaluation for Region 1. No operating reactor in Region 1 considered to have either Abnormed or unusual safety concern.

  ORIER.B.H. Region is Philedelphia: Office of the Director.
  78/11/91. 4pp. 00002:259.
- 7811290199 Forwards JE Circular 78-18, "UL Fire Test."

  ORIER.B.H. Ragion i, Philadelphia, Office of the Director, 78/11/06. ip. 00002: 226.
- 7812270047 Forwards IE Insp Rept 50-289/78-18 & 50-320/78-31 on 781006, 10-12 & 17-19 & notice of violation.

  BMITH.9.H. Region 1. Philadelphia, Fuel Facility & Materials Sefety Brench. 78/11/21. 3pp. 00007:362.
- --7812270051 Notice of violation from inep on 781006,10-12 & 17-19.
   Region 1, Philedelphie, Office of the Director. 78/11/21. 2pp.
- 00007: 002. --7812270057 IE Insp Rept 50-289/78-18 & 50-320/78-31 on 781006,10-12 &
- 17-19, Noncompliance noted: fallure to barricade high redistion area or maintain records of effluent sampling. PRUMLER, K. E., BERABIAN, J. A. Region j. Philadelphia, Office of the Director. 78/11/15. 12pp. 00008.004. 7812150144 Forwards IE Bulletin 78-12A. "Atypical Weld Matl in Reactor
  - Pressure Vessel Helds, "

- 7819290116 Forwards corrected page of Table D-1 to "Inservice Insp Program Pumpe." M/justification as Attachment A. HERBEIN.J. O. Hetropolitan Edison Co. 78/12/13. 3pp. 94082:319.
- R. Periodic operating reports & related correspondence
- 7810170147 Forwards monthly operating rapt for Bapt 1978. HERBEIN, J. Q. Matropolitan Edison Co. 78/10/10. ip. 94236:077.
- --7810170148 Monthly operating rept for Sept 1978. LENGELIR. A Metropolitan Edison Co. 78/10/09. 4pp. 94236:078.
- 76:12:0380 Farwards monthly operating rapt for Oct 1978 & corrected "Unit Shutdown & Power Reductions" page for Spet rapt. HERBEIN. J. G. Metropolitan Edison Co. 78/11/15. 1p. 94483:156.
- --7811210384 Monthly Operating rept For Oct 1978 & corrected "Unit Bhutdown & Power Reductions" page for Sept rept. LENGEL.R.A. Metropolitan Edison Co. 78/11/15. 5pp. 94485:157.
- 7812190132 Forwards monthly operating rept for Nov 1978. MERDEIN, J. Q. Matropolitan Edison Co. 78/12/15. ip. 94340:348.
- --7812190134 Monthly operating rept for Nov 1978. HARDING, L. W. Metropolitan Edison Co. 78/12/15. Spp. 94340:349.
- 8. Reportable occurrences. LERs & related correspondence
- 7810100088 Forwarde LER 78-053/03L-0 HERBEIN, J. G. Metropolitan Edison Co. 78/09/26 ip. 94033:172.
- --7810100095 LER 78-053/03L on 780831: safety injection channel "C" did not trip when pressure was reduced below 1640 pei. Caused by fallure of bi-stable.
  LENGEL,R.A. Metropolitan Edison Co. 78/09/26. 1p. 94033:173.
- 7810100076 Forwards LER 78-054/03L-0.

  MERBEIN, J. O. Matropolitan Edison Co. 78/09/27. ip. 94032:238.
- --7810100080 LER 78-054/03L-0 on 780907: while in Mode 5, determined containment grade suitches torque switch & motor. Caused by purchasing error. LENGEL.R.A. Metropolitan Edison Co. 78/09/27, 2pp. 94032:239.
- 7810180165 Forwards LER 78-057/03L-0.
  HERBEIN.J. Q. Metropolitan Edison Co. 78/09/29. 1p. 94317:094.
- --7810180169 LER 78-057/03L-O on 780830: during maint on ramets ehutdown display patch panel, patch power supply was grounded, causing lose of display instruments.

  4 Matropolitan Edison Co. 78/09/29. ip. 94317:095.
- 78i0110092 Forwards LER 78-059/03i-0.
  HERBEIN.J. Q. Metropolitan Edison Co. 78/10/02, 1p. 94063:350.
- --7810110083 LER 78-059/03L-0 on 780908: Driginal boited connections on containment isolation values MU-V2A/8 not taped properly caused by personnal arror during construction.

  LENGEL-R. A. Matropolitan Edison Co. 78/10/02. ip. 94063: 351.
- 7810110130 Forwards LER 78-058/03L-0. HERBEIN.J. G. Metropolitan Edison Co. 78/10/04, ip. 94378:359.
- --7810110134 LER 78-058/03L-O on 780908: containment isolation valve MDL V1125 failed to close on manual initiation test signal. Ballayed event caused by dirty control relay contact. LENGEL.R. A. Matropolitan Edison Co. 78/10/04. jp. 94378:360.
- 7810180171 Forwards LER 78-055/03L-0. HERBEIN.J. G. Metropolitan Edison Co. 78/10/05. 1p. 94317:100.
- --7810180174 LER 78-055/021-0 on 780913: damper 4092-0 failed to respond to close eignal caused by drawing misinterpretation.

  \* Matropolitan Edison Co. 78/10/05. 1p. 94317:101.
- 7810240125 Forwards LER 78-060/03L-0. HERBEIN, J. O. Metropolitan Edison Co. 78/10/13. 1p. 00001:239.
- --7810240129 LER 78-060/03L-0 on 780915: trip setpoint of reactor bldg pressure switch 88-78-3987 was . Ol psig greater than allowed. Caused by setpoint drift.
  8TAIR.J. R. Metropoliten Edison Co. 78/10/13. 1p. 00001:240.

- 7810240131 Forwards LER 78-056/03L-0.
  HERBEIN, J. Q. Hetropolitan Edison Co. 78/10/16. ip. 90001:2
- --7810240134 LER 78-056/03L-0 on 780917: while in Mode 2 & pulling roots to increase power, asymmetric plarm was activated. Caused by improperly operating rase switch.
  GTAIR.J. R. Matropolitan Edison Co. 78/10/16. 1p. 00001: 20
- 7811090247 Confirms RD 78-62/IP on 781019:Action B for T. S. 3. 4. 6. not invoked when surveillance 2301-301 showed unidentified issage over 1 gpm. Causand by personnel arror.
  BEELINGER, J. L. Metropolitan Edison Co. 78/10/19. ip. 00002:
- 7811090171 Forwards LER 78-062/017-0.
  HERBEIN, J. O. Metropolitan Edison Co. 78/11/01. Ip. 94038:41
- ---7811090174 LER 78-062/017-0 on 781019: misinterpretation of Tec lad to increased fraguancy of performance of surveillance procedura, causing laskaga iimits to appear excessive. STAIR.J. R. Metropoliten Edison Co. 78/ii/OI. 3pp. 94038:
- 78i1090274 Forwarde LER 78-061/03L-0. HERBEIN.J. Q. Matropolitan Edison Co. 78/11/01 1p. 00002:1
- 7811210332 Forwards LER 78-066/03L-0.

  MERBEIN, J. Q. Metropolitan Edison Co. 78/11/15. 1p. 94484:3
- --7811210336 LER 78-066/03L-0 on 781014; control rod drivé trip biclosed w/only one source range datector operable. Causad by inoparabla power supply for one eource range channel. LENGEL.R.A. Matropolitan Edison Co. 78/11/15. 2pp. 94484
- 7812050171 Forwards LER 78-053/03L-0.
  HERBEIN, J. O. Matropolitan Edison Co. 78/11/28. 1p. 94382:0
- --7812060177 LER 78-063/03L-0 on 781029; during shutdown-ratchet Group 5 control rods occurred. Caused by incorract installation of field change in three gate drive modules. LDMGL.R.A. Hetropolitan Edison Co. 78/11/28. 1p. 94382:
- 781210278 Notifies NRC of a reportable occurrence discovered at meeting between facil & Babcock & Wilcox. Station procedure EP-1202. 26 directed operator to take action that kept Steam Generator from going up to 120".
  MURRAY-T.D. Tolado Edison Co. 78/11/28. ip. 94213:249.
- 7812130195 Forwards LER 78-064/03L-0.
  HERBEIN, J. Q. Metropolitan Edieon Co. 78/12/04. 1P. 94306:0
- ---78i2130197 LER 78-064/03L-O on 78ii07; borated water storage ta switches siceeded Tach Spec limit. Caused by switches out of calibr. LENGELIR.A. Metropolitan Edison Co. 78/12/04. ip. 94306;
- 7812200275 Forwards LER 78-067/03L-0. HERBEIN, J. G. Metropolitan Edison Co. 78/12/11. 1p. 94207:1
- --7812200278 LER 78-067/03L-0 on 781112: fuses blaw in bettery ch 2-2A & 2-28. Caused by defective gating filter module in each bettery charger. BTAIR, J. R. Metropolitan Edison Co. 78/12/11. 2pp. 94207:
- 78i2290093 Confirms RO 78-7i/IP on 7Bi208:control logic discrapa existed for make-up (HPI) pumps.
  KUNDER, Q. A. Hetropolitan Edison Co. 78/12/11. 1p. 94190:11
- 7812260259 Forwards LER 78-068/03L-0. HERBEIN, J. Q. Metropolitan Edison Co. 78/12/13. ip. 94159:3
- --7812260261 LER 78-068/03L-O on 781113: noted that 12 diesei gen load sequence timers' setpoints were outside Tech Spac limits. Caused by sepoint drift. 8TAIR.J. R. Metropolitan Edison Co. 78/12/13. IP. 94159: 3
- T. Hearing transcripts on non-antitrust matters
- 7812200331 Transcript of 781212 avidentiary hearing before ABLAS Includes questions on takeoff & landing speeds.Pp 224-320. # Atomic Bafety and Licensing Appeal Panel. 78/12/12, 450pp 00003:105.

- DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1
  F. Security, medical, emergency & fire protection plans
- 7810100039 Forwards Amend 8 to Fire Protection Rept for operating lice DPR-57 & NPF-5. Hill TREP. C. F. Georgie Power Co. 78/09/21. 2pp. 94033:050.
- --7810100045 Amend 8 to Fire Protec Prog Rept for subj fecil.
  Contains rev to show rooms prior to Amend 4.
  \* Georgia Power Co. 78/09/21. 17pp.
- 7811030043 Ack 781011 phone conversation with Gillespie 10CFR2.790(d) exempts from pub disclosure activities involving safeguards & security measures & enci will not be pieced in PDR.W/out encl.
  KENNA.M.S. Region 2. Atlante. Sefeguards Branch. 78/10/24. 2pp. 02721:336.
- 7811220200 Responds to 780727 ltr forwarding Rev 2 to Emergency Plan: Rev 2 is acceptable, inesmuches it merely consists of aditorial changes to previously approved Plan. Incl Rev 1. IPPOLITO.T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/26. 2pp.
- 78ii280223 Forwards rev. "Shutdown from Outside Control Room. "procedures which are applicable to commitment contained in sval of fire protec prog.

  HHITMER.C. F. Georgie Power Co. 78/ii/i6 36pp. 940i2:093
- O. Adjudicatory correspondence
- 7Bi0140146 Notice of Issuance of Amend#60 to Fecii/Oper Lic #DPR-57 on 781004 re facii mod for firs protec. IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/04. 2pp. 94421:162.
- J. Insurance & indemnity information
- 7811170205 Requests Transmittel of 5 signed originals of Amand 10 to Indemnity Agreement 8-69 to replace first 5 which were lost in transit.

  WHITMER.C.F. Georgie Power Co. 78/11/19. ip. 94048:297.
- P. Operating license stage documents & correspondence
- 7Bi1010062 Mods into in 7B0322 ltr to NRC, which responded to 1E Bulletin # 78-03. Requests extension until 781231 for commitment to develop procedures for handling conditions which threaten integrity of off-gas sys.

  BTAFFA.R.W. Georgie Power Co. 7B/10/02. 1p. 94302:334.
- 7811130093 Submits add1 info to mod 770613 ltr re response to infraction 1, A, 2, 781031 extension will be necessary to install hardwere & perform functional tests to equiparlocks.
  8TAFFA.R. W. Georgia Power Co. 78/10/02. 1p. 94113:275.
- 78:014005: Sefety Evaluation supporting Amand #40 to Facil Oper Lic #DPR-57 concluding that the probability of disruptive fires is small & mode to improve fire resistance capability for fire doors dampers, fire barriers are acceptable. • Commissioners. 78/05/16. Sipp. 9442::101.
- 7Bi0140046 Forwards Amend M60 to Facil Oper Lic MDPR-57 rev Tech 8pec w/8afety Evaluation & Notice of Issuance. IPPCLITO.T. A Operating Reactors Branch 3 (Pre 790625). 7B/10/04. 2pp. 94421:097.
- ---7810140049 Amend 860 to Facil Oper Lic 8DPR-57 revising Tech Specs re limiting conditions for oper & surveillence requirements for existing fire protec sys & admin controls of subj facil IPPOLITIO.1.A. Operating Reactors Branch 3 (Pre 790625), 78/10/04. 2pp. 94421:099.
- --7810140053 Notice of Issuence of Amend #60 to Facil Oper Lic #DPR-57 on 781004.
  IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/04.
  Pps.
- 7810160104 Responds to draft Append I model Tech Specs issued by NRC on 780711 & forwards mark-up of sections of draft NUREQ-0473, WHITMER, C. F. Georgia Power Co. 78/10/06. 76pp. 94234:131.

- 7810240iiO Proposes amend to Tech Spec for Oper Lick#DPR-57, substituting Core Maximum Fraction of Limiting Pur Density for Maximum Tatal Peaking Factor in determining Average Pur Range Monitor scram & rod block trip settings.

  HHITMER, C. F. Osorgia Power Co 78/10/18 12pp.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Duniers Group re-progress of Long Term Prog w/attendance list & agenda(RD-9-A-Mark), Standards. ) GRIMES, C. Pient Systems Branch (Pre 791030). 78/10/26 67pp
- 7812260154 Forwards Reactor Containment Bldg Integrated Leak Rate Test for subj facil.
  MANRYM, Georgia Power Co. 78/11/07. ip. 94144:277.
- --7812260136 "Resector Containment Bidg integrated Leakage Rate Test."

  Type A & suppl verification tests performed in accordance w/tech space using formules from ANBI N45.4-1972 & BN-Top-1.

  Rev 1.

  MANRY.M. Georgie Power Co. 78/06/30. 70pp. 94144:278.
- 7811200409 Forwards results of measurements of radioactive matl in NRC phantom on whole body counter. Enci 1 contains actual amount of sech radionucide present-enci 2 gives ratio of measurements to DDE values & enci 3 gives recommendations. BUTHERLAND.J. T. Region 2. Attanta. Fuel Facility & Materials Safety Brench. 78/11/09. Spp. 94419:311.
- 7811210297 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effiuent Tech Space & encl seminar info sheet, registration form, & proposed agenda. O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 78/11/09. 5pp. 94488:131
- 7811300066 Forwards NRC staff paper.Policy Bession item(8ECY-78-554) relicenses reg performance evaluation. Three methods for evaluation ere: statistical trend analysis & regional survey method. H/o enci.

  O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 78/11/15.
  200.
- 78i2i30i64 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attenders to facilities sending out bath. Whenc? Registration Form & List of Locations.
  MILLERIJ. R. Assistant Director for Site & Bafeguards (Pre 79i030), 78/11/13. 3pp.
- 7812180277 Forwards RavW1 "Draft Radiological Effluent Tech Specs" for BUR's (NUREO-0473) & "Preparetion of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

  ORINES B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/16. 6pp. 94357:012.
- 7812060003 Forwards Amend#61 to Fecil Oper Lic#OPR-57 changing Tech specs as requested in 780613 ltr.
  IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16.
  2pp. 94328:092.
- --7812060009 AmendM61 to Facil Oper Lic#DPRN57 rev Tach Specs to delets existing Append 8 Environ Tech Specs (ETS) t adopt ETB approved for Unit 2. iPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/\$1/16.61pp. 9428:094.
- --7812060013 Environ impact Appraisal supporting Amend#61 to Fact1 Open Lic#DPR-57 concluding that there will be no environ impact attributable to proposed action & no environ impact statement need be prepared. • Office of Nuclear Reactor Regulation. Director. 78/11/16. 5pp.
- 94328: 155
- --7812060119 Notice of Issuence of Amend#61 to Fecil Oper Lic#DPR-57.
  1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16.
  2pp. 94028:160.
- 7812110035 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for centinuing. W/encl ANO: W7812080207.

  IPPOLITO. T. Operating Reactors Branch 2 (Pre 790825). 78/11/29.

  Bpp. 74408.141.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings help & providing tesk-by-task activity summary for the month. 8DBCN:L.J. General Electric Co. 78/12/04. ilps.

- 7812280170 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants info submitted must be substantiated by date & calculations. Licenses must notify NRC of any inaccuracies or snforcement action will result. DAVIB, J O Office of Inspection & Enforcement, Office of the Director 78/12/06 2pp. 94375.009.
- 7812270274 Forwards proposed amends to Tech Boscs & to Environ Tech Boscs of subj facils minus section on solid redicective wasts which is still under dev Requests delay of implementation to 790701 or later pending review completion. WHITMER, C. A. Georgis Power Co. 78/12/21. 400pp 94231:001
- 78:1210367 Forwards add1 info re multiple consecutive sefety/relisf valve actuation of Mark I containment program.
  SOBIN.L.J. General Electric Co 78/11/13. 3pp.
- O inspection reports. iE Builetins & correspondence
- 7810130092 Ack receipt of 1E inspec Rept#50-321/78-27 & #50-366/78-35 on 780724-0804 Oces not consider any info therein to be proprietary STAFFA.R.H Georgia Power Co. 78/09/27. lp.
- --7810130095 Forwards 18 inspec Rept#50-321/788-27 & #50-366/78-35 on 780724-0804 during which no items of noncompliance were noted LONG.F. J. Region 2. Atlanta, Reector Operations Nuclear Support Branch 78/09/11 2pp.
- --7810130099 iE Inspec Rept#50-321/78-27 & #50-366/78-35 on 780724-0804 during which no itses of noncompliance were noted. Major areas inspected included inspec to review LER. plant oper carried in response to 18 Circular 78-08.
  CANTRELL, F B . KLINDLER. O. R . VDOT-LOWELL, R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/08 9pp.
- 7810110089 Forwards proposed amend to Tech Specs which will upgrade the Iniv Inspac requirements per IOCFR55e(g)(4)(11) Proposed changes rely on standard Tach Specs.

  WHIDMSR.C.F. Georgia Power Co. 78/10/03. 3ipp. 940a6:258.
- 7811100168 Responds to 781003 NRC ltr re violations noted in inspec Repts#50-321/78-30.#50-366/78-38 Corrective action:detaile withheld IAN IOCFR2 790(d). STAFFA:R.W Georgia Power Co. 78/10/23, ip. 94179:346.
- 7811100105 Act receipt of 781023 itr informing NRC of steps taken to correct violations noted during inspec#50-321/78-30 & #50-366/78-38 KENNA B. Region 2. Atlanta, Bafsguards Brench. 78/10/31, 1p. 94179,345.
- 78iii30256 Ack receipt of 78i027 itr informing NRC of steps taken to Correct violations noted during insper#50~321/78-29.#30~366/ 78-37 LONG. F. J LONG.F.J Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/06 lp.
- -- 7811130261 Responds to 781004 NRC 1tr ra violations noted in inspec Rep to #50-321/78-29 & #50-366/78-37. Corrective actions: formel instruc to departmental supervisors on manning of work w/OC hold points.

  BYAFFA.R H. Georgia Power Co. 78/10/27. 2pp.
- --7811130262 Forwards 15 Inspec Repts#50-321/78-29 & #50-366/78-37 on 780821-24 t Notice of Violation. LONG:F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/04. 2pp.
- --78iii30268 Notice of Violation from inspec on 780821-24.

   Region 2. Atlanta, Office of the Director. 78/10/04, ip.
- --7911130286 IE Inspec Repts#50-321/78-29 & #30-366/78-37 on 780821-24 during which 2 items of noncompliance were noted failure to failure to failure 2 different procedures 321/78-18-29-01 % 366/78-37-01
  - SKDLDS, J. L. Region 2. Atlanta, Office of the Director. 78/10/04.
- 7811150118 Forwards 1E Circular 78-18. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/06.
- 7811220034 Act receipt of 1E Inspec Repts#50-321/78-31 & #50-366/78-39 on 780905-08. Does not consider any into therein to be proprietary.
  BTAFFA.R.H. Georgia Power Co. 78/11/13. ip. 94336:007.

- --7811220059 Forwards IE Inspec Repts#50-321/78-31 & 50-366/78-39 on 780805-08 during which no Items of noncompliance were noted ECNO.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/20. 2pp. 94335 008.
- --7811220064 1E Inspec Repta#30-321/78-31 & #50-366/78-39 on 780905-08 during which no items of noncompliance were noted Major areas inspected included:lic operator requal training progr training prog for monlic personnel & plant tour.
  BRADFORO, W. H., TAYLOR, P. A., KELLOGO, P. J. Region 2, Atlanta,
  Reactor Operations Nuclear Support Branch. 78/10/19. 2pp.
- 7811280006 Ack receipt of IE Inepec Repte#50-321/78-32 & #50-365/78-40 on 780913-15. Does not consider any info therein to be proprietary STAFFA.R.W. Georgia Power Co. 78/11/13. 1p. 02726:314.
- --7811280008 Forwards iE Inspec ReptsM50-321/78-32 & 850-366/78-40 on 780913-15 during which no items of noncompliance were noted. LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/18. 2pp.
- --7811280012 IE Inspec Repts#50-321/78-32 & #50-366/78-40 on 780913-15 during which no itsms of noncompliance were noted. Major ereas inspected included: ravism of LER strept procedure for 10CFR21 repts & fire squip inspec & off-gas sys hardware. CMTRELL, F. S., RILEY-B. W. DANCE, H. C., Ragion 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/10/18. Spp. 02726:317.
- 78:2120043 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafaguards Newsletter, KENNA, N. B. Region 2, Atlanta, Bafaguards Branch. 78/11/17 4pp. 94278: 100.
- 7812070002 Act recaipt of 1E Inspec Repts#50-321/78-28 % #50-366/78-36 on 780815-19. Does not consider any info therein to be proprietary. BTAFFA-R.W. Georgia Power Co. 78/11/20. 1p. 94347:348.
- --7812070097 Forwards iE Inspec Rept 50-321/78-28 & 50-366/78-36 on 780815-18 No itams of noncompliance noted. LCNO:F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/20. 2pp. 94347:349.
- --7812070148 1E Inspec Repts#50-321/78-28 & #50-366/78-36 pm 780815-18 during which no items of noncompliance were noted. Major areas inspected incl: surveillance activity on pips support & restraint sys for Unit 1 Incl examination of procedures. HHITEMER. H. L. MARTIN, R. D. Region 2, Atlants, Office of the Director. 78/11/20. 9pp. 94347:331.
- 7812040310 Forwards IE Bulietin#78-12A. suppl to IE Bulletin 78-12. W/encl ANO.7811300055.

  O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 78/11/24
  ip. 94129:176.
- 7812060343 Ack receipt of TE inspac Repts#50-321/78-35 & #50-366/78-43 on 780828-1006. Dose not consider any info therein to be proprietary. STAFFA:R.H. Georgia Power Co. 78/11/27. 1p. 94382:248.
- --7812060345 Forwards IE Inspec Repts#50-321/78-35 & #50-366/78-43 on 780828-1006 during which no items on noncompliance were LONG. F. J. Region 2. Atlanta, Office of the Director. 78/11/07. 20P. 94382:249.
- --7812050350 1E Inspec Repts#50-321/78-35 & #50-356/78-43 on 780828-100 during which no itsms of noncompliance were noted. Hajor areas inspected incl: unit i plant operations. Unit 2 startup testing. lic accase training & on-sita comm meeting minutes. ROSERB, R. F., DANCE, H. C. Region 2. Atlanta. Office of the Director. 79/11/01. 6pp. 94382:251.
- 7812280286 Ack receipt of IE Inepsc Repts#50-321/78-39 & 50-366/78-48 on 78130. Dose not consider any info therein to be proprietary. STAFFA.R.W. Georgia Power Co. 78/12/14. ip. 94089:117.
- --7812280290 Forwards IE Inspec Repts#50-321/78-39 & 50-366/78-48 on 781007-1110 during which no items of noncompliance were noted. LOWO,F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/30. 2pp. 94083:118.

- --7812280294 IE Inspec Repts#50-321/78-39 & 50-356/78-48 on 781007-1110 during which no itsme of noncompilance were noted Major areas inspected incl:plant opers, startup testing minutes, Tech Spec compilance & reportable occurrences.

  DANCE, M. C. RODERS, R. F. Region 2, Atlenta, Reactor Operations Nuclear Support Branch. 78/11/20. 5pp. 94083:120.
- 7812280022 Forwarde IE Bulletin 78-14.

  O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/12/19.

  1P. 94131:036.
- 7810270018 Forwards 1E Circular #78-17. (See AND: 7810230221. Docket 50-133.781013)
  D'REILLY, J. P. Region 2. Atlanta. Office of the Oirector. 78/10/13. ip.
- R. Pariodic operating reports & related correspondence
- 7810170141 Monthly Oper Rept for Sept 1978.
  WILSON,B.M. Georgia Power Co. 78/10/05. 7pp 94236:001.
- 7811180066 Forwarde Monthly Open Rept for Oct 1978. MANRY, M. Georgia Power Co. 78/11/08. 1p. 94133:122.
- ~-7811160068 Monthly Open Rept for Oct 1978. WILSON.S. Georgia Pawer Co. 78/11/05. 10pp. 94133:123.
- 7812150287 Forwards Monthly Open Rept for Nov 1978. MANRY, M. Georgia Power Co. 78/12/07. 1p. 94409:191.
- --7812:50294 Monthly Oper Rept for Nov 1978. WILSON, S. Georgia Power Co. 78/12/05. 11pp. 94409:192.
- B. Raportabla occurrencae, LERs & raiated corraspondence
- 7810170233 Forwards LERN7B-077/01T-0.
  MANRY, M. Georgia Power Co. 78/09/25. 1p. 94235:316.
- --7810170237 LERW78-077/01T-0 on 780920; while under oper-follow-up raview of diesel generator Control logic identified potentiel problem under LOCA & LOBP preventing diesel which felled or was ehutdown from being restarted by control room GREENE, T. Tennatsee Valley Authority. 78/09/28. 3pp. 94236:317.
- 7810170256 Forwards LERW78-071/03L-D.
  MANRY, M. Georgis Power Co. 78/09/25, ip. 94236:343.
- --7810170261 LERM78-071/03L-0 on 780911: peak LHOR want from about 98% of limiting value to about 100.01%. Caused by inaccurate base distribe in process computer, resulting in arronsous calculation of LHOR in that region.

  GREENE.T. Georgia Power Co. 78/09/25. 2pp. 94236:344.
- 7810170291 Forwarde LERN7B-074/03L-0.
  MANRY, M. Georgie Power Co. 78/09/25. 1p. 94415:087.
- --7810170298 LERW78-074/03L-0 on 780913: During inepec of fire rated penetration seal rapair in cabla epreading room floor. 3 penetratione in calling were discovered which had not been essled. Caused by calling limited accessibility.

  GREENE, T. Georgia Power Co. 78/09/25. Rpp. 94415:088.
- 7810180112 Forwarde LERN78-073/03L-0.
  MANRY, M. Georgia Power Co. 78/09/27. 1p. 94195:204.
- --7810180114 LERN78-073/03L-0 on 780912: fire teals in RPS vantical cabia way were found to be breached at 130 k 147 elevatione, Caused by failure of conetr crew to repair fire seals after installing 2 cables thru RPS room.

  NIX.R.T. Georgia Power Co. 78/09/27. ip. 94195:205.
- 7810170329 Forwards LERN78-076/03L-0. MANRY.M. Georgie Power Co. 78/09/29, ip. 94234:340.
- --7810180014 LER878-076/03L-0 on 780915:Refueling vant sthauet seneor gave false, high & erratic indication while at 99X reactor pur. Caused by failure of G-M tube which was raplaced. NIX.R. T. Georgia Power Co. 78/09/29. 1p. 94234:341.
- 7810180029 Forwarde LERW78-075/031-0.
  MANRY.M. Georgia Power Co. 78/09/29. 1p. 94195:195.
- 7810180010 Forwarde LERR78-078/03L-0. MANRY:M. Georgia Power Co. 78/10/06. 1p. 94429:012.

- --7810180011 LER#78-078/03L-0 on 780924: while in hot etandby, discovered main steamline radiat monitor survelliance test had not been performed during hot etandby due to personnel oversight. MANRY.M. Georgia Power Co. 78/10/06. 1p. 94422:013.
- 7810230175 Forwards LER#78-080/03L-0.
  MANRY-M. Georgia Power Co. 78/10/13. 1p. 94164:100.
- --7910230176 LER#78-080/03L-0 on 780929: during normal release of bat liquid radweste the Hi starm trip of liquid radwaste radiat monitor terminated flow due to lab technician selecting wrong analyzer. Cautioned lab personnel to be very careful. ROSERS-H. H. Georgia Power Co. 78/10/13. 3pp. 94169: 305.
- 7810310146 Forwards LER878-079/03L-0 MANRY, M. Georgia Power Co. 78/10/13. 1p. 94090: 176.
- --7810310150 LERM78-079/03L-0 on 780928: main steam flow switch was overranged & made inoper by overpreseurized DP call Switch & other redundant Barton instru with enubbers in sensing line were checked & verified to be cleer.

  OREENETTU. Georgia Power Co. 78/10/13. 2pp. 94090:177.
- 7810310157 Forwards LERM78-082/03L-0.
  MANRY.M. Georgia Power Co. 78/10/20. 1p. 94090:211.
- --7B10310162 LERM78-082/03L-0 on 781010. After 880T fan removed from W/ra@ctor in run mode, other 880T train not run w/in 4 hours to prove operability. Requirement fargotten during work on other 880T. Personnel responsible admonished.

  BAXLEY, B. X. Georgia Power Co. 78/10/20. 2pp. 74090: 212.
- 7810310165 Forwards LERM78-084/03L-0.
  MANRY-M, Georgia Power Co. 78/10/23. 1p. 94090:225.
- --7810310171 LER 78-084/031-0: on 781014, secondary containment broken Caused by opening of both turbine bidg roof access airlock doors elaultaneously, Parsonnel edmonished.
  BAXLEY, B. X. Georgia Power Co. 78/10/23. 1p. 94090: 226.
- 7810310117 Farwerds LER M78-068/3L-0.
  MANRY-M. Georgia Power Co. 78/10/24. Lp. 94093:330.
- --7810310182 LER #78-086/03L-0 on 781016:Peak LHQR rose to 100.2 per after calibration. Caused by epatial renon vertations, which induced slightly non-conservative calculation of the LHQR in affected ragion.

  OREENE, T. Georgia Power Co. 78/10/24. 2pp. 94093:331.
- 7810310160 Forwarde LERM78-083/03L-0.
  MANRY, M. Georgia Power Co. 78/10/25. 1p. 94090; 218.
- --7B10310166 LER #7B-0B3/O3L-0:on 7B1011.water discovered in starter Caused by low pressure inside dissel bidg: low pressure pulled moisture-ladan air into dissel bidg pullbox. Moieture condensed t collected in starter box.

  NIX.R.T. Georgia Power Co. 7B/10/25. ip. 94090:219.
- 7811060131 Forwards LER#78-088/03L-0 MANRY,M. Georgia Power Co. 78/10/30. ip. 944Q4:201.
- --7811060138 LERW78-088/03L-0 on 781021: CMPF found to be R. 562 while about 82% during load increase Did not drop significantly after 2 hours. Caused by CMPF increased during large zeron transients increase faster than correctable. GREENE, T. V. Georgia Power Co. 78/10/30. 1p. 94424: 202.
- 7811060135 Forwards LERRT8-081/03L-0. NANRY-M. Georgia Power Co. 78/10/30. 1p. 94424:207.
- --7811060140 LER#78-081/03L-0 on 781005:during rapair work the valve seat for P41-F3138 blew out Coused by removal of piping Svc Hater Strainer backwash line.Rev to be mada. 8XLEY,8.x. Georgia Power Co. 78/10/30. 2pp. 94424:208.
- 7811140136 Forwerds LERN78-089/031-0.
  MANRY.M. Georgie Power Co. 79/11/02. 1p. 94383:306.
- --7811140162 LER#78-089/031-0 on 781022: eever# arcing observed at ax collector ring of 831-8001A, "A" M. O. eet tripped before it could be removed from avc. Bolts used to fasten brush holders to yoke assembley caused brushes to arc.
  NIX-R.T. Georgia Power Cq. 78/11/02. 2pp. 94383:307.
- 7811210342 Forwards LER#78-090/03L~0.
  MANRY, M. Gaorgia Power Co. 78/11/13. ip. 94484;340.

#### ノししいたし ヒレ こしきいいろ

- --7811210346 LER#78-090/03L-0 on 781028.at 95% rated per.LPRM calibr OD-1 was performed changing CMFLPD from 0.97 to 1.004.Flow was reduced after which peak LHGR was reduced to 99% of its limit Caused by Inaccurate base dietrib in computer.

  ORCENE.T. Opergia Power Co. 78/11/13 1p. 94484-341
- 7811220026 Forwards LER#78-091/03L-0 MANRY,M Georgia Power Co. 78/11/14. 1p. 94308:359
- --7811220028 LER#78-091/03L-0 on 781031: surveillance of fire protec equip circuitry(Procedures HNP-1-3356 & HNP-1-33601had been neglected due to personnel oversight importance of fire detector surveillance resmphasized to personnel. NIX.R.T. Georgia Power Co. 78/11/14. 1p 94308:360
- 7811240341 Forwards LER#78-092/03L-0.
  MANRY-M. Georgia Power Co 78/11/13. ip 94483:052
- --7811210366 LER#78-092/03L-0 on 781101:a main state line radiation monitor (Dii-K603D) feiled to initiate a heif scram during a test Caused by a longe wire which had damaged some components.

  NIX.R T. Georgia Power Co. 78/11/15. lp 94485-053
- 7812060392 Void+ LER#50-321/78-85.
  MANRY.M. Georgie Power Co. 78/31/16. 1p. 94382 350
- 7812070033 Voids LERNSD-321/78-87.
  MANRY, M Georgie Pouer Co. 78/11/16. 1p 94127.235.
- 7811280242 LER878-093/03L-0 on 781109 during normal oper core drille were made thru diesel generator room walls to allow conduit to be run thru walls Fire watch established per Tech Spece. NIX.R.T. Georgia Power Co. 78/11/20. 1p. 94012 133.
- 7811280235 Forwards LERM78-093/03L-0.
  MANRY.M. Georgie Power Co. 78/11/20. ip. 94012:154.
- 7812180164 Forwards LER#78-094/03L-0 HANRY.M. Gaorgia Power Co. 78/11/20, 1p. 94366:032.
- --7812180170 LER#7B-094/03L-0 on 781120; during NRC sudit it was found that RHR time delay relay E11-Ki26 had been laft in uncelibrated state from 780412 to 780627. Redundent releys E11-Ki25 A & B were functioning Proceduras will be rev. 9REENE.T. Oeorgia Power Co. 78/11/20. iP. 94366:033.
- 78:2180165 Forwards LERM78-089/03L-0.
  MANRY.M Georgia Power Co 78/12/08. ip. 94366:034.
- --7812180169 LERM7B-0B9/03L-0 on 781027: severe arcing at exciter collector ring of B31-8001A tripping A\*M0 set ceueing ring & brushes to burn. Caused by bolts used to factor brush holders to got assembly having insufficient length.
  NIX.R. T. Georgia Power Co. 78/12/09. 2pp. 94366:035.
- 7812270280 Forwards LER#78-043/03L+1, MANRY.M. Georgia Powar Co. 78/12/14, 1p. 94229:313.
- --7812270285 LERM7B-043/03L-1 on 780509: procedure XNP+1-3902, "Bafety Reifef Valve Punctional Test" tried unsuccessfully on 2 solanoids. One failed due to bent plunger; other failure due to plunger not properly secured to actuating springs. GREENE, T. Georgia Power Co. 78/06/30. 2pp. 94229:314.
- 7812270295 Forwards LERB78-054/03L-1.
  MANRY-M. Georgia Power Co. 78/12/18. ip. 94229: 347.
- --7812270296 LERM78-054/03L-1 on 780710. shock suppressor RHRM-229 found to be low on fluid. Caused by leaking "D" ring seal.

  NIX.R.T. Quargia Power Co. 79/12/18. 1p. 94229:248.
- 7812270315 Forwards LERM78-095/03L-0. MANRY-M. Georgia Power Co. 78/12/18. 1p. 94230:352.
- --7812270318 LERM78-095/03L-O on 781130: refueling floor vent exhaust sensor(Dir-N012C)gave false high indication. Caused by sensor mounted in such a way se to allow rain water to enter. NIX-R.T. Georgia Pawer Co. 78/12/18. 1s. 74230:353.

- DOCKET 50-322 SHOREHAM NUCLEAR POHER STATION

  A Application/construction stage documents & correspondence
- 7810110307 Ack receipt of proposed agreement re "Discinsure of Confidential Info" filed 780817, which is satisfactory. Requests inspec of proprietary QE reptineeds permission from QE.
  HAND.R.C. Reilly & Like. 78/09/25. 4pp. 94061:012
- 78:0180175 Notice of mseting on 78:1006 to discuss subj facil MarklI Closure Prog. HILEON.J.N. Light Hater Reactors Branch 4. 78/10/02. 3pp. 94317:107.
- 70:0270394 Response to 780919 ltr informing recipient that GE offices in Ban Jose & Topical Rept#21021-P will be made available for inspec Draft "Agreement Re Disclosure of Confidential Commercial Info" enci.
  WMITTEMORE, F.C. Hunton & Williams. 78/10/04. 6pp. 94033:273.
- 78:01:00017 Forwards add1 info requested during NRC Reactor Bys Branch masting of 780928 rs coolant water to recirculation pump.scram capability.line break.new computer codes.& RCPB
- lealage detection. NOVARRO, J.P. Long Teland Lighting Co. 78/10/05. 5pp.
- 7Bi0270001 Burmery of trip to subj fecil by Reactor Sye Branch representatives to tour facil & discuse RSB open itams.
  Expects submittel of addi info re items discussed. W/encl list ettendees.
  MILLS.W.R. Division of Systems Befety. 78/10/11. 3pp. 94056:053.
- 7810200231 Burmery of meeting of 781005 to discuss subj facil's containment cideure prog issues discussed include epplicant LiL's plan to use Tea-Ouencher loads rether then Rems Head loads & plan to combine OBE & BRV loads by SRBS.
  HILEON.J.N. Light Hater Reactors Branch 4. 78/10/13, 4pp. 94081-272
- .7811130360 Bummerizes 781019 mesting w/Mark 2 Owners Group to discuss Staff's Merk 2 Contesiment Acceptance Criteria. Wettendees list mesting handouts, summery of owner's position & final disposition of criterie for addi review by staff. PELTIER: A. Light Wetar Resctors Branch 1. 78/11/01. 37pp. 94008:087.
- 7811130258 Notifies DBS of forthcoming meeting w/representatives from Merk R Owner's Group on 781115 at Dethasda. MD. to discues LOCA/BRV submerged etructure drag loade for lead plants. ANDERSON. C. J. Containment Systems Brench (Pre 790101). 78/11/02.
- 7811280097 Forwards Ravel Draft Radiological Effluent Tech Spec for PRR's(NUREG-0472) & "Preparation of Radiological Effluent Tech Spac for Nuc Pur Plants"(NUREG-0133). W/encl ANO: 7811270173 & 2811270180, VASSALLO, D. S. Assistant Director for Light Water Reactors, 78/11/16. Spp. 03584:274,
- 781128004A Responde to 781107 NRC request for new lic appl plane. Has no new lic appl plane between now & 811231.

  MOFFDRD. A. W. Long Island Lighting Co. 78/11/17. ip. 02726: 333.
- 7812070152 Notice of seminar on 781208 on new Model Radiological Effluent Tech Bpece for nuc pur plants. Requeste edvance submission of seminar specific questions. W/encl Beminar Info Bheet, Proposed Agenda & mape.

  GRIER.B. H. Region i. Philadelphia. Office of the Diractor. 78/11/21. 8pp. 94375:202.
- 7812080223 Bummery of 781019 mseting. Discusses intent on future effort: toward completion of staff review of mark II generic acceptence criteria for lead plante Espects delay in overell review of Intermediets Prog Tasks. W/encl tasks & criteria. BOYD. R. S. Division of Project Management. 78/11/24. App. 94137: 105.
- 7812280162 Emphasizes importance of submitting accurate & complete inf to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J.O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 74311:332.
- 7812200134 Notice of 781215 meeting in Betheeda, MD to discuss Shoreham design for containment isolation & leek test.
  WILBON, J. N. Light Water Reactors Branch 4. 78/12/08, 3pp. 94189:002.

- 7812200131 Notice of 781214 meeting in Bethesda MD w/applicant to discuss unresolved issues in facil review. WILEON, J.N. Light Water Reactors Branch 4 78/12/12. 2pp. 94136, 297
- 7812260126 Forwards Rev83 to Pient Design Assessment Reet for BRV & LOCA loads. W/Executive Summary of Mark 11 Loads Closure Prog. Finei rev will be submitted in June 1979.
  NDVARRO.J P Long Island Lighting Co 78/12/10. 7pp 94026:001
- --7812260129 RevN3 to Plant Dasign Assessment Rept for SRV & LOCA loads. Provides info on load definition load combination methode, acceptance criteria & plant capability to accept hydrodynamic loade

  > Long Island Lighting Co. 78/12/18 400pp 94026:008.
- 7812260196 Forwarde Proprietary Suppl to SNRC-347. "Design Analysis Rept Rev 3. " Document withheld from pub disclosure.pursuant to 2.790 NDVARRO.J.P. Long leland Lighting Co. 78/12/11. Ip
- 7812260221 Forwards NRC request for add1 info contained in BA Verga itr to AH Hofford dtd 780831; etruc assessment of sacrificial ehelld wall under effects of annulus presentation to rev responses M23, previously submitted.
  NGVARRO, J. P. Long leiand Lighting Co. 78/12/20. 19pp. 94160.026.
- 7812290005 Summary of Maeting on 781213 u/Mart 2 Owners Group to discuse Staff's Mart 2 containment acceptance Criteria W/attendance liet & meeting handouts encl.
  ANDERSON, C. J. Containment Systems Branch (Pra 790101). 78/12/20. 95p. 94207 239
- F. Bacurity, medical, amargency & fire protection plane
- 7812140166 Forwards add1 info ra fire analysis in response to requeste from 8A Varga to AN Wofford dtd 780627 & 780809 re fire equip & fire hezerde equip & fire hezerde NOVARROJ P. Long letend Lighting Co. 78/12/11. 150pp. 94088.022.
- 78:2140105 Forwards comments on 780808 version of Amended Physical Becurity Plan for subj facil. Encl withheld from disclosurs pursuant to 2, 790.
  ROSE D. O. Los Alamos Scientific Laboratory. 78/12/12. ip.
- 9. Adjudicatory correspondence
- 7810160201 Hotion in opposition to intervenor BUCO's Motion of 780919 > seeking an indefinite amount of time to respond to applicant LIL's interrogs of 771208. If Motion is granted a deadline of not later than 781016 for BUCO's answer is cought. WHITTEMORE, F. C. Hunton & Williams. 78/10/02. Spp. 94092:346.
- 7810270301 Advisee of status of MHB rept on County contentions in proceeding. HuB proposel will be further delayed due to submission of resolution to be voted on by Full legislature. LIKE I. Reilly & Like. 78/10/03. 2pp. 06403.356.
- 7810230130 Notice that J.P. Novarro has replaced T. J Burke as facil Proj Mgr. WHITTEMORE.F. C. Hunton & Williams. 78/10/11. 1p. 94169:070.
- --7810230133 Notice that J.P. Noverro has replaced T. J. Burks se facil Proj Hgr. NOFFORD, A. W. Long Island Lighting Co. 78/10/05. 1p. 94165:071.
- 7810250003 Order Relative to Discovery Schedule. If Suffalk Legis approves funding for HHB on 781024, then Suffalk will file response to interroge by 781113. SDHERS.E.B. Atomic Safety and Licensing Seard Panel: 78/10/12.
- 7810300218 Affidevit in Opposition. H Blau is atty for Conedidated Intervenors Dil Heat Inst of Long Island: Inc. & the North Bhore Comm Against Thermal & Nuc Pollution. Affidavit responds to 780818 Motion to Impose Banctione W/cert of syt. BLAV.H.L. Affiliation Unknown. 78/10/12. 3pp. 94034:098
- 78:1020325 Forwards recent memoranda re certain problems experienced in connection w/plps support base plate design. Staff is determining if these problems have generic implications for oper facils & will keep Lic Bd informed of any new info. QRAY, J.R. Diffice of the Executive Legal Director 78/10/19. 1p. 94240:221.

- --7811020332 Forwards 780628 memo to R Mattson re info on foilures of safety-related pipe supports at Millstone i & design deficiencies on similar equip on Shoreham 1. Hemo gives Dd notification of pipe support base plate design SELLO.V Division of Operating Reactors 78/09/28. 2pp. 94240 222
- --7811020343 Addresses pipe support base plate problem Discusses review of support redesigns & capability of the anchor bolts to withetend cyclic loadings.

  NCONAN.V S Engineering Branch (Pre 791030) 78/06/02. 2pp 94240, 228.
- 78:1200002 On 78:024 Suffett County Legis authorized preparation of rept as requested by staff & applicant. Will attempt to complete rept by 78:11:3. LIKE 1. Reilly & Like. 78/10/25 ip. 942:5-220
- 78ii070023 Order Granting NRC Staff Hotion of 760Bi8 to Imposs Banctions Consolidated Intervenors have frustrated Bisff's Efforts & have not complied u/Bo orders Staff's motion for diemissai of Intervenor's Contention 7(g)is granted. BUMERS.E 8 Atomic Safety and Licensing Board Panel. 78/10/27 2pp. 94037:132
- 7811300373 Request by BUCO thet applicant LiL produce any & all documents reparding communication between LiL & 0E relation? Reed Task Force Rept Cart of Buc encl. LIKE.1. Suffolk County, NY. 78/10/30. 3pp. 94116:360.
- 781120000B Forwarde NRC & Appeal Bd decisions to subj facil, dealing w/ treatment of issues relevant to issuence of 10CFR70 lic to etore unitradiat nuc fuel assembles at facil under construction to issuence of oper lic H/encl 1976 NRC Decisione. HDERLING, R. K. DPFice of the Executive Legal Director 7B/11/03 26pp. 94215.200
- 7811200022 Lic appl has been placed in the local PDR. Staff expects to complete review & issue Part 70 lic to store new fuel at site. HDEFLING.R.K. Office of the Executive Legal Director 78/11/03. ip. 94215:288
- 7812110012 Requests extension of time from 781113 to 781130 to respond to 80's "Order Relative to a Discovery Schedule" directing Buffolk County to file responses to interrog. Delay due to lack of funding for county consultants HHB Tach Assoc.

  LIKE 1. Reilly & Like. 78/11/10. ip 94339:259
- 7812110281 Applicant LIL's Reply to intervenor Buffolk County's Request 2 for production of documents.LIL objects to request on basis that all documents sought are trial preparation matls to that LIL has not satisfied 10CFR2.740(b)(2).

  WHITTEMORE,F.C. Hunton & Williams. 78/11/17. 2pp. 94203:237.
- 7812210471 Comments on 2 interrogatories by Suffoll County answering Applicants' Second interrogatories of 781026 ra why Criterian 3 mandatas teste for suitability of met) selection design & bases for higher source terms for accidents.

  LIKE I. Railly & Like. 78/11/21. 2PP 94393:358
- 7812140026 Forwards nev Section 3.7 of FES dtd Oct 1977, NUREG-0285 HOEFLING.R.K. Dffice of the Executive Legal Director. 78/11/28. 9pp. 94127:191
- 7812140342 Recipients may attend any pub hearing on euby facil.as stated in anci 780628 Fed Regietar Notice. & will be routinely placed on dietrib list for relevant meeting notices & summartss.

  HOEFLING.R.K. Diffice of the Executive Legal Director. 78/11/28.
  2pp. 03557:165
- 7812260322 Motion by intervenor Suffals County to compel applicant LIL & GE to produce documents sought by Suffalk County on 781030. Asserts LIL & OE must show that documents are "trial preparation matis."Cart of Svc encl.

  LIKE J. Suffalk County, NY. 78/11/28 Spp. 94160: 111.
- 7812210411 Reviews status of all contentions raised by intervenor Buffolk County in proceedings re subj fectis. Tech bases & supporting documentation for each contention are provided. Cert of Svc encl.
  LIKE I. Suffolk County, NY. 78/11/30. 145pp. 94014:012.
- 7812270042 NRC Steff Motion for an Extension of Time from 781211 to 790112 w/in which to file a motion to compel responsive answers to its interrogs. Cert of Svc anci. HQEFLING.R.K. Office of the Esecutive Legal Director. 78/12/08. 5pp. 94160:219.

- 78:2210297 Grants NRC Staff's Motion for extension of time until 790:12 to file a motion to comps! Suffolk County to provide responsible enswers to interrogs submitted to Suffolk County on 7905:15
  BOMERS.E 5 Atomic Bafsty and Licensing Board Panel 78/12/12
  2pp 94:10: 337
- 78:2280333 Applicant's Answer to SC's Motion to Compel. Subj util urgss Suffolk County's motion be denied Showing request based on false premises is one of the ressons for urging denial Cert of Buc and halfitemore. C. Hunton & Hilliams 78/12/13 App. 03555. 14b.
- 7811210110 Intervenor SUCO's suppl response to applicent LiL's second set of interrogs re inclusion of credible lerge accidents, containment sys design verification & transient condition design verification Cert of Svc encl LiKE | Suffait County, NY 78/10/26 Spp. 94482-167
- M Utility Final Sefety Analysis Report (FSAR) & emends
- 7810200091 Notice of Svc of Amend #29 to Lic Appl. Consisting of FBAR Rev #13 MCCAFFREY. B R Long Island Lighting Co. 78/10/12 ip. 94367:091.
- 7812260136 Forwards Amende30 to Lic appl for subj fecil.consisting of Revel4 to FSAR Rev contains analysis of pipe failure outside containment for both high & moderate energy systems Corrections to FSAR elso included MOFFORD.A N Long Island Lighting Co 78/12/18. 2pp. 94141:001.
- --7812260139 Amend#30 to fic applifor subj faciliconsisting of Rev#14 to FEAR.

  + Long Island Lighting Co 78/12/18. 300pp 94141:003.
- D Advisory Committee on Resctor Safeguards reports & correspondence
- 7811240157 Notice of 781128-30 meeting in 6en Francisco w/ACRS Fluid Dynamic Subcommittee re Nort II LOCA & SRV pool dynamic looks & lood combinations.

  ANDERSON.C J. Conteinment Systems Branch (Pre 790101). 78/11/13.
  3pp. 44456 261.
- ~-7811240161 Agende for 781128-30 ACRB meeting In Ben Frencisco of Fluid Hydreulic Dynamic Effects Subcome re Mark II LDCA & BRV pool dynamic loads & load combinations ANDERSON.C J. Containment Systems Branch (Pre 790101). 78/11/13. 3pp. 94456-264
- G Inspection reports, IE Bulletine & correspondence
- 7810160255 Forwards IE Bullstin878-12: "Atupical Wald Material in Reactor Pressura Vessel Walds' requesting action w/in 60 days & list of IE Bullatin issued in 1978 (see ANO 7810040253) GRIER.B.H Region i. Philadelphie, Office of the Director. 78/09/29. 6pp. 94007:013.
- 7811300303 Forwards IE Inspec Rept#50-322/78-14 on 780913-13 during which no lites of noncompliance were noted. BRUNERE J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/10. 2pp.
- --7811300306 IE Inspec Rapt#50-322/78-14 on 780913-15 during which no items of noncomplishes were noted Major erass inspected incli-admin controls, eched for completion of syst & tests, status of procedure completion t fecil inspec.

  SHEDLOBKY.J.T., BR10961.E. Region i, Philadelphis, Reactor Operations Nuclear Support Branch. 78/10/10. 3pp.
- 7810180074 Forwards rave to Presvo Inspec Prog Plan for subj facil: RaveO for ultransonic examination procedures for plping waids & RaveO for ultrasonic examination procedures for closure head welfs.

  NOVARRO, J. P. Long Island Lighting Co. 78/10/11. 7pp. 94421:264.
- 7811060195 Forwards 1E Circulara78-17. (800 ANO:7810230221, Docket 850-133, 78013.)
  ORIER. 8.M. Region 1. Philadelphia, Office of the Director, 78/10/13. 1p. 94499:175.
- 7812120022 Forwards IE Insp Rept 50-322/78-15 on 780926-29 & notice of violation.
  CARLEMON R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 78/10/17. 3pp. 94277:323.
- --7812120024 Notice of Violation from into on 780926-29.

   Region 1. Philadelphia. Office of the Director. 78/10/17. 18.

- --7812120026 IE Insp Rept 50-322/78-15 on 780926-29 Noncompliance noted: failure to use qualified procedure for welding pipe support. TOTH.A.D. Replon 1. Philadelphie. Defice of the Director. FABAND.A.N., MCGAUGHY.R.W. Region 1. Philadelphie. Reactor Construction & Engineering Support Branch. 78/10/17. 10pp. 94277:327.
- 7811140229 Ack receipt of 781018 ltr informing NRC of steps taken to correct violetions noted during inspects0-322/78-12.

  CARLBON.R.T. Region i. Philadalphia, Reactor Construction & Engineering Support Branch. 78/11/02. ip. 94400:070.
- --7811140234 Responds to 780830 NRC ltr re violetions noted in Inspec Rept#50-322/78-12 Corrective actions:weld technique sheet lasued & slip-on Pianga welds to be inspected MOFFORD.A.M. Long (sland Lighting Co. 78/10/18.
- --7811140239 Forwards IE Inspec Rept#50-322/78-12 on 780808-11 & Notice of Violation.
  CARLEGN, R. T. Region 1- Philadelphia. Reactor Construction & Engineering Support Branch 78/08/30 2pp. 94400:074.
- --7811140243 Notice of Violation from inspec on 780808-ii. CARLEON, R. T. Region J. Philadalphia, Office of the Director. 78/08/30. 2pp. 94400:076.
- --7811140249 iE Inspec Rept#50-322/78-12 on 780808-11 during which 2 items of noncompliance were noted:single-bavel-groove weld joints for ploe restraints were 30 degraes, ploe spool slip- on fisings less than quarter-inch.

  TOTH.A.O. Region 1, Philadelphia. Office of the Director.

  DURR,J,P. Region 1. Philadelphia. Resctor Construction & Engineering Support Branch. 78/08/30. 9pp. 94400:078.
- 7811290188 Forwards IE Circular #78-18. "UL Fire Test, "W/encl AND: 7811150002.

  @RIER, B. H. Region 1. Philadelphia. Office of the Director. 78/11/06. ip. 94239:219.
- 7812130167 Forwards IE Bulletin#78-12A.suppl to 1E Bulletin#78-12. H/Pncl ANO.7811300055. ORIER.B.H. Region i. Philedelphia. Office of the Director. 78/11/24. 1p. 94212:237.
- 7812290254 Ack receipt of 781120 ltr Informing NRC of steps taken to correct violetions noted during inspect50-322/78-12.
  CARLBON.R. T. Region 1. Philedelphia. Reactor Construction & Engineering Support Brench. 78/12/04. ip. 94191:298.
- --781229025B Responds to 780830 NRC ltr rs violations noted in Inspec Rept#50-322/78-12-01. Corrective actions: evel of sampling Inspec of undersized welds on pipe stool slip-on flanges indicate defects on class 150 & 301. Repairs will be made. MOFFORD. A. M. Long Island Lighting Co. 78/11/20. 1p. 94191:299.
- 7812270469 Ack receipt of 781124 ltr informing NRC of steps teken to correct violations named during Inspec#50-322/78-18. CARLSON, R. I. Region J. Philoselphia. Reactor Construction & Engineering Support Branch. 78/12/06.
- --78:2270478 Responds to 78:10:17 NRC itr re violations noted in Inspec Rept#50-322/78-15. Corrective actions: tubular pipe supports having Blaued Tae Joints reviewed & those having angle less than 60 degraes identified. WDFFORD. A. H. Long Island Lighting Co. 78/11/24. 2pp. 94016: COR.
- S. Reportable occurrences. LERs & related correspondence
- 7810270190 Rapts deficiency w/miscellaneous alec fittings used in the Installation of cable tray & conduit supplied by vendor not listed in field use spec No corrective action required. NGVARRO, J. P. Long Island Lighting Co. 78/10/10. 3pp. 94054:237.
- 7811150172 Ack receipt of 781010 ltr re cable tray & conduit support fittings certifications. Rept will be reviewed & evaluated & util will be contected if further info je required. 'CARLBON.R. T. Region 1. Philedeiphie. Reactor Construction & Engineering Support Branch. 78/11/01, 1p. 94242:346.
- 7812070i10 Ack receipt of 781103 finel rept re pipe break outside containment.
  CARLBON, R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Brench. 78/11/21. 1p. 94271; 191.
- --7812070115 Final Deficiency rept on Pipe Break Gutside Containment, SEM Computer progressited in nonconservative temp predictions. Corrective action: new computer model & environ analysis of temp conditions. Equip eval is in progress.

  NOVARRO, J. P. Long Island Lighting Co. 78/11/02. 488. 94071-188

- 7812260211 Rept of deficiency in Beiley Controls pur supplies installed in 10 Category I apple principally HVAC analog instrumentation control loops. All potentially defective pur supplies will be replaced.

  NOVARRO, J. P. Long island Lighting Co. 78/12/11. 2pp. 94160:175.
- 78:2260215 Deficiency rept on installation of socket weld fittings on Category I schedule i60 small bore pipe. All fillst welds for eocist weld fitting attachments will be inspected for proper fillst leg length NDVARRO. J P Long Island Lighting Co. 78/12/11. 4pp. 94162:094.
- A. Application/construction stage documents & correspondence
- 7811210113 Forwerde 781107 itr to Chairman Hendrie rs ACRS review of appl for permits to oper eubj facil STOLZ-U.F. Light Water Reactors Branch 1 78/11/14. 3pp. 94482:172
- 78:20:00:0 Forwards steff eval of probabelietic emismic risk assessment covering. PQE studies on probabilities of earthquakee & resulting ground acceleration at site. & probabilities of various consequencee
  BTOLZ.J.F. Light Weter Reactors Branch i. 78/ii/2i. 3pp. 94409: 128
- --7Bi2010014 Discusses PQE studies in 1977-78 on probabilistic eval of eerthqueke hazard.Various eesumptione are questionsd. STEPP-J.C. Gsosciences Brench. 78/05/08. 4pp. 94409:i3i.
- --7812010015 Forwarde staff evel of Amend 52 to lic appl re Riek to Pub from Betemic Events. BURL.A.R. Probabilietic Analysis Brench (Pre 791030). 78/09/08. 7pp. 94409:135.
- --7Bi2010019 Clarifiss certain points of eval of analysic of rick to pub from exismic syente contained in 780908 memo. Covers probability of Core meltdown. & certhquake probabilities. BURLAR Probabilistic Analysis Brench (Pre 791030). 78/81/06. 2pp. 94409:144.
- 78i2120i61 Forwards 8 requests for exemption from ABME Code Section ii pump & vaive testing requirements. Requests 1 thru 4 are continuations of attachments 7 & 9 to 771010 PGE itr recompliance w/Bection 50.55a(g).10CFR50.

  CRANE.P.A. Pecific Cas & Elsctric Co. 78/12/06. 10pp. 94276:343.
- 7812210200 Seismic test procedure for 125 volt DC suitchgeer, distribution panel & mold cese circuit breakers. PATIERSON, H. OOAD, L. F., SHIPHAY, Q. D. Pecific Qae & Electric Co. 78/11/28. 34pp. 94279.031.
- 78:01:401:4 Forwards matl in support of open lic eppl re environ qualification of equip. Requests ack of receipt of Metl. CRANE.P. A Pacific Ges & Electric Co. 78/09/21. 16pp. 94421:081.
- 7810130058 Forwards responses to informal questions posed by 780804 NRC memo on seismic qualifications. Submission is nonproprietary version.

  CRANE.P.A. Pacific Gas & Electric Co. 78/09/22. 64pp. 94081:194.
- 781019007: In response to 780321 NRC request for additinfo on containment purging, forwerde enswers to queetions, dreft Tech Specs & rept on "Analysis of Off-Bite Exposures due to LOCA coincident w/Containment Purging."

  CRANE.P.A. Pecific Gee & Electric Co. 78/09/27. 106pp. 94323:001.
- 7810170179 Forwarde response to 780728 ltr rs reactor vessel mati properties noncomplience w/10CFR50, Appendix G. fracture toughness requirements. & 10CFR50, Appendix H. reactor vessel metl surveillancs prog requirements.

  CRANE.P. A. Pacific Ges & Eisetric Co. 78/10/02, Epp. 94270:073,
- 7810310226 Forwards responses to 780728 NRC itr re reactor vessel meth properties noncompliance w/100FR90 toughness & surveillance requirements. Requeste ack of receipt.
  CRANG.P.A. Pacific Oas & Electric Cp. 78/10/02. 8pp. 74090:339.
- 78i0170221 Submits info re "degraded grid voltage" as result of discussions w/Instrumentation & Control Sys Branch reviewer on 780929 se suppl to previous eubmittals on second level under/aver voltage protec, Design is acceptable by ICBB rav. GRANE.P. A. Pacific Oas & Electric Co. 78/10/04. ip. 94236:145.

- 7810230038 Ack receipt of 780906 ltr re subj facil Provides Info or selsmic easessment of site decomm estimate & Waste mgt.
  DIRCKS.H.J. Opfice of the Executive Director for Operations.
  78/10/06. 3pp. 94032:333
- --78102300A2 Requests eddl info re issuance of constr permit. BURTON, P. House of Rep. 78/09/06. ip. 94052-338.
- 7811290294 Trip rept:plant visit & mesting w/seplicant on 780905 to discuss remaining open issues re-subj facil. W/summary of remaining unreceived ieeeee

  KUD.P. T. Structural Engineering Branch. 78/10/06 4pp. 94239:
- 7810170205 Attached Table & 3-iO, which appeared in Amend &7, has been changed as indicated to reflect Steff's concerns re-edded values position & function. Change to be documented in future amend. Five copies of submittal sent to D. Allison. CRANE, P. A. Pacific Gas & Electric Co. 78/10/io. 2pp. 94235:33
- 78:01601:8 Forwards emand fas per 7808:1 & 23 requests for extension const completion dates of CPPR-69 & CPPR-39.
  CRANE.P.A. Pacific Gas & Electric Co. 78/10/il. 2pp. 94005:16
- 78i0170229 Summarizes discussion w/NRC.PQE. & QE on 780830 in Bethe MD. re-electrical penetretion qualification. CRANE.P.A. Pacific Qas & Electric Co. 78/10/11. 4pp. 94236:17
- 7810230205 Responds to requeste of 780811 & 780823 by issuing Order estending construction dates for subj facil. STGLT-U.F. Light Water Reactors Brench 1. 78/10/13. 3pp. 94372:203.
- --7810250212 Order extending constr completion dates for subj facil 790430 for Unit i & 781031 for Unit 2.Eval of Request for Extension of Conetr Permit encl. 8070.R.B. Division of Project Hanagement, 78/10/13. Epp. 94372:356.
- 7B10260219 Forwards esismic design audits & lists squip qualified feevers environ.
  ALLIBON.D. P. Light Water Reactors Brench 1. 78/10/16. 34pp. 94058:112.
- 78:1080257 Forwards gen repair prog for arc strikes & weld epatter ASME Cods Class i.2 & 3 pressure boundaries in eccordance w/ requirements of ASME Cods section XI.summer 1978 addendum. W/o encl.
  CRANE.P.A. Pacific Qas & Electric Co. 78/10/16. 2pp.
- 7810260099 Summary of 781012 meeting re seismic qual of elec equip. Reviswed test results of elec aquip. Did not discuss review of mech aspects of test involving type t severity of sheking. H/enci hist of attenders & resulte of discussion. ALLISON. D. P. Light Water Reactors Branch 1. 78/10/18 13pp. 94367:309.
- 7BiiOlO3Bi Bummeriree 7BiOO5 meeting re sub; Patil review sched. Ob of meeting: to discuse stetus of numerous specific items under review & to identify items of most concern re meeting the schedule\_Liet of attendees and.
  ALLIBON, D. P. Light Water Reactors Brench i, 78/10/18, 15pp. 94388:149.
- 7811020029 Summery of 781020 meeting re selemic quel of subj facil elec equip, 15 items found acceptable & 8 items fiseded mod. All items pertain to instru/Control Sys.W/enci Brench Review of NSBS scope equip w/in Meetinghouse quel prog. ALLISON, D. P. Light Water Reactors Stench 1, 78/10/25, 9pp. 94374:117.
- 78ii060021 References commente in matter of cross-exemination of consultants to ACRS at licensing froc be decided as soon as possible. Comm will consider the matter on a generic basis since 3d agrees that it is a top-level policy question.
  30MERS.E. B. Atomic Bafety and Licensing Seerd Panel. 78/10/27. 04422:219
- 7811080040 Ack receipt of 781020 NRC ltr.Repeats opposition to croexamination procedures of ACRB consultants in liceneing proc. CRANE,P.A. Pacific Gas & Electric Co. 78/10/27. 1p. 94398:11
- 7811080005 Forwards 781026 Gen Elec response to 780830 NRC question subj facil elec penetrations qual. Bome info is new. ALLIGON.D. Light Water Reactors Branch 1. 78/10/30. 3pp. 94397:343.

- --7811080008 Responds to questions raised at 780830 meeting w/NRC requalification of elec penetration esteablies for subj facil.
  Addresses justification of qual by similarity verification of repaired assemblies & GE knowledge of repair.
  CLEVELAND, J. W. General Electric Co. 78/10/16. 14pp. 94397:346.
- 7811070271 Advises that cannister-type penetrations meet environ qual requirements consistent withose found acceptable for Three Mile Island, Also supplies data its main line steam break analysis & use of dissel generator under test.

  CRANE, P. A Pacific Oas & Electric Co. 78/11/02. 2pp. 94040:284.
- 7811200366 Forwards OE draft ltr is testing of penatrations-adequacy of repair. GE tested a loaking-unrepaired penatration to test apoly seal & concluded that a repaired penatration should not act differently

  LAINSD. Plant Systems Branch (Pre 791030). 78/11/09 ip. 94419:211.
- --7811200984 Responde to 780830 NRC ltr questioning qual of electrometration assemblies supplied to subj fecil, incl attachment on "Companison of Commister & 100 Series Penetration Designe". CLEVELAND. J M. Openeral Electric Co. 78/10/26. 13pp. 94419:212.
- --7811200392 Final prototype test rept "Hillstone 2 Elec Penetration Post-LOCA Prototype Test". Low voltage pur & control modules were subjected to 143F degree. 5 psig. 1002 RH environ for 52 weeks Leakage rate was less than 1:10 to 8 pur cc He/sec. LURIA. N Q. General Electric Co. 78/11/09. 4pp.
- 7011210234 Forwards salamic qual summary forms for all HE valves identified in Tables 7-7 & 7-7A of "Hospri Rapt." ANDERSON T.M. Westinghouse Electric Corp. 78/11/10, 33pp. 94497:149.
- 7811210018 Presents ACR8 conclusion from 781102-04 meeting that Dr Luco's concerne re-seismic eval bases for subj facils were considered in findings & recommendations in 780714 ACR8 rapt LAMPOSKI. 8. ACR8 Advisory Committee on Reactor Befaguards. 78/11/07. pp. 94482:175.
- 78120500B3 Formards Rev#1 Oraft Radioligical Effluent Tach Spec for Pur's (MURRO-0472) t "Preparation of Radiological Effluent Tach Spec for Nuc Pur Plants" (NUREG-0133), H/o encl ANO: 7811270173 t 7811270180 VABBALLO, D. B. Assistant Director for Light Water Reactors, 78/11/16. Spp. 94036:164.
- 7811220181 Forwards Amend#72 & Amend#73 to Oper Lic appl. CRANE.P A Pacific Oas & Electric Co. 78/11/20. 3pp. 94387:001.
- ~~7811220182 Amend#72 & Amend#73 to Open Lic appl w/addl matl for Hoegri Belamic Eval & FSAR, respectively. BOHACKLEFORD, B. Pacific Gae & Electric Co. 78/11/15. 286pp. 94387-004
- 781:300364 Informs POE that NRC have contracted w/Mountsin West Res Inc to undertake a series of post-licensing studies of nuc pur estations. Studies will anelyse eocloseon impacts which occurred during constr & post-constr periods of each plant. DEVOUND, N.C. Division of Site Sefety & Environmental Analysis. 78/11/20. 2pp. 94116:299.
- 7811300079 Porwards log of contacts from 780419-780505 by resident POLE engr in Betheede Por Ileison w/NRC. ALLISON D. P. Light Water Reactors Branch 1. 78/11/21. 12pp.
- 7812210229 Forwards esiamic teet procedure for aub; facil 4160V Clase iE Buitchgear Bus Undervoitage Relays. CRANE. P. A. Pacific Oas & Electric Co. 78/11/28. 1p. 94279:129.
- --7812210235 Seismic test procedure for 4160V Class 16 Switchgear, Undervoltage Relays, demonstrates relays performence while being switched on & off during the shats. HERBST, J.E., NIEUSEN, D., COLWELL, J.W. Pecific Gas & Electric Co, 78/11/27, 31pp. 94279:130.
- 7812120208 Requests add1 info re means of accomplishing quality inspec at sub; facil. 8TOL2.J.F. Light Water Reactors Branch 1. 78/11/20, 3pp. 94276:061.
- 7812210197 Forwards seismer test procedure for subj facil diesel generator control cabinet. CRANE, P. A. Pacific Cas & Electric Co. 78/11/30. 1p. 94279:068.

- --7812210209 Beismic test procedure for dissel generator control cabinat Tests will demonstrate that relays are capable of changing state during a selemic event if necessary. HERBST. J. E. NIELSEN. D. COLNELL. J. H. Pacific Oas & Electric Co. 78/11/30. 9pp. 94279:069.
- 7812210223 Forwards selemic test procedure for subj facil local starter LPF35. CRANE.P.A. Pacific Que & Electric Co. 78/12/01. 1p. 94279:121.
- --7812210225 Seismic test procedure for local starter LPF35. Tests will determine if LPF36 motor contacts main pur contacts change etats during a seismic event.
  YOUNG.R. A., NIELBEN.D., COLWELL, J. H. Pacific Gas & Eisctric Co. 78/12/01. 3PP. 94279: 122.
- 7812130389 Forwards 781101 ltr from Wiley Labe re test mounting configurations for seismic qual testing of elec equip. This meso places meta in file & the PDR & informs parties of info availability.

  ALUBON.D.P. Light Water Reactors Branch 1. 78/12/06. 3pp. 94292; 231.
- --7812130390 Clarifles questions raised at 781020 meeting re test prog for elec equip. SHIPMAY, Q. D. Affiliation Unknown, 78/11/01. 2pp. 94292:234.
- 78:2130033 Forwards informal info "Invastigation of A Saiche due to Design Spectra at Rew Water Storage Reservoir: Subj Facil Nuc Proj" by CE Cacillo discussing potential for eaching in raw water reservoirs.

  ALLISON, D. P. Light Water Resectors Brench 1. 78/12/06. 20pp. 942(0:030
- 7812210193 Forwards estemic test procedure for 125 VDC ewitchgear, distribution panel & mold case circuit breakers & test rept sattisted "Beismic Testing of Befety-Related Elec Equip for POE."

  CRAME.P. A. Pecific Que & Electric Co. 78/12/06. App. 94279:027.
- 7812280095 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inscruracies or anforcement action will result. DAVIS.J. G. Office of Inspection & Enforcement. Office of the Director. 78/12/06. App. 03555:311.
- 7812190143 Forwards rapt presenting results of a large-break loss-of-coolant/LDCA/eccident. New enalysis incorp a correction to cled-weter hest of reaction calculation & recent ECCB eval model laprovements.

  CRANE, P. A. Pacific 9ss & Electric Co. 78/12/07. 78pp. 94376: 031.
- 7812190374 Forwards request for add1 info re bolted connections in linear supports of subj facil support base plates. Requests response sched.

  8TOLIJE. Light Weter Reactors Branch 1. 78/12/08. Spp. 94357:275.
- 7812260217 Requeets edd1 time to dev dreft Appendix 1 Tech Specs. Proposes submittel by 790216. GRNE-P.A. Pecific Ges & Electric Co. 78/12/14. 1p. 94162:098.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7812070055 Forwards Suppl 8 to SER for subj fecil. VASSALLD, D. B. Assistant Director for Light Water Reactors. 78/11/15. 1p. 94462:032.
- ~~7812070063 Forwarde Supplies to SER for subj fecil. STOLZ.J.F. Light Water Reacture Branch 1. 78/11/14. 3pp. 94462:033.
- --7812070067 Suppl B to facility SER.

  \* Division of Project Management. 78/11/15. 110pp. 94462:001.
- 7812050155 Forwards additinfo to address Bection7.8.open item 3 of SER Buppl 7.re environ qual of Fan Cooler Pur Cables, Attachment 81 on Speck, Tasks & Installation of Hires & Cables at subj facil is not enci.

  CRANE, P. A. Pacific Gas & Electric Co. 78/11/27. 12pp. 94335;074.
- F. Becurity, medical, emergency & fire protection plans
- 7811270307 Summery of 780214-15 meeting w/util re subj facil fire protec prog.All mode will be made prior to fuel loading. HEARN.P.C. Auxiliary Bystems Branch. 78/03/29. 33pp. 94181:306.

- 7811210164 Forwards ray rasponses to NRC fire Protec Review questions 5.8,9,21,23,24,26-29.45,46 & 49-51 & ray rapt "Supplementary Info for Fire Protec Review." Review question (tems inc): Constr design, fire protec valves & automatic aprintlers. CRANE.P.A. Pacific Oas & Electric Co. 78/11/13. 34pp. 94485;294.
- --7811210169 "Suppl Info for Fire Protection Review." \* Pacific Gas & Electric Co. 78/11/13. 138pp. 94486:001.
- 7Bi1290400 Forwards suppl detailed info related to subj fecile seismic design audite & the fire protection review.W/31 drawings available in Central Files.
  ALLIBON, D. P. Light Weter Reactors Branch 1. 78/11/21. 1029pp. 941B2:001.
- 7812290102 Review of fire Protec safety evel rapt for subj fecil has been completed. Concurs in NRC findings & in NRC conclusion that upon implementation of mode listed in rapt, fire protecting will be acceptable.

  BEHN.J.D. Oage-Babcock Associates, Inc. 78/11/29. ip. 94190:116.

## Q. Adjudicatory correspondence

- 78iii00014 No objection to Intervanor's request of 78i016 to subpoena Dr Graha for the upcoming evidentiary hearing.
  TOURTELLOTTE.J. Office of the Executive Legal Director. 78/10/97.
  1p. 94176:351.
- 78:2010048 Expresss view on gen policy question of subpoening ACRB consultents to require their attendence at evidentiary hearings before ABLB Exceptional circumstences standard should not be limited to direct knowledge witnesses. FLEIBCHAKER.D. Center for Lew in the Public interest. 78/11/14.3pp. 94416:133.
- 7812010198 Attorney RK Hoefling enters appearance in captioned matter. Cert of Svc encl. MDEPLING.R.K. Office of the Executive Legal Director. 78/11/09. 3pp. 94409:235.
- 7812040179 Applicant OGE has until 781205 & NRC Staff until 781211 to respond to intervenor's Patition for directed certification to review ASLB's rejection of DD Comey as an expert witness on security matters.

  DUFLD.M.E. Atomic Befaty and Licensing Appeal Panel. 78/11/21.

  2pp. 94875:073.
- 7812080024 Requests to make appearance statement at 781204 hearing in Ban Luis Obiego County CA. RICEL. Affiliation Unitnoum. 78/11/27. 1p. 94104:002.
- 7812110219 Asks whether seismic hearings will begin 781204. Believes facil should not be allowed to oper for love of humenity in general.
  ROBENBERG, H. Affiliation Unknown. 78/11/17. ip. 94337:353.
- 7812180037 Forwards "Interpretive Comm Stetement on Amenebility to Subpoems of Consultants to ACRS under 10CFR2.720." which now represents the Comm's views & which will be presented for formal vate at next Comm Affirmative Session.

  KELLEY.J.L. Office of the Executive Legal Director. 78/11/29. ip. 74130:341.
- 7810160135 Requests by intervenors for production of documents by NRC staff & applicants & enlargement of time to file interrogs, also submits interrogs to appl & requests that attached documents be explained. FLEIBCHAMER.D., PHILLIPS.J. Center for Lew in the Public Interest. 7B/09/27, 19p. 9400b;143.
- 7810190207 Forwards various pleedings of Intervenors(Beanic Shoreline Preservation Conference, San Luis Obispo Mothers for Peece, Ecology Action Club, B. A. Silver, & J. J. Forster)re oper 11c. PLEISCHAKER, D. Fleischaker, D. 9. 78/09/28. 3pp. 94052:017.
- --7810190262 Intervenors(Scenic Shoreline Preservation Conference, etc).
  request for oral argument.
  FLEISCHAKER, D. Fleiechaker, D. B. PHILLIPB, J. P., KRISTOVICH, S.
  Center for Law in the Public Interest. 78/09/28. 3pp. 94052:020.
- --7810190267 Intervenors(Scenic Bhorelins Preservation Conference, etc)
  request to reply to NRC & applicant response to intervenors
  request for istuance of ABLB subposense.
  FLEIBCHAKER, D. Fleischaker, D. S. PHILLIPS, J. P., RIBTOVICH, B.
  Center for Law in the Public Interest. 78/09/28. Spp. 94052:093.

- --7810190269 Intervenore (Scenic Shoreline Preservation Conference, etc.)
  request to reply to NRC & applicant response to intervenore
  request for lawance of ASLB subpoenes.
  FLE18CHARER, D. Fleischaker, D. 9 PHILLIPS, J.P., KR18TQVICH, 8
  Center for Law in the Public Interest. 78/09/28 32pp.
  94052 025.
- 7810140108 Natice of reconstitution of ABLAB re OL proceeding.

  R Salzenia Rosenthel & M Johnson will serve on board

  DUFLO M.E. Atomic Befety and Licensing Appeal Panel. 78/10/03 lp.
- 7811010324 Suppl Nemo in support of intervenor SLOM appeal from 780511 & 780505 Orders re quel of security experts BLOM now seeks direct certification & quel only of D Comey es security expert for discovery purposes.

  JUNES, Y. 1. . VALENTINE, P. C. San Luie Obispo Mothers for Peace.
  78/10/06. 22pp. 94387:275.
- 78:0190126 Grants request by intervenor for extension to 78:006 to respond to PGE motion to dismiss security contention.hRG staff is also granted extension to 78:006.per their request. BOWERS E.S. Atomic Sefety and Licensing Board Penel. 78/10/10. 2pp. 94414 025.
- 7810250182 Denies request by Intervenors that 8d subpoens 13 persons as withseses in evidentiary heering. Denied because 06 receine unconvinced that circumstences are exceptional & warrant granting the request.

  BUNERS.E. 8. Atomic Sefety and Licensing Board Panel. 78/10/10.

  App. 94392:234.
- 781030000B Requests Bd stay issuance of eny order on Applicants motion to diemies security contention until Appeals Bd issues ite ruling in repeonse to intervenors motion for direct certification. W/encl cert of svc. VALENTINE.P.C. Ban Luis Obispo Mothere for Peace 78/10/10. App. 94034:216.
- 78:0300350 PQ&E response to intervenor SLOM's Petition for direct certification & SLOM's appeal from ABLB Order of 780905. PQ&E asserts that csrtification is not appropriate Supporting documentation & Cert of Svc enci.

  NORTON.B. . MORRISGEY.J.C., CRANE.P.A. Pecific Ges & Slectric Co. 78:10113 35pp. 94253:279.
- 7810270274 Intervenor's Request to Bubpoens Dr 8 Orahem to testify recontentions that Applicent has failed to conduct thorough investigations of Hosgri Fault sys. Cart of 8vc encl. FLEISCHAKER, D. Fleischaker, D. B. PHILLIPB.J.P., RRISTOVICH, B Affillation Unknown. 78/10/16. 11pp. 94023:347.
- 7810300128 Advises Lic Bd of status of 6 independent experts subpossed at request of Intervenors. FLEISCHAKER.D. Fleischaker. D. 8. 78/10/16. 2pp. 94035:140.
- 781101031B NRC Steff Anewar to Appl Motion to Dismiss Security Contention, Staff suggests the 3d dafer on a ruling while Intervenor Sen Luis Obiespo Mothers for Peece Ausits ruling on their Appeal re the security issue.

  STAENBERG, M.R. Office of the Executive Legal Director. 78/10/16, Spp. 94387:285.
- 7810300082 Informs Bd that Staff will comply w/Intervanor's request for documents & interrogs to the Staff no later than 781025 due to error in mails. There will be the same answering time originally anticipeted by parties.

  TOURTELLOTTE, J. Hearings Division. 78/10/17. 2pp. 94035:096.
- 78:10:10099 Replies of Bub; Util to Intervenors' Interrops dbd 780997.
  Resumes of Guel for Safety Heerings & Cert of Byc encl.
  GRAGE,P.A., NORTON,S., FURBUSH,M.H. Pacific Ges & Electric Co.
  78/10/17. 95pp. 94290:008.
- 7Bii:130314 Forwards subposes for signature of E Bowere. One will be served upon Dr Stephen Graham; the other 2 copies ere for file reference. FLEISCHAKER, D. Fleischaker, D. B. 78/10/23. ip. 94087: 042.
- 7811060058 Notice of addition of & J Bullivan to list of staff witnesses provided in Rept 1978 Davis for re-radiological health & safety hearings.
  TOURTELLOTTS, J. Office of the Executive Legal Director. 78/10/20.
  Epp. 94423;325.
- 7811130199 "NRC Staff Response to Intervenor's San Luis Obispo Mothers for Peace Petition for Directed Cert & Appeal from Licensing 8d Order of 780905." Urges Intervenors petition be denied. Cert of Svc encl.
  8TAENBERG.M.R. Office of the Executive Lagel Director. 78/10/26.

- 78if080i85 flamorandum & Order grenting the petition for directed certification vacating Bd's 780905 order & remanding the cause for immediate further consideration consistent withis opinion in the oper licensing proc.
  DUFLO.M E. Atomic Sefety and Licensing Appeel Panel 78/10/27, 12pp 74405:113
- 78:1080029 Forwards "Staff Commente on Generic Matter of Cross-Examination of ACRB Consultants in NRC Licensing Proceedings" Wiencl Cert of Svc.
  TREBY.S.A. Office of the Executive Legal Director. 79/10/30. 18pp. 9439:067
- 7811280489 Notice that PGE will teka depositions of E Silver, J Brune & R Hubbard. Also encl is response of PGE to intervenors' request of 780927 for production of documents. Documents sought are now available for inspec. Cert of Syc sncl CRANE, P. A. Pacific Oas & Electric Co. 78/10/30. 4pp. 94414,269.
- 7811070358 Urges ACRS permit cross-esemination of consultents, Cross-esamination is essential to accurate interpretation of opinion 5 determination of factual bases of essumption. VALENTINE, P. C. Valentine, P. C. 78/10/31. 1p. 94043.196.
- 7811170007 "Reconsideration of Bd's Order of 780905." Petition of San Luis Obiago Mothers for Peace to establish David Comsy es an expert witness is denied.

  80NERS. S. Atomic Safety and Licensing Board Penal. 78/11/03.

  3789. 94116:104.
- 7811200042 Evidentiary hearing on 781204 will be held in Avila Baech, CA First 2 days of heering will be set aside for limited appearance statements of no longer than 3 minutes sech. Hritten statements of any length may be submitted.

  BOMERS.C. 8. Atomic Safety and Licensing Board Penel. 78/11/07.
  2pp. 78215:224.
- 7812040321 Testimony of N Newmark re aerthquala resistance design criteria utilized in constr of subj facile. "Rationele for Development of Design Spectra for Diablo Canyon Reactor Facil" & Cert of Svc ancl. NEWMARK.N. M. N. Newmark Consulting Engineering Services, 78/11/15. 75pp. 94122-001.
- --7812040324 Testimony of CJ Stepp re aubj facil seismic concerns addressed during constr parmit & Oper Lic review. STEPP, J. C. Geosciences Branch, 78/11/15, 41pp. 94122;076.
- --78:2040027 "Dieblo Canyon Testimony of J Knos & F Rose to Beismic Qual of Class IE Equip." discussion of esismic qual eval with criteria in Bafety Eval Rapt 3.10 & auppls. ROBA.F. Power Systems Branch. 78/11/15. 12pp. 94122:117.
- ---7B12040930 "Testimony of RB Hofmann" is conservative value for ground acceleration from a 7.50 serthquake on the Hoagri fault. HUFMANN, R. B. Office of Standards Development. Director. 7B/11/15. 22pp. 94122: 129.
- --7812040334 Tastimony of MJ Hall is edequecy of the etructurel criteria for Unit R for an 88E of 0-4 g Found during both reviews (1967-9 i 1975-8) that facil had sufficient realetence to meet salemic haisrd.

  HALL+M.J. Affiliation Unknown. 78/11/08. 7pp. 94182:151.
- --7812040338 Testimony of JP Knight re the scientic design process (definition of risk & dasign of sufficiently resistant structures) & its relation to the auby fecil saismic raviaw. KNIGHT.J.P. Assistant Director for Engineering. 78/ii/15, 36pp. 94122:158.
- 7812130006 Request for info re hearings on sub, facil. TURNER, A. J. Affiliation Unknown. 78/11/15, ip. 94207:172.
- 7812:80324 Forwards testimony on bahalf of Intervenors re Contention I, Gaology & sets forth conclusions re through-poing continuity of the San Gregario-Hosgri fault zone. Resume. Study results & Cart of Svc encl.
  ORAHAM.S.A. Affiliation Uninown. 78/11/17, 19pp. 94336:299.
- 78:2180309 Petition for directed certification for review of "Reconsideration of Bd's Order of 780905" relating to qual of security expert Forwards Cart of Svc.
  VALENTINE.P.C. San Luis Obiepo Mathers for Peacs. 78/11/20, 40pp. 94336:190.
- 7812050191 Memorandum ack receipt of intervanor's Petition for Directed Certification, Applicant's response in due 781205;8teff's 781211.8d will not favor requests to extend time.

  DUFLOM E. Atomic Safety and Licensing Appeal Panel. 78/11/21.
  299. 94382:122.

- 78:2130:146 Porwards list of publications & rev qualifications sheet omitted from 780927 Staff's response to Intervenor's interrog.

  KETCHEN.E. G. Dffice of the Executive Legal Director. 78/11/21.
  22pp. 94289:064.
- 7812060004 Order granting permission to make opening statements pricto limited appearances. Each stetament limited to 20 minutes. No change util be made from stated location.
  BOHERS.E. B. Atomic Safety and Licensing Board Penel. 78/i1/27.
  2pp. 94103:314.
- 7812140346 Forwards list of publications of JF Davins & resume of F McKeown. KETCHEN.E. Q. Office of the Executive Legal Director. 78/11/27. 10pp 03557-175.
- 7812140085 Suppl reply of POE to intervanors' interroga of 780927. Forwards nemss & quals of 4 addi witnesss POE intends to call in the licensing hearing re subj facile. Cert of Svc encl.
  CRAMS.P. A., NORTON. 8. HORRISSEY, J. C. Pacific Ges & Electric Co. 78/11/28. 10pp 94128: 231.
- 7812140344 Gives notice that E Ketchen enters on appearance on behalp FRC in procine subj facils. Cart of Svc encl.
  KETCKEN.E. G. Office of the Executive Legal Director. 78/11/28. : 03557:168.
- 7812140373 Confirms 781122 convarsation of a status of 2 USOS witness appearing for NRC Both witnesses whose USOS mept which is append C to Suppl 4 of SER & will be et hearing to enswer questions.
  TOURTELLOTTE, J. Hearings Division. 78/11/29. 1p. 03558:118.
- 7812180027 Forwards mamo to subpose to ACRS consultante entitled "Interpretive Comm Statement on Amenebility to Subpoens of Consultants to ACRS under IOCFR2.720."

  BOMERS.E.B. Atomic Safety and Licensing Board Penel. 78/11/30. 4pp. 94130:340.
- 7812180416 NRC Staff's Response to Petition submitted by intervenor Luis Obispo Mothere for Peece seeking review & reversal of ASL8's upholding of deniel of D Comey's quals. NRC urges that intervenor's petition be denied. Cert of Svc ancl. STADMBERG, M. R. Office of the Executive Legal Director. 78/12/01 Dpp. 74336:338
- 781221032: "Suppl Reply of Jt Intervenors' to Applicant's Interrogs 780927. " Cart of Svc enci.
  HUBBARD.R.B. MHB Technical Associates. 78/12/01. 4pp. 94407:3
- 78:2270025 Urgss approval of plant oper as acon as possible.einca t also pur is vitally needed. RUSSELL.H.K. Affiliation Unknown. 78/12/05. ip. 94:59:239.
- 7812140273 Forwards Amend®1 to Constr Psrmit@CPPR-39 & Amend®4 to Constr Psrmit@CPPR-69 w/related correspondence, OLDBERQ,J.R. Office of the Executive Lagel Director. 78/12/07. 1p. 03557:289.
- --7812140275 Forwards AmendM1 to constr permitMCPPR-39 & AmendM4 to constr permitMCPPR-69 & Fed Register Notice.
  BOYD.R.B. Division of Project Management, 78/12/06. 4pp. 0357: 290.
- --7812140278 Amend#1 to Constr Permit#CPPR-39, adding antitrust cond to Peragraph 2.D. SOYD.R.B. Division of Project Management. 78/12/06. 10pp. 00557:294.
- --7812140279 Amend#4 to Constr Permit#CPPR-69.adding entitrust cond to Paragraph 2.D. BUYD.R.B. Division of Project Hanagement, 78/12/06. 10pp. 03957:304.
- --7812140283 Notice of lecuence of Amandel to Constr Parmit#CPPR-39 Amend#4 to Parmit#CPPR-69. W/encl Evel of Amand by LWR#1. BTDLZ, J. F. Light Meter Reactors Brench 1. 78/12/06. 5pp. 03557: 314.

# H. General correspondence

7812110040 Responds to 781030 ltr re esismic design conservation to W/regard to elec load projections & notice of hearing. BALLARD, R.L. Environmental Projects Branch 1. 78/11/30. Epp. 94408;149.

- 7811120130 Expresses concern over role of nuc energy in US energy progreugeste more res be directed towards solar energy.

  Deplores Liquid Hetal Greeder Reactor & the idea of siting a plant on the James River near her home.

  NELSON.E.S. Affeliation Unknown. 78/10/21. 3pp. 94272:361
- 7611210312 Ack receipt of 780918 ltr & environ impact statement. Request data & location of public hearing on subj facil & submits questions of concern re subj facil.
  MURPHY.E. Affiliation Unknown. 78/10/30. ip. 94488:090.
- 7812180289 Forwards for Dept of Energy Response, a memo re an inquiry by 9 Surns into who inspects the structural steel of the subj facil.
  LAQUIMARBIND, R. J. House of Rep. 78/11/22, 200, 94365-142.
- 7812270059 Strongly recommands putting subj facil into oper as econ as possible, since the energy is necessary. QEONGL. Affiliation Unknown. 78/12/07 1p. 94160.291.
- 7811210413 Beliaves nut pur cannot be made safe & that constr of subj facil should be atopsed.

  STANLAR, Affiliation Unknown. 78/11/13. ip. 94483:126.
- K. Utility Finel Bafety Analysis Raport (FBAR) & amends
- 78:11:40:26 Forwards copy of Amenda 70 & 71 to open itc appl for subj facile. Amends incl addit mati for Hosgri eval & FBAR. Cant of Svc encl.

  CRANE.P.A. Pacific Gas & Eisetric Co. 78/11/09. 2pp.
- --7811140145 Amands 70 & 71 to Open Lic appl for subj facile. Amands incl addl mell for Hosgri Eval & FBAR. BYMCKLEFDRD B. Pacilic Ose & Electric Co. 78/11/09. 400pp.
- O. Advisory Committee on Reactor Sefeguards reports & correspondence
- 7812150050 Comments transmitted in 780922 ltr from ACR8 consultant E Luco re satemic eval bases were discussed at 781102-04 ACR8 masting. These coments were considered in the findings & recommendations in ACR8 rept of 780714. LAWROSKI, 8. ACR9 Advisory Committee on Reactor Safeguarde. 79/11/07. ip. 94210:253.
- 7811010382 Forwards ACRB consultant rapt subj facil seismic design for info.
  ALL180N,D.P., Light Water Reactors Branch 1. 78/10/24. 3pp. 94388:164.
- --7811010384 Forwards commente by Dr Luco re seismic deeign basis for subj facil. HCKINLEY, J. C. ACRB - Advisory Committee on Reactor Sefeguards. 78/10/13 ip. 94388:167.
- --TBil010288 Comments on 780614 & 780707 acrs meatings ra use of affactive pack acceleration & underestimation of supj factly response to offstors fault resulting from use of large reduction for tau-affact & small torsion excitation. LUCO, J. E. Catifornia, Univ. of, San Diego. 78/09/22. 5pp. 74388:168.
- G. Inspection reports, IE Bullatins & correspondence
- 7810230316 Forwards 1E Circuier#78-17. (Sea AND: 7810230221, Docket 50-313,781013) ENGELKEN.R.H. Region 5. San Francisco, Office of the Director. 78/10/13. 1p. 94166:347.
- 7811220263 Forwards IE Inspac Repts#50-275/78-14 & #50-323/78-14 on 780901-30 during which no items of noncompliance were noted. CREMB(J.L. Region 3, Ben Francisco, Reactor Operations Nuclear Support Branch. 78/10/17. Rpp. 94273:355.
- --7811220267 IE Inspec Repte#50-275/78-14 & #50-323/78-14 on 780901-30 during which no items of noncompliance ware moted. Major areas inspected included: preoper testing, fuel storage, followup on licensee event & IE Bulletin-Circuler, testing. HTERNBERO, D. M. Region 5, Ben Francisco, Reactor Operations Nuclear Support Branch. YOUNG, T., BTERNBERO, D. H. Region 2, Atlante, Reactor Operations Nuclear Support Branch. 78/10/16. Dpp. 94473:357.
- 7811070111 Responds to 781006 NRC itr re violation noted in inspec.
  Corrective actions:circuitry is being placed in conformance
  w/FBAR paragraph 3.3, & implementing instruc will be issued
  by 78116.
  CRANE, P. A. Pacific Gas & Electric Co. 78/11/02. 2pp. 94043:348.

- 78:11:00007 Forwards IE Circular 78-18. ENORLKEN,R M Region 5, San Francisco, Office of the Director. 78/11/06. 1p. 94112:301.
- 7812150001 Forwards IE Ineps: ReptsW50-275/78-17 & 50-323/78-16 on 781001-31 during which no items of noncompliance were noted. CREUR.J L. Region 5, San Francisco. Resctor Operations Nuclear Support Branch. 78/11/16. 2pp 94209:190.
- --7812130004 IE Inspec Repts#50-275/78-17 & 50-323/78-16 on 781001-31 during which no items of noncompilance were noted Hajor areas inspected incliprapper testing-fire protect-plant tour, problem repts if bulletin followup & design changes. YOUNG, T., BTERMERO, D. M. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 78/11/15 App 94209:192
- 7811300088 Forwards 1E Bullatin#78-12A suppl to 1E Bullatin 78-12. W/antl AND:7811300055. ENGLKEN,R H Region 5, Ben Francisco. Office of the Director. 78/11/24 ip.
- 7812290033 Forwards IE Bulletin 78-14. ENGELKEN.R.H. Region 5, San Francisco, Office of the Director 78/12/19. 1p. 06911:001
- S. Reportable occurrences, LERS & related correspondence
- 7812210385 Forwards add1 info re 80 defect in Unit 2 NEMA size#2 motor controllars Unit 1 inspec complete.inspec & replacement of kick-out springs for Unit 2 will be completed prior to functional test.

  WDRTHINOTON.U.D Pacific Oes & Electric Co. 78/12/07. 1p. 94015:094.
- T. Hearing transcripts on non-entitrust matters
- 7812070227 Transcript of POLE testimony on 781204. Testimony of RV Bettinger, DH Hemilton, RH Jahns & SM Smith enci.

  Atomic Befety and Licensing Board Panel. 78/11/20. 239pp. 74188: 016.
- --7812070237 fastimony of POLE on 781204.

   Atomic Bafety and Licensing Board Panel. 78/11/20. 2009p.
  74188.278.
- --7812070242 Testimony of PotE on 781204.

  \* Atomic Sefety and Licensing Board Panes, 78/11/20. 107pp.
  74187:162.
- 7812180056 Transcripts of 781204 hearings re subj Facils Pp 3758-3997. BDMERB.E. MARTIN.M.E.: BRIGHT.G.O. Atomic Sefety and Licensing Board Panel. 78-12/04. 239pp. 94211:030
- 7812130064 Transcript of 781205 hearing re subj fecil.Limited Appserance Statements in Avile Seach. CA.PP 3398-4249. BOMERS.E., MARTIN.H.E., BRIGHT.O.D. Atomic Sefety and Licensing Board Panel, 78/12/05. 251pp. 94296:012.
- 7812200344 Transcript of hearing in Aviis Beach.CA on 781207.
  Appearences on behalf of applicant: 8 Norton.MH Furbuch. E.
  F. Cransson behalf of joint intervanors: DB Flaisheker.8
  Kristovitch & für NRC: E. Katchen. Pp. 4486-4679.
  BOWERS.E., MARTIN.M. E., BRIGHT. 0. 0. Atomic Sefety and Licensing
  Board Panel. 78/12/07. 193pp. 94124: 188.
- 7812200308 Transcript of hearing in Avile Beach, CA on 781208. Appearance on behalf of Pecific Ges & Elec: B Norton, Mt Furbush P Crame, on behalf of joint intervenore: DB Fielschaker, B Kristovich & for NRC: M Steenberg, Pp 4679-4862.
  BDMERS, E., MARTIN, M. E., BRIGHT, G. O. Atomic Befaty and Licensing Board Fanel, 79/12/08. 183pp. 94124:003.
- 7812270345 Transcript of hearing ra subj facil at Avile Beach, CA on 781213.Pp 5309-5506.
  BOMERS.E. Atomic Befety and Licensing Board Panel. 78/12/13.
  1979p. 94229:024.
- 7812220014 Transcript of 781214 hasning in Avila Beach.CA TP subjectiles 5507-5706.
  SOMERS.E., MARTIN.H.E., BRIGHT.G.O. Atomic Befaty and Licensing Board Panal. 78/12/14. 199pp. 94248:024.
- 7812290002 Transcript of a 781218 hearing in Avila Beach CA re sub; facil.Pp 6102-6389.
  BOWERS,E,, MARTIN,M.E., BRIGHT,O.O. Atomic Sefety and Licensing Board Panel. 78/12/18. 257pp. 94208:030.

- 7812290279 Transcript of a morning 781214 hearing at Avila Beach.CA resubj factl.ep £350-£471.
  DOMERS.E. MARTIN.W.E. BRIGHT.O. D. Atomic Safety and Licensing Board Penel. 78/12/19. 11ipp. 94192:001.
- 7812290280 Transcript of 781229 hearing on 781220 et Avila Beach.Co. Pp6472-6688 BDMCR8.C. MATIN.W.E., BRIGHT.O.D. Atomic Safety and Licansing Board Pana1 78/12/20. 216pp. 94193.001.
- 78:2290282 Transcript of 78:22: hearing in Avile Beach.CA re subj facit.Pp 6689~6862.
  BOMERS.E. MARTIN.W.E., BRIGHT.G.O. Atomic Safety and Licensing Board Panel 78/12/21. 173pp 94:99.001.
- 7812290283 Transcript of a morning 781222 heering in Avila Beach CA resubj fecil.pp6853-6949.
  BDMRRS-E MARTIN, M.E. & BRIGHT, Q.O. Atomic Safety and Licansing Spard Penel. 78/12/22. Bapp. 94195:001.
- U. Congressional/Executive Correspondence
- 78i1080032 Responds to encl 780831 & 780925 congressional correspondence w/DDE requesting info to answer constituent's therees the number of subjectil near geologic fault.

  DIRCKS H J. Office of the Executive Director for Operations. 78/10/30. 10pp 94378:089
- DOCKET 50-324 DRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

  A. Application/construction stage documents & correspondence
- 7010130122 Analysis of suppression pool tamp translants as requested by NRC 780113 ltr & as mod et 780309 meeting. Hork has begun & rept will be submitted in about 3 months.

  UYLEY, E. E. Carolina Power & Light Co 78/10/10. 1p 94079:297.
- F Security, medical, emergency & fire protection plans
- 7812080157 Notification of 781217 site visit by R Lesp & D Cameron, security plan reviewers affil w/Los Alamos Sci Lab.

  1PPCL1TD.T A Operating Reactors Brench 3 (Pre 790625). 78/11/30.
  2pp 94107.354
- P. Operating license stege documents & correspondence

1

. 1

ŀΪ

- 7GiOli01iO Responds to 780829 ltr indicating that no incident of control rods failing to fully insert occurred at subj facil.

  UTLEY.E.E. Carolina Power & Light Co. 78/10/04. 1p. 94066:356.
- 7810100143 Hes requested assistance from OE ra undetected eingle failures in reactor protect sys pur aupplies. Hill not be able to respond to 780807 HRC Str w/required info until 781215.

  UTLEY, E. E. Ceroline Pawer & Light Co 78/10/10. ip. 94002:315.
- 7810240127 Requests rev to Tech Spec for subj facil in response to 780912 NRC itr requesting rev to spec on total annual gaseous releases.
  UTLEY, E.E. Carolins Power & Light Co. 78/10/16. 16pp.
- 70:1130335 Burmary of 780914 meeting w/GE representatives & Mark 1 Duners Group re progress of Long Term Prog w/attendence list & agenda(RD-9-A-Marki. Standards.) ORINEB.C Plant Bystems Branch (Pre 79:030), 78/10/26. 67pp.
- 7811090109 Requests rev of Tech Space for subj facil re operability requirements for suppression pool-reactor bidg vacuum breaters. Hanual valves will be closed & valves will be governed by admin controls.
  UTLEY/E.E. Carolina Power & Light Co. 78/11/03. App. 94042:282.
- 78:1240154 Notice of 78:106 meeting in Setherde w/CPt4, to discuss companiatory measures to allow continued plant oper w/single valve (soletion in R8-supression chamber vacuum relief lines.

  HANDON, J. N. Operating Reactors Branch 3 (Pre 790625). 78/11/03.

  19. 94456:259.
- 78:11:60:135 Buppi to 78:103 ltr requesting emend to Tech Boec to mod operability requirements of suppression pool-reactor bldg vacuum breakers. Ltr documents info discussed w/staff during 78:105 meeting & 78:107 telcon.

  UTLEY.E.E. Carolina Power & Light Co. 78/11/08. 5pp. 94:35:236.

- 7811220279 Confirms verbel authorization to change Tach B facil in response to 781103 request. Amend allows ell suppression pool-Resctor Bidg Vecuum breakers to be ope w/opening setpoint of 0.3 psig w/manual valves closed. GRIMES.B.K. Assistant Director for Engineers & Project 790623). 78/11/0B 3ps. 94308:211.
- 78:12:0273 Notifies util of 78:205 seminar in Atlante to Model Rod Effiusht Tech Space & ancl seminar info sheet registration form. & proposed aganda.

  D'REILLY-J.P. Region 2. Atlanta. Office of the Directo 5pp. 94485:162.
- 7811290406 Forwards NRC steff paper, policy session item (relicense reg performence eval. Three methode for eval stetistical, trend enalysis & regional survey method. W/o encl.

  O'REILLY, J. P. Region 2, Atlante, Office of the Directo 2pp. 94180:099.
- 7812150157 Notice of workshops re implementation of train requirements contained in Append B of 10CFR73. Requests pre-workshop registration of ettendees to fectlitate se out catl. W/encl Registration Form & List of Locations. MiLLER.J. R. Assistant Director for Site & Sefeguards ( 78/11/15. 5pp.
- 7812180274 Forwards Rev#1 "Draft Rediological Effluent Ta BMR's(NUREQ-0473) & "Preparation of Radiological Efflue Tech Space for Nuc Pur Plants" (NUREQ-0133). QRIME8-B.K. Assistent Director for Engineers & Project 770223). 78/11/16. App. 94336:346.
- 7812080164 Confirms meeting on 781206 to discuss plans refor refueling outege sched for Jenuary 1979. 1PPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625) 2pp. 94108-008.
- 7812110023 Discusses possible dengers of LOCA in contains during normal pient oper. Requeste either commitment to purging or justification for continuing. A/encl ANO: e7812080207.

  1PPCLITO.T. Operating Reactors Branch 2 (Pre 790625).

  8pp. 94339:302.
- 78:21:03:5 Notification of meeting on 78:206 in Bethasda. condition of jet pump riser safe-ands & evaluate relets action proposed for refusiing outage to begin Jan 1979. HANDN.J. N. Operating Reactors Brench 3 (Pre 790625). ip. 94204:157.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing & providing task-by-task activity summary for the month BDBON.L.J. Osneral Electric Co. 78/12/04. 11pp.
- 7812280114 Emphesizes importance of submitting accurate to NRC by licensess & applicents, info submitted must be substantisted by data & calcoletions. Licenses must not NRC of any ineccuraciae or enforcement action will resum DAVIS. J. 0. Office of Inspection & Enforcement, Office Ofiractor. 78/12/06. 2pp. 94133:228.
- 7812210100 Forwards amends#42 & 17 to DPR-71 & DPR-62 & 1 impact Appraisal & Fed Register Notice.

  BALLARD.R.L. Environmental Projects Branch 1, 78/12/194267-182.
- --7812210102 Amend#42 to Oper Lic DPR-62, changing the In of the cooling tower.

  MORE, V. A. Assistant Director for Environmental Pro
  78/12/15. 2pp. 94269:184.
- --7812210104 Amend#17 to Oper Lic DPR-71.chenging the in of the cooling tower. MORE V. A. Assistent Director for Environmental Pro 78/12/15. 3pp. 94269:186.
- --7812210107 Notice of Issuance of Amends#42 & 17 to Ope 71 & Negative Declaration. BALLARD, R.L. Environmental Projects Branch 1, 78/1 94269: 188
- --7812210109 Environ Impact Appraisal supporting Amends Lics DPR-62 & 71 re cooling tower installation date. 9 Division of Site Sefety & Environmental Analysis, 18pp. 74269:190.

- 78:2270192 Due to delays in OE's analysis of reactor protect ays pursupplies.CPL will be unable to respond to 780807 itree previously committed to in 78:010 ltr. Estimates response by 790301.

  UYLEY.E.E. Caroline Power & Light Co. 78/12/18. 2pp. 94018:038.
- 78:2270207 Forwards results of reactor recirculation safe ands inspec prog including a description of szisting NDS techniques & discussions of alternate techniques Concludes that present techniques used by subj facil are adequate.

  UTLEY.E.E. Carolina Power & Light Co. 78/12/22: 13pp. 94:68:08:
- Q. Inspection reports, 1E Builetine & correspondence
- 7810310134 1E Inspec Repts#50-324/78-19 & #50-325/78-19 on 780808-11 during which no items of noncompliance were noted Major areas inspected included; calibr. surveillance. design & procurement changes & mods
  KELL000,P.J. Region 2. Atlanta, Office of the Director. OU278.J.E. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/09/20. Spp. 94090:133.
- 7810310128 Forwards IE Inspec Repts#50-324/78-19 & #50-325/78-t9 on 780808-11 during which no items of noncompliance were noted. LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp 94090:131
- 7811010397 Forwards IE Inspec Rept#50-324/78-20 & #50-323/78-20 on 780815-18 during which no items of noncempliance were noted. LONO-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94388.313
- --7811010402 IE Inepac Rept#50-324/78-20 & #50-325/78-20 on 780815-18 during which no items of noncompiliance were noted. Hejor areas inepacted included: licensee event rept. IE bulletins & circulars. Follow-up of open items.
  HINCKLEY.D.O. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/09/20. dpp. 94388:315.
- 78:01:0240 Ack receipt of 780830 ltr informing NRC of steps taken to correct violations noted during inepac#50-324/78-14 & 50-325 /78-14.

  8UT-ERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafaty Branch. 78/09/27, 1p. 03553:242.
- --7810110242 Responds to 780717 NRC ltr re violations noted in Inspec Repta#50-324/78-14 & #50-325/78-14. Corrective actions:Rev checklist added to chlorination log & level limits added to log checklists, BANKS, H. R. Caroline Power & Light Co. 78/08/30. 3pp. 94068:169.
- --7810110245 Forwards IE Inspec Repts#50-324/78-14 & #50-325/78-14 on 780612-15 & Notice of Violation BUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/07/17. 2pp. 94068:172.
- ---7810110249 Notice of Violation from inspec on 780612-15.
  4 Region 2: Atlanta: Fuel Facility & Materials Bafety Branch. 78/07/17. 2pp. 94068:174.
- --7810110253 IE Inspec Rept#50-324/78-14 & #50-325/78-14 on 780612-15 during which 3 items of noncompliance were noted failure to include specs in annual audit & surveillance techniques for chlorination.
  HUFHAN, J. W. Region 2. Atlanta, Fuel Fecility & Hateriels Bafety Branch. 78/07/14, 7pp. 94068:176.
- 7810110291 Responds to 780821 NRC ltr re violation noted in Inspec Rept#50-324/78-17 & #50-323/78-17. Corrective actions: personnel made aware of necessity of protec clothing. BANKS.H.R. Commonwealth Edison Co. 78/09/20. 2pp. 94068:317.
- --7810110295 Forwards IE Inspec Rept#30-324/78-17 & #50-323/78-17 on 780718-21 & Notice of Violation.
  LCNG,F.J. Region 2. Attents, Reactor Operations Nuclear Support Branch. 78/08/21. 2pp. 94068:319.
- --7810110299 Notice of Violation from inspec on 780718-21.

  # Region 2. Atlanta. Reactor Operations Nuclear Support Branch.
  78/08/21. ip. 94048:321.
- --7810110302 IE Inspec Rept#50-324/78-17 & #50-325/78-17 on 780718-21 during which I stem of honcompliance was noted: feilure to follow approved health physics procedures. DANCE.H.C., HINCKLEY, D.Q., RILEY, B.W. Region 2, Atlante, Reactor Operations Nuclear Support Branch. 78/08/21. 4pp. 94068:322.

- 78i1200029 Foruerds IE Inspec Repts#50-324/78-24 & #50-325/78-24 on 780918-20-22-26-28 during which no item# of noncompliance were noted. MURPHY-C. E. Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch 78/10/11 2pp 94215:303
- --7811200034 TE Inspec Repts#30-324/78-24 & #50-325/78-24 on 780918.20-22.26-28 during which no items of noncompliance were noted Major areas inspected included Non-Destructive Erathation of Jet-Pung Riser Bafe-Ends.

  BLAXE, J.J. WILLIAMS, C.C. CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/11 5pp 94915-307
- 7810260249 Reports that no external pipe enubbers were found in United.

  None were found in Unite2 but one accessible enubber w/out
  a readable serial number wee replaced.

  UTLEV.E.E. Caroline Power & Light Co. 78/10/17. 1p 94058:320.
- 7810270232 Forwards summary of 781016 meeting re-subj facil inspect O'REILLY-J.P. Region 2. Atlanta. Office of the Director. 78/10/20 Ip 94029 210
- --7810270272 Summary of 701016 meeting re-util eval of BSEP Reactor Recirculation Safe-End Examination Results Util will inform Region II whather Nov inspec can be deferred BLAKE, J. J. Region 2, Atlenta, Defice of the Director. 78/10/20. 20p. 94029:211.
- 7810270111 Describes planned feedwater & control rod drive return line nozile inspects to be performed during refueling outages.
  UTLEY.E.E. Caroline Power & Light Co. 78/10/24 2pp. 94059 303.
- 78:1090009 Act receipt of 76:1026 ltm informing NRC of steps taken to correct violations noted during inspec#50-324/70-21 & #50-325/78-21.
  KENNAW, B. Region 2. Atlenta. Bafaguards Branch. 78/11/01. lp 94039:337.
- --7811090013 Responds to 781003 NRC ltr re violations noted in Inspec Repta#30-324/78-21 & #90-325/78-21 Corrective actions: info w/held from public disclosure pursuant to 10CFR2 790. (See ANU, 7810140041) FER.B.J. Caroline Power & Light Co 78/10/26 ip 94039: 338.
- 7812110245 Forwards 1E Insp Repts 50-323/78-27 & 50-324/78-27 on 781018-19. Noncompliance noted. KENNA, W.B. Region 2, Atlants, Sefequards Branch. 78/11/03. 22p. 94307-249.
- --7812110291 IE Insp Repts 50-324/78-27 & 50-325/78-27 on 781016-19.
  Noncompliance noted Major areas inspected security plan access controls communications controls & security organization.
  MCNUTER N. B. Recent 2. Atlanta, Defice of the Director.
  - organization.
    MCOUTRE, D.R. Region 2. Atlenta, Défice of the Director.
    GILLEBPIE,F.P. Region 2. Atlenta, Safequards Branch 78/11/01.
    3pp. 94337:291.
- 78111500B7 Farwards IE Circular 78-18 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 78/11/06 ip.
- 7811170232 Ack receipt of 781108 ltr informing NRC of steps taken to correct violations noted during inspec450-324/78-18 & #30-325/78-18.
  SUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/11/08. ip. 94136:226.
- --781117023B Responds to 780921 NRC ltr re violations noted in Inspec Repts#50-324/7B-18 & #50-325/7B-16. Corrective actions: self-locking spring loaded door locks installe6.doors ilmiting access to high radiat areas will be yellow BANKB, H. R. Carolina Power & Light Co. 78/10/17. 2pp. 94136:227
- --7811170240 Forwards IE Inspec Repts#50-324/78-18 % \$50-325/78-18 on 780808-11 & Notice of Violetion.

  EUTHERLAND, J. T. Region Q. Atlanta, Office of the Director. 78/09/21. 2pp. 94136: 229.
- --7811170242 Natice of Violation from inspec on 780808-11.

  \*\* Region 2, Atlanta, Office of the Director, 78/09/21. 1p.
- --78:1170245 IE Inspec ReptsW50-324/78-18 & W50-325/78-18 on 780808-11 during which I item of honcompliance was noted: Control of high radiat areas.
  TRUPO I . NAVIS. I H. Region 2. Atlanta, Fuel Facility &

- 7812210152 Forwards IE Inagec Repts#50-324/78-23 & #50-325/79-23 on 781002-06 during which no items of noncompliance were noted BUTHERLAND.J T Region 2. Atlanta. Fuel Facility & Materiels Safety Branch 78/11/09. 2pp. 94278 176.
- --7812210155 IE Inspec Repts#50-324/78-23 & #50-325/78-23 on 781002-06 during which no items of noncompliance were noted. Heyer ereas inepected incl: radiat protec & radioactive wests mgt prog TROUP.0 L Region 2. Atlanta. Fuel Facility & Materials Sefety Branch. 78/11/09 7pp. 94278:178
- 7812180335 Provides info requested in IE Insper Repte#50-324/78-25 & #50-325/78-25. Info concerns varification of use of E-P seal metl in sefety-related enubbers & determination of bleed rate at rated load.

  TOLLIBONIA C Caroline Power & Light Co. 78/18/16. 2pp. 94338:004.
- --7812180340 Forwards IE Inspec Repts#50-324/78-25 & #50-325/78-25 on 780926-9 during which no Itams of noncompliance ward noted. LUNG-F J Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/09 2pp. 94358:006.
- --7812180345 IE Inspec ReptsW50-324/78-25 & W50-325/78-25 on 780926-9 during which no items of noncompliance were noted Mejor stees inspected incl: records. plant tour, pips support & restraint egs. follow-up on IE circulars & requests HINCKLEY.O.O. . WHITENER.H.E. . DANCE.H.C. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/11/09. 12pp. 94359:008.
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Sefeguerds Newsietter. KENNA.W.B. Region 2. Atlanta, Sefeguerds Brench. 78/11/17. 4PP. 94277:083.
- 7812040339 Forwards 1E Bullstin#78-12A, suppl to IE Bullstin 78-12. W/enci ANC:7811300035. D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 78/11/24. 6pp. 94127 143.
- 7812130294 Ack receipt of 781127 ltr informing NRC of steps taken to correct violations noted during investigation#50-325/78-29 & e50-0324/78-29.

  KENNA, M. S. Region 2, Atlanta, Sefeguards Stanch, 78/12/07, ip. 94294-329
- --7812130296 Responds to 781107 NRC ltr re vipiations noted in Investigation ReputSO-322/78-29 & 650-324/78-29. Corrective actions: improved admin controls over documentation & testing of security force training prog have been implemented.

  BANKB.H R. Carolina Power & Light Co. 76/31/27. Jpp. 94296: 330.
- --7812130300 Forwards IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 & Notice of Violation.
  O'REILLY.J.P. Region 2: Atlanta, Office of the Director.
  78/11/07 2pp. 94296: 333.
- --7812130304 Notice of Violation from investigation on 781023-25.

  # Region 2. Atlanta. Office of the Director. 78/11/07. ip. 94294:335.
- --7812130310 IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 during which I item of noncompilance was noted: literace peratted unquelified & improperly informed individual to guard security posts on 781016. KENNALW B. Region 2: Atlanta: Safeguards Branch. 78/11/06. 13pp. 94276:33b.
- 7812130115 Documents reinaged results of four recirculation inlet notific safe ands & acceptability of continued oper of facils until next refueling outage. Concludes that continued oper presents no safety hexard to the public.

  UTLEY, E. E. Cerolina Power & Light Co. 78/12/08. 45pp. 94295: 331.
- 7812260024 Forwards IS Sulletin 78-14.
  D'REILLY.J.P. Region 2. Atlanta, Diffice of the Director. 78/12/19.
  1P. 94/31:037.
- R. Periodic operating reports & related correspondence
- 7810130121 Forwards Monthly Open Rept for Sept 1978.

  BANKS.H R. Caroline Power & Light Co. 78/10/10. 1p. 94079:298.

- 7811150091 Forwards monthly open rept for Oct 1978.

  BANKS, H. R. Carolina Power & Light Co. 78/11/10. 1p. 94134:351.
- --7811160094 Monthly open rept for Oct 1978 WILLIS.E. Carolina Power & Light Co. 78/11/02. 9pp. 94134:35
- 7812150330 Forwards Honthiy Oper Repts for Nov 1978.
  BANKS-H R Caroline Power & Light Co. 78/12/11. 1p. 94022:043.
- --7812150332 Monthly Oper Repts for Nov 1978.
  WILLIB,E. Caroline Power & Light Co 78/12/05. 12pp. 94022:0-
- S. Reportable occurrences. LERs & related correspondence
- 78101000R9 Forwards LER#78-065/03L-D.
  BANKS-H.R. Carolina Power & Light Co. 78/10/03. 1p. 94033:037.
- --78:0100032 LERN78-066/03L-0 on 780904: rod block monitor "B" inoper trip came on & stayed on for 1/4 of the control rod ealection metrix. Caused by Pailed integrated circuit in rod block monitor salf-test circuitry.
  TOLLIBON.A C. Caroline Power & Light Co. 78/10/03. 1p. 94033-03B.
- 7810130177 Forwards LERM78-059/03L-0 BANKBiH R. Carolina Power & Light Co. 78/10/04. ip. 94003:020.
- --7810130181 LER#78-059/03L-0 on 780904:RCIC isolation channel "A" tripped momentarily.causing RCIC sys to be inoper.due to defective RX-2 relay.
  TOL-LISON.A C. Carolina Power & Light Co. 78/10/04. 1p. 94003-021
- 7810230143 Forwards LER#78-068/03L-0 BANKS-H.R. Carolina Power & Light Co 78/10/11, ip. 94489:009.
- --7810230146 LERM7B-068/03L-O on 780912; during LPCI pump discharge pressure interlock channel functional test, pressure switches Ei1-P8-N016B & Ei1-P8-N020D failed to actuate at 115P810 due to corrosion buildup in switch plungers.

  a Carolina Power & Light Co. 78/10/11. ip. 94489:010.
- 7810230193 Forwards LERW78-069/03L-0.
  BANKB, H. R. Caroline Power & Light Co. 78/10/11, 1p. 94052: 257.
- --7810230195 LERM78-069/03L-0 on 780912: Fire alarma received but wou not reset. Fire datection instrumentation not operable. Caused by emoke & dust resulting from welding & operation of jackhammer. Fire datectors clashed & repaired.

  BANKS, H. R. Carolina Power & Light Co. 78/10/11. 2pp. 94052: 2
- 7810310232 Forwards LER#78-070/03L-0. BANKS-H.R. Caroline Power & Light Co. 78/10/23. 1p. 94090:355.
- --7810310236 LERW78-070/03L-0 on 780723:Reactor Coolant Conductivity escended micro-mha's in Tech Space. Caused by restarting RMCU filter pump after it had tripped which injected resin into reactor coolant. RMCU oper procedure will be revised.

   Carolina Power & Light Co. 78/10/23. 2pp. 94090:356.
- 7810310139 Forwards LER#78-071/03L-0.

  BANKB.H.R. Cerolina Power & Light Co. 78/10/24. ip. 94090:165.
- --7810310142 LERW78-071/03L-O on 780924: RCIC sys component test foun that RCIC turbine trip & throttie valve E51-v8 was in closed position, due to unknown cause. TCLLISON, A. C. Cardine Power & Light Co. 78/10/24, 1p. 94090; 166.
- 7810310217 Forwards LERM78-073/03L-0.
  BANKS, H. R. Carolina Power & Light Co. 78/10/25. ip. 94090: 321.
- --7810310222 LER#78-073/03L-D on 780927: condensate deep-bed deminera conductivity recorder found inoper during shift turnover inspec. Transmitter was turned off due to mislabeling of om-off switch positions.
  TCLLIBON.A.C. Caroline Power & Light Co. 78/10/25, 1p. 94090; 322.
- 7811220187 LERM78-079/03L-0 on 781017: reactor bldg radiat exhaust Meniter Dig-RM-NOICE failed safe causing reactor bldg vent

- 7812070175 Forwards LER#78-072/03L-0.
  BANKS.H.R. Carolina Power & Light Co 78/11/30 ip 94375-022.
- --7812070181 LERM78-072/03L-0 on 781101.rod block monitor(RBH) channel A was found out of calibr during testing due to setpoint drift Calibr Prequency will be increased from once to twice par year.
  TCL180N.A C. Cerolina Power & Light Co. 78/11/30 ip.
- 7812200198 Forwards LERW78-082/03L-0. FURR 8.J. Carolina Power & Light Co. 78/12/13 1P 94148:358
- --7812200199 LERM78-082/03L-0 on 781117: while reactor wee in hot shutdown torus level increased . 2" above tech epace. Caused by demineralized make-up water leakage through valves from RHR Keep-fill system causing torus level to riss.

  TOLLIBON.A. C. Carolina Power & Light Co. 78/12/13. 3PP. 94148: 359.
- 7812200200 Forwards LERW78-074/031-0 FURR B. J. Carolina Power & Light Co 78/12/13. 1p 9414B: 361.
- --7812200201 LERN78-074/00L-0 on 781112: reactor steen done high pressure switch B32-P8-N0188 did not reset & would not allow RHR valve Eli-F008 to open for shutdown cooling at reactor pressure of 102psig. Caused by sticking micro-switch TCL180N.A C. Carolina Power & Light Co. 78/12/13 lp. 74148.362.
- 7812270298 Forwards LERN78-075/03L-0.

  BANKS, H. R. Ceroline Power & Light Co. 78/12/21 ip 94229: 358.
- --7812270303 LERN78-075/03L-0 on 781122:HPCI & RCIC component tests were overloaked because rescheduling technique provided no clear indication of test due dates. Responsible technicien reinstructed & admin operating instruction A01-5 rev. TCLUBON.A.C. Caroline Power & Light Co. 78/12/21. 2pp. 94229-1350
- DOCKET 50-325 GRUNBNICK STEAM ELECTRIC PLANT, UNIT 1

  A. Application/construction stage documents & correspondence
- 7810130122 Analysis of suppression pool temp transisate as requested by NRC 780113 ltr & as mod at 780309 meeting Work has begun & rept will be submitted in about 3 months.

  UTLEY, E. E. Carolina Power & Light Co. 78/10/10. ip. 94079: 297.
- F. Security, medical, amargancy & Aira protection plans
- 7812080157 Notification of 781217 sits visit by R Leep & D Cameron, security plan reviewers affil w/Los Alamos Sci Lab. IPPCLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/30. 2pp. 94107:354.
- P. Operating license stags documents & correspondence
- 7812080164 Confirms meeting on 781206 to discuss plans re sefs-snds for refusling outage sched for January 1979.

  1PPCL1TG, I.A. Operating Reactors Branch 3 (Pre 790625). 78/11/29.

  2pp. 94108:008.
- 7812110023 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing. A/encl ANO: W7812080207. IPPOLITO, T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Spp. 94339:302.
- 7812110315 Notification of meeting on 781206 in Bethasda, MD to discuss condition of jet pump riser safs-ands & evaluate related action proposed for refueling outage to begin Jan 1979. HANNON, J. N. Operating Reactors Branch 3 (Pre 790625). 78/12/01. 1p. 94204:137.
- 7811220177 Withdraws request for extension fo subj facil inaccessible snubber inspec internal due to present operable status of facil.

  UTLEY.E.E. Carolina Power & Light Co. 78/09/22. ip.
- --7811220180 Requests temporary, one-time-only, Tech Specs chengs for subj facil to extend inaccessible inspec period thru 781004 due to continuing sus cepecity shortege caused by forced maintenencs outage. UTLEY, E. E. Carolina Power & Light Co. 78/09/20. 3pp.

- 7810110110 Responds to 780829 ltr indicating that no incident of control rods failing to fully insert occurred at subj facil. UTLEY.E.E. Caroling Power & Light Co. 78/10/04 ip 94066.356
- 7810130143 Has requested assistance from QE re-undatected single failures in reactor protective supplies. Will not be able to respond to 780807 NRC ltr w/required info until 781215.

  UTLEY.E.E. Caroline Power & Light Co. 78/10/10 ip. 94002.315.
- 7810240127 Requests rev to Tech Spec for subj facil in response to 780912 NRC ltr requesting rev to spec on total annual gassous releases.
  VTLEV.E.E. Carolina Power & Light Co 78/10/16 16pp.
- 7811130335 Burmary of 780914 meeting w/GE representatives & Mart 1 Duners Group re progress of Long Tarm Prog w/attendance list & agende(RD-9-A-Mart), Standards. )
  QRIMES. C. Plant Systams Branch (Pra 791030). 78/10/26 67pp.
- 7811090109 Requests rev of Tech Specs for subj facil re operability requirements for suppression pool-reactor bidg vectom breakers. Henuel valves will be closed & valves will be governed by admin controls.

  UTLEY,E.E. Caroline Power & Light Co 78/11/03 4pp 94042:282.
- 7811240154 Notice of 781106 meeting in Bathasda w/CP&L to discuss compensatory massures to allow continued plant oper w/single velvs isolation in R8-supression chamber vacuum ralief lines.

  HANNON-J.N Operating Reactors Branch 3 (Pre 790625). 78/11/03. ip. 94456-239.
- 7811160135 Suppl to 781103 ltr requesting amend to Tech Spec to mod operebliity requirements of suppression pool-reactor bldg vacuum breekers. Ltr documents info discussed w/staff during 781106 Meeting to 781107 tslcon.

  UTLEY.E. E. Carolina Power & Light Co. 78/11/08. Spp. 94135: 236.
- 7811220279 Confirms varbel authorization to change Tsch Epec at subjecti in response to 781103 request Amend allows all suppression pool-Reactor Bldg Vacuum breakers to be open w/opening setpoint of 0.5 paig w/menuel valves closed. OR[MES.8.K. Aselstant Director for Engineers & Projecte (Pra 790620). 78/11/08. 3pp. 94308:211.
- 7811210273 Notifies util of 781205 saminar in Atlanta to discuss new Model Rod Effluent Tach Space & encl saminar info sheet, registration form, a proposed agenda. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/09. 5pp. 94485:162
- 7811290406 Forwards NRC staff paper.policy session item (BECY-78-534) relicenses ray performance eval. Three methods for eval are; statistical.trend enalysis & regional survey method.W/o encl.

  O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 78/11/15.
  2pp. 94180:099.
- 7812150157 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attsindess to facilitate sending out meti. W/sncl Registration Form & List of Locations.
  MILLER.J.R. Assistant Director for Bite & Safeguarde (Pre 791030). 78/11/15. 5pp.
- 7812180274 Forwards Rev#1 "Draft Radiological Effluent Tach Specs" for BuR's(NJREG-0473) & "Preparetion of Radiological Effluent Tach Specs for Nuc Pur Plants" (NUREO-0133).
  GRINES.B.K. Assistant Director for Engineers & Projects (Prs 790423), 78/11/15, 6pp. 94356:346.
- 7812140176 Forwards Oct 1979 Prog Activity Review lifeting meetings hal & providing tesk-by-task activity summary for the month, BOBON-L. J. General Electric Co. 78/12/04. Iipp.
- 7812280114 Emphasizes importants of submitting accurate & complete inf to NRC by licenses & applicants info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or suforcement action will result. DAVIS.J. 9. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94133:228.
- 7812210100 Forwards amends#42 & 17 to DPR-71 & DPR-62 & related Enviro Impact Appraise! & Fed Register Notice.

  SALLARD, R. L. Environments! Projects Branch 1. 78/12/15. 2pp. 94267:182.

- --7812210102 Amand#42 to Oper Lic OPR-62, changing the installation date of the cooling tower.

  MODRE, V.A. Assistant Director for Environmental Projects.
  78/12/15. 2pp 94269.184.
- --7812210104 AmendW17 to Oper Lic OPR-71, changing the installation data of the cooling tower MCORE.V A Assistant Director for Environmental Projects. 78/12/15. 3pp. 94269:186.
- --7812210107 Notice of Issuance of Amends#42 & 17 to Open Lics DPR-52 & 71 & Negative Declaration BALLARD, R L Environmental Projects Branth 1. 78/12/15. Rpp. 94269 188
- --7812210109 Environ Impact Appraisel supporting Amends#42 & 17 to Oper Lies DPR-62 & 71 re cooling tower installation date. • Division of Site Safety & Environmental Analysis. 78/12/15. 1800 94269:190.
- 7812270192 Due to daisys in GE's analysis of reactor protec sys pur supplies.CPL will be unable to respond to 780807 ltr as previously committed to in 781010 ltr.Estimates response by 790201. UTLEV.E.E. Caroline Power & Light Co. 78/12/18. 2pp. 94018:056.
- 7812270207 Forwards results of reactor racirculation esfa ends inspec prog including a description of asisting NDE tachniques & discussions of alterneta tachniques. Concludes that present techniques used by subj facili are adequate.

  UTLEY.E.E. Carolina Power & Light Co. 78/12/22. 13pp. 94168:081.

# Q. Inspection reports. iE Builetine & correspondence

- 78ii170232 Act receipt of 78ii08 itr informing NRC of steps tetan to correct violations noted during inspec#50-324/78-18 & #50-325/78-18.
  BUTHERLAND.J T. Region 2, Atlenta. Fuel Fecility & Hatsriele Befety Branch. 78/ii/08. 1p. 94i36 R26.
- --781117023B Responds to 780921 NRC ltr re violations noted in Inspec Repts#50-324/78-18 & #50-325/78-18 Corrective actions: salf-locting spring loaded door locks installed doors limiting access to high radiet areas will be validum. BANKS.H R Carolina Power & Light Cc. 78/10/17. 2pp. 94136:227.
- --7811170240 Forwards IE inspsc Repts#50-324/78-18 & #50-325/78-18 on 780808-11 & Notice of Violation. SUMERLAND, J. T. Region 2. Atlanta, Diffics of the Director. 78/09/21, 2pp. 94136:229.
- --7811170242 Notice of Violation from inspec on 780808-11.

   Region 2. Atlanta. Office of the Director. 78/09/21. 1p. 94136:231.
- --78iii70245 IE Inspec Repta#30-324/78-18 & #50-323/78-i8 on 780808-li during which i item of noncompliance was noted: Control of high rediat areas. IRDUP,Q.L., DAVIS,J.H. Region P. Atlante, Fuel Facility & Materials Bafaty Branch. 78/09/20. 10pp. 94136:232.
- 7812110246 Forwards IE Insp Repts 30-325/78-27 & 50-324/78-27 on 781018-19 Noncomplience noted. KENNA-H.B. Region 2. Atlenta, Safeguerds Brench. 78/11/03. 2pp. 9437: 249.
- --7612110251 IE Insp Repts 50-324/78-27 & 50-325/78-27 on 781018-19. Noncompliants noted Mejor Areas inspected security plan access controls communications controls 4 security organization. MCGUIRE, O.R. Region 2. Atlanta, Office of the Director. GILLERFIE, F.P. Region 2. Atlanta, Befeguards Branch. 78/11/01. 3pp. 74337:251.
- 7812130294 Act receipt of 781127 itr informing NRC of steps taken to correct violations noted during investigations50-325/78-29 th 850-024/78-29.

  KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 78/12/07. 19. 94296: 329.
- 7810310134 IE Inspec Repts#50-324/78-19 & #50-325/78-19 on 780808-11 during which no items of noncompliance were noted Major areas inspected included: calibr, surveillance, design & procurement changes & mode.

  KELLOGO,P. J. Region 2: Atlanta, Office of the Director. OUZTB, J. E. Repion 2: Atlanta, Reactor Operations Nuclear Support Branch. 78/09/20. 8pg. 94090:132.

- 78103(0128 Forwards 15 Inspec Reptam50-324/78-19 & M50-325/78-19 on 780808-11 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94090:131.
- 7811010397 Forwards IE Inspec Rept#80-324/78-20 & #30-325/78-20 on 780815-18 during which no items of honcompliance were noted. LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94388:313.
- --781010402 IE Inspec Rept#50-324/78-20 & #50-325/78-20 on 780815-18 during which no itams of noncompliance were noted. Major ereas inspected included: liceness event rept, IE bulletins & circulars/foliow-up of open items. HNCMLEV.N D. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/09/20. App. 94388:315.
- 7810110240 Ack receipt of 780830 ltr informing NRC of steps taken to correct violations noted during InspecM50-324/78-14 & 50-325 /78-14.

  BUTHERLAND, J. T. Region 2, Atlents, Fuel Fecility & Materials Sefety Branch. 78/09/27. jp. 03555:242
- --7810110242 Responds to 780717 NRC itr re violations noted in Inspac Repts#30-324/78-14 & #30-325/78-14. Corrective actions: Rev checilist added to chiorination log & level limits added to log checklists.
  BANKS.H.R. Carolina Power & Light Co. 78/08/30. 3pp 94068: 169.
- --7810110245 Forwards iE Inspec Repts#50-324/78-14 & #50-325/78-14 on 780612-15 & Notice of Violetion.
  BUTHERLAND, J. T. Region 2, Atlants, Fuel Facility & Materials Safety Branch, 78/07/17. 2pp. 94068:172.
- --7810110249 Notice of Violation from inspec on 780512-15.

   Region 2, Atlanta: Fuel Facility & Materiela Safety Branch. 78/07/17. 2pp. 94068:174.
- --7810110293 JE Inspec Rept#50-324/78-14 & #50-325/78-14 on 780612-15 during which 3 items of noncompliance were noted; failure to include apecs in annuel audit & survaillance tachniques For chlorination.
  HIFHAM.J.M. Region 2. Atlanta. Fuel Facility & Materials Befaty Branch. 78/07/14. Top. 94068;176.
- 7810110287 Act receipt of 780920 itr informing NRC of steps taken to correct violations noted during Inspec#30-324/78-17 to #30-325/78-17. LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/27. tp. 03556:057.
- --7810110291 Responds to 780821 NRC itr re violation noted in Inspec ReptM30-324/78-17 & M30-323/78-17. Corrective attions: personnal made aware of necessity of protec clothing. BANKS.H.R. Commonwaalth Edison Co. 78/09/20. 2pp. 94068:317.
- --7810110295 forwards IE Inspac Rept#90-324/78-17 & #50-325/78-17 on 780718-21 & Notice of Violation.
  LOWS.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/08/21. 2pp. 94068:319.
- --7810110299 Notice of Violation from inspec on 780718-21.

  \* Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/08/21. ip. 94068:321.
- --7810110302 | E inspec Rept#50-324/78-17 & #50-325/78-17 on 780718-21 during which I item of noncomplience was noted: failure to follow approved health physics procedures.

  DMCE, H. C., HINCKLEY, D. O., Falley, S. M. Region 2. Atlente, Reactor Operations Nuclear Support Stanch. 78/08/21. 4pp. 94068:322.
- 7811200029 Forwards IE Inspec Repts#50-324/78-24 & #50-325/78-24 on 780918,20-22,26-28 during which no items of agricompliance were noted.
  - MURPHY, C. E. Region 2, Atlenta, Reactor Construction & Engineering Support Branch. 78/10/11. 2pp. 94218:305.
- --7811200034 iE Inspec Repts#30-324/78-24 & #50-325/78-24 on 780718,20-22,26-28 during which no itams of noncompliance were noted Major areas inspected included: Non-Destructive Eradination of Jet-Pump Riser Bafe-Ends.

  BLAKE.J.J., WILLIAMB.C.C., CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/11. Spp. 94215;307.
- 7810280249 Reports that no external pipe snubbers were found in Unit#1. None were gound in Unit#2 but one accessible anubber w/out a readable serial number was replaced.

  UTLEN'E.E. Carolina Power & Light Co. 78/10/17. ip. 94058:3RO.

94022:043.

- 7810270252 Forwards summary of 781016 meeting re subj facil inspec. D'REILLY.J P. Region 2. Atlanta. Office of the Director. 78/10/20. 1p. 94029:210.
- --7810270272 Summary of 781016 meeting re util eval of BBEP Reactor Recirculation Safe-End Examination Results Util will inform Region 11 whether Nov inspec can be deferred. BLAKE, J J. Region 2. Atlanta, Office of the Director. 78/10/20. 2pp. 94029:211.
- 7Bi0270iii Describes planned feedwater & control rod drive return line notile inspects to be performed during refueling outages.
  UTLEY, E. E. Carolina Power & Light Co. 78/10/24. 2pp. 94059; 303.
- 7811090009 Ack receipt of 781026 itr informing NRC of steps taken to correct violations noted during inspec#50-324/78-21 & #50-G25/7B-21. KENNA. H.B. Region R. Atlanta. Safeguards Branch. 78/11/01. 1p.
- -7811090013 Responds to 781003 NRC Itr re violations noted in inspec Repts850-324/78-21 & 850-328/78-21. Corrective actions:info w/held from public disclosure pursuent to 10CFR2.790. (See ANO:7810140041) FURR. B. J. Carolina Power & Light Co. 78/10/26. 1p. 74039; 338.
- 7811150097 Forwards IE Circular 78-19. O'REILLY, J. P Region 2. Atlanta, Office of the Director. 78/11/06.
- 7812210152 Forwards IE Inspec Repts#50-324/78-23 & #50-325/78-23 on 781002-06 during which no items of noncompliance were noted. BUTHERLAND. J. T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/09. 2pp. 94278:176.
- --7812210155 1E Inspec RepteM50-324/78-23 & M50-325/78-23 on 781002-06 during which no litems of noncompliance were noted. Major areas inspected incl:radiat protec & radioactive waste mot pros. TROUP, O. L. Region 2. Atlanta. Fuel Facility & Materials Sefety Branch. 76/11/09. 7pp 94278.170.
- 7812180335 Provides info requested in IE Inspec ReptsW50-324/78-25 & W50-325/78-25 Info concerns verification of use of E-P seal mati in safety-related snubbers & determination of bleed rate at rated load. TOLLIBON. A. C. Carolina Power & Light Co. 78/11/16. 2pp. 94358: 004.
- --7812180340 Forwards 1E Inspec Repts#50-324/78-25 & #50-325/78-25 on 780926-9 during which no items of noncompliance were noted. LDNO.F. J. Ragion 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. Rpp. 94358:006.
- --7812160345 1E Inspec Repts#50-324/78-25 & #50-325/78-25 on 780926-9 during which no itsme of noncompliance were noted Major areas inspected incl:records.plant tour.pipe support & restraint eys, follow-up on IE circulars & requests. HiNCKLEY.D. G., HMITENER.H. L., DANCE. H. C. Region 2. Atlanta, Resctor Operations Nuclear Support Branch. 78/11/09. 12pp. 04378 006 74358, 008.
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 additions of Nuc Security Bafaguards Newsletter. KENNA, N. B. Region 2. Atlanta. Safeguards Branch. 78/11/17. 4PP. 43277-022 94277:093
- 7812040359 Forwards 1E Bulletin878-12A. suppl to 1E Bulletin 78-12. W/encl ANG: 7811300055. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/24. 6pp. 94127: 143.
- 7812130296 Responds to 781107 NRC ltr re violations noted in Investigation Rept#50-325/78-29 & #50-324/78-29, Corrective actions: Improved admin controls over documentation & testing of security force training prog have been implemented. BANNG-H.R. Carolina Power & Light Co. 78/11/27. 3pp. 94296:330.
- --7812130300 Forwards IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 & Notice of Violation. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/07. 2pp. 94294:333.

-- 78/2130304 Notice of Violation from investigation on 78/023-25.

- --7812130310 IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 during which I item of noncompliance was noted: licenses parmitted unqualified & improperly informed individual to guard hacurity posts on 781016. KENNA, H. B. Region 2. Atlanta, Bafeguarde Branch. 78/11/04 15pp. 94296: 336.
- 7812130115 Documents reinspec results of four recirculation inlet nozzle safe ends & acceptability of continued oper of facils until next refueling outage. Concludes that continued oper presents no safety hazard to the public UTLEY, E.E. Caroline Power & Light Co. 78/12/08. 43pp. 94295.331.
- 7812280024 Forwards IE Bulletin 78-14. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/12/19. IP 94131.057
- R. Periodic operating reports & related correspondence
- 7810130121 Forwarde Monthly Oper Rept for Sept 1976.

  BANKS-H R. Caroline Power & Light Co 78/10/10. ip 94079 298
- --7810130124 Monthly Oper Rept For Sept 1978. WILLIB, E. Carolina Power & Light Co. 78/10/05. 13pp. 94079: 299.
- 7811160091 Faruards monthly open rept for Oct 1978.

  BANKS, H. R. Caroline Power & Light Co. 78/11/10. ip. 94134:351.
- --7811160094 Monthly oper rept for Oct 1978.
  WILLIB.E. Carolina Power & Light Co 78/11/02. 9pp. 94134: 352
- 7612150330 Forwards Monthly Open Repts for Nov 1978. BANKS, H.R. Carolina Power & Light Co. 78/12/11
- --7812150332 Monthly Oper Repts for Nov 1978.

WILLIS.E. Carolina Power & Light Co. 78/12/05 12pp. 94022:044.

- 9. Reportable occurrences, LERs & related correspondence
- 7810100049 Forwards LER#78-071/03L-0. BANKS, H. R. Carolina Power & Light Co 78/10/03. 1p. 94032:176.
- --7810100053 LER#78-071/03L-0 on 780905:during periodic test, redist monitor DIZ-RM-N0108 HI-HI trip point driffed to higher than premitted level. Monitor recalibrated. Drift appears to be Isolated incidentino further action taken. TOLLIBON. A. C. Carolina Power & Light Co. 78/10/03. 1p. 94032: 177.
- 7810130152 Forwards LER#78-072/03L-0. BANKS, H. R. Carolina Power & Light Co. 78/10/09. 1p. 94002.340.
- --7810130186 LERM78-072/03L-0 on 780911:Snubber 8W-14289164 found Inoperable during periodic test. Caused by seal degradation & resulting loss of fluid. TOLLIBON, A. C. Carolina Power & Light Co. 78/10/09. 1p. 94002: 361.
- 7810130189 Forwards LER 78-072/03L-0. BANKS, H. R. Caroline Power & Light Co. 78/10/09. 1p. 94079:151.
- 7810130158 Forwards LER#78-074/03L-0. BANKS.H.R. Carolina Power & Light Co. 78/10/10. 1p. 94003:001.
- --7810130162 LER#78-074/03L-0 pn 780911: during monthly #1 diesel generator load test it was found that #1 cylinder was not firing due to faulty fuel pump. TGLLIBDN.A.C. Carolina Power & Light Co. 78/10/10. 2pp. 94003:002
- 7811090194 Forwards LER#78-075/03L-0. BANKG, H. R. Ceroline Power & Light Co. 78/11/02. 1p. 94038:253.
- --7811070197 LERE78-075/03L-0 on 781004: pressure switch Eli-P8-N0168 failed during periods PLCI pump discharges ADB permissive test, due to corrosion buildup on plunger of switch.
  TCLLISON, A.C. Caroline Power & Light Co. 78/11/02. ip. 94038; 254.
- 7811160137 Forwards LER#78-078/03L-0.

- --7811160141 LERM78-078/03L-0 on 781105 Control oper received control rod drift alarm for rod 10-31. When rod position display was selected. a false "3" was superimposed on actual rod position due to aground on the RPLS probe.
  TQLL18DN.A C Caroline Power & Light Co. 78/11/06. Ppp. 94105-245.
- 7811160138 Forwards LER#78-077/03L-0 FURR B.J Carolina Power & Light Co 78/11/07. 1p. 94135:247.
- --7811140144 LER#78-077/03L-O on 781006 condensete storage tank level suitch E41-LB-N003 found out of calibration during periodic condensate etorage tank low level channel. Caused by instrudrift.

  TOLLISON.A.C Caroline Power & Light Co. 78/11/07. Ip 94135:248
- 7811160088 Forwards LERM78-076/03L-0.
  8ANKS.H R Carolina Power & Light Co 78/11/09 1p 94134: 346.
- --7811160092 LERe78-076/03t-0 on 78101) torus level dropped below Tech Spec minimum while water from torus was being pumped via ROR to redwests in efforts to reduce torus water level. Caused by operator being distracted. TOLLISON.A.C. Cerolina Power & Light Co. 78/11/09. 1p.
- 7811160132 Forwards LERW78-083/03L-0.

  9ANKB.H R. Carolina Power & Light Co. 78/11/09. 1p 94135:233
- 7812140158 Forwards LER#78-086/03L-0.

  \$ANKS,H.S. Carolina Power & Light Co. 78/11/11. 1p. 94133:297.
- --7812140160 LER878-086/03L-0 on 781109; Reactor vessel chemistry exceeded Tech 8sec limits for conductivity & concentration due to presence of argenic compounds in condensate sys. Organic filtration & high concentration of ion resin ciseoup begun.

   Carolina Power & Light Co. 78/12/11. 3pp. 94133:298
- 78:1170209 Forwards LERM78-082/01T-0. BANKS.H.R. Cerolina Power & Light Co. 78/11/14. 1p. 94136:101.
- --7811170213 LER#78-082/01T-0 on 781101; util wes informed by NRR of nonconformence w/iOCFR50 Append A Gen Deeign Criteria 54 & 56 Two reactor bidg-to-torus vecuum breater lines have never had deeign review by NRC Tech B
- 7811220193 Forwards LERM78-079/03L-D.
  BANKS, H. R. Carotine Power & Light Co. 78/11/15. ip. 94074: 222.
- 7812070214 Forwards LER#78-081/03L-0 BANKS, H. R. Carolina Power & Light Co. 78/11/28. 19. 03555:105.
- ~-7812070217 LER#78-W081/03L-O on 781029:main steamline drain isolation valve B21-F017 failed to operate due to faulty brush holder in valve motor. Motor replaced & valve declared operable. TGL180N,A.C. Carolina Power & Light Co. 78/11/28. 1p. 03355:106
- 7812070145 Forwards LER#78-080/03L-0.
  BANKS, H. R. Carolina Power & Light Co. 78/11/30. ip. 94085:345.
- --7812070168 LER#78-080/03L-0 on 781101: containment oxygen monitor CAC-AT-1263 found inoperable. Caused by 2 defective Jenon diodes & capacitors in oxygen enelyser transmitter. TQLI8QN, A. C. Caroline Power & Light Co. 78/11/30, 1p. 74085:346.
- 7812080127 Forwards LER#78-084/03L-0. BANKE, H. R. Carolina Power & Light Co. 78/12/01, 1p. 94106:346.
- --7812080130 LERB78-084/03L-0 on 781102: unit I reactor scremmed on loss of condenser vacuum & approximetely 2 hours later the torus lavel went over Tech Spec limit by 0.2 inchesedue to eteam blowdown & use of RCIC efter acrem & operator negligence. TCLL180N.A.C. Ceroline Power & Light Co. 78/12/01. lp. 94106: 347.
- 7812210181 forwards LER#78-089/03L-0. BANKS, H. R. Caroline Power & Light Co. 78/12/14. 1p. 94278:332.

- --7812210185 LERB78-089/03L-0 on 781114 during Periodic Te HPCI EOR actuator failed to oper properly due to water hydreulic fluid corroding EOR actuator. Steam leaking p asat of velve HPCI E41-F001 allowed water into fluid. TOLLISON, A.C. Carolina Power & Light Co. 78/12/14. 94278: 333
- 7812210187 Forwards LERM78-088/03L-0.
  8ANNS.H.R. Carolina Power & Light Co. 78/12/14. 1p.
- --7812210192 LERM78-089/03L-0 on 781114: Fire hoses of Radu elevation fire stations were found missing due to use personnel for routine raducete washdown. New firehoses installed & mod re alternate water supply is in progre TCLLIBON. A C. Caroline Power & Light Co. 78/12/14. 9478. 338.
- 7812210218 Forwards LER#78-087/03L-0.

  BANKSi H. R. Caraline Power & Light Co. 78/12/14. 1p.
- --7812210222 LERW78-087/03L-0 on 781114 torus level of the control sys was slightly above the allowed 27 inches. Future level restored to normal Torus level indicator amore clearly merked.
  TCL 180N. A.C. Carolina Power & Light Co. 78/12/14. 94279-120.
- 7812270288 Forwards LERW78-091/03L-0.
  FURR.B.J. Carolina Power & Light Co. 78/12/19. 1p. 5
- --7812270292 LERW78-091/03L-0 on 781120:Senior Control Opthave completed hetch leak rate test before beginning startup due to misunderstanding. Test completed. GP-1 rito require leak test verification by control operators TQLISON.A C. Carolina Power & Light Co 78/12/19. 94229: 339.
- DOCKET 50-326 UNIV. OF CALIFORNIA AT INVINE REB. REACTOR
  G. Inspection reports, le Builetins & correspondence
- 7812080237 Forwards Inspec Rept#50-326/78-03 on 781016 & which no items of noncompliance were noted. CREME,U.L. Region 5. Ben Francieco, Reactor Operations Support Branch. 78/10/31. 2pp. 94137:162.
- ---78:2090238 IE Inspec Rept#50-326/78-03 on 78:016 & 19 di items of noncompliance were noted Mejor eres inspec refueling related activities. CANTER.H.L. MILLER.L.F. HORN.A.J. Region 5, Ben Fr. Reactor Operations Nuclear Support Branch. 78/10/30. 94:37:164.
- S. Reportable occurrences, LERs & related correspondence
- 7812060145 Forwards incident rept on 780928 involving fing ring dropped into resector core. Present etatus: ban on respect pending decision on whether removal of objects belief core should be attempted.

  ROMLAND.F.S. Californie, Univ. of. Irvine. 78/10/23. 94382; 001.
- DOCKET 90-327 BEOUDYAM NUCLEAR PLANT, UNIT 1

  A. Application/construction steps documents & corresponds
- 7811070240 Finel rapt re incorrect sclenoide in chem voi velves. Overly long velve strake times due to neglect by constr personnel to follow drawings. # Tennessae Velley Authority. 78/09/08. ip. 94039:1
- 7812210323 Summerizes 780922 Licensing Schedules Review C restetus of subj Facils & the lic review process.
  BOYD.R.S. Division of Project Management, DEYOUNG.R.C Site Sefety & Environmental Analysis. MATTBON.R.J. Di Bystems Befety. 78/09/28. 12pp. 03556:128.
- 78:01:01:58 Forwards info & test results showing Flamemest suitable substitute for Flamemestic 71-A. which is prohiby local govts due to estestos content.
  GILLELAND, J.E. Tennesses Valley Authority, 78/10/03.
  94096:201.
- 7610130262 Forwards request for add1 info re seismic desi review of applicent's rept "Justification of Seismic De Criteria Used for Subj Facils, Phase I & II", BUYD, R. S. Division of Project Management. 78/10/04. 94079:171.

- 7810180093 Forwards statement providing add1 justification of seismic design criteria used for subj facils.per NRC request of 780817. Statement supports conclusions drawn in TVA rept of 780501.
  - GILLELAND, J. E. Tennessee Valley Authority 78/10/05. 18pp.
- 7810230156 Hydrology Engr summary for subj facil as requested in 780913 L.G.Hulman ltr.Recommendations for Rev to Bafety Eval Rept is included. BCHRIEBER, D.L. Consulting Engineering Geologist. AT-(49-24)-1283. 78/10/07. 38pp. 94164-302.
- 7810250120 Forwards environ monitoring rept. "Environ Radioactivity Levels. Sequoyah Nut Plant. 1977". GILLELAND. J. E. Tennessee Valley Authority 78/10/19 1p.
- --7810250122 "Environ Redicactivity Levels, Sequoyah Nuc Plant, 1977". Since the plant has not achieved criticality. It is not contributing radioactivity to the environ incressed tavels of radiet are a result of not weepons testing in Chine.

  \* Tannesses Veiley Authority. Ri-78-4-801 78/09/30 45pp
- 7811070277 Forwards "Tritium Mgt Considerations for PWRs," prepared by GILLELAND, J. E. Tennessee Valley Authority. 78/10/19. 1p. 94040: 324.
- --7811070281 "Tritium Mgt Considerations for PWR's" re tritium dose assessmente, alternetive disposal methods & TVA conclusions. Concludes that release of overwhelming mejority of tritium ae liquid is the preferred method of disposel.
  \* Tennessee Valley Authority. 78/10/19. 226pp.
- 7811010073 Forwards results of review of environ aspects of changes to subj facil. 4 sncl: description of changes referenced tables & drawings anylron assessment of changes copy of "Tritium Mgt Considerations for PMRs". No suppl to FES is nacessary. OILLELAND. J. E. Tennessee Valley Authority. 78/10/30. 197pp. 944E1: 060
- 7811060094 Confirms that Solid State Protec Bys gen warning alarm circuit has been mod IAN Westinghouse Field Change Notices TVA-105955 Unit 1 & TEN-10572 Unit 2 GILLELAND, J. E. Tennessee Vallay Authority. 78/10/30. 1p. 94424: 144
- 7811290147 Notice of 781109 mesting in Bethosds w/util to ravisu seismic questions & responses.

  BILVER.H. Light Weter Resctors Branch 4. 78/11/02. Ip. 94239:331.
- 7811150137 Responde to 780330 & 780612 NRC request for eddl info on demonstration test & forwards 3 repts on sump & spray pumps.
  GILLELAND. J.E. Tennssee Valley Authority. 78/11/07. 2pp. 94272:304
- --7811150176 "Study of Effects of Steam Jete & Mater Jete on Emergency Sump." Concludes that air entrainment dus to break at steem gensrator noisle wilk not adversely affect functional capability of sump.

  # Tannessee Vallay Authority, 78/09/30, IApp. 94272;306.
- --7811150196 "Model Study of Bequoysh RHR Sump." Concludes initial design of tump was satisfactory for all design conditions.incl worst-cess 50% screen blackage.excepting air entrapment during initial filling.
  FAIN.T.9. Tennesses Veiley Authority. WM28-1-45-102. 78/10/31. 29pp. 94272:320.
- --7811150199 "Rev NPBH Calculations for RHR & Containment Sprey Pumps Operating in Recirculation Mode "Verlities effectiveness of the containment sump & describes constr of 1:4 scele physical model w/test results. \* Tennessee Valley Authority, 78/10/27, 9pp. 94272:349.
- 7811150152 Forwards draft response to Gusstion#8 transmitted in 770510 NRC ltr.Response rays Amend#49 to Pacil FBAR & will be incl in Amend#5B.
  OILLELAND, J. E. Tennessee Valley Authority. 78/11/09. 18pp.
- 78ii2i0298 Notifies util of 78i205 seminar in Atlanta to discuss new Model Rod Effluent Tech Space & sncl seminar info sheet, registration form & proposed aganda. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/iI/Q9. Sop.
- 781116009B Responds to 78062B questions transmitted by R Boyd re FBAR. Encl responses will be intorp into Amenda5B of FBAR. GILLELAND. J. E. Tennessee Valley Authority. 78/11/14. 3pp. 94135:091.

- 7811160149 Responds to 770802 NRC request for info re analytical modused to determine maximum containment temp & pressure for spectrum of postulated main steam line breaks for various reactor pur levels. OILLELAND. J E. Tennessee Valley Authority 78/18/14. 29pp. 94135-265
- 7811210305 Forwards Amend#37 to Lic Appl.
  MILLB.L.M. Tennesse Valley Authority. 78/11/15. 1p. 94487:183
- --7811210310 Amend#57 to Lic Appl consisting of deletion of chapter major rev to Section 15.4 to incl ECCS Append K enalysis & TVA's responses to questione 10-23 in 780628 NRC ltr. e .Tennesses Vallay Authority. 78/11/17
- 7812060099 Urges timely & complete responses to NRC question to avoid further delays in preparing an acceptable SER for subject. Informs that earliest date SER can be issued is Feb 1979 due to numerous elippages in TVA responses. 80YD.R.S. Division of Project Management 78/11/15 3pp. 94382-003.
- 7811280081 Forwards RevMi"Draft Radioligical Effluent Tech Bpsc"for PMR's (NUREQ-0472) & "Preparation of Rediological Effluent Tech Spsc for Nuc Pur Plants" (NUREQ-0133). W/enci AND: 7811270173 & 7811270180.

  VASBALLO, D. B. Assistant Director for Light Water Reactors. 78/11/16 6pp. 02728: 181.
- 7812080208 Forwards restated NRC views on selemic lesuss in Phase II of subj facils BOYD.R.S. Division of Project Management. 78/11/30. Spp. 94109:355.
- 7812080091 Forwards ray rasponse to 770910 NRC 1tr & add1 responses 780811 & 780628 NRC ltrs requesting info on preoper tests to be performed w/UHI sys & sequence of changeaver oper from injection to recirculation. OILLELAND, J. E. Tennasses Valley Authority. 78/12/04. 4pp. 9410R:028
- 7812150350 Forwards corrections to 781106 ltr transmitting anviron & seismic qual info.
  GillELAND, J. E. Tennesses Valley Authority. 78/12/05. ip. 94418: 140.
- 7812110142 Responds to 781115 itr relic sched for subj facil.Forwar list of TVA responses to NRC questions dtd 1977 & 1978. Response to outstanding fire protect issues will be submitted by 781215. Requeste leguance of BER & ACRS hearing. GILLELAND, J. E. Tennesses Velley Authority. 78/18/05. 9pp. 02499-029 94393: 258.
- 7812280141 Emphasizes importance of submitting accurate & complete to NRC by licenesss & epplicants info submitted must be substantiates by data & calculations.Licensea must notify NRC of eny ineccuracies or anforcement action will result. DAVIB.J.O. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp.
- 7812120158 Forwards Abnormal Open Instruc #AOI-I for reactor trip # requested by V Benaroya on 781027. The ADI addresses use of auxiliary feedwater sys. invites NRC to view 790121 preoper hot functional test of subj sys.

  GILLELAND. J. E. Tennesses Vallay Authority. 78/12/07. 10pp. 94276: 333.
- 7812120170 Forwards marked-up Grawings of control room as requested NRC during 781027 meeting w/TVA, W/sncl 3 oversize drawings available in Central Files. GILLELAND, J. E. Tennessee Velley Authority. 78/12/07. 4pp. 94275: 362.
- 7812180130 Forwrds addl matt re Balance of Plant Class IE equip qua Add1 mat1 not enc1. OILLELAND, J. E. Tennessee Valley Authority. 78/12/07. 1p. 94366:001.
- 7812140242 Forwards requests for add1 info re containment, else, inst control sys of subj facit. VARGA:S.A. Light Water Reactors Branch 4. 78/12/08. ISpp. 74205: 226.
- 7812270202 Responds to 781004 request for edd1 info on seismic dest bases for subj facils. Info discusses sensitivity of site specific SSE response spectra dev from atrong motion records to probabilities of exceeding SSE design spectra.

  GILELAND, J. E. Tennessee Velley Authority. 78/12/19. 1200p. 94017: 220.

- 7812290047 Summary of a 781207 meeting w/TVA re Subj Facil Environ Tech Spece WATKINS,R V Environmental Projects Branch 1 78/12/21. 2pp 94189-359
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 7B11020024 Rept of 7B0921 conference call w/TVA representatives rathe ratoutution of 20 open instrumentation & control items in subj facil draft SER Participant list enci.
  LASHERD R Electric, Instrumentation & Control Systems Branch, 78/10/25 11pp 94355 340
- F. Becurity, medical, emergency & fire protection plans
- 7810220135 Bubmitting second interim rept re high pressure fire protection pump feilures Redesigned acchanism for locking pump impelier to pump shaft Next rept will be submitted by 78103
  OILLELAND J E. Tennessee Valley Authority 78/09/14. Ip
- 7810300235 Notifies of 781026 meeting w/TVA to discuss fire protec at sub; facil BILVER:H Light Weter Reactors Branch 4: 78/40/19 3pp. 94034 038
- 7810310113 Forwards 780825 Physical Security Plan, revised to reflect latest changes in progosed security sqs. Replaces 770310 Physical Security Plan Encl withheld (ref. 10CFR2, 7901 OILLELAND, J. E. Tennasses Valley Authority, 78/10/19 2pp. 94053, 318
- 7811140134 Forwards responses to 780920 NRC ltr re Radiological Emergency Plan & quality assurance prog Responses will be documented in Amend 38 of the FSAR OILLELAND, JE. Tennesses Valley Authority 78/11/09. 13pp.
- 7811150123 Forwards responses to fire protection review questions in Autiliary Sys Branch 780901 ltr.

  OLLELAND, J.E. Tennesses Valley Authority 78/11/09. 85pp
- 78:2180374 Stemary of 78:026 meeting w/epplicant to discuss protect items: Containment Annulus Aras.ERCM Pur Cables: Feeduater Line Meter Hammer & implementation schadule SILVER-H Light Mater Reactors Brench 4 78/12/08. 6pp. 94338. 200
- 7812210248 Forwards TVA's response to fire profec review quastions#i.
  812 & 813 re subj fecil. Also encl are revised definition of
  implementation sched & minor editorial revs to TVA responses
  of 781109.
  OILLELANO, J. E. Tennesses Velley Authority, 78/12/19. 104pp.
  94188 05A
- M. Utility Final Sefety Analysis Report (FSAR) & amends

i .:

- 7810170197 Forwards affidavit cartifying that on 781010.coples of Amend 55 to duby facil FBAR were served on individuals identified in affidavit by use of U.S Mail.
  MILLS.L M. Tennsess Valley Authority. 78/10/10 2pp. 94411:256.
- 7811300198 Forwards cart of svc for amend 57 to subj facil FBAR MILLS, L.M. Tennesses Velley Authority. 78/11/24 2pp.
- 7812120166 Forwards metl for NRC review of subj facil's change of cleaning procedures of sustenitic pips FBAR draft amend page 5.2-38.ref Westinghouse space 84351NL & 597760, & ref Dept of Energy Space.RDT F-IT era encl.
  01LELAND.J.E Tennessee Valley Authority 78/12/07. 33pp. 94278: 108
- 7812760131 Forwards Amend#58 to appl for sub; facil FSAR, changing Chapters 5,7,8,9 t 12.
  01LLELAND, J.E. Tennessee Valley Authority. 78/12/21. 1p. 94028: 226.
- --7812260134 Amend#58 to FBAR, changing Chapters 5.7.8,9 & 12.
   Tennesses Valley Authority. 78/12/21. 150pp. 94028:227.

- P Operating license stage documents & correspondence
- 7812040194 Rept on 780927 visit to facil for familiarization info. Industrial & transp facile & control room area were observed. FBAR subjects were discussed W/list of participants FONTECTULA. H M Systematic Evaluation Programs Branch (Pt 78/11/20. 6pp 94457: 122
- Q. Inspection reports. IE Bulletins & correspondence
- 7812120031 Forwards reproductions of articles that appeared Aug 1978 editions of Nuc Security Safeguards Newsletter. KENNA, N B Region 2. Atlanta. Safeguards Branch. 78/11/1
- 7810270213 Forwards IE Inspec Rapts #30-327/78-23 & #50-328/780802-03 during which no Itams of noncompilance were not SUTHERLAND. J. T. Region 2. Atlanta. Fuel Facility & Materi
- --7810270221 IE Inspec Rept#80-327/78-23 & M50-328/78-17 on during which no items of noncompliance were noted. Major areas inspected included liquid wests sys-status of unresolved items & preoper testing.
  EMALD.8 C. JACKSON.L.L. Region 2. Atlanta. Dffica of the Director 78/09/12. 4pp. 94033.133
- 78110B0187 Forwards IE Inspec Repts#50-327/78-22,#50-328/78
  780802-03 during which no items of noncompilance were not SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Mater Branch. 78/09/27 2pp 94405.131
- --7811080191 IE Inepac Rapts#50-327/78-22.#50-328/78-16 on during which no items of noncompliance were noted Major areas inspected included preoper environ monitoring.con effects monitoring.environ controls metaorology measure CUNNINGHAM.A.L. Region 2. Atlanta, Fuel Facility & Mat Barety Branch. 78/09/27. App. 94405:133.
- 7811080194 Forwards IE Inspac Rept #50-327/78-25 on 780823which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Branch. 78/09/27. 2pp. 94405:142
- --7811080198 IE inspec Regtam30-327/78-26 on 780823-25 duri items of noncompliance were noted. Mejor areas inspected included, review of prepar test procedures.review of pr test packages.unresolved items.facil tour. DYER.J A., DONAT.T J. Region 2- Atlante. Reactor Opera Nuclear Support Branch. 78/09/27. 2pp. 94405 144.
- 7811130095 Forwards IE Inspec Repte#50-327/78-29 & #50-328/780829-30 & 780901 during which no items of noncompliance were noted, MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Er Support Branch 78/10/02 2pp. .94011:192.
- --7811130108 IE Inspec RepteM50-327/78-29 & #30-328/78-20 of during which no items of noncompliance were noted. Major areas inspected included: procedures work activities, questated records for safety-related components. RAUSCH, J. R., HARRIS, J. R., HERDT, A. R., Region 2, Atlanta Construction & Engineering Support Branch. 78/10/02. 94011, 194.
- 7811200021 Forwards IE Inspec Rept#50-327/78-28 on 780920-5 which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Branch. 78710/13. 2pp. 94215-280.
- --7811200024 1E Inspec Rept#50-327/78-28 on 780920-23 duris items of noncompliance were noted. Major areas inspacted included: preoper tests, procedures, & facil. MARTIN.R.D., DDNAT.T.J. Region 2. Atlanta, Office of 178/10/13. dpp. 94215:282.
- 7810230093 Forwards rev 5 to "Presvc Baseline Inspec & Inspecy incorporating changes to Class B presvc inspecs to include only those welds & components which req insvc esamination.
  OILLELAND, J. E. Tennesses Valley Authority. 78/10/19.
- 7812030158 Forwards IE Inspec Rept#50-327/78-31 on 780919-1 which no items of noncompliance were noted. LDMG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Branch. 78/10/23. 2pp. 94335:097.

- items of noncompliance were noted Major areas inspected inclormoper test progradministrative controls new fuel storage test activities in progress HEBSFAN.R.H., JENMINS.H.D. Region 2. Atlanta. Reactor Operations Nuclear Support Brench 78/10/23. 5pp 94333.099.
- 7812050303 Forwards IE Inspec Rept#50-327/78-30 & #50-328/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHYC E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 78/10/24. 2pp 94203.044
- --7812050307 IE Inspec Rept#50-027/78-00 & #50-028/78-02 on 780919-01 during which no items of noncompilance were noted Major areas inspected incl:reactor coolent pressure boundary piping welding records & sefety related structures welding VANDOGN.P K Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/10/23 4pp. 94200.046
- 7812060268 Forwards IE Inspec Repts#30-327/78-24.50-328/78-19 on 780926-29 during which no items of noncompliance were noted. MURBING E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 78/10/31. 2pp. 94372-241.
- --7812060274 [E Inspec Rets#50-327/78-24,50-328/78-19 on 780926-29 during which no items of noncompliance were noted Major areas imspected incl. licensee action on previous findings,licensee identified item,instru work & GC records
  OIBSDMS,T D., RUFF.A. Region 2. Atlanta, Reector Construction & Engineering Support Branch 78/10/27. 5pp. 94372-243.
- 7812060287 Forwards IE Inspec Repts#50-327/78-32.50-320/78-23 on 780921-22 during which no items of noncompliance were noted. MURPHY.C E. Region 2. Atlenta. Reactor Construction & Engineering Support Brench. 78/10/31. 2pp. 94372:301.
- --7812060291 IE Inspec Reptem50-327/78-32, 50-328/78-23 on 780921-22 during which no items of nuncompliance were noted Major area inspected inclination on previous inspec findings, epoxy anchored bolts in concrete. ERCW concrete cells & pipe HARRIB.J.R. COMPTON.R.M. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 78/10/31 4pp. 94372:303.
- 7812130001 Forwards JE Inspec Repts#50-327/78-27 & #50-328/78-21 on 780926-29 & Notice of Violation MURPHY.C.E. Region 2: Atlanta, Reactor Construction & Engineering Support Branch 78/11/01. 2pp 94318: 266.
- --7812:30004 Notice of Violetion from inspec on 780926-29.

  \* Region 2, Atlanta. Office of the Director 78/11/01 ip 94318,268.
- --7812130005 IE Inspec Repts#50-327/78-27 & #50-320/78-21 on 780926-29 during which I item of noncompliance was noted: fallure to document audits of all applicable alements of the QA prog. HERDT.A R Region 2. Atlante. Office of the Director. RAUSCH.J.R., MCFARLAND.C.R. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 78/11/01. 13pp. 94310-269
- 7811150073 Forwards 1E Circular 78-18.
  D'RELLY, J. P. Region 2, Atlanta, Diffice of the Director, 78/11/06.
  10.
- 7812150030 Forwards IE Inspec Repts#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted. MURPHY-C.C. Region 2. Atlenta. Reactor Construction & Engineering Support Branch. 78/11/07. 2pp 94210:022
- --7812150040 IE Inspec Repta#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted Major Areas inspected incl: previously identified (tems concerning understrength concrete in Unit i & 2 shield pldgs HARRIS.J.R., COMPTON.R.M., BRYANT.J.C. Region 2, Atlante, Office of the Director. 78/11/02. 3pp. 94210.024.
- 7812050111 Ack receipt of 781025 ltr informing NRC of steps taken to correct violetions noted during inspec#50-327/78-25 & #50-328/78-18.
  MURPHY-C.E. Region 2. Atlanta. Recetor Construction & Engineering Support Branch. 78/11/21. 1p. 94333-175.
- --7812050117 Responds to 781002 NRC ltr rs violations noted in Inspec Rept#50-327/78-29 & #50-328/79-18. This is rev in response w/add1 infor as requested Corrective actions several steps & to be taken are detailed re installation of proper snubers. 91L.EL.AND.J. E. Tennessee Valley Authority 78/11/14. 4pp. 94333:176

- Repts#30-327/78-29 & #30-328/78-18 Corrective actions:paint removed form greate fittings of snubber, proper lubrication documented, debris removed from spring can of support OILLELAND, J. E. Tennessee Valley Authority 78/10/29. 3pp. 94-333 180.
- --7812050140 Forwards 1E Inspec Repts#50-327/78-25 & #50-328/78-18 or 760808-11 & Notice of Violation MURPHY, C. E. Region 2. Atlanta. Reactor Construction & Engineerin Support Branch. 78/10/02. 3pp 94333.183.
- --7812050147 Notice of Violation from inspec on 780808-11
   Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/10/02 ip. 94333:186.
- --7812050150 IE inspec Repts#50-D27/78-25 & #50-D28/78-18 on 780808-1 during which I item of noncompliance was noted failure to follow procedures during hanger installation. AND.N.P., BRYANT.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/07/29 5pp. 94303.187.
- 78:2040369 Forwards IE Bullstine78-12A, suppl to IE Gulletin 78-12. W/enci AND 78:1300055. D'REILLY, J. P. Region 2. Atlanta, Défice of the Director. 78/11/2/1p.
- 7812060065 Ack receipt of 781130 ltr informing NRC of steps taken to correct violations noted during insp 50-327/78-14 % 50-328/78-10.

  MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 78/11/20. 1p. 94232 264
- --7812060074 Responds to 781002 NRC itr requesting additinfo re viole noted in Inspec Repts#50-327/78-14 & 50-328/78-10 Corrective ections; employees instructed to protect permanent equip inclinate utubing & stainless steel piping from arc denage. Oilce.AND. J. E. Tennessee Valley Authority. 78/11/09. App.

94232-249

- 7812070177 Forwards responses to 781111 IE Insp Repts 50-327/78-27 to 50-328/78-21, re GA unit audits. Contends full compliance has been meintained. Firm audit policy has been established GILLELAND, J. E. Tennessee Valley Authority. 78/11/30 3pp 94375: 025.
- 7812270229 Forwards IE Bulletin 78-14.

  O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/12/19

  2pp. 94017; 131
- 7812290114 Ack receipt of 78:207 ltr informing NRC of steps teken to correct violations noted during inspec#50-327/78-33 & #50-329/78-24.

  MURPHY.C.E. Region 2. Atlenta. Reactor Construction & Engineering Support Branch 78/12/20. Ip. 94190:188
- --7812290117 Responds to 781116 NRC ltr re violations noted in Inspe Repts850-327/78-33 & #50-328/78-24, Corrective actions: closer surveillance over maintenance of oven temp logs, OILLELAND, J. E. Tennessea Valley Authority. 78/12/07. 2pp. 94190:189
- --7812290122 Forwards IE Inspec Repts#50-327/78-33 & #50-328/78-24 o 781023-27 & Notice of Violation.
  MLRPHy.C.E. Region 2. Atlanta, Reactor Construction & Engineeri Bupport Branch. 78/11/16. 2pp. 94190:191.
- --7812270125 Notice of Violation from inspec on 781025-27.

   Region 2, Atlenta, Diffice of the Director. 78/11/16. ip. 74190.193.
- --7812270128 IE Inspec Repts#50-327/78-33 & #50-328/78j-24 on 781025 during which I item of noncompliance was noted; fellure to log welding rod oven temp. VANDORN.P.K.. CONLON.T.E. Region 2. Atlanta, Reactor Construct b Engineering Support Brench. 78/11/16. 5pp. 94190:194.
- B. Reportable occurrences. LERs & related correspondence
- 7811070236 Forwards final deficiency rept re incorrect solanoids on valves.

  OlLLELAND, J. E. Tennasses Valley Authority. 78/09/09. 1p. 94009:187.
- 78:0190164 Submits first interim mept me failure to provide seismically quelified path for makeup to spent fuel storage facil. Proposed under study to install quelified line & necessary valves from common discharge of pumps.

  GILELAND. J. E. Tennessee Valley Authority. 78/09/14. 2pp. 94414-102.

- 7811030263 Forwards First Interim Rept to difference between Plant Configuration & Drawing NCR-2p.
  01LELAND, J.E. Tennesses Valley Authority. 78/10/16 lp.
  02725:256
- --7811030265 First Interim Rept of Deficiency NCR 29: "Plant Configuration Different than Drawings of Record", due to error to IVA drawing certification process.

  OILLELAND.J.E. Tennessee Velley Authority 78/10/16 fp. 02725, 297.
- 7811070276 Third Interim Rept re Diesel Oenerator Hydraulic Actuator Motors. States that supplier has instructed governor affect test governor speed control motor. Next rept will be submitted 781220.

  GILLELAND. J. E. Tennessee Valley Authority. 78/10/03 19 94440. Dee
- 7812040192 Forwards final rept re incomplete documentation of seismit qual of elec panetretions.

  OILUSLAND, J.E. Tennesses Valley Authority. 78/10/20 1P. 94457: 11B.
- ~~7812040197 Final rept re incomplete documentation of ssismic qual of elsc penetrations. Documentation written per old TVA requirements. Current construc will withstand ell design loadings & ho changes in hardware are req.

   Tennessee Valley Authority. 78/10/20. 1p. 94457:119.
- 7812010266 Forwards final deficiency rest to failure of sump velves to open during automatic switchover testing.

  9ILLELAND, J. E. Tennessee Valley Authority. 78/10/26 1p. 94417: 154.
- --781201026B Finel rept on failurs of sump velvas to open during automatic switchover testing. Circultry design was inadequate a schematics have been corrected. Correction will be tested before unit oper.

  \*\* Tennessee Valley Authority. 78/10/26. ip 94417:155.
- 78:1060063 Forwards Final rept re reportable deficiency re OEDC GA auditeM77-7.

  OILLELAND, J. E. Tennessee Velley Authority. 78/10/30. 1p.
- 78:2050265 Forwards final deficiency rept re seismically qual path for melaup to spant fuel storege facil.
  OILLELAND, J.E. Tannessee Valley Authority. 78/11/03. 1p. 94202:143.
- --7819350270 Finel deficiency rept: seismically qual path for meksup to spent fuel storage facil not provided due to improper design. Line & velvss will be inetalled & selemically qual. Francesse Velley Authority. 78/11/03. 1p. 94202: 164.
- 7812050121 Forwards final deficiency rapt on Control Room Back Draft Demper Failure. OILLELAND, J. E. Tannessee Valley Authority, 78/11/08, 1p. 94332:227.
- --7812060129 Final Rept:failure of Back Dreft Dampsr in Nein Control Room Air Hendling Unit discovered during routine mod of eys.

  Damper lost all blades due to excessive blade bearing weer.
  Failed dampers replaced'w/high-pressure units.

  Tennessee Valley Authority. 78/11/08. 3p.
- 7812140286 Forwards revised Pinal rapt "Deficient Foundation Preparation for Concrete Calle for the ERCW Pumping Station Access Roadway." GILLELAND, J. E. Tennessee Velley Authority, 78/11/29. 1p. 02857:339.
- --7812140288 Revised rept "Deficient Foundation Preparation for Concrete Cells for the ERCH Pumping Station Access Roadwey."

  9ILLELAND.J.E. Tennesses Valley Authority. 78/11/29. 3pp.
  00357:360.
- DOCKET 50-328 SEGUDYAH NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7812040099 Urges timely & complete responses to NRC question to avoid further delays in preparing an ecceptable SER for subject. Informs that earliest date SER cen be issued is Fab 1977 due to numerous slippages in TVA responses.

  BOYD.R.S. Division of Project Henagement. 78/11/15. 3pp. 94382:003

- 7812080091 Forwards rev response to 770310 NRC ltr & add1 r 780811 & 780628 NRC ltrs requesting info on preoper teste be performed w/UHI sys & sequence of changeover oper from injection to racinculalition.
  OILLELAND. J. E. Tennsses Valley Authority. 78/12/04. 4 94108-028
- 7812080208 Forwards restated NRC views on seismic issues in of subj facile.

  BOYD.R.B. Division of Project Management. 78/11/30. 5p 94109:335
- 7812110142 Responde to 781113 ltr re lic sched for subj facilist of TVA responses to NRC questions dtd 1977 & 1978. Response to outstanding fire protec issues will be submitted by 781215 Requests issuence of SER & ACRB heari OllLELAND. J. E Tennesses Velley Authority. 78/12/06. 9
- 7812120138 forwards Abnormal Oper Instruc HAOI-1 for reactor requested by V Benerous on 781027. The AOI addresses use of auxiliary feedwater sys. Invites NRC to view 790121 preoper hat functional test of subject AOI-1, 2012/07. 174276: 333
- 7811070240 Finel rept re incorrect solamoids in chem vol & velves. Overly long velve stroke times due to neglect by constr personnel to follow drewings.

   Tennesses Valley Authority. 78/09/08. ip. 94039:188
- 7812210323 Summerizes 780922 Licensing Schedules Review Controlled of subj Facils & the lic review process.

  BDYD.R.S. Division of Project Hanagement. 78/09/28. 12
- 78i0ii0158 Forwards info & test results showing Flememastic suitable substitute for Flamemastic 71-A.which is prohibibly local govts due to asbestos content.

  GILLELAND. J. E. Tennesse Velley Authority. 78/10/03. 274048-201
- 7810130262 Forwards request for add1 info re saismic design review of applicant's rept "Justification of Baismic Designitude of Substitution of Baismic Designitude of Substitution of Project Menagement, 78/10/04, 55 94079;171.
- 7810180093 Forwards statement providing add1 justification design criteria used for subj facils, per NRC request of 780817. Statement supports conclusions drawn in TVA rept of 780301.

  GILLELAND, J. E. Tennesses Velley Authority, 78/10/06.
- 7810230156 Hydrology Engr summery for subj facil as request L. Q. Hulmen ltr. Recommendations for Rev to Sefety Eval Re; is included. SCHRIEBER, D. L. Consulting Engineering Osologist. AT-(4978/10/07). 38pp. 94164:302.
- 7810230120 Forwards environ monitoring rept. "Environ Radi-Levels Bequoyah Nuc Plent 1977". GILLELAND, J. E. Tennessee Valley Authority. 78/10/19.
- --7810250122 "Environ Rediosctivity Levels Bequoyen Nuc Pl Bince the plant has not achieved criticality if is not contributing radiosctivity to the environ Incressed le of radist ere a result of nuc weapons teeting in Chine Tennessee Valley Authority. RH-78-4-801. 78/09/30
- 7811070277 Forwards "Tritium Mgt Considerations for PNRs." TVA.
  OILLELAND, J. E. Tennesses Vellay Authority. 78/10/19, 94040:324.
- --7811070281 "Tritium Mgt Considerations for PHR's" re tri essemmats.alternative disposel methods & TVA conclus Concludas that release of overwhelming majority of tri es liquid is the preferred method of disposal. "Tennasses Valley Authority, 78/10/19. 226pp.
- 7811010073 Forwards results of review of environ espects o subj facil. 4 ancl:description of changes, referenced tabl & drawings, environ essessment of changes, copy of "Tritlu Mpt Considerations for PHRS". No suppl to FES is necessar QILLELAND, J. E. Tennessee Valley Authority. 78/10/30. 94481:060.

- 7811050074 Confirms that Solid State Protec Sys gen warning alarm circuit has been mad IAH Westinghouse Field Change Notices TVA-105755 Unit 1 & TEN-10572 Unit 2.
  OILLELAND. V.E. Tennessee Valley Authority. 78/10/30. ip.
- 7811290147 Notice of 781109 meeting in Bethesde w/util to review selsmic questions & responses.
  81LVER.H. Light Weter Reactors Branch 4. 78/11/02. 1p. 94239:331.
- 7811150137 Responds to 780330 & 780612 NRC request for add1 info on damonstration test & forwards 3 tests on sump & spray pumps. OILLELAND. J. E. Tennessee Valley Authority. 78/11/07 2pp. 94272: 304.
- --781i150i76 "Study of Effects of Steem Jets & Water Jets on Emergency Sump." Concludes that eir entrainment dus to break et steem generator nozzle will not adversely affect functional cepebility of sump.

  \* Tennessee Vailey Authority. 78/09/30. 14pp. 94272-306.
- --7811150196 "Model Btudy of Bequoyeh RHR Bump." Concludes initial design of sump was satisfactory for eli design conditions incl worst-cess 50% screen blockage, excepting air entrepment during initial filling.

  FAIN.T.Q. Tennesses Vallsy Authority, WM28-1-45-102. 7B/10/31.
  27pp 94272:320.
- --7811150199 "Rev NPSH Calculations for RHR & Containment Byray Pumps Operating in Racirculation Mode. "Verifies effectiveness of the containment sump & describes constr of 1:4 sceis physical model w/test results.

  4 Tennessee Velley Authority. 78/10/27. 9pp. 94272:349.
- 7811130152 Forwards dreft response to Gusstion#8 transmitted in 770510 NRC ltr.Response revs Amend#49 to fecil FBAR & will be incil in Amend#58.
  GILLELAND, J. E. Tennesses Veiley Authority. 78/11/09. 18pp. 94273:015
- 7811210288 Notifies util of 781205 seminar in Atlente to discuse naw Model Rod Effluent Tech Spece & and seminar info sheet, registration form & proposed agends.

  O'REBLLY, J. P. Region 2. Atlenta, Office of the Director. 78/11/09. See.
- 7811160098 Responds to 780628 questions trensmitted by R Boyd re FBAR. Enc1 responses will be incorp into Amend#58 of FBAR. OlLLELAND.J.E. Tendessee Valley Authority. 78713714. Jpp. 94139:091.
- 781116014B Responds to 770802 NRC request for info re energytical model used to determine maximum containment temp & pressure for epectrum of postulated main steem line breaks for verious reactor pur levels.
  OILLELAND, J. E. Tennessee Velley Authority. 78/11/14. 29pp. 94139: 265.
- 7811210305 Forwards Amend#57 to Lic Appl.
  MILLB.L.M. Tennessee Valley Authority. 78/11/15. 1p. 94487:183.
- --78:12:03:10 Amend#57 to Lic Appl cansisting of deletion of chapter 16.
  major rev to Bection 15.4 to incl ECCB Append K enelysis &
  TVA's responses to questions 10-23 in 78050B NRC ltr.
  e Tennesses Valley Authority. 78/11/17. 149pp. 74487:184.
- 78i1290081 Forwards RevMi\*Draft Radioligical Effluent Tech Bpec"for PMR's (AVRE0-0472) & "Preparetion of Rediological Effluent Tech Spec for Avc Pur Plants" (AVRE0-0133). W/encl AND: 78i1270173 & 78i1270180. VASBALLD, D.B. Assistant Director for Light Hetsr Reactors. 78/11/16. 6pp. 02798:181.
- 7812130330 Forwards corrections to 781106 ltr transmitting snyiron & seismic qual info.
  OILLELAND, J. Tennesses Valley Authority. 78/12/05. ip. 94418: 140.
- 7812280141 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants info submitted must be substantiated by data & calculations, Licenses must notify NRC of any inaccuracies or anforcement action will result. DAVIB.J. 9. Optice of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp.
- 7812120170 Forwards marked-up drawings of control room as requested by NRC during 781027 meeting w/TVA. W/encl 3 oversize drawings available in Central Files.

  91LLELAND, J. E. Tennesses Velley Authority, 78/12/07, App. 94275:362.

- 7812180130 Forwids addl metl re Balance of Plant Class IE equip qua Addl metl not encl. OILLELAND, J. E. Tennessee Valley Authority. 78/12/07. 1p. 94365:001.
- 7812140242 Forwards requests for add1 info re containment, elec.inst control sys of subj facil.
  VARQA, 8.A. Light Water Reactors Branch 4. 78/12/08 13pp. 94205; 226.
- 7812270202 Responds to 7B1004 request for add1 info on seismic desibess for subj facils. Info discusses sensitivity of site specific SBE response spectra day from strong motion records & probabilities of exceeding SBE design spectra GILLELAND. J.E. Tennesse Vailey Authority 78/12/19 120pp. 94017: 220
- 7812290047 Summary of a 781207 meeting w/TVA re Subj Fecil Environ Specs.
  HATKINS.R.V Environmentel Projects Branch 1. 78/12/21. 2pp. 94189:339
- E NRC Sefety Evaluation Report (SER), supple & correspondence
- 7811020024 Rept of 780921 conference cell w/TVA representatives re the resoulation of 20 open instrumentation & control items in subj facil draft BER.Perticipant list encl. LASHER.D.R. Electric, Instrumentation & Control Bystems Brench. 78/10/25. ilpp. 94355:340
- F. Security, medical, emergency & Pirs protection plans
- 7810230135 Submitting second interim rept re high pressure fire protection pump failures. Redesigned mechanism for locking pump impailer to pump sheft. Next rept will be submitted by 781103.

  OILLELAND, J. E. Tennesses Vailey Authority. 78/09/14. 1p. 94271:173
- 7810300236 Notifies of 781026 meeting w/TVA to discuss firs protecting facil.
  81LVER.H. Light Weter Reactors Brench 4. 78/10/19. 3pp. 94034:038.
- 7810310113 Forwards 760825 Physical Security Pien, revised to rafls istast changes in proposed security eys. Replaces 770510 Physical Security Plan. Encl withheld (ref 100FR2.790), GILLELAND, J.E. Tennesse Valley Authority. 78/10/19. 2pp. 94093.318.
- 78:1140:34 Forwards responses to 780920 NRC ltr re Rediological Emergency Plan & quality assurance prog. Responses will be dotumented in Amend 58 of the FBAR. GILLELAND. J.E. Tennesse Valley Authority. 78/11/09. 15pp. 94428-250
- 7811150123 Forwards responses to fire protection review questions i Auxiliary Sys Branch 780901 itr. OILLELAND, J.E. Tennesse Vailey Authority. 78/11/09. 85pp. 94114:147.
- 78:2180374 Summery of 78:1026 mesting w/applicent to discuss protectives: Conteinment Annulus Area, ERCM Pur Cebles, Fsedwater Line Neter Hammer & implementation schedule, SILVER, H. Light Weter Reactore Branch 4, 78/12/08, 6pp. 94358: 200.
- 7812210248 Forwards TVA's response to fire protec review questions #12 & #13 re sub; facil, Also encl are revised definition of implementation sched & minor editorial revs to TVA responses of 781109.

  GILLELAND, J. E. Tennessee Valley Authority. 78/12/19. 104pp. 74/46: 036.
- K. Utility Finel Safety Analysis Report (FSAR) & amends
- 7812120166 Forwards meth for NRC review of subj facil's change of cleening procedures of sustenitic pipe.FSAR draft amend page 5.2-68.ref Hestinghouse space 84351NL & 597760, & ref Dept of Energy Space.RDT F-1T are encl. GILLELAND, J. E. Tennesse Valley Authority. 78/12/07. 33pp. 94278: 108.
- 7810170197 Forwerds affidavit certifying that on 781010, copies of A 55 to subj facil FBAR were served on individuels identified in affidavit by use of U.S. Hail.
  MILLE, L. M. Tennasses Valley Authority. 78/10/10. 2pp. 94411:8

- 7811300198 Forwards cert of evc for amend 57 to subj facil FBAR.
  MILLS, L. M. Tennessee Valley Authority. 78/11/24. 2pp.
- 7812260131 Furwards Amend#58 to appl for subj facil FSAR changing Chapters 5,7,8,9 & 12.

  OILLELAND, J E. Tennessee Valley Authority, 78/12/21. 1p. 94023:226
- --7812260134 Amend#59 to F9AR, changing Chapters 5,7,8,9 % 12.
  P Tannessee Veliay Authority, 78/12/21, 150pp. 94028; 227.
- @ Inspection reports. IE Builetins & correspondence
- 7812120051 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Nawsletter.
  KENNA.W.B. Region 2. Atlanta. Safeguards Branch. 76/11/17. 4PP.
- 7810270213 Forwards IE Inspec Repts #50-327/78-23 & #50-328/78-17 on 780802-03 during which no items of montempliance wars noted. BUTHERLAND, J. T. Ragion 2. Atlants, Fuel Facility & Materials 8afety Branch. 78/09/12: 2pp 94053:131.
- --7810270221 IE Inspac Reptm50-327/78-23 & #50-328/78-17 on 780802-03 during which no itams of noncompliance were noted. Major areas inapacted included: liquid waste sys. status of unreactived items & preoper testing.

  EWALD. B. C. JACKBON-L. L. Region 2, Atlants. Office of the Director 78/09/12. 4pp. 94053-133.
- 7811080187 Forwards 1E Inspec Repts#30-327/78-22-#30-328/78-16 on 780802-03 during which no items of noncompliance were noted. BUTHERLAND.J. T. Region 2. Atlante. Fuel Facility & Materials Safety Branch. 78/09/27 2pp. 94405:131.
- --7811080191 IE Inspac Reptem50-327/78-22.#80-328/78-16 on 780802-03 during which no items of moncompliants were noted Hajor areas inspected include:preoper anviron monitoring, constressed effects monitoring, environ controls meteorology measurement. CLNNINGHAM, A.L. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/09/27. App. 94403:133.
- 7811130093 Forwards IE Inapac Repts#50-327/78-29 & #50-328/78-20 on 780829-30 & 780901 during which no itams of noncompliance were noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/10/02. 2pp. 94011:192.
- --781113010B IE Inspec Rapts#50-327/78-29 & #50-329/78-20 on 780829-30 during which no items of noncompliance were noted. Major areas inspected includes: procedures work activities, quality related records for sefety-related components. RAUSCH. J. K., HARRIS. J. K., HERDI. A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/02. 7pp.
- 7810250095 Forwards rev 5 to "Presvc Baselina Inspec & Insvc Inspec Prog", incorporating changes to Class B presvc inspecs to include only those welds & components which req insvc axamination.

  OllELAND, J. E. Tennasses Vallsy Authority. 78/10/19. App.
- 7812050303 Forwards 1E Inspac Rept#50-327/78-30 & #50-328/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHY-C.E. Region 2, Atlants, Reactor Construction & Engineering Support Branch. 78/10/24.
- --7812050307 IE Inspec Rept#50-327/78-30 & #30-328/78-29 on 780919-21 during which no items of noncompliance were noted Major area inspected incl.:reactor coolant pressure boundary piping welding records & safety related structures welding. VANDOORN.P.K. Region 2. Atlants. Reactor Construction & Engineering Bupport Branch. 78/10/23. 4pp. 94203-046.
- 7812060268 Forwards 1E Inspec Repts#50-327/78-24,50-328/78-19 on 780926-29 during which no items of nontempliance were noted, NURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/31. 2pp. 94372:241.
- --7812060274 1E Inspec Rats#50-327/78-24,30-328/78-19 on 780926-29 during which no items of noncompliance were noted. Major areas inspected intilicensee action on previous findings, licensee identified item, instru work & GC records.

  GIBBONS, T. D. RUFF, A. Region 2, Atlenta, Resotor Construction & Engineering Support Branch. 78/10/27. Spp. 94372:243.
- 7812060287 Forwards IE Inspec Repts#50-327/78-02,50-328/78-23 on 780721-22 during which no items of noncompidance were noted. MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Bupport Brench. 78/10/31. 2pp. 94372:301.

- ---7812060291 IE Inspet Repts#50-327/78-32.50-328/78-23 on 780921-22 during which no items of noncompliance were noted Major areas inspected incliection on previous inspec findings. eposy anchored bolts in concrete. ERCH concrete cells & pips. HARIS.J.R. COMPTON.R.M. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 78/10/31. 4pp. 94372:303.
- 7812130001 Forwards 1E Inapec Repte#50-327/78-27 & #50-328/78-21 on 780726-27 & Notice of Violation MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/11/01. 2pp. 94318:266.
- --7812130004 Notice of Violation from inspec on 780926-29.

  A Region 2. Atlants, Office of the Director. 78/11/01. ip. 9418-348
- --7812130005 IE Inspec Repts#50-327/78-27 & #50-328/78-21 on 780926-29 during which i item of noncompliance was noted failure to document audits of all applicable alements of the GA prog. HEDDIA.A.R. Region 2. Atlanta. OPFice of the Director. RAUBCH.J.K. MCFARLAND.C.R. Region 2. Atlanta. Reactor Construction & Enginearing Support Branch. 78/11/01. 13pp. 2020.
- 7811130073 Forwards IE Circular 78-18.

  D'REELLY, J. P. Region 2. Atlanta: Diffice of the Director. 78/11/06.

  1p.
- 7812130030 Forwards 1E Inaper Repts#30-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Brench. 78/11/07. 2pp. 94210:022.
- --7812150040 IE Inspec Repts#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted Major areas inspected incli-previously identified items concerning understrangth concrets in Unit 1 & 2 ahiald bldgs. HAR18-J.R. COMPTON.R.M. BRYANT.J.C. Region 2. Atlanta, Defice of the Director. 78/11/02 3pp 94210:024.
- 7812050111 Ack recaipt of 781020 ltr informing NRC of staps taken to correct violations noted during Inspec#50-327/78-25 & #50-328/76-18.
  MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/21. 1p. 94333:175.
- --7812050117 Responds to 781002 NRC itr re violations noted in inspec Rept#80--327/78-25 & #50-328/78-18. This is rev in rasponse w/add1 infor as requested. Corrective actions: savaral atess & to be taken are detailed re installation of proper enubers. GILLELAND, J.E. Tennessee Valley Authority, 78/ii/14. 4pp. 94330: 176.
- --7812050125 Responds to 781002 NRC ltr re violation noted in Inspec Repts#30-327/78-25 & #30-328/78-18. Corractive actions: paint removed form grease fittings of snubber-proper lubrication documentad, debris removed from apring can of support. GILELAND.J.E. Tennassee Valley Authority. 78/10/25. 3pp. 7433: 180.
- --7812050140 Forwards IE Inspec Repts#50-327/78-25 & #50-328/78-18 on 780808-ii & Notice of Violation. MRFHy.C.E. Region 2. Atlanta: Reactor Construction & Enginaering Support Branch. 78/10/02. 3pp. 94333:183.
- --7812050147 Notice of Violation from Inspec on 780808-il.

   Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 7870702. 19. 94030:186.
- --7812050150 IE Inspec Repts#50-327/78-28 & #50-328/78-18 on 780808-19 during which I item of noncompliance was noted: failure to follow procedures during langer installation.
  AND, M.P., BRYANT, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/09/29, 5pp. 94333:187.
- 7812040369 Forwards IE Bullstin#78-12A, suppl to IE Bulletin 78-12.
  W/ancl ANO: 7811300055.
  O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24.
- 7812040065 Ack receipt of 781130 its informing NRC of steps taken to correct violations noted during insp 50-327/78-14 & 50-38/78-10. MURHY.C.E. Region 2, Atlanta, Redctor Construction & Engineering Support Branch. 78/11/30. 1p. 94232:264.

# DOCKETED ITEMS

- --7812060074 Responde to 781002 NRC ltr requesting addl info re violation noted in inspec ReptaMSO-327/78-14 & SO-328/78-10. Corrective actions: employees instructed to protect permanent equip incl instructed to the protect permanent equip incl instructed to stationary actions are demage. OILLELAND. J. E. Tennesses Valley Authority. 78/11/09. 4pp. 94232: 265.
- 7812070177 Forwards responses to 781111 IE insp Repts 50-327/78-27 & 50-328/78-21.re GA unit audits Contends full compliance has been mainteined. Firm audit policy has been established.
  OILLELAND.J.E. Tennesses Valley Authority. 78/11/30. 3pp.
- 94375: 025.
- 7812270229 Forwards 1E Bullstin 78-14. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/12/19. 2pp. 94017:131.
- 7812290114 Ack receipt of 781207 itr informing NRC of staps taken to correct violations noted during inepec#50-327/78-33 &
- #50-G28/78-24.
  MURPHY.C.E. Region 2. Atlanta. Resctor Construction & Engineering Support Branch. 78/12/20. ip. 94190:188.
- --7612290122 Forwards 1E Inspec Repts#50-327/78-33 & #50-328/78-24 on
- 3122/0122 Forwards to suspect representation of the suspect representation of Violetion. MRPHY, C. E. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 78/11/16. 2pp. 94190; 191. --7812290125 Notice of Violation from inspec on 781025-27.
  \* Region 2, Atlanta, Office of the Director. 78/11/16. ip.
- --7812290128 IE Inspec Repte#50-327/78-33 & #50-328/78j-24 on 781025-27 during which i Item of honcompilence was noted: feilure to
  - log welding rud oven temp.
    VANDORN.P.K., CONLON, T.E. Region 2: Atlante, Resctor Construction
    & Engineering Support Brench. 78/1:/16. 3pp. 74190:194.
- 8 Reportable occurrences, LERs & related correspondence
- 7812010266 Forwards final deficiency rapt re failure of sump velves to open during automatic switchover testing. GILLELAND, J. E. Tennessee Valley Authority. 78/10/26. 1p. 94417: 154.
- --78:2010268 Fine: rept on failure of sump valves to open during automatic switchover testing. Circuitry design was inadequate & schematics have been corrected. Correction will be tested
  - before unit oper. \* Tennessse Valley Authority. 78/10/26, 1p. 94417:155.
- 7812140288 Revised rept "Deficient Foundation Preparation for Contrete Cells for the ERCH Pumping Station Access Readway."
  GILLELAND. J. E. Tennesses Vellay Authority, 78/11/29. 3pp. 03557:360.
- 7811070236 Forwards final deficiency rept re incorrect solanolds on
- velves. GILLELAND, J. E. Tennesses Velley Authority. 78/09/08 lp. 94039: 187.
- 7810190164 Bubmits first interim rept re failure to provide selamically quelified path for makeup to spent fuel storege fecil Proposel under study to install qualified line & nacessery velves from common discherge of pumps. GILLELAND. J.E. Tennesses Valley Authority. 78/09/14. 2pp.
- 94414: 103. 7Bii030263 Forwards First Interim Rept re difference between Plant
- Configuration & Drawing NCR-2p.

  Q1LLELAND, J. E. Tennessee Valley Authority. 78/10/14. ip. 02725: 256.
- ~-7811030265 First Interim Rept of Deficiency NCR Ep: "Plant Configuration Different than Drawings of Record" due to error to TVA drawing certification process. GILLELAND, J.E. Tennessee Valley Authority. 78/10/16. 1p.
- 7811070275 Third Interim Rept re Dissel Generator Hydraulic Actuator Motors. Status that supplier has Instructed governor and to test governor appead control motor. Next rept will be submitted 781220.

  OILLELAND. J. E. Tennesse Valley Authority. 78/10/05. 1p. 94040: 299.

- --7612040197 Final rept re incomplate documentation of selsmic qual of electrons. Documentation written per old TVA requirements. Current construc will withstand all design
- loadings & no thanges in hardware are req. Tennssses Valley Authority. 78/10/20. 1p. 94457:119.
- 7812030265 Forwards final deficiency rept re seismically qual path fo makeup to spent fuel storage factl.
  GILLELAND, J. E. Tennessee Valley Authority. 78/11/03 ip. 94202: 143.
- --7812050270 Final deficiency rept: seismically qual sath for makeup t spent fuel storage facil not provided due to improper design. Line & velves will be installed & seismically qual. 6 Tennesses Valley Authority. 78/11/03. 1p. 94202:164.
- 7812060121 Forwards final deficiency rapt on Control Room Back Draft Damper Failurs.
  GILLELAND, J. E. Yennesese Valley Authority. 78/11/08 1p 94332: 227.
- -- 7812040129 Final Rept: Pailure of Back Draft Damper in Main Control ( Air Hendling Unit discovered during routine med of sys.

  Damper lost all blades due to excessive blade bearing wear.
- Failed dampers replaced w/high-pressure units. \* Tennesess Valley Authority. 78/11/08. 7812140286 Forwards revised finel rept "Deficient Foundation Praparation for Concrete Cells for the ENCW Pumping Station Access Resdway."
- GILLELAND, J. E. Tennessee Veiley Authority, 78/11/29. 1p. 03557: 359. DUCKET 50-329 MIDLAND PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7810270024 Forwards I & E Initial Rept on Response to Bulletin 77-03/05A re Use of Elec Connectors appropriate 8ds should be notified where there is a question re use of connectors in sefety sys:780207 memo also encl.

  TEDEECO.R.L. Assistant Director for Plant Bystems. 78/02/08. ip.
- --7BiO270246 Forwards "Btatus of Responses from Licensees of Plents of Construc to Bulletins 77-05 & O5A".
  MCBELEY, N. C. Division of Reactor Construction Inspection. 78/02/07. Spp.
- 7810310061 Forwards preliminary chart on results of land use survey completed last year re building & housing trends in Midland County 1969-1977.

  \* Midland County MI. 78/04/10. 3pp. 94093:179
- 7810140006 Notice of time & sgenda change for meeting on 781025 to discuss augmented insic inspac & testing of pumps & valves. HOOD, D. Light Weter Reactors Branch 4. 78/09/23. 5pp. 94329:097 7810120072 Forwards BEW rept "Analysis of Beering Failure in LH&O 900 HP Vertical Pump Motor Resulting From Gil Cooler Failure" prepared for CPC, Rept evailable in CF only, DDMELL.8. Consumers Power Co. 78/10/05. ip. 94470:345.
- --78:0120077 "Anelysis of Bearing Fallure in LMt0 9000KP Vertical Pun
- Motor Resulting from Oil Cooler Failure properts by BLW for CPC. & forwarded to NRC. Determines Kingsbury thrust bearing to be critical component in event of oil cooler failure.

   Babcock & Wilcox Co. 77/10/10. 107pp.
- 7810130231 Forwards archesological site survey for Midland County MI to be edded to minutes of Baginaw meeting of 780906.

  BRUNETT, F. V. Beginaw Archeeological Commission. 78/10/05. 11pp.
- 7810200128 Requests add1 info as result of sits visit to subj fecil : order to review environ factors. Response should be submitted by 781025. Response should be suppl to Environ
- Rept. REGAN, W. H. Environmental Projects Branch 2. 78/10/11, 9pp. 94366: 310.
- 7B10R30375 Believes that there is a potential problem w/clase IE bettery racks supplied to suby facil. Addl isolation bar for asismic protec will be available for retrefit w/in 60 days. MCMANUS.C. K. EBB. Inc. 78/10/11. ip. 94271:184.
- 7810190066 Forwards duplicate of original 780629 lir containing affidavit re proprietary response to request for addl info.
- 7812040192 Forwards final rept re incomplete documentation of seismic

- 7811010308 CPC request to withhold as proprietary section 4.C of their gen Agreement w/Dow of 783621 per 10CFR2790 is granted. LYNCH.CLD. Environmental Projects Branch 2 78/10/12. 2pp. 94389-160
- 7810240013 Forwards summary dtd 780327: "Summary of March 21-22.1978 masting & sits visit".for the info of the NRC. TOURTELLOTTE. J Office of the Eracutive Legal Director. 78/10/13. ip.
- --7810240017 Summary of 780321 & 22 meeting w/util in Hidlend-Hi re facility const completion schedule. CROCKER, L. P. Division of Project Management 78/03/27. 13:pp.
- 7810740213 Requests eddi info for FBAR raview W/encl questionneire. VARGA:S.A. Light Water Reactors Branch 4. 78/10/13. 80pp.
- 7810220199 Repts on site visit to subj Pacil during week of 780905.
  Encloses summarized schedule of week's activities & principal personnel contacted
  LYNCH.D. Environmental Projects Branch 2 78/10/13. 15pp. 94392-205
- 7810250099 Forwards enci praliminary rapt "Prelimiary Pump & Veive Inservice Testing Program for CPC Midland Plants Units 1 & 2." Submitted in response to NRC question or FBAR.Plan.in part to form basis of 781025 meeting w/NRC. HOWELL.S.H. Consumers Power Co. 78/10/18. 2pp.
- --7810250100 "Pump & Valve Inexc Testing Prog" covering definitions of operational modes, pump summary listing legend & requeste for relief from Section-XI requirements. PETERSEN.T.A., RICE, R.M., BUCZMINSNI, I.A. Consumars Power Co. 78/10/18. 123pp.
- 7810250131 Requeste addi info re setimated GNP annual growth & ON vahicle produc growth rates used to forecast QM elec seles. REOAN-U.H. Environmental Projects Branch 2. 78/10/18. 3pp. 94372: 260
- 7811080015 Responds to 781011 NRC request for add1 info re 2 items of noncompliance noted in 780817 NRC ltr. Encl 781020 ltr from Bechtel to CPC discusses document control stamping & removal of void drawings from flies.

  HOWELL, S. H. Consumers fower Co. 78/10/20. 3pp. 94398:035.
- 7Bi0270199 Response to 7Bi004 FDIA request for documents re completion dates for subj facil & detailed plent-specific enelysis. Forwards requested documents. W/snc1 list of documents. FELTON.J.M. Division of Rules and Records. 7B/10/23. QPP. 74056:30B.
- 7810270201 FBIA request for documents re estimated constr completion dates for subj facil & "detailed plant-epcific analysis"of those units.

  DOW.M. Public Interest Research Group. 78/10/04. ip. 94036:310.
- 7810310293 Approves request for withholding, section 4. C of the Gen Agreement between Dow Chem & util re price of energy sold to util under agreement. Price & cost of producing energy is held to be confidential info by NRC.
  REGAN. W. H. Environmental Projects Brench 2. 78/10/23. 3pp.
- 7811070332 Bummery of 780913 Masting at Bethesde, MD on info requested by Auxiliary Sys Branch re main steem & process steem piping-reactor coolent pump cooling & Pusi cask drop. HGOD. 0. H. Light Water Reactors Branch 4. 78/10/23. 4pp. 94039: 358.
- 7Biii30021 Bummary of 7B0914 meeting w/utii, Bechtel Corp & B&W in Betheede. MD re separation criteria & administrative procedures for installation of Class IE balance of plant equipment & circuits identified in PBAR Amend 32.

  KOOD D. Light Water Reactors Branch 4. 78/10/23. App. 94075:313.
- 7810310364 Concludes that separation criteria for NSBS & Class IE belance-of-plant aquipment to non-Class IE circuits are per IEEE Btd 384-1974 & Reg Ouids 1.75 & acceptable. VARGALS.A. Light Mater Reactors Branch 4. 78/10/24. 3pp. 94093:106.
- 78:10:10092 Act receipt of 780929 interim rept re settlement of Diesel Generator Found & Bidg. Finel rept will be reviewed upon receipt.
  HEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/24. 1p. 94381:315.

- 78:101000G Responds to 780926 itr requesting NRC decision or potential release of section 4.C of contract between Dow Chem Co & Consumer Pur Co.NRC finds section 4.C metl confidential & proprietary. Request is denied. FELTON.J.N. Division of Rules and Records. 78/10/26. I 94290.240.
- --7811010010 FOIA request for info re correspondence involvement Dow Chem & Consumer Pur Co.
  FREEDMIN.B. Public Interest Research Group 78/09/26 94290:241.
- --781i010013 FOIA request for esction 4. C specifying retes process steam supplied to Dow Chemical by util. FREEDRING. Public Interest Research Group. 78/07/15.
- 94270.242.

  7811130107 Notice of 781106 meeting w/subjutil on staff refer addl info re extension of construction dates for
- facile
  HDOD, D. Light Water Reectore Brench 4. 78/10/30. 2pp.
- --78iii50i09 Requests addl info re constr permit extension on 770829. VARQA, B.A. Light Water Reactors Branch 4. 78/10/27. SAII3-200
- 7811240185 Responds to 781025 ltr.City hee 41 police office cars & no impact on crime rate from constr of subj facil.
  HARCEK.D.S. Midland County, MI. 78/10/30. 1p. 94458:
- 7811240199 Forwards Mi Supreme Court decision dtd 771024 L documentation re ennaxation of sub; sits to City of Midla RAE, J. J. Midland City, Mi. 78/10/30. ap. 94458:305.
- 7811240188 Responds to 781025 ltr.Pert ecreage in City of Papptor 2700 acres & total park space exceeds standards. MOFFATT, D. W. Midland City. Mi. 78/10/31. ip.
- 7811140039 Forwards request for add1 info re main steam lie accident, Requires that power distribution distortions can by stuck rod be considered during both initial portion to later return-to-subcritical-power portion of enalyses. VARQA, 8 A. Light Water Resctors Brench 4, 78/11/01. 39 94425:001.
- 7811240166 Confirms 780912 info.41 law enforcement officers cars involved. Crime rate not effected by conetr of subjecti.

  MCNUTT.J.R. Middend County, Mi. 78/11/01. ip. 94458:
- 78:1090:43 Responds to 78:01: request for addi info re equiscology; hydrology, water use & quality, & traffic count daw/Agreement batwaen Wolverine Pur Co & CPC, Discharge PeriAppl by CPC, & other enci.
  HOWELL, S. H. Consumers Power Co. 78/11/03. 10:1pp. 940:
- --78i1090149 "Study of a Non-Buoyant Plume: Presence of a Bi in an Undirectional Ambient Flow." Hydrothernel model : when conducted to determine satisfactory design for copond blowdown dischargs. RUBEROEL J.C., NYQUIST.R.O. Bechtel Power Corp. (subs. Corp. ), 78/09/30, 98pp.
- --7811070156 "Cooling Pond Oper Study". Preliminary Rept. Far pond oper was simulated by use of makeup & blowdown ey control pond TDS contentrations. LIOU.C.P., APADAKIS.C.N. Bachtel Power Corp. (subs. o Corp.). 78/09/30. 55pp. 94043:015.
- --7B11090139 Tabular data on traffic counts for county roa of proposed sits. RADD-U.H. Michigan, State of, 78/10/13, 34pp.
- 7811240186 Confirms 780912 telephone conversation, City of treatment facils will be expended to treat total of 48 million gallons/day & be adequate until 1990. EMING.M.C. Midland City. MI. 78/11/06. 1p.
- 7811130143 Natifies applient of 781188 NRC-sponsored semi Radiological Effluent Tach Space for Nuc Pur Plents. End w/Sminer info Sheet to be completed & returned by 78111 Proposed Agenda. KEPPLER. J. G. Region 3. Chicago. Office of the Director. App. 74087:333.
- 78:1240:84 Responds to 78:025 ltr. Current school enrollmen Bldgs in school district can accommodate 2500 new studen in 190. BAKER.R. Midland City, MI. 78/11/07. lp. 94458:301.

```
76:1200159 Forwards for review by Baismic Qual Review Team(8QRT) listings of encl portions of SQRT info & schedule for providing currently unavailable data & completed SQRT forms.
    HOHELL, B. H. Consumers Power Co. 78/11/13. 84pp. 02760: 061.
78it20012i Forwards Crana Packing Co Builetin 3472: "Beal Performance
Test for Nuc Pur Plant Sefety Injection Sys" to support
util's assumptions on HPI pump seal leakage as discussed et
780920 meeting w/NRC re ESF filtretion issue.
    HOHELL, B. H. Consumers Power Co. 78/11/14. 83pp. 94220: 257.
```

- 78ii 240i 90 Responds to 78i025 request for confirmation of telephoned data re Midland Hosp Assoc(personnel count. Not admissions). Confirms info on file is provided by hosp. Occupancy rate is
- RATHBUN, K. J. Michigan, State of. 78/11/14. 2pp. 94458:310. 78:1280127 Summary of 78:106 masting w/CPC in Bathasde.MD ra extension of const completion dates. Dreft response to 78:027 questions
- HOOD, D. Light Water Reactors Brench 4. 78/11/14. 15pp. 7811280130 Notification of 781203-04 meetings w/CPC in Midland, MI Ta settlement of dissal generator bldg & other structures. Agenda ancl.
- HOOD, D. Light Water Reactors Branch 4. 78/11/14. App. 7811280131 Summary of 780820 meeting on steam line breek methodology, cold shutdown position & sefeguerds pump room leakage Wanci list of attendas & applicant's responses to NRC questions.
  HOOD, D. Light Hater Reactors Branch 4, 78/11/14, 27pp. 94013:083.
- 7811270087 Forwards request for eddl info for review of eppl for oper lic for subj facil.Response req by 781208:3 originals & 147 coples/41 ere to be forwarded & 109 to be reteined.
  REGAN.M.H. Environmental Projects Branch 2, 78/11/16. 5pp.
- 7811280091 Forwards Ravel"Draft Rediciogical Efficient Tach Spec for PWR's"(NUREO-0472) & "Preparation of Radiciogical Efficient Tach Spec for Nuc Pur Plants"(NUREO-0133). W/enc1 7811270173 & 7811270180.
  VABBALLO.D.8. Assistant Director for Light Hater Reactors, 78/11/16. 6pp. 02726:322.

94260: 340.

- 7811300007 Porwards order extending completion on dates from 781201 & 791201 to 821001 & 911001 for Units 1 & 2.respectively.

  \* VAROA.S.A. Light Heter Reactors Branch 4. 78/11/17. 3pp. 94047: 348. --7811300011 Order extending const completion dates from 781201 to 821001 to 811001 for Units 1 to R. respectively, Evaluation of request for extension of CPPR-81 to CPPR-82 encl.
- BOYD.R.S. Division of Project Management, 76/11/17, 7pp. 94049:344. ---7811300019 States environ impact statement for extension of constr permit not warranted. All necessary info described in Final Environ Statement-Constr Permit Stage. REDAN, W. H. Environmentel Projects Brench 2, 78/11/17. Spp. 94077: 023.
- ~-7811200023 EIA concluding no EIB need be prepared for proposed action. \* Division of Bits Sefety & Environmental Analysis. 78/11/17. 2pp. 94077: 025.
- 7812050074 Sefaby evaluation supporting extension of Const Parmits CPPR-81 & CPPR-82.
- HOOD, D. , VARQA, S. A. Light Weter Reactors Brench 4. 78/11/17, 5pp. ~-7812080097 Environ Impact Appraisal concluding that extension of subj facil Constr Parmita CPPR-Bi & CPPR-B2 will cause no major add1 environ impact, W/Negative Declaration. Division of Site Barety & Environmental Analysis. 78/11/17.
- 7811270147 Forwards Amend 53 to CP & OL application, containing update to general info portion.
  HOWELL.S.H. Consumers fower Co. 78/11/21. 1p. 94271:343.
- ~-7811270(51 Amend 52 to CP & CL application re basis for completion date extension. Unit i extension from 771201-781201 to 811001-821001 & Unit 2 extension from 781201-791201 to 801001-811001. Delay partially due to finances.

  \*\* Consumers Power Co. 78/11/21. 16pp. 94271:344. 7811270182 Forwards add1 copies of CPC responses to Suppl Requests for Add1 Info:Part2.originally transmitted to NRC by 1tr of 781102 M/enc1 ANC:791140108.
  HCMELL.S.H. Consumers Fower Co. 78/11/21. 1p. 94232:355.

- 7812070280 Notification of 781211 meeting w/CPC.Bechtel & B&W in Bethesds, MD to appeal NRC position that facilities be capable of obtaining cold shutdown conditions using only sefety grade equipment. HOOD D. Light Water Reactors Branch 4. 78/11/27. 4pp. 94085.05 7812050142 Forwards Cart of Svc for Appl for Constr Permit & Oper Li BACCN. J. L. Consumers Power Co. 78/11/29. 2pp. 94334: 350.
  - 7812000213 Forwards Certificate of Bvc for Amend 54 to CP & OL application containing Revision 15 to FBAR BACON, J. L. Consumers Power Co. 78/11/30. 1p. 94318:345.
  - 78:2120002 Forwards supplemental second round question from Resector Physics Section re-criticality of proposed high density storage system. 80061305491
    TEDEBCO.R.L. Division of Bystems Sefety. 76/12/01. 1p. 94274:29
  - 78:2120068 Responds to 78:01: NRC ltr.eddi info re Aquetic Ecology & Hydrology, Weter Use & Quality & Archaeology, Forwards rev of 8tate Discherge Permit Appl.rev of Appl for Permit to Discharge Weter & Archaeological Rept HOWELLS.H. Consumers Power Co. 78/12/05. 283pp. 94278: 104.
- 7812280118 Emphasizes importance of submitting accurate & complate in to NRC by licensess & applicants info submitted must be
- substantiated by data & celculations. Licensee must notify NRC of any inaccuraties or enforcement ection will result. DAVIS.J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:213.
- 7812120104 Forwards Amend 55 to application for CP & DL & Revision 4 to Environ Rept, OL stage.
  HOWELL-8. H. Consumers Power Co. 78/12/07. 1p. 94275: 029.
- --7812120111 Application for CP & OL. W/Revision 4 of Environ Rept. HOWELL, 8. H. Consumers Power Co. 78/12/07, 194pp. 94275:030. 7812180391 Responds to request for withholding info submitted on 7804 & 0629 (ref 100582, 790). Forwards tables listing criteria used by 8kH to determine whether submitted matis are proprietary & proprietary cleim of mati submitted. VAROA-8. A. Light Water Reactors Branch 4. 78/12/07. 7pp. 92377-244
  - 94357: 266. 7812260188 Discusses questions raised during visit re dissei generate settlement problem.
    COOME.T.C. Consumers Power Co. 78/12/07. 2pp. 94159:156.

  - 7812210274 Notification of 781220 masting w/CPC & 8&M in Sethesda MD to discuss single failure proof crane for apent fuel, datails of full-scals modeling tests planned for containment sump & steam line break analysis w/stuck control rod assembly.

    H000 D. Light Water Reactors Brench 4. 78/12/11. 4pp. 94167:320

  - C. Utility Environmental Report (ER), emends & correspondence
  - 7811070149 Responds to 781011 NRC 1tr re review of subj facil Environ Rept-Oper Lic Stage. Answers questions is archeological investigation of Tittebawassee River floodplain, mitigation or avoidance of archaelogical sites, acological survey. HDWELL, S. H. Consumers Power Co. 78/10/30, 2pp. 94044:096.
  - 7811170294 Forwards Amend 52 to Environ Rept re corrections of error requests for add1 info re original Amend.
    HOWELL,B.H. Consumers Power Co. 78/11/10. 1p. 94045:274. ~-7811170298 Amend 52 to Environ Rapt Ta corraction of errors & raquifor add1 into as requested by WH Regen's 780522,781011, &
- 7811280282 Forwards affidavit distributing copies of Amand#52 to CPC Appl for Constr Permit. Cent of Svc anci. BAN.J. Consumers Power Co. 78/11/20. 4pp. 94395: 2R8,

- 7812190095 Forwards affidevit for Amend 55 Rev4 to Environ Rept app1 for reactor conetr permit & open lic on 781211.

  BACON.J.L. Consumers Power Cp. 78/12/12, 4pp. 94381:036.
  - D. NRC Draft/Final Environmental Statements, supple & correspondence 7812050222 Ack cooperation in providing into for EIS for sub; facile Requests written confirmation of date provided re staffing.

781018 1trs. HOHELL, B. H. Consumers Power Co. 78/11/10, 20249. 94045:277.

- admissions & occupancy rate of Midland Hospital.
  HONO.S.W. Argonne National Laboratory. 78/10/25. 1p. 94201:148

- 7812050225 Act cooperation in providing info for EIS for subj facile. Requests unitten confirmation of data provided re planned expansion of water capacity of City of Hidland HDNO.S W. Argone National Laboratory. 78/10/25
- 7812050227 Act cooperation in providing info for EI8 for subj facile Requests written confirmation of data provided re acreege of partiand in the City of Midland & that the total space devoted to parts & recreation exceeds gan standards HONO.S.W. Argonne National Laboratory 78/10/25 ip. 94201-200
- 7812050232 Act cooperation in providing info for E18 for subj facils. Requests written confirmation of data provided rs W of law sufforciment officials & patrol cars in Hidland County, & that constr of facils has not affected local crime rate HONO, S W Argonna National Laboratory. 78/10/25 ip 94202:023.
- 7812050239 Act cooperation in providing into for E19 for subj facils. Resusts written confirmation ofdate provided rem of police & petrol cars in City of Midland.k that constr of facils does not impect on local crime rete

  HONO, 9 H Argonna National Laboratory 78/10/25. 1p 94202:045
- 7812050244 Act cooperation in providing info for EIS for subj facile.
  Requests written confirmation of data provided re current
  enrollment & unused capacity of the Bullock Creek School
  District
  HDNO. B W Argonne National Laboratory 78/10/25. Ip. 94202-067.
- 7812050250 Act cooperation in providing info for EIB for subj fecils. Requests written confirmation of deta provided re current enrollment & unused cepacity of the Midland School District. HDNG.5-W. Argonne National Laboratory 78710725. ip. 94202:114.
- 7812050255 Act cooperation in providing info for EIS for subj facils. Requests written confirmation of deta provided reconfirmation by State Supreme Court of annexation HDNO, S.W. Argonna National Laboratory. 78/10/25 ip. 94202:127.
- G. Adjudicatory correspondence
- 7810110309 Answer of Consumers Pur Co to Patition for Leave to Intervene of M.H Marehall on behalf of the Mapleton Intervenors Intervention should be denied for untimeliness. & perticipation would not contribute to record.

  MILLER-M 1. 01885, M.E. Isham, Lincoln & Besle. 78/09/28. 13pp. 94061 016
- 7810250152 Natice of withdraws) from proceeding as of 780929. Certificate of Byc shcl. OROSSAN.H.J. Hearings Division. 78/09/29. 3pp.
- 7810140027 NRC staff ensuar to patition submitted 780909 by H Marshell requesting leave to intervene on behalf of Megalton interveners NRC staff does not oppose patition at this time. OLHSTEAD.H. J. Office of the Executive Lagel Director. 78/10/03. 7pp. 94421-032
- 78i1020381 Notice of Hithdrawal of Appearance accompanied by Notice of Appearance for David Bonderman, replacing Cohen & Cert of Svc.
  COHEN.R.C. Arnold & Porter. 78/10/06. Spp. 94354:282.
- 7810240157 Notice of hearing on issuence of DL license. SER, FEB, DEB, ACRS rept on DL application. Tech Space & intervention patitions, related papers & Soard 780814 margrandum & order may be inspected at NRC PDR. Cartificate of Svc enci.

  SHITM, I W Atomic Bafety and Licensing Board Panel 78/10/12. 4pp.
- 78102:0198 Hendrendum & order granting HH Marshall temporary etatus as intervanor pending Board final determination on adequecy of intervantion getition. Hegalaton intervanore mey file enended patition demonstrating interest in proceeding.
  SMITH, I.M. Atomic Bafaty and Licensing Board Penel. 78/10/12. 6pp. 94072:241.
- 7810300311 Repts predicted util figures for long-term electricity demand for 1978-88 per letest short-term forecast. MILLER.M.I. leham. Lincoln & Seals. 78/10/18 2pp. 94253:317.
- 7811010006 Forustds another copy of the 8d Hemo & Order of 780814 & Natice of Hearing on Issuence of Facil Oper Lic of 781012 In response to 781018 Hailgram Informs that requests for data should go to staff, not 8D. M/o enci.

  SMITH. I. M. Atomic Sefety and Licensing Appeal Panel. 78/10/23.
  29s. 94290.237.

1

- 7812050132 Order referencing re-encetation of subjects to Ci Midland MI forwarded as enci to ANO.7811240199. HARRISON M. O. Michigan, State of 78/10/30. 43pp. 01791
  - 78:1100146 Forwards contentions that MI law prevents lic that a nuteants: illegal redist spills are occurring apent fuel restorage has created becards loing & forging nuteants is occurring & present tech feils to achiev zero emission. NARBHALL-W. H. Hapleton Intervenors. 78/10/31. ip. 9404:
  - 78:11:30:89 In response to motion of 78:029 from W Marshall Trescheduling of prehearing conference, ordered that 8 Gadler will represent Marshall & Mepleton Intervenors at the
- will represent Marshall & Mepleton Intervenore at the special prehearing conference.

  8MITH.I.W. Atomic Bafety and Licensing Board Panel. 78/16 03353:330.
- --781130192 Request by intervenor H Marehall for continuence prehearing conference on 781110 due to his unavailability that day Request for resched made on his dwn behalf & on behalf of Mepleton intervenors.

  MARSHALL.N.H. Affiliation Unknown. 78/10/29. 1p. 033
- 78[1150080 "Brist of Consumers Pur Co in Support of its Posi WH Mershall's Petition to Intervene is Barred by Ras Judicata Urgss petition be denied Cart of Svc & supporting matl enclosed. MILLER.M I., QIBBS.M.E. Consumers Power Co 78/10/31. 9
- 781:2:0040 Submits addit contentions in support of 780906 con objecting to subj facil re Illegal charges & spills, geological conditions & storage of epent fuel rode. Cartificate of Svc ancl.
- 7811150039 Requests that CPC file brief supporting util post NH Marshall patition to intervene be barred by 781031 res judicata Cartificate of Svc encl.
  MARBHALL, H. H. Mapleton Intervenors. 78/11/02. ip. 9411

MARGHALL, W. H. Mapleton Intervenore, 78/10/31, 5pp. 941

Judiceta Certificate of Svc encl.

MARBHALL, M. M. Mepleton Intervenore. 78/11/02. ip. 9411

7811210036 Berves SJ Gadler w/"Brief of Consumers Pur Co in its position that Marshell's petition to intervene is barr

Q1888, M E. 1sham, Lincoln & Beals. 78/11/02. ip. 03557

7BI1210493 Contention of intervenor M Sinclair, Asserts that is responsible for assuring compliance w/Atomic Energy Act of 1934, Also claims that NRC has not implemented an assertive Alsort insert property of Says and

res jucideta."

94382: 025.

- of 1934. Also claims that NRC has not implemented an affective direct inspec prog. Cert of Syc entl. SINCLAIR, M.P. Affiliation Unknown. 78/11/03. 40pp. 031
- 7811150252 Only issue remaining for ABLB to consider re-sub, charge re-CPC's conduct. Bd will also address issue of seviron effects of redon. Bd will not consider CPC's allegt history of QA-OC violations k last of finencial quals. CHIUK, S. J. Office of the Secretary of the Commission. 787pp. 94273:086.
- 7811220215 Supple 781018 notice of hearing that special preconference per 10CFR2.751(a) would begin on 781115. Meeting will not be held on 781214 in Midland.MI.
  8MITH-1.W. Atomic Safety and Licensing Board Panel. 787.74071:282.
- 7811300369 Memorandum & order postponing special prehearing previously scheduled for 781115, until 781214 at same hr & locetion.
  SMITH 1. W. Atomic Befety and Licensing Board Panel. 78/94136:281.
- 7812060126 Requeste change of location for 781214-18 prehea conference from Midland.MI to Chicago.IL. CHERRY.M.M. Cherry. H. M. Cherry. Flynn & Kanter. 78/11
- --7812050172 Requests comments on NRC 781105 memorandum & o consideration of operating & const matters. CHERRY, M. M. Cherry, H. M. /Cherry, Flynn & Kanter. 78/94382:027.
- 7812080005 Forwards 780929 iOCFR50.05(e)rept from CPC & Kep mano to Thornburg re proposed contentions concerning settlement of diesel generator bldg foundations pending before the ABLB. he ABLB.

  CLMSTEAD.H.J. Office of the Executive Legal Director. 7 12pp. 94103:315.

### OOKETED HEIMS

- 7811300356 Objects to M Cherry 781113 request to change location of licensing hearings to Chicago Poor health would prevent attendance if hearing was not held in Midland, NI. Certificate of Ovc enc1 MARBHALL, H. H. Affiliation Unknown. 78/11/17. 1p. 94116:238.
- 7812050257 Informs that itr transmitting radon record should have been atamped "Served 78117." Docksting & Bervices Branch. 78/11/21. 1p. 94202.132
- 7812010257 Memorandum & order confirming date of special prehearing conference. Location of future sessions will be discussed at conference Board will begin 70:1214 by dealing w/problems involving lewyers Limited appearance statements deferred. BHITH, I. N. Atomic Bafaty and Licensing Board Panel. 78/11/22. 2pp. 94417:123.
- 7812140087 Brief submitted by CPC in response to ASLB Order of 781113 CPC asserts that 27 of patitioner to intervens M Binclair's suppl contentions are inadmissible & that patition to intervene of M Marshail be denied. Cart of 8vc encl. MillER.M. I. . 01889.M. E. Isham, Lincoln & Beals, 78/11/28. 49pp. 94128: 242.
- 78:2140362 Answer of CPC to Motion by M Cherry representing all intervenors other than Dow Chem Co. for joint consideration of oper & constructors CPC asserts that consolidation is neither req nor justified. Cert of Syc enci.
  MILLER.M. i., 01888.M.E. Isham, Lincoin & Deeie, 78/11/28. 12pp. 03557: 251.
- 7812260065 Forwards "Participation in the instent Proc." W/Cert of Svc. TAYLDR.g.T. Michigan, State of. 78/11/28, 1p. 94027:133.
- --7812260067 "Participation of the State of MI in the Instant Proc." Responds to Bd Order 781117 requiring MI to advise if it intends to participate. Scope & aub; matter of intended participation are outlined. TAYLOR, 9. T. Michigan, State of, 78/11/28, 2pp. 94027; 134,
- 7817260298 NRC Staff's Response to consentions of petitioners to intervens Hapleton Intervenors. Stoff asserts that contentions #1.3.4.6 & 7 are vagus or w/out basis in fect. Contentions #2 & 5 may be proper if rephrased #/Cert of Svc. OLMSTEAD.W. J. Office of the Executive Legal Director. 78/11/28 5pp. 94160:052.
- --7812260303 NRC Staff's response to Contentions of petitoner to intervens M Sinciair. Staff objects to contentions#1-21,23, 26,35,39-41,45,46,444,45a,47a-74,No objection is made to contentions#22,24,27-34,42-44,47,48 & 46e. DUMSTEAD, W. J. DF: 10pp. 94160: 055. Office of the Executive Legel Director 78/11/28.
- 7812140223 Responds to 781120 request for advence notification of meetings between NRC & consumers is subjects. Respondent has already been sent such notices, & recent Fed Register Notice affirms open meeting policy which holds for subjects. OLMSTEAD, H. J. Office of the Executive Lagel Director. 78/11/29. ip. 94204:340.
- 7812180383 Corrects factual error in 781128 Consumers Pur Co brief.

  8 beam rate may or may not be subj to jurisdiction of M1 Pub Byc Comm. 91888.M.E. Isham, Lincoln & Beale, 79/11/29, 1p. 94357:319.
- 7812280325 Forwards documents re sattlement of Olesel Generator Bidg foundations at subj facil.

  OLMBTEAD, M. J. Office of the Executive Lagel Director. 78/12/07. 14pp. 94082: 141.
- --7812280332 Forwards 781120 itr from M Charry w/poseible allegations against resident NRC inspector at subj fecil. DAVIB.J.G. Office of Inspection & Enforcement, Office of the Director. 78/12/05. ip. 94082:360.
- --7812280334 Forwards 1tr from M Cherry re tub; constr proj. Response is being prepared. KEPPLER, J. Q. R Region 3, Chicago, Office of the Director. 78/11/24. 1p. 03555: 152.
- --7812280340 Expresses concern that NRC is attempting to minimize problem of diesel generator bldg settlement at subj facil. Buggests NRC resident inspector may be coopted by util. Requests info a permission to ettend next inspect.

  CHERRY, M. M. Cherry, M. M. /Cherry, Flynn & Kenter. 78/11/20. 3pp. Q3555: 157.

- --7812280343 Transfers lead responsibility for problem of signific settlement of diesel generator bldg to NRR. W/encl repts on deficiency. VABSALLO.D.B. Assistant Director for Light Water Reactors 78/11/17. 11pp. 94082.204.
- 7812270132 NRC Staff's resonae to NRC Mero & Order of 781106 to t issue. Asserts that ABLB has no need for add1 written evidence re radon question Notice of appearance for BM Bordsnike & Cert of Byc snc1.
  BDBRENICK, B. M. Office of the Executive Legal Director. 78/12/0
- 10pp. 94161:086.
- 7812280350 Memo of CPC re environ effects of radon per NRC Order o 781106. Asserts that Parkins decision is supported by record of that proc & that radon emissions do not critically effect cost-benefit balance Wencl documentation & Cert of Svc. MILLER.M. I., 01889, M. E. Isham, Lincoln & Beate 78/12/08, 19p 94082: 217

# H. General correspondence

- 7811010014 Requests OL documents: 50-329 & 30-33 to be sent to N Hatlis P.O. Bor 103, 3609 Shoreline Dr., Nararve, Mn 53392, also to place Hatlis pn circulatory list. MARSHALL, W. H. Hepleton Intervenors. 78/10/18 ip. 94290 239.
- 7812280198 Responds to 781120 ltr. Forwards info re-resident inspect being co-opted by Midland personnel NRC has initiated an investigetion into settlement of diesel bldg at fecil. KEPPLER.J. O. Region 3. Chicago. Office of the Olysctor. KEPPLER, J. Q. Regi 125pp. 94373:090. 78/12/
- K. Utility Final Bafsty Analysis Report (FBAR) & amends
- 7810230192 Forwards Amend 51 to CP & OL applications.consisting of Revision 14 to FSAR. HOWELL-S.H. Consumers Power Co. 78/10/17. 1p.
- --7810230196 Revision 14 to FBAR, Vols 1&2.
  \* Consumers Power Co. 78/10/17. 1153pp.
- 7810270168 Forwards Cert of Byc for copies of Amend#51(Rev 14 to F Safety Analysis Rept) to appl for constr permits & oper lics.
  BACON.J.L. Consumers Power Co. 78/10/24. Rpp. 94056:R66
- 7812010251 Forwards Amend 54 to CP & OL application.containing Rev 15 to FBAR. HOWELL, S. H. Consumers Power Co. 78/11/27, 18pp. 94390: 159.
- --7812010252 Ray 15 to the FBAR vols 1 & 2:responses to requests f informs re orifice rod assemblies & high density funt racks
- 7812120154 Forwards edvance copy of util response to NRC Request 4 "GA During Operations Phase," FSAR Subsection 17.2 re personnel training. staff changes, cleaning of fluid sys & GA audit.Response to be submitted w/Revision io of FBAR. HOMELL.B.M. Consumers Power Co. 78/12/08. 1ipp. 94276:286

# M. Antitrust correspondence

- 7812180246 Intervenue & applicant CPC rept that prospect for settlement of issues contested in proceedings is subj facils is excellent An understanding has been reached in all but 2 areas. Cart of Byd encl. ROBB.W.W. wATBON.K.B. Wald, Harkrader & Ross. JABLON.R.A Sp & McDiermid. 78/12/06. App. 94059:003
- G. Inspection reports, IE Builetins & correspondence
- 7810270024 Forwards I & E Initial Rept on Response to Dulietin 77-03/05A re use of Eiec Connectors. Appropriate Eds should be notified where there is a question re use of connectors in safety sys. Hemo dtd 780209 also enci.

  TEDEBCO.R.L. Assistant Director for Plant Bystans 78/02/08.
- --7810270246 Forwards "Status of Responses from Licensees of Plant Construc to Bulletins 77-05 & 05A". MCBELEY, N.C. Division of Reactor Construction Inspection. 78/02/07. 3pp.
- 7811130340 Forwards IE Inspec Repts#50-329/78-09 & #50-330/78-09 780829-3) & Notice of Violation.

- --7811130343 Notice of Violation from inspec on 780829-31 # Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/09/21. 1p. 94007:311.
- --7811130350 IE Inapec Repts#30-329/78-09 & #50-330/78-09 on 780829-31 during which I item of noncompliance was noted: failure to follow procedure in welding root pass.
  LEF,E.W., DANIELBON.O.H. Region 3. Chicago: Office of the Director. 78/09/21. 3pp. 94007:312.
- 7810160197 "Preservice & First 10-Yr Interval lnep Plan for NDE & Sus Pressure Testing at CPC Hidland Units 1 & 2 " Prepared For util. SLAGER.H.W., BIRKLE.A. J., MAYNARD.C. J Sechtel Corp. 78/09/27. 2470s.
- 7810160196 Forwards "Preservice & First 10-Yr Interval Insp Plen For NDE & Bys Preserve Teating et CPG Midland Units 1 & 2." Dete reported in Section 3 of plan is prallminary & subj to change as const progresses. Plan basis of 781025 meeting MDMELLS.H. Consumers Power Co. 78/10/05. 2pp. 94007:150.
- 7811140048 Forwards 1E Inspec Repts#50-329/78-10 & #50-330/78-10 on 780913-15 during which no items of noncompliance were noted. HEISHMAN,R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/10. 2pp. 94420.343.
- --78i1i40004 IE Inspec RepteM50-329/78-i0 & #50-330/78-i0 on 7809i3-i5 during which no items of noncompliance were noted. Major areas inspected included: installetion of sefety-related hengars & restraints.

  YIN, I. T. Region 3. Chicago, Office of the Director.

  ONNIELBON, D. H. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/10/10. App. 94420:245.
- 78:02/00211 Act receipt of 78/0918 itr informing NRC of steps taken to correct item of noncompliance identified in IE Insp Repts 50-329/78-07 t 50-330/78-07. Addl info is requested. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 78/10/11. 2pp. 94367:064.
- 7811070336 Responds to 780921 NRC ltr re noncompliance noted in Inspec Repta#50-329/78-09 & 50-330/78-09. Corrective actions:rev of Bechtel Walding Procedure Spec & Bechtel Project Quality Control Instruction#7220/H-1.00, HOMBLL-8 M. Consumers Power Co., 78/10/23. 3pp. 94043:080,
- 7812140021 Forwards IE Inspec ReptsW50-329/78-11 & 50-330/78-11 on 780926-28 during which no items of noncompliance were noted. HEISHMAN.R.F. Region 3, Chicago, Office of the Director. 78/10/27. 2pp. 94119:347.
- --7812140028 IE Inspec Repts#50-329/78-11 & #50-330/78-11 on 780926-28 during which no Items of noncompliance were noted Major state inspected incl: Sebcock & Hilcox Constr Co nondestructive examinetion prog procedures & personnel cert. HARD. H. D., DANIELBON, D. H. Region 3. Chicago, Office of the Director. 78/10/26. 7pp.
- 7811280124 Responds to 780504 NRC ltr re violations noted in Inspec Repte850-329778-03 & #50-330778-03. Corrective actions:weld epst rev.weld voltage range monitoring procedure prepared disagrase on 15% voltage range limitation. HOWELL, S. H., Consumers Power Co. 78/10/31. 2pp. 94013:023.
- 7812060064 Forwards 1E Inspec Repts#50-329/78-13 & #50-330/78-13 on 780724-28: 31,0801-31,0901-08 & Notice of Violation. HEID-MAN.R.F. Region 30, Chirago, Resector Construction & Engineering Support Branch. 78/11/03. 2pp. 94232:254.
- --7812060067 Natice of Violation from ineges on 780724-0928.

  \* Region 3. Chicago, Reactor Construction & Engineering Support Stench, 78/11/03. 29p. 94232:256.
- --7812040070 IE Inspec Repts#50-339/78-13 t #50-330/78-13 on 780724-0908 during which 2 items of noncompliance were noted:welds with unequal outside diameters were accepted & Safety Releted Control Rod Drive Primary Breakers were not well protected. CODK.R.J., HAYNGS.D.H., Region 3. Chicago, Office of the Director. 78/11/03. App. 94232:238.
- 78:1130:057 Forwards IE Circular 78-18.
  KEPPLER, J. O. Region 3. Chicago, Défice of the Director. 78/11/06.
  1p. 94:12:192.
- 7811200041 Ack receipt of 781020 ltr informing NRC of steps taken to correct violations noted during inspec. HEIS-MAN,R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/08. jp. 44215:322.

- 7812140130 Forwards IE Inspec Repts#50-329/78-14 & 50-330/78-14 on 780910-29 during which no items of noncompliance were noted. HEIBMAN.R.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/08. 2pp. 94128:334.
- --7812140139 IE Inspec ReptsW50~329/78-14 & 30-330/78-14 on 780910-29 during which no items of noncomplience were noted. Major areas inspected incl:examination of gen site condition & steem generator & reactor vessel hold down bolting.
  CDDW.R.J., HAYEB.D.W. Region 3. Chicage, Reactor Construction & Engineering Support Brench. 78/11/06. 4pp. 94128:336.
- 7811220006 Ack receipt of 781023 itr informing NRC of steps taken to correct violations noted in 780921 itr. Corrective actions will be reviewed during a future inspec.

  HEISHMAN,R.F. Region 3. Chicago. Reactor Construction & Engineering Bupport Branch. 78/11/15. ip. 94308:246.
- 7812190168 Forwards IE Inagec Repte#50-329/78-12.50-330/78-12 on 781024-27 during which no items of noncompliance were noted.

  HEIS-MAN.R.F. Region 3. Chicago: Reactor Construction & Engineering Bupport Brench. 78/11/17. 2pp. 94340:162.
- --7812190160 IE Inspec RepteM50-329/78-12 & 50-330/78-12 on 781024-27 during which no ltems of noncomplience were noted. Major erass inspected incl: 100FR50. 55(s) rept concerning settlement of dissel generator foundation & bldg. GALLAGHER, E. J., 8PE6BARD, R. L. Repion 3, Chicego, Office of the Director. 78/11/14. https: 94340:149.
- 7812050102 Ack receipt of 781031 itr informing NRC of eteps taken to correct violetions noted in 780504 & 780913 itrs. Re issue(b) NRC requests that sampling measurement eye provide assurance that all welding mechanes are covered by amperage & voltage. HEISHMAN.R.F. Region 9, Chicago, Resctor Construction & Engineering Support Branch. 78/11/22. 1p. 94335:287.
- 7812050333 Forwards IE Bulletin978-12A, suppl to IE Bulletin 78-12. W/enc1 ANO: 7811300055. KEPPLER, J. Q. Region 3, Chicego, Office of the Director. 78/11/24. pp. 74409:001.
- 7812080249 Informs NRC of ongoing preparation of response to IE Bulletin 78-12, "A Typical Waid Matl in Reactor Pressure Vessel Walds" for subj feci) & states that written response wiil be forwarded by 781215. HOWELLES.H. Consumers Power Co. 78/11/28. 1p. 94137:191.
- 7812140080 Act receipt of IE Sulletin878-12A re etypical weld metl in pressure vessels. Response will be consistent w/extended sched of IE Sulletin878-12A.

  HOWELLS.H. Consumers Power Co. 78/12/05. ip. 94128:226.
- 7812290015 Forwards IE Bulistin 78-14.

  KEPPLER, J. C. Region 3, Chicago, Office of the Director, 78/12/19.

  1p. 04911:001.
- R. Periodic operating reports & related correspondence
- 7810270142 Forwards Monthly Nonconformance rept for Bept 1978. HOWELL.B. H. Consumers Fower Co. 78/10/25. 1p. 94060:030.
- 9. Reportable occurrences, LERO & related correspondence
- 7810180095 Interim deficiency rept re reactor bidg spray piping supports. Bechts1 Associates Prof Corp rept of status of corrective action & investigation encl. Further rept to be submitted by 781117.

  HOWELL-B.H. Consumers Power Co. 78/10/13. 4pp. 94401:028.
- 7811010401 Ack receipt of 780929 finel deficiency rept re conteinment bldg personnel airlocks. Review will be completed during future ineps.
  HEIBHMAN, R. F. Region 3, Chicago, Reactor Construction & Engineering Support Brench. 78/10/24. ip. 94388:323.
- 7811010115 Ack receipt of 780929 interim rept re small breet analysis. Final rept will be reviewed upon receipt. HEIBMAN, R. F. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/10/25. ip. 44375:355.
- 7811070222 Act receipt of 781013 interim mept to reactor bldg apray alping supports.
  MEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Buppart Branch. 78/10/30. 1p. 94039:141.

- 7811170212 Interim deficiency rept re settlement of diesel generator foundations & bldg. Provides status of actions to be taken.
  Review meeting tentatively planned for last two wks in Nov.
  Further rept to be submitted by 781229.
  MDHELLS.H. Consumers Power Co. 78/11/07. 7pp 94136:114.
- 78iii70222 Interim deficiency rept re reactor bldg apray piping supporte. Provides status of analysis being conducted to resolve question of adequacy of supporte per ABME Section III Code allowable stress requirements. Final rept by 78i219, HOWELL, S. H. Consumers Power Co. 78/11/10. 4pp. 74i36. 2i3.
- 78:1220176 Interim deficiency rept re Class IE station battery.Exide Industrial Battery Div ested to provide additional info describing condition-failure mode & analysis of why condition was reportable.Related correspondence MOMELL.B.H. Consumers Power Co. 78/11/17. 2pp. 94623:267.
- --7811220178 Reports that add1 isoletion bar must be edded to Class IE battery recks sent to aubj facile in order to isolete horizontal momentum during setumic events. Design its being worked out & will be reedy in 60 days for retrofit. MCMANUS.C.K. ESB. Inc. 78/10/11. ip. 94623:269.
- 78i1290293 Ack receipt of 78iii7 interim rept pursuant to iOCFR30, 35(a) re settlement of dissei generator foundations & blog. HEIB-HWAN, R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/ii/22. 1p. 94239:246.
- 7812010155 Ack receipt of 781110 interim rept pursuant to iOCFR50.55(e) re reactor building spray piping supports.
  HEIBMAN.R.F. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/22, ip. 94418;125.
- 7812040287 Ack receipt of 781ii0 interim mept me reactor bldg spray piping supports.
  HEISHMAN,R.F. Region 3. Chicago. Office of the Director. 78/11/22.
  10.
- 7812140366 Ack receipt of 781117 interim deficiency rept re class IE station bettery racks. HEISPMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/11/22. 1p. 03557:288.
- 7812040218 Interim deficiency rept re component quelification test documentation re-review Rept is being generated by Bechtel documenting statue of re-review & results on individual meti requisition basis for all G-components requiring testing.

  HONELLIB.H. Consumers Power Co. 78/11/28. 2pp. 94445:359.
- 7812270184 Interim deficiency rept re reactor bldg spare piping aupports. Bechtel Assaciates Prof Corp rept on etatus of analysis being conducted to resolve question of adequacy of reactor bldg egray piping supports per ABME requirements. HOWELL.8.H. Consumers Power Co. 78/12/15. 3pp. 94017:361.
- 7812270254 Forwards nonconformance rapt for Nov 1978. (Encl 80081806851 HOWELL-8. H. Consumers Power Co. 78/12/20. 2pp. 94016:082.
- 7812290146 Interim deficiency rept re settlement of diesel generator foundations & bldg. Use of preload to densify existing fill matt in place selected as corrective action. Bectal rept detailing tasks to be sent by Jan. Related correspondence.
  HOWELLAS. H. Consumers Power Co. 78/12/21. 2pp. 94190:281.
- DOCKET 50-330 HIDLAND PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7811090143 Responds to 781011 request for add1 info re aquetic ecology; hydrology, water use & quality, & traffic count data w/Agreement between Wolverine Pur Co & CPC, Discharge Parmit Appl by CPC, & other encl.
  HDMELL, B. H. Consumers Power Co. 78/11/03. 101pp. 94042: 357.
- --7811090149 "Btudy of a Non-Buoyant Plume: Presence of a Buoyant Plume in an Undirectional Ambient Flow." Hydrothermal model tests were conducted to determine estimated design for cooling pond blowdown discharge.
  ROBERGE, J. C., NYQUIST, R. Q. Bechtel Power Corp. (eubs. of Bechtel Corp.). 78709/30. 98pp.
- --7811090186 "Copling Pond Oper Study", Preliminary Rept. Facil cooling pond oper was simulated by use of makeup & blowdown sys to control pond TDB concentrations.
  LIOU.C.P., APADAKIS.C.N. Bechtel Power Corp. (subs. of Bechtel Corp.). 78/09/30. 55pp. 94043:015.

- --78:1090159 Tabular date on traffic counts for county roads in vicin: of proposed site.
  RAD.J.H. Michigan, State of. 78/10/13. 34pp.
- 7812120068 Responds to 781011 NRC ltr.eddl info re Aquetic Ecology & Hydrology, Nater Use & Guelity & Archaeology, Forwards rev of Btate Discharge Permit Appl.rev of Appl for Permit to Discharge Nater & Archaeological Rept. HONELLS H. Consumers Power Co. 78/12/05. 283pp. 94278:104.
- 7812120104 Forwards Amend 55 to application for CP & OL & Revision 4 to Environ Rept.OL stage.
  HDMELL.B.H. Consumers Power Co. 78/12/07. ip. 94275:029.
- --7812120111 Application for CP & OL, H/Revision 4 of Environ Rept. HOMELL.S. H Consumers Power Co. 78/12/07. 194pp. 94275:030
- 7810310061 Forwards preliminary chart on results of land use survey completed last year re building & housing trends in Midland County 1969-1977.

   Midland County, MI. 78/04/10 3pp. 94093:179.
- 7810140006 Notice of time & agenda change for meeting on 781025 to discuss augmented inevolinepec & testing of pumps & values. HOOD, D. Light Water Reactore Branch 4. 78/09/25. 5pp. 94329:097
- 7810120072 Forwards 8kW rept "Analysis of Bearing Failure in LMbG 9000 HP Vertical Pump Motor Resulting From Dil Cooler Failure" prepared for CPC. Rept available in CF only. ODWELL-8. Consumers Power Co. 78/10/05. 1p. 94470:345.
- --7810120077 "Analysis of Beering Failure in LMt0 9000MP Vertical Pump Motor Resulting from Oil Cooler Failure"prepared by 8tW for CPC. & forwarded to NRC. Determines Kingebury thrust bearing to be critical component in event of oil cooler failure. • Bebcock & Wilcox Co. 77/10/10. 107pp.
- 7810130231 Forwards erchaeological site survey for Midland County.Ni to be added to minutes of Baglnew meeting of 780906.

  8RUNETT:P. V. Beginsw Archaeological Commission. 78/10/05. ilpp.
- 7810200128 Requests add1 info as result of sits visit to subj fecil is order to review environ factors. Response should be submitted by 781025. Response should be suppl to Environ Rept.

  REGAM. M. M. Environmental Projects Branch 2. 78/10/11. 9pp. 94366-310
- 7810230375 Baliaves that there is a potential problem w/Class iE battery recks supplied to subj facil. Add1 isolation bar for asismic protec will be available for retrofit w/in 60 days. MCNANUS.C.K. ESB. Inc. 78/10/ii. 1p. 9427i:184.
- 7610190066 Forwards duplicate of original 780629 ltr containing affidavit re proprietary response to request for eddl info. ttr not previously received. HONELL-8. H. Consumers Power Go. 78/10/12. ip.
- 78:1010308 CPC request to withhold as proprietary section 4.C of theilgen Agreement w/Dow of 78062: per 10CFR2790 is granted. LYNCH.O.D. Environmental Projects Branch 2. 78/10/12. 20p. 94397: 160.
- 7810240013 Forwards summary dtd 780327: "Bummary of March 21-22,1978 meeting & site visit", for the info of the NRC. TOURTELLOTTE, J Office of the Executive Legal Director. 78/10/13.
- --7810240017 Summary of 780321 & 22 meeting w/util in Midlend.Ml refeatility const completion echedule. CHOCKER, L. P. Division of Project Management. 78/03/27. 13pp.
- 7810240213 Requeste eddl info for FSAR review Wiencl questionneire. VARGA, S. A. Light Water Reactors Branch 4. 78/10/13. 80pp.
- 7810250199 Repts on eite vielt to subj facil during week of 780905. Encloses summarized schedule of week's activities & principal personnel contacted. LYNCH.O.D. Environmental Projects Branch 2. 78/10/13. 15pp. 94392:205.
- 7810250099 Forwards entl praliminary rept "Prelimiary Pump & Valve Inservice Testing Program for CPC Midlend Plants Units 1 & 2." Bubaisted in response to NRC question ra FBAR Plantin parts to form besis of 781025 meeting w/NRC. HOMELLS. H. Consumers Power Co. 78/10/18. 2pp.

781023013: Requests add1 info re estimated ONP annual growth & ON vehicle produc growth rates used to forecast ON elect sales.

REGNER, M. H. Environmental Projects Branch 2. 78/10/18. 3pp.

- 7811080015 Responds to 781011 NRC request for add1 info re 2 items of noncompliance noted in 780817 NRC ltr. Encl 781020 ltr from Sachtel to CPC discusses document control stamping & removel of void drawings from files. HOWELL-8 H Consumers Power Co. 78/10/20 3pp. 94398: 035.
- 7810270149 Response to 781004 FQIA request for documents re completion dates for subj facil & detailed plant-specific analysis. Formande requested documents. Wencil list of documents. ELTON, J. H. Division of Rules and Records. 78/10/23. 2PP. 94056.308
- 7810270201 FOIA request for documents is setimated constr completion deten for sub; facil & "datailed plant-spoific analysis"of those units. DOW:W Public Interest Research Group. 78/10/04 1p. 94056:310.
- 7810310293 Approves request for withholding section 4.C of the Gen Agreement between Dow Chem & util rs price of energy sold to util under agreement Price & cost of producing energy is held to be confidential info by NRC.
  REOMN H. Environmental Projects Branch 2, 78/10/23. 3pp.
- 7811070332 Summary of 780913 Meeting et Betheede.MD on info requested by Auxiliary Sye Branch re main eteem & process steem piping-resctor coolent pump cooling & duel cash drop. HOOLD H Light Meter Reactors Brench 4 78/10/23. 4pp. 94038:358.
- 78ill30021 Summary of 780914 meeting w/util. Sechtel Corp & B&W in Setheeds ND re separation criteria & administrative proceduras for installation of Class IE belance of plant squipment & circuite identified in PSAR Amend 32.

  HOOD. D. Light Water Resctore Branch 4. 78/10/20. 4pp. 94079: 313.
- 7810310364 Concludes that esperation criteria for NBBB & Class IE halance-of-plant squipment to non-Class IE circuits are per IEEE 8td 384-1974 & Reg Ouids 1.75 & acceptable. VAROM.8 A. Light Mater Resctors Srench 4. 78/10/24. 3pp. 94093: 105
- 7811010092 Act receipt of 780929 interim rept re settlement of Diesel Generator Found & Bidg. Final rapt will be reviewed upon receipt. HEISTAN.R.F. HEIB<del>i</del>Wh.R.F. Region 3. Chicago. Resctor Construction & Engineering Support Brench. 78/10/24 ip. 94381:315.
- 78:10:0008 Responde to 780926 itr requesting NRC decision re-review & potential release of section 4.C of contract between Dow Chee Co & Consumer Par Co.NRC sinds section 4.C each confidential & proprietary. Request is denied. FELTON.J.M. Division of Rules and Records. 78/10/26. ip. 42940 pag. 94290. 240.
- --7811010010 FDIA request for info re correspondence involved in contract between Dow Chem & Consumer Par Co. FREDKIN.8 Public Interest Research Group. 78/09/26. ip. 94290: 241.
- 94290, 242
- 7811130107 Notice of 781106 meeting w/subj util on staff requests for addl info re extension of constr completion dates for HOOD, D. Light Water Reactors Branch 4. 78/10/30, 2pg. 94113:307.
- --- 7811150109 Requests soul info re constr parall extension as requested YAROA, 8. A. 94113: 309. Light Hetsr Resctore Branch 4. 78/10/27. 2pp.
- 78:1240:03 Responds to 78:025 ltr. City has 41 police officers. 16 pstrol cars & no impect on crims rate from constr of subs facil.

  HARCEK, D. B. Midlend County, MI. 78/10/30. 1p. 94438:302.

- 7811240188 Responds to 781025 itr Park acreage in City or approx 2700 acres & total park space accessed standards. MOFFATT, D. H Migland City, MI. 78/10/31. lp.
- 78:1140059 Forwards request for add1 info re main steam 1 accident. Requires that power distribution distortions c by stuck rod be considered during both initial portion later return-to-subcritical-power portion of enalyses. VARGA-B.A. Light Water Reactors Branch 4. 78/11/01. 94425:001.
- 7811240166 Confirms 780912 info. 41 law suforcement office: cars involved. Crime rate not affected by constr of subj MCNUTT, J. R. Midland County, MI. 78/11/01. 1p. 94458
- 78i1240186 Confirms 780912 telephone conversation. City of trestment fecile will be expanded to treat total of 48 million gallons/day & be edequate until 1990. EHING.M. C. Hidland City. MI. 78/11/06. ip.
- 78iii30i43 Notifies applient of 78ii28 NRC-aponsored teal Radiological Efficient Tech Boscs for Nuc Pur Plants.Enc y/Seminer Info Sheet(to be completed b returned by 78ii Proposed Agenda. KEPPLER, J. O. Region 3: Chicago, Office of the Director. 6pp. 94087:333.
- 7Bi1240184 Responds to 7Bi025 ltr. Current echopi snrollmer Bidgs in echool district can accommodate 2500 new studer
- BAXER, R. Midlend City, MI. 78/11/07. 1p. 94458:301.
- 78ii200159 Forwards for review by Baismic Qual Review Tasmiletings of sncl portions of BGRT info & schedule for providing currently uneveilable dats & completed BGRT fc HOMELLS.H. Consumers Power Co. 78/11/13. 84p. 0278
- 7811200121 Forwards Crane Packing Co Suitatin 3472: "Seal F Test for Nuc Per Plant Sefety Injection Sys", to support util's secumptions on HPI pump seal leakage as discussed 780920 meeting w/NRC re EBF filtration issue. HOHELL, B. H. Consumers Power Co. 78/11/14. B3pp. 9426
- 7811240190 Responds to 781025 request for confirmation of date re Midland Hosp Assoc(personnel count, Bof admission Confirms info on file is provided by hosp. Occupancy rate RATIBUN, K. J. Michigan, State of. 78/11/14. 2pp. 9445
- 7811280127 Summary of 781106 meeting W/CPC in Setheeda, MD of conet completion dates. Draft response to 781027 quest HDOD.D. Light Water Reectors Branch 4. 78/11/14. ISpp
- 7811280130 Notification of 781203-04 meetings w/CPC in Mid asttlement of diseal generator bldg & other atructures. Agenda encl.
- HOOD D. Light Water Reactore Branch 4. 78/11/14. 4pp.
- 7811280131 Bummary of 780820 meeting on steam line break m cold shutdown position & safeguarde pump room leakags. H/ list of strendses & applicant's responses to NRC question HOOD. D. Light Water Reactors Branch 4. 78/11/14. 27pp
- 7811270087 Forwards request for add1 info for review of ap lic for subj facil. Response req by 781208:3 originals & copies:41 are to be forwarded & 109 to be retained. REGNN.H.H. Environmental Projects Branch 2. 78/11/16. 94260: 340.
- 781128009: Forwards Rev#i"Draft Radiological Effluent Tech PHR's"(NUREG-0472) & "Preparation of Radiological Effica Tech Bpsc for Nuc Pur Plants"(NUREG-0132). M/encl 7811270173 & 7811270180. VABBALLO, D. B. Assistant Director for Light Water Reacto 78/11/16. 6pp. 02726:322.
- 7811300007 Forwards order extending completion on dates for 791201 to 821001 & 811001 for Units I & 2, respectively. VAROA.8.A. Light Weser Reactors Branch 4. 78/11/17. 3 94009:348.



- \*\*\* 781 1300011 Order extending const completion dates from 781201 & 791201 to 821001 & 811001 for Units 1 & 2 respectively. Evaluation of request for extension of CPPR-B1 & CPPR-B2 entl. BCVD.R.B. Division of Project Management. 78/11/17. 7pp. 94069:344.
- --7811300019 States environ impact statement for extension of construent not warrented. All necessary info described in Final Environ Statement-Constr Permit Stage.

  REDAN. H H Environmental Projects Branch 2. 78/11/17. 2pp. 94077:023.
- --7211300023 E1A concluding no E18 need be prepared for proposed action.

  9 Division of Site Bafety & Environmental Analysis. 78/11/17.
  2pp. 94077:025
- 78 12050094 Safety evaluation supporting extension of Const Permits CPPR-81 & CPPR-82 H00D. D. VARCA.S.A. Light Weter Reactors Dranch 4. 78/11/17. 3pp.
- --7812050097 Environ Impact Appraisal concluding that extension of subj facil Conett Permits CPPR-B1 & CPPR-B2 will cause no major add1 environ impact.M/Negetive Declaration. • Division of Site Bafety & Environmental Analysis. 78/11/17. 200.
- 78:1270147 Forwards Amend 33 to CP & DL application.containing update to general info portion.
  MOMELLO H. Consumers Power Co. 78/i1/21. ip. 94271:343.
- --78:1270151 Amond 53 to CP & DL application re basis for completion date extension. Unit 1 extension from 77:201-78:201 to 8:1001-82:001 & Unit 2 extension from 78:201-79:201 to 80:001-81:001 Delay partially due to finances.

   Consumers Power Co. 78/11/21. 16pp. 9427:344.
- 78:11270152 Forwards add1 copies of CPC responses to Suppi Requests for Add1 Info:Part2.originally transmitted to NRC by itr of 78:102.W/enci ANO:78:11160108.

  HGWELL-8 H. Consumers Pawer Co. 78/11/21. 1p. 94232:355.
- 78 12070280 Notification of 781211 meeting w/CPC.Bechtal & 86W in Bethesda.MD to appeal NRC position that facilities be capable of obtaining cold shutdown conditions using only safety grade equipment.

  MODD.D. Light Water Reactors Brench 4. 78/11/27. 4pp. 94080:054.
- 7B 12050142 Forwards Cert of Svc for App1 for Constr Permit & Oper Lic-Asende53. BACCN-J.L. Consumers Power Co. 78/11/29. 2pp. 94334:350.
- 78:12050213 Forwards Certificate of Svc for Amend 54 to CP & DL application: containing Revision 15 to FBAR, BACON.J.L. Consumers Power Co. 78/11/30. 1p. 94318:345.
- 7812120002 Forwards supplemental second round question from Reactor Physics Section re criticality of proposed high density storage eys. (Enci B008130549)
  TEDEBCO.R.L. Division of Systems Befety. 78/12/01. 1p. 94274:295.
- 7B12280118 Emphasizes importance of submitting accurate & complete info to NRC by itcensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. O. Dffice of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp.
- 78:2180391 Responds to request for withholding info submitted on 780609 & 0629 (ref 10CFR2. 790). Forwards tables listing criteria used by BtH to determine whether submitted maths are proprietary & proprietary claim of math submitted. VAROA. B. A. Light Water Reactors Branch 4. 78/12/07. 7pp. 474357:266.
- 7812260188 Discusses questions raised during visit re discal generator estitisment problem.
  COOMS. T.C. Consumers Pawer Co., 78/12/07. 2pp. 94139:156.
- 7812210294 Notification of 781220 meeting w/CPC & 8&W in Bethesda.MD to discuss single failure proof crane for spent fuel.details of full-scale modeling tests planned for conteinment sump & steam line break analysis w/stuck control rod estembly.

  MOOD.D. Light Water Reactors Branch 4, 78/12/11, 4pp. 94147:320.
- C. Utility Environmental Report (ER), amends & correspondence
- 7811170294 Forwards Amend 82 to Environ Rept re corrections of arrors & requests for addl into re original Amend.
  HOWELLE, M. Consumers Fower Co. 78/11/10. ip. 94045:274.

- --7811170298 Amend 52 to Environ Rept re correction of errors & requested by WH Regen's 780922-781011. & 781018 itrs.
  HOMELL, S. H. Consumers Pawer Co. 78/11/10. 202pp 94043.277
- 7811070149 Responds to 781011 NRC itr re-review of subj facil Environ Rept-Oper Lic Stage. Answers questions re-archeological investigation of Tittabawasse River Floodplain. httpation or avoidance of archeological sites
- 7811280282 Forwards affidevit distributing copies of Amend#52 to CPC's Appl for Conetr Permit. Cert of Svc enci.
  BANJJ. Consumers Power Co. 78/11/20. 4pp. 94395:228
- 7812190095 Forwards affidavit for Amend 55 Rev4 to Environ Rept app1 for reactor constr parmit & open lic on 781211. BACCN:J.L. Consumers Power Co. 78/12/12, 4pp 94391:036
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 7812050222 Ack cooperation in providing into for E18 for subj facils. Requests written confirmation of data provided re staffing, admissions & occupancy rate of Midland Hospital. HDNO.8.W. Argonne National Laboratory. 78/10/29 ip. 94201-148
- 7812030225 Ack cooperation in providing info for EIS for subj facile. Requests written confirmation of data provided re planned expansion of water capacity of City of Midland. HONG S.W. Argonna National Laboratory 78/10/20 ip. 94201 199
- 7812050227 Ack cooperation in providing infe for E19 for subj facile Requests written confirmation of data provided relaxed of partiand in the City of Midland & that the total space devoted to parks & recreation exceeds gen standards HONG 8.M. Argonne National Laboratory 78/10/25 ip. 94201 200.
- 7812030232 Ack comperation in providing into for E18 for subj facils. Requests written confirmation of data provided re 4 of law enforcement officials & patrol cars in Midland County, & that construct facils has not affected local crime rate. HDNO, 8. M. Argenne National Laboratory. 78/10/23. 1p. 94202.023.
- 7812030239 Ack cooperation in providing info for EIS for subj facile Requests written confirmation ofdata provided rem of police & patrol cars in City of Midiand, & that constr of facile does not impact on local crime rate.

  HDN9.8.M. Argonne National Laboratory. 78/10/25. ip. 94202:045
- 7812030244 Ack cooperation in providing into for E18 for subj facils
  Requests written confirmation of data provided re-current
  smrollment & unused capacity of the Bullock Creek School
  District.
  HONO.S.M. Argonna National Laboratory. 78/10/25. lp. 94202:067.
- 7812050250 Ack toopsration in providing info for EIB for sub; facils. Requests written confirmation of data provided recurrent enrollment & unused capacity of the Midland School District. HONG.S.M. Argonne National Laboratory, 78/10/85. 1p. 94202:114.
- 7812030205 Ack cooperation in providing info for EIB for subj facilis. Requests written confirmation of data provided reconfirmation by State Supreme Court of ennexation. HONG S.M. Argonna National Laboratory. 78/10/23. 1p. 94202:127.

### Q. Adjudicatory correspondence

- 7811100146 Forwards contantions that MI law prevents lic that creates a nuisancs, illegal radiet spills are occuring, spent fuel rod storage has created hazards, icing & fogging nuisance is occurring & present tech fails to achiev iero enission.

  MARBHALL, H. H. Mepleton Intervenors, 78/10/31. 1p. 94047:169.
- 7811300369 Hemorandum & order postponing special prehearing conference previously scheduled for 781113, until 781214 at same hr & iocation.

  BRITH-I.W. Atomic Safety and Licensing Roard Panel, 78/11/13. 3pp 94136-281.
- 7812280350 Hemo of CPC re environ effects of radon per NRC Order of 781106. Asserts that Partins declaion is supported by record of that proc & that radon emissions do not critically effect cost-benefit beience. Wienci documentation & Cert of Byc. MILLER.M. I., 01888, M.E. Isham, Lincoin & Beale. 78/12/08. 19pp. 94082:217.

- 78:01:0309 Answer of Consusers Pur Co to Petition for Leave to SIMILITY Answer of Consumers run to to relision for Leave to intervene of M H Harshell on behalf of the Mapieton (intervenors intervention should be denied for untimaliness. A perticipation would not contribute to record. HILLERIN I. O(BBS.M E. Isham, Lincoln & Beale 78/09/28. 13pp. 94061 016
- 7810220152 Natice of withdrawal from proceeding as of 780929. Certificate of Svc enci. GROSSKANLH J. Hearings Division. 78/09/29 3pp
- 7810140027 NRC staff answer to patition submitted 780909 by W. Marshall requesting leave to intervene on behalf of Hepelton intervenes NRC staff does not oppose patition at this time. DLHSTEAD.W J. Office of the Esecutive Legal Director. 78710703 94421 002
- 781102028) Notice of Mithdrawal of Appearance accompanied by Notice of Appearance for David Sondarmen, replacing Cohen & Cert of COMEN.R C Arnold & Porter 78/10/06 5pp 94354-282
- 78:0240157 Notice of hearing on issuance of OL license SER.FES.DES.
  ACRS rept on OL application.Tech Space & intervention
  patitions.related papers & Search 780814 membrandum & order
  asy be inspected at NRC PDR Certificate of Svc enci.
  8MITH.1.W Atomic Befety and Licensing Board Panel. 78/10/12. App.
- 78102501BB Memorandum & order granting WH Marshall temporary status as intervenor pending Board final determination on adequacy of intervention patition Maplaton Intervenors day file amended patition descripting interest in proceeding.

  SHITH: IM Atomic Sefety and Licensing Board Panel, 78/10/12. Opp. 94392 241
- 7810000311 Repts predicted will figures for long-term electricity demend for 1978-88 per latest short-term forecast MILLER. M 1. Ishae, Lincoln & Seele 78/10/18 2pp. 94253:317
- 7811010006 Forwards another capy of the 86 Mass & Order of 780814 & Notice of Hearing on Issuance of Facil Open Lic of 781012 In response to 781018 Mailgres Informs that requests for data should go to staff, not 80. Mrs and 80. Mrs an SMITH I. W Atom
- 7811060048 Requests rescheduling of NRC hearing in Hidland. Mi from 781015 to another date. MARBIALL, H H Affiliation Unknown 78/10/29 ip. 94398:140
- 7812060152 Order referencing re annexation of subjects to City of Midlend, H1 forwarded as encl to ANO: 7811240199.

  MARRISON.M. Q Michigan, State of, 78/10/30, 43pp. 01791: 057.
- 7811130189 In response to motion of 781029 from W Marshail re prictions of the profits to motion of /BIV29 from M Marshall representation of preherring conference, ordered that B Gadlar will represent Marshall & Mapleton Intervenors at the special preherring conference.

  BMITH. 1M. Atomic Safety and Licensing Sound Penel. 78/10/31. 2pp. 03053:330.
- -- 78:11:30:92 Request by intervenor W Marshell for continuance of special prehearing conference on 78:110 due to his unavailability on that day Request for reached made on his own behalf & on behalf of Mapiaton intervanors.
  MARSHALL, H. H. Affiliation Unknown, 78/10/29, 1p. 03553: 332.
- 7811210040 Submite eddi contentions in support of 780906 contentions objecting to sub, faci re illegal charges & spills, gadlogical conditions & storage of spent fuel rade. Certificate of Svc enci.
  MARBHALL.M.H. Mapieton Intervenore. 78/10/31. 3pp. 94(01:35).
- 7811150039 Requests that CPC file brief supporting util gosition that HM Marshell patition to intervens be berred by 781031 resignificate of Sec encl. MARSHALL, N. H. Mapleton Intervenore. 78/11/02. ip. 94112:349.
- 7811210036 Serves SJ Gedler w/\*Srief of Consumers Pur Co in support of its position that Marshell's petition to intervane is barred by Tes justists. 0[888.M.E. ]shem. Lincoln & Beale. 78/11/02. 1p. 03557; 039.
- 7811210493 Contention of Intervenor H Sinclair, Asserts that HRC Staff is responsible for assuring compliance w/tonic Emergy Act of 1934. Also claims that NRC has not implemented an effective aftert inapse prog. Cert of 8vc encl.

  BINGLAIR.H.P. Affiliation Uninown. 78/11/03. 40pp. 03558:163.

- 7811130232 Only issue remaining also address issue of charge ra CPC's conduct. 3d will also address issue of environ effects of reson. 3d will not consider CPC's alleg soviety of OA-OC violations & lack of financial quals history of OA-OC violations & lack of financial quals CMLK. 8 J. Office of the Becretary of the Commission. 7 7pg. 94273:086.
- 7811220215 Supple 781018 notice of hearing that special pre-conference per 10CFR2.751(a) would begin on 781115. Meetin will not be held on 781214 in Midland Mi SMITH I.M. Atomic Sefety and Licensing Board Penel 78
- 7812050125 Requeste change of incation for 781214-15 proha-conference from Midland.MI to Chicago IL. CHERRY.H M. Cherry. M M /Cherry. Flynn & Kanter. 78/1

94071: 282.

94382: 025.

- --7812060172 Requests comments on NRC 781106 memorandum & comeideration of operating & const matters CHERRY.M.M. Cherry, M. M. /Cherry, Flynn & Kenter. 78 94382:027
- 78:1300356 Objects to M Cherry 78:133 request to change la licensing hearings to Chicago Poor health would prayent attendence if hearing was not held in Midlend Mi. Certifi MARGHALLIN. H APPillation Unknown 78/11/17. 1p. 941
- 7812050257 Informs that itr transmitting radon record show stemped "Berved 781117." . Docketing & Bervices Branch. 70/11/21. ip. 94202:1
- 78:2010297 Memorandum & order confirming date of special p conference. Location of future sessions will be discussed conference. Board will begin 79:214 by dealing w/problems involving lawyere, Limited appearance statements deferred BMITH. i.W. Atomic Sefety and Licensing Board Panel. 7E 94417:123.
- 7812140087 Brief submitted by CPC in response to ABLB OrdicPC asserts that 27 of petitioner to intervane H Bincle suppl contentions are inadmissible & that petition to intervene of W Marshall bs denied. Cert of Svc and MILLER.M. 1. 01888, M.E. Isham, Lincoin & Beale, 78/11. 94128:242.
- 7812140362 Answer of CPC to Motion by M Charry, represents intervenors other than Dow Chem Co, for joint considerat of oper & constr matters. CPC esserts that consolidation neither req nor justified. Cert of Byc encl. MILLER.M. 1., 01888, M.E. leham, Lincoln & Beale, 78/11 03557-251.
- 7812260065 Forwards "Participation in the Instant Proc." TAYLOR.Q.T. Michigan, State of. 78/11/28. ip. 94027
- --7812260067 "Participation of the State of HI in the Ins Responds to Bd Order 781117 requiring HI to advise it intends to perticipate Scope & subj matter of intends participation are outlined. TAYLOR. G. T. Michigan, State of. 78/11/28. Rep. 94
- 7812260278 NRC Staff's Response to contentions of patitic intervane Mapleton Intervanors. Staff asserts that contentions NL. 3, 4, 6 % 7 are vague or w/out basis in faction tentions NL. 5 % may be proper if rephrased. W/Cert of DLMSTEAD, N. J. Office of the Executive Legel Director. 5pp. 94160:052.
- -- 7812260305 NRC Staff's response to Contentione of peti intervence of Sincialir. Staff objects to contentione of per-intervence of Sincialir. Staff objects to contentione of 26.35, 39-41, 49, 46, 44e, 45e, 47e-34. No objection is mad contentions 22.2.24, 27-34, 42-44, 47, 48 & 46e. CMSTEAD.H. U. Office of the Executive Legal Diracto 10pp. 94160:035.
- 7812140223 Responde to 781130 request for edvance notifit meetings between NRC & consumers re subj aits. Responde already been sent such notices. & recent Fed Register effirms open meeting policy which holds for subj site. OLMSEAN, W. J. Office of the Executive Legal Director. ip. 94204:340.
- 7812180383 Corrects factual error in 781128 Consumers Pu Steam rate may or may not be subj to jurisdiction of h 91988.M.E. Isham. Lincoln & 80010. 78/11/29. 1p. 5

- 7812280325 Forwards documents or settlement of Diesel Queerator Bidg foundations at eubj facil.

  OLMSTEAD, H. J. Office of the Executive Legal Director 78/12/07.
  14pp 94082:141.
- --7812280332 Forwards 781120 ltr from M Cherry w/possible ellagations against resident NRC inspector at sub J facis. DAVIS.J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/05. 1p. 94082:340.
- --7812280334 Forwards 1tr from M Cherry re subj constr proj. Response ie being prepared. KEPPLER, J.O. Region 3. Chicego. Office of the Director. 78/11/24, 1p. 03555:152.
- --7812280340 Expresses contern that NRC is ettempting to minimize problem of diesel gamerator bldg settlement at subj facil. Suggests NRC resident inspector may be coopted by util. Requests info & permission to attend next inspec.

  CHERRY.M.M. Cherry. M. M./Cherry. Flynn & Kanter. 78/11/20. 3pp. 00355:157.
- --7812280343 Transfers Isad responsibility for problem of significant settlement of dissel generator bidg to NRR. M/enci repts on deficiency.
  VABBALLO, D. B. Assistant Director for Light Water Resectors.
  78/11/17. lipp. 94082:204.
- 7812270132 NRC Btaff's response to NRC Memo & Order of 781106 re radon iesus. Asserts that ABLB has no need for addi written evidence re radon question. Notice of appearance for BM Bordenick & Cert of Bvc encl.

  SDRDENICK.B.M. Office of the Executive Legal Director. 78/12/09. 10pp. 94161:086.

### H. General correspondence

- 78ii010014 Requests OL documents:50-329 & 50-33 to be est to N Hetits P.O. Box 103,3609 Shoreline Dr., Nererve, Mn 55392, aiso to place Hatis on circulatory liet. MARGHALL, M. H. Mapleton Intervenors. 78ii0/18. ip. 94290:239.
- 7812280198 Responds to 781120 itr.forwarde info re resident inepector being co-opted by Midland personnel. NRC has initiated an investigation into settlement of diessi bidg at facil. KEPPLER, J. O. Region 3, Chicego, Office of the Director. 78/12/14. 125pp. 94073:090.
- K. Utility Final Bafety Analysis Report (FBAR) & amende
- 7812010252 Rev i5 to the FBAR vole i & 2: responses to requeste for additinforevine orifice nod assemblies & high density fuel racks & routine design deviaddi info scheduled for entry. W/snci amend appl for CP & DL.

  \* Consumers Power Co. 78/11/30, 1300pp.
- 7810230192 Forwarde Amend 51 to CP & OL applications.consisting of Revision 14 to FSAR, HOWELL, B. H. Consumers Power Co. 78/10/17. 1p.
- --7810230196 Revision 14 to FBAR, Vols 122. # Consumers Power Co. 78/10/17, 1153pp.
- 7810270168 Forwards Cert of Svc for copies of Amende51(Rsv 14 to Fine) Bafety Analysis Reptito appl for conetr psemits & oper lice. BACON-U.L. Consumers Power Co. 78/10/24. 2pp. 74056:266.
- 7812010231 Forwards Amend 54 to CP & DL application containing Revision 15 to FBAR.
  HOMELL.S.H. Consumers Power Co. 78/11/27. 18pp. 94390:159.
- 7812120154 Forwards advance copy of util response to NRC Request 421.2. "GA During Operations Phase." FSAR Subsection 17.2 repartonnel training, staff changes, cleening of fluid sys & GA audit. Response to be eubmitted w/Revieton 16 of FSAR. HOWELL.S.H. Consumers Power Co. 78/12/08. lipp. 94276:286.

# M. Antitrust correspondence

7812180246 Intervenore & applicant CPC rept that prospect for settlement of issues contested in proceedings re sub; facils is excellent an understanding has been reached in all but 2 areas. Cert of Svc encl. ROSS. H. W. WATSON, K. S. Weld, Harkrader & Ross. JABLON, R. A. Spiegel & McDiarmid. 78/12/06. App. 94359:335.

# Q. Inspection reports, IE Bulletins & correspondence

- 7812050333 Forwards IE Suiletin#78-12A.suppl to IE Bulletin 78-12 H/encl ANO: 7811300055. KEPPLER, J. O. Region 3. Chicago. Office of the Director 78/11/24 lp. 74409:001.
- 7812080249 Informs NRC of ongoing preparation of response to 1E Bulletin 78-12."A Typical Held Matl in Reactor Pressure Vessel Helds" for subj facil & states that written response will be forwarded by 781215.
  HONELL.S.H. Consumers Power Co. 78/11/28 ip. 94137-191.
- 78:2:40021 Forwards IE Inspec ReptsM50-329/78-11 & 50-330/78-11 on 780926-28 during which no itsme of noncompliance were noted. HEISHMAN,R.F. Region 3. Chicago, Diffice of the Director. 78/10/27. 2pp. 94:19:347.
- 7810270024 Forwards I & E Initial Rept on Response to Bulietin 77-05/05A he Use of Elec Connectors Appropriate 8ds should be notified where there is a question re use of connectors in sefety sue Memo dtd 780207 also enci.

  TEDESCO.R. L. Assistant Director for Plant Systems 78/02/08. 19
- --781027024& Forwards "Status of Responses from Licensees of Plants und Construc to Bulletine 77-05 & 03A". MOBELEY, N.C. Division of Reactor Construction Inspection. 78/02/07, 3pp.
- 7811130340 Forwards IE Inepec Repts#50-329/78-09 & #39-330/78-09 on 780829-31 & Notice of Violation.
  HEIBHMAN,R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch, 78/09/21. 2PP. 94007:309.
- --78:ii30343 Notice of Violation from inspec on 780829-3i.

  Region 3, Chicago, Reactor Construction & Engineering Support Branch, 78/09/21, ip. 94007:3ii.
- --7811i30350 IE inspec Repts#30-329/78-09 & #50-330/78-09 on 760829-3i during which i item of noncompliance was noted:failure to follow procedure in welding root pass.

  LEE,E.M., DANMELRON, D. H. Region 3, Chicaga, Office of the Director, 78/09/21. Spp. 94007:312
- 7810160197 "Pressrvice & First 10-Yr Interval Insp Plan for NDE & 8ue Pressure Testing at CPC Midland Units 1 & 2." Prepared for util.

  BLAGER, H. M., BIRKLE, A. J., MAYNARD, C. J. Bechtel Corp. 78/09/29. 247pp.
- 78:0160196 Forwards "Preservice & First 10-Yr Interval Insp Pian for NDE & Sys Pressure Teeting at CPC Midlans Units 1 & 2." Date reported in Section 3 of pian is preliminary & subj to change as const progressee. Plan basic of 78:025 meeting. HDWELL-8, H. Consumers Pawer Co. 78/10/05 2pp. 94007-150
- 78iii40048 Forwards IE Inspec Repts#50-329/78-i0 & #50-330/78-i0 on 780913-15 during which no items of noncompliance were noted. HEIBHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch, 78/10/10, 2pp. 94420:343.
- --7811140054 IE Inepec Repts#50-329/78-10 & #50-330/78-10 on 780913-15 during which no items of noncompliance were noted. Major area e inepected included: installation of sefety-related hangers & restraints.

  YIN.1.T. Region 3. Chicago. Office of the Director OANTELBON, D. H. Region 3. Chicago. Resettor Construction & Engineering Support Branch. 78/10/10. 6pp. 94420:345.
- 7810200211 Ack receipt of 780918 ltr informing NRC of steps taken to correct item of noncompliance identified in IE Inep Repts 50-329/78-07 & 50-330/78-07, Addi info is requested. KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/10/11. 2pp. 94367:064.
- 78i1070336 Responde to 780921 NRC ltr re noncompliance noted in Inepec Repts#850-329/78-09 & 50-330/78-09. Corrective actions:rev of Bechtel Welding Procedure Spec & Bechtel Project Quelity Control Instruction#7220/W-1.00.
- 7812140028 IE Inspac Repts#50-329/78-11 & #50-330/78-11 on 760926-28 during which no items of noncompliance were noted Major eras inspected incl: Isabcock & Wilcox Constr Co nondestructive exemination prog procedures & parsonnel cert. HARD.K.D., DANIELSON.D.H. Region 3. Chicago, Office of the Director 78/10/26. 7pp.

- REPERSOO-3297/78-03 & #50-3307/8-03. Corrective actions weld spec ray, weld voltage range monitoring procedure prepared disagress on 15% voltage range limitation HOMELL, S. H. Consumers Power Co. 78/10/31. 2pp. 94013-023
- 7812040064 Forwards IE Inspec Repts#50-329/78-13 & #50-330/78-13 on 780724-28, 33,6801-31,0901-03 & Notice of Violetion. HEIBHMAN R.F. Region 3. Chtraga. Reactor Construction & Engineering Support Brench. 78/11/03 2pp. 94232.254
- --7812050057 Notice of Violation from inspec on 780724-0928.

  \* Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/03 2pp. 94232-255
- --7812050070 IE Inspec ReptsM50-329/78-13 & #50-330/78-13 on 780724-0908 during which 2 ttems of noncompliance were noted welds with unequal outside diameters were accepted & Safety Related Control Red Drive Primery Breakers were not well protected. CCOM.R J. HAYNES, D. W. Region 3. Chicago, Office of the Director. 78/11/03. 6pp 94232:258
- 7811150057 Forwards IE Circular 78-18.
  KEPPLER. J G. Region 3, Chicago. Office of the Director 78/11/06
  1p. 94112:192.
- 78ii20004i Ack receipt of 7Bi020 itr informing NRC of steps taken to correct violations noted during inspec.
  MEIB-MAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch 78/11/08. 1p 94215-323.
- 7B12140130 Forwarde IE Inspec Repts#50-329/78-14 & 50-320/78-14 on 780910-29 during which no items of noncompliance were noted. HEIS-MAN.R.F. Region 3. Chicago, Resector Operations Nuclear Support Branch. 78/11/08 Spp. 94128:334
- --7812140139 iE Inspec Repts#50-329/78-14 & 50-330/78-14 on 780910-29 during which no itams of noncompliance were noted Major areas inspected incl: exemination of gen sits condition & eteam generator & reactor vessel hold down bolting CCDK.R.J. HAYEB,D.W. Region 3. Chicago. Reactor Construction & Engineering Gupport Branch. 78/13/06 4pp. 94128.336.
- 7811220006 Act receipt of 781023 ltr informing NRC of steps taken to correct violetions noted in 780921 ltr Corrective actions will be reviewed during a future inspec. HEIBMAN.R F. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/15 ip. 94308-246.
- 7812050102 Acv receipt of 781031 itr informing NRC of steps taken to correct violations noted in 780504 & 780913 ltrs. Re issue(b) NRC requests that empiling measurement sup provide essurence that all weiding mechines are covered by emperage & voltage. HEIBHMAY, R. F. Region 3, Chicago, Reactor Construction & Engineering Support Brench, 78/11/22, ip. 94030:287.
- 7812140080 Ack receipt of IE Builetin#78-12A re stypicel weld mati in pressure vessels. Response will be consistent w/sxtended eched of IE Builetin#78-12A.

  HOHELL-8. H. Consumers Power Co. 78/12/05. Ip. 94128: 226.
- 7812290015 Forwards IE gulletin 78-14. KEPPLER J. 9 Region 3. Chicago, Office of the Director. 78/12/19. 1p. 06911.001.
- R. Periodic operating reports & related correspondence
- 7810270142 Forwards Monthly Nonconformance rept for Sept 1978, HDHELL, S. H. Consumers Power Co. 78/10/25 1p. 94060:050.
- 8. Reportable occurrences. LERs & related correspondence
- 7812010155 Ack receipt of 781110 interim rapt pursuent to 10CFR50.55(s) re reactor building spray piping supports HEIS-MAN.R.F. Region J. Chicago, Reactor Construction & Engineering Support Branch. 78/11/22 ip. 94418:125.
- 7810180075 Interim deficiency rept re reactor bldg spray piping supports. Bechtel Associates Prof Corp rept of status of corrective action & investigation encl. Further rept to be submitted by 781117.

  HONGLIS.H Consumers Power Co. 78/10/13. 4pp. 94401:028.
- 7811010401 Ack receipt of 780727 final deficiency rept re containment bidg personnel airlocks. Review will be completed during future insps.

  HEIG-MAN, R. F., Region D. Chicago, Reactor Construction & Engineering Bupport Branch. 78/10/24. ip. 94388:323.

- Final rept will be reviewed upon receipt HEISHMAN.R F Region 3. Chicago, Reactor Construction & Engineeri: Support Branch. 78/10/25 ip 94375:355.
- 7811070222 Ack receipt of 781013 interim rept re reactor bidg sprey piping supports.
  HEJBHRAN.R.F. Region 3, Chicago, Reactor Construction & Engineerin Support Branch. 78/10/30 1p. 94039-141.
- 7811170212 Interim deficiency rept re settlement of diesel generator foundations & bldg. Provides status of actions to be taken. Review meeting tentatively planned for last two whe in Nov. Further rept to be submitted by 781229.

  HDMELLE H. Cansumers Power Co. 78/11/07. 7pp. 94136:114
- 78:1170222 Interim deficiency rept re reactor bldg spray piping supports Provides status of analysis being conducted to resolve question af adequacy of supports per ABHE Sation III Code allowable stress requirements Final rept by 78:1219. HONELL-8 H. Consumers Power Co. 78/11/10. 4pp. 94:136.213.
- 78i1220i76 Interim deficiency rept re Class iE station battery. Exide Industriel Bettery Div asked to provide edditional info describing condition. failure mode & analysis of why condition was reportable. Related correspondence.

  HOWELLIS H. Consumers Power Co. 78/11/17. 2pp. 94623:267.
- --7811220178 Reports that addition ber must be added to Class: battery racks sent to sub; facils in order to isolate horizontal momentum during seismic events. Design is being worked out & will be ready in 60 deye for retrofit. MCMANUS, C. K. ESB. Inc. 78/10/11. 1p. 94623:269.
- 7811290293 Ack receipt of 781117 interim rept pursuant to 10CFR50 55: re settlement of diesel generator foundations & bldg.
  REISHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineeric Bupport Branch. 78/11/22. 1p. 94239:244.
- 78:2040287 Act receipt of 78:11:0 interim rept re reactor bldg spray plying supports.
  HEISMAN.R.F. Region J. Chicago, Office of the Director. 78/11/27
- 7812140366 Ack receipt of 781117 interim deficiency rept re class 16 station battery racks HEIGHMAN.R.F. Region 9. Chicago, Reactor Construction & Engineerin Bupport Branch. 78/11/22. 1p. 03557:288.
- 7812040218 Interim deficiency rept re component qualification test documentation re-revisu Rept is being generated by Bechtel documenting statue of re-review & results on individual meti requisition basis for ell G-componente requisition basis for ell G-componente requisition to the region of th
- 7812270184 Interim deficiency rept re reactor bidg spere piping supports. Bechtei Associates Prof Corp rept on stetus of analysis being conducted to resolve question of adequacy of reactor bidg spray piping supports per ASME requirements. HOWELL 8 H Consumers Power Co. 78/12/15. 3pp. 94017:361.
- 7812270254 Forwards nonconformance tept for Nov 1978, (Enc.1 8008180685 HONELLIS.H. Consumers Power Co. 78/12/20, 2pp. 94016:082.
- 7812290146 Interim deficiency rept re eettlement of diesel generator foundations & bldg. Use of preioed to deneify existing fill meti in place selected as corrective action. Bectal rept detelling tasks to be sent by Jan. Related correspondence, HOWELL, B. H. Consumors Power Co. 78/12/21. 2pp. 94190:281.
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- F. Security, medical, emergency & fire protection plane
- 7810230173 Analysis of subj fecil fire protec sys will be submitted b 781115. LIU.L. Jowe Electric Light & Power Co. 78/10/10. jp. 94164:299.
- 7811070121 Responds to 781031 NRC request for fire protec mod effort. Forwards design info re Control Room Fire hazards & Water Buppression Bys. Requests approval by 781030. LIU.L. Iowa Electric Light & Power Co. 78/10/30. 3pp. 94038:296
- 7611170159 Fowards subj facil security Proj sched, Recent proj incl sitework & fencework continuing on sched, security hardware contract has commenced, bldg facil contract constr work has commenced.

  LTU.L. Iowa Electric Light & Power Co. 78/11/01. 3pp. 94048: Oge

- 7811130052 Confirms meeting to be hald between util & NRC Region III on 781113 to discuss security prog at site including items of noncomplience identified during past 3 inspections KEPPLER, J. O. Region 3, Chicago. Office of the Director. 78/11/03 ip. 94010 244
- 7812110106 Forwards Security Proj Schad & states that site & fencing work has been complated while security hardware & bidg facil contract work is proceeding as eched LIU.L lowa Electric Light & Power Co. 78/12/01. 1p 94339.064
- 78ii210354 Analyses is adequacy of elec cable fire barrier penetrations will be submitted by 781231 & fire protec sys fire hazard analysis will be submitted by 790131
  LIU.L. lowe Electric Light & Power Co 78/11/15 ip 94405.016

## Q. Adjudicatory correspondence

- 7812290233 Requests that NRC institute a hearing suspending facil lic until augmented insvc images prog is incorp into the lic iOCR250 55e(al(d))req licenses to test & inspec qual standards commensurate w/safety function performed HALLIN.O. Citizens United for Responsible Energy. 78/12/20. 2pp. 94191:212
- H. Ganerai correspondenca
- 7812130100 Raquasts full investigation of pipe cretting of facil since lask was discovered in coolant pipe efter elac malfunction shut down reactor. Recommends institution of more efficient inspec & monitoring procedures.

  KIEGELJ A Affiliation Unknown 78/11/21 ip. 94294-328
- J. Insurance & Indomnity information
- 7810110143 Forwards eigned copy of Amend#5 to Indemnity Agraement#B-&8. SECKMAN.P.E. loue Electric Light & Power Co 78/10/04 ip. 94064-277
- --7810110146 Amend#5 to Indemnity Agraement #8-68.adding Article 8 ra payment of pramiums. BALTZMAN.J Antitrust & Indemnity Group. 78/10/04. 2pp. 94064:278
- P. Operating license stage documents & correspondence
- 7811280030 Forwards request for info on recirculation inlet nozzle analysis, to be delivered in orel & written form et 780707 neeting.

  KEPPLER. J. G. Region 3, Chicago, Office of the Director. 78/07/03 2ps 02728-357
- 7811280016 Summary of meeting on 780707 u/IELP to discuss crack in safe-end on inlet recirculation noisile. Indications in other safe-ands on inlet recirculation noisiles & repair of crack W/statch.hendouts at meeting & attendance list WOORNUFF, R W Division of Reactor Operations Inspections 78/07/10. 20pp 02728:260
- 7811280036 Rasponds to 780703 itr re subj facil Racirculation Inlet Nozila Analysis. Covers dynamic analysis on piping. Piping isometric drawing of racirculation lina. nozila load summary, design transients for stress enalysis.strass analysis. LIU.L. Iowa Electric Light & Power Co. 78/07/26. 133pp. 02728:012.
- 7811270202 Forwards rapair rept entitled. "Duane Arnold Energy Canter Recirculation inlat Safa-End Repair Prog " LIU,L lowa Electric Light & Power Co. 78/07/31. 9pp. 94272:142.
- 78:128049: Announces espansion of scape of the Pipe Crack Study Group to incl examination of Intergranular stress carrosion Cracking in the Inconal safe ends at subj facil in Juna 1978 & recommends actions to be taken to determine cause DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/09/29, 1pp. 94414.279.
- --7811280493 Outlines recommendations & proposed course of action re results of safe and inspec & metallographics exams relevant to insvc inspec, mod & dealgn qual of 4 types of safe ands for recirculation nozzies. JCRDAN.E.L. Office of Inspection & Enforcement, Office of the Director. 78/09/29. 4pp. 94414.280.

- --78:1280494 Reports that praliminary test results re pump riser crack problem indicates cracks are intergranular & start in area formed by thermal sleeve & Incomel transition piece & may elist in other plants CDLING.W Office of International Programs. Director. 78/09/14. 3pp 94414-284
- 7810120047 Responds to 780829 NRC itr re control rods failing to fully insert on scram No evidence exists that this has occurred eccording to 1977 records
  HAMMOND,E L. lows Electric Light & Power Co. 78/10/05 1p
- 7810240104 invites NRC staff to conduct tech review meeting re repairs on subj fecil at corporate headquarters of IELP This would foilow NRC policy of bringing meetings closer to pub actually served by nuc facil.

  \*\*TUTHILL.9.\*\* J low Electric Light & Power Co 78/10/06. 1p
- 78ii030205 Forwards Amend#46 to Facil Oper Lic#DPR-49 ravising Tech Bpacs as requested in 770414 ltr w/6efety Evaluation & Notica of Issuance. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/17 2pp 02724 143
- --7811030208 Amand#46 to Facil Oper Lic#DPR-49 ravising Tech Specs re limiting conditions for oper & surveillance requirements for drywell to suppression chamber differential pressure control & suppression pool water leval. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/17 Ppp. 02724.145
- --78i10302i0 Notica of Issuance of Amand#45 to Facil Oper Lic#DPR-49 on 78i017.
  IPPOLITO.T A. Operating Reactors Branch 3 (Pra 790625). 78/10/17.
  Zpp. 02724:160
- --781i030215 Sefaty evaluation supporting Amend 46 to Facil Oper Lic DPR-49 concluding that each Mark 1 containment sys would maintain its integrity in evant of LOCA BHR facile can oper safely • Office of Nuclear Reactor Regulation, Director, 78/10/17 5pp (2724:154
- 78i1130335 Burmary of 7809i4 meeting w/GE representatives & Mark | Owners Group ra progress of Long Term Prog w/attendance list & agenda(RD-9-A-Marki, Standards.) GRIMES.C. Plant Systems Branch (Pre. 79i030), 78/i0/26. 67pp
- 7810310220 Forwards"Metaliurgical Investigation of Crecking In a Reactor Vessel Nozzle Bafe-End". Old 781020. No significant deviations espected in final rept which FR will incl stress corroston cracking review of inconel 600
  L1U-L lowe Electric Light & Power Co 78/10/27 ip. 94089: ii3.
- 7811280363 Announces 781114 meeting in Cadar Rapids.1A w/util re repair prog for racirculation sys inlet nozzla safe ends at subj facil.
  CLARK.R. Operating Reactors Branch 3 (Pre 790623). 78/11/02 ip. 74397:227.
- 7811120173 Notifies applicant of 781128 NRC-sponsored seminar ra Model Radiological Effluent Tach Specs for Nur Pur Plants Encl w/8minar into Sheet(to be completed & returned by 781117) & Proposed Agenda.

  KEPPLER. J. Q. Ragion 3. Chicago. Office of the Director. 78/11/07 App. 03533:233.
- 7812130161 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. Wenci Registration Form & List of Locations. MILER, J.R. Assistant Director for Site & Safeguards iPre 791030). 78/11/15. 5pr.
- 7812180279 Forwards Rev#1 "Draft Radiological Efficient Tech Specs" for 8WR\*s(RWREG-0473) & "Preparation of Radiological Efficient Tech Specs for Nuc Pur Plants" (NUREG-0133).

  ORINEB.D.K. Assistant Director for Engineers & Projects (Pra 790425). 78/11/13. Spp. 94357:023.
- 781127029; Forwards immediate action ltr(IAL) requesting subj facil not to resume welding on individual recirculation inlet nozzle plping weld joints until actions of IAL have been met. KEPPLER, J. G. Region G, Chicago, Office of the Director. 78/11/17. 2pp. 94224:340.
- 7811290258 Informs NRC that sample location#97 is being dropped from environ monitoring prog. since milk animals are no longer

- 7812110007 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justicitation for continuing Wiencl AND: 87812C80207 IPPCLTTD, T Operating Reactors Branch 2 (Pre 790625). 78/11/29. 6pp 94339 225
- 7812130234 Forwards summary of 781113 meeting w/util re physical security inspecs at subj facil from Aug 1977-Aug 1978 Meeting summary w/beld per 10CFR2 790 KEPPLER.J Q Region 3. Chicago. Office of the Director. 78/11/30. 2pp 94305 337
- 7812120205 Notice of 781206 meeting to discuss IA Elec Light & Pur Coresponses to outstanding issues from 781114 meeting on repelling for recirculation sys injet noticle eafe ende at subj facil CLARWR J. Operating Reactors Brench 3 (Pre 790625). 78/12/04 2pp. 94276-035
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month 8080N.L.J. General Electric Co 78/12/04 lipp
- 7812280167 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicante. Info submitted must be substantiated by date & celculatione Licensee must notify NRC of any inaccuracise or enforcement action with result. DAVIS. J O Defice of Inspection & Enforcement. Office of the Director 78/12/06. 2pp. 94375.003
- 7812130136 Forwards rept"Duene Arnold Energy Ctr Recirculation Inhet Safe End Repair Prog. 781208" euppl rept submitted 780731.
  Replacement design stress rept seni.
  LIU.L. ious Electric Light & Power Co. 78/12/08. ip. 94290.001.
- --7812130140 "Duane Arnold Energy Ctr Recirculation Inlet Safe End Repair Prog. 781208. " Suppl IE Repair Rept submitted on 780731. Repts purpose is to document info presented at 781114 meeting in Ceder Rapids. IA. \* lows Electric Light & Power Co. 78/12/08. 101pp. 94295:002.
- --7812130145 "Stress Rept Recirculation Inlet Norrie Bees End Replacement at Duane Annoid Nuc Pient." incl:primary stress analysis, thereal analysis & primary plus secondary stress analysis.

  PARDUE, L. H. Iowa Electric Light & Power Co., 78/08/10. 200pp.
  74295 108
- 7812210118 Confirms moeting on 781218 to discuss alleged welding deficiencies in repair work KEPPLER.J.O. Region 3. Chicago. Office of the Director. 78/12/08. tp. 94269.301.
- 7812270297 Farwards Bafety Analysis Review requested from GE to verify safety of reconstituted care, informs that during shutdown subj facil experienced higher off-ges rates. Fuel sipping was performed & leaking bondles will be replaced.

  LIU.L. lows Electric Light & Power Co. 78/12/13, 1p. 94229:349.
- --7812270301 Safety analysis review re Cycle 46 modified core. Mode do not involve unreviewed safety questions per 10CFR30.59 & no Tech Spec change needed.

   Iowa Electric Light & Power Co. 78/12/15. Bpp. 94229:330.
- 7812290130 Provides Environ Tach Spec Violetion Rept #78-01: on 781911 a discharge of water from make-up demineralizer sye neutralizer tank began w/o tenk first being serpied k ph was 12 i due to incomplete maint work.

  HAHDND, E. L. iowa Electric Light & Power Co. 78/12/21, 2pp. 94190:214
- 78i12i0367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark 1 containment program. SOBON, L. J. Ceneral Electric Co. 78/11/13. Spp.
- 78:12:10329 Submits questions to fiuid mechanics at subj facil as a result of 78:114 pub mosting in Coder Rapids, IA. H/oncl diagram from Coder Rapids Carette.
  PUGH R. Affiliation Unknown, 78/11/15. 2pp. 94484:314.
- Q. Inspection reports. IE Bulletine & correspondence
- 7812060337 Forwards IE Inspec Rept#30-331/78-17 on 780620-23, 780707 & 780711-3 during which no items of noncompliance were noted. FIORELLI.O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/06/27. 2pp. 94332:060.

- --7812060340 IE Inspec Rept#50-331/78-17 on 780620-23,780707 &780711-3 during which no items of noncompliance were noted Major arrae inspected incl-piant operstiesk records, pipe crack & core offloading.

  8HAFER, M. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch. MENNING. J. E., WALKER, R. Region 3, Chicago, Office of the Director 78/06/27 8pp.
- 7810250216 Forwards IE Inspec Rept#50-331/78-18 on 780724-26 & Notice of Violation. F108ELI-0 Region 3. Chicago Reactor Operations Nuclear Support Branch. 78/09/19. 3pp 94368:361.
- ~~9810250220 Notice of Violation from Inspec on 780703-0816. KNDP-R.C. Region 3, Chicago, Reactor Op≠rations Nuclear Support Brench. 78/09719, ip. 94368:339.
- --7810250222 IE Inspec Rept#50-331/78-18 on 780705-0816 during which 1 item of noncompliance was noted: Peliure to maintain positive control over a high radiat area KNDP.R.C. Region 3. Chicago. Resctor Operations Nuclear Support Brench. 78/09/19, 7pp. 94370:331.
- 7811130004 Forwards 1E Inspec Rept#50-331/76-21 on 760629-30 & Notice of Violation. Fig. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/10/02. 2pp 94077:009.
- ~-7811130005 Notice of Violation from inspec on 780829-30.

   Repidn 3. Chicago. Office of the Director. 78/09/27. ip. 94077:007.
- ~~781i1300iO IE Inspec Rept#50~33i/7B-2i on 780B29~30 during which 1 its of noncompliance was noted: failure to maintain adequate training records.

  MRIGHT.Q.C., LITTLE.S.B. Region 3. Chicago. Office of the Director, 78/09/27. 3pp. 94077:010.
- 7810300258 FDIA request for inevolutions rept of 780301 re-subj facil. CONNOR.L. Affiliation Unknown. 78/10/04. 2pp. 94185:331.
- 7811210214 Forwards IE Inspec Rept#50-331/78-25 on 780829-31 & 780918-21 & Natice of Violation. FIORELLI-Q. Region 3. Chicago, Resctor Operations Nuclear Support Branch. 78/10/12. 2pp. 94487:132
- ~-781[210216 Notice of Viplation from inspec on 780918-21.

  \*\* Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/12. ip. 94487:134.
- --7811210220 iE Inspec Rept #50-331/78-25 on 780829-31,780918-21 & 26 & 27 during which I item of noncomplience was noted: failure to properly control design change packages.

  BMFER. W. D., WALKER. R., JACKIN. I. W., Replon 3, Chicago, Reactor Operations Nuclear Support Brench, 78/10/10, 7pp. 94487:135.
- 7810230341 Forwards 1E Circular#78-17, (See AND: 7810230221; Dockst 50-013, 781013)
  KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/10/13. ip. 74167:039.
- 7810240112 Forwards responses to NRC request of 780522 for add1 info re insvc inepac & testing prog & 16LP request for relief from ASME Code requirements at subj facil.

  LIU-L. fows Electric Light & Power Co. 78/10/13. 146pp.
- 7811150086 Forwards IE inepec Rept#50-331/78-22 on 780803-04 & 780818-23 during which no items of noncomplians were noted. HEIBHMAN.R.F. Region 3. Chicago, Resctor Construction & Engineering Support Branch. 78/10/13. 2pp. 94113:192.
- --78111500BB IE Inspec Rept#50-331/78-22 on 780803-04 & 780818-23 during which no items of nuncompliance were noted. Major areas inspected included:review of procedures dev for cutting & removal of feedwater recirculation noizies.

  KEY.M.J. Region 3. Chicago. Defice of the Director.

  DANIELSON.D.M. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/10/13. 5pp. 94113:194.
- 7811080002 Responds to 781002 NRC itr re deviation noted in Inspec Rept e50-G31/78-21. Corrective actions: training records updated & personnel instructed. Compliance targeted for 781020. HALLACE. J. A. Iowa Eisetric Light & Power Co. 78/10/19. 2pp. 94398: 001.
- 7811210018 Forwards IE Inspec Rept#50-331/78-23 on 780623.28-30, Q707, 11-12 & 17 during which no items of noncompliance were noted.

  HE184MAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/19. 2pp. 94482:023.

- items of noncompliance were noted. Major eress inspected included: test of recirculation sys riser pipe crackireactor vessel N2 norzie safe end )
  WillLiAMB.C.C., KEY. N. J. HARD.K. D. Region 3. Chicago, Office of the Director, 78/10/19, 22pp. 94482:025.
- --7811280032 IE Inspec ReptH30-331/78-23 on 780623 during which no items of noncompliance were noted Major areas inspected incl: nondestructive test activity of Licenses See AND 7811210018 WILLIAMS.C.C., KEY.N.J., WARD.K.D. Region 3, Chicago, Rector Construction & Engineering Support Branch. 78/10/18. 22pp. 74480. 283.
- 7810310215 Ack receipt of 780929 itr informing NRC of steps teken to correct violations noted in 780727 NRC itr.
  HIND, J.A. Region 3, Chicago, Bareguerde Branch. 78/10/24, ip. 94090.320.
- 7811010303 Forwarde insvc inspec rept & essot documents for subj facil in response to 781004 FDIA request. FELTON.J.M. Division of Rules and Records. 78/10/24. 2pp.
- 7811070231 Ack receipt of 780920 ltr & response to noncompliance item #2 of 15 Inspec Rept#80-331/78-19:encl discussion of corrective action is withheld from public disclosurs.
  HIND.J.A. Region 3. Chicago. Bafeguards Brench. 78/10/24. 2pp. 94039:188.
- 78i1210090 Responds to NRC ltr re violation noted in Inspec Rept #50-331/78-25 Corrective ections:new control method to better control & treck design chenge packages routed thru site review & epproval process.

  WALLACE J. A. Ioue Electric Light & Power Co. 78/11/03. 2pp. 94482: 229.
- 78iii50068 Forwards iE Circular 78-i8. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 78/ii/06. lp. 94ii2:264.
- 7811200037 Ack receipt of 781019 ltr informing NRC of steps taken to correct violations noted during inepec. FIDRELLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/08 p. 94215.318.
- 7812140063 Forwards iE Inspec Repts50-331/78-24 on 780919-32,26-29 & 1023-27 during which no items of noncompliance were noted. HEIBHMAN,R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/08. 2pp. 94127:340.
- ---7812140066 IE Inspec Rept#50-331/78-24 on 780919-22.0926-29 & 1023-27 during which no items of noncomplience were noted Major area inspected inclineview of recirculation wafe end repeir procedures & observetion of installation.

  KEY.W.J., DANIELSON,D.M. Region 3. Chicego, Diffice of the Director. 78/11/06. 10pp. 94127:342.
- 7812120216 Forwerds 1E Inspec Rept#50-331/78-26 on 781004-06 & 18-20 during which no items of noncompliance were noted. FIORELLI 0. Region 3. Chicago. Resctor Operations Nuclear Support Brench. 78/11/09. 2pp. 94276: 137.
- --7812120226 IE Inspec Rept#50-331/78-26 on 781004-06 & 18-20 during which no items of noncompliance were noted. Major erass inspected incl: previous noncompliance & outstanding inspec items & review of decontemination methods.

  8HAFER.H.D. Region 3. Chicego. Office of the Director.
  JACKIH.I.N., MILLER.D.E. Region 3. Chicego, Reactor Operations
  Nuclear Support Branch. 78/11/06. 8pp. 94276:139.
- 7812130127 Forwards IE Inspec Rapt#50-331/78-28 on 780726-28.0818.0914. 0921.1002 & 1026. during which no items of noncompliance were noted. HEIBHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/11/09. 2pp. 94307:196.
- --7812130134 IE Inspec Rept#50-331/78-28 on 780726-28 OB18:0914:0921; 1002 % 1026; during which no items of noncompliance were noted Major areas inspected incl: licenses's metallographic studies of recirculation inject nozic safe and N2-A. WILLIAMB.C.C., KEY.M.J. Region 3. Chicago. Office of the Director. 78/11/09. 15pp. 94307:198.
- 7812010053 Ack receipt of 781103 ltr informing NRC of etep teken to correct violetions noted during inspec & discussed in 780929 ltr.Also submits info re review of forms NRC-741 & 742. KEPPLER.J.O. Region 3, Chicego, Office of the Director. 78/11/16. 2pp. 94416:144.

- 7811280480 Ack receipt of 781103 itr informing NRC of steps taken to correct noncompliance noted in NRC itr of 781012. FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/20. ip. 94381:346
- 7812050282 Forwards IE Builstin#78-12A.suppl to IE Builstin 78-12. W/enci AND: 7811300055. KEPPLER J. G. Region 3. Chicago. Office of the Director 78/11/24 1p. 94202:288.
- 7812280323 Ack receipt of 780803 itr informing NRC of steps taken to correct violetions noted during inspec#50-331/78-19. Enci withheld from disclosure.
  HIND, J. A. Region 3, Chicago, Sefeguards Branch 78/12/14. ip 94082-105.
- 7812280052 Forwards IE Bulletin 78-14. KEPPLER.J. G. Region J. Chicago, Office of the Director. 78/12/19. 19. 03354: 336.
- R. Periodic operating reports & related correspondence
- 781020006: Forwards Monthly Open Rept for Sept 1978
  HAMPOND 5. L. Towe Electric Light & Power Co. 78/10/11. ip.
  94412:191.
- --7810200063 Monthly Oper Rept for Best 1978
  VAN BICKEL J. Town Electric Light & Power Co. 78/10/11. 6PP
- 7811210390 Forwards monthly Oper Rept for Oct 1978 HAMMOND.E.L. Towa Electric Light & Power Co. 78/11/10 1p. 94480-041.
- --7811210394 Monthly Open Rept for Oct 1978.

  VAN BICKEL, J. Towa Electric Light & Power Co. 78/11/13: 7pp 94486:042.
- 7811280237 Correcte esmiennuel rept for 3rd & 4th quarter, 1977 Percent of environ tech spece for gaseous efficients during that time should be changed to X of 16X limit: 5.63X third quarter & 6.63X 4th quarter.

  HAMPOND.E.L. lowe Electric Light & Power Co. 78/11/17. 1p. 94012: 142.
- 7812190137 Forwards Monthly Oper Rept for Nov 1978.

  HAMPOND E. L. Iowa Electric Light & Power Co. 78/12/14. ip.
- --7812190139 Monthly Oper Rept for Nov 1978.

  VMN BICKEL, J. Towe Electric Light & Power Co. 78/12/14. 6pp. 94740.252
- B. Reportable occurrences, LERs & releted correspondence
- 781:270:60 Notifies NRC of Reportable Occurrence on unspscified date: during inspec of drywell to determine source of unidentified leak leak was discovered in recirculation loop inist noizis & plent was pieced in cold shutdown.

  HAMOND.E.L. lows Electric Light & Power Co. 78/06/19. ip. 9422:356.
- 7811270148 Forwards LERW78-030/OiT-0. HAMMOND.E.L. lous Electric Light & Power Co. 78/06/30. ip. 94271:360.
- --7811270180 LER#78-030/017-0 on 780517: water leak found in area of "B" rectriculation eys N2A inlet noizile caused by well creck in noizile safe end. Leb analysis will be performed to determine cause of cracking.

  VANBICKEL.J. lows Elsctric Light & Power Co. 78/05/30. 2pp. 94271: 361.
- 7810230152 Repte abnormal occurrence evant per 42FR10950 at subj facilimajor degredation of primery coolant preseure boundary in boiling water reactor resulted from crack in fitting that joins recirculation pipe to recetor vessel. CHIXx.S.J. Office of the Secretary of the Commission. 78/08/02. 6pp. 94194:345.
- 7810110141 Reporte an violation of Environ Tech Spec 3.3.1.8.2 of subjecti. Open LicHDPR-49.Qn 780925 discharge of radioattive liquid effluent was begun prior to completion of eample analysis. Approx 500 gallone were discharged.

  HAMMOND.E.L. Iswa Electric Light & Pawer Co. 78/10/04. 2pp. 94064:274.

- 7810310227 "Hetallurgical Investigation of Cracking in a Reactor Vessel Novile Bafe-End. SHRI Proj 02-5289-001. Interim Rept 781020 "
  Teets & evaminations performed includitasonic insput of safe-end. Chen analyses of safe-end & thermal sleevs.
  BURGHARD.H C Towa Electric Light & Power Co. 78/10/20. 52pp. 94009-113
- 7811280204 Forwards LER#78-020/017-1 HAMMOND,E. L. Town Electric Light & Power Co. 78/11/20. ip. 94013-245
- --7811280206 LER#78-020/017-1 on 780405 bearing out-of-alignment & rotated sufficiently to shear bearing dowel pin.Caused by lack of lubrication. Valve line-up procedure changed.

  VAN BICKEL J lowe Electric Light & Power Co. 78/11/17. Rpp. 94013-265.
- 7812050156 Forwards suppl. "Hardness Data", to 781020 rept by 8H Res Inst802-5389-991, "Metallurgical Investigation of Cracking in a Reactor Vessel noisle safe-End Interim Rept." LIU.L. loue Electric Light & Power Co 78/11/27. Bpp. 94335.086.

#### DOCKET 50-332 BARNWELL REPROCESSING PLANT

- A. Application/construction stage documents & correspondence
- 7812180147 Requests that Constr Parmit CPCBF-4 for Saparations Facil be sitended to 811231.

  BAXTER.B.C Aliied General Nuclear Bervices. 78/11/09. 3pp. 94365:294
- 7812180144 Forwards add1 copies of 781109 request for extension of completion date under Constr Permit CPC8F-4. BAXTER.R.C. Allied General Nuclear Services. 78/11/14. 2pp. 94363-259
- O inspection reports. iE Bulletine & correspondence
- 7811130009 Forwards Inager Rept#50~332/78-4 on 780822-25 during which no items of noncompilance were noted.
  BUTIERLAND, J. T. Region 2, Atlanta Fuel Facility & Materiale Sefety Branch. 78/09/29. 2pp 94075:291.
- --781130014 lE Inspec ReptM50-332/78-4 on 780822-25 during which no items of noncompliance were noted Areas inspected include revisu of demonstration run in progress review test procedures audit prog & facil mod records POTIER, J. P., CORYELLO, P. Region 2, Attente, Fuel Facility & Materia) a Bafety Branch. 78/09/28, 5pp. 94075:293
- 7811090266 Forwards IE inspec Rept#50-332/78-03 on 780906-07 during which no items of noncompliance were noted.

  MURPHY.C.E. Region 2, Atianta, Reactor Construction & Engineering Support Branch. 78/10/02. 2pp. 02729:039.
- --7811090269 IE inspec Rept #50-332/78-05 on 780906-07 during which no items of noncompliance were noted Major areas inspected incl:@nergency diesel generator, ventilating blowsrs, & fuse fellures in startere.
  HUNT:N D.: BRYANT.J.C. Region 2: Atlenta: Reactor Construction & Engineering Support Branch. 78/09/29. 3pp. 02729:341.

### DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

- 7811170110 Forwards analysis by Teledyne Engr Svc re Multiple consecutive cafety relief velve actuation evel.as requested by NRC on 781018.
  EARLY P. J. Power Authority of the State of New York, 78/11/14.
  11pp. 94047:120.
- F. Becurity, medical, emergency & fire protection plans
- 7810270149 Forwards responses to NRC staff concerns/positions re fire protec. Futher responses will be submitted in Nov 1978. EARLY.P.J. Power Authority of the State of New York. 78/10/23. 7pp. 94037:009.
- 7811070126 Forwards responses to EnclW4 of 780922 NRC 1tr re firs protec prog at subj facil. Reply to EnclW3 will be submitted by Nov 1978 ORONBERO, N. L. Power Authority of the State of New York. 78/10/27. 3pp. 94038:305.

- 7812290140 Forwards responses to 780922 NRC ltr Enci 43 re Staff positions on fire protec prog. Responses to Enci42 & M3 of 780922 NRC ltr were submitted to NRC on 781023 & 781027. EARLY,P. J. Power Authority of the State of New York. 78/12/21. 4pp. 94190:274.
- 9. Adjudicatory correspondence
- 7810300275 Forwards request for hearing pursuant to Section 2. 105(d)(1) of the rules of practice of NRC & notice of proposed issuence of emend to facil oper lic issuend 780901 % noticed in 43FR40580-B1(1978).

  CABBAN.V. J. Power Authority of the State of New York. 78/10/02.
  19. 94271:068.
- ~-7810000280 Request for a hearing re eppl for Facil Oper Lic Amand fil 780726. Util would urge relief requested in appl be granted. Appl would eath increase in apent fuel atorage capacity. Amend would revise design features & oper limits. BENNETI.L.R. Power Authority of the State of New York. 78/10/06 29p. 94271:069.
- P. Operating license stegs documents & correspondence
- 7810200204 Notice of Issuance of Amend#38 to Facil Oper Lic#DPR-59. Revises Tech Space re radioactive protection-reduction of squib charge batch asia for surveillance testing & miscellaneous changes to correct errors in present space. IPPLL170,1.A. Operating Reactors Branch 3 (Pre 790623). 78/07/28. 2pp. 94367:087.
- 7810:10156 Responds to 77:209 ltr re subj facil suppression pool temperature transients & monitoring sys. Forwards proposed analysis cases & description of present sys. GRONBERG.M.L. Power Authority of the State of New York. 78/09/29. 18pp. 94069:179.
- 7810120055 Buby reactor protecting supplies were evaluated as requested by NRC 780807 ltr.& interim surveillance measures were effected but PABN believes that continuation of such measures or mod of per supplies is unwarranted. EARLY,P.J. New York, State of: 78/10/06. 3pp. 94471:351.
- 7810170175 Provides addi info re Ahalog Transmitter/Trip Unit Bys as requested by phone 780906. Provides transmittor vendor name & model s. divisional separation criteria: cabinet layout environ & seismic qual & interconnection diagrem. EARLY.P. J. Power Authority of the State of New York. 78/10/10. i2pp. 94236:300.
- 7810180075 Requests oper lic emends be made effective 21 days after date of issuance. Buggests special communications when emend rage immediate or other rapid action.

  EARLY,P, J. Power Authority of the State of New York. 78/10/11.

  Rpp. 74422:046.
- 781017010B Forwards proposed changes to Tech Spec for facii Cycle 3 oper re Reloed #2.8tertup is scheduled for 781113. EARLY,P. J. Power Authority of the State of New York. 78/10/13. 2pp. 94234;278.
- ---78i0170111 Appl for Amend to Oper Lic DPR-59 changing Tech Spec re Raised Sefety/Relief Valve Setpoints for facii reload#2 EARLY, P. J. Power Authority of the State of New York. 78/10/13. Spp. 94234:280.
- --7B10170114 "Raised Safety/Relief Valve Setpoint Reenelysis for Subj Facil for Reload M2". Provides results of reenelysis of the most limiting thermal & pressurisation transients. 7LLL.H. General Electric Co. NEOO-24129-1 S01. 78/09/30. 12pp. 94234:288.
- 7811010111 Responds to 780601 NRC ltr re results of Comm Befety evel to util's proposed reduction of frequency of control rod scram time souveillance requirements. Plans to respond w/further justification by 790301.
  EARLY/P, J. Power Authority of the State of New York. 78/10/24.
  Jpp. 94301:359.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re-progress of Long Term Prog w/sttendance list & aganda(RD-9-A-Marki, Standarde, ) GRIMES.C. Plant Systems Branch (Pre-791030). 78/10/26. 67pp.
- 7811130299 Finds 780901 proposed Tech Spec changes acceptable. LAIMS.G. Plant Sustams Spanch (Pre 791030). 78/11/02. Ppp.

- --7811130301 Bafety Evel of proposed changes to Tech Bosc ra Battery Surveillance Test for subj facil. Finds changes acceptable. a Plant Bystems Branch (Pre 791030). 78/11/02. 1p. 94086:113.
- 78:1270243 Forwards Amend#40.8ER & Notice of issuence of mod to Tech Bacs to proposed use of motor operated valves for containment isolation in HPCI.RCIC.LPCI & the Core Spray Sys & air operated check valve surveillance requirements. IPPCLITO.1.A. Operating Reactors Branch 3 (Pre 790625). 78/11/09. 2pp. 94199: 184.
- --7811270246 Amend#40 to Facil Oper Lic re mod of Append A & 8 Tech Space related to proposed use of motor operated valves & addition of air operated check valve surveillance requirements.

  IPPOLITO\_T\_A\_ Operating Reactors Branch 3 (Pre 790623). 78/11/09.
- --7811270250 SER in support of Amend#40 to oper lic.Concludes that amend does not involve significant hazerds consideration.essures that publ hapith & sefety will not be endangered, complies w/all NRC regs. Operating Reectors Branch 3 (Pre 790625). 78/11/09. App. 94199: 208.
- --7811270253 Notice of Issuance of Amend#40 to Facil Oper Lic#DPR-59. Rev Tach Specs re lack rate testing requirements for sys which penetrate containment boundary & ere connected to reactor coglant preseurs boundary. 1PPOLITO, T. A. Op 20p. 94199: E11. Operating Reactors Branch 3 (Pre 790625). 78/11/09.
- 78/1290298 Responds to 781106 request for info concerning licenses reg parformance evel for Region i plante by NRC Provides details.

  QRIER. 8. N. Region i. Philadelphia. Office of the Director.
  78/11/09. 9pp.
- 7811160069 Provides responses to 780913 NRC request for add1 info re Tach Spec changes & delation of APRM trip in REFUEL mode. EARLY,P.J. Power Authority of the State of New York, 78/11/13. 3pp. 94133: 136.
- 78:2180028 Notice of workshops rs implementation of training & qual requirements contained in Append B of 100FR73. Requests pre-workshop registration of attendees to fertilitate sending out mat. W/snc1 Registration Form & Liet of Locations.

  MILLER.J. R. Assistant Director for Site & Bafeguards (Pre 791030). 78/11/15. 5pp. 94130:345.
- 7812180270 Forwarde Rev#1 "Draft Radiological Effluent Tech Bpsce" for BRR's(NJREG-0473) & "Preparation of Radiological Effluent Tach Specs for Nuc Pwr Plants" (NUREG-0133). GRIMES,B.K. Assistent Director for Engineers & Projects (Pre 790625). 78/11/15. 4pp. 94366:073.
- 78:1280291 Forwards results of Gen Elec Co analysis of rotated bundle loading arror syent. Transmite original Tach Bass regarding Cycle 1 off-gas radiat monitor & new Minimum Critical Pwr Ratio Oper Limit for BxoR fuel. Wratts.

  EARLY.P. J. Power Authority of the State of New York. 78/11/16. 6pp. 94395; 248.
- 7812050336 Forwards Amend#41 to Facil Open Lic#DPR-59 for subj facil. Amend changes Tech Specs as requested in 780901 itr.W/safety Evaluation & Notice of issuance. IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790685). 78/11/16. 2pp. 94409: 012.
- --7812050343 Amend#41 to Facil Oper LicHDPR-59 revising Tach Specs of subj facil re surveillance requirements for discharge testing performed on Station Batteries & on LPCL Motor Operated Valve Pur Supplies to reflect type tasting. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. Epp. 94409:014.
- 94409: 022.
- --7812050351 Notice of Issuance of Amend#41 to Facil Oper Lic#OPR-59, IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 2pp. 94409:024.
- 7811210300 Responds to 780713 request for addi info re proposed changes to Tech Space, Reload R Licensing Submittal for Cycle 3 operation w/47 oversize drawings evaliable in Central Files. EARLY, P. J. Power Authority of the State of New York. 78/11/17. 22pp. 94488: 105.

- 7811300376 Informs PASN that NRC has contracted w/Mountain West Res Inc to indertake a series of post-licensing studies of nuc pur stations. Studies will analyze socioecon impacte which occurred during constr & post-constr periods of each plant.

  DEVOUNG.R. C. Division of Bite Bafety & Environmental Analysis. 78/11/20. 2pp. 94136: 249.
- 7812070197 Notice of saminar on 781208 on new Model Rediciogical Effluent Tech Space for nuc pur plants, Requests advence submission of seminar specific questions. W/encl Seminar Info Sheet Proposed Agenda & maps.

  GRIER, B. H. Region I. Philadelphia, Office of the Director. 78/11/21. Spp. 94375:081.
- 7812080168 Forwards Amend#42 to Oper Lic#DPR-99. Changing Tech Spacs to reflect installation of Analog Transmitter/trip Unit Sys. Bafety Eval & Fed Register Notice. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/22.
- --7812080170 Amend#42 to facil Oper Lic#DPR-59, changing Tech Specs to reflect installation of Analog Trensmitter/Trip Unit Sys. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 5pp. 94106:288.
- --7812080173 Safety Evel Supporting Amend#42 to Facil Oper Lic\*DPR-59. Finds proposed amend will not be inimical to common defents & sacurity. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 3pp. 74106: 293.
- --781208017A Notice of Issuants of Amend#42 to Facil Oper Lic#DPR-59. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/22. %pp. 94106:296.
- 7812110319 Forwards recently issued Amend 43 to License DPR-59, sefety evaluation & notice of issuance. Has not approved APRM mod. BRV mods approved on interim basis susiting final resolution of Mark I Containment long term program. IPPOLITO. T. A. Operating Resectors Branch 3 (Pre 790625). 78/11/22. 3pp. 94204: 159.
- --7812110320 Amend 43 to License DPR-59, revising Tech Speca re-safety relief valve-analog transmitter/trip unit sys to reactor protection sys. & relied mods.

  IPPOLITO, T.A. Operating Reactore Branch 3 (Pre 790625). 78/11/22. 45pp. 94204: 162.
- --7812110322 Salaty Evaluation supporting Amend 43 to License DPR-59.

  \* Operating Resctore Branch 3 (Pre 790628). 78/11/22. 11pp.
- --7812110323 Notice of Issuance of Amend#43 to Operating LicHUPR-59. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 79062B). 78/11/PR. 2pp. 94R04:21B.
- 7812180310 Confirms that meeting will be hald at Region I office. King of Prussia, PA on 781130, to discuss certain requirements of util's radiat protect prog conducted par LicMDPR-59.

  ORIER, 8. H., Region 1. Philadelphia. Office of the Director.
  78/11/24. 1p. 94356: 280.
- 7812110046 Discusse possible dangere of LOCA in containment purglag during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/ancl ANO: e7812080207. IPPOLITOIT. Operating Reactors Branch 3 (Pre 790625). 78/11/89.
- 7812110153 Forwards summary tabulation of control rods failing to fully insart during reactor scram for calendar year 1977.per NRC its of 780829.Rept of drives raplaced during current refueling outage included in Oct 1978 Monthly Rept. EARLY, P. J. Power Authority of the State of New York, 78/12/04. 2pp. 94393;279.
- 7812140175 Forwards Oct 1978 Prog Activity Review listing meetings held to providing task-by-task activity summary for the month. 8080N-L.J. General Electric Co. 78/18/04. 11pp.
- 7812120080 Forwards QE Rept NERDO-Q4129-Q Suppl 2, "Fuel Bundle Logding Erpor Re-analysis for JA Fitzpatric Nucleer Power Plant for Reload E." dtd Nov 1978. EARLY,P.J. Power Authority of the State of New York. 78/12/06. 1p. 94274:115.
- --7812120082 "Fuel Bundle Loading Error Reanalysis for the JA Fitipatr: Nuc Per Plant for Reload 2. Suppl 2. "
  ZULL,L.M., SRUQGE,R.Q. General Electric Co. NEDD-24127-2 SOP.
  78/11/30. 11pp. 94274:116.

- 7812140276 Forwards pages for Amend#43 to Facil Oper Lic DPR-59 that were inadvertently omitted.
  1PPC\_ITG.T A Operating Reactors Branch 3 (Pra 790625). 78/12/06.5pp 03357 319.
- 7812280096 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants Info submitted must be substantizated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS-J O Office of Inspection & Enforcement. Office of the Director 78/12/06 29.0 03555-313.
- 7812190114 Requests immediate temporary waiver of Tech Space re leak for the "A" gain attem isolation valve to allow plant oper at full pur rather than reduced load w/one main steam line out of svc EARLY.P J Power Authority of the State of New Yort. 78/12/12. 309. 94381, 202.
- 7812260189 RO 78-151 on 781215: switches according with the factor of HPCI turbine /stem line area high temp set arroneously due to personnel error. Cautionary werning placed on surveillance procedure to indicate proper conversion table LEDWARO. J D. Power Authority of the State of New York. 78/12/18. 1p. 74159 158
- 78:12:0367 Forwards add: Info re-multiple consecutive mefety/relief value actuation of Merk I conteinment program.
  8080N.L.J. General Electric Co. 78/11/13 3pp.
- 7811210389 Forwards response to NRC's request for edd1 info reinstallation of Analog Transmittar/Trip Unit Sys(ATTUB). Info supports Appl for Amend to 780810 oper Lic suppl by 781010 Info EARLY.P.J. Power Authority of the State of New York. 78/11/16. 6pp. 94485-356.
- 0. Inspection reports, 16 Bulletins & correspondence
- 7811080172 Forwards 1E Inapac Rept#50-333/78-15 on 780828-31 during which no itims of noncoepliance were noted.

  MARTIN.N 9. Region 1. Philadelphia. Sefeguards Branch. 78/09/20.
  2pp. 94379:354
- --7811080177 1E Image: Rept#50-333/78-15 on 780828-31 during which no items of noncompliance were noted. Major error inspected included: ascurity plan & organization, access controls; communications detection aids: Response Procedures. MADEN. N. J. LADUN. R. H. Region 1, Philadelphia, Bafeguarde Branch. 78/09/19. 19, 94399:336.
- 7811050171 Forwards IE Circular#78-17. (See ANG: 7810230221.Doctet 650-133.781013 1 ORIER, B.H. Region i, Philadeiphia, Office of the Director. 78710713 1p. 94489:092.
- 7812010034 Forwards iE Inspec Rept#50-333/78-20 on 780927-29 during which no items of noncompliance were noted. SMITH-0 M. Region 1. Philedelphia. Fuel Facility & Materials Sefety Branch. 78/10/20. 2pp. 94416:070.
- --7812010036 IE Inegec Rept#50-333/78-20 on 780927-29 during which no items of noncompliance were noted Major areas (nepacted incliprog for quality control of analytical mesturement, audit results & effluent control procedures.
  RGITAM.J.J. STORR.J.P. Repton i. Philodelphia. Fuel Facility & Hateriels Sefety Branch. 78/10/19. 8pp. 94416:072.
- 7812060365 Forwards 1E Inspec Rept#50-033/78-22 on 781004-6 during which no items of noncompliance were noted. BRUNNER,E. J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94382:323.
- --7812060367 IE inspec Rept850-333/78-22 on 781004-6 during which no items of noncompliance were noted Major areas inspected inclibet testing & procedures previous inspec findings, plant modes guaps & velves action on IE pubs. H1001N8, J. C., BMITH.T. H., MDNG.H. D. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/27. 10pp. 94382:325
- 7811290195 Forwards IE Circular #78-t8."UL Fire Test. "W/encl AND: 7811150002.

  QRIER.B.H. Region i, Philadelphie, Office of the Director. 78/11/06 ip. 94239:290.
- 7812270433 Forwards IE Inspec Rept#50-333/78-18 on 780918-22 & 1003-06 & 1011-13 during which no items of noncompliance were noted. CARLBON.R. T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/13. 2pp. 94015:339.

- --7812270457 IE Inspec Rept#50-333/78-18 on 780918-22 % 1003-05 % 1011-13 during which no items on noncompliance were noted. Major areas inspected incl:insvc inspec activities & activities assoc w/removal of feedwater spargers.

  MCBREARTY, R. A. EBNETER, B. D. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 78/11/08. 10pp. 74015; 241.
- 78:2183034 Forwards IE Bulletine78-:2A. Suppl to 1E Bulletin 78-12. Wencl AND 78:1300035. GRIER. B.H. Region I. Philadelphia. Office of the Director. 78/11/24. ip. 94:133:019
- R. Periodic operating reports & related correspondence
- 7810130128 Forwards Monthly Open Rept for Sept 1978. LEONARD J. D. Power Authority of the State of New York. 78/10/05. 19. 03555: 270.
- --7810130132 Monthly Open Rept for Bept 1978. ZUFELT, E. Power Authority of the State of New York. 78/10/05. 4pp. 03555:271.
- 78:1140121 Forwards Monthly Open Rept for Oct 1978.

  LECHARD. J. D. Power Authority of the State of New York. 78/11/10.

  1p. 94425:211.
- --7911140123 Monthly Oper Rept for Oct 1979. ZUFELT, E. Power Authority of the State of New York. 78/11/10. 11pp. 94425:212.
- 7812150267 Forwards Monthly Open Rept for Nov 1978. LEDMARD.J. D. Power Authority of the State of New York. 78/12/09. 1p. 94210:062.
- --7812150274 Monthly Oper Rept for Nov 1978. ZUFELT.E. Power Authority of the State of New York. 78/12/09. 18bo.
- B. Reportable occurrences. LERs & related correspondence
- 7810100022 Forwards LERB78-079/04L-0. LEDMARD.J. D. Power Authority of the State of New York. 78/10/00. ip. 94033:008
- --7810100026 LER#78-079/04L-0 on 780914: An apparent excessive colute release from Makeup Mater Treatment Maste Neutralizer tanks to Circulating water Dischargs Tunnel was detected while performing Aug 78 24-hour complete sample enelysis. CHLDS: M. V. Power Authority of the State of New York. 78/10/03. 3pp. 94033:009.
- 7810120045 Forwards LER#78-080/03L-0. LECHARD, J. D. Power Authority of the State of New York. 78/10/06: 1s. 9432:324.
- --7810120046 LERM7B-GB0/03L-0 on 780714:Restlient seals on valva covers (bonnets) & both ends of oper shafts in pressure suppression chamber were not subjected to "Type B" local leek rate tests as required by Tech Spec Append A. 4.7. A. 2. d. 2. GHILDB-M. V. Power Authority of the State of New York, 78/10/06 Ppp. 94332:325.
- 7810120073 Farwards LER#78-081/03L-0. LEDMARD.J. D. Power Authority of the Stata of New York, 78/10/04. 1p. 9472:326.
- --7810120079 LERW78-081/03L-O on 780915:circuit breaker for RHR pump 10-P 10-P-3C would not "charge." Ceused by bending of control pur fuse halder causing pump circuit breaker not to make contact.
  CHILDS.W. V. Power Authority of the State of Naw York. 78/10/06. Rpp. 94472:327.
- 7810230186 Forwards LERW78-075/03L-1. LECNARD, J. D. Power Authority of the State of New York. 78/10/18. 1p. 94193:152.
- --7810230189 LER#78-075/03L-1 on 780902: during surveillance test F-BT-30. normally closed inboard core apray injection value 14-MV-128 failed to open electrically k made 1 core apray sys inopen; due to high differential pressure. CHLDS.H.V. Power Authority of the State of New York. 78/10/18. 2pp. 94195: 153.
- 7810230263 Forwards LERW78-082/03L-0. LEOMARD.J. O. Power Authority of the State of New York. 78/10/18. 19. 9471:151.

- --7810230265 LER#78-082/03L-0 on 780920: in refuel shutdown.pressure suppression pool(tarus)leval increased to 0.8 inches above Tach Specs level.due to waterleaking past seat of safety relief valve.

  CHILDS.M.V. Power Authority of the State of New York. 78/10/18. 2pp. 94271: 152.
- 7810230308 Forwards LER#78-056/03L-1.

  \* Power Authority of the State of New York. 78/10/19. 1p. 94166:344.
- --7810230310 LER#78-056/03L-1 on 780722: Core spray sys outboard isolation valva would not close due to fact that limitorque oper shaft key was sheared. Key was replaced CHILDS, M. V. Power Authority of the State of New York. 78/10/18 2pp. 94166: 345.
- 7810240122 Forwards LER#78-084/03L-0.
  LEGNARD. J. D. Fower Authority of the State of New York. 76/10/19.
- --7810240126 LERW78-084/OOL on 780924 During refueling shutdown & discharge of "B" floor drain sample tank the Liquid Redweste Effluent Monitor sample pump would not deliver adequate flow to monitor, due to clogging.

  \* Fower Authority of the Steta of New York. 78/10/19. Zpp.
- 7810240133 Forwards LERN78-083/03L-0. LEONARD, J. D. Power Authority of the State of New York. 78/10/19.
- --7810240139 LER#78-083/03L-0 on 780923: during refusiing & meint shutdown the logic pur for the "B"LPCI subsys was desnergized.dus to operator error.

  CHILDS.W. V. Power Authority of the State of New York. 78/10/19.
  200.
- 7811070244 Forwards LERR78-085/04L-0. LEDWARD.J.D. Power Authority of the State of New York. 78/11/08. 19. 94039:196.
- ---7811070248 LER878-085/04L-0 on 781006:Rept level per Tach Spec Appand B Paragreph 2.3.8.5. was exceeded for third querter of calendar year.July high release rate caused by steam leats & fuel pin clad perforation. Corrective actions: refueling & repair. Power Authority of the State of New York. 78/11/01. 2pp. 94039:197.
- 7811070318 Forwards LERW78-087/04T-0. LEONARD.J.D. Power Authority of the State of New York. 78/11/01, 1p. 94041:165.
- --78:1070323 LER#78-087/04T-0 on 78:10:18:Environ Radiological Monitoring Bample of perlphyton samples pCi/gm(Wat)does not meet sub; facil Tach Spac Appand B.Paragraph 5. 5. 2. 6 CHILOS, W. V. Power Authority of the State of New York. 78/11/01. 2pp. 9404:166.
- 7811140238 Forwards LERM78-086/03L-0. LEONARD.J.D. Power Authority of the State of New York. 78/11/10. 1p. 94400:093.
- --78:1140248 LER 78-086/03L-0; on 78:016. during refuel shutdown two election conduits passing through safety related area fire barrier found to be improperly seeled in violation of Tech Spec.

  Both penetrations immediately sealed.

  CHILDS,M.V. Power Authority of the State of New York. 78/11/10.

  2pp. 94400:094.
- 7811210414 Forwards LER878-088/04L-0. LEDNARD.J.D. Power Authority of the State of New York. 78/11/17. 19. 94483:128.
- --7811210422 LERW78-088/04L-0 on 781024; excess solute release from Makeup Mater Treatment Maste Neutralizer Tanks to Circulating Mater Discharge Tunnel detected, Caused by unsound sampling & method of determining concentrations & dissolved solids. CHILDS,N.V. Power Authority of the State of New York. 78/11/17. 3pp. 94483:129.
- 7812040156 Forwards LERE78-089/03L-0. LEDMARD.J.D. Power Authority of the State of New York. 78/11/28. 1p. 9456:123.
- --7812040157 LER878-089/03L-0 on 781101: during refueling & meint shutdown it was found that surveillance test had not been performed for combustion ionization products smote detectors installed in diesel fire pump room on 780310, due to oversight. CHILDE.N.V. Power Authority of the State of New York. 78/11/28. 2pp. 74456:124.

- 7812070174 Forwards LER#78-090/03L-0. LEDNARD.J D. Power Authority of the State of New York. 78/12/05. 1p. 94275-020.
- --7812070178 LERW78-090/03t-0 on 781106 supply to part of safety relate hore stations in Reactor Bldg was shut off making stations inoparable Caused by intentional isolation to permit installation of add post indicator valva.

  CHILDS.H V Power Authority of the State of New York. 78/12/05.

  1p 94375:021.
- 781220099 Forwards LERW78-085/04X-1. LEONARD,J.D. Power Authority of the State of New York. 78/19/18. 1p. 94243.349.
- --7812220100 LERA78-085/04X-1 on 781006: 3rd quarter raisess of Haiogeni particulates greater than Tech Space. Caused by atom lacke the fuel pin clad performence.

  CHILOS.W. V. Power Authority of the State of New York. 78/12/16.

  2pp. 94343: 350.
- 7812290246 R0R78-097/01X-0: during surveillance of Texp switches, instruwere found set above Tech Spec limit due to personnel using wrong conversion table. LEONARD, J. D. Power Authority of the State of New York. 78/12/18. 1p. 94191:282.
- 7812270242 Forwards LERW78~094/03L~0. LEONARD.J D. Power Authority of the State of New York. 78/12/20 1p. 94017: 152,
- --7812270250 LER678-094/03L-0 on 781122:during ehutdown & surveillance test.a number of bettery calls were found u/specific gravity &/or individual cell voltege variationsthigh or ioul greeter than ellowed by Tast acceptance criteria.

  CHILDS.H. V. Power Authority of the State of New York. 78/12/20.

  2209. 94017:153.
- DOCKET 50-334 BEAVER VALLEY POHER STATION, UNIT 1
  F. Becurity, medical, amergency & fire protection plans
- 7812120227 Forwards results of 781030-781103 site visit & NRC staff positions concarning subj fatil fire protec prog. Requests comments & implementation sched. SCH-ENCER. A. Operating Reactors Branch i (Pre 790625). 78/12/01. 30pp. 94277:142.
- 78:2140:09 Forwards add1 info requested in 78:07:18 NRC itr ra Fire Protec prog. Subj covered incl:combined fire & security emergency personnel failure analysis, suppl fire dept. & in-house audit plan.

  HOOLEVER, E. J. Duquesne Light Co. 78/12/11. 164pp. 94:19:163
- 7812190144 Forwards Figure : Inadvertently left out of 781211 Fire Protec Prog. WDOLEVER.E. J. Duqueene Light Co. 78/19/15. 2pp. 94381:034.
- O. Advisory Committee on Reactor Safeguards raports & correspondence
- 7812060424 Nutification of 780907-09 open meeting of ACRB (changes fro 780823) in Washington, DC to discuse failure of subj facil mein transformer. FFTF, & avaluation of SWAN-1400. HDYLE, J. C. Office of the Becretary of the Commission. 78/08/25. 5pp. 94383:045.
- 7812070094 Responds to 780828 request for clarification rs ACR8 recommends tions made between 770101 k 0930. Forwards clarifying info.
  CABA E.O. Office of Nuclear Reactor Regulation, Director. 78/11/28 44pp. 94274-022.
- P. Operating license etaga documents & correspondence
- 7812030004 Forwards Licenses Performance Eval Questions for subj fection response to 771123 request. Feets it is possible that develop the statistical methodology for such swall may not justify the effort. Qualitative eval may be as good. Urgas impair test. ORIER, 8. H. Region 1, Philadelphia. Office of the Director. 77/12/13. 12pp.
- 7810110144 Forwards proposed Tech Spece for Overpressure Protec per NR 780828 request. No fee encl should be considered as part of the original submittal which predates fee schedule requirements of 100FR170, 22a.

  DUNN.C.N. Duquesne Light Co. 78/10/04. 12pp. 94044: 280.

- 78i0190072 Encl \$12,300 voucher for license fee omitted in 780922 appl for change to Append A Tech Specs.

  DUNK C N Duqueene Light Co. 78/10/81. ip. 94421.263.
- 7810200100 Forwards Proposed Teth Specs 3.1.2 3 & 3.4.1.4 correcting submittal of 781004.which Pailed to include required action statements & surveillance requirements. DUNNGC.N Duquesne Light Co. 78/10/16. 4pp. 94367-347.
- 7810200047 Forwards copy of Chlorina Trailing-Out Study Results. MODRE. 0 H Duquesne Light Co. 78/10/17. 1p. 94411:330.
- --7810200030 Submits results of chloring trailing-out study. Concludes that trailing-out beyond 2 hours per day does occur, but that permit limitations are not acceeded. Chlorination level is rag to prevent bio-fouling of condenser.

  MCALLISTER.R. J. Duqueens Light Co. 78/07/20. 178p. 94411.331.
- 78i0270195 Enruards requested info on tabulation of mass & energy ralease data by Westinghouse. Provides proposed Tech Space rev 100 gal incresses in refueiling water storage tanks DUNN C.N. Duquesne Light Co 78/10/24 Spp 94094: 242.
- 78110-20107 Requests amend to Facil Oper Lice25 to accommodate new Bleamline Break Protec Sys which is sched for installation in Spring of 1979. Forwards proposed Tach Spec & check for \$12.300 for class IV Amend.
  DWAN-C.N. Duquesne Light Co. 78/10/27 423pp. 02722:001.
- 7811080259 Forwards request for additinfo to feeduater pipe vibration for transmittal to applicant.

  LAINAS.0. Plant Systems Branch (Pro 791030). 78/10/31. 2pp. 94405. 150.
- 78i1220239 Provides limited approval of P642 seel mati for hydraulic anubbers for up to 2 normal refueling outages or within months under spacified conditions t defines ineger schad for those seels,w/FE80 Rept on seel mati dtd 780817 SCM-ENCER, A Operating Reactors Branch i (Pre 790625) 78/i1/09. 12pp. 94381:318
- 7811280385 Forwards request for add1 info re Nuc Sys Corp Rapt#1-78-012 transmitted by ltr on 780317 re feeder line vibration monitoring prog results for subj facil Raquests response w/in 30 days.

  SCHENCER.A. Operating Reactors Branch 1 (Pra 790625). 78/11/13.

  3pp. 74397 292
- 78ii24004i Ack recaipt of 7807i7 transmittal of "Potantlai Consequances of 011 Pipeline Failure. "Requests payment of Class III fee of \$4000.
  MiLLER.H. O. License Fee Nanagement Branch. 78/11/15. 2pp. 94457: 242.
- 7812150141 Notice of workshops re implementation of training & qual requirements contained in Appand B of 10CFR73. Requests pre-workshop registration of attendese to facilitate sending out mati. W/ancl Registration Form & List of Locations. MILLER, J R Assistant Director for Bita & Bafeguards (Pra 791030), 78/11/15. 5pp.
- 7812190028 Forwards Revel "Draft Radiological Effluent Tach Specs" for PMR's(NVREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NVREG-0133), ORIMES, N. Assistant Dirattor for Engineers & Projects (Pra 790625), 78/11/15 6pp. 94214:322.
- 78:2070143 Notice of seminar on 78:208 on new Model Rediological Effluent Tech Space for nuc pur plants Requests advance submission of seminar specific quastions. W/encl Saminar Info Sheet-Proposed Agenda & maps.
  GRIER.S. H. Region 1, Philadelphia, Office of the Director. 78/11/21. 8pp. 94375:268.
- 78:2080143 Notification of masting w/Duqueene Light Co on 78:205 in Betheeda to discuss containment lask test w/containment liner weld channels unvented. WIGOINTON, D. Operating Reactors Branch 1 (Pre 790625), 78/11/28. 2pp. 94:04:325.
- 7812130066 Discusses possible dangers of LOCA in conteinment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/enci ANO: 7812080207
  BCHENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. 6pp. 94210:168.
- 7812060162 Responds to NRC 781115 1tr & forwards \$4000 class III fee. MODRS 0.W. Duquesos Light Co. 78/11/30. 1p. 94371:257.

- 7812280103 Emphasizes importance of submitting accurate & complete it to NRC by licensees & applicants info submitted must be substantiated by data & calculations Licensea must notify NRC of any inaccuracies or enforcement action will result. DAVIG. J O Director of inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 03555.319
- 7812050013 Requests views of Regional Directors on Licenses performs eval of subj facils. Forwards questions to be answered by 771209.

  THOSONINGO, N. Division of Reactor Construction Inspection 77/11/
  - THOMASURO, H Division of Reactor Construction Inspection. 77/11/ 2pp.
- 78:2190:01 Forwards review comments on Suppl#2 to "Soil Study-Cetago 1 Struc: of suby facil. "Applicant Falls to provide basic info re sampla preparation & test proceduras. Requests study of liquefaction potential & stability analysis by util.

  STEPP-J. C. Geosciences Branch. 78/12/13. 4pp. 94376:301.
- 7812210215 Forwards addi info re Ractor Vessel Overpressura Protecto follow up 781123 request that sys be detegorized as interim sye. Request interim sys be upgraded as valves now qual to selsmid design requirements OUNN.C.N. Duquesne Light Co. 78/12/14. lp. 94279.i14.
- 78:2220071 Forwards add1 info re lic emend appl covering aval of low family family for the following family for the family family for the family family family for the family fam
- 7812260214 Forwards proposed amend to Oper LiceDPR-66 for subj facili Basis thange to Append "B" of Tech Space Section 3.1.2 ra documentation concerning them raiseses. DUNN.C.N. Duquesns Light Co. 78/12/14. 2pp. 94160:187.
- ---7812260216 Proposed amend to Oper Lic for sub; facil. Reviews Amend by seeking change to Appl "B" of Tach Bpecs section 3.1.2 re documentation concarning chem releases. a Duquesne Light Co. 78/12/14. 2pp. 94160:189.
- Q. Inspection reports, IE Builstins & correspondence
- 7810300292 iE Inspec Rept#30-334/78-21 on 780822-25 \$ 0829-31 during which no items of noncompliance were nated. Major ereas inspected included: naw high density spent fuel racks & addy current inspec of steem generator tubes.

  PASNO.A.N. Region 1. Philadelphia, Office of the Director.
  78/09/13 9pp. 94035:180.
- 7810300117 Forwards IE Inspec ReptM50-334/78-21 on 780822-25 & 0829-during which no items of noncompliance were noted.
  CARLSDN.R.T. Region is Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/13. 2pp. 94035:178.
- 7810180215 Forwards 1E Inspec Rept #50-334/78-19 on 780808 & Notice of Violation. MARTIN.M.Q. Region 1, Philadelphia, Bafaguerds Branch. 78/08/31. 2pp. 94311:357
- --7810180217 IE inspac Rept #50-334/78-19 on 780808-11 during which temb of noncompliants were noted; sacurity organization testing & waint.

  BALLEY.R.J. Region 1, Philadelphia, Sefeguerde Branch. 78/08/5 1p. 9431: 339.
- 7810160240 Forwards IE Bulletins78-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days. List of IE Bulletins issued in 1978. (See ANO 87810040253)
  GRIER, 8. N. Region 1. Philadalphis. Diffice of the Director. 78/09/29. App. 94004:001.
- 7811130271 Forwards IE Inspec Rept#50-334/78-23 on 780909 during whit no Itams of noncompliance were noted.

  BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94011:218.
- --7811130275 iE Inspec Rept#50-334/78-23 on 780906 during which no of noncompilance were noted. Hejor araes inspected included; corrective actions re environ qual for aiac components. RAYMORD, M. J. Region 1. Philadelphia, Office of the Director. 78/09/06. Bpp. 94011: 220.
- 7811130280 Forwards IE Inspec Rept#50-334/78-25 on 780919-21 during which no items of noncompliance were noted. CARLSON.R.T. Region 1. Philadelphia. Resector Construction & Engineering Support Branch. 78/10/05. 2pp. 94011:240.

## **DOCKETED ITEMS**

- --7811130285 IE Inepet Rept#50-334/78-25 on 780919-21 during which no Items of noncompliance were noted Major areas inspected included: insvc inspec activities, including procedure review & witness of insvc examinations WALTON.Q.A. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 78/09/29 3pp. 94011:242.
- 7811060198 Forwards 1E Circular#78-17. (See ANO: 7810230221, Docket #50-133,781013. ) REDEATH H. Region 1. Philadelphie, Office of the Director. 78/10/13. | Ip. 94489;189.
- 7810270185 Act receipt of 780926 ltr informing NRC of steps teten to correct violetions noted during Inspec MSO-334778-20 BRUNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Brench. 78/10/16 1p. 94057:093.
- --7810270189 Responds to 780830 NRC ltr re violetion noted in Inspector #50-334/78-20. Corrective actions: station edministrative directive will be rev to ensure control re vendor procedures Vendor will be notified.

  DUNN-C.N Duqueene Light Co. 78/09/26 3pp. 94037:094.
- --7810270192 Forwards IE Inspec Rept #50-334/78-20 & Notice of Violetion BRUNNER, E.J. Region 1, Philedelphia, Reactor Operations Nuclear Bupport Branch. 78/08/30. 2pp. 94057:097.
- --7810270194 Notice of Violation from inspec on 780808-11.

   Region 1, Philadelphia, Resctor Operations Nuclear Support Branch. 78/08/29, 1p. 94057:099.
- --7810270196 IE Inspec Rept #50-334/78-20 on 780808-11 during which 2 items of noncompliance were noted; failure to have approved procedures for conduct of surveillance test & failure to reg periodic reviews of maint procedures
  JCHNSON,D., KEIMIG,R.R. Region 1, Philedelphie, Reactor Operations
  Nucleer Support Branch, 78/08/29, 9pp. 94037:100.
- 7812110232 Forwards IE Inspec Rept#50-334/78-28 on 781013 during which HAITH, O.H. Region i, Philadelphia, Fuel Facility & Materiels Safety Branch. 78/11/01. 2pp. 94338:030.
- --7812110235 IE Inspec Rept#50-334/78-28 on 781013 during which no items of noncompliance were nated. Mejor arees inspected incl: results of effluent semples split between licensee & NRC Region I.

  KOTTAN-J. J. Region 1, Philadelphie, Fuel Facility & Materiels
  Bafety Brench. 78/11/01. App. 94338:032.
- 7612080080 Forwards IE Inspec Rept#50-334/78-27 on 781016-18 during which no items of noncomplience were noted.

  BRUNNER.E.J. Region 1. Philadelphie, Reactor Operations Nuclear Bupport Brench. 78/11/02. 2pp. 94108;013.
- --7812080083 IE Inspec Rept#50-334/78-27 on 781016-18 during which no items of noncompliance were noted. Major eress inspected incl:conteinment integrated leak rets test procedure & local leak rate test.

  CAPHTON.D.L., HIGGINS.J.C. Region 1, Philedelphie, Reactor

  Operations Nuclear Support Branch. 78/10/31. 7pp. 94108:015.
- 7811300241 Ack receipt of 781016 1tr informing NRC of steps taken to Correct violations noted during Inspec#50-334/78-22.
  BMITH, O. H. Region 1, Philadelphia, Fuel Fecility & Materials Safety Branch. 78/11/03. 1p. 94074:355.
- --7811300243 Responds to 780926 NRC ltr re violations noted in inspec Rept#50-334/78-22 Corrective actions; repositioned barrier & signs at entry to high rediet area. DUNN.C. N. Duquesne Light Co. 78/10/16. 3pp. 94074:336.
- --7811300246 Forwards IE Insper Rept#50-334/78-22 on 780830-0901 & Notice of Violation. GROCKER, M. W. Region 1, Philadelphie, Fuel Facility & Meteriels Befety Branch. 78/09/26. 3pp. 94074:359.
- ~~7811300248 Notice of Violetion from inspec on 780830-0901.

   Region 1, Philadelphia, Fuel Facility & Materiels Safety Branch, 78/09/26. 1p. 94074:362.
- --7811300250 IE Inspec Rept#50-334/78-22 on 780830-0901 during which i item of noncompliance was noted failure to control high radiat arest IAW Tach Specs. MHITE.V. R. Region I. Philadelphie, Office of the Director. 76/09/26. 10pp. 94075:001.

- 7812080144 Forwards IE Inapec Rept#50-334/76-26 on 781002-06 & 78101 12 & Notice of Violation,
  ORIER.B H Region 1. Philadelphia, Office of the Director.
  78/11/03. 3pp 94104: 327.
- --7812080145 Notice of Violation from inspec on 781002-06 & 781010-1 GRIER B. H. Region i, Philadelphia, Office of the Director. 78/11/03. ip 94104: 330.
- --7812080147 IE Inspec Rept#50-334/78-26 on 781002-05 & 781010-12 du which i item of noncompliance was noted failure to comply w/equip control procedures. KIBTER, H., MARKONEKI, R. S., BECKMAN, D. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 78/11/03 18pp. 94104. 331.
- 7811290212 Forwards IE Circular #78-18. "UL Fire Test. "Wenci ANO: 7811150002. GRIER, B. H. Region to Philadelphia, Défice of the Oirector. 78/11/06. 1p. 94237: 320.
- 7812270149 Forwards IE Inspec Rept#50-334/78-24 on 780912-19 during which no items of noncompliance were noted

  BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear

  Bupport Brench. 78/11/13 2pp 94161-152
- --7812270163 IE Inspec Rept#50-334/78-24 on 780912-15 during which n items of noncompliance were noted Major areas inspected incl:plant oper.conformance w/Tech Spec L888.LCO's & GL. review of LER's & outage maint activities RAYMOND,N.J., KEIMIQ.R.R. Region 1, Philedelphia, Reactor Operations Nuclear Support Branch. 78/11/09 17pp. 94161:134
- 7812290211 Forwards IE Inspec Rept#50-334/78-29 on 781013-15 & 27 during which no items of noncompliance were noted.

  CARLBON, R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 78/11/15. 2pp. 74170:350.
- --7812270220 IE Inspec Rept#50-334/78-27 on 781023-25 & 27 during whino items of noncompliance were noted Najor areas inspected inclinigh density spent fuel racks & Insvc Inspec date. FABAND.A.N. UALTON.G.A. Region 1, Philedelphia, Reactor Construction & Engineering Support Branch 78/11/15. 5pp. 94100-1957 94190: 352
- 7812150136 Forwards IE Bulletin#78-12A. suppl to 1E Bullstin#78-12 W/encl AND: 7811300055. GRIER, 8, H. Region I, Philadelphia, Office of the Director. 78/11/74. 1p. 94212:184.
- R. Periodic operating reports & related correspondence
- 7810160114 Forwards Monthly Open Rept Par Sept 1978
  DUNN C.N Duquesne Light Co. 78/10/10, ip. 94007:121.
- --7810160116 Monthly Oper Rept for Sept 1978 HITKOWSKY, F. P. Duqueene Light Co. 78/10/04 Spg. 94007:122.
- 7811030169 Forwards copies of EPA Quarterly Rept for Sept 1978.4s submitted to EPA & PA Dept of Environ Resources.
  MODRE-O. H. Duquesna Light Co. 78/10/27. 39pp. 02724:028.
- 7811160109 Forwards Monthly Open Rapt for Oct 1978.

  DUNN C.N. Duquesne Light Co. 78/11/11. 1p. 94135:152.
- --7811160111 Monthly Open Rept for Oct 1978. WITHOMSKY, F. P. Duquesne Light Co. 78/11/03. 5pp. 94135:153.
- 7812110128 Forwards Monthly Oper Rept for Nov 1978.

  DUNK C.N. Duquegne Light Co. 78/12/06. Ip. 94339:334.
- --7812110132 Monthly Oper Rept for Nov 1978, WITKOWSKY, F. P. Duqueane Light Co. 78/12/01. 4pp. 94339:335.
- 8. Reportable occurrences, LERs & related correspondence
- 7810100030 Forwards LERM78-048/03L-0. WERLING, J. A. Duquesne Light Co. 78/09/25. 2pp. 94033:034.
- --7810100034 LER#78-048/03L-0 on 780221: during rev test data on 7801 noted that final satigaint valve entered on 780221 for RCS Loop 18 Coid Leg Loop 8top Valve relief line flow interlock was 124 GPM caused by improper sation.

  WERLING J.A. Duquesna Light Co. 78/09/23. 1p. 94033:036.

- 7Bi0100004 LER#7B-031/01T-0 on 7B0912: During survaillance testing of #1 Deisel Generator, output breater failed to close using control switch #1 Generator operable. Test panel instelled to detect abnormal oper.

  WERLING, J. A. Duquesne Light Co. 7B/09/26 2pp.
- 7811030164 RO 78-053/OIP: on 7B1026 during review of stresscalrulations for safety injection piping inside containment errors in piping stress analysis were discovered. Causad by error in hand calculating method.

  WERLING, J. A. Duquesne Light Co. 78/10/27. 1p. 02724:019.
- 7811130218 Forwards LER078-054/03L-0. WERLING, J. A. Duquesne Light Co. 78/11/04 2pp. 03554-058
- --7811130220 LERM7B-054/O3L-O on 781003 During surveillance test on containment high pressure distable the setpoint was 2.3 lbs instead of 2.0 Causad by faulty ELCO connector on loop signal comperator. Comparator was replaced.

  WERLING J.A. Duquesne Light Co. 78/11/04. ip. 03354:060.
- 78:1170214 Reportable Occurence#78-058/04P on 78:105-08:during plant shutdown, reactor plant river water & turbine plant river water header chlorination lavels exceeded ellowable value, due to abnormal lineup.
  WERLING. J. A. Duquesne Light Co. 78/11/09. 2pp. 94:135:120.
- 7811170219 Bubmits interim rspt re previous LERN78-53/017: Purther investigation into apparent errors in stress analysis for aefeky injection piping inside containment reveals original rept will follow.

  WERLING, J. A. Duquesne Light Co. 78/11/09. 2pp. 94136: 126.
- 7811170172 Forwards LER#78-055/03L-0. WERLING, J. A. Duquasne Light Co. 78/11/13 2pp. 94048: 125.
- --7811170178 LERM78-055/03L-0 on 781013: channel N41 rate trip set at 11.6% in 2.2 seconds rather than limit of 5.5% in 2 seconds. Caused by inadvertent readjustment or improper calibr of the setpoint.

  WERLING-J.A. Duqueses Light Co. 78/11/13, 1p. 94048:127.
- 7811170221 Forwards LERB78-036/03L-0.
  WERLING, J. A. Dugusens Light Co. 78/11/13. 2pp. 94048: 299.
- ---7811170234 LERM78-056/03L-0 on 781011: vent sihaust monitor RM-VB-101 removed from eve for grab samples. Sample not taken for one day due to personnel arror. (For ltr sea ANOM7811170172.)
  HERLING. J. A. Duquesne Light Co. 78711/13. 1p 94048:301.

- 7812120143 Forwards LER 78-053/01T-0. HERLING, J. A. Duquasna Light Co. 78/12/06. 2pp. 94276:260.
- --7812120148 LER 78-053/01T-0 on 781026, error noted in original pi strsss analysis for on steam infection lins Error caused by misopplication of simplified analysis technique employed during original design. Corrective action implemented. WERLING. J. A. Duquesne Light Co. 78/12/06. 3pp. 94276:262.
- 78:2180180 Forwards LER#78-057/04L-0. WERLING.J. A Duquasne Light Co. 78/12/08. 2pp. 94359:344.
- --7812180184 LERW78-057/04L-0 on 781110. records review showed gase waste monitorWRM-CH-1088 was inoper from 780210-13 & nd results of greb samples could be located, due to failure by Radcon parsonnel to obtain the samples.
  WRRLING, J. A. Duquesne Light Co. 78/12/08. Ip. 94359:346.
- 7812290222 Forwards LERB78-058/04T-0. WERLING.J. A. Duquesne Light Co. 78/12/19. 2pp. 94191:193.
- --7812290226 LERW78-058/04T-0 on 781108: chlorination was performs: river water headers during plant abutdown & free chlorine residual exceeded allowable 0.8ppm.due to personnel error. WERLING, J. A. Duquesne Light Co. 78/12/19. 2pp. 94191: 195.
- 7812290216 Forwards LERM78-059/03L-0.LERM78-060/03L-0 LERM78-061/03L-0. LERM78-061/03L-0. LERM78-061/03L-0. Puquesne Light Co. 78/12/22. 2pp. 94191:181.
- --7812290223 LERM78-059/03L-0 on 781108:during performance of Typ Containment Paretration Leek Test.12 valves were found to be leeking at a rate greater than maximum messurable on leek rate monitor caused by excassive valve leekegs. -MERLING. J. A. Duquesna Light Co. 78/12/22 3pp. 94191:183.
- --7812290227 LERe78-060/03L-0 on 770718: during review of surveilltest records it was determined that monthly test for 18 RPRW Pump was not parformed by 770718 as req. Gaussed by Improper athed of surveillance test. WERLING. J. A. Duquesne Light Co. 78/12/22. 1p. 94191:186.
- --7812270235 LERM78-061/03L-0 on 781012: during performance of constoletion check valve surveillance test iA RCP seal injection apring-loeded check velvs was found to have an opening prassure of 11.5 PBID Caused by sicase force. WERLING, J. A. Duquesns Light Co. 78/12/22. 1p. 94191:187.

ş

# PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed Items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principa document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principa Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGOR
ABBOTT. W. S.	7812010042*	50-471	- a	ANDERSON T. M.	7811210234	50-275	A	ANTIO, H. A.	7811280473	50-29
ABBOTT. H. S.	7811210140	50-471	Ā	ANDERSON D.	7812210204*	50-213	R	APADAKIB, C. N.	7B11090156*	50-329
ABRAMBON L.	78122700324	50-320	ä	ANDERSON, C. J.	7811240137	50-322	ö	ARCHER, J. F.		
ASSTON, C. O.	7810300249*	50-389	B	ANDERBON C. J.		50-322	ŏ		7811220237	50-466
					7811240161*			ARCHER, J. F.	7812040316	50-466
ABBTON. C. C.	7811280425	50-400	A	ANDERBON D.	7812130009	50-70	0	ARCHITZEL, R. E.	7B11300363*	50-184
ACHTERBERG. J.	7810270231*	50-249	8	ANDERBON T. M.	7811160127	50-572	B	ARCHITZELIR. E.	7810160082*	50-293
ACHTERBERG. J.	7811160115*	50-237	8	ANDERBON T. M.	7811240164	50-445	A	ARNOLD, T. Q.	7810310135=	50-348
ACHTERBERO, J.	7811210181*	50-237	8	ANDERBON, T. M.	7811240165	50-445	A	ARON, R.	7811210325*	50-29
ACHTERBERG. J.	7812270271+	50-237	8	ANDERSON T. M.	7812080039	50-272	P	ARTHUR, J. E.	7812280191	50-485
ADAMB. H. E.	7810110119	30-235	R	ANDERBON P. L.	7812200217*	50~309	8	ARTIGAB.R.	7812010249*	50-447
ADAMS. J.	7611020251#	50~187	þ	ANDERBON P. L.	7812200254*	30-309	8	ASHENDEN, J.	7810110290+	50-338
ADAMB, W. E.	7811140147	50-255	R	ANDERBON, J. M.	7812190140	50-545	A	ABPERGER, R. Q.	7810230373	50-341
ADAMSON. R. W.	7812070066	50-394	ë	ANDERBON C. J.	7812290005	20-355	A-	ASPERGER, R. G.	7811080063	50-341
ADAMB. H. E.	7812110122	50-255	R	ANDERSON, T. M.	7812290136	50-480	Ä	ABPERGER, R. O.	7811080282	50-341
ADAMB. D. S.	7812270075*	50-485	ò	ANDERSON T. V.	7812270197*	50-106	P	ASHELL, D. L.	78110100282	20-385
			_							
ADAMS, D. S.	7812270076*	50-485	٥	ANDOONINI.Q.C.	7810170136	50-293	P	ABWELL, D. L.	7810110113	20-385
ADAMS, D. S.	7812270081	30-4B5	0	ANDOGNINI Q. C.	7810180113	50-293	P	ABHELL, D. L.	7811170086*	50-3B2
AINGER. K. A.	7811240129*	50-295	8	ANDDONINI, Q. C.	7810270105	50-293	P	ABWELL, D. L.	7811300233	50-382
ALBERT, W. G.	7811010037 <b>*</b>	50-361	G.	ANDOONINI, Q. C.	7811070185	50-293	P	ABHELL D. L.	7812110230	50-382
ALBERY, W. Q.	7811270199*	50-522	Q.	ANDOONINI.G.C.	7811140132	50-293	K	ABHELL, D. L.	7812050182	50~382
ALBERT. M. G.	7812210153*	50-460	Q.	ANDDONINI. Q. C.	7811150168	50-293	F	ABHELL, D. L.	7812110155	50-382
ALBERT, W O.	7812280246*	50-361	Q.	ANDOONINI, Q. Q.	7812080185	50-293	Q	ASWELL, D. L.	7812120115	50-382
ALBIE. K.	7810120084*	50-344	9	ANDDONINI. O. C.	7811270163	50-293	.P	ASWELL, D. L.	7812170072	50-3B2
ALDEN, W.M.	7810230167+	50-277	R	ANDCIONINI. O. C.	7812060223	50-293	P	ASWELL, D L.	7812200133	50-382
ALDEN, W. M.	7811150116	50-171	W	ANDOGNINI. Q. C.	7812110166	50-293	P	ASHELL, D. L.	7812200133	50-382
						** **	_			
ALDEN, W. M.	7811140144*	50-277	R	ANDOONINI. O. C.	7812210259	50-293	p	ASWELL, D. L.	7812200248	20-385
ALDEN, W. M.	78111600B6#	50-277	R	ANDDONINI. O. C.	7812260218	50-273	K.	ABWELL, D. L.	7812200250#	50~382
ALDEN, W. M.	7812220064*	50-277	R	ANDOGNINI. Q. C.	7812260223*	50-293	ĸ	ABWELL, D. L.	7B12290175	50-362
ALDERBON C. E.	7810310074*	50-259	G	ANDREWB.C. W.	7810170194	50-250	P	AUBRE, R.P.	7810250184	50-312
ALINGER.K. A.	7810170246*	50-295	8	ANDREWS.R. L.	7910110113	50-285	8	AVERBACH, M.	7810300281*	98E~QC
ALLAN, J. M.	7810240018	50-219	Ρ	ANDREWS.R. L.	7810110100	50-285	8	AUT IO, H. A.	7810180009	50-27
ALLEN, J.	7812060220*	50-338	н	ANDREWS.R.L.	7810100010	50-285	8	AUTIO, H. A.	7810180015	50-29
ALLEN, D.R.	7811070315	50-592	M	ANDREWS.R. L.	7810110112	50-285	8	AUTIO, H. A.	7810240152	50-29
ALLEN, D. R.	7811160036	50-572	М	ANDREWS R. L.	7810180159	50-285	ä	AUTIO, H. A.	7810240136	50-29
ALLEN, R.	7811210392*	50-10	8	ANDREWS R. L.	7811060200	50-285	8	AUTIO, H. A.	7811090145	50-27
							•			·
ALLIBON, D. P.	7810260219	50-275	A	ANDREWS.R. L.	7811060204*	50-285	9	AUTIO. H. A.	7811170200	50-29
ALLIBON.D.P.	7810260099	50-275	A	ANDREWS.R. L.	7811210368	50-295	8	AUT IO, H. A.	7811170211	20-54
ALLISON, D. P.	7811010381	50-275	A	ANDREWS, R. L.	7812010238	50-285	8	AUTIO, H. A.	7811300378	50~29
ALLIBON, D. P.	7811010382	50-275	0	ANDREWS.A.L.	7812050173	50-285	8	AUT 10: H. A.	7811210317	50-29
ALLIBON, D. P.	7811020029	50-275	A	ANDREWB.R.	7812200272*	50-285	8	AUTIO, H. A.	7811280284	50-27
ALLIBON.D.	7811080003	50-275	A	ANDREWS.R.L.	7812200264	50-285	В	AUT IO, H. A.	7811280326	50-27
ALLIEON. D. P.	7B11270400	50-275	Ë	ANDREWS . R. L.	7812200265	50-285	8	AUT IO, H. A.	7B11280314	50-27
ALLIBON, D. P.	7811300079	50-275		ANDREWS R. L.	7812200227	50-285	B	AUT 10, H. A.	7811290198	50-29
			À							
ALL.180N, D. P.	7812130389	50-275	Ą	ANDREWS R. L.	7812270213	50-285	B	AXELRAD, H.	7B10200003	50-344
ALLIBONID. P.	7812150033	50-275	۸	ANDREWS R. L.	7812270219	50-285	8	AXELRAD, M.	7810140019	50-344
ANCARROW M. R.	7812260014	50-247	P	ANDREWBIR. L.	7812270258	50-285	8	AXELRADIM.	7810270386	50-344
ANDERBON 8. L.	7812080142+	50-306	P	ANDREWS.R. L.	7812270332	50-285	8	AXELRAD, M.	7B11020041	50-376
ANDERBON S. L.	7811140131*	80-266	P	ANDREWS.R. L.	7812290225	50-285	8	AXELRAD, M.	7812040028	50-344
ANDERBON B. L.	78111401334	50-266	P	ANO, W. P.	7812050150*	50-327	a	AXELRAD. M.	78120400314	50-344
ANDERBON P. L.	7811030140+	50-309	8	ANO, W. P.	7812060035*	50-375	G.	AXELRAD, M.	7812180438	50-344
ANDERSON P. L.	7811030135*	50-309	в	ANO, H. P.	7812280080*	50-424	Q.	AXELRAD, M.	7812270485	50-344
ANDERSON P. L.	7811220217*		8	ANO. W. P.	7812290040*	50-390	ā	AXEL BON, W. L.	7812010070*	50-344
		50-309			7812210048*	50-413	ă	AXELSON, H. L.		
ANDERSON L. H.	7811210254	50-466	9	ANG. W. P.		50-438	a a		7811290397*	50-123
ANDERSON C. J.	7811130258	50-322	A	ANO, W. P.	7812290070*		uj P	AXELSON, H. L.	7812280229+	50-456
ANDERSON P. L.	7811220202#	50-309	8	ANGELO, J.	7811270104	50~295	۲	AYCOCK, M. B.	7812130044*	50-566

Ayerb. T. Q. Bachrach. S. L. Backus. R. A. Backus. R. A. Backus. R. A.	7812040207+ 781102007+ 7811020077 7810170060 7812260087 7812260092+	50-454 50-516 50-443 50-443 50-443	X 0 0 0	BANCROFT, M. H. BANCROFT, M. H. BANCB, H. R. BANCB, H. R. BANCB, H. R.	7812010337 7812180077 7810110242* 7810110291* 7810100043	50-493 50-493 50-324 50-324 50-261	0 0 0 8	BARTH, C. A BARTON, A. R. BARTON, A. R. BARTON, A. R. BARTON, A. R.	7812290272 7811020351 7811130204 7812070022* 7812110307	50-400 50-364 50-364 50-364 50-364
BACON, J. L. BACON, J. L. BACON, J. L. BACON, J. L. BADGER, C. H.	7810270148 7812050142 7812050213 7812190095 7810230104	50-329 50-329 50-329 50-329 50-437	K A A C	BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R.	7810100029 7810100049 7810130177 7810130152 7810130189	50-324 50-325 50-324 50-325 50-325	8 8 8	Baskin K. P. Baskir E. Baskin K. P. Baskin K. P. Baskin K. P.	7810170103 7810200240 7810180083 7810230155 7810230268	50-361 50-466 50-361 50-206 50-206
Baer R. L Baer R. Baer R. L Baer R. L Baer R. L	7812160428 7810110003 7811010183 7811100169 7811150015	50-70 50-369 50-369 50-369 50-437	P A A A	BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKS, H. R. BANKS, H. R.	7810130121 7810130138 7810160147 7810230020* 7810230143	50-324 50-325 50-261 50-324	я в я с	Babkin, K.P. Babkin, K.P. Babkin, K.P. Babkir, E. Baskin, K.P.	7810310132 7811220169* 7811060086 7811200118 7811220168	50~205 50~361 50~205 50~456 50~361
Baer, R. L. Baer, R. L. Baer, R. L. Baer, R. L. Baer, R. L.	7811150030 7811150035 7811160194 7812040042 7812070015	50-369 50-437 50-349 50-369 50-369	A A Q	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	7810230193 7810230195* 7810270215 7811170238* 7810310143	50-324 50-324 50-261 50-324 50-261	8 8 0 8	Babkin, K.P. Babkin, K.P. Babkin, K.P. Babkin, E. Babkin, K.P.	7811280219 7811300209 7811280259 7812120220 7812040193	50-206 50-361 50-206 50-466 50-361
Baer, R. L. Baer, R. L. Baer, R. L. Bacchi, Q. Bailey, R. J.	7812110214 7812110243 7812150208 7810240037 7810190114	50-352 50-367 50-395 50-70 50-57	H A A P Q	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	7610310232 7610310139 7610310210 7610310217 7611070186	50-324 50-324 50-261 50-324 50-261	8 8 8 8 8	BABKIN, K. P. BABKIN, K. P. BABT, S. A. BABT, E. A. BABT, E. A.	7812120101 7812890113 7812110306 7812140359 7812180267	50-206 50-361 50-305 50-266 50-305
BAILEY, R. J. BAIR, O. BAIR, G. BAIR, G. BAIR, G.	7810180217+ 7810170145+ 7811070198+ 7811140141+ 7811160101+	50-334 50-344 50-344 50-344 50-344	Q R R R	Bankb, H. R. Bankb, H. R. Bankb, H. R. Bankb, H. R. Bankb, H. R.	7811070174 781116008B 7811160119 7811160132 7811160091	50-325 50-325 50-261 50-325 50-324	9 9 R 8 R	BABT, B. A. BATCH, B. BATEMAN, H. H. BATEG, R. W. BATES, R. W.	7812070452 7812050206+ 7811300387+ 7811280300+ 7812120113+	50-266 50-346 50-410 50-336 50-336
Dair, Q. Q. Baird, J. B. Baird, J. E. Bajwa, B. Baker, E. J.	7812120153* 7811050008* 7811270107* 7810300019 7810240005*	50-344 50-268 50-344 50-549 50-437	R G G A	Banke, H. R. Banke, H. R. Banke, H. R. Banke, H. R. Banke, H. R.	7812140158 7812140163 7811170209 7811120183 7812010232	50-325 50-261 50-325 50-325 50-261	8 8 8 R	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, Y. L.	7810100079* 7810110132* 7810230262* 7810200112* 7810200118*	50-280 50-281 50-281 50-281
BAKER, K.R. BAKER, R. BAKER, K.R. BAKER, D.A. BALAUGH, R. G.	7810270398* 7811240184 7812130045* 7812130220 7812130231	50-315 50-389 50-315 50-305 50-498	Q Q Q	BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R.	7812130251* 7812130294* 7812070214 7812070165 7812070175	50-261 50-324 50-325 50-325 50-324	0 8 8	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	7811040213+ 7811070240+ 7811070215+ 7811070217+ 7811070217+	50-281 50-281 50-280 50-280
BALDWIN, W. A.	7810300062 7810190193 7810230084 7812110278 7812210512	50-70 50-70 50-70 50-70 50-70	• • •	Banke, H. R. Banke, H. R. Banke, H. R. Banke, H. R. Banke, H. R.	7812080127 7812150330 7812150348 7812210181 7812210187	50-325 50-324 50-261 60-325 50-325	8 R R B	BAUCOM, T. L.	7811090210* 7811170185* 7811210266* 7811280292* 7811280238*	50-280 50-280 50-281 50-281 50-280
BALLARD,R.L. BALLARD,R.L. BALLARD,R.L. BALLARD,R.L. BALLARD,R.L.	7810230057 7810130024 7810180223 7810310243* 7811030182	50-247 50-498 50-498 50-244 50-286	P C P P	Bankb, H. R. Bankb, H. R. Bankb, H. R. Banta, F. L. Bardeb, C. F.	7812210218 7812270257 7812270298 7812270068 7811090096	50-325 50-261 50-324 50-338 50-259	9 8 8	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	7812040233+ 7812050209+ 7812050211+ 7812050214+ 7812140126+	50-280 50-280 50-280 50-280 50-280
BALLARD,R.L. BALLARD,R.L. BALLARD,R.L. BALLARD,R.L. BALLARD,R.L.	7812260039* 7811070098 7811080186 7811080235 7811130289	50-247 50-510 50-548 50-510 50-373	P D A A D	Bardes, C. R. Barker, J. L. Barker, J. L. Barker, J. L. Barker, H. A.	7812180151* 7811010022* 7811010022* 7811300268* 7812290124	50-213 50-10 50-10 50-10 50-546	J a a A	BAUCOM, T. L.	7812140129* 7812140131* 7812140229* 7812140234* 7812200207*	30-260 50-260 50-261 50-261 50-260
BALLARDIR.L. BALLARDIR.L. BALLARDIR.L. BALLARDIR.L. BALLARDIR.L.	7811130292* 7811130428 7811140001 7811200017 7812010331	50-373 50-373 50-373 50-373 50-368	D D D A	BARLOW, Q. BARNETT, E. W. BARNETT, E. W. BARR, R. W. BARRETT, P. A.	7812040348 7810270322 7812180258 7811070285 7811010057*	50-70 50-498 50-445 50-341 50-358	0 0 M 0 0	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUM, E. A BAUM, E. A	7812270281+ 7812270294+ 7812270324+ 7810110142 7810180139	50-281 50-280 50-280 50-338 50-338
BALLARD, R. L.	7812130030 7812040379 7812070049 7812070275 7812110040	50~546 50~454 50~448 50~341 50~275	A A C H	BARRETT, P. A. BARRETT, J. E. BARRETT, L. SARRETT, P. A. BARRETT, J. E.	7811020169* 7810160074* 7810180187 7812170155* 7811280271*	50-341 50-302 50-220 50-463 50-302	O R P Q R	BAUM, E. A. BAUMACK, H. H. BAUMACK, H. H. BAUMACK, H. H.	7810270112 7811020304 7810260028+ 7811080246+ 7811150194+	50-404 50-338 50-220 50-219 50-220
BALLARD, R. L. BALLARD, R. L. BALLARD, R. L. SALLARD, R. L. BALLARD, R. L.	7812140102 7812140115 7812140134 7812140172 7812140253	50-502 50-502 50-502 50-502 50-502	A A A A	BARRETT, P. A. BARRETT, J. E. BARRETT, J. E. BARRUS. C. BARTH, C. A.	7812070108* 7811200187* 7812200179* 7812050138* 7810240019	50-456 50-302 50-302 50-298 50-488	G R R	BAUNACK, H. H. BAUNACK, H. H. BAXLEY, E. X. BAXLEY, E. X. BAXLEY, B. X.	781129D339* 7812110310* 7810180039* 7810180122* 7810310162*	50-336 50-245 50-366 50-366 50-321
BALLARD, R. L.	7812140269 7812120027 7812120034+ 7812120035+ 7812140236	50-502 50-443 50-445 50-445 50-395	<b>A</b>	BARTH, C.A. BARTH, C.A. BARTH, C.A. BARTH, C.A. BARTH, C.A.	7810270289 7811130213 7811220047 7811210007 7811210029	50-580 50-400 50-400 50-491 50-400	9 9 9 F	BAXLEY, B. X. BAXLEY, B. X. BAXLEY, B. X. BAXLEY, B. X. BAXLEY, B. X.	7810310171* 7811060140* 7811280220* 7811280293* 7812180186*	50-321 50-321 50-366 50-366 50-366
BALLARD, R. L. BALLARD, R. L. BALLARD, R. L. BALLINGER, P. BALQUOH, R. C.	7812190085 7812210100 7812210107* 7812290201* 7810270297	50-346 50-324 50-324 50-298 50-498	P P B M	BARTH, C. A.	7811210093 7811210116 7811270052 7811290007 7811290362	50-498 50-580 50-489 50-488	0 0 0 0	BAXLEY, B. X. BAXTER, T. A. BAXTER, T. A. BAXTER, T. A. BAXTER, T. A.	78121802020 7810140022 7810160091 7810190210 7811010080	50-366 50-464 50-464 50-484 50-484
BALBLEY, J. R. BALTZ, J. BAN, J. BANCROFT, M. H. BANCROFT, M. H.	7810270134 7810100634 7811980282 781999040# 7811970069	50-568 50-346 50-329 50-358 50-483	A B C A G	BARTH. C. A. BARTH. C. A. BARTH. C. A. BARTH. C. A. BARTH. C. A.	7612130224 7812130188 7612120218 7612270389 7812270452	50-448 50-580 50-400 50-244 50-264	0 0	BAXTER, T. A. BAXTER, R. O. BAXTER, R. C. BAYNE, J. P. BAYNE, J. P.	7810270005 7812180147 7812180144 78111001584 7812010085#	50-484 50-332 50-332 50-286 50-286

AUTHOR	ACCESSION NUMBER	CATEDURY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
BAYNE, J. P. BAYNE, J. P.	7811100145 7811100138*	50-286 G	BERKOW, H. N. BERRY, Q. T.	7812210260* 7810110085	50-397 Q 50-286 P	SLACK, R. L. BLACK, R. L.	7810140073	20-255
BAYNE, J. P. BAYNE, J. P.	7810250135# 7810100098	50-286 Q	BERBON, B. A.	7810110018	50-266 0	BLACK, R. L.	7810230233 7811020315	50-522 50-354
BAYNE, J. P.	7810120058	50-286 8 50-286 8	BERBON. B. A. BERBON. B. A.	7810110023 7810110072	50-266 0 50-266 0	BLACK, R. L. BLACK, R. L.	7811150083 7811130448	50-522 50-341
AYNE, J. P. AYNE, J. P.	7810130167 7811100129#	50-286 R 50-286 g	BERSON, B. A.	7810260222	30-265 G	BLACK. R. L.	7811150113	50-341
AYNE, J.P.	7811090086*	50-286 0	BERBON: B. A. BERBON: B. A.	7811150089 7812040344	50-266 G	BLACK, R. L. BLACK, R. L.	7812040342 7812040345	50-522
AYNE, J. P. AYNE, J. P.	7812010076 <b>*</b> 7811060210	30-286 8	BERSON, B. A. BERSON, B. A.	7812080163 7812080169	30-380 g 30-346 g	BLACK, R.L. BLACK, R.L.	7812040345 7812080162 7812140353	50-522 50-341
AYNE J.P.	7811070253	50-286 P	BERBON, B A.	7812080172	50-548 0	BLACK, R. L.	7812140353	50-341
YNE, J. P. YNE, J. P.	7811140104 7811140247	50-286 R 50-286 B	BERBON. B. A. BERBON. B. A.	7812080173 7812130224	50-266 0 50-448 0	BLACK.R.L. BLACK.R.L.	7812270370	50-522
YNE, J. P. YNE, J. P.	7811220189 7812150237	50-286 B 50-286 R	BEBECKER, K. H. BEBECKER, K. H.	7811100130# 781210363#	30-249 Q 50-259 Q	BLACH, R. L. BLAKE, J.	7812270366 7812270114 7610130101+	50-320 50-320 50-413
YNE, J.P.	7812260130	50-286 Q	BEBECKER, K. H.	7811300013+	50-335 0	BLAKE, J. J.	7611200034*	50-324
YNE, J. P. YNE, J. P.	7812220095 7812290170	50-286 B 50-286 P	BEST, J. BETTENHAUSEN, L.	7811070052 7812010282*	50-220 Q 50-320 Q	BLAKE, J. BLAKE, J. J.	7611240033*	50-250
ACH, A.B. ATTY, Q. P.	7812210179* 7810200160	50-445 G 50-302 F	BETTENHAUSEN, L.	7812110310+ 7812130317+	50-320 0 50-245 0 50-269 0	BLAKE, J. J. BLANSETT, V.	7810270272* 7812210064* 7810110079	50-324 50-413
CHHOEFER. C.	7810300053	50-409 Q	BEVIS. R. M.	7811020262	50-466 H	BLASINGAME, J. H.	7810110079 7811100062*	50-186 . 50-387 8
CHHOEFER.C. CHHOEFER.C.	7811010432 7811070272	50~387 0 50~498 0	BEYER. B. Biden. M. D.	7810310346#	50-346 8	BLAU, H. L.	7810300218	20-355 0
CHHOEFER.C.	7811060261 7811100166	50-387 Q 50-498 Q	BIELAWSKI, A. P. BIELAWSKI, A. P.	7812060234* 7812120223 7812130122	50-295 Q 50-295 Q 50-237 Q	BLOCK, S. BLOCK, J. D. BLOOM, J. A.	7812010373 7812270050 7810250228	50-244 F 50-247 0
CHHOEFER. C.	7811220099	50-341 Q	BIELAHBKI.A.P.	7812130122	50-237 G	BLUM, S.	7810260225* 7811080060	50-275 A
CHHOEFER, C. CHHOEFER, C.	7811300355 7811290085	50-358 Q 50-498 Q	BIELAWSKI, A. P. BIERBAUM Q. A.	7812270010	50-556 0	BLUM, S. BLUMBERG, N. J.	7811290350	50-369 (
CHHOEFER. C.	7812050087 7811300410	50-478 G 50-407 G	BIERBAUM O. A. BIRKEL, R. A.	78:0180125* 78:1150149* 78:1200168*	50-133 R 50-133 R 50-437 A	BLUME, M. B. BLUME, M. B.	7812270449+ 7810230124 7811130427	50-220 ( 50-445 r 50-498 h
CHIDEFER. C.	7812070251	50-341 0	BIRKEL, R. A.	7811200258*	50-437 A	BLUME. M. B.	7812080216	30-498 N
CHHDEFER.C. CHHDEFER.C.	7819130125 7819270043	50-341 0 50-387 0	BIRKEL, R. A. BIRKEL, R. A.	7811200435* 7811200430*	50-437 A 50-437 A	BLUME, M. B. BLUME, M. B.	7812210372 7812210242	50-445 h 50-498 h
CHHOEFER, C. CKMAN, D.	7812290281 7810260028#	50-341 T 50-220 G	BIRKEL, R. A. BIRKEL, R. A.	7811200428* 7811200174*	50-437 A 50-437 A	BLUME, M. B. SOHN, R. J.	7812270091 7810130139	50-49B 8 50-367 A
KMANID, A. KMANID,	7811080097*	50-286 Q	BIRKEL R. A.	78112002134	50-437 A	SOHN, R. J.	7811080224	50-367 F
HAN.D.	7811090017# 781110014B#	50-247 G 50-311 G	BIRKEL.R.A. BIRKEL.R.A.	7811200186* 7811200177*	50-437 A 50-437 A	BOHN, R. J. BOHN, R. J.	7810160136 7811030144	50-367 A 50-367
KMAN•D. VAR•L.F.	7812080147* 7812030170*	50-334 G 50-278 S	BIRKEL.R.A. BIRKEL.R.A.	7811200359+ 7811200298+	30-437 A 50-437 A	BOHN, R. J. BOHN, R. J.	7810270091 7811030147	50-376 F 50-367 A
NAR.L.F. NER.L.F.	7812050145# 7812200274#	50-298 B 50-298 B	BIRKEL, R. A. BIRKEL, R. A.	7811200295* 7811200246*	50~437 A 50~437 A	BOHN, R. J. BOHN, R. J.	7811140208	50-347 4
ROBIAN. P.	7810310286*	50-568 A	BIRKEL R. A.	7B10110019	50-369 F	BOHN, R. J.	7811170106 7811210360	30-367 A
ROBIAN, P. ELER, T.	7811210382+	50-568 A 50-344 8	BIRKEL, R. A. BIRKEL, R. A.	7810250195 7810260096	50-369 A 50-369 A	BOHN, R. J. BOHN, R. J.	7812050183 7812110119	50-367 A 50-367 R
LER, T. HAIN, L. E.	7810100063* 7811020177*	50-346 B 50-223 G	BIRKEL•R.A. Birkel•R.A.	7811030032 7811220041	50-369 A 50-437 A	BOHN, R. J. BOLAND, E. P.	7812210174 7812010046+	50-367 R 50-471 G
N, J. D. LMAN, T. P.	7812270102#	50-275 F	BIRKEL, R. A.	7812010148	50-369 0	BOLLNOW, D. 1. BOLLNOW, D. 1.	78101101224	50-255 F
MAN+T. P.	7810180158* 7810110192*	50-315 8 50-315 8	BIRKEL R. A. BIRKLE A J.	7812130283 7810160197*	50-369 0 50-329 0	BOLLNOW, D. I.	7811140148* 7812110125*	50-235 F
LHAN, T. P.	7810250117* 7811240172*	50-315 8 50-315 8	BISHOP, T. W. BISHOP, T. W.	7811070179* 7810190093*	50-397 Q 50-397 Q	BONGHI, L. BONNER, J. F.	7812080184 7812130008+	50-361 G 50-133 J
ILMAN: T. P.	7811240173*	50-315 8	BISHOP, T. W.	7811270126*	50-70 G	BOOK, H. E.	7810300Q1B	50-206 C
ILMAN, T. P. ILMAN, T. P.	7811240174* 7811300181*	50-315 £ 50-316 £	#188ETT.P.H. #198ETT.P.H.	7810180191* 7811010099*	50-20 0 50-277 0	BOOK, H. E.	7810300020* 7811060007	50-288 C
ILMAN, T. P. ILMAN, T. P.	7811300199* 7812080048*	50-316 8 50-316 B	BIXEL.D.A.	7812040178* 7810170217	50-255 Q 50-155 B	BOOK, H. E.	7811060008* 7811270102	50-298 G 50-344 G
LMAN, T. P.	7812080087* 7812120167*	50-315 8 50-315 8	BIXEL, D. A. BIXEL, D. A.	7810110104 7811240170	50-155 B 50-155 Q	800K+H, E.	7811270088 7811270093*	20-315 C
ILMAN, T. P.	7612270286*	50-316 8	BIXELID.A.	7811240231	50-155 8	900K. H. E.	7812140072+	50-70
.anger, J. L. .isle, g. a,	7812140086* 7812150063*	50-10 B 50-261 G	BIXEL, D. A. BIXEL, D. A.	7810130171 7810160097	50-155 B 50-155 F	BOOK, H. E.	7812140070 7812150180	50-70 C 50-206 G
L. H. H L. H. A	7811200276*	50-437 A 50-344 B	BIXEL, D. A.	7810250045 7811210349	50-155 P 50-155 B	800K, H, E. 300K, H, E.	7611270097 • 7812190194	50-312 0 50-133 0
L. L. K	7811220060#	50-344 B 50-549 T	BIXEL, D. A.	7810250096	50-155 8	BORDENICK, 9. M.	7810140004	50-516
L, N. L. More, C. 1.	7812140324 7810270097*	50-344 0 50-217 R	BIXEL.D.A. BIXEL,D.A.	7810310130 7811010143	50-155 B 50-155 P	BORDENICA, B. M. BORDENICK, B. H.	7810240209 7810200247	50-516 G
ARDYA V. ARDYA V.	7812040244 7812060327	50-368 P 50-369 F	BIXEL, D. A. BIXEL, D. A.	7811020212 7811030134	50-155 P 50-155 B	BORDENICK B. M. BORDENICK B. M.	7811040108 7811040040	50-516 0 50-582 0
ER. B. B.	7612120121*	50-295 B	BIXEL. D. A.	7811060084	50-155 P	BORDENICK, B. M.	7811060132	50-514
DER. B. B. EDICT. R. A.	7908080684 <b>*</b> 7810120133	50-295 B 50-382 F	BIXEL, D. A. BIXEL, D. A.	7811280032 7811140146	50-155 0 50-155 B	BORDENICK, B. M. BORDENICK, B. M.	7811140003 7811140019	50-443 G 50-582 F
EDICT, R. A.	7811220294 7812130323	50-382 A 50-382 F	BIXELID.A. BIXELID.A.	7811150138 7812080192	50-155 P 50-155 G	BORDENICK, B. M. BORDENICK, B. M.	7811100182 7811200060	50-592 C
WETT, L. R.	78103002804	50-333 9	BIXEL, D. A.	7811270094	50-155 P	SORDENICK, S. M.	7811200057	50-220
TON, L. P.	7811080230 7811220102	50-48B A 50-70 H	BIXEL, D. A. BIXEL, D. A.	7812040220 7812040237	50-155 P 50-155 B	BORDENICK, B. H. BORDENICK, B. H.	7811210101 7812050292	50-516 G
LETTO J. A.	7811100045 7811100046	50-361 0 50-361 0	BIXEL, D. A. BIXEL, D. A.	7812070215 7812050224	50-155 P 50-155 P	Bordenick, B. H. Bordenick, B. M.	7811290386 7812050033	50-582 G
LETTO J. A.	7811100045	20-307 6	BIXEL. D. A.	7812110171	50-155 B	BOADENICK, B. M.	7812040261	50-397 C
LETTO J. A.	7811100048 7811200103	50-206 0 50-389 M	BIXEL, D. A. BIXEL, D. A.	7812120182 7812220074	50-155 P 50-155 B 50-155 P	BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M.	7812110221 7812130005 7812270132	50-516 G 50-514 G 50-329 G
			40 0 U 600	7812260212	50-135 P	HURLINI DAJE M.	7812270172	
EROER, M. O. EROER, M. O. EROER, M. O.	7812040260 7812040032	50-389 M 50-346 M	BIXEL, D. A. BIXEL, D. A.	7812270180	50-155 Q 50-155 P	BORER, P. J. BORER, P. J.	7810170299* 7811160114*	50-298 P

AUTHOR	ACCEBSION RSEMUN	BUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	NUMBER ACCESSION	BUB- CATE
BORER, P J.	7812130160+	50-298	R	DOYD, R. B.	7810270026	50-454	Ą	BRENNER.L	7811010323	50-5
BORES, R. J. BORES, R. J.	7811040247# 7811100181#	50-3 50-286	0	BOYD, R. S. BOYD, R. S	7811030172 7811080330	50~545 50-397	A	BRENNER.L. BRENNER.L.	78110101 <b>93</b> 7811140003	50-3 50-4
ECRES.R.J.	7812180038*	50-3	0	BOYO, R. S.	7811140259	50-410	A	BRENNER.L.	78120500B2	50-4 50-4
BORGMANN E. A	7810110157	50-358	A	BOYD, R B	7811140265*	50-410	A	ORENNER.L.	7812130081	
BORGMANN E. A BORGMANN E. A	7811210170 7811070370	50-358 50-358	a n	BOYD, D. C. BOYD, R. S	7812060236# 7811130397	50-295 50-445	Q A	BRENNER.L. BRENNER.L.	7812140123 7812160305	50-3 50-4
BORGMANN, E. A	7611010169	50-358	K	DOYD, R. S.	7811200099	50-490	A	BRENNER.L.	7812140177	50-4- 50-3
BORGMANN, E. A BORGMANN, E. A	781101 <b>0171</b> 7811090069	50-358 50-358	K K	90YD, R. S. 90YD, R. S.	78112900034 7811290006 <del>4</del>	50~572 50~572	A	BRIGOS.L.E BRIGOS.L	7811300306* 7812010276*	50-3
BORGMANN, E. A.	7811220008	90-358	a	BOYD, R. B.	7812060099	50-027	A	ERICHT. C D	7812110266	50-4
BORGMANN E. A BORGMANN E. A.	7812060016	50-358	a	SOYD, R. S	7811290275	50-443	A	BRIGHT, Q. D. BRIGHT, Q. D.	7812150096	20-5
BORGMANN E. A.	7612070119 7612070147	50-358 50-358	E K	80YO+R. B. 80YO+R. B.	7811290278 7811300276	50-440 50-458	A	BRIGHT. Q. O.	7812130064 7812200344	50-2
BORGMANN E. A.	7812200228	50-358	0	SOYD, R. E.	7811300315	50-424	A	BRIGHT, O. D.	7812200338	50-2
BOROMANN E. A. BOROMANN E. A.	7812210163	50-359		80YO-R. S.	7811300319	50-413	A	BRIGHT, Q. O.	7812220014	50-2 50-2
BOROMANN, E. A.	7812150306 7812190146	50-358 50-358	K A	80YD+R. S. 80YD+R. S.	7911300323 7811300326	50-491 50-410	A	BRIGHT, Q. O. Bright, Q. O.	7812270002 781227027 <i>9</i>	50-2
BOROMANN E. A. BOROMANN E. A.	7812170084 7812200214	50-358 50-358	K	80YD, R. S. ODYD, R. S.	7811300331 7811300340	50-546 50-367	A	BRIGHT, O. O. BRIGHT, O. O.	7812270280 7812290282	50-2 50-2
BOROMANN E. A	7612270191	50-358	К	80YD. R. S	7811300372	50-363	A	BRIGHT, O. O.	7812290283	50-2
BOROHANN E. A.	7612270305	50-358	A	8DYO, R. S.	7811290395	50-367	A	BROEHL, D. J.	7810110161	50-3
BORKNIGHT.JA. BOROS.J.J.	7610270322 7611100094*	50-479 50-213	0	90YD• R. 8 80YO• R. 8	7811300011* 7811290371	50-329 50-387	A	BROEHL, D. J. Broehl, D. J.	7810120026 7810200015	50-3 50-3
BOSNACKIR J.	7811200365+	50-437	A	80YO, R. S	7812040015	50-373	A	BROEHL. D. J.	7810130147	50-3
BOUKNIGHT, J A	7810310179*	50-498	H	80YO. R. B.	7612050099	50-352	A	BROEHL, D. J.	7811020103	50-3
BOUKNIGHT, J. A. BOUKNIGHT, J. A.	7810140017 7811080021	50-498 50-498	M M	90YO.R. 8 90YO.R. B.	7812050279 7811270262	50-389 50-352	A	BROEHL: D. J. BROEHL: D. J.	7810240091 7811080228	50-3 50-3
BOUKNIGHT, J. A. BOUKNIGHT, J. A.	7611130239 7811130404	50-389 50-398	H	80YO: R. S. BOYO: R. S.	7812010379 7812050006	50-382 50-404	A	BROEHL: D. J. BROEHL: D. J.	7811100114 7811070112	50-3 50-3
BOUKNI OHT. J. A.	7811130431	50-389	н	gpyD, R. S.	7812050104	50-492	A	BROEHL D J.	7812110006	50-3
BOUKNIGHT, J. A.	7612160259	50-445	M	80YO, R. S.	7812050114	50-460	A	BROEHL, O J.	7611280324	50-3
BOURNTOHT, J. A. BOURNTA, A.	7812270410 7810130026	50-389 50-373	H A	80Y0, R. B. 80Y0, R. B.	7612070061 7812120005	50-354 50-412	A	BROOKS, A. B. BROOKS, E. H.	7811200092* 7812140277*	50-3
BOURNIA.A.	7810120106	50-344	H	BOYD. R. B.	7812120046	50-423	A	BROOKE, B. P.	7812110116#	50-4
DOURNIA. A.	7812140025	50-373	A	DOYD. R. S.	7812120179	50-461	٨	BROWN, D.	7811210374*	50-3
BOURNIA, A. BOURNIA, A.	7812200026 7812220101	50-373 50-373	A	DOYD: R. B. BOYD: R. B.	7812120201 7812030369	50-400 50-438	A	BROWN. D. BROWN. D.	7810120078* 7810310330*	50-3 50-3
BOUTWELL R. L. BOUTWELL R. L.	7810180009* 7811280290*	50-29 50-29	8	80YD, R. S. 80YO, R. S.	7812060017 7812080223	50-49B 50-322	A	BROWN, Q. D. BROWNLEE, V. L.	7811210121* 7811080220*	50-3 50-3
BOUTHELL R. L.										
BOWERS E. B.	7811290203 <b>*</b> 7810190126	50~29 50-275	8	80YD•R. B. 80YD•R. B.	7812080246 7812120019	30-410 50-397	A	BROWN, C. BROWN, M. S	7810310168* 7810100064#	50-1 50-3
DOWERS, E. S. DOWERS, E. S.	7810230182 7810190160	50-275 50-397	0	80YO, R. B. 80YD, R. B	781211003 <b>1</b> 7812060306	50-566 50-518	A	BROWN M. S. BROWN M. S.	7810100068* 7810180032*	50-3 50-3
DOWERS, E. S.	7810250003	20-355	ō	80YD, R. S	7812070103	30-554	L	BROWN, B. A.	7810230264	50-3
SOWERS, E. S.	7810250193	50-48B	9	EQYO, R. B	7812080208	50-327	Ą	BROWN. B. C.	7810170109	90-4
OOWERB, E. S. BOWERB, E. S.	7811010121 7811060021	50-397 50-275	O A	80YD, R. S 80YD, R. S	7812070257 7812140013	50-387 50-368	A P	BROWN, B. C. BROWN, B. C.	7810230307 7810200054	50-4 50-3
BOWERB, E. S. BOWERB, E. S.	7811070023 7811080073	50-322 50-488	0	80YO.R. 8 80YO.R. 8	7812140014* 7812120030*	50-369 50-445	P A	BROWN, S. C. BROWN, S. C.	7810230299 7812010321	50-3 50-3
BOWERS, E. S.										
BOWERS. E. S.	7811070356 7811170007	50-397 50-275	0	BDYD, R. B. BDYD, R. B	7812120032+ 7812140248	50-445 50-368	A P	BROWN+ 9. C. BROWNLEE, V. L.	7810240140 7811300170#	50-3 50-4
BOHERB. E. S. BOHERB. E. S.	7811200427 7811210016	50-488 50-580	0	BOYD, R. B. BOYD, R. B.	7812130017 7812140275*	50-59\$ 50-275	A G	BROWN, Q. O. BROWN, C. H.	7812130336# 7812040046#	50-3 50-2
BOWERB, E. S.	7811210026	50-44B	ō	BOYO, R. B.	7812140278*	50-275	Ģ	BROWN, B. C.	7811060102	50-3
BOWERB, E. S.	7811200042	50-275	0	BOYD. R. O.	7812140279*	50-275	Q.	BROWNLEE, V. L.	7812270372*	50-3
BOWERS, E. B. BOWERS, E. B.	7812070260 7812080004	50-397 50-275	0	80YD, R. O. 80YD, R. O.	7812150179 7812210254	50-387 50-416	A	BROWN, S. C. BROWN, S. C.	7811070146 7811070326	50-3 50-1
BOWERS, E. B. BOWERS, E.	7812180027 7812150056	50-275 50-275	O T	BOYO, R. S. BOYO, F. Q	7612210040 7612270171	50-36B 50-275	P H	BROWN, B. C. BROWN, B. C.	7811090243 7811140129	50-3 50-3
Bowers, E.	7812130064 7812200344	50-275 50-275	T	BOYER, V. S. BOYER, V. S.	7812130098* 7812130083*	50-352 50-352	Q Q	BROWN, B. C. BROWN, B. C.	7811160097 7811210399	50-3 50-3
BOWERS, E. S.	781220033B 7812210297	50-275 50-322	0	BOYER, V. B. BOYER, V. S.	7811280248 7812110213	50-352 50-352	8	BROWN, B. C. BROWN, B. C.	7811210309 7811240111	50-0 50-0
SOWERS, E. S.	7812210317	50-397	Ö	BOYTER, N. C.	7810140092+	50-313	9	BROWN, S. C.	7811240111	50-4
BOWERS. E.	7812270346	50-275	Ţ	BOYTER, N. C.	7811030036+	50-285	q	BROWN, D. H.	7811280202*	50~0
BOWERB. E. B.	7812220014 7812280088	50-275 50-488	T 0	BOYTER, N. C. BRADFORD, W. H.	7811280062* 7810310074*	50-285 50-259	0	BROWN, B. C. BROWN, B. C.	7812060142* 7812010255	80-0 50-0
BOWERB. E. BOWERB. E.	7812290002 7812290279	50-275 50-275	T	BRADFORD, P. A. BRADFORD, W. H.	7810300266* 7810110270*	50-389 50-338	9	BROWN, Q. D. BROWN, M. S.	7812270244* 7812080087*	50-1 50-1
BOWERB. E.										
BOWER B. E.	7812290280 7812290282	50-275 50-275	Ţ	BRADFORD, W. H. BRADFORD, W. H.	7810310144# 7811130241•	30~261 30~280	9	BROWN: B. C. BROWN: B. C.	7812120117 7812200225	50-1 50-1
BOWERS, E. BOYD, R. S.	7812290283 7811200049*	50-275 50-437	T A	BRADFORD, W. H. BRADFORD, W. H.	7811220064* 7812210350*	50-321 50-302	9	BROWN, S. C. BROWN, S. C.	7812240255 7812270170	50-0 50-0
BOYD, R. S.	7812130054	50-572	Ä	BRADLEY, R. D.	7811300170+	30-400	ã	BROWN. S. C.	7812270194	50-3
BOYD, R. B.	7812210323	50-327	A	BRADLEY, R. D.	7812210345+	50-400	9	BROWN, B.C.	7812270189	50-3
BOYD, R. S.	7811090074* 7810130242	50-275 50-327	Q A	BRADLEY, E. J. BRAND, W. E.	7812180160 7812210374	50-276 50-375	P M	BRUCKNER, G. E. BRUCER, G. F.	7610180102 <b>*</b> 7811070164 <b>*</b>	50~3 50~4
BOYD, R. S. BOYD, R. S.	7810130008 7810260038	50-592 50-437	A	BRATTON, J. K. BRATTON, J. K.	7811210086* 7811070351	50-70 50-70	Ÿ	BRUGGE, R. O. BRUGGER, R. M.	7812120082* 7812290080	50-:
BOYD, R. S.										
BOYD, R. S.	7810230387 7810250212*	50-592 50-275	A	Bredeme Ier. O. E. Brenner. L.	7810190217 7810140140	50-344 50-546	9	Brunettif. V. Brunnerie. J.	7810130231 7810190005#	50~1 50~1
80YD, R. S. 80YD, R. S.	7811010368+ 7811010052	50-320 50-414	Q A	BRENNER.L. BRENNER.L.	7810140011 7810140065	50-443 50-443	0	BRUNNER, E. J. BRUNNER, E. J.	7810270192* 7810180177	50-: 50-:
BOYD, R. S.	7811010064+	50-414	A	BRENNER . L.	78101400B0	50-443	ŏ	BRUNNER, E. J.	7810260023*	50-

AUTHOR	ACCESSION NUMBER	BUDJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7810250048 7811150100* 7811300361 7811020182* 7811020178*	50-311 0 50-309 0 50-184 0 50-223 0 50-223 0	BRYANT, J.C. BRYANT, J.C. BRYANT, J.C. BRYANT, J.C. BRYANT, J.C.	7812070030* 7812070023* 7812120045* 7812130040* 7812280080*	50-364 0 50-518 0 50-395 0 50-327 0 50-424 0	BURWELL'S B BURWELL'S B. BUSCH'R'W BUSCH'R' BUSHSBAUM'P'A.	7811220082 * 7812080236 7811130128 7811200144 7811130234	50-549 7 50-549 4 50-522 0 50-522 0
BRUNNER, E. J.	7811080238* 7810230224 7811080090* 7811080092* 7811080244	50-219 0 50-219 0 50-286 0 50-286 0 50-286 0	BRYANT, J. C.	7812200057* 7812290111* 7812290048* 7812060362* 7812040175*	30-556 H 50-553 0 50-390 0 50-389 0 50-395 0	BUST. B. A BUTLER, R. M. BUTLER, R. M. BUTLER, R. M. BUTLER, R. M.	7812140368* 7810230205 7811090140 7811140200 7811210326	50-266 H 50-293 I 50-471 I 50-471 # 50-471 I
BRUNNER, E. J.	7811080290 7811080091 7811090284 7811090053 7811090016	50-311 Q 50-317 Q 50-320 Q 50-277 Q 50-247 Q	BRYAN, J. K. BRYANT, J. C. BRYAN, S. E. BRYAN, J. K. BUCHBBAUM, P. A.	7812200237 7812210048* 7812130318 7812290277 7612120233	50-483 G 50-413 G 50-244 G 50-483 A 50-354 G	BUZY, J. J. BYRD, H. F. Caba, E. Caba, E. C. Caba, E.	7811130241* 7812280254 7811070188* 7811140136* 7812150298*	50~280 G 50~338 F 50~346 E 50~346 F 50~346 F
BRUNNER, E. J.	7811100099 7811150190* 7811130192* 7811100008 7812010294*	50-311	BUCKLEY.B.C. BUCZWINSKI.T.A. BUHL.A.R. BUHL.A.R. BUITER.O.H.	7812220006 7810250100* 7812010015* 7812010019* 7812150234*	50-280 P 50-329 A 50-275 A 30-275 A 50-305 S	CABA: E. CAFFEY: L. H. CAHILL: H. J. CAHILL: W. J. CAHILL: H. J.	7812120173* 7812120090 7810100067 7810110099 7810110153	50-346 E 50-537 E 50-247 E 50-247 P 50-247 E
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7810160080 7812010097* 7811100157 7811100075 7811130271	50-293 Q 50-309 Q 50-311 Q 50-213 Q 50-334 Q	BURCHETTE, W. H. BURDETTE, T. E.	7812140246 7811080220* 7811220264* 7812080052* 7812080052*	30-445 M 50-369 G 50-395 G 50-518 G	CAHILLOW J. CAHILLOW J. CAHILLOW J. CAHILLOW J.	7810160105 7810160138 7811060044* 7810200064 7810230149	50-247 E 50-247 E 50-562 G 50-3 R 50-247 R
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811140037 7811100142 7812010132* 7810260019 7811150272*	50-311 0 50-311 0 50-219 0 50-220 0 50-317 0	BURDICK,M.B. Burder,A Burder,A Burder,A Burder,A	7812200177= 7812180404 7812180357 7812180414 7810180218	50-458 A 50-70 P 50-70 P 50-70 P 50-206 F	CAMILL, H. J. CAMILL, H. J. CAMILL, H. J. CAMILL, H. J. CAMILL, H. J.	7811140255≠ 7811070120 7811070274 7811070221 7811070157	50-3 Q 50-3 P 50-247 P 50-247 B
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811150274* 7811020060 7811300295 7811300303 7812010277	50-317	BURDER, A BURDER, A BURDHARD, H. C. BURKE, D. J. BURKE, D. J.	7810300111 7811070300 7810310227* 7811130241* 7812060262*	50-206 F 50-29 F 50-331 B 50-280 G 50-280 G	CAHILLIH J. CAHILLIH J. CAHILLIH J. CAHILLIH J. CAHILLIH J.	7811070163* 7811200181 7811210340 7811220076 7811200155	50-247 P 50-3 F 50-3 R 50-3 J 50-247 F
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7611290387 7610270165 7811290335* 7811290338* 7812060194*	50-272 0 50-334 0 50-336 0 50-336 0 50-20 0	BURKE, D. J. SURNASTER, M. BURNETT, P. T. BURNETT, P. T. BURNETT, P. T	7812210113* 7810250041 7810110236* 7811200214* 7812210154*	50-280 0 50-409 0 50-261 0 50-280 0 50-335 0	CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J.	7811220153 7811280260 7812070182* 7812190121 7812190102	50-3 R 50-247 B 50-3 P 50-247 B 50-247 F
BRUNNER, E. J.	7812010280 7811300337 7811080229 7812010016* 7812010336	50-320	BURNETT,P.T. BURNETT,P.T. BURSEY,B. BURSEY,B. BURSEY,B.	7812180311* 7812130317* 7810310118 7812270139 7810180046*	50-302	CAHILL, W. J. Cahill, W. J. Cahill, W. J. Cahill, W. J. Cahill, W. J.	7812200193 7812200206 7812190174 7812190180= 7812270188	50-247 S 50-247 S 50-3 P 50-3 P 50-3 R
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812010047 7812010275 7812110314 7812040353 7811080082	50-286 Q 50-219 G 50-245 G 50-311 G 50-286 Q	BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B.	7810180043 7810180038 7810180040+ 7810180099 7810170171	30-266 8 50-266 8 50-266 8 50-301 R 50-266 R	CAHILLAN J. CALDHELL B. CALDHELL R. A CALDHELL D. M. CALDHALL D. M.	7812210207 7811010290 7811200330* 7811220092* 7812130235	50-3 R 50-466 G 50-298 G 50-349 7 50-389 M
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812060298 7812060365 7812110303 7811150265 7812080080	50-244	BURGTEIN. B. BURBTEIN. B. BURBTEIN. B. BURBTEIN. B. BURBTEIN. B.	7810170153 7810230272 7810250108 7811240130 7811240136*	50-266 P 50-266 P 50-502 A 50-301 8 50-301 8	CALVO, J. A. CAMPBELL, J. CAMPBELL, J. CANTER, H. L. CANTER, H. L.	7812060382 7811240139+ 7812110154+ 7810230092+ 7812080238+	50-311 A 50-304 E 50-295 E 50-70 C 50-326 C
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812110295 7811150092 7811150184 7812200276* 7812200280*	50~336	Burbtein, B. Burbtein, B. Burbtein, B. Burbtein, B. Burbtein, B.	7811240131 78112401344 7810250086 7811240149 7811240155	50-301 8 50-301 8 50-502 A 50-264 8 50-266 8	CANTER, H. CANTER, H. L. CANTER, H. L. CANTRELL, F. B. CANTRELL, F. B.	7812070276* 7812130314* 7812270436* 7810130099* 7811280012*	50-206 G 50-275 G 50-133 G 50-321 G 50-321 G
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812010291 7812270051 7812270149 7812270417 7812270446	50-317	Burbtein, 8. Burbtein, 8. Burbtein, 8. Burbtein, 8. Burbtein, 8.	7811240158+ 7811070374 7811140102 7811140108+ 7811140171	50-266 8 50-266 0 50-302 A 30-502 A 50-502 B	CAPHTON, D, L. CAPHTON, D. L.	7810250052* 7812010031* 7811140043* 7812080083* 7812270044*	50-311 ( 50-277 ( 50-311 ( 50-334 ( 50-311 (
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812280009 7812290028 7812290042 7812010009 7812070284	50-272	BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B.	7811140173* 7811130203 7811150167 7811140124 7811140174	30-502 B 50-266 P 50-266 F 50-266 P 50-266 R	CAPLAN, R. CAPRA, R. CARBON, M. CARDONNE, A. T. CARLISON, D. M.	7811210467 7811070053 7611100051 7810130219* 7810240033*	50~485 50~502 50~280 50~400 50~315
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811290328 7812010090 7812010130 7812040180 7812200114	50~336	Burstein B. Burstein B. Burstein B. Burstein B. Burstein B. Burstein B.	7811280240 7812010225 7812110189 7811280229 7811300179	50-502 B 50-266 P 50-266 B 50-266 P 50-502 A	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	7812130102* 7811080192* 7811080194* 7810250194* 7811140243*	50-352 50-363 50-363 50-387 50-322
BRUNNER, E. J. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C.	7812270057 7810110303* 7810110174* 7810250091* 7810310082*	50-336	BURSTEIN S. SURSTEIN S. SURSTEIN S. SURSTEIN S. SURSTEIN S.	7812050188 7812270157 7812270158* 7812110110 7812120085	50-301 P 50-502 C 50-502 C 50-302 A 50-266 R	CARLBON, R. T.	7811140237* 7611140278* 7810250258 7810270284 7810270391	50-322 50-311 50-354 50-311 50-363
BRYANT, J. C.	7811090269* 7812050150* 7811090238* 7812060035* 7812010040*	50-332 0 50-327 0 50-375 0 50-375 0 50-366 0	Burgtein B. Burgtein S. Burt L. Burton, P. Burhell, B. B.	7812150305 7812260169 7812010044* 7810230042* 7810120108	50~502 A 50~266 F 50~471 Q 50~275 A 50~549 A	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, J. T. CARLBON, R. T.	7811140277* 7810250133 7810300117 7811100095 7811130135	50-311 50-412 50-334 50-443 50-387

	ACCES910N	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUT#©R	ACCESSION NUMBER
AUTHOR  CARLSON.J D  CARLSON.R T  CARLSON.R T	NUMBER 7811130231+ 7811130280 7810230233	50-344 0 50-334 0 50-334 9	CARTHRIGHT. H R CARTHRIGHT. H R CARTHRIGHT. H R CARTHRIGHT. H R	7812040211* 7812040213* 7812040215* 7812040217*	50-338	CHILK. B J CHILK. B J CHILK. B J	7812270430# 7811240308 7811240359 7811240377
CARLSON.R T. CARLSON.R T. CARLSON.R T CARLSON.R T CARLSON.R T	7811170295 7810250186 7811300383 7811080175 7811070373	50-311 Q 50-387 Q 50-410 Q 50-363 Q 50-412 S	CARTURIGHT. U. R CARTURIGHT. U. R CARTURIGHT. U. R CARTURIGHT. U. R	7812010265* 7812050226* 7812070190* 7812070195*	50-339 R 50-339 B 50-339 B 50-338 B	CHILK. B J CHILK. B J CHILK. B J CHO. J	7812040035 7812070261 7812130117 7812260011 7812270073
CARLSONIR T CARLSONIR T	7811300345 7812120022 7812120241	50-312 0 50-322 0 50-363 0	CARTHRIGHT H R CARTHRIGHT H R CARTHRIGHT H R	7812110192¢ 7812110208¢	50-338 S 50-338 S	CHONFERN C CHONFRN C CHONN N A	7810300187 7810110185* 7811210436*
CARLSON-R T CARLSON-L R CARLSON-R T CARLSON-R T	7812010109 7810300156 7811130069 7812060344	50-29 0 50-263 1 50-387 9 50-271 0	CARTHRIGHT H R CARTHRIGHT H R CASE E. O CASE C. P.	7812200239* 7812270238* 7811300102* 7812140331*	50-338 8 50-338 8 50-338 A 50-437 H	CHOULES N. C. CHOWLES N. C. CHOW, E. T.	78120A0128\ 7812290032\ 7812140147\
CARLEON-J D CARLEON-J D CARLEON.R T CARLEON.R T CARLEON.R T	7812130350+ 7812070043+ 7811150172 7811140229 7811140271	50-187	CASE, E Q CASEY, Q. E. CASEY, 9 8 CASEY, 8 8 CASEAN, V. J.	7612070094 7812210077* 7811060050 7812130093 7810300275	50-334 0 50-245 P 50-361 0 50-206 H 50-333 0	CHRISTMAN, J.N. CHRISSDIINOS, N. CHRISTOFFER, O. M. CHRISTIE A. M. CHRISTMAN, J.N.	7811070367 7811300268* 7811070044* 7812200247* 78122000171
CARLSON.R. T. CARLSON.R. T. CARLSON.R. T. CARLSON.R. T. CARLSON.R. T.	7812180078 7811280454 7812280313 7812270453 7811290337	50-20 0 50-412 5 50-310 0 50-333 0 50-443 5	CAVANAUGH, W CAVANAUGH, W CAVANAUGH, W CAVANAUGH, W CAVANAUGH, W	7810100081 7810180117 7811160062 7811170227 7811160121	50-313 P 50-358 P 50-313 P 50-313 G 50-368 P	CHRISTMAN, J N CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W CHURCHILL, B	7812260259 7811070322 7812130084* 7812280345 7812290100
CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.O M	7812290211 7612290249 7812290234 7812080220 7811300117+	50-334 0 50-485 0 50-387 0 50-423 8 50-255 0	CAVANAUGH, W CERNE - A C CHADWELL - H. M CHADWELL - H. M CHALL ER. D V	7811220190 7812290238+ 7810230202+ 7811210278+ 7811090225	50-368 P 50-387 0 50-315 6 50-315 8 50-315 8	CHURCHILL B W CHURCHILL B W CIEBZKIEHICZ B CIEBZKIEHICZ B. CLARE G.H	7812290105# 7812270452 7810270305# 7811240211# 7810170257#
CARLEON.R. T. CARLEON.J. D. CARLEON.R. T CARLEON.J. C CARLEON.R. T.	7812070110 7812270382* 7812180153 7812270436* 7812270039	50-322 S 50-397 0 50-363 0 50-243 0 50-352 9	CHALMERS, W. J. CHAN, J. CHAN, J. CHANANIA, F. D. CHANANIA, F. D.	7811140147 7812270302* 7812270289* 7811080353* 7810300083	50-187 H 30-237 8 50-249 8 50-389 M 30-393 M	CLARK, J.R. CLARK, R.H. CLARK, D. CLARK, A.D. GLARK, J.R.	7811100125 7810200120 7810170180* 7810230245 7011170233
CARLSON.R. T. CARLSON.R. T CARLBON.R. T CARLTON.R. T CARROLL.J. T.	7812270254 7812270469 7812280210 7810230190+ 7810140116	50-322 0 50-322 0 50-311 0 50-387 0 50-484 A	CHANANIA F D CHANANIA F. D CHANANIA F D. CHANDLER L J. CHANDLER L. J	7810310327 7811080243 7812080226 7810140106 7810300223	50-395 M 50-389 M 50-389 M 50-320 G 50-70 G	CLARK, D. D GLARK, R. H CLARK, A. Y. CLARK, R CLARK, R.	7812050270* 7811200050 7811280411 7811280363 78120402254
CARROLLIJ. T CARROLLIJ. T, CARROLLIJ. T CARROLLIJ. CARROLLIJ.	7810110174* 7811080100 7810310216* 7811060133 7811060161*	50-317 B 50-219 B 50-318 B 50-318 B 50-318 B	CHANDLER. L. J.	7811030219 7812040264 7812130375 7812130088 7812270030	50-361	CLARK, L. CLARK, D. CLARK, R. H CLARK, R. H. CLARK, L.	7812060185* 7812110178* 7812180410 7812180412 7812080073
CARROLL.J. T CARROLL.J. T CARROLL.J. T. CARROLL.J. T. CARROLL.J. T.	7811170187• 7812110093 7812280231 7812290089 7812130174•	50-318 8 50-219 8 50-219 8 50-219 8 50-318 8	CHANDLER, L. J. CHANDLER, L. J. CHANDLER, L. J. CHARNOFF, Q. CHARNOFF, Q.	7812180307 7812270360 7812280314 7810190230 7810240227	50-320	CLARK, R. H. CLARK, R. J. CLAY, E. L. CLAYTON, F. L CLAYTON, F. L	7812280177 7812120203 7812140059# 7810130068 7810100066
CARROLL, J. T CARROLL, J. T. CARROLL, J. T. CARROLL, J. T. CARROLL, J. T.	7812130187* 7812130194* 7812200261 7812260248* 7812200236	50-318 8 50-317 8 50-317 8 50-318 8 50-219 8	CHARNOFF, O. CHARNOFF, O CHARNOFF, O. CHARI 6, B CHEATUM, E. L	7811270050+ 7812220109 7812130057 7812260002 7812110266	50-483 Q 50-502 Q 50-483 Q 50-247 Q 50-466 Q	CLAYTON,F, L CLAYTON,F, L, CLAYTON,F, L, CLAYTON,F, L, CLAYTON,F, L	7810100085 7810110102 7810180097 7810180145 7810250229
CARTER.R.S. CARTER.R.S. CARTHRIGHT.H.R. CARTHRIGHT.H.R. CARTHRIGHT.H.R.	7812060286+ 7811210320 7810130145+ 7810130148+ 7810230291+	50-184 0 50-184 9 50-338 8 50-338 8 50-338 8	CHENG, T.M. CHERRY, M.M. CHERRY, M.M. CHERRY, M.M. CHERRY, M.M. CHIANGI, N.J.	7812260045 7812060126 7812060172* 7812280340* 7812270187	50-155 P 50-329 Q 50-329 Q 50-329 Q 50-400 B	CLAYTON.F.L. CLAYTON.F.L. CLAYTON.F.L CLAYTON.F.L CLAYTON.F.L	7810250239 7811070229 7810180079 7010180181 7810200077
CARTHRIGHT, H. CARTHRIGHT, H. R. CARTHRIGHT, H. R. CARTHRIGHT, H. R. CARTHRIGHT, H. R.	7810230260+ 7810260128+ 7810260129+ 7810260130+ 7810260131+	50-338 8 50-338 8 50-338 8	CHILDS. W. V.	7810100026> 7810120046* 7810120079> 7810230189> 7810230265>	50-333 8 50-333 8 50-333 9 50-333 8	CLAYTON:F. L, CLAYTON:F. L. CLAYTON:F. L CLAYTON:F. L. CLAYTON:F. L.	7810250141 7810250112 7810310070 7810310131 7811080159
CARTURIGHT, W.R. CARTURIGHT, W.R. CARTURIGHT, W.R. CARTURIGHT, W.R. CARTURIGHT, W.R.	7810260132+ 7810260133+ 7810260135+ 7811280326+ 7810260164+	50-338 8 50-338 8 50-338 8 50-338 8	CHILDS, W V. CHILDS, W V. CHILDS, W V. CHILDS, W V. CHILDS, W V	7810230310• 7810240139• 7811070323• 7811140248• 7811210422•	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8	CLAYTON.F. L. CLAYTON.F. L. CLAYTON.F. L CLAYTON.F. L. CLAYTON.F. L.	7811130226 7811080140 7811170038 7812050010* 7811090183
CARTHRIGHT, H. R.	7810310242+ 7810310252+ 7811060237+ 7811060240+ 7811060242+	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	CHILDS. W V.	7812040159* 7812070178* 7812220100* 7812270250* 7812080211*	50-333 8 50-333 8 50-333 9 50-330 U	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	7811140085 7811140152 7811140225 7811140111 7811210355
CARTURICHT, U.R. CARTURICHT, U.R. CARTURICHT, U.R. CARTURICHT, U.R. CARTURICHT, U.R.	7811060245+ 7811070261+ 7811170184+ 7811170189+ 7811210294+	30-338 8 50-338 9 50-338 8 50-338 8	Chilk. B. J. Chilk. B. J. Chilk. B. J. Chilk. B. J. Chilk. B. J.	7810230026 7810230152 7810300277+ 7810230315 7810260201	50-70 0 50-331 8 50-389 8 50-338 9 50-247 0	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	7811210176 7811270176 7811210258 7811280283 7811280336
CARTHRIGHT, N. R.	7811210315* 7811280325* 7811280330* 7811280321*	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	Chilk. B. J. Chilk. B. J. Chilk. B. J. Chilk. B. J. Chilk. B. J.	7811010118 7811070040 7811150252 7811290184 7812010154	50-389 Q 50-437 Q 50-329 Q 50-247 Q 50-247 Q	CLAYTON, F. L.	7811280258 7811280267 7812010253 7812050159 7812110134

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCEBBJ ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGOR
CLAYTON.F. L CLAYTON.F. L CLAYTON.F. L CLAYTON.F. L CLAYTON.F. L	7812130131 7812140117 7812270169 7812210202 7812200163	50-348 P 50-348 G 50-348 F 50-348 R 50-348 B	CONNER. E. L. CONNER. T. B. CONNOLLEY. J. CONNOR. L. CONNULLEY. J.	7812270354 7812280197 7810110117* 7810300258 7810180162*	50-317 P 50-477 0 50-289 S 50-331 0 50-285 S	COOPER. J COOPER. J COOPER. J COOPER. J COOPER. J	7811280307* 7812010247* 7812200181* 7812200273* 7812180155*	50-302 50-302 50-302 50-302 50-302
CLAYTON,F.L. CLAYTON,F.L CLAYTON,F.L CLAYTON,F.L CLEBRCH.A.	7812270308 7812270306 7812270306 7812270127 7812270278 7810230134	50-348 8 50-348 8 50-348 P 30-348 8 50-274 P	CONNOLLEY, J CONNOLLEY, J CONNOLLEY, J CONRAN, J H	7811210371+ 7812210304 7812270217+ 7812270224+ 7811200369+	50-285 8 50-335 P 50-285 5 50-285 8 50-437 A	COOPER. J COOPER. J COOPER. J COOPER. J COPELAND, J O.	7812220084* 7812220105* 7812270243* 7812270293* 7810130195	50-302 50-302 50-302 50-302 50-466
CLEVELAND, J. H CLEBSKIEHICŽ, S. CLEBSKIEHICŽ, S.	7811090063 7812200238 7811150049* 7812180220* 7811080008*	50-274 P 50-274 H 50-220 G 50-237 S 50-275 A	CONRAD, V. L.	7811130334 7811130135 7812050265* 7812130138 7812270231	30-384 A 30-336 B 30-336 G 30-336 A 30-336 A	COPELAND, J G COPELAND, J G COPELAND, J G COPELAND, R L COPELAND, J G	7810110294 7810140139 7810130091 7810170134 7811080054	30-466 50-466 30-466 50-537 50-466
CLEVELAND, J H. CLOUD, J.D CDALWELL, T.N CDCHRAN, B. J COCHRAN, B. J	7811200384* 7812010153 7810110098 7811300339* 7811220284*	50-275 A 50-546 A 50-264 J 50-390 Q 50-395 Q	CONTE.R J CONTE.R.J. CONTE.R.J. CONWAY, W F COMMAY, W F.	7811270389+ 7812110301+ 7812270449+ 7812180173 7812180176+	50-272	COPELAND. J. G. COPELAND. R. L. COPELAND. R. L. COPELAND. J. G. COPELAND. J. G.	7812050037 7812110014 7811170177 7812110256 7812040024	50-466 50-537 50-537 50-466 50-466
COCHRAN.T. B COHEN. R.C. COHN, D. B. COHN, D. B COLBERT.W F	7811130391* 7811020381 7811270009 7812180077 7811090172*	50-220 P 50-329 G 50-483 0 50-483 0 50-341 B	CONHAY, W. F.	7812180193 7812180199* 7812180213 7812180216* 7812180190	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	COPELAND. J. Q COPELAND. J. Q COPELAND. J. Q COPELAND. J. Q COPELAND. R. L	7812070058 7812120224 7812040331 7812050046 7812050276	50-466 50-466 50-466 50-466 50-537
COLEMAN, H. E. COLEMAN, H. E. COLLINS, H. COLLINS, P. F. COLLINS, P. F.	7812070295* 7812010282* 7811280494* 7810180173 7810140099	50-219 Q 50-320 Q 50-331 P 50-344 V 50-309 H	CONMAY.W F CONMAY.W F CONMAY.W F CONMAY.W F. CONMAY.W F.	7812180174* 7812180237 7812180241* 7810310244 7810310248*	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	COPELAND, J G COPELAND, J. G COPELAND, J O COPELAND, R. L CORDARD, W M	7812130026 7812130219 7812130020 7812200243 7812210006	50-466 50-466 50-466 50~537 50-305
COLLINB.P.F. COLLINB.P.F. COLLINB.P.F. COLLINB.P.F. COLLINB.P.F.	7810170281 7810190130 7810190035 7810230380 7810230384	50-387 A 50-266 P 50-592 E 50-382 A 50-341 A	CONHAY, W. F.	7811160102 7811160103* 7811160128 7811160130* 7812180219	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	CORE, M CORE, M. CORKIN, C. CORKIN, C CORKIN, C	7812200267 7812200231 • 7810310286 • 7810310281 • 7810110310	50-265 50-265 50-569 50-568 50-443
COLLINS.P.F. COLLINS.P.F. COLLINS.P.F. COLLINS.D.M COLLINS.P.F.	7810300284 7811130127 7811130132 78122803484 7810170110	50-89 V 50-180 P 50-206 V 50-250 0 50-261 V	CONNAY: W. F. CODK: K. W. COOK: K. W. COOK: K. W. COOK: R. J	7812180222* 7812110272 7812110274* 7812110277* 7812060070*	50-271 8 50-277 P 50-277 P 50-277 P 50-329 Q	CORKIN.C. CORYELLIQ.P COSTLE.D.M. COSTLE.D.M. COTA.P.C	7811200146 7811130014* 7810140048* 7612060157* 7811170048	50-443 50-332 50-213 50-437 50-341
COLLINS.P.F. COLLINS.P.F. COLLINS.P.F. COLLINS.P.F. COLLINS.P.F.	7010180170 7812050317 7812130089 7812210025 78101000554	50-261 V 50-502 R 50-367 F 50-413 A 50-312 B	COOK, R. J. COOKE, H. D. COOKE, T. C. COONEY, M. J. COONEY, M. J.	7812140139* 7810120038 7812260188 7810100082 7810100096	50~329 G 50~97 P 50~329 A 50~277 B 50~278 B	COTE, F. M COTE, F. M COTNER, M. L COTTLE, M. T. COTTLE, M. T.	7811130127 7811130336 7812140168 7810230072* 7810310319*	50-592 50-341 50-361 50-335 50-369
COLOMBO,R. H. COLOMBO,R. H. COLOMBO,R. H. COLOMBO,R. R. COLOMBO,R. H.	7810100077# 7810100021# 7810100069# 7811030152# 7811030156#	50-312 B 50-312 B 50-312 B 50-312 B 50-312 B	COONEY-M J. COONEY-M J. COONEY-M J. COONEY-M J. COONEY-M J.	7810100101 7810100038 7810130155 7810130163* 7810200094	50~277 8 50~277 8 50~277 8 50~277 8 50~277 0	COTTLE, W.T. COUGHLIN, J. COUGHLIN, J. COUGHLIN, J. COUGHLIN, J.	7811130364* 7810110138 7810300365 7810300184 7811130196	50~369 50~546 50~546 50~546 50~546
COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H.	7810110126* 7810130135* 7810170201* 7810200106* 7810230285*	50-312 R 50-312 B 50-312 B 50-312 B 60-312 B	CODNEY, M. J. CODNEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7810230164 7810270261 7810270270* 7810240164 7811090137	50~277 R 50~278 8 50~278 8 50~277 8 50~277 8	COUGHLIN J. COULBON-CURRIN COUNBIL. H. O. COUNBIL. W. O. COUNBIL. W. O.	7812130128 7811080047¢ 7810110140 7810110176 7810260182	30-346 30-336 50-243 50-243 50-213
COLOMBOR, W. COLOMBOR, W. COLOMBOR, W. COLOMBOR, W. COLWELLIJ, W.	7811140078* 7811140234* 7812200197* 7812110173* 7812210235*	50-312 R 50-312 8 50-312 R 50-312 B 50-275 A	COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7811090141 * 7811090146 7811090152* 7811160095 7811140142	50-277 8 50-277 9 50-277 8 50-277 8 50-277 8	COUNBIL.M. Q. COUNBIL.M. Q. COUNBIL.M. Q. COUNBIL.M. Q. COUNBIL.M. Q.	7810130138 7810170140 7810170210 7810200060 7810240099	50-245 50-245 50-336 50-336 50-245
COLWELL+J. W. COLWELL+J. W. COMPTON-R. M. COMPTON-R. M. COMPTON-R. N.	7812210209# 7812210225# 7810250091# 7812060291# 7812150040#	50-275 A 50-275 A 50-424 0 50-327 Q 50-327 0	CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. COONEY, M. J. COONEY, M. J.	7811160084 7811280225 7811280227 7811280230* 7812070210	50-277 R 50-277 B 50-278 B 50-278 B 50-277 B	COUNBIL, H. Q.	7810260171 7810270203 7810310073 7811210178 7810310077	50-213 50-245 50-245 50-245 50-496 50-336
CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E.	78102402104 78101301014 78110801584 78111500674 78112000344	50-390 0 50-413 0 50-395 0 50-398 0 50-324 0	CODNEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. CDONEY, M. J.	7812070213* 7812070173 7812130162 7812130130 7812220063	50-277 8 50-277 8 50-277 9 50-277 9 50-277 8	COUNBIL.H. O. COUNBIL.H. O. COUNBIL.H. O. COUNBIL.H. O. COUNBIL.H. O.	7811030097 7811070196 7811160152 7811090132 7811130193	50-213 50-336 50-245 50-423 50-213
CONLON, T. E.	7812040068# 7811240033# 7811020360# 7812050172# 7812070320#	50-390 0 50-250 0 50-364 0 50-294 0 50-269 0	COONEY, M. J. COONEY, M. J. COOPER, J. COOPER, J. COOPER, J.	7812210165 7812290198 7810200158* 7810110152* 7810110120*	50-278 \$ 50-278 \$ 50-302 \$ 50-302 \$ 50-302 \$	COUNSIL.H. Q. COUNSIL.H. Q. COUNSIL.H. Q. COUNSIL.H. Q.	7811140155 7811170217 7811290332* 7811170208 7811210232	50-213 50-213 50-213 50-236
CONLON, T. E CONNER, T. B. CONNER, T. B. CONNER, T. B. CONNER, T. B.	7812270128* 7810270313 7810310017 7811030038 7811270046	50-327	COOPER, H. P. COOPER, J. COOPER, J. COOPER, J. COOPER, J.	7810180111# 7810170252* 7810180155* 7810180107* 7810240124*	50-302 B 50-302 B 50-302 B 50-302 B 50-302 B	COUNBIL.H. Q. COUNBIL.H. Q. COUNBIL.H. Q. COUNBIL.H. Q. COUNBIL.H. Q.	7812210056+ 7811240187 7811170210 7811270183 7812070184	50-245 50-245 50-336 50-213 50-245
CONNER, T. B. CONNER, E. L. CONNER, T. B. CONNER, T. B. CONNER, E. L.	7811220159 7811290209 7812130025 78121300279 7812180265	50-510 0 50-336 P 50-395 0 50-358 0 50-317 F	COOPER, J. COOPER, J. COOPER, J. COOPER, J. COOPER, J.	7810240162* 7810310141* 7810310169* 7811070235* 7811160140*	50-302 8 50-302 8 50-302 8 50-303 8	COUNBIL.M. O. COUNBIL.M. O. COUNBIL.M. O. COUNBIL.M. O. COUNBIL.M. O.	7812290061* 7812080121 7812210101 7812260012 7812180143	50-336 50-245 50-213 50-245 50-245

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTIOR	ACCEBBION NUMBER	BUBJECT CATEOGRY
COUNSIL. H. O. COUNSIL. H. O. COUNSIL. H O. COUNSIL. H O. COHAN. F. P.	7812190083 7812260169 7812200187 7812280137 7810270345#	50-245 P 50-476 A 50-336 P 50-336 O 50-344 Q	CREWS. E. H CREWS. J. L. CREWS. J. L. CREWS. J. L. CREWS. J. L.	7811220184 7812130301 7812270432 7812270430 7812280335	50-395 A 50-275 G 50-243 G 50-133 G 50-344 G	CUTCHINIJ H CUTCHINIJ M CUTCHINIJ M CUTCHINIJ H CUTCHINIJ M	7811150018 7811130040 7811280416 7811290004 7812270108	50-443   50-568   50-443   50-387   50-987
COHAN. B. Z. COHAN. F. P. COHAN. F. P. COHAN. B. Z. COHAN. B. Z.	7810160112 7810160221 7810230109 7810230383 7811150257	50-437 0 50-344 0 50-344 0 50-437 0 50-437 0	CREMB.E.H CREMB.J L CREMB.E.H CREMB.J L CREMB.J L	7812130364 7812270377 7812050231 7812070126 7812130331	50-395 0 50-397 0 50-395 F 50-344 0 50-197 0	CYR-R D DAIL-L C. DAIL-L C. DAIL-L C. DAIL-L C. DAIL-L C.	7812130035 7810260081 7812040277 7810300330* 7810130075	50-556 50-413 50-413 50-469 50-413
COX. E. L. COX. E. L. COX. T. H COX. T. H. COX. T. H.	7810180146 7810310051 7810110209 7810190067 7812130044*	50-556 8 50-556 8 50-566 A 50-566 A	CREMB.E.M CREMB.E.H CRINI GAN.P.T CRINI GAN.P.T CROCKER.L.P	7812120200 7812120156 7810130176+ 7811030117+ 7810240017+	50-395 R 50-395 A 50-317 8 50-317 8 50-329 A	DAIL.L C DAIL.L C DAIL.L C DAIL.L C DAIL.L C DAIL.L C	7810230214 7810250217 7811270227 7812010143 7812130287	50-413 50-413 50-413 50-488 50-491
CDZENS.Q. CRABTREE.R.A CRABTREE,R.A CRAHILLIW.J. CRANDALLIW.E.	7811020251* 7810120056 7810230137 7812170075 7811020248	50-187 P 50-309 J 50-309 J 50-247 P 50-187 P	CROCKER.H H CROCKER.H. H CROCKER.H. H CROCKER.H. H CROCKER.H. H	7811100165* 7812060300* 7812010087* 7811020183* 7811020179*	50-286 0 50-184 0 50-286 0 50-271 0 50-271 0	DAIL.L.C DAIL.L.C. DAIL.L.C. DAILEY.E.H. OAIVE.C.L.	7812200312 7812210035 7612210059 7811160126 7811300013*	50-488 50-413 50-413 50-568 50-335
CRANDALLI W. E. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7812130342* 7812060276 7810140114 7810130058 7810190071	50-187 G 50-133 P 50-275 A 50-275 A 50-275 A	CRDCXER.H.W CROCKER.H.W CROCKER.H.W CROCKER.H.W CROCKER.H.W	7810250136 7811080260 7811090032 7811090034 7811140259	50-286 0 50-219 0 50-317 0 50-317 0 50-3 0	DALTON: A DALTON: A T. OALTON: A T. OALTON: A T. OALTON: A T.	7810300211 7811290105 7812050052 7812130196 7812130341	50-55& 50-55& 50-55& 50-55& 50-55&
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, E. CRANE, P. A.	7810170179 7810310226 7810170221 7810300074 7810170205	50-275 A 50-275 A 50-275 A 50-466 A 50-275 A	CROCKER.H.W. CROCKER.H.W. CROCKER.M.W. CROCKETT.J.O CROCKETT.J	7811140256+ 7811300246+ 7811150043+ 7811080146+ 7811080161+	50-3 0 50-334 0 50-220 0 50-336 8 50-336 8	DALTROFF, 8. L. OALTROFF, 9. L. DALTROFF, B. L. DALTROFF, B. L. DALTROFF, B. L.	7811010089* 7810110105 7812010012* 7811300217 7812180221	50-277 50-277 50-277 50-277 50-277
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A CRANE, P. A.	7810160118 7810170229 7810180028 7810240113* 7810300350	50-275 A 50-275 A 50-133 B 50-133 P 50-275 0	CROCKER, L. P. CROCKETT, J. CROCKETT, J. CROCKER, L. P. CROCKER, L. P.	7812130044+ 7812030161+ 7812120129+ 7812200296 7812210167	50-566 0 50-336 8 50-336 B 50-260 0 50-500 A	DALTROFF. B.L. DAMBLY, D.C. DANCE, H.C. DANCE, H.C. DANCE, H.C. DANCE, H.C.	7812260192 7812270419 7810110302* 7810250154* 7811100030*	50-277 50-556 50-324 50-302 50-302
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7611080257 7611010039 7610240111 7611080040 7611280488	50-275 A 50-275 Q 50-133 P 50-275 A 50-275 Q	CROBBMAN. H. A CROBBMAN. H. A CROBBMAN. H. A CROBBMAN. H. A CROBBMAN. H. A.	7810230015+ 7810240236+ 7811030040+ 7811040105+ 7811070308+	50-445 0 50-498 0 50-466 0 50-382 0 50-445 0	OANCE H. C OANCE H. C DANCE H. C DANCE H. C. DANCE H. C.	7811220256* 7811280012* 7812050076* 7812060350* 7812150063*	50-261 50-321 50-321 50-261
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7811070111 7811070271 7811140126 7811210164 7811220181	50-275 G 50-275 A 50-275 K 50-275 F 50-275 A	CROBBMAN, W. A. CROBBMAN, W. A. CROWL EY+ B. R CROWL EY+ B. R CROWL EY+ B. R.	7811280054+ 7812210179+ 7810240210+ 7811150067+ 7812040068+	50-556 G 50-445 G 50-390 G 50-395 G 50-390 G	OANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C. OANIELSON, D. H.	7812180325* 7812180345* 7812280294* 7812200161* 7810190029*	50-259 50-324 50-321 50-13 50-305
GRANE P. A. CRANE P. A. GRANE P. A. GRANE P. A. GRANE P. A.	7812050135 7812140085 7812210229 7812210197 7812210223	50-275 E 50-275 G 50-275 A 50-275 A	CRONLEY, B. R. CRONLEY, B. CULP, R. H. CULP, R. H. CULP, R. H.	7812180353+ 7812280315+ 7811080054 7812040024 7812040331		OANIELSON, D. H. OANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H.	7811010059* 7811090007* 7811130350* 7811020111* 7811140269*	50-373 50-341 50-329 50-315 50-341
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7812130002 7812120161 7812210193 7812190143 7812260217	50~133 J 50~275 A 50~275 A 50~275 A 50~275 A	CULP, R. H CULP, R. H CULP, R. H CULP, R. H CUNNINGPAM, A. L.	7812050046 7812130020 7812130026 7812130219 7811080191*	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-327 Q	OANTELBON. D. H. DANTELBON. D. H. DANTELBON. D. H. DANTELBON. D. H. DANTELBON. D. H.	7811140054* 7811150088* 7812140028* 7812060178* 7812080057*	50-329 50-331 50-329 50-266 50-358
CREED. J.R. CRESWELL J.B. CREWB.J.L. CREWB.J.L. CREWB.J.L.	7812060391* 7811270326* 7810240092 7810240094* 7810230090	50-315	CURNINGHAM, A. L. CURNINGHAM, A. L. CURNINGHAM, G. E. CURNINGHAM, G. H. CUPP, E. A.	7811130393* 7812050249* 7811070115 7811200423 7812180331*	50-250 G 50-70 P 50-295 G	DANIELBON, D. H.	7812140066* 7812270136* 7812200308* 7812210131* 7812270078*	50-331 50-341 50-374 50-266 50-409
CREWS, J. L. CREWS, J. L. GREWSE, R. G. CREWS, E. H. GREWS, E. H.	78102300924 7811130227 7810260147 7810120137 7810170105	50-70 G 50-344 Q 50-320 P 50-395 A 50-395 A	CUPP.E.A CURRAN,J M. CURRAN,J M. CURRAN,J M. CURRAN,J M	7812210184* 7810130159 7812130280 7811140181* 7811140080	50-206 R 50-206 B	OARBY, C. B OARBY, C. B. DARMITZD., R. W. DARMITZD., R. W. DARMITZD., R. W.	7812040072 7812040084* 7812180435 7812180401* 7810110165	50-397 50-397 50-30 50-70 50-70
CREMB.E.H. CREMB.J.L. CREMB.J.L. CREMB.E.M. CREMB.E.M.	7810230161 7811270111 7811220263 7810300217 7810310083	50-395 A 50-344 O 50-275 O 50-395 A 50-395 A	CURRAN, J.M. CURRAN, J.M. CURTIB, J.R. CURTIB, N.W. CURTIB, N.W.	7811280281	50-206 R	DARMITZEL, R. W DARMITZEL, R. W. DARMITZEL, R. W. DARMITZEL, D. W. DATTILO, T. M.	7811130177 7812080131 7812140121 7812280275 7810230229	50-18 50-70 50-70 50-70 50-346
CREWS, E. M. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, E. M.	7811010173 7812070246* 7812130346* 7812130347* 7811010120	50-395 C 50-361 G 50-187 G 50-187 G 50-395 K	CURTIS N W. CURTIS N W. CURTIS J R. CURTIS N W. CURTIS N W. CURTIS N W.	78111300734 7811170123 78121501854 78112001904 7811200165	50-387 A 50~206 G	DAUGHERTY, T. M. DAUGHERTY, T. M. DAUGHERTY, T. M. DAVENPORT, B. O. DAVIDBON, J. A	7810160112 7811150257 7812210451 7810110092* 7812080142*	50~437 50~437 50~437 50~287 50~306
CREMB, E. H. GREMB, J. L. CREMB, J. L. CREMB, E. H. GREMB, E. H.	7811010125* 7812070041 7812080237 7811070128 7811210284	50-395 K 50-106 G 50-326 G 50-395 A 50-395 K	CURTIS.E. CURTIS.N W. CURTIS.N W. CURTIS.N W. CURTIS.N W. CURTIS.N W.	7812080028 7811200185 7811270114 7812050178 7812120076	50-367 Q 50-387 K 50-387 A 50-387 A 50-387 A	DAVIDSON D. R.	7810110261• 7811140131• 7810100007 7811270022 7812070223	50~440 50~266 50~440 50~440 50~440
CREMB, J. L. GREMB, E. H. CREMB, J. L. CREMB, J. L. CREMB, J. L.	7812070289 7811150181 7812140037 7812130316 7812150001	50-206	CURTIS, N.W. CURTIS, N.W. CURTIS, N.W. CURTIS, N.W. CUTCHIN, J.H.	7812130118 7812210168 7812210173 7812210177 7810140002	50-387 C 50-387 A 50-387 A 50-387 A 50-392 O	DAVIS.D.L. DAVIS.D.K. DAVIS.A.B. DAVIS.A.B.	7811290026 7812140038* 7812140311* 7810110052 7810110263	
	•							

-	7810260179 7811170245* 7810300375 7810110248 7811300398	50-155 50-324 50-315 50-556 50-263	0 0 0 0 0	DAVIS-J. G. DAVIS-J. G. DAVIS-J. G. DAVIS-J. G. DAVIS-J. G.	7812280104 7812280107 7812280108 7812280110 7812280112	50-341 50-220 50-409 50-367 50-213	A P P	DENTON, H. R.	7811200044 7811030077 7811070059 7811080024 7811130341	50-70 50-458 50-568 50-584 50-580	H A A H
	7812010065 7810130252 7811080077 7811090037 7810140165	50-305 50-556 50-254 50-2 50-556	0 0 0	DAVIS. J. Q. DAVIS. J. Q. DAVIS. J. Q. DAVIS. J. Q. DAVIS. J. Q.	781 2280113 781 2280114 781 2280117 781 2280118 781 2280119	50-568 50-261 50-29 50-329 50-305	A P P A P	DENTON, H. R.	7811140157 7811210250 7811220107 7811220088 7811220184	50-440 50-591 50-272 50-70 50-220	F A B A P
	7811070278 7811170316 7811140185 7810200018 7810200203	50-255 50-6 50-315 50-346 50-10	0 0 0 0	DAVIS, J. Q. DAVIS, J. Q. DAVIS, J. Q. DAVIS, J. Q. DAVIS, J. Q.	7812280121 7812280123 7812280124 7812280126 7812280129	50-271 50-440 50-358 50-3 50-10	P A A P	DENTON, H.R. DENTON, H.R. DENTON, H.R. DENTON, H.R. DENTON, H.R.	7811240117 7811280157 7811200406 7812060260 7812060376	50-70 50-458 50-382 50-269 50-549	H 1 A P A
	7810300068 7810270087 7811290358* 7811290366* 7810270240*	50-206 50-556 50-400 50-400 50-317	P 0 0 8	DAVIE.J.G. DAVIE.J.G. DAVIE.J.G. DAVIE.J.G DAVIE.J.G.	7812280131 7812280138 7812280140 7812280141 7812280143	50-280 50-293 50-317 50-259 50-528	P P P A	DENTON: H.R. DENTON: H.R. DENTON: H.R. DENTON: H.R. DENTON: H.R.	7812130293 7812110087 7812120014 7812120017# 7812120018#	50-317 50-280 50-424 50-424 50-424	₽ ₽
	7810310105* 7810310200* 7811010041* 7811270393 7811300397	50-317 50-317 50-244 50-123 50-373	8 9 0 0	DAV18.J.G. DAV18.J.G. DAV18.J.G. DAV18.J.G. DAV18.J.G.	7812280146 7812280148 7812280149 7812280150 7812280153	50~313 50~348 50~315 50~483 50~445	P P P A A	DENTON, H. R.	7812110292 7612180398 7812210324 7812160329 7812270003	50-267 50-387 50-346 50-70 50-220	P A H P
	7812010284 7811130146 7811010036 7811080222 7811290327	50-409 50-318 50-244 50-356 50-346	0 8 0 0	DAVIS.J.Q. DAVIS.J.Q. DAVIS.J.Q. DAVIS.J.Q DAVIS.J.Q.	7812280154 7812280155 7812280156 7812280160 7812280161	50~346 50~312 50~245 50~416 50~289	P P P A H	DENTON H R. DENTON H R. DENTON H R. DESYLVA, D. P. DESYLVA, D. P.	7812280274 7812270240 7812270242 7811160001 7811080073	50-267 50-272 50-498 50-463 50-488	H P A F Q
	7811010116* 7812080219* 7811160158 7811160159* 7812060293*	50-317 50-13 50-356 50-356 50-261	8 0 0 0	DAV18, J. Q. DAV18, J. Q. DAV18, J. Q. DAV18, J. Q. DAV18, J. Q.	7812280142 7812280143 7812280144 7812280145 7812280165	50~322 50~382 50~482 50~219 50~461	A P P A	DEVLIN. J. H. DEVLIN. J. H. DEVLIN. J. H. DEVLIN. J. G.	7810110078 7811010133* 7812150240* 7812280309* 7811020362	50~569 50~443 50~245 50~293 50~259	A 0 0 0 8
	7811130214 7811140170 7811120014 7811240018 7811200052	50-318 50-318 50-556 50-556 50-2	8 0 0	DAVIBJJ.Q. DAVIBJJ.Q. DAVIBJJ.Q. DAVIBJJ.Q DAVIBJJ.Q.	7812260167 7812280168 7812260169 7812280170 7812280171	50-331 50-466 50-458 50-321 50-250	P A A P P	DEMEABE, J. Q. DEMEABE, J. Q. DEMEABE, J. Q. DEMEABE, J. Q. DEMEABE, J. Q.	7810160107* 7810250035 7810160106 7810250085* 7810170161*	50-259 50-259 50-259 50-259	Д В Р Р
	7812040185 7812050055 7812050058* 7812050061 7811170171*	50-556 50-556 50-556 50-556 50-318	0 0 0 0 8	DAVIS.J.Q. DAVIS.J.Q. DAVIS.A.D DAVIS.D.K. DAVIS.A.D.	7812280172 7812280173 7812140252 7812240051 7812240314	50~302 50~269 50~366 50~298 50~255	P G P O	DEWEASE, J. Q. DEWEASE, J. Q. DEWEASE, J. Q. DEWEASE, J. Q. DEWEY, L. 8.	7811140137 7812070264 7812190161 7812190162* 7811200103	50-259 50-259 50-259 50-259	R R R
	7811280430 7812080203* 7812190172* 7811270238 7812200299	50-10 50-546 50-344 50-344 50-255	P A O P G	DAY, P. L. DAY, P. L. DEALE, V. B. DEBREMAECKER, J. DEBREMAECKER, J.	7810310375 7811200400 7812180418 7810230018* 7811220274	50~466 50~466 50~338 50~466 50~466	0 0 0	DEMEY, L. S. DEMEY, L. S. DEYDUNG, R. C. DEYDUNG, R. C. DEYDUNG, R. C.	7812040260 7812140092 7811200243* 7811200032* 7811200093*	50-389 50-389 50-437 50-437 50-437	M M A A
	7811210409* 7811300199* 7811240067 7812210003 7812210005*	50-317 50-317 50-440 50-358 50-358	8 0 0	Debremaecker, J. Deck, J. Deck, J. Deck, J. Defalco, P.	7812030113 7810240003 7810240086 7811270261 7812030174	50-466 50-437 50-437 50-437 50-592	O A A A D	DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C.	7811200043* 7811200419* 7811200403* 7811200172* 7811200196*	50-437 50-437 50-437 50-437 50-437	^ ^ ^
	7812270244 7812280226 7812270059 7812130036 7811270267*	50-556 50-456 50-255 50-356 50-317	0 0 0	DELAND, L. H. DELAPORTE, C. T. DELFING, J. B. DELFING, J. B. DELGEORGE, L. D.	7811080145 7811070123 7811070361 7811240096# 7810100035	50-344 50-568 50-70 50-70 50-373	0 A G U A	DEYDUNG.R. C. DEYOUNG.R. C. DEYOUNG.R. C. DEYOUNG.R. C. DEYOUNG.R. C.	7811200310+ 7811200224+ 7812210323 7811300034 7811300037	50-437 50-437 50-327 50-280 50-289	A A P P
	7811300223# 7812130214 7812060371 7812110264 781228033R#	50-318 50-356 50-155 50-482 50-329	8 0 0 A 0	DELOEORGE, L. D. DELGEORGE, L. D. DELGEORGE, L. D. DELLUMS, R. V.	7810240101 7811140175 7812050100 7812060153 7810110268	50-373 50-373 50-373 50-373 50-70	A H K F O	DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C. DEYDUNG.R.C.	7811300039 7811300042 7811300045 7811300046 7811300050	50-335 50-295 50-313 50-317 50-316	ր թ թ
	7812280017 7812280035 7812280045 7812280054 7812280060	50-263 50-171 50-272 50-397 50-266	Р Р Р	DELLUMS, R. V. DELLUMS, R.	7810110271 7810230084 7811130246 7811270297 7812210171	50-70 50-70 50-70 50-70 50-70	Q Q Q	DEYOUNG R. C. DEYOUNG R. C. DEYOUNG R. C. DEYOUNG R. C. DEYOUNG R. C.	7811300358 7811300364 7811300367 7811300376 7811300379	50-275 50-275 50-220 50-333 50-267	P P P
	7812280067 7812280071 7812280075 7812280077 7812280083	50-395 50-206 50-244 50-522 50-554	A P P A A	DENESS. B. J. DENISE. R. P. DENTON: H. R. DENTON: H. R. DENTON: H. R.	7811300215 7812200056 7811200432# 7811200434# 7811200110#	50-433 50-556 50-437 50-437 50-437	J H A A	DEYOUNG R. C. DEYOUNG R. C. DEYOUNG R. C. DIAZ N. J. DIAZ N. J.	7811300385 7811300389 7812070297 7810110196* 7810180081	50-277 50-312 50-448 50-83 50-83	ያ የ ል ያ
	7612280087 7812280090 7812280092 7812280094 7812280095	50-546 50-267 50-387 50-344 50-133	A P P P	DENTON; H. R.	7811200440# 7811200076# 7811200424# 7811200390# 7811200211#	50-437 50-437 50-437 50-437 50-437	A A A	DICKERBON, M. W. DICKERBON, M. W. DICKERBON, M. W. DICKERBON, M. W. DIENHART. A. V	7810110308* 7811210501* 7812060332* 7812180331* 7812070311	50-267 50-313 50-148 50-267 50-484	0 0 0 0
	7812280094 7812280098 7812280102 7812280103 7812280103	50-285 50-285 50-580 50-334 50-278	P	DENTON, H. R.	7811200302+ 7812190231 7810140043+ 7811280491 7810310240	50-437 50-70 50-213 50-331 50-847	A P U P P	DIOOS.R.M. DIOOS.R.M. DIOOS.R.M. DIOOS.R.M. DIOOS.R.M.	7811150159* 7812140340 7812180055 7812270375 7812290110	50-220 50-29 50-368 50-10 50-266	P P P

	ACCESSION	SUBJECT		ACCESSION NUMBER	BUBJECT CATEODRY	RDITUA	ACCEBBION	EUBJECT CATEGORY
AUTHOR DIOGRAR M DIONAN. T O DIONAN. T O DILLINBECK. L	7812290154 7811010244 7811080195 7812130090	0-366 P 50-443 P 50-443 P 50-368 P 50-220 P	DROMERICA A W DROMERICA A W DROMERICA A W DROMERICA A DUFLO H. E.	78121100B1 7812190175 7812200070 7810140148 7810140147	50-338 P 50-311 A 50-328 P 50-437 Q 50-509 Q	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7811170110 7811210389 7811280291 7811210300 7811290182	50-333 50-333 P 50-333 P 50-333 P 50-286 P
DIPIAZZAR P DIRCKS. H. J DIRCKS. H. J DIRCKS. H. J DIRCKS. H. J	7811030146 7809260256 7810110207* 7810110200 7810140036	50-70 50-70 90-70 90-70 90-70 90-70 90-70	DUFLO.M E  DUFLO.M E  DUFLO.M E  DUFLO.M E  DUFLO.M E	7810140108 7810230089 7810240046 7810300041 7810300133	50-275 0 50-516 0 50-320 0 50-483 0	EARLY, P. J. EARLY, P. J EARLY, P. J. EARLY, P. J. EARLY, P. J	7812040205 7812050139 7812050216 7812180388 7812110153	50-549 A 50-549 E 50-549 A 50-549 0 50-333 P
DIRCXS.H J LH.EX3RID LH.EX3RID LH.EX3RID LH.EX3RID LH.EX3RID LH.EX3RID	7810230038 7810240009 7810240115 7811080032 7811150207*	50-275 A 50-440 A 50-488 H 50-275 U 50-556 A 50-70 U	DUFLO: M. E. DUFLO: K. E. DUFLO: K. E.	7811010097 7811010101 7811010177 7811070034 7811080165	50-483 0 50-346 M 50-500 0 50-338 0 50-275 0	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7812120080 7812130168 7812170114 7812170180# 7812270140	50-333 P 50-286 Q 50-333 P 50-3 P 50-333 F
DIRCKS.H J DIRCKS.H J DIRCKS.H J DIRCKS.H J DIRCKS.K J	7811240091 7812010039 7812030043 7812080210 7812140297	50-70 U 50-70 U 50-471 U 50-213 U 50-302 U 50-70 H	DUFLO: M. E.	7811080001 7811200071 7811130090 7811170094 7811200046	30-489 0 30-346 M 50-336 0 50-336 0 30-366 0	ERNETER: 8. D EBNETER: 8. D EDNETER: 8. D EDNETER: 8. D EBNETER: 8. D.	7810270288* 7811130151* 7812010111* 7812120248* 7812180082*	50-311 8 50-387 0 50-29 0 50-363 0 50-20 0
DIRCKS. H J DIRCKS. H J DIRCKS. H J DISE, D P DISE, D P DISE, D P	7812060160 7812110068 781220193* 7810110089 7810170188	50-367 U 50-522 G 50-220 P 50-220 P 50-220 F	DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E.	7811220278 7811290312 7812040166 7812040179 7812060191	50-553 0 50-346 M 50-320 0 50-275 G 50-275 0	EBNETER: 9. D EBNETER: 8 D. ECKHARDT: J H ECKHARDT: J H ECKHARDT: J H	7612280319* 7812270457* 7810110212* 7810230094* 7812110240*	30-361 0 30-361 0 50-333 0 50-318 0
D18E. D P D18E. D P D18E. D P D18E. D P D18E. D P	7611070114 7611270172 7611240103* 7612050148 7612140136	50-220 P 50-220 F 50-220 0 50-220 P 50-220 F	DUFLO M. E. DUFLO M. E. DUFLO M. E. DUFLO M. E. DUFLO M. E.	7812110086 7812050302 7812060055 7812070268 7812130217	30-316 9 30-366 9 50-366 9 50-483 9 30-277 9	ECKHARDT, J. H ECONOMOB, N ECONOMOB, N ECONOMOB, N ECONOMOB, N.	7812270391+ 7811080314+ 7812050172+ 7812070320+ 7812270372+	50-369 0 50-369 0 50-269 0 50-269 0
DISE.D P DISE.D P DISE.D P DISE.D P DITTERT.J L	7812200194 7812270176 7812270240 7812270287 7810140083	50-220 P 50-220 P 50-220 P 50-220 P 50-486 0	DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E.	7812130203 7812140215 7812140337 7812180443 7812270119	50-556 0 50-513 0 50-513 0 50-338 0 50-443 0 50-546 0	ECONOMOS. N ECONOMOS. N EDDLEMAN. W EDDLEMAN. W EDDLEMAN. W.	7811290325* 7812280315* 7811140034 7811290059 7812140114*	50-387 0 50-375 0 50-400 0 50-400 0 50-400 0
DIVER. 8 9 DOBEL. D. C DODD. C. J. DODDS. R. T DODGE. W. A	7611070097 7610230170 7612050044* 7810260232* 7810180124	50-556	DUQQER, L. J. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N.	78122702620 78102701890 7810110144 7810160114 7810180072	50-285 8 50-334 0 50-334 P 50-334 R 50-334 P	EDDLEMAN H. EDGAR Q. L.	7612220121 7611040122 7611070340 7611210451 7611300054	50-400 Q 50-554 Q 50-556 Q 50-70 Q 50-70 Q
DOHERTY-J F DOHERTY-J F DOHERTY-J, F DOLAN-T, E DOLAN-J E.	7810110250 7812040038 7812040041 7810120042 7811080138	50-466 0 50-466 0 50-466 0 50-316 P 50-315 0	DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N.	7810200100 7811300243+ 7810270195 7811030107 7811160109	50-334 P 50-334 G 50-334 P 50-334 P 50-334 R	EDMARDS.O. W EFROB.M. EFROB.M. EFROB.M. EFROB.M.	7810230153 7811150232 7811270193 7811240083 7812130193	50-309 P 50-556 9 50-556 9 50-556 9
DOLAN, J.E. DONALDSON, D.E. DONALDSON, O.E. DONAT, T.J. DONAT, T.J.	7811210446 7811020188* 7811080268* 7811080198* 7811200024*	50-315 Q 50-271 Q 50-219 Q 50-327 Q 50-327 Q	DUNN, C. N DUNN, C. N DUNN, C. N DUNN, C. N DUNN ING, 1.	7812110128 7812210213 7812220071 7812260214 7810230142	50-334 R 50-334 P 50-334 P 50-334 P 50-206 F	eprob. M. Ehrensperoer. H. Ehrensperoer. H. Ehrensperoer. H. Ehrensperoer. H. Ehrensperoer. H.	7812110215 7811080162 7811200259* 7811210217 7811200173	50-554 9 50-424 A 50-424 A 50-424 A 50-424 A
DONAT, T. J DOUGHERTY, T. H. DOUGHERTY, T. H. DOUGLASS, R. H. DOUGLASS, R. H.	7812050076* 7810230383 7812290019 7810100051 7810110169	50-302 Q 50-437 Q 50-437 Q 50-317 S 50-317 B	DURDCHER, H. J. DURR, J. P. DURR, J. P. DURR, J. P. DURR, J. P.	7810190184 7810250207+ 7810190007+ 7810190006+ 7811140249+	50-344 T 50-387 G 50-320 G 50-320 G 50-322 G	EHRENBPEROER, W. EHRENBPERGER, W. EICHENHOL Z. H. EICHHDRW W. H. EIBENHUT, D. Q.	7812270145 7812270137 7811270134+ 7812180111 7812170178	50-424 B 50-424 F 50-271 P 50-347 9 50-70 P
DOUGLASE R M DOUGLASE R M DOUGLASE R M DOUGLASE R M DOUGLASE R M	7810130173 7810270235 7810310102 7810310197 7810310209	50-317 8 50-317 8 50-317 8 50-317 8 50-318 8	DURR, J. P. DURR, J. P. DYER, J. A. DYER, J. A. DYER, J. A.	7811130151% 78111702996 78110902799 78110801980 78120703150	50~327 Q	E I BENHUT, D. Q. E I BENHUT, D. Q. E I BENHUT, D. Q. E I BENHUT, D. Q. E I BENHUT, D. Q.	7811130059 7811130044 7811130082 7811130089 7811130100	50-10 P 80-213 P 50-217 P 50-245 P 50-27 P
DOUGLASS, R. M.	7811010113 7811030112 7811060155 7811130211 7811140164	50-317 8 50-317 8 50-318 8 50-318 8 50-318 8	DYM.H. EARLY.P.J. EARLY.P.J. EARLY.P.J. EARLY.P.J. EARLY.P.J.	7812260031 7812260019* 7810110094 7810110160 7810120055	50-389 M 50-247 P 50-286 P 50-286 P 50-333 P	EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EISENHUT, D. Q. EIBENHUT, D. Q.	7811130080* 7811130083* 7810300331 7811070042 7811170142*	50-250 P 50-250 P 50-260 P 50-348 P 50-344 P
DOW, H DOWELL, R, DOWNER, J. DOYLE, J.E. DRAKE, M.Q	7810270201 7810120072 7811070064* 7810270296* 7810270373*	50-330 A 50-329 A 50-568 A 50-237 B 50-341 Q	EARLY, P. J.	7810170175 7810240080 7810180075 7810170108 78101701114	30-333 P 30-349 A 50-333 P 50-333 P 50-333 P	EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. EISENHUT, D. Q. ELDER, Q. Q.	7812140033 7812270086* 7812120054 7812150321 7812200251*	50-213 P 50-320 9 50-280 P 50-3 P 50-537 A
DRAKE, M DRAKE, J. H DRAKE, J. H DRAKE, M DRAKE, J. H.	7810240212 7810260118* 7810260115 7812270129 7812190120	50-341 0 50-361 K 50-361 K 50-341 0 50-361 K	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7810230191 7810240109 7810270149 7811010111 7812040113	50-286 P 50-286 F 50-333 F 50-333 P 50-286 H	ELIABON, L. R. ELIABON, L. R. ELIABON, L. R. ELIABON, L. R. ELIABON, L. R.	7810240117 7810300145 7811210307 7812010215 7812210170	50-263 B 50-263 P 50-263 P 50-263 P 50-263 P
DRAKE, J. H. DREHER, F. A. DROMERION, A. H. DROMERION, A. H. DROMERION, A. H. DROMERION, A.	7812190124# 7810130187# 7810140042 7810230098 7810230002	50-341 K 50-556 Q 50-338 P 50-311 P 50-311 A	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7811030099 7811200023 7811080110 7811080183 7811080184	30-349 A 30-349 A 30-286 P 30-286 P 50-286 P	ELIABON,L.R. ELIN,J.C. ELLIOT,R.B. ELLIB,Q.B. ELLIB,L.J.	7812240193 78110100374 7811140138 78101702584 7812140247	50-445 A
DROMERICK, A. DROMERICK, A. DROMERICK, A. DROMERICK, A. DROMERICK, A. M. DROMERICK, A.	7811090034 7811220261 7811280397 7811290354 7812120240	50-311 A 50-311 A 50-339 A 50-311 A 50-339 A	EARLY: P. J.	7811080123 7811080127 7811080127 781114004 781114004 7811210274		enoelken R. H. Enoelken R. H. Enoelken R. H. Enoelken R. H. Enoelken R. H.	7810230305 7810230316 7810230320 7810230321 7810230325	50-344 9 50-133 9 50-204 0 50-312 0 50-397 0

### PERSONAL AUTHOR INDEX

50-294 50-294 50-259 50-259

50-296

7811140186 7811140201 7811140217 7811140240

7811160099

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCERSION NUMBER	TOSLEUB		AUTIOR	ACCESSION NUMBER	BUBJE
ENGELKEN R. H	7810300110	50-361 6	FASANO. A. N	7811140280	50-311		FIDRELLI, O.	7811300349	50-255
ENGELKEN R. H.	7810310357	50-528 8	FABANO. A. N.	78103002924	50-334	ă	FIORELLI. O.	7812010124	50-255
ENGELKEN R. H.	7812070238	50-361 0	FABANO. A. N	7812120026*	20-355	0	FIORELLI, O.	7812040124	50-305
ENGELKEN R. G. ENGELKEN R. H.	7811150005 7811150007	50-344 0 50-133 0	FABANO, A. N.	7812290220+	50-334	9	FIDRELLI, O.	7812050027#	50-10
				7811280250	50-556	B	FIGRELLI.O.	7812070074	50-263
ENGELKEN R. H. ENGELKEN R. H.	7811150009 7811150012	50-52B Q 50-312 G	FAULKENBERRY, D. FAULKENBERRY, B.	7812140039 <b>+</b> 7812130314+	50-312 50-275	0	FIORELLI, O. FIORELLI, O.	7812040033 7812040231	50-254 50-295
ENGELKEN R. H	7811150013	50-397 G	FAN.R.E.	7810110029	50-188	P	FIDRELLI. O.	7812140010	50-263
ENGELKEN R. H.	7811150019	50-204 0	FEE. W. F.	7810260171	50-213	P	FIDRELLI. O.	7812060072	50-409
ENGELKEN R. H.	7811220195	30-397 8	FEIERABEND. C. D.	7812200099*	50-282	a	FIORELLI. 9.	7812120225	50-305
ENGELKEN R. H.	7811300063	50-133 0	FEIST.C.K	7811220093	50-445	A	FIORELLI.O	7811200037	50-331
ENGELKEN R. H	7811300072	50-344 0	FEIST, C.K.	7812270259	50-445	K	FIORELLI.O.	7811200045	50-315
ENGELKEN R. H. ENGELKEN R. H.	781130007 <i>6</i> 7811300082	50-528 G 50-397 G	FELDMANN H. J. FELTON, J. H.	7810250107	50-293	P	FIORELLIO FIORELLIO	7812120216 7812200091	50-331 50-282
ENGELKEN R. H.	7811300088	50-275 0	FELTON, J. H.	7810270199 7811010353	50-330 50 <b>-</b> 331	A G	FIGRELLI. G.	7812140141	20-599
ENGELKEN R. H.	7811300090	30-361 0	FELTON, J. M.	7811010008	50-329	A	FIDRELLI, O.	7812210046	50-282
ENGELKEN R. H.	7811300092	50-312 0	FELTON, J. M.	7811020236	50-245	Ö	FIDRELLI, Q.	7812200105	50-263
ENGELKEN R. H.	7811300097	20-509 0		7811070268	50-245	P	FIORELLI. O	7811200480	50-331
ENGELKEN R. H. ENGELDER: T. C.	781211019B 7812200156	50-50B Q 50-13 Q		7811210403 7811220128	50-382 5 <i>0-26</i> 7	H	FIORELLIO. FIORELLIO	7812270062 7812210041	50-346 50-358
				1911840189	30-257	U			
ENGELKEN, R. H. ENGELKEN, R. H.	7812210110 7812210261	50-528 B	FELTON, J. M. FELTON, J. M.	7812060296 7812070052	50-466 50-373	A	FIDRELLI.O. Fidrelli.o	7812290068 7812290009	50-266 50~305
ENGELKEN R. H	7812290030	50-133 0	FELTON J. M.	7812180321	50-3/1 50-267	A	PIDRELLI, G.	7812290009	50-255
ENGELKEN R. H.	7812290033	50-275 0	FEROUSON, J. H.	7810250110	50-213	8	FIORELLI.O	7812290022	30-596
ENGELKEN R. H.	7812290036	50-528 0		7812110069*	50-522	ō	FIDRELLI. 0	7812260292	50-254
ENGELKEN R. H.	7812290085	50-344 Q	FERRIBIM J.	7812130179*	50-267	8	FIORELLI, Q.	7812240293	50~255
ENGELKEN R. H.	7812290094	50-312 @		7812280234*	50-219	8	FIORELLI, O.	7812260302	50-155
ENGELKEN R. H. ENGELKEN R. H.	7812290098 7812290099	50-206 G 50-361 G		7812260014	50-247	P	FIDRELLI, Q. FIDRELLI, Q.	7812240308 7812270028	50-263
ENGELKEN R. H.	7812290103	50-357 G		7812270138 7810130223	50-247 50-395	O J	FIRESTONE, L	7810130161+	50-580 50-282
ENOLE, L. B.	7810120094	50-368 P	F1EDLER.J.	7812010256	50-259	J	F18CHER.D.	7810270110	50-70
ENOLE, L. B.	7810230309*	50~368 P	FINFROCK I.R.	7811080189•	50-363	0	FIBH. R. F.	7812140072*	50-70
ENOLE, L.	7811170223	90-369 P	FINFROCK, I. R	7810110118	50-219	P	F18H.R.F.	7812190197#	50-133
ENGLE, L. S. ENGLE, L.	7811140061 7811200129	50-368 P		7810160115	50-219	P	FISHER, H.L. FISHER, J.R.	7910110062*	50-10
				7810160120+	50-219	Р		7810120042*	50-305
ENOLE, L. B.	7811200378	50-348 P		7810160143	50-219	P	FISHER. N. L.	7811070040+	50-2
ENGLE, L. B. EPLER, E. P.	7812140020* 7811010251	50-368 P 50-572 0		7810170200 7810170240	50-219 50-219	R P	FIBHER, W.L. FIBHER, W.L.	7811060080* 7812200302*	50-254 50-255
EPBTEIN.E.	7010300351+	50-201 G		7B10270094	50-219	R	FITCH, H. A.	7811170173	50-568
ERB. C. M.	7810260184=	50-341 0		7811070304	50-219	P	FITE, J. P.	7811080225	50-445
ERB. C. M.	7811010059*	50-373 0		7811030114	50-219	P	FLEISCHWER. O.	7810160155	50-275
ERB, C. M.	7811300221*	50-358 0	FINFROCK, I.R.	7811070105	50-219	9	FLEISCHARER. D.	7810190257	50-275
ERB.C.M. ERICKBON.P.	7812050241* 7811070050	50-456 G 50-335 P		7811220129	50-219	P	FLEISCHAKER.D. FLEISCHAKER.D.	7810190262*	50-275 50-275
ERICKBON P. B.	781 1280073	50-335 P		7812180161* 7811200160	50-363 50-219	Q P	FLEISCHAKER, D.	7810190267 <b>+</b> 7810190269+	50-275
EBSIO, T. H.	78101102704	50-346 0			50-219	P	FLEIBCHAKER. D.	7810270294	50-275
EBBIO, T. H.	78120100704	50-305 0		7811200164* 7811240194	20-513	F	FLEIBCHAKER, D.	7810270294	50-275
E9910, T. H	7812280229*	50-456 Q	FINFROCK 1. A.	7811280262	50-219	P	FLEIBCHAKER. D.	7811130314	50-275
ESBIG.T.H. EBTES.J.	7812290063 7811200268	50~255 Q		7812120127*	50-219	8	FLEIBCHAKER, D. FLEMING, B. T.	7812010048 7811210385•	\$0-275 50-213
				7812120133	50-219	D			-
ETHER INGTON, H.	7811100051	50-280 T 50-298 G	FINFADOK 1. R.	7812120136	50-219	8	FLEMING B. T.	7811210311*	50-213
EVANB, E. A. EVANB, D. J.	7811200330* 7811080144	50-298 G		7812120123 7812180204	20-514 20-514	8	FLIEGEL•M. H FLYNN•J.D.	7811070293 7812200148	50-387 50-358
EVANS, C. A.	7812070002	50-12B Q		7612180204	30-219	9	F009. H. C.	7811210172	50-155
EVANS, C. A.	78121804244	50-59 0		7812190105	50-219	9	F000. W. O.	7812270146	50-255
EVANS. D. J.	7812270037	50-305 0		7812270185	50-219	ρ	FOLEY. T.	7812010134+	50-219
EVERETT,R.J.	7811170174*	50-556 Q	FINKEL, A. E.	7810270286*	50-311	Q	FOLSOM, B. A.	7811010135*	50-443
EVRAETS: J. C. EHALD: S. C.	7812080099	50-142 P 50-327 0		7812060337	50-331	<b>Q</b>	FOLSOM. B. A. FONTANA.L.	7811100097# 7811080180	50-443 50-382
EWALD, S. C.	7810270221* 7811240081*	20-305 0	FIORELLI, O. FIORELLI, O.	7810110182 7810110218	50~305 50~358	G G	FONTANA.L.	7811210408	50-382
EHALD. B. C.	7812110225*	50-280 0			50-315		FONTECILLA, H. M.	7811130315	50-244
EWING, T.N.	7810240095	50-280 0		7811080104# 7810250216	50-315	Q Q	FONTECILLA, H. M.	7812040194	50-10
EWING, H. C.	7811240186	50-329 A	FIDRELLI, O.	7811010067	50-254	ŏ	FONTECILLA, H. M.	7812040198	30-213
EWING, T.N.	7811130222	50~556 A	FIORELLI.O.	7810270371	50-301	Q	FORTUNA R. A.	7810300281*	50-389
EWING, T. N.	7811140192	50-556 L	FIDRELLI. O.	7811010018	50-10	Q	FORTUNAIR. A.	7810310030	90-400
EWINO, T. N.	7811160081	50-556 A		7811010016#	50-10	G C	FOBTER, J.E. FOBTER, J.E.	7810110274*	50-35B
EWINO, T.N. EWINO, T.N.	7811140214 7812220115	50-556 B		7810270385 7810310029	50-315 50-182	a a	FOSTER, J. E. FOSTER, M. H.	7811170264= 7810310030	00-358 50~400
EWINO, T.N.	7812220115	50-556 A		7811010027	50-10	o o	FOSTER, E.R.	7811090133*	50-423
FAHRNERIW, J.	7811070076	50-341 B		7810310335	50-316	ā	FOSTER, J. E.	7812290247*	101-06
FAHRNER, W. J.	7811090169	50-341 8	FIORELLI. 9.	7811300314	50-255	a	FDX. A.	7811200179	50-70
FAIN, T. Q.	7811150176*	50-327 A	FIDRELLI.O.	7811130004	50-331	G .	FOX, H. B.	7810100002	50-296
FAIRODENT, J. E.	7810300050	50-341 A		7810110297	50-315	o .	FOX.H.B.	7810100042	50-296
Fairtile n. 8. Fairtile m.	7810260149 7811210032	50-269 P		7810110197 78110800&6	50-282 50-295	G G	FOX. H. B. FOX. H. B.	7810100036 7810180138	50~259 50~260
				\a1100000		u			
FAIRTILE M.	7812060019	50-269 F		7811090192	50-315	o .	FOX. H. S.	7810240144	50-296
FARON: R. B. FARRARI D.	7812220113 7812180177*	50-244 P 50-10 B		7811140264 7811150033	50-373 50-346	g Q	FOX. H. B. FOX. H. S.	7810300168 7810310183	50-250 50-259
FARRIB, J. R.	7810250075	50-556 0	FIORELLI.O.	7811210214	50-331	ã	FOX, H. S.	7811140165	50-296
FARRIS, J. R.	7811150232	50-556 9		7811210415	50-266	ā	FOX. H. S.	7811140168	30-298

50-320 50-266 50-10 50-10

50-155

99999

7811290324

7811290333 7811300261 7811020335

7811300135

FOX, H, S. FOX, H, S. FOX, H, S. FOX, H, S.

FOX. H. 8.

FARRIS, J. R.

FARRIS, J. R. FABANO, A. N. FABANO, A. N. FABANO, A. N.

7811270193

7811240083 7810250207\* 7810190007\*

7810190006#

30~356

50-356 50-387 50-320 50-320

00000

FIORELLI.Q.

FIDRELLI.O. FIDRELLI.O. FIDRELLI.O.

PIORELL 1. Q.

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	EURJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
FOX.H B FOX.H B FOX.H S FOX.H S FOX.H S	7811280214 7811280167 7811280294 7811280205 7811280201	50-259 9 50-259 50-276 8 50-259 9 50-260 B	GAMI, J. H. GAMI, J. H. GAMI, J. H. GAMI, J. H. GAITANIB, M. J.	7812130179# 7812130185* 7812200210* 7812270206* 7811130375	50-267 8 50-267 8 50-267 8 50-267 8 50-267 8	OIAMBUSED, A. OIAMBUSED, A. OIAMBUSED, A. OIBBUNS, T. D. OIBBUNS, T. D.	7811200331* 7811200026* 7811200291* 7810110194* 7811090238*	50-437 A 50-437 A 50-437 A 50-439 @ 50-373 0
FOX.H S FOX.H S FOX.H S FOX.H S	7812050199 7812080101 7812110148 7812120174 7812190110	50-296 8 50-260 8 50-296 8 50-260 8 50-296 8	GAITANIS M J. GALLAGHER E J. GALLAGHER E J. GALLAGHER E J. GALLAGHER E J.	7811220062¢ 7810110184¢ 7811210112¢ 7811170264¢ 7812030241¢	50-549 T 50-367 Q 50-440 Q 50-338 Q 50-456 Q	OIBBONS.T.D. OIBBONS.T.D. OIBBS.M.E. OIBBS.M.E. OIBBB.M.E.	7612060274* 7612120045* 7610110309 7611150060 7611210036	50-327 G 50-395 G 50-329 O 50-329 O 50-329 O
FDX.H 8 FDX.H 9 FDX.H 5 FRAMM.R K. FRALEY, R. F	7812190119 7812270265 7812290221 7810140026+ 7811200239+	50-296 S 50-259 S 50-260 S 50-556 Q 50-437 A	CALLAGHER, P. M. CALLAGHER, E. J. CALLAN, K. P. CALLAGHER, E. J. CALLAGHER, K. R.	7811060034 7811300260* 7811080329 7812190160* 7812190169	50-361	01888, M.E. 01888, M.E. 01888, M.E. 01888, M.E. 01880N, O. T.	7612140087 7612140362 7612160383 7612260350 7610260073+	50-229 Q 50-229 Q 50-229 Q 50-220 Q
Franson, R S Franson, M B Franson, R S Franson, R S Franson, R S Franson, L	7810240033 7811210245 7811210249 7812050291 7810310092	30-466	GALLINA.C. GALLO.R.M. GALLO.J. GALLO.J. GALLO.J.	7812150240# 7810250207# 7810160202 7810170216 7810250021	50-245 G 50-387 G 50-556 G 50-556 G 50-556 G	01880N, A.F. 01880N, A.F. 01880N, O.T. 01880N, A.F. 01880N, A.F.	7810180192* 7810190177* 7811010411* 7811130049* 7810230036*	50-335 G 50-389 G 50-250 G 50-259 G 50-369 G
FRANKLIN, W J FRANKLIN W J FRAZAR-R. A FRAZAR-R. A FREEDKIN S	7812280249 7812270405 7812040127* 7811030214 7811010013*	50-498 M 50-498 M 50-498 G 50-498 S 50-329 A	QALLO: J. QALLO: J. QALLO: J. QALLO: J. QALLO: J.	7810260199 7811010433 7811130066 7811130252 7811240076	50-556 @ 50-556 @ 50-556 @ 50-556 @ 50-556 @	01890n, A.F. 01880n, A.F. 01880n, A.F. 01880n, Q.T. 01880n, A.F.	7810130064* 7810310054* 7811010171* 7811030235* 7812050031*	50-269 G 50-230 G 50-335 G 50-269 G
FREEDKIN S FREEMON A M. FRIEDELL E. FRIEDELL E B FRIEDELL E. B.	7811010010+ 7812050251+ 7810110037 7810140044+ 7810130242	50-329 A 50-259 P 50-466 0 50-466 Q 50-452 Q	GALLO, J. GALLO, J. GALLO, J. GALLO, R. M. GALLO, J.	7812050281 7812040235 7812070008 7812290238* 7812110107	30-336	01880n. A.F. 01880n. A.F. 01880n. A.F. 01880n. A.F. 01880n. A.F.	7812040337* 7811240057* 7812040033* 7812070312* 7812110225*	50-269 Q 50-238 Q 50-259 Q 50-261 Q 50-280 Q
FRIEDELLE 9 FRIEDELLE 9 FRIEDELLE 9 FRIEDELLE 6 FRIEDELLE 9	7810240030 7810300252 7811070172 7811140094 7811130038	50-466	Gallo. J. Gallo. J. Gallo. J. Gallo. J. Gambardella. A.	7812050347 7812040014 7812140078 7812140285 7811080035	50-556 T 50-556 T 50-556 0 50-556 0 50-338 0	GIBSON, A.F. GIBSON, G.T. GIBSON, G.T. GILBERT, L.D. GILBERT, R.A.	7812280348* 7812140122* 7812210076* 7810250015* 7810120097	50-250 G 50-348 G 50-250 G 50-445 G 50-592 A
FRIEDELLES FRIEDELLES FRIEDELLES FRIEDELLES FRIEDELLES FRY.D.N	7811280483 7812050085 7811220097 7811280143 7812270182	50-219 0 50-219 0 50-466 0 50-466 0 50-267 P	OAMBLE.F.W. GAMMILL.H.P. DAMMILL.W.P. GAMMILL.W.P. GARDEBRING.B.	7811220192+ 7812180330 7812180425 7811270211 7812260328+	50-286 8 50-70 P 50-70 P 50-267 P 50-263 P	GILBERT.R.A. GILBERT.B. GILBERT.L.D. GILBERT.B. GILBERT.R.A.	7810130093 7810230126 7812060342* 7811160053 7811270054*	50-592 A 50-466 G 50-445 G 50-466 G 50-460 A
FRYLING.C. FRYLING.R. FUCHKO.J. M FUJITA.T. T FULLER.J.K.	7811280159+ 7812280046 7812290112+ 7812200053 7810100005	50-458 1 50-272 0 50-302 0 50-70 P 50-267 P	GARDEBRING.8.8. GARFIELD.G. GARRETT.8.M GARRETT.8.M. GARRETT.8.M.	7812270023* 7811010166 7812260061 7811020235 7812260332	50-263 H 50-245 P 50-344 G 50-344 O 50-344 O	OILINBKY, V. OILINBKY, V. OILINBKY, V. OILINBKY, V. OILLELAND, J. E. OILLELAND, J. E.	7811200015* 7811060260 7811200013* 7810310064* 7811020074	50-407 / 50-407 ( 50-407 / 50-259 ( 50-400 /
FULLER, J. K FULLER, J. K FULLER, J. K. FULLER, J. K. FULLER, J. K.	7810100012 7810110136 781018014] 7810170139 7810170174	30-267 P 30-267 P 30-267 P 30-267 P 30-267 F	GARY: R. J. GARY: R. J. GARY: R. J. GARY: R. J. GARY: R. J.	7810240221* 7810240161 7810240186 7811030249* 7811070260*	30-445 G 30-445 A 50-445 A 50-445 G 50-445 G	OILLEBPIE.F.P. OILLELAND.J.E. OILLELAND.J.E. OILLELAND.J.E. OILLEBPIE.F.P.	7811130007# 7811070236 7810190164 7810230135 7811100130#	50-250 C 50-327 E 50-327 F 50-267 C
FULLER, J. K.	7810310094 7810250047 7810260205 7810310085 78111160096	30-267 P 30-267 P 30-267 P 30-267 P 30-267 F	GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J.	7811280367 7811080033 7811070134 7811300109* 7811300020*	50~445 8 50~445 0 50~445 8 50~445 0 50~445 0	OILLELAND, J. E. OILLELAND, J. E. OILLEBPIE, F. P. OILLELAND, J. E. OILLEBPIE, F. P.	78102302274 7811070245 7810110059* 7811030078* 7810140060*	50-259 50-816 50-259 50-438 50-297
FULLER, J. K. FULLER, J. K. FULMER, B. FULMER, B. FURBUSH, M. H.	7812070186 7812270177 7811030158* 7811210359* 7811010039	50-267 P 50-267 P 50-346 8 50-346 8 50-275 0	GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J.	7811170133 7811210401 7812190142* 7812190232 7611210348	50~445 A 50~445 B 50~445 G 50~445 G 50~445 A	OILLETT,W.T. OILLELAND,J.E. OILLELAND,J.E. OILLELAND,J.E. OILLELAND,J.E.	7810200036# 7810110136 7810110107 7810120065 7810190228	50-316 50-327 50-259 50-259 50-390
FURR, B. J FURR, B. J FURR, B. J FURR, B. J FURR, B. J	7810110229+ 7810310123 7811090013+ 7811160137 7812070065+	50-261 0 50-261 8 50-324 0 50-325 6 50-261 0	GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J. GARY, R. J.	7811280183 7811280218 7812070111 7812150264 7812200184	50~445 8 50~445 A 50~445 K 50~445 C 50~445 A	OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7811070276 7810170206 7810180093 7810230244 7811130013+	50-327 50-390 50-327 50-259 50-259
FURR. B. J. FURR. B. J. FURR. B. J. FURR. B. J. GAD. R. K.	7611160138 7612200198 7612200200 7612270268 7611010244	50-325 8 50-324 8 50-324 8 50-325 8 50-443 9	CARY, R. J. Cabchler, J. A. Cabe, E. D. Casber, R. A. Cateb, O.	7812280109 7812120089 7812170020+ 7811240032+ 7810100014+	50~445 B 50~267 B 50~70 P 50~363 H 50~265 B	GILLELAND, J. E.	7811080254* 7811030265* 7811030265* 7811070204* 7811060090	50-430 ( 50-327 ( 50-327 ( 50-259 (
GAD.R.K. GAFFNEY.C. GAPM.J.H. GAPM.J.H. GAPM.J.H.	7811080195 7812200185* 7810300194* 7810160103* 7810300190*	50-368 0 50-293 R 50-267 8 50-267 R 50-267 8	GATEB, G. GAZLEY, C. GEHR, A. C. GEDRGE, J. GEDRGE, K. D.	7810110114+ 7811200019+ 7811020082 7812270059 7812190091	30-285 S 30-437 A 50-592 M 30-275 H 30-34 P	OILLELAND, J. E.	7810240153 7811030257 7810240144 7810250082 7810250088	50-259 50-428 50-259 50-260 50-566
OAPM, J. H. OAPM, J. H. OAPM, J. H. OAPM, J. H.	7810300313* 7810270232* 7810270283* 7810310230* 7811070238*	50~267 8 50~267 8 50~267 8 50~267 8 50~267 8	GERLACH, D. GERBTNER, H. C. GETTY, B. C. GIAMBUBBO, A. GIAMBUBBO, A.	7819280277* 7810110057* 7812150311* 7811200096* 7811200002*	30-267 H 50-461 G 30-133 R 50-437 A	OILLELAND, J. E.	7610250095 7810250120 7810300103 7810310113 7811070277	50-027 50-327 50-259 50-327 50-327
OMM, J. H. OMM, J. H. OMM, J. H. OMM, J. H.	7811280289• 7811280318• 7812130141• 7812130141• 7812130192•	50-267 8 50-267 8 50-267 8 50-267 9 50-267 9	CIAMBUSSO, A. CIAMBUSSO, A. CIAMBUSSO, A. CIAMBUSSO, A. CIAMBUSSO, A.	7811200067* 7811200406* 7811200213* 7811200208* 7811200339*	50-437 A 50-437 A 50-437 A 50-437 A 50-437 A	GILLELAND, J. E.	7810250080 7812040192 7810310074 7812050125# 7812010266	50-296 50-327 50-259 50-327 50-327

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	NOIBBBODA REBHUN	SUBJECT CATEGORY	,	AUTHOR	ACCESSION NUMBER	BUBJEC CATEGO
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7811020231 7812040226 7811010073 7811060063 7811060094	50-43B K 50-390 8 50-327 A 50-390 8 50-327 A	OIRARD.E. H. GIRARD.E. H. GITTON.E. C. GLABER.M. GLENN.J.	7811150067* 7812180343* 7811200019* 7812130003 7810240011*	50-395 50-400 50-437 50-445	G G A N	ORAVEG. R. H. GRAVES. R. H.	7812050140 7812050134 7812210201 7812220061 7810140150	50-213 50-213 50-213 50-213 50-213
GILLELAND, J.E. GILLETT, W.T. GILLELAND, J.E. GILLELAND, J.E. GILLESPIE, F. P.	7811080164 7811210391* 7811210438* 7811080160 7812110251*	50-51B A 50-315 R 50-316 R 50-390 F 50-324 Q	OLENN, J. OLENN, J. ODAO, L. F. ODDDARD, R. J. OODDARD, R. J.	7812190236 7812120041* 7812210200* 7810300324 7810310223	50-580 50-275 50-237	0 H 4 0 0	GRAY, J. R GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R.	7810260227 7810300070 7811020270 7811030237 7811020325	50-344 50-344 50-344 50-344 50-344
OILLELAND, J. E. QILLELAND, J. E. QILLELAND, J. E. QILLELAND, J. E. QILLELAND, J. E.	7811220091* 7812080213 7811070132 7811080114 7811080132	50-260 G 50-518 B 50-296 P 50-390 A 50-390 K	QODDARD,R.J. QODDARD,R.J. QODDARD,R.J. QODDARD,R.J. QODDARD,R.J.	7811130216 7811220233 7811220010 7811300147 7812050054	50-237 50-237 50-295	0 0 0 p	GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R.	7811030176 7811160001 7812040253 7812080048 7812070228	50-344 50-463 50-344 50-344 50-344
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E.	7612040055# 7812050245 7811140047 7811150128 7811150129#	50-390 Q 50-327 B 50-438 6 50-260 P 50-260 P	QDDDARD, R. J. QDDDARD, R. J. QDDDARD, R. J. QDLDBERQ, B. C. QOLDBERQ, B. C.	7812080158 7812270371 7812270230 7810180176 7810230120	50-295 50-10 50-395	H 9 0 0 0	ORAY, J. R. GRAY, J. R. GRAY, J. R. GRAY, J. R. OREENE, T.	7812070231# 7812130096 7812140084 7812190171 7812270285#	50-344 50-344 50-344 50-321
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLEBPIE, F. P. OILLELAND, J. E.	7811150137 7811220147 7812040121 7812210343* 7811140134	50-327 A 50-390 A 50-327 B 50-259 Q 50-327 F	OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C.	7810140009 7810230369 7810310332 7811130091 7811060129	50-395 50-395 50-338	00000	GREENMAN. E. G. GREENMAN. E. G. GREENE, T. GREENE, T. GREENE, T.	7811020186* 7811090058* 7810170238* 7810170230* 7810170261*	50-223 50-277 50-366 50-321
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLESPIE, F. P.	7811150123 7811150132 7812050266 7812060074* 7811210289*	50-327 F 50-327 A 50-390 B 50-327 G 50-338 G	GOLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C.	7811060193 7811070366 7811130116 7811160170 78111200068	50-395 50-395 50-302	0 F 0 0	OREENE, T. OREENE, T. OREENHOOD, J. OREENE, T.	7810170298* 7810170237* 7810180118* 7811210349 7810180022*	50-321 50-321 50-366 50-301 50-366
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7811170113 7811170175 7812130372 7811160098 7811160148	50-259 P 50-259 P 50-259 0 50-327 A 50-327 A	OCLDBERG, 8. C. OCLDBERG, 8. C. OCLDBERG, 9. C. OCLDBERG, 9. C. OCLDBERG, 9. C.	7811200288+ 7812130080 7812130084+ 7812210264 7812140273	50-302 ( 50-302 (	00000	OREENMAN E. OREENE, T. OREENE, T. GREENWOOD, J. GREENE, T. V.	7812010031# 7810160024# 7810180024# 7811210393 7810230190#	50-277 50-366 50-266 50-266 50-366
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLEBPIE, F. P. OILLELAND, J. E.	7812050117# 7811200200 7811210406 7812270112# 7811220211	50-327	OOLDMAN; M. OOLLER; K. R. OOLLER; K. R. OONZALEB; R. O. OODDHOPE; A. C.	7810140045* 7811200078* 7810130107 7811200362 7811220086	50-437 50-70 50-592	U A P A Q	GREENE, T. V. GREENMAN, E. GREENE, T. GREENE, T. V. GREENE, T. V.	7810310150* 7819060219* 7810310182* 7811140254* 7811060138*	50-321 50-20 50-321 50-366 50-321
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812070250 7812080229 7811280251 7811280255 7812040021*	50-390 8 50-390 8 50-438 A 50-296 F 50-259 0	OCCDHOPE, A. C. OCCDHOPE, A. C. OCCDHOPE, A. C. OCCDHOPE, A. C. OCCDHOPE, A. C.	7812040200 7812140047 7812280265 7812280303 78121101724	50-549 50-549 50-549	9 9 0 0	oreen.d. Oreenberg.m. Oreene.t. Oreene.t. Oreene.t.v.	7811140140+ 7811220070+ 7811210346+ 7812180170+ 7812180205+	50-259 50-549 50-321 50-321 50-366
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLEBPIE, F. P.	7811270248 7812110017 7812140286 7812140288* 7812140287*	50-390 K 50-390 E 50-327 E 50-327 E 50-406 G	GOODMAN, R. E. GOODMAN, R. E. GOODMIN, C. GOODMIN, C. GOODMIN, C.	7812110177* 7812180218* 7810120009 7810180070 7811010075	50-10 . 50-344 ! 50-344 !	J P P	OREENE, T. V. OREER, R. J. OREER, R. J. OREEVEB, J. T.	7810180217# 7810300383# 7811090303# 7812270063 7811030259	50-246 50-315 50-255 50-255 50-70
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812050171 7812050243 7812070177 7812200244 7812050189	50-276 P 50-259 P 50-327 Q 50-259 K 50-259 P	ODDHIN,C. ODDHIN,C. ODDHIN,C. ODRDDN.H. J. ODRE, A. S.	7811070162 7811140159 7812280128 7810110025 7810120085*	50-344 8 50-344 8 50-269 8	P K P B	OREEVEB.J.T. OREEVEB.J.T. OREOER.L.R. OREOER.L.R. ORIBBON.D.M	7819260096 7819280281 7810110062* 7811090040* 7812280051	50-18 50-361 50-10 50-2 50-389
OILLETT, H. T. OILLETT, H. T. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812200174* 7812200205* 7812080091 7812070170 7812070183	50-315 R 50-316 R 50-327 A 50-257 P 50-566 A	90RE, J. W. 90881CK,L.Y. 90881CK,L.Y. 90881CK,L.Y. 90881CK,L.Y.	7810170162 7812050283 7812050284* 78120502874 7812050293*	50-437 50-437 50-437	P A A A	ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H.	7812050004 7811060239* 7812130092* 7811010127 7810160232	50-3 50-3 50-352 50-443 50-352
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812150350 7812110142 7812120075 7812120099 7812120168	50-327 A 50-327 A 50-390 A 50-390 G 50-327 A	90881CK, L. V. 90881CK, L. V. 90881CK, L. V. 90881CK, L. V. 9000E, M. J.	7812050297* 7812050301* 7812200346 7812210336 7811290323*	50-437 50-363 50-259	A A A H G	ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H.	7810160236 7810160238 7810160240 7810160241 7810160243	50-29 50-277 50-334 50-286 50-219
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812120166 7812120170 7812180130 7812290043* 7812290117*	50-327 K 50-327 A 50-327 A 50-327 A 50-327 Q	QOULD, W. R. QOULD, W. R. QOULD, W. QOWER, Q. C. QRAHAM, R. L.	7810130160* 7811160082* 7812170157* 7812080041 7811160050	50~206 F 50~206 F 50~184 (	R R R 0 0	ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H.	7810160246 7810160246 7810160250 7810160255 7810160257	50-3 50-309 50-289 50-322 50-443
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLEBPIE, F. P.	7812290058* 7812150248 7812200154 7812200256 7812210287=	50~438 0 50~296 0 50~259 P 50~259 P 50~276 0	Oraham, S. A. Orant, J. S. Orant, H. B. Orant, J. S. Orant, J. S.	7812180324 7811200067 7812010286* 7811150124 7811240159	50-346		ORIER, B.H. ORIER, B.H. ORIER, E.H. ORIER, B.H. ORIER, B.H.	7810170001 7810170003 7810170023 7810170024 7810170025	50-367 50-465 50-271 50-412 50-363
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812240163 7812210248 7812270175 7812270202 7812260131	50-259 P 50-327 F 50-259 P 50-327 A 50-327 K	GRAVES, R. H. GRAVES, R. H. GRAVES, R. H. GRAVES, R. H. GRAVES, R. H.	7611240163 7611210376 7611210306 7610130166 7610180134	50-213 6 50-213 6 50-213 6	8 8 8 8 R	ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7810170026 7810170029 7810170030 7810180291 7812070290+	
GILLELAND, J. E. GILLELAND, J. E. GILLILAND, O. L. GILHAN, D. H. GIRARD, E. H.	7812290217 7812290126 7812280275 7810260118* 7811080158*	80-259 P 50-390 A 50-70 P 50-361 K 50-395 G	ORAVES, R. H. ORAVES, R. H. ORAVES, R. H. ORAVES, R. H. ORAVES, R. H.	7810240093 7810250106 7811060103 7811910282 7811910212	50-213 E	R 8 9 R P	ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H.	781 1060171 781 1060173 781 1060174 781 1060176 781 1060178	50-333 50-272 50-244 50-273 50-271

AUTHOR	ACCEBBION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY
ORIER, B.H. ORIER, B.H ORIER, B.H ORIER, B.H ORIER, B.H	7811060181 7811060182 7811060184 7811060186 7811060188	50-29 G 50-213 G 50-286 G 50-289 G 50-317 G	ORIER.B.H GRIER.B.H ORIER.B.H. GRIER.B.H. ORIER.B.H.	7812150049 7812150121 7812150125 7812150131 7812150131	50-387 0 50-293 0 50-317 0 50-213 0 50-3 0	GROCE, R. H.	78112700Bb 7811270130 7811280221 7812010214 7812040171	50-309 P 50-271 P 50-27 P 50-309 0 50-29 P
GRIER. B. H GRIER. B. H ORIER. B. H ORIER. B. H ORIER. B. H.	7811060190 7811060192 7811060195 7811060197 7811060198	50-387 0 50-309 0 50-322 0 50-219 0 50-334 0	GRIER.B.H. GRIER.B.H GRIER.B.H GRIER.B.H. GRIER.B.H.	7812150136 7812150140 7812150142 7812150144 7812150146	50-334	OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H.	7812050128 7812050130 7812140145 7812200230 7812200220	50-27 F 50-271 F 50-27 P 50-27 P 50-27 P
GRIER.B H GRIER.B H ORIER.B.H ORIER.B.H GRIER.B.H	7811040201 7811040203 7811040205 7811040208 7812040275	50-3 0 50-277 6 50-245 0 50-240 0 50-184 0	ORIER. B. H. GRIER. B. H. GRIER. B. H. GRIER. B. H. GRIER. B. H	7812150150 7812150155 7812150158 7812150160 7812150169	50-245 0 50-277 0 50-286 0 50-363 0 50-322 0	ORDNBERO, W. L. ORDNBERO, W. L. ORDSBMAN, M. J. ORDSBMAN, M. ORDSBMAN, J. B.	7810110156 7811070126 7810250152 7812120020* 7812270123	50-333 P 50-333 F 50-329 0 50-424 0 50-389 H
ORIER. B H ORIER. B H ORIER. B H ORIER. B. H. ORIER. B H	7812130071 7811080043 7811060224 7811100036 7811100120	50-352	GRIER. 8. H GRIER. 8. H GRIER. 8. H. GRIER. 8. H. GRIER. 8. H.	7812150171 7812180022 7812180025 7812180025 7812180030	50-410	OROSSMAN. J. B. OROTENHUIB: M. OROTENHUIB: M. OROTENHUIB: M. OROTENHUIB: M.	7812280051 7810300100 7810250252 7812170154 7812180378	50~389 N 50~282 P 50~250 P 50~262 P 50~250 P
ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H.	7812010272 7811130115 7812010345 7812080144 7812080145	50-245 0 50-272 0 50-3 0 50-334 0	GRIER.B.H. GRIER.B.H. GRIER.B.H GRIER.B.H GRIFFITHB.R.	7812180032 7812180034 7812180310 7812219053 7811280275	50-244 0 50-333 0 50-333 P 50-245 0 50-272 J	ORDVE, P. A. OUASCO, Q. OUMBLE, F. W. OUMBLE, F. W. OUMBLE, F. W.	7810310207 7810160151+ 7810100100+ 7810120060+ 7811060215+	50~133 P 50~409 P 50~286 8 50~286 8
ORIER. 8 H. ORIER. 8 H. ORIER. 8 H. ORIER. 8 H. ORIER. 8 H.	7811290139 7811290142 7811290145 7811290149 7811290151	50-410 0 50-387 0 50-271 0 50-412 0 50-29 0	Grimes, B. K. Grimes, C. Grimes, C. Grimes, B. K. Grimes, B. K.	78121303B5* 7810140015* 7811130335 7811270103* 7811220279	50-344 P 50-298 P 50-219 P 50-263 P 50-224 P	GUMBLE, F. W. GUTTERMAN, A. H. GUTTMAN, D. HAABS, W. P.	7812220098# 7810240037 7812180339 7812180342# 7811170088	50-286 8 50-566 9 50-389 M 50-361 A
ORIER. B H.	7811290154 7811290158 7811290160 7811290164 7811290170	50-244 0 50-286 0 50-277 0 50-245 0 50-220 0	Grimes. B K. Grimes. B K. Grimes. B. K. Grimes. B. K. Grimes. B. K.	7812180248 7812180250 7812180251 7812180253 7812180255	50-10 P 50-133 P 50-219 P 50-245 P 50-409 P	HAABB, N. P. HAFHAM, J. N. HAGA, P. B. HAGA, P. B. HAGA, P. B.	7812170077 7811130373* 7811200058* 7810240103 7811070163	50-10 P 50-364 0 50-437 A 50-437 A
ORIER. B. H. ORIER. B. H. ORIER. B. H. ORIER. B. H. ORIER. B. H.	7811290174 7811290177 7811290183 7811290188 7811290190	50-483 0 50-443 0 50-352 0 50-322 0 50-383 0	ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K.	7812180259 7812180262 7812180263 7812180264 7812180266	50-293 P 50-271 P 50-247 P 50-155 P 50-254 P	Haga, P. B. Haga, P. B. Haga, P. B. Haires, F. D. Hairston, H. G.	7812070176 7812200160 7812220097 7812150293 7810270311	50-437 A 50-437 A 50-437 A 50-466 A 50-348 8
GRIER. B H GRIER. B. H GRIER. B. H GRIER. B. H GRIER. B. H	7811290193 7811290195 7811290199 7811290205 7811290208	50-272 0 50-333 0 50-289 0 50-309 0 50-219 0	ORIMEB.B.K. GRIMEB.B.K. GRIMEB.B.K. GRIMEB.B.K. GRIMEB.B.K.	7812180268 7812180270 7812180271 7812180271 7812180273	50-171 H 50-333 P 50-298 P 50-259 P 50-254 P	Hairbion W. Q. Hairbion W. Q. Hairbion W. Q. Hairbion W. Q. Hairbion W. Q.	7810180082* 7810100072* 7810100086* 7811140233* 7810180149*	50~348 R 50~348 8 50~348 B 50~348 B 50~348 B
ORIER, B. H. GRIER, B. H. GRIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7811290212 7811290214 7811290216 7811290218 7811290220	50-334 0 50-3 0 50-213 0 50-293 0 50-317 0	ORIMES B.K. GRIMES B.K. ORIMES B.K. ORIMES B.K. ORIMES B.K.	7812180275 7812180277 7812180279 7812180283 7812180284	50-263 P 50-321 P 50-331 P 50-272 P 50-344 P	Hairston, W. Q. Hairston, W. Q. Hairston, W. Q. Hairston, W. Q. Hairston, W. Q.	7810180134* 7810200081* 7810200085* 7810200089* 7810250145*	50-348 8 50-348 8 50-348 8 50-348 8
QRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H.	7811290222 7811290288 7811290291 7812070140 7812070141	50-311 0 50-171 H 50-245 R 50-465 A 50-271 P	ORIMES B. K.	7812160268 7812190002 7812190006 7812190008 7812190011	50-281 P 50-313 P 50-348 P 50-317 P 50-295 P	Hairston H. G. Hairston H. G. Hairston H. G. Hairston U. G. Hairston H. G.	78102501144 78110701878 78110701728 78110701768 78110702004	50-348 8 50-348 8 50-348 8 50-348 8
ORIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H. GRIER, B. H.	7812070143 7812070144 7812070146 7812070149 7812070150	50-334 P 50-412 A 50-244 P 50-352 A 50-387 A	ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K.	7812190014 7812190017 7812190023 7812190025 7812190028	50-3 P 50-255 P 50-261 P 50-213 P 50-334 P	HAIRSTON, W. G. HAIRSTON, W. G. HAIRSTON, W. G. HAIRSTON, W. G. HAIRSTON, W. G.	7811140237# 7811140242# 7811140246# 7811140251# 7811210358#	50-348 8 50-348 8 50-348 6 50-348 8
ORIER, B. H.	7812070152 7812070153 7812070154 7812070155 7812070155	50-322 A 50-3 P 50-213 P 50-273 P 50-311 A	ORIMES, B. K.	7812190031 7812190033 7812190036 7812190038 7812190039	50-267 P 50-302 P 50-250 P 50-315 P 50-289 P	Hairston H. G. Hairston H. G. Hairston H. G. Hairston H. G. Hairston H. G.	7812080224 7811210179# 7811200272# 7812010254# 7812210212#	50-348 8 50-348 R 50-348 8 50-348 8 50-348 R
ORIER, B.H. ORIER, B.H ORIER, B.H. ORIER, B.H. ORIER, B.H.	7812070159 7812070159 7812070161 7812070163 7812070166	50-29 P 50-443 A 50-317 P 50-220 P 50-245 P	ORIMES, B. K.	7812170042 7812170044 7812170047 7812170048 7812170051	50-307 P 50-335 P 50-282 P 50-286 P 50-283 P	Hairbton H. G. Hairbton H. G. Hairbton H. G. Hairbton H. G. Hairbton H. G.	7812110138+ 7812200165* 7812270313* 7812270309* 7812270313*	50-348 8 50-348 8 50-348 8 50-348 8
ORIER. B. H.	7812070191 7812070194 7812070197 7812070200 7812070205	50-272 P 50-289 P 50-333 P 50-286 P 50-277 P	ORIMES B. K.	7812190054 7812190057 7812190059 7812190060 7812190062	50-244 P 50-206 P 50-312 P 50-266 P 50-305 P	HAIRSTON, M. Q. HAIST, D. P. HAIST, D. P. HALL, R. E. HALL, R. E.	7812270283+ 7811270126+ 7812210380+ 7810270417+ 7810110074+	50-348 8 50-70 0 50-206 0 50-213 P
ORIER. B. H. ORIER. B. H. ORIER. B. H. ORIER. B. H. ORIER. B. H.	7812070207 7812070209 7812070212 7812070282 7812060271	50-363 A 50-219 P 50-309 P 50-410 A 50-387 A	GRIMEB, B. K. GRIMEB, B. K. GRIMEB, B. K. GROCE, R. H. GROCE, R. H.	7812190043 7812280345 7812280345 7812180105* 7810110171 7810190056	50-29 P 50-346 P 50-277 P 50-309 P 50-309 P	HALL, R. E. HALL, R. E. HALL, R. E. HALL, R. E. HALL, W. J.	7812130386 7812120125= 7811030040= 7811200218= 7812040334=	50-303 P 50-250 F 50-464 G 50-498 G 50-275 G
ORIER. B. H. GRIER. B. H. GRIER. B. H. GRIER. B. H. GRIER. B. H.	7812060290 7812110212 7812150041 7812150042 7812150045	50-387 A 50-387 A 50-392 G 50-311 G 50-485 G	OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H.	7610130127 7811090166 7811130091 7811170201 7812010146	50-29 P 50-271 H 50-307 P 50-29 P 50-29 Q	HALL, R. E. HAMILTON, D. S. HAMMER, B. J. HAMMER, M. E. HAMMOND, E. L.	7812120119 7810240001 7811280252* 7812270237* 7811270160	50-250 F 50-313 F 50-243 F 50-243 F 50-263 F

HAMHOND.E. L. 781010141 50-331 8 HAVERIAMP.D.R. 78120103038 50-320 0 HAMHOND.E. L. 7810120047 50-331 P HAVE.C. 7811300393 50-70 0 HAMHOND.E. L. 7810200061 50-331 R HAVE.C. 7811300393 50-70 0 HAWHOND.E. L. 7811210390 50-331 R HAVE.F. 7811200373 50-70 0 HAWHOND.E. L. 7811280204 50-331 R HAVE.F. 7811280373 50-40 Q HAWHOND.E. L. 7811280204 50-331 B HAVAKAWA.B.I. 7811240094* 50-70 U HAWHOND.E. L. 7811290207 50-331 P HAVAKAWA.B.I. 7811240094* 50-70 U HAWHOND.E. L. 7811290137 50-331 P HAVAKAWA.B.I. 7811010037* 50-331 P HAVAKAWA.B.I. 7811010037* 50-341 Q HAWHOND.E. L. 781290130 50-331 P HAVES.D.W. 7811010037* 50-341 Q HAVES.D.W. 7811010112* 50-440 Q HAVE.C. 7811010307 50-324 Q HAVE.D.W. 7811010307* 50-440 Q HAVE.C. 7811010307 50-322 A HAVE.D.W. 7811210027* 50-456 B HAVE.W. C. 7811010307 50-502 Q HAVE.D.W. 7811210037* 50-456 B HAVE.D.W. 7811210037* 50-456 Q HAVE.D.	HEISHMAN, R. F.	7811010092 7811010091 7811030093 7811010103 7811010113 7811030237 7812040021 7812040160 7812140021 7812190117 7811070222 7812060108 7812060174	50-329 50-329 50-341 50-341 50-329 50-452 50-452 50-465 50-329
HAMMOND, E. L. 7811280204 50-331 8 HAYAKAHA, S. T. 7811240094 50-70 U HAMMOND, E. L. 7811290288 30-331 P HAYAKAHA, S. T. 7811240094 50-70 U HAMMOND, E. L. 7812190137 50-331 R HAYES, D. H. 7811010037 50-358 G HAYES, D. H. 7811010037 50-358 G HAYES, D. H. 7811010037 50-354 Q HAYES, D. H. 7811010037 50-354 Q HAYES, D. H. 7811010027 50-440 Q HAYES, D. H. 7811010027 50-456 B HAYES, D. H. 7811010027 50-456 B HAYES, D. H. 7811010037 50-456 G HAYES, D. H. 781101038 50-456 G HAYES, D. H. 78110101038 50-456 G HAYES, D. H. 78110101038 50-456 G HAYES, D. H. 78110101038 50-456 G H	HEISHMAN R. F.	7812040021 7811300251 7812040160 7812140021 7812190117 7811070222 781206010B 7812060174	50-452 50-440 50-546 50-329 50-483 50-329
HAND, R. C. 7810110307 50-322 A HAYES, D. W. 7811210027* 50-456 B HANLEY, M. C. 7811010310 50-502 Q HAYES, D. W. 7811210013* 50-456 Q HANLEY, M. C. 7812130088* 50-502 Q HAYES, D. W. 7812040163* 50-546 Q	HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F. HEISHMAN, R. F.	7811070222 781206010B 7812060174	50-329
		7812060225	50-483 50-266 50-254
HANNGIN J. N. 781210315 50-324 P HAYES, D. M 7812060358 50-454 9 H HANNUN D. 78122002414 50-254 R HAYES, D. M. 7812070108 50-454 9 H HANSEN, P. 7811240176 50-304 8 HAYES, D. M. 78121401379 50-329 0 H	HEISHMAN R.F HEISHMAN R.F. HEISHMAN R.F.	7611080284 7611100074 7811130104 7812040044 7812040352	50-358 50-341 50-341 50-329 50-454
HANSEN. P. A. 7812210075* 30-546 0 HAYNEB. R. C. 7810190973* 50-397 0 HANSEN. P. H. 7812110159* 50-295 8 HAYNEB. R. C. 781010007* 30-361 Q HANSEN. P. H. 7812110163* 50-295 8 HAYNEB. R. C. 7810230094* 50-508 Q H	HEISHMAN, RF	7812070105	50-456
	HEISHMAN, RF,	7811200041	50-329
	HEISHMAN, RF,	7811200126	50-367
	HEISHMAN, RF	7812140063	50-331
	HEISHMAN, RF	7812140130	50-329
HARDING.V.R. 7811020333* 30-349 0 HAYNES.R.C. 7811270046* 50-361 0 HAYNES.R.C. 7811270126* 30-70 0 HAYNES.R.C. 7811270126* 30-70 0 HAYNES.R.C. 7811270038* 50-312 0 HAYNES.R.C. 7811270038* 50-312 0 HAYNES.R.C.	HEIBHMAN R.F.	7812080055	50-358
	NEIBHMAN R.F.	7812130206	50-315
	HEIBHMAN R.F.	7812130129	50-331
	HEIBHMAN R.F	7812130329	50-295
	HEIBHMAN R.F.	7812270034	50-341
HARDINA K. 78120300189 50-348 0 HAYNES J. 0. 7810270214 50-206 0 HAYNES J. 0. 7810270214 50-206 0 HAYNES J. 0. 7811010167 50-30-361 H HARDING V. R. 7812180441 50-344 0 HAYNES J. 0. 7811070243 50-206 P 1	HE18HMAN R.F.	7811130425	50-341
	HE18HMAN R.F.	7812280237	50-367
	HE18HMAN R.F.	7811220006	50-329
	HEI8HMAN R.F.	7811280373	50-341
	HE18HMAN R.F.	7811290109	50-341
HARDING, U.R. 7812220028 50-502 Q HAYNES, J. Q. 7811080105 50-206 F HARDING, L. M. 7812190134* 50-320 R HAYNES, J. Q. 7812210153* 50-460 Q HAYNES, J. Q. 781210316 50-206 P	HE I SHMAN, R. F.	7812010051	50~440
	HE I SHMAN, R. F.	7812010054	50~358
	HE I SHMAN, R. F.	7812190158	50~329
	HE I SHMAN, R. F.	7812200306	50~374
	HE I SHMAN, R. F.	7812210069	50~546
HARPSTER. T. L. 7812140016* 50-263 Q HAYNES. D. H. 7812210075* 50-546 Q HAYNES. T. L. 7812200295* 50-358 Q HAYNES. T. C. 7812280246* 50-361 Q HAYNES. T. R. 7811200437* 50-437 A HAYNES. J. D. 7811280212 50-205 P	he ishman R. F	78122(0120	50~266
	Heibhman R. F.	7812270074	50~409
	Hèibhman R. F.	7812040287	50~329
	Hèibhman R. F.	7811290293	50-329
	Heibhman R. F.	7812010155	50~329
HARRIB.B.H. 7810170203* 50-247 8 HAYNEB.J.O. 7812050219 50-206 F HARRIB.J.D. 7812200132 50-206 F HAYNEB.J.O. 7812200132 50-206 P HAYNEB.J.O. 781220132 50-206 H	HEISHMAN, R. F.	7812030102	50-329
	HEISHMAN, R. F.	7812140366	50-329
	HEISHMAN, R. F.	7812040365	50-358
	HEISHMAN, R. F.	7812120192	50-374
	HEISHMAN, R. F.	7812120193	50-358
HARRISON M.F. 7811200109 50-546 P HEAD, J. T. 7810180089 50-206 8 HARRISON M.C. 7812070023% 50-518 Q HEAD, J. T. 7810180157 50-206 8 HARRISON M.C. 7812060152 50-329 Q HEAD, J. T. 7810250123 50-206 8	Heishman R. F	7812120198	50-358
	Heishman R. F.	7812140289	50-456
	Heishman R. F.	7812270241	50-461
	Heishman R. F.	7812280217	50-367
	Heishman R. F.	7812290251	50-341
HARRIBON A. 7811240169 50-466 D HEAD, J. T. 7811280277 50-206 B HARRIBO J. T. 7812220082 50-206 F HARRIBOTON, J. 78112100464 50-368 A HEAD, P. C. 7811290307 50-275 F	Heltemes, C. J.	7810180185	50-595
	Heltemes, C. J.	7811070365	50-584
	Heltemes, C. J.	7811130387	50-584
	Heltemes, C. J.	7811130437	50-470
	Heltemes, C. J.	7811280134	50-495
HARRIE J L. 7812140280 50-498 M HEISHMAN R.F. 7810110178 50-367 0 HARRIE J 7812130298 50-491 0 HEISHMAN R.F. 781010026 50-305 0 HARRIN NOTON, J 7812040151 50-368 A HEISHMAN R.F. 781010030 50-358 0	HELTEMEB. C. J.	7812040203	50-470
	HELTEMEB. C. J.	7812110250	50-495
	HELTEMEB. C. J	7812130290	50-584
	HELTEMEB. C. J.	7812180403	50-584
	HELTEMEB. C. J	7812140358	50-584
HART. 0. 7812130326 50-400 U HEISHMAN.R.F. 7810300113> 50-341 0 HART.R.D. 7812150279 50-346 M HEISHMAN.R.F. 7811130340 50-327 0 HART.GAM.J. 7812030162= 50-346 8 HEISHMAN.R.F. 7811020106 50-315 0	HENDRIE.J.M. HENDRIE.J.M HENDRIE.J.M. HENDRICKSON.R. HENDRIE.J.M.	7810200354* 7811200170* 7811200242* 7811040074* 7811200271*	50-201 50-437 50-437 50-116 50-437
HARTLEY, T. P. 7811070157 50-272 J HEISHMAN R. F. 7811070001 50-367 0 HARTLEY, T. F. 7812040223 50-272 J HEISHMAN R. F. 7811210103 50-440 0 HARTMAN C. J. 781121030 50-135 8 HEISHMAN R. F. 7811140268 50-341 0	HENDR I E. J. M HENDR I E. J. M. HENDR I E. J. M. HENDR I CABON, R. HENDR I E. J. M.	7811200238* 7810140039* 7811200006 7811060073 7812130016	50-437 50-213 50-437 50-116 50-549
HABRING.R. C. 7812201212 50-257 U HEISHMAN.R.F. 7810200016 50-367 Q HABRING.R.C. 781220241* 50-456 Q HEISHMAN.R.F. 7811020076 50-331 Q HARTING.N. 7911010066 50-331 Q	Hennessey, R. J. Hennessey, R. J. Herbein, J. Q. Herbein, J. Q. Herbein, J. Q.	7810140060* 78112102894 7810190001* 7810100088 7810100074	50-297 50-338 50-320 50-320 50-320
HAUGHNEY, C. J. 7811280370 50-201 F HEISHMAN, R. F. 7811210005 50-456 Q HAUERKAPP, D. R. 781019007* 50-200 Q HEISHMAN, R. F. 7811210018 50-201 Q HAUERKAPP, D. R. 781019007* 50-200 Q HEISHMAN, R. F. 7810200236 50-456 Q	HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O.	7810100090 7810180165 7810110082 7810100046 7810110130	50-289 50-320 50-320 50-320 60-320

AUTHOR	ACCEBSION NUMBER	BUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHDR	ACCESBION NUMBER	SUBJECT CATEODRY
HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O.	7810110148 7810180171 7810170147 7810180132 7810240125	50-289	H1001NS.J. C. H1001NS.J. C. H1001NS.J. C. H1001NS.J. C. H1001NS.J. C	7810250138* 7810250052* 7812010303* 7812010136* 7812040367*	50~286 0 50~311 0 50~317 0 50~217 0 50~233 0	Hoffman.D.P. Hoffman.D.P. Hoffman.D.P. Hofmayer.C.H Hofmann.R.B.	7812260206 7812270174 7812270202 7811200202* 7812040330*	50-255 50-255 50-255 50-255 50-437 50-275
HERBEIN.J. 0. HERBEIN.J. 0. HERBEIN.J. 0. HERBEIN.J. 0. HERBEIN.J. 0.	7810240131 7810240097 7810240120 7810210184 7810300137	30-320 8 30-320 P 30-320 P 30-289 8 30-289 F	H1601NB.J.C H1LL.H.J. H1LL.J.L. H1LL.E.E. H1LLER.D.	7812080083* 7811240162 7811270014 7812180418 7810240023	50-334 Q 50-263 8 50-498 Q 50-338 Q 50-341 Q	HOGGATT.O. D. HOGGATT.O. D HOLDDY, D. J. HOLDDY, D. J HONO, S. N.	7812210331 7812280275 7810180181+ 7812030304+ 7812030222	50-70 50-70 50-80 50-97 50-329
HERBE I N. J. O. HERBE I N. J. O. HERBE I N. J. O. HERBE I N. J. O. HERBE I N. J. O.	7811070191 7811070135 7811070114 7811070101 7811080204	50~289 8 50~289 F 50~320 P 50~289 F 50~289 F	Hillman, R. E. Hillyard, H. H. Himebauch, N. Himebauch, N. Hinckley, D. O	7810270097* 7812180245* 7812120112* 7812270198 7810110302*	50-219 R 50-267 R 50-155 R 50-155 R 50-324 G	Hong, B. H Hong, B. H. Hong, B. H. Hong, B. H. Hong, B. H.	7812050225 7812050227 7812050232 7812050239 7812050244	50-329 50-329 50-329 50-329
MERBEIN.J.O. MERBEIN.J.O. MERBEIN.J.O. MERBEIN.J.O. MERBEIN.J.O. MERBEIN.J.O.	7811070171 7811090274 7811140172 7811090048 7811130161	50-320 8 50-320 P 50-320 K 50-320 P	Hinckley, D. Q. Hinckley, D. Q. Hinckley, D. Q. Hind, J. A Hind, J. A	7811010402* 7812180345* 7812200161* 7810230371 7810240035*	50-324 Q 50-324 Q 50-13 Q 50-409 Q 50-315 Q	HONG, B. W. HONG, B. W. HOOD, D. HOOD, D. M. HOOD, D.	7812050250 7812050255 7810140006 7811070332 7811130021	50-329 50-329 50-329 50-329
Herbe in J. O. Herbe in J. O. Herbe in J. O. Herbe in J. O. Herbe in J. O.	7811210184 7811210332 7811210380 7811270155 7811240110	50-289 R 50-320 B 50-320 R 50-320 F 50-289 P	Hind, J. A. Hind, J. A. Hind, J. A. Hind, J. A. Hind, J. A.	7810240032 7810110186 7810130245 7810190247+ 7810190079	50-310 G 50-255 O 50-112 G 50-155 O 50-266 G	HOOD+ D. HOOD+ D. HOOD+ D. HOOD+ D. HOOD+ D.	7811150107 7811280127 7811280130 7811280131 7812050094*	50-329 50-329 50-329 50-329 50-329
HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O. HERBEIN.J. O	7811260243 7812040171 7812050098 7612050161 7812050168	30-289 P 50-320 B 50-289 P 50-287 P 50-287 F	HEND, J. A HEND, J. A HEND, J. A HEND, J. A HEND, J. A	7810190234 7812060391* 7810310215 7811070231 7811070002	50~155 G 50~315 G 50~331 G 50~331 G 50~254 G	HOOD, D. HOOD, D. HOOKER, K. HOOKER, K.	7812070280 7812080241 7812210294 7810260002 7811160046#	50-329 50-458 50-329 50-466 50-466
Herbein J. G. Herbein J. G. Herbein J. G. Herbein J. G. Herbein J. G	7812070203 7812080090 7812130193 7812180187 7812200278	30-320 P 50-289 P 50-320 8 50-320 P 30-330 8	Hind, J. A Hind, J. A Hind, J. A Hind, J. A Hind, J. A	7812060388 7811070044* 7811070043 7811280486 7812140086*	50-315 G 50-87 G 50-87 O 50-10 G 50-10 G	Hooker, k Hooker, k Hooker, k Hooker, k	7811160045 7811210030 7812040302* 7812110318 7812050294	50~466 50-466 50-466 50-466 50-466
HERBEIN-J. Q. HERBEIN-J. Q. HERBEIN-J. Q. HERBEIN-J. Q. HERBEIN-J. Q.	7812120092 7812190096 7812190113 7812190166 7812200171	50-289 H 50-320 P 50-289 F 50-289 R 50-289 G	Hind, J. A Hind, J. A Hinderbtein, C. Hinderbtein, C. Hinderbtein, C.	7812080217 7812280323 7810230248 7811130126 7812040300	50-135 G 50-331 G 50-466 G 50-466 G	HOOKER, K. HOOKER, K. HOOKER, K. HOPPER, D. M. HORN, A. J.	7812040361 7812110103 7812120215 7812010265* 7811130231*	50~466 50~466 50~466 50~338 50~344
Herbe In. J. O. Herbe In. J. O. Herbe In. J. O. Herbe In. J. O. Herbe In. J. O.	7812260259 7812280116 7812290131 7812190132 7812260191	50-320 8 50-320 Q 50-320 P 50-320 R 50-289 8	Hines, E. Hinkel, E. Hinkel, L. Hinkes, N. E. Hitchens, D.	7811070285 7811210082 7812130015 7812080097 7811210357*	50-341 0 50-341 0 50-70 0 50-395 A 50-346 8	HORN, A. J. HORRY, C. M. HOBEY, C. M. HOBEY, C. M. HOUSE, D. R.	7812080238* 7812070294* 7812050031* 7812040339* 7810200115	50~326 50~269 50~269 50~369
HERBE IN, J. G. HERBBT, J. E. HERBBT, J. E. HERDT, A. R. HERDT, A. R.	7812290086 7812210235* 7812210209* 7810120092* 7811020092*	50-289 P 50-275 A 50-275 A 50-339 Q 50-438 G	HJELMFELT, D. C. HODOEB, J. W. HODOEB, J. W. HOEFLING, R. K. HOEFLING, R. K.	7812150279 7812040325* 7812140059* 7811210100 7611200008	50-346 M 50-260 G 50-269 0 50-369 9 50-322 9	HOWARD, J. E. HOWARD, J. E. HOWE, P. M. HOWE, P. M. HOWE, P. M.	7810170160 7810170164* 7811300165 7812180334* 7812210319	50~471 50~471 50~400 50~400 50~400
HERDT A.R. HERDT A.R. HERDT A.R. HERDT A.R. HERDT A.R.	7810230239 7811030054* 7811130108* 7811130120* 7811140253*	50-553 Q 50-424 Q 50-327 Q 50-438 Q 50-516 Q	Hoefling, R. K. Hoefling, R. K. Hoefling, R. K. Hoefling, R. K. Hoefling, R. K.	7811200022 7812010198 7812140026 7812140342 7612270042	50-322	HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H. HOWELL, S. H.	7810160196 7810190066 7810180095 7810230192 7810250099	50-329 50-329 50-329 50-329 50-329
HERDT.A.R. HERDT.A.R. HERDT.A.R. HERDT.A.R. HERDT.A.R.	7811140233+ 7811210088+ 7811200188+ 7811240068+ 7811220284+	50-51B Q 50-339 Q 50-518 Q 50-424 Q 50-395 Q	HOFFMAN.R.P. HOFFMAN.D.P. HOFFMAN.D.P. HOFFMAN.D.P. HOFFMAN.D.P.	7810140017 7810170244 7810100015 7810110111 7810170233	50-305 9 50-255 8 50-255 8 50-255 P 50-255 R	Homell, B. H. Homell, B. H. Homell, B. H. Homell, B. H. Homell, B. H.	7811080015 7811070336 7810270142 7811070149 7811280124	50-327 50~327 50-327 50-327 50-327
HERDTIAR. HERDTIAR. HERDTIAR. HERDTIAR. HERDTIAR.	7611300170 > 7612130005 > 7812080052 * 7812180353 > 7812130298 >	50-400 Q 50-327 Q 50-518 Q 50-416 Q 50-491 Q	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	7810110164 7810130137 7810190218 7810270075 7811200079	50-155 P 50-255 R 50-155 P 50-155 P 50-256 Q	Howell, B. H. Howell, B. H. Howell, B. H. Howell, B. H. Howell, B. H.	7811090143 7811170212 7811170222 7811170294 7811170298	50-329 50-329 50-329 50-329 50-329
HERDT, A.R. HERDT, A.R. HERDT, A.R. HERNANDEZ, G. HERRING, K. B.	7812210064* 7812210345* 7812270070* 7812270391* 7810260228*	50-413 G 50-400 G 50-438 Q 50-508 G 50-344 G	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	7811070210 7811070217 7811070183 7811140223 7812060029	10-255 8 50-155 8 50-255 8 50-255 8 50-255 0	HOMELL, E. H. HOMELL, B. H. HOMELL, J. C. HOMELL, J. C. HOMELL, E. H.	7811200159 7811200121 7811220176 7812140086* 7811270147	50-329 50-329 50-329 50-10 50-329
HERRING, K. 8, HERRING, K. B. HETZEL, N. C. HICKLE, B. J. HICKLE, B. J.	7810300077* 7812130106* 7811220198 7810130196* 7811140161*	50-344 0 50-344 0 50-352 0 50-285 R 50-285 R	HOFFMAN, D. P.	7811200112 7811210330 7812060024 7812060361 7812040164	30-255 R 30-255 B 50-255 G 50-255 G 50-255 P	HOWELL, & M. HOWELL, B. H. HOWELL, B. H. HOWELL, B. H. HOWELL, B. H.	7811270132 7812010251 7812040218 7812080249 7812120068	50-329 50-329 50-329 50-329 50-329
HICKLE'S. J. HIESTAND. O. S. HIESTAND. O. S. HIESTAND. O. S. HIESTAND. O. S.	7812130181* 7810130229 7810230136 7810140029 7810140104	50-285 R 50-409 O 50-409 O 50-409 O 50-409 O	HOFFHAN, D. P. HOFFHAN, D. P. HOFFHAN, D. P. HOFFHAN, D. P. HOFFHAN, D. P.	7812030119 7812030167 7812120100 7812110206 7812120093	30-255 P. 30-255 8 50-255 P. 30-255 8 50-255 B	HOHELL, 8, M. HOHELL, 8, H. HOHELL, 8, H. HOHELL, 8, H.	7812140080 7812120104 7812120111= 7812120154 7812270184	50-329 50-329 50-329 50-329 50-329
HIESTAND, O. S. HIESTAND, O. S. HIESTAND, O. S. HIESTAND, O. S. HIESTAND, O. S.	7810270300 7811070316 7811070034 7811160167 7812010354	50-409 G 50-409 G 50-409 G 50-409 G 50-409 G	Hoffman, D. P. Hoffman, D. P. Hoffman, D. P. Hoffman, D. P. Hoffman, D. P.	7612130133 7812130141 7812130241 7812220106 7812210230	50-155 P 50-155 F 50-255 B 50-255 B 50-255 B	HOHELL, R. H. HOHELL, R. H. HOHLETT, O. H. HOHLETT, O. H. HOHLETT, O. H.	7812270254 7812290146 7810160130# 7811140113# 7812150308#	50-327 50-329 50-336 50-336 50-336

HOYLE, J. C. HOYLE, J. C. HOYLE, J. C.	7812060424 7812060394 7812060389	50-334 50-295 50-280	0	1PPOLITO T. A 1PPOLITO T A 1PPOLITO T A	7811010393* 7811010400* 7810140046	50-277 50-277 50-321	P P	IPPOLITO T. IPPOLITO T. IPPOLITO T.	7812110021 7812110023 7812110029	50-263 50-324 50-259
HUBACEK.H O HUBACEK.H O HUBACEK.H.Q.	7810240236* 7811030040* 7811200218*	50-498 50-466 50-498	0 0	IPPOLITO, T. A. IPPOLITO, T. A.	7810140049* 7810140053* 7810140146	50-321 50-321	P P	IPPOLITO T. IPPOLITO T. A. IPPOLITO T. A.	7812110035 7812080157 7812180104	50-321 50-324 90-277
HUBACEK.M. Q. HUBBARD.R. B. HUBBE.C.	7811280054* 7812040307* 7812210521 7811220277	50-556 50-556 50-275 50-344	0 0	IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A.	7810230011 7810230016* 7810230019* 7810230028*	50-277 50-277 50-277 50-277	P P P	IPPOLITO T. A. IPPOLITO T. A. IPPOLITO T. A. IPPOLITO T. A.	7812180112* 7812270018 7812080149 7812110197	50-277 50-263 50-254 50-298
HUETER, L. J. HUETER, L. J. HUFHAM, J. H. HUFHAM, J. H. HUFHAN, J. W.	7811080080* 7812200302* 7810110253* 7810190061* 7810260067*	50-254 50-255 50-324 50-390 50-261	0 0 0 0	IPPOLITO, T. A.	7810230039 7810230043+ 7810230048+ 7810270239 7811020066	50-271 50-271 50-271 50-276 50-271	P P P	IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A. IPPOLITO, T. A. IRWIN, D. P.	7812140276 7812270047 7812270236 7812270230 7810170223	50-333 50-220 50-282 50-293 50-450
HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. H. HUFHAM, J. H.	7810250207* 7811030235* 7811130419* 7812070075* 7812050249*	50-369 50-335 50-338 50-261 50-250	Q Q Q Q	IPPOLITO T.A IPPOLITO T.A IPPOLITO T.A IPPOLITO T.A IPPOLITO T.A	7811020071* 7811020086* 7811030013 7811030016* 7811030019*	50-271 50-271 50-366 50-366 50-366	P P P	IRWIN, D. P. IRWIN, D. P. IRWIN, D. P. JABBOUR, K. N. JABLONSKI, F. J.	7810270007 7811130435 7812130212 7811060172 7811090189*	50-463 50-450 50-469 50-244 50-315
HUPHAM, J. W. HUPHAM, J. W. HUPHAM, J. W. HUPHAM, J. W. HUPHAM, J. W.	7812080010+ 7812140122+ 7812290086+ 7812210076+ 7812290066+	50-280 50-348 50-280 50-250 50-339	0 0 0 0	IPPOLITO T. A IPPOLITO T. A. IPPOLITO T. A. IPPOLITO T. A. IPPOLITO T. A.	7811030022* 7810240008 7811060124 7811060125* 7811060130*	50-366 50-271 50-277 50-277 50-277	P P P	JABLON, R. A JABLON, R. A JABLON, R. A, JABLON, R. A. JABLON, R. A.	7810270370 7811080064 7811100180 7811200103 7811100163	50-498 50-389 50-389 50-389 50-498
HUGHEB, J. HUGHEB, N. G. HUGHEB, J. HUGHEB, J. HUGHEB, J.	781 1020168* 781 0250037 781 1210436* 781 1300268* 781 2060230*	50-341 50-206 50-266 50-10 50-254	0 0 0	JPPOLITO T. A. IPPOLITO T. A.	7811030205 7811030208* 7811030210* 7811030006 7611220230	50-331 50-331 50-331 50-220 50-321	Ե Ե	JABLON, R. A. JACKIU, I. N.	7812040260 7812180246 7812270071 7812270063 7811010076*	50-389 50-329 50-250 50-389 50-254
HUGHEB, J HULMAN, L. O. HULMAN, L. O. HULMAN, L. O. HULMAN, L. O.	7812130338* 7811200253* 7811200433* 7811200386* 7811200375*	50-295 50-437 50-437 50-437 50-437	0 A A A	IPPOLITO T. A.	7811160022 7811220251 7811220252* 7811220138 7811220140*	50-220 50-220 50-243 50-243	6 6 6	JACKEW, I. H. JACKEW, I. N. JACKEW, I. N. JACKEON, R. E. JACKEON, L. L.	7811210220* 7812040046* 7812120226* 7812190198 7810270221*	50-331 50-254 50-331 50-70 50-327
HULMAN, L. Q. HUME, Q. N. HUMPHREYB, L. L. HUMPHREYB, L. L. HUMPHREYB, L. L.	7811130372 7810270167 7810110272* 7812260170* 7811070246	50-549 50-443 50-458 50-458 50-510	A G A A	IPPOLITO, T. A.	7811220144* 7811220248 7811270041 7811270100 7811270110*	50-263 50-298 50-298 50-263 50-263	6 요 요 요 요	JACKBON. L. L. JACKBON. J. B. JACKBON. L. L. JACKBON. R. E. JACKBON. L. L.	7611240013* 7610160143 7612060033* 7611030259 7612110225*	50-335 50-437 50-259 50-70 50-280
HUMPHREYB. L. L. HUNSTAD. A. A. HUNSTAD. A. A. HUNSTAD. A. A. HUNSTAD. A. A.	7812260166 7810180036* 7810180013* 7810120031* 7810120033*	50-458 50-306 50-282 50-282 50-282	A 8 8 R R	1PPOLITO.T.A. 1PPOLITO.T.A. 1PPOLITO.T.A. 1PPOLITO.T.A. 1PPOLITO.T.A.	7811240058 7811270243 7811270246* 7811270253* 7811300058	50-220 50-333 50-333 50-237	ե Ֆ Ե	JACKBON, T. J. JACKBON, R. E. JACOBBON, N. JACOBBON, O. H. JAMEG, E. H.	7812270078+ 7612260076 7612170133+ 7612050180 7810100055	50-201 50-18 50-266 50-522 50-305
HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A.	7810180025* 7811140117* 7812120094* 7812140161* 7812240209*	20-585 20-309 20-585 20-369	8 R R 8	IPPOLITO T. A. IPPOLITO, T. A. IPPOLITO, T. A. IPPOLITO, T. A. IPPOLITO, T. A.	7811300064* 7811300067* 7811300070* 7811300073*	50-237 50-237 50-237 50-237 50-237	P P P P	Jameg, E. H. Jameg, E. H. Jameg, E. H. Jameg, E. H. Jameg, E. H.	7810120041 7810110093 7810130149 7810230247 7810170156	50-305 50-305 50-305 50-305 50-305
HUNDT AD+A, A, HUNT+M, D, HUNT+M, D, HUNT+M, D, HUNT+M, D,	7812260237* 7811080314* 7810230223* 7811070269* 7811240068*	50-306 50-369 50-413 50-332 50-424	8 0 0 0	IPPOLITO, T. A.	7811290367 7812050003 7812050009* 7812050017* 7812050026*	50-263 50-259 50-259 50-259 50-259	P P P	JAMES, E. H. JAMES, E. H. JAMES, E. H. JAMES, E. H. JAMES, E. H.	7811070227 7810240128 7810270139 7810300105 7811140116	50-305 50-305 50-305 50-305 50-305
HUNT, M. D. HUNT, M. D. HUNT, M. D. HUNTER, D. R. HUNTER, D. R.	7812070030* 7812270372* 7812110313* 7811300318* 7811300141*	50-364 50-369 50-364 50-255 50-155	g g g o	IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A.	7812050336 7812050343* 7812050351* 7812060003 7812060009*	50-333 50-333 50-321 50-321	P P P	JAMEB, E.W. JAMEB, E.W. JAMEB, E.W. JAMEB, E.W. JAMEB, E.W.	7811220196 7811280299 7812080108 7812150232 7812210194	50-305 50-305 50-305 50-305 50-305
HUNTER, D. R. HUBAIN, I. HUTCHIBON, F. D. HUTBON, T. W. HUTBON, T. W.	7811300354* 7810160146* 7811080033* 7810110257* 7812270391*	50-255 50-409 50-584 50-344 50-508	Q P A O Q	IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A.	7812060119* 7811290078 7812050012 7812050016* 7812050020*	50-321 50-277 50-259 50-259 50-259	P F P P	JAMEB, E.W. JANAK, B. JANAK, B. JANBEN, T. JANBEN, T.	7812270171 7612110054 7812110057* 7810240141* 7811030191*	50-305 50-498 50-498 50-249 50-249
ianni, p. W. 1880n, A. F. 1 Deker, R. E. 1 Hrig, R. 1 Hrig, R.	7812010249* 7810300385* 7811210192* 7810190202 7810190220*	50-447 50-369 50-368 50-484 50-484	A G R O	1PPOL 1TO, T. A. 1PPOL 1TO, T. A. 1PPOL 1TO, T. A. 1PPOL 1TO, T. A. 1PPOL 1TO, T. A.	7812060062 7812080168 7812080170* 7812080176* 7812110319	50-259 50-333 50-333 50-333 50-333	P F F P	Janeen, T. Janeen, T. Janeen, T. Januska, A. Q Januska, A. Q	7811280179* 7812180178* 7812270215* 7810110266* 7810110270*	50-249 50-249 50-237 50-346 50-346
IHRIG.R. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A.	7810300369 7810200204 7810200151 7810200131 7810250191	50-484 50-333 50-271 50-259 50-277	0 P P P	1PPDL TTG. T. A. 1PPOL 1TG. T. A.	7812110320* 7812110323* 7812050045 7812050371 7812060188	50-333 50-333 50-263 50-263 50-220	P F P	Januska, a. q. Januska, a. q. Januska, a. q. Jape, f. Jape, f.	7811300401* 7811290331* 7812290063 7811080166* 7812140048*	50-262 50-246 50-255 50-295 50-269
IPPOLITO T. A.	7810130200 7810130202* 7810130210* 7810130233 7810130266	50-259 50-259 50-259 50-298 50-298	P P P P	IPPOLITO, T. A. IPPOLITO, T. A. IPPOLITO, T. IPPOLITO, T. IPPOLITO, T.	7812050272 7812080164 7812110046 7812110048 7812110052	50-293 50-324 50-333 50-220 50-277	Р Р Р Р	Jenkinb, O. A. Jenkinb, G. R. Jenkinb, H. D. Jenkinb, Q. R. Jenkinb, Q. R.	7813240013* 7812050031* 7812050165* 7811240057* 7812070312*	50-335 50-265 50-327 50-335 50-261
IPPOLITO, T. A.	7810140024* 7810140035 7810190043 7810130232* 7811010390	50-298 50-259 50-271 50-277 50-277	P P P P	IPPOLITO T.  1PPOLITO T.  1PPOLITO T.  1PPOLITO T.  1PPOLITO T.	7812110038 7812110001 7812110002 7812110007 7812110018	50-293 50-254 50-271 50-331 50-298	P P P P	JENS, H. H JENSCH, B. W. JENSCH, B. W. JENSCH, B. W. JENSCH, B. W.	7811070096 7810240053 7811090286 7812040347 7812050277	50~341 50~522 50~522 50~522 50~522

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	GUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	CATEO
Jenoch, 8 M. Jernigan, E. P. John, D. F. John, D. F. John, D. F.	7812070273 7811130151* 781026008 7812040050 7812270416	50-522 0 60-397 0 50-498 M 50-498 M	Kafin R. J. Kafoury. G. Kafoury. G. Kainer. G. J. Kalivianakib. N.	7812180406 7810270341 7811140027 7811210123 7810170198	50-549 0 50-344 0 50-344 0 50-466 0 50-265 8	KELLY, D. L. KELMON, R. M. KENDALL, D. M. KENNA, H. B. KENNA, H. B.	7810130053* 7812050228 7811290014 7810270103 7811130003	50-313 50-273 50-478 50-13 50-25c
JOHNE, C. JOHNEON, E. H. JOHNEON, E. H. JOHNEON, E. H. JOHNEON, H. D	7810160132 7610140133* 7810270176* 7610120016* 7611030036*	50-456 H 50-298 Q 50-334 Q 50-298 Q 50-295 Q	KAL1VIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N.	7810170172 7811020375* 7810170232 7811240175 7811240222	50-265 B 50-254 F 50-254 B 50-254 B 50-265 S	Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B.	7810110198* 7811100086* 7811100124* 7810110187 7810140057	50-83 50-25 50-83 50-83 50-83
JOHNBON, E. H. JOHNBON, R. W. JOHNBON, R. W. JOHNBON, D. F. JOHNBTON, D. W.	7811060055* 7810140087 7810140122 7811080096* 7810240094*	50-298 0 50-344 0 50-344 0 50-317 0 50-133 0	KALIVIANAKISI N. KALIVIANAKISI N. KALIVIANAKISI N. KALIVIANAKISI N KALIVIANAKISI N.	7811240237 7811240192 7811240179 7811240179 7811070118 7811240203	50-254 P 50-265 B 50-254 B 50-254 B 50-265 B	Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B.	7810260015 7811010298 7812010175 7811060036 7812040322	50-280 50-301 50-140 50-336 50-260
JOHNSON: A. JOHNSON: L. C. JOHNSON: M. C. JOHNSON: W. D. JOHNSON: W. P.	7811130381# 7811070294# 7810130046 7811210501# 7810110163	50-359 @ 50-243 P 50-395 @ 50-313 @ 50-29 P	KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N. KALIVIANAKIS, N	7811240239 7811240133 7811220031 7812110181 7812110176	50-265 8 50-265 8 50-254 R 50-254 8 50-254 8	Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B.	7811030043 7811090198 7811100103 7811140257 7811100082	50-321 50-255 50-245 60-346 50-25(
JOHNBON: D. F. JOHNBON: R. H. JOHNBON: R. D. JOHNBON: R. JOHNBON: R.	7811150276+ 7810130150+ 7811280062+ 7811240201+ 7811240223+	50-317 0 50-344 0 50-285 q 50-295 B 50-295 B	Kalivianakib, n. Kalivianakib, n. Kalman, g. Kalman, g. Kalman, g.	7812200235 7812270225 7812070295* 7812010031* 7812010276*	50-254 R 50-254 P 50-219 0 50-277 0 50-219 0	Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B. Kenna, W. B.	7811100106 7811090009 7812060288 7812110246 7812130310*	50-32: 50-32: 50-32: 50-32:
JOHNSON, M. C. JOHNSON, A. H. JOHNSON, R. W. JOHNSON, M. C.	7811080151+ 7812120237+ 7810240085 7811070364 7811070232	50-375 G 50-250 G 50-27 P 50-344 G 50-375 G	Kaltman, M. Kaminskas, V. A. Kanciruk, P. Kane, O. Kane, W. F.	7810270162+ 7812140152* 7810140076 7812200262* 7812130144	50-443 A 50-251 P 50-395 T 50-260 R 80-550 A	Kenna, W. B. Kenna, W. B Kenna, W. B. Kenna, W. B. Kenna, W. B.	7811900335 7812910355 7811910242 7812990101* 7811300003	50-28( 50-23) 50-33( 50-33)
JOHNSON, M. C. JOHNSON, W. P. JOHNSON, W. P. JOHNSON, P. H. JOHNSON, P. H.	7811150062* 7811090147 7811290341* 7812180356* 7812130350*	50-395 Q 50-443 8 50-445 8 50-298 Q 50-187 Q	KANE, W. F. KAPPLE: A. W. KAPPLE: A. W. KAPPLE: A. W. KAPPLE: A. W.	7612270012 7810100033* 7810100041* 7810100089* 7810200123*	50-447 A 50-272 8 50-272 8 50-272 8 50-272 8	Kenna, W. 8. Kenna, W. 8. Kenna, W. 8. Kenna, W. 8. Kenna, W. 8.	7811300010* 7812120049 7812120051 7812120053 7812120057	50-85 50-85 50-85 50-33
10HN80N, R. Q. 10HN80N, H. D. 10HN80N, R. H. 10HN80N, R. H.	7811140180 7812040381 = 7811210044 = 7811300374 7811320280	50-263 J 50-285 D 50-466 D 50-344 P 50-395 Q	Kapple: A.W. Kapple: A.W. Kapple: A.W. Kapple: A.W. Kapple: A.W.	7810230249* 7810230255* 7810230304* 7810310240* 7811070265*	50-272 8 50-272 8 50-272 8 50-272 8 50-272 8	KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B.	7812120063 7812120157 7812120164 7812120175 7812120180	60-32 50-28 50-41 50-43 60-34
JOHNBON:M C. JOHNBON:D.F, JOHNBON:M C. JOHNBON:A.D. JOHNBON:M.C.	7812040028# 7812290034# 7812240147 7812140039# 7812040374	50-395	KAPPLE: A.W. KAPPLE: A.W. KAPPLE: A.W. KAPPLE: A.W. KAPPLE: A.W.	7811070181* 7811070268* 7811200203* 7811240137* 7811280313*	50-272 8 50-272 8 50-272 8 50-272 8 50-272 8	KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B.	7812120165 7812120189 7812120197 7812140055* 7812140255	50-24 50-41 50-30 50-26 50-40
JOHNSON, E. H. JOHNSON, R. W. JOHNSON, R. W. JOHNSON, M. C.	7812210184* 7812040031* 7812140211 7812140267 7812010329	50-298 0 50-344 0 50-514 0 50-344 0 50-395 8	KAPPLE, A. H. KAPPLE, A. H. KARMAN, M. KARMAN, M. KATANICB, Q.	7812140169* 7812220086* 7812050050 7812130149 7810120091	50-272 8 50-272 8 50-263 9 50-263 9 50-344 9	Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B.	7812130294 7812180315 7812180346 7812180352 7812210281	50-32 50-33 50-34 50-26 50-27
JOHNBON M. C. JOHNBON A. H. JOHNBON R. W. JOHNBON R. W. JOHNBON M. C.	7812140057 7812040333* 7811280327* 7811280317* 7812120029	50-395 8 50-289 0 50-344 0 50-344 P 50-395 0	Kahula L Kahula L Kahula L Keane B. E. Kearney P.	7810230150* 7811210344* 7812210211* 7812130220 7810110137*	50-247 R 50-3 R 50-3 R 50-305 G 50-368 B	Kenna, W. B. Kenrick, J. R. Kenrick, J. R. Kenrick, J. R. Keppler, J. Q.	7812290096 7810160112 7810230383 7811150257 7812120212	50-30 50-43 50-43 50-25
JOHNOBON, R. H. JOHNOBON, J. JOHNOBON, P. H. JOHNOBON, R. W. JOHNOBON, R. W.	7812140377 7812050218# 7812270382* 7812270096 7812280179	50-344	KEARNEY, P. KEBLUBEK, B. KEBLUBEK, B. KEEFE, F. T. KEHOE, D. V.	7810170194* 7811130331 7812130377 7810230197 7812010338*	50-36B 8 50-369 A 50-369 A 50-496 A 50-320 G	Keppler.j. q. Keppler.j. q. Keppler.j. q. Keppler.j. q. Keppler.j. q.	7812040172 7811280030 7810110269 7810140050 7810110257	50-25 50-35 50-35 50-37 50-44
JOHNBON, M. C. JOHNBON, A. Q. JONEB, Y. I. JONEB, C. E. JONEB, C. E.	7612280302 7812270197# 7811010324 7811210027# 7811210013#	50-395 G 50-106 P 50-275 G 50-456 G 50-456 G	Keiler, E. H. Keimig, R. R. Keimig, R. R. Keimig, R. R. Keimig, R.	7811010389* 7810270196* 7811150105* 7811080096* 7812010062*	50-524 A 50-334 Q 50-309 Q 50-317 Q 50-266 Q	Keppler, J. O. Keppler, J. O. Keppler, J. O. Keppler, J. O. Keppler, J. O.	7811080104* 7811010306 7810300106 7810130217 7810110053	50~31 50~34 50~34 50~4t 50~4t
JONES C. E. JONES C. E. JONES C. E. JONES V. I.	78120401634 78121502404 78120701084 78122100754 7812180309	50-346 G 50-245 G 50-456 G 50-346 G 50-275 G	Keimio, R. R. Keimio, R. R. Keimio, R. R. Keimio, R. R. Keith, R. B.	7812270423+ 7812280012+ 7812270034+ 7812270153+ 7811300193+	50~272	Keppler.j.q. Keppler.j.q. Keppler.j.q. Keppler.j.q. Keppler.j.q.	7811080101 7810110293 7811170260 7810110228 7810130034	20-01 20-01 20-01 20-01
Jones, D. Jordan, E. L. Jordan, E. D. Jordan, H. H. Jorgensen, B. L.	7612200272* 7611280493* 7610170186 7611080073 7611300316*	50-285 8 50-331 P 60-77 P 50-468 G 50-255 G	Kethir, R. B. Kelley, D. L. Kelley, J. L. Kelley, J. J. Xelleher, J. A.	76122702824 76101200164 7610300262 76111402054 76112200924	50~316 8 50~298 0 50~387 8 50~336 8 50~547 T	KEPPLER.J. Q. KEPPLER.J. Q. KEPPLER.J. Q. KEPPLER.J. Q. KEPPLER.J. Q.	7810130088 7810130185 7811300225 7810200211 7810200207	50 - 4: 50 - 2: 50 - 2: 50 - 2: 50 - 2:
JORDENSEN, B. L. JOYCE, J. P. JOYNER, J. H. JOYNER, J. H. JUBACH, R.	7811300354* 7811320082* 7810270113* 7811010097* 7811070296	50-255 G 50-549 T 50-13 G 50-277 G 50-368 A	Kelleher, J. A. Kelley, J. L. Kellogo, P. J. Kellogo, P. J. Kellogo, P. J.	7811220096+ 7812180037+ 7810110262+ 7810310144+ 78103101344	50-547 T 50-275 Q 50-250 Q 50-261 Q 50-324 Q	Kepplerij, O. Kepplerij, O. Kepplerij, O. Kepplerij, O. Kepplerij, O.	7810230328 7810230332 7810230334 7810230336 7810230338	200-20 200-20 200-21 200-21
Julian, C. A. Jutrag. R. Kafin, R. J. Kafin, R. J. Kafin, R. J.	7812130317* 7812140154* 7810200136 7810270265 7812180052	50-269 G 50-220 B 50-549 G 50-549 G 50-549 G	Kellogo.p. J. Kellogo.p. J. Kellogo.p. J. Kellogo.p. J. Kellogo.p. J.	7810310116* 781122064* 7811130229* 7812140156* 7812210350*	50~338	Keppler. J. Q. Keppler. J. Q. Keppler. J. Q. Keppler. J. Q. Keppler. J. Q.	7810230341 7810230343 7810230346 7810230336 7810230357	50~3i 50~3i 50~4i 50~3i
								-

AUTHOR	ACCEBBION REMUN	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTI-DR	ACCEBBION RBBMUN	SUBJECT CATEGORY
KEPPLER, J. O KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7810300030 7811020160 7811020349 7811030206 7812050011	50-10 0 50-315 0 50-254 F 50-483 H 50-10 0	KEPPLER.J. O KEPPLER.J. O KEPPLER.J. O KEPPLER.J. O KEPPLER.J. O	7812280041 7812280044 7812280047 7812280052 7812280053	50-483 Q 50-440 Q 50-315 Q 50-331 Q 50-305 Q	KNOP.R.C KNOP.R.C. KNOP.R.C KNOP.R.C KNOP.R.C	7811010076* 7810250220* 7810250222* 7811010022* 7811080074*	50-254 0 50-331 0 50-331 0 50-10 0 50-295 0
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7812050027* 7811060072 7811080190 7811130338 7811140022	50-10 0 50-266 0 50-346 P 50-282 P 50-282 P	KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O	7812280055 7812280056 7812280057 7812280059 7812280062	#0-409	KNOP, R. C. KNOP, R. C KNOP, R. C KNOP, R. C. KNOTTS, J B.	7812040046* 7812050027* 7812060234* 7812270070* 7812180278	50-254 Q 50-10 Q 50-295 Q 50-346 Q 50-498 M
KEPPLER.J.O. KEPPLER.J.O. KEPPLER.J.O KEPPLER.J.O	7811160191 7811130052 7811130066 7811130351 7811130004	50-282 P 50-331 F 50-407 G 50-305 O 50-461 O	Keppler, J. O Keppler, J. O Keppler, J. O. Keppler, J. O Keppler, J. O.	7812280064 7812280065 7812290015 7812290016 7812290018	50-484	A L.BITONX B. RNOTTB. J B. RNOTTB. J B. RNTDNX B. J B. RNTDNX B. RNTDNX	7810110064 7810200137 7810110279 7810140141 7811070174	50-397 0 50-498 M 50-445 0 50-445 M 50-498 H
Keppler, J. O. Keppler, J. O Keppler, J. O Keppler, J. O Keppler, J. O.	7811150024 7811150025 7811150031 7811150036 7811150044	50-546 0 50-440 0 50-341 0 50-358 0 50-367 0	KEPPLER, J. O Keppler, J. O Keppler, J. O. Keppler, J. O. Kerr, H.	7812270021 7812270023 7812270026 7812270037 7811080135	50-461 Q 50-346 Q 50-10 Q 50-546 Q 50-2 Q	KNOTTS, J B KNOTT, D F	7811150021 7811300008 7812200224 7812290123 7811200147	50-397 Q 50-445 M 50-445 A 50-445 M 50-437 A
KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O.	7811150048 7811150051 7811150054 7811150057 7811150059	50-484 G 50-155 O 50-263 G 50-329 G 50-483 O	KETCHEN, E. O. KETCHEN, E. O. KETCHEN, E. O. KETCHEN, E. O KETCHEN, E. O	7810110055 7810140152 7810200006 7810200241 7811090262	50-369 0 50-566 0 50-369 0 50-369 0 50-369 0	KNUTH: D. F KNUTH: D. F. KOCH: L. J KOCHANNY: O. L KOCHER: C. A.	7811200151* 7811200114* 7812260141 7810300037 7811060050	50-437 A 50-437 A 50-461 A 50-264 F 50-361 Q
KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O KEPPLER, J. O.	7811150061 7811150063 7811150068 7811150069 7811150071	50-315 0 50-10 0 50-331 0 50-346 0 50-266 0	KETCHEN, E. O. KETCHEN, E. O. KETCHEN, E. O KETCHEN, E. O. KETCHEN, E. O	7811160016 7811200074 7811210100 7811210119 7812010087	50-369 0 50-566 0 50-369 0 50-366 0 50-369 0	KOENIO, L. A. KOEBTER, O. L.	7811200019* 7812110282* 7812110276* 7811030217 7811140186*	50-437 A 50-482 A 50-482 A 50-482 A 50-482 B
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7811130072 7811130137 7811130141 7811130143 7811130157	50-305 Q 50-440 A 50-305 P 50-327 A 50-263 P	KETCHEN.E. O. KETCHEN.E. O. KETCHEN.E. O. KETCHEN.E. O. KETCHEN.E. O. KETCHEN.E. O.	7811220149 7812050088 7812050065 7812050091 7812130038	50-566 0 50-369 0 50-460 0 50-566 0 50-566 0	KOESTER.O L. KOESTER.O L. KOESTER.O L KOESTER.O. KOESTER.O.	7811160189 • 7810250031 • 7810270320 7812110271 • 7811170249 •	50-482 B 50-482 G 50-482 A 50-482 A
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7811130159 7811130160 7811130163 7811130164 7811130167	50-484 A 50-367 A 50-546 A 50-315 P 50-155 P	KETCHEN.E. Q. KETCHEN.E. Q. KETCHEN.E. Q. KETCHEN.E. Q. KETCHEN.E. Q.	7812070262 7812110327 7812080225 7812130146 7812140346	30-366 Q 50-513 Q 50-269 Q 50-275 Q 50-275 Q	KOESTER.O.L KOESTER.O.L. KOHLER.J.E. KOHLER.J.E KOHLER.J.E	7812200349 7812200349+ 7810270376+ 7810310340+ 7812140147+	50-482 B 50-482 B 50-301 Q 50-316 Q 50-266 Q
KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0.	7811130167 7811130172 7811130173 7811130174 7811140002	50-407 P 50-358 A 50-331 P 50-483 A 50-10 P	KETCHEN, E. O KEUCH, R. L. KEY, H. J. KEY, H. J.	7812140344 7811290304* 7810110274* 7811150068* 7811280032*	50-275 0 50-70 0 50-358 0 50-331 0 50-331 0	KDKOBIKA, C. KOKOBIKA, C. KONKLIN, J. E KONKLIN, J. E. KDNKLIN, J. E.	7811210284* 7812050164* 7810190252* 7811210112* 7811300254*	50-213 R 50-213 R 50-454 G 50-440 G 50-440 G
Keppler.J. O Keppler.J. O Keppler.J. O Keppler.J. G. Keppler.J. G.	7811140275 7811140276 7811210452 7812010083 7812130035	50-346 P 50-461 A 50-282 P 50-287 P 50-315 G	KEY, W. J. KEY, W. J. KIDD, M. B. KIDD, M. B.	7811210024* 7812140066* 7812130134* 7811270014* 7812060336*	50-331 0 50-331 0 50-331 0 50-338 0 50-338 0	KONKL IN. J. E. KONKL IN. J. E. KOO I. M. KOPAC Z KORCHYNSKY, M.	7812060358+ 7812280316+ 7811240177+ 7811240193+ 7811210339+	50-454 9 50-440 9 50-254 9 50-265 9 50-249 9
KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0. KEPPLER.J. 0.	7811210457 7812010053 7811270291 781220029R 7811300114	50-255 G 50-331 G 50-331 P 50-358 G 50-255 O	KIEOEL, J. A. Kinder, E. T. Kintioh, A. E. Kintioh, A. E. Kintioh, A. E.	7812130100 7810180077 7812270264 7812270265 7812270266	50-331 H 50-443 A 50-596 A 50-596 F 50-596 B	KOTTAN, J. J. KOTTAN, J. J. KOTTAN, J. J. KOTTAN, J. J.	7811020188+ 7812010150+ 7812010041+ 7811300342+ 7812060244+	50-271 C 50-244 C 50-220 C 50-213 C 50-317 C
KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. G.	7812050263 7812050271 7812050274 7812050278 7812050282	50-407	Kintioh.a.e. Kintner.l. L. Kintner.l. L. Kippler.j. g. Kirch.d.f.	7812290267* 7812040206 7812130328 7812050267 7812210153*	50-596 A 50-341 A 50-341 A 50-305 Q 50-460 Q	KOTTAN, J. J. KO:TAN, J. J. K-VACH, B. KOVACH, B. KOVACH, B. A.	7812110235+ 7812270078+ 7811210352+ 7811210362+ 7811210375+	50-334 ( 50-201 ( 50-346 5 50-346 5
KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O.	7812050287 7812050300 7812050305 7812050308 7812050311	50-10 0 50-358 9 50-346 0 50-463 0 50-315 9	Kirbch, D. F. Kirbch, D. F. Kibter, H. B. Kibter, H. B. Kibter, H.	7810110259* 7810230094* 7811080097* 7811090017* 7812010103*	50-344 Q 50-508 O 50-286 Q 50-247 Q 50-309 Q	KOVACH, S. A.	7810180042+ 7810160140+ 7810310201+ 7811070267+ 7811070275+	50-346 50-346 50-346 50-346
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7812050314 7612050325 7612050333 7612050335 7612050337	50-155	KIBTER, H. 8. Kibter, H. B. Kibter, H. Kibter, H. B. Kibter, H.	7812110310+ 7812110301+ 7812080147+ 7812270449+ 7812270053+	50-245 Q 50-336 Q 50-334 Q 50-220 Q 50-271 Q	KOVACH, 8 KOVACH, 8 KOVACH, 8 KOVACH, 8 A KRAFT, D C.	7812050206+ 7812070201+ 7812120146+ 7812120161+ 7811170293+	50-346 50-346 50-346 50-346 50-148
Keppler.J. O. Keppler.J. O. Keppler.J. O. Keppler.J. O. Keppler.J. O.	7812050338 7812050344 7812280334• 7812050062 7812130234	50-367	KLINE, R. V. KLINE, R. V. KLINGLER, G. R. KLUTH, F. C. KNAPP, P. J.	7810160013+ 7811030155 7810130099+ 7811160160+ 78120603164	50-471 A 50-471 A 50-321 G 50-440 F 50-184 G	KRAFT, D. C. KRAHCZAK, A. T. KRESER, M. E. KRISTOVICH, S. KRISTOVICH, S.	7812060319* 7812210221* 7811210463 7810190262* 7810190269*	50-148 50-304 50-556 50-275 50-275
KEPPLER, J. 9. KEPPLER, J. 0. KEPPLER, J. 0. KEPPLER, J. 0. KEPPLER, J. 0.	7812140081 7812220037 7812150202 7812210118 7812200365	50-10 G 50-35B A 50-255 G 50-331 P 50-367 G	KNAPP P. J. KNAPP P. J. KNAPP P. J. KNAPP P. J. KNÆCHT M. G.	7812010076* 7811070036* 7811150047* 7811300380* 7812210396	50-286 Q 50-317 Q 50-220 Q 50-20 Q 50-482 B	KRIBTOVICH.8. KUESTNER.P. KUNDER.Q.A. KUNBITIS.T.J. KUO.P.T.	7810270294 7812120042+ 7812290093 7810180121+ 7811290294	50-275 50-580 50-320 50-280 50-275
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7812210354 7812280198 7812280307 7812280002 7812280003	50-313 F 50-329 H 50-440 Q 50-295 0 50-266 0	Knight, J. E. Knighton, G. Knight, J. P. Knoll, R. M. Knop, R. C.	7810260243* 7811030177 7812040338* 7811100076* 7811010309*	50-344 0 50-250 P 50-275 9 50-213 0 50-346 9	Kurkjian, T. G. Kuron, F. Kubek, L. T. Kubek, L. T. Kubek, L. T.	7812180431 7810260086 7812010240* 7812050179* 7812270333*	50-341 50-285 50-285

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
KUZHYCZ-Q KUZHYCZ-Q. KUZHYCZ-Q. KUZHYCZ-Q. KUZHYCZ-Q.	7811010207 7812010157 7812080021 7812110242 7812130273	50-267 P 50-267 P 50-267 P 50-267 P 50-267 P	LEECH.P. LEED.R.M LEED.R.M LEED.R.M LEED.R.M	7812130320 7810130089 7811300400 7812080165 7812150259	50-592 A 50-522 0 50-522 G 50-522 O 50-443 0	LEHIB. B H LEWIB. R. C LEWIB. R. C LEWIB. R. C	7810250214 7811080088 7811130381* 7810250234* 7811070320*	30-484
LABLONSKI, F. J LADUN, R. H LADUN, R. LAFLEUR, J. D LAFOLLETTE, B. C	7812130209+ 7811080177+ 7812280309+ 7811200215+ 7810190085	50-315	LEED.R.M. LEED.R.M. LEFEVRE.H.E. LEFEVRE.H.E. LEGATE.R.E.	7812110199 7812190080 7810120102 7812080139 7811270099*	50-522 0 50-522 0 50-522 A 50-522 A 50-155 P	Lehib. R. C Lehib. R. C. Lehib. B. H Lehib. B. H Lehib. R. C	7811130364* 7811270014* 7810300243 7811010148 7611220005*	50-369 @ 50-338 0 90-247 P 90-484 9 90-335 @
lagomarbino, R. J	7812180289	50-275 H	LELLOUCHE, O. B.	7812210193*	50-500 A	Lewis.r.C	78120401814	50-395 0
Lainab, G	7811020012	50-29 F	LEMANOHICZ, I.	7811010435*	50-387 G	Lewis.r.C	7811280398*	50-269 0
Lainab, G	7811030255	50-206 F	LEMANOHICZ, I.	7812260008*	50-387 O	Lewis.r.C	7812060228*	50-338 0
Lainab, G	7811030011	50-29 P	LEMANOHICZ, I.	7812260003	50-387 G	Lewis.r.C	7812060262*	50-280 0
Lainab, G	7811020091	50-313 P	LEMLY, M. B.	7811200102*	50-437 A	Lewis.r.C	7812010109*	50-280 0
Lainas, 0	7811020096* 7811030277 7811080259 7811130299 7811170055	50-313 P	LEMLY, M. 8.	7811200083*	50-437 A	Lewis, S. H	7811060236	50-484 0
Lainas, 0		50-155 P	LENAHAN, J. J	7812070023*	50-518 0	Lewis, S. H	7811070284	50-263 0
Lainas, 0		50-334 P	LENAHAN, J. J	7812290111*	50-553 0	Lewis, S. H	7811130002	50-263 0
Lainas, 0		50-333 P	LENGEL, R. A	7810100095*	50-320 B	Lewis, S. H	7811140003	50-443 0
Lainas, 0		50-313 B	LENGEL, R. A.	7810100080*	50-320 B	Lewis, S. H	7811140026	50-482 F
Lainab. 9 Lainab. 0 Lainab. 0. Lainab. 0 Lainab. 0.	7811210060 7811200047 7811200366 7811280361 7811290076	50-206 F 50-247 P 50-275 A 50-259 P 50-282 F	LENGEL R A. LENGEL R A. LENGEL R A LENGEL R A LENGEL R A	7810110083* 7810110134* 7810170148* 7811210336* 7811210384*	50-320 8 50-320 8 50-320 8 50-320 8 50-320 R	Lewis, J. O. Lewis, J. O. Lewis, B. M. Lewis, N. O. Lewis, N. O.	7811210353 7811210418 7811150231 7811140279 7811160042	50-255 8 50-255 8 50-549 0 50-522 0
Lainas, o	7612260001	50-269 P	LENGELIR A. LENGELIR A. LEONARD, J. D. LEONARD, J. D. LEONARD, J. D. LEONARD, J. D.	7812060177*	50-320 8	Lemis. 8 H.	78121500A5	50-482 G
Lainas, o	7812270365	50-295 F		7812130197*	50-320 8	Lemis. 8. H	78111500A0	50-549 G
Lancaster, j l	7812170118	50-261 J		7810100022	50-333 8	Lemis. R. C.	78120A033A*	50-33B G
Lancaster, j l	7812170123*	50-261 J		7810130128	50-333 R	Lewis. A S.	7811270049	50-70 G
Lancaster, j l	7810250062	50-269 P		7810120045	50-333 8	Lewis. 8 H.	7811220058	50-549 G
LANGNER: R. R	7810300037	50-264 F	LEONARD.J.D	7810120073	50-333 S	Lehib. B. H	7811220154	50-482 Q
LARMI: O. J.	7812280329	50-387 G	LEONARD.J.D.	7810230186	50-333 S	Lehib. B. H.	7811220157	50-484 Q
LARSON: L. K	7810160108	50-244 P	LEONARD.J.D.	7810230263	50-333 S	Lehib. R. C.	7812210113*	50-280 Q
LARSON: L. K.	7810230238	50-244 G	LEONARD.J.D	7810240122	50-333 S	Lehib. B. H.	7812040358	50-549 Q
LARSON: L. K	7810160149	50-244 P	LEONARD.J.D	7810240133	50-333 S	Lehib. B. H	7812130061	50-549 Q
LARSON, L. K.	7810190068	50-244 P	LEDNARD, J. D	7811070318	50-333 8	Lewis, B. H.	7812130065#	30-349 Q
LARSON, L. K.	7811010376	50-485 G	LEONARD, J. D	7811070244	50-333 8	Lewis, R. C	7812140048#	50-269 Q
LARSON, L. K.	7811060241	50-485 G	LEONARD, J. D.	7811140121	50-333 8	Lewis, R. C.	7812050018#	50-348 Q
LARSON, L. X.	7812040283	50-485 G	LEONARD, J. D.	7811140238	50-333 8	Lewis, B. H.	7812150189	50-349 Q
LASHER, D. R	7811020024	50-327 E	LEONARD, J. D	7811210414	50-333 8	Lewis, B. H.	7812180405	50-450 Q
LASIOVKA J M	7811270281	50-440 G	LEONARD, J. O	7812040156	50-333 8	LEHIS, 8. H	7812270469	50-549 0
LATHAM M E	7810200052	50-70 H	LEONARD, J. D	7812070174	50-333 8	LEHIB, 8. H	7812280262	50-247 9
LAURGEN H 1	7810270402	50-344 T	LEONARD, J. D.	7812150267	50-333 8	Librizzi, F. P.	7810110091	50-272 P
LAWRENCE J. F.	7810110275	50-514 G	LEONARD, J. D.	7812220079	50-333 8	Librizzi, F. P.	7810100028	50-272 8
LAWRENCE J. F.	7811150234	50-514 G	LEONARD, J. D.	7812260189	50-333 P	Librizzi, F. P.	7810100037	50-272 8
LAWRENCE J. F	7811210471	50-305 P	LEONARD, J. D. LEONARD, J. D. LEOSOR, L. C. LEBBOR, L. C. LEBBOR, L. C.	7812290246	50-333 8	L19R17Z1,F P.	7810100087	50-272 S
LAWRENCE J. F.	7811290044	50-514 P		7812270242	50-333 8	L19R1ZZ1,F,P	7810250118	50-272 P
LAWRENCE J. F.	7812040141	50-305 P		7810300173	50-298 8	L19R1ZZ1,F P	7810200119	50-272 S
LAWRENCE J. F.	7812040144	50-309 P		7810300201	50-298 8	L19R1ZZ1,F P	7810240083	50-272 P
LAWRENCE J. F.	7812040285	50-309 P		7812050166	50-298 8	L19R1ZZ1,F,P	7810230243	50-272 B
LAWRENCE, J. F.	7812040288+ 7812030243 7812050252+ 7811290259 7811290273	50-305 0 50-305 0 50-305 0 50-514 0 50-305 0	LESSOR, L. C. LESSOR, L. C. LESSOR, L. C. LESSOR, L. C. LESSOR, L. C.	7810170268 7812050135 7811160113 7812050144 7812200259	50-298 R 50-298 B 50-298 B 50-298 B	LIBRIZZI, F. P. LIBRIZZI, F. P. LIBRIZZI, F. P. LIBRIZZI, F. P. LIBRIZZI, F. P.	7610230252 7810230275 7810250103 7810310254 7811060087	50-272 8 50-272 8 50-272 R 50-272 9 50-272 P
LAWRENCE J F.	7811290355	50-397 Q	LESSOR, L. C.	7812130158	50-298 R	L 1971   771   F. P	7811040091	50-272 P
LAWROSKI. S.	7812050007	50-500 D	LESSOR, L. C.	7812290197	50-298 B	L 1971   771   F. P.	7811070242	50-272 8
LAWROSKI. S.	7811210318*	50-275 A	LESSOR, L. C.	7812200271	50-298 B	L 1971   771   F. P.	7811070178	50-272 8
LAWROSKI. S.	7812150050	50-275 G	LESSY, R. P.	7810310179*	50-498 M	L 1971   771   F. P.	7811070244	50-272 8
LAZARUS. W. J.	7811150105*	30-309 Q	LESSY, R. P.	7810140156	50-498 0	L 1971   771   P. P.	7811200201	50-272 8
LAZARUS.H. J LAZARUS.H. J LAZARUS.H. J LAZO.R M LAZO.R M	7811100094* 7811100076* 7812010278* 7810230337 7811130044	50-213 Q 50-213 Q 50-27 Q 50-263 Q 50-369 Q	LESSY-R.P. LESSY-R.P. LESSY-R.P. LESSY-R.P. LESSY-R.P.	7810230124 7810310020 7811680047 7811080076* 7811080118	50-445 M 50-456 M 50-466 M 50-466 M	L18R17ZI, F, P, L18R17ZI, F, P, L18R17ZI, F, P, L18R17ZI, F, P, L18R17ZI, F, P,	7811240132 7811240219 7812080134 7811280304 7812110150	50-272 8 50-272 P 50-272 R 50-272 8 50-272 0
LAZO,R.M	7812110280	30-592 Q	LESSY.R.P.	7811270055	50-445 M	LIBRIZZI, F. P. LIBRIZZI, F. P. LIBRIZZI, F. P. LIBRIZZI, F. P. LIGRIZZI, F. P. LICITRAIE. A	7812140167	50-272 8
Lear.Q.	7812130198	30-277 P	LESSY.R.P.	7812110203	50-346 Q		7812210206	50-272 F
Lear.Q	7811200080*	50-346 P	LESSY.R.P.	7812210372	50-445 M		7812220085	50-272 8
Lear.Q.	7810230035	50-277 P	LESSY.R.P.	7812210262	50-498 M		7812270181	50-272 P
Lear.R.	7810180004*	30-316 B	LESSY.R.P.	7812270091	50-498 M		7810140110	50-482 A
LEASE, R. S. LEASE, R. S. LEASE, R. S. LEASE, R. S. LEASE, R. S	7810230183* 7810230185* 7810270314* 7811140226* 7812080120*	50-316 8 50-316 8 50-316 8 50-316 8 50-316 8	LEVING, J. M. LEVIN, H. A. LEVING, A. J. LEVIN, H. A. LEVIN, H. A	7810130169* 7811100131 7812040018* 7812060303 7812220067	50-213 8 50-237 P 50-556 T 50-10 P 50-237 P	LICITRAÆ LICITRAÆ, A LICITRAÆ, A LIKÆ, I LIKÆ, I	7811210277 7811280128 7811280161 7810160107 7810190226	50-466 A 50-582 A 50-582 H 50-71 0
Lease.r. 8 Leavittij. B Leberbtein, J. H. Lee. E. H. Lee. E. H.	7812080122* 7813010071 7810180121* 7810260184* 7811130350*	50-316 8 50-225 J 50-280 P 50-341 0 50-329 Q	Levin, H. A. Levin, H. A. Lewald, O. H. Lewald, O. H. Lewald, O. H.	7812240026 7812270106 7811070001 7811070004 7812010057	50-29 P 50-213 P 50-471 Q 50-471 Q	LIKE, I. LIKE, I. LIKE, I. LIKE, I.	7810200156 7810190235 7810270301 7810310374 7810240087	50-516 0 50-516 0 50-322 0 50-324 A 50-516 0
LEE, E. SJ. K. LEE, E. SJ. K. LEE, E. H. LEE, N. R. LEECH, P. H.	7811300254» 7812270156» 7812209308» 7812260146 7812130252	50-440 G 50-341 G 50-374 G 50-458 A 50-592 A	Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C. Lewis, R. C.	7810240211# 7810240217* 7810230072* 7810130077* 7810230345*	50-250 0 50-250 0 50-335 0 50-348 0 50-335 0	LIKE, I. LIKE, I. LIKE, I. LIKE, I.	7811200002 7811210110 7811200020 7811300373 7811270311	50-322 0 50-322 0 50-516 0 50-516 0

				_ , , , , , , , , , , , , , , , , , , ,				
AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	NOIE8933A REMUN	BUBJECT CATEODRY	AUTHOR	ACCEBBION NUMBER	SUDJEC
LIKE, I. LIKE, I. LIKE, I. LIKE, I. LIKE, I.	7812110012 7812150019 7812210471 7812260322 7812210411	50-322 0 50-322 0 50-322 0 50-322 0	LONO, F. J. LONO, F. J. LONO, F. J. LONO, F. J. LONO, F. J.	7810310312* 7810310307* 7810230224* 7810310138 7810310128	50-359 0 50-359 0 50-338 0 50-251 0 50-324 0	LUNDVALL, A. E LUNDVALL, A. E LUNDVALL, A. E LUNDVALL, A. E LUNDVALL, A. E	7810230246 7810310271 7811150269* 7812010299* 7810230162	50-318 50-317 50-317 50-317 50-317
LINDBERG.C.	7810240102+	50-249 8	LONG, F. J.	7811010397	50-324	LUNDVALL A E	7810260202	50-317
LINDBERG.C.	7810200097+	50-237 8	LONG, F. J.	7810310115		LUNDVALL A E	7811150155	50-317
LINDBERG.C.	7811060162+	50-249 8	LONG, F. J.	7811090275		LUNDVALL A E	7811150189	50-317
LINDBERG.C.	7811140199+	50-237 1	LONG, F. J.	7810110287		LUNDVALL A E	78110900304	50-317
LINDBERG.C.	7811140227+	50-249 8	LONG, F. J.	7811080163		LUNDVALL A E	7811200206	50-317
LINOBERO C.	7811280309*	50-249 8	LONG, F. J.	7811080174	50-327 0	LUNDVALL A E	7811170197	50-317
LINDBLAD H. J	7811280315	50-344 P	LONG, F. J	7811080285	50-261 0	LUNDVALL A E	7812110105	50-317
LINDBERO C.	7812210245*	50-249 8	LONG, F. J.	7811200140*	50-280 0	LUNDVALL A E	7811240183	50-317
LINDBERO C.	7812180148*	50-249 8	LONG, F. J.	7811200210*	50-280 0	LUNDVALL A E	7812080125	50-317
LINDER, F. H.	7810100003	50-409 P	LONG, F. J.	7810110226	50-261 9	LUNDVALL A E	7612060096	50-317
LINGER, F. LINGER, F. LINDER, F. LINGER, F. LINGER, F.	7611130206 7811170220 7811270109 7812040216 7812070307	50-409 R 50-409 B 50-409 P 50-409 S 50-409 O	LONG. F. J LONG. F. J LONG. F. J LONG. F. J LONG. F. J	7810250231 = 7811070314 = 7811100023 = 7810110247 7811130357 =	50-348	LURIA, N. G. LUTON, E. LUTON, E. LUTON, E. LUTON, E.	7811200392* 7810140113 7810130188 7811020241 7811170012	50-275 50-70 50-70 50-70 50-295
LINDER, F.	7812080137	50~409 P	LONG, F. J.	78I 1130239#	50-280 0	LUTON, E.	7811220133	50-70
LINDER, F.	7812110165	50~409 B	LONG, F. J.	78I 1130262#	50-321 0	LUTON, E.	7811220137	50-70
LINDER, F.	7812110156	50~409 B	LONG, F. J.	78I 1130278#	50-369 0	LUTON, E.	7812040047	50-295
LINDER, F.	7812120126	50~409 R	LONG, F. J.	78I 1130409	50-302 0	LUTON, E.	7812040045	50-295
LINDER, F.	7812140162	50~409 P	LONG, F. J	7810230049	50-335 0	LYDON, J. M.	7812010050+	50-471
Linder, F.	7812200216	50-409 H	LONG, F. J.	7810240067	50-250 0	LYNCH, O. D.	7811010308	50-329
Linder, F.	7812290161	50-409 F		7811220093*	50-260 9	LYNCH, O. D.	7810250199	50-329
Linenberger, Q.	7811160001	50-463 F		7810200258	50-369 9	LYNCH, M. D.	7811170361	50-397
Linenberger, Q.	7811070360	50-522 Q		7810230013	50-261 9	LYNCH, M. D.	7811200010	50-440
Lingenfelter, J.	7810310309*	50-346 B		7811200021	50-327 9	LYNCH, M. D.	7811220208	50-440
Lingenfelter, J.	7811210382*	50-346 B	LONG, F. J.	7812050014* 781120254 7811270011 7812120232 7811280008+	50-348 0	LYNCH, M. D.	7811270349	50-397
Lingenfelter, J.	7812070199*	50-346 B	LONG, F. J		50-261 0	MACARTHUR, T. C.	7612080010*	50-280
Lingenfelter, J.	7812140140*	50-346 B	LONG, F. J.		50-338 0	MACCARY, R. R	7611200157*	50-437
Liou, C. P.	7811090136*	50-329 A	LONG, F. J.		50-250 0	MACCARY, R. R	7611200156*	50-437
Lipineki, H. C.	7810230382	50-267 0	LONG, F. J.		50-321 0	MACCARY, R. R	7611200153*	50-437
LITTLE, D. B.	7810130087	50-522 0	LDNO, F. J	7811280390*	50-269 0	MACCARY, R. R.	7811200136* 7811200441* 7811200442* 7811200205* 7811220094	50-437
LITTLE, W. B.	7810310168*	50-182 0	LONG, F. J	7812040180	50-395 0	MACCARY, R. R.		50-437
LITTLE, W. B.	7811130010*	50-331 0	LONG, F. J	7811220003*	50-335 0	MACCARY, R. R.		50-437
LITTLE, W. B.	7811150055*	50-346 0	LDNO, F. J	7811220059*	50-321 0	MACCARY, R. R.		50-437
LITTLE, W. B.	7812070078*	50-263 0	LDNO, F. J	7811130228*	50-348 0	MACKENZJE, V.		50-592
LITTLE, W. 8. LITTLE, D. 8. LITTLE, D. H. LITTLE, H. B.	7812210054* 7812200109* 7812130227 7812040047 7812210043*	50-282 Q 50-263 Q 50-522 Q 50-295 T 50-358 Q	LDNO.F.J. LDNO.F.J. LDNO.F.J. LDNO.F.J. LDNO.F.J.	7812010104* 7812050070* 7812050158 7812060224 7812060258	50-250 0 50-302 0 50-327 0 50-338 0 50-280 0	MACVITTIE, D.K. MACVITTIE, D.K. MACVITTIE, D.K. MACVITTIE, D.K. MACVITTIE, D.K.	7811070273+ 7811070165+ 7811210283+ 7811210287+ 7811210292+	20-550 20-550 20-550 20-550 30-550
LITTLE, M. S. LITTLE, L. H. LITTON, F. LIV. L. LIV. L	7812290025# 7812040045 7811220070# 7811280036 7811270202	50-255 0 50-295 T 50-549 T 50-331 P	LONG, F. J. LONG, F. J LONG, F. J. LONG, F. J. LONG, F. J.	7811030031 7812050053 7811100017 7812060334 7812070313	50-338 0 50-259 0 50-302 0 50-338 0 50-349 0	MADDEN, H. J. MADDEN, H. MADEDA, T. J. MADEDA, T. J. MADEDA, T. J.	7811080177# 7812280309# 7810240035# 7812050391# 7811090044#	50-333 50-293 50-315 50-315 50-87
LIU, L.	7810230173	50~331 F	LONG, F. J.	781 1130256	50-321 0	MADEDA: T. J.	7811300117*	50-255
LIU, L.	7810240112	50~331 0	LONG, F. J.	781 2060345 **	50-321 0	MADGETT: J. P.	7810160142	50-409
LIU, L.	7810310220	50~331 P	LONG, F. J.	781 2140151	50-280 0	MADGETT: J. P.	7810120035	50-409
LIU, L.	7811070121	50~331 F	LONG, F. J.	781 1130237	50-280 0	MADGETT: J. P.	7810240123	50-409
LIU, L.	7811170159	50~331 F	LONG, F. J.	781 1200127	50-280 0	MADGETT: J. P.	7810240143	50-409
L I U	7811210354 7812030156 7812030132 7812110106 7812130136	50-331 F 50-331 B 50-333 F 50-331 F 50-331 P	LONO, F. J.	7612140265* 7812140270* 7612180312 7612180308 7612180320	50-255 0 50-355 0 50-302 0 50-302 0 50-259 0	MADGETT, J. P. MADGETT, J. P. MADGETT, J. P. MADGEN, O. L. MADGEN, O. L.	7810310066 7810310080 7811240233 7810130053# 7810130045	50-409 50-409 50-409 50-313 50-313
LIU, L.	7812270297	50-331 P	LDNO. F. J.	7812180340*	50-324 0	Madsen.o.L. Madsen.o.L. Madsen.o.L. Hadsen.o.L. Madsen.o.L.	7810110304	50-267
LOE, L.	7810260088	50-466 Q	LONO. F. J.	7812210344*	50-302 0		7810140132	50-298
LOE, L.	7811200004	50-466 Q	LONO. F. J.	781220110	50-267 0		7810140092≥	50-313
LONG F. J.	7812150057	50-261 Q	LONO. F. J.	7812210108	50-280 0		7810140133≥	50-299
LONG, F. J.	7811010423*	50-280 Q	LONO. F. J.	7812210147*	50-335 0		7810140089	50-313
LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J.	7811010414 7810310069* 7810310060 7810240208* 7810110231*	50-280 Q 50-259 Q 50-259 Q 50-250 Q 50-261 Q	LONG, F. J LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J.	781 1220087 781 2270383 781 2170238* 781 2070097* 781 2060329*	50-240	Madben. O. L. Madben. O. L. Madben. O. L. Madben. O. L. Madben. O. L.	7810180206 7810120012 7810120016# 7811030036# 7811030034	
Lano, F. J. Lano, F. J. Lano, F. J. Lano, F. J. Lano, F. J.	7810110256# 7810110295# 7810239059# 7810239068# 7810110284	50-250	LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J. LONG, F. J.	7812130311* 7812140046* 7812050008 7812050063 7812280290*	50-269 0 50-269 0 50-348 0 50-302 0 50-321 0	Madeen. O. L. Madeen. O. L. Madeen. O. L. Madeen. O. L. Madeen. O. L.	7811060051 78110600558 7811210114 7810110260 7810110276	50-298 50-298 50-313 50-267 50-313
LONG, F. J.	7810130047*	50-366	Long, F. J.	761 22001 58*	50-13 G	Madben, O. L.	7810110219	50-285
LONG, F. J.	7810300017*		Long, F. J.	781 2100236	50-250 G	Madben, O. L.	7810110224	50-365
LONG, F. J.	7810230023*		Long, F. J.	781 2210333	50-302 G	Madben, O. L.	7810230209	50-276
LONG, F. J.	7810230067*		Lowenbtein, R.	781 0230324	50-344 G	Madben, O. L.	7811170119*	50-176
LONG, F. J.	7810130095*		Lowenberg, H.	781 02110072*	30-437 G	Madben, O. L.	7811210480	50-313
LONG, F. J.	7810230339*	50-335 0	LOWERRE, R. W.	781 1290014	50-498 Q	Madben, Q. L.	7811170111	\$0-28
LONG, F. J.	7810130072*	50-348 0	LUCD, J. E.	781 1010368#	50-275 Q	Madben, Q. L.	7811170114-	
LONG, F. J.	7811010269	50-259 0	LUNDVALL, A. E.	781 0250143	50-317 P	Madben, Q. L.	7811280058	
LONG, F. J.	7810250116	50-302 0	LUNDVALL, A. E.	781 0180073	50-318 P	Madben, Q. L.	7811280062-	
LONG, F. J.	7810250139	50-280 0	LUNDVALL, A. E.	781 0230146	50-317 P	Madben, Q. L.	7812060324	

REHTUA	ACCESSION NUMBER	SUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	TOBLEUB
Madsen. O. L Madsen. O. L Madsen. O. L Madsen. O. L Madsen. O. L	7811200325 7812210159 7812210169% 7811080106 7812130327%	50-348 0 50-368 0 50-368 0 50-398 0 50-313 0	MANRY, M MANRY, M. MANRY, M. MANRY, M MANRY, M.	7810310165 7810310117 7810310151 7810310160 7810310175	50-321 5 50-321 5 50-366 5 50-321 9 50-366 6	MARTIN, R D. MARTIN, J B MARTIN, I J. MARTIN, R D MARTIN, R D.	7811220099* 7811200219 7810170133* 7811200024* 7812120237*	50-260 0 50-201 P 50-272 P 50-327 0 50-290 0
Madsen, O l Madsen, O l Madsen, O l Madsen, O l Madsen, O. l.	7812180348 7811210128+ 781206034B 7812190053 7812190061+	50-313 0 50-313 0 50-313 0 50-313 0	Manqy, M. Manry, M. Manry, M. Manry, M. Manry, M.	7811060130 7811140243 7811060131 7811060133 7811140136	50-366 6 50-366 6 50-321 5 50-321 8 50-321 8	MARTIN-K. MARTIN, I J. MARTIN, I O. MARTIN, R D MARTIN, W G	7812130090 7811140274* 7812130214 7812070315* 7812050286	50-220 0 50-311 0 50-245 0 50-369 0 50-97 0
Madsen. O. L. Madsen. O. L. Madsen. O. L. Madsen. O. L. Madsen. O. L.	7811170289 7811130079 7811130313 7812180328 7812190187	50-148 0 50-278 0 50-313 0 50-267 0 50-267 0	Manry, M. Manry, M. Manry, M. Manry, M. Manry, M.	7811140209 7811140198 7811210246 7812260154 7811160066	50-366 S 50-366 S 50-366 S 50-321 P 50-321 R	MARTIN.R D MARTIN.J A MARTIN.J A MARTIN.R. MARTIN.U G.	7812140277* 7811220060* 7811220065* 7811130247 7812260300	50-335 0 50-549 T 50-549 T 50-364 A 50-293 0
MADSEN. O. L HADBEN. O. L MADSEN. O. L MADSEN. O. L. MADSEN. O. L	7812270020 * 7812270017 7811270123 7812210180 7812210184 *	50-313 0 50-313 0 50-298 0 50-298 0 50-298 0	MANRY, M. MANRY, M MANRY, M MANRY, M. MANRY, M	7811160106 7811210351 7811210398 7811210342 7811210238	50-366 R 50-366 S 50-366 S 50-321 S 50-366 S	MARTIN, T. J. MARTIN, R. D. MARTIN, A. Q. MARTIN, R. D. MARTIN, R. D.	7812280215* 7812210154* 7812270386* 7812070148* 7812130317*	50-311 0 50-335 0 50-390 0 50-321 0 50-269 0
MADSEN. O. L MADSEN. O. L MADSEN. O. L MADSEN. O. L. MADSEN. O. L.	7812070002 + 78120603	50~128 G 50~149 B 50~128 G 50~285 G 50~368 G	Manry. M Manry. M Manry. M Manry. M. Manry. M.	7811220026 7811210361 7812060392 7812070033 7812070035	50-321 8 50-321 8 50-321 8 50-321 8 50-366 8	MARTIN, T. J. MARTIN, H. E. MARTIN, W. E. MARTIN, W. E. MARTIN, W. E.	7812070224 7812150056 7812130064 7812200344 7812200338	50-354 B 50-275 T 50-275 T 50-275 T 50-275 T
MADBEN. O. L. MADBEN. O. L. MADBEN. O. L. MADBEN. O. L MADBEN. O. L.	7812290239 7812060049 7812060278 7812180421 7812180424	50-267 Q 50-298 Q 50-285 Q 50-59 Q 50-59 Q	MANRY, M MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7812070038 7811280217 7811280222 7811280235 7811280268	50-366 8 50-366 8 50-366 8 50-321 8 50-366 8	MARTIN.H.E MARTIN.HE. MARTIN.T.J. MARTIN.HE. MARTIN.HE	7812220014 7812290002 7812280204* 7812290279 7812290280	50-275 T 50-275 T 50-477 0 50-275 T 50-275 T
MADSEN, D. L. MADSEN, O. L. MADSEN, O. L. MAGUIRE, P. J. MAHAN, R. R.	7812130309 7812210216 7812210224 7811210341 7810300384	50-313 0 50-313 0 50-368 0 50-293 8 50-395 0	Manry, M Manry, M. Manry, M. Manry, M. Manry, M.	7812180164 7812180182 7812180231 7812180201 7812180135	50-321 8 50-366 8 50-366 8 50-366 8 50-366 8	Martin. U.E. Martin. W.E. Magge. R.E. Magge. R.E. Magge. R.E.	7812290282 7812290283 7811090189* 7812120231* 7812130045*	50-275 T 50-275 T 50-315 0 50-305 0 50-315 0
Mahan, R. R Mahan, R. R. Mahan, R. R Makepeace, J. M Makepeace, J. M	7810300387* 7810190229 7810190163 7810110155* 7810160110*	50-395 G 50-395 G 50-395 G 50-247 S 50-247 S	MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7812180162 7812180179 7812150287 7812150334 7812180178	50~366 8 50~366 8 50~321 R 50~366 R 50~366 6	MATERS B R MATERS B R MATERS B R MATHIS C. J. MATHIS C. J.	7810120021 7810130146 7811280231 7810310163* 7811080156*	50-16 J 50-341 A 50-341 A 50-293 B
MAKEPEACE, J M. MAXEPEACE, J M. MAKEPEACE, J M. MAKEPEACE, J M. MAKEPEACE, J.	78101601134 7810160141* 7810160165* 7811070230* 7811210344*	50-247 8 50-247 8 50-247 8 50-247 8 50-3 R	Manry, M. Manry, M. Manry, M. Manry, M. Manry, M.	7812180163 7812180220 7812180214 7812270280 7812270295	50-321 8 50-366 8 50-321 8 50-321 8	MATHIB.C.J. MATHIB.C.J MATHIB.C.J MATHIB.C.J. MATHIB.C.J	7811090168* 7811140212* 7811140188* 7811210345* 7812040176*	50-273 8 50-273 8 50-273 8 50-273 8 50-273 8
MAKEPEACE, J. M. MAKEPEACE, J. M. MAKEPEACE, J. M. MAKEPEACE, J. M. MALMROS, M. H.	7811280270+ 7811280263+ 7812190131+ 7812200208+ 7811270115+	50-247 8 50-247 8 50-247 8 50-247 8 50-247 8 50-344 0	MANRY, M MANRY, M. MANRY, M MANRY, M MANRY, M	7812270315 7812270325 7812270266 7812270314 7812270319	50-321 8 50-366 8 50-366 8 50-366 8 50-366 8	MATHIB-C J. MATHIB-C J. MATHIB-C J. MATTHENS.P.R MATTEA.J.C.	7812050192+ 7812120141+ 7812180172+ 7811060093+ 7812130112+	50-293 8 50-293 8 50-293 8 50-356 9 50-352 0
MALMROS-M H MALONEY-O. P. MALONEY-G P. MANRY-M. MANRY-M.	7812130324+ 7811270171 7812270182 7812260136+ 7810170236	50-344 0 50-315 P 50-315 P 50-321 P 50-366 8	MANRY.M. MARCH.L.T. MARKE.D. MARKE.D. MARKE.D. MARKONSKI.R B.	7812270326 7810240137* 7811060077 7811130415 7812010103*	50~366 8 50~488 H 50~466 0 50~466 0 50~309 Q	MATTIMOE. J. J. MATTIMOE. J. J. MATTIMOE. J. J. MATTIMOE. J. J. MATTIMOE. J. J.	7810100050 7810100073 7810100016 7810100061 7811030149	50~312 8 50~312 8 50~312 8 50~312 8 50~312 8
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7810170226 7810170233 7810170235 7810170236 7810170291	50-366 8 50-321 8 50-366 8 50-321 8 50-321 8	MARKOWSKI.R. MARKOWSKI.R.S MARLEY.J. MARLEY.J MARQUARDT.P.A.	7811100148* 7812020147* 7810160127* 7812120173* 7810200111	50-311 0 50-334 0 50-346 8 50-346 9 50-452 A	MATTIMOE J.J. MATTIMOE J.J. MATTIMOE J.J. MATTIMOE J.J. MATTIMOE J.J. MATTIMOE J.J.	7811030133 7810130131 7810130178 7810170179 7810120027	50-312 8 50-312 8 50-312 8 50-312 8 50-312 P
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M	7810180031 7810180112 7810170311 7810170329 7810180029	50-366 S 50-321 S 50-366 8 50-321 B 50-321 B	MARRACH, D. MARRACH, D. MARBHALL, W. H. MARBHALL, W. H MARBHALL, W. H	7811020244 7811300111 7811010014+ 7811080048 7811130192+	50-466 0 50-466 0 50-329 H 50-329 0 50-329 0	J. J	7810230160 7810200104 7810230099 7810230277 7811130089	50-312 8 50-312 8 50-312 8 50-312 8 50-312 0
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7810180116 7810180019 7810170318 7810170322 7810180037	50-366 8 50-366 8 50-366 8 50-366 8 50-366 8	MARSHALL W. H MARSHALL W. H. MARSHALL W. H. MARSHALL W. H. MARTIN, R. D	7811100146 7811210040 7811150039 7811300356 7810110236*	50-329 0 50-329 0 50-329 0 50-329 0 50-261 0	MATTIA, J. C. MATTIMOE, J. J.	7812190155* 7811070201 7811140230 7811270096* 7812120147	50-483 Q 50-312 P 50-312 8 50-312 G 50-312 8
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7810180120 7810170309 7810170312 7810180023 7810180001	50-366 8 50-366 8 50-366 8 50-366 8 50-366 8	MARTIN, N. O. MARTIN, N. O. MARTIN, N. O. MARTIN, N. D. MARTIN, R. D. MARTIN, R. D.	7810190107* 7810180215* 7810180178 7810130051* 7810230064*	50-57	MATTIMOE J. J. MATTIMOE J. J. MATTIMOE J. J. MATTIMOE J. J. HATTIMOE J. J. HATTIMOE J. J.	7811170117 7811210319 78122902530 7811210261 7811280209	50-312 P 60-312 P 50-485 Q 50-312 P
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7810180003* 7810180010 7810180011* 7810180020 7810230206	50-366 8 50-321 8 50-321 8 50-366 8 50-366 8	MARTIN, W.O. MARTIN, H.O. MARTIN, W.O. MARTIN, R.O. MARTIN, T.J.	7811010093* 7811080172 7811080236 7811200214* 7810100020	50-277	MATTIMOE J. J.	7812050116 7812050146 7812080094 7812110170 7812130107	50-312 P 50-312 F 50-312 P 50-312 6 50-312 P
MANRY, M. MANRY, M. MANRY, M. MANRY, M. MANRY, M.	7810230175 7810230188 7810310148 7810310167 7810310205	30-321 8 30-346 8 50-321 8 50-321 8 30-366 8	MARTIN.T. J. MARTIN.H. G. MARTIN.H. G. MARTIN.H. G. MARTIN.H. G. MARTIN.H. G.	7810250262+ 7810190104 7812050295+ 7811130412+ 7811010085	50-354 8 50-57 Q 50-97 Q 50-302 O 50-277 Q	MATTIMOE, J. J. MATTIMOE, J. J. MATTIMOE, J. J. MATTBON, R. J. MATTBON, R. J.	7812140142 7812180159 7812200159 7810300307* 7812210323	50-312 P 50-312 P 50-312 P 50-336 Q 50-327 A

	ACCESSION	SUBJECT			ACCESSION	SUBJECT	r		ACCESSION	SUBJECT
AUTHIR	NUMBER	CATEGOR	/ - <del></del>	AUTIUR	NUMBER	CATEGOR		RONTUA	NUMBER	CATEGOR
MATTEON.R J	7811220132* 7812130200*	90-966 848-08	0 P	MCDONALD. J R	7811210046	50-416	A	MEAD. E.	7811020388*	50-349
HATTEDN.R. J HATTEDN.R. J	7812210173*	50~500	A	MCDUFFIE, M A MCDUFFIE, M A	7811140216 7810270123	50-400 50-400	E A	MEAD, E MEANS, D. 8	7811020385 7811130128	50-549
MAURA, F.A MAXWELL, O F	7810110220 7811090003»	90-358 90-367	0	MCDUFFIE M A	7810300140	30-400	A	MECCA, J.E.	7811080142	50-522
			_	MCDUFFIE M A	7611280226	50-400	F	MECCA, J. E.	7811080193	50-522
HAXWELL.O F MAXWELL.O F	7811300254* 7812280244*	30~440 30~367	0	MCDUFFIE M. A MCENENIJE	7812130383 7812210210*	30-400 30-272	g F	MEHAFFEY.R. MEIEROTTO.L E.	781229 <b>0228*</b> 7810240142	50-285 50-582
MAY, E L.	7810183017*	50-29	8	MCFARLAND, C R	7811210088+	50-339	ā	MELNICOFF. M A	7810240142 7811240178*	50-304
MAY.E.L. HAY.E.L	7811280332¢ 7811280323¢	50-29 50-29	8	HCFARLAND, C R HCFARLAND, C R	7812130003* 7812210064*	50-327 50-413	0	MELNICOFF.M A MENDE.R.Q.	7612210213* 7612140152*	30-295 50-251
HAY, E. L.	7812010224	90-29	8							
MAYER L. O.	7812060318	50-263	P	HCOARRY, J. M HCOARRY, J. M	7810120020 7810140127	50-369 50-369	0	MENGÉRIW M. MENNINGIJ. E	7812210029# 7812060340#	50~499 50~331
MAYER.L D. MAYER.L D.	7812080138* 7810180034	50-306 30-306	P 5	MCGARRY.J. M MCGARRY.J. M	7810140030 7810140139	30-49B 30-49B	0	MENNING.J.E.	7B11150055* 7B11290336*	50-346 50-266
HAYER. L. O	7810100012	20-505	8	HCGARRY. J. M	761 0230389	50-369	ŏ	MENNINO. J. E	7812210043#	50-358
MAYER. L. O	7810110180	50-263	В	MCQARRY.J. M.	7810200132	50~369	Ť	MERNICKI M. J	7814310200+	50-317
MAYER L D MAYER L D	7810120029 7810120030	20~593	R ft	MCGARRYIJ, M MCGARRYIJ, M	781 1 1 3 0 0 3 4 781 1 2 4 0 0 6 3	50-369 50-468	0	MERRILL.D.N. MERRILL.D.N	7810310189* 7811070140*	50-443 30-443
MAYER L O	7610160122	50-263	F P	MCGARRY, J. M	7811220231	50-488	ō	MERSON. B. D.	7810230178	30-317
HAVER, L O	7810170099	90-563		MCGARRY, J. M	7011220272	50-369	G	MERSON. 8 D.	7811240215	50-317
MAYER.L.O	7810170220 7810180021	50~282 50~282	P 8	MCGAUGHY, R. W MCGAUGHY, R. W	7812130112+ 7810230261+	50-352 50-354	0	MERSON. 8 D. HERSON. 8 D.	7811240217 <b>+</b> 7812220076	50-317 50-317
MAYER. L. O	7810250076	20-593	P P	MCGAUGHY, R. W	7812120026*	50~322	o	MERBON, S. D.	7812220077*	50-317
MAYER.L.O MAYER.L D	7810200078 7810300191	20-593 20-593	9	MCQAUGHY, J. P MCQAUGHY, J. P.	781 1 150097 781 1 160073	50-416 50-416	O A	MEYER.B.A. MEYER.B.A.	7812110147+ 7812210228+	50-295 50-295
MAYER.L D.	7810300237	20-505	p	HCQAUGHY, J. P.	7812060400	50-416	8	MICHULKA C. L.	7810310372	90-466
MAYER, L D	7811240124	50-563	Ð	HCQAUGHY, R. W	78122902384	50-387	G	MICHULKA C. L.	7811170006	50-466
MAYER.L D MAYER.L.D	7811070247 7811130113	50-282 50-282	B P	MCGAUGHY, R. MCGAUGHY, J. P	7812290253 <b>&gt;</b> 7812070179	50-485 50~416	8	MICHULKA C. L. MIDURA H J,	7812210368 7810160084	50-466 50-272
MAYER, L. O.	7811140194	50-263	F	MCGAUGHY, J. P.	7812120098	50-416	Ä	HIDURA: H J.	7810180092	30-272
MAYER L D	7811140143	50-282	F	MCQAUQHY, J. P	7812290133	50-416	A	HIDURA. H J.	7810100128	50-272
MAYER, L. D. MAYER, L. D	7811140115 7811160116	50-263	R R	MCQAUGHY, J. P MCQAUGHY, J. P	7812140133 7812290260	50-416 50-416	0	HIDURA, H. J. HIDURA, H. J.	7810180144 7810310137	50-272 50-272
MAYER L.D.	7811210334	20-593 20-593	P 8	HCQAUQHY, J. P	7812290256	50-416	a	MIDURA, H J.	7811130266	50-272
	7811280234			MCGUTRE.P. J.	7610180130	50-293	R	MIDURA, IL J.	7810310180	50-272
HAYER, L. D MAYER, L. D	7811260279 7812070221	20-563	P P	MCOUTRE P. J.	781031015B 7811210263	50-293 50-293	8 R	MIDURA, H. J. MIDURA, H. J.	7811130263 7811170181	50-272 50-272
MAYER.L.D.	7812080135	90-306	P	HCOUIRE, D. R	7812110251+	50-324	Q	MIDURA, H. J.	7811280460	50-272
MAYER.L.O MAYER.L.O.	7812110118 7812110136	50~263	P R	MCQUIRE.P. J MCQUIRE.P. J	7811080152 781109016 <b>1</b>	50-293 50-293	<b>8</b>	MIDURA, H. J. MIDURA, H. J.	7811160074 7811210323	50-272 50-272
MAYER. L. D	7812120091	20-585	R	MCGUIRE.P. J.	7811140207	50-293	S	MIDURA, H. J.	7811210343	50-272
MAYER, L. Q.	7812140143	50-263	P	MCOUIRE,P. J.	7811140183	50-293	9	HIDURA, H. J.	7812050229	50-272
MAYER L. O. MAYER L. O	7812140159 7812200283	50-30A 50-263	8 9	MCGUIRE.P. J. MCGUIRE.P. J	7811280333 7012040173	50~293 50~293	8	MIDURA, H. J. MIERNICKI, M. J	7812150242 7810270240*	50-272 50-317
MAYER. L. O.	7812200211	20-593	8	MCGUIRE, P. J.	7812050185	50-293	8	MIERNICKI, H. J.	78110101116*	50-317
HAYER, L. O.	7812260256	90-563	9	MCOUTRE P. J	7612200183	50-273	R	MIERNICKI, M. J.	7811130214+	50-318
MAYER, L. O. MAYER, L. O.	7812260207 7812260222	50~304 50~304	8 8	MCQUIRE.P. J.	7812120135 7812180168	50-293 50-293	6 6	MIERNICKI, M. J. MIERNICKI, M. J.	7911210409* 7812130187*	50-317 50-31 <i>0</i>
MAYER.L.Q.	7812270232	50~263 50~263	8 8	HCQURREN, 11. J.	7810170012	50-549	0	HIERNICKI, M. J.	7812130194*	20-317
MAYER, L Q.	7812270241			HCQURREN, H. J	7810190015*	50-549	o	MIERNICKI, M. J.	7812260248+	30-318
MAYER, L. O MAYNARD, C. J	7812270246 7810160197*	50-263 50-329	8	MCGURREN, H. J. MCGURREN, H. J	7810190018* 7810190021*	50-549 50-349	0	MILHOLLIN, O. L. MILHOLLIN, O. L.	7810230322 7811010063	50-272 50-23 <i>1</i>
MAYNARD, R.	7812130191	50-341	Q	MCQURREN, H. J.	7810190024*	50-549	Q	MILHOLLIN, O. L	7811090259	50-237
MAYNARDIR, MAZZOLAIG, A	7812130202+ 7812030334+	50~341 50~549	O T	MCQURREN. H. J MCQURREN. H. J.	7810240222 7811170027	50-549 50-549	e F	MILHOLLIN, O, C. MILHOLLIN, O, C.	7811160021 7811200003	50-237 50-237
MCALL 18TER . R. J.	7810200050+	50-334	P	MCOURREN H J	7811130234	50-341	e	MILHOLL IN G. L.	7812110284	50-237
MCBREARTY, R A.	7811140280+	50-311	o	MCQURREN, H. J.	7811150113	50~341	0	MILHOLLIN, O. B.	7812270133	50-237
MCBREARTY, R. A MCBREARTY, R. A	7812280319* 7812270457*	50~318 50~333	0 0	MCOURREN, H. J. MCOURREN, H. J.	7812050059 7812050370	50-341 50-341	0	Miller, R. N Millen, C. K	7810300338* 7810110264*	50-201 50-267
HCCABE, E.C.	7611300363*	50-184	G	MCOURREN H. J.	7812050372+	50-341	e	MILLER, O. P.	7811150145	50-289
HCCABE. E. C.	7810250227+	50-219	g	MCOURREN, H. J.	7812050090	50-370	G	HILLER, L. E.	7810230092*	50-70
MCCABE, E. C. MCCABE, E. C	7811070038* 7810160082*	50-277 50-293	Q Q	KCOURREN H. J. KCHENRY, T. J	78120302 <b>39</b> 7811080289*	50-498 50-261	G G	MILLER,M.I. MILLER,W.O.	7610110309 7810110030	50-329 50-254
MCCABE, E. G. MCCAFFREY, B. R.	7812110316* 7810200071	50~245 50~322	g K	MCHENRY, T. J. MCHENRY, T. J.	7811220256* 7812150063*	50-261 50-261	Q Q	MILLER, M.E. MILLEN, C. K.	7810200135 7810120063	50-344 50-267
MCCANN. W. J. MCCAUGHAN. D. M	7810110129* 7811070352	50-336 50-510	B 0	MCHENRY.T. J. MCINDOE.D. W	7812200161* 7810130227	50-13 50-170	G P	MILLEN, C. K. MILLER, L. K.	7810120064* 7810160090*	50-2 <i>67</i> 50-272
MCCAUGHAN, D. M. MCCLAIN, C. M	7811070354 7810230261+	50~498 50~219	Q R	MCKEOWN.L. MCKIBBEN.J.C.	7811080245* 7811060076	50-271 50-186	0 8	MILLER, H. O. MILLER, H. O.	7810120104 7810140112	50-335 50-237
MCCLAIN.C.M	7811210241*	50-219	Ř	MCKIBBEN J. C.	7812290080	30-185	ř	HILLER, W O.	7810230157	50-285
HCCLAIN.C. M	7812200182*	50-219	R	HCKINLEY, J. C.	7811010384*	50-275	o	MILLER, D. E.	7811170319*	50-6
MCCOLLUM K A	7611020379 7611100054	50-344 50-344	T T	MCLANE, F. E. MCMANUS, C. K.	7810170259* 7810230375	50-537 50-206	A	MILLER, M.E. MILLER, W.O.	7811070025 7810230159	50-344 50-289
MCCOLLOM K. A	7811100050	50-344	T	MCMANUB.C. K	781122017B#	50-329	8	MILLER, W O.	7810240020	50-219
MCCOLLOM K. A.	7811130305	30-344	T	HCNAMARA A. E.	7810170215*	50-244	R	MILLER, M. E.	7810310366	50-344
MCCOLLOM K. A. MCCOLLOM K. A	7811100058 7811100024	50-344 50-344	Ţ	MCNAT T. T. MCNUTT, J. R.	7811140043* 7811240166	50-311 50-329	G A	MILLER, M. I. MILLER, M. E.	7810300311 7810260203	50-329 50-498
MCCOLLON K. A	7811100111	50-344	Ť	HCHHORTER, R. J.	7810130157	50-580	A	MILLER, M. E.	7811010153	50-445
MCCOLLON K. A. MCCOLLON K. A	7811100019 7811130380	50-344 50-344	T T	MCHHORTER, R. J. MCHHORTER, R. J.	7810160128 7810230201	50~380 50~380	E	MILLER, W.O. MILLER, W.O.	7810260076 7810300003	20-520 20-313
HCCOLLON K. A.		30~344	1	HCHHORTER, R. J.	7610250115	50-580	A	MILLER, M.O.	7810300290	50-339
MCCOLLON K. A.	7812280003 7812280004	50~344	T	HÇIHOR TER: R. J.	7B11140184	50~580	E	MILLER, N. E.	7811020379	50-344
MCCORKLE, B. A. MCCORKLE, B. A.	7811130129 7812040300	50-466 50-466	0	HCWHORTER, R. J. HCWHORTER, R. J.	7811150126 7812050196	50-580 50-580	S A	MILLER, W. O. MILLER, W. O.	7811080078 7810300378	50-285
MCCORKLE B. A	7812040303	50-466	ŏ	MCWHORTER, R. J.	7812270204	50-580	A	MILLER, M.E.	7811100054	50-344

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	TOBUBUB CATEGORY	AUTHDR	ACCESSION NUMBER	SUBJECT
MILLER, M E MILLER, M E MILLER, M E	7811100050 7811130305 7811100058	50-344 T 50-344 T 50-344 T 50-220 P	HILLER M E. HILLER M I. HILLER J E HILLER J E	7812140221 7812280350 7812150258 7812220062	50-445 M 50-329 0 50-39 P 50-267 P	MOON, C. H MOON, C. H MOON, C. H MOON, C. H	7810230163 7810300241 7811170356 7811130236	50-443 50-466 50-466 50-443
MILLER.W O MILLER.L F MILLER.M I MILLER.M E	7811150154 7812050238+ 7811150080 7811100024	50-326 G 50-329 G 50-344 Y	MILLER.CK MILLER.LK MILLER.WO	7812220069# 7812150244= 7812150228	50-267 P 50-272 R 50-237 P	MOON, C. H. MOORE, R. N. MOORE, D. E	7811270297 7811270286 7811130007*	50-466 50-597 50-250
MILLER, M E MILLER, M E	7811100111 7811100019 7811130380	50-344 T 50-344 T 50-344 T	HILLER: M E HILLER: M E HILLER: J.	7812260003 7812260004 7812220079	50-344 T 50-344 T 50-59 F	MOORE, J. MOORE, H. Q. MOORE, Q. H.	7810230101 7811030104# 7810200047	50-361 50-390 50-334
MILLERIN D MILLERIN E MILLERID E MILLERIN E MILLERIL N	7811150016 7811210458 7812120226* 7811210235 7811160075*	30-335 P 30-344 G 30-331 G 30-445 M 30-272 R	MILLBAP, W. J. MILLBAP, W. J. MILLBAP, W. J. MILLB, L. H. MILLB, W. R.	7810120004+ 7811010191# 7810300385+ 7810170197 7810270001	50-259 0 50-338 0 50-369 0 50-327 K 50-322 A	MOORE, V. A. MOORE, V. A. MOORE, J. B. MOORE, V. A.	7810240228* 7811060036 7811030169 7811140177 7811170133	50-368 50-445 50-334 50-206 50-463
MILLER, L. K MILLER, W O MILLER, W O MILLER, M I MILLER, M E	7812120131 7811200361 7811240087 7812040235 7811220018	50-272 R 50-346 P 50-285 P 50-556 G 50-568 G	MILLB.M. MILLB.L.M. MILLB.L.M. MILLB.L.M. MILLB.L.M.	7811030101 7811070109 7811150120 7811170215 78111210305	50-390 P 50-438 K 50-390 H 50-259 P 50-327 A	MOORE, J. B. MOORE, V. A. MOORE, D. E. MOORE, O. W MOORE, R.	7812210078* 7812040242 7812140257* 7812060162 7812270052*	50-361 50-463 50-406 50-334 50-320
MILLER. H D MILLER. H D MILLER. H MILLER. L P MILLER. J R	7811240035 7811240041 7812290048• 7812130314• 7812130071	50-368 P 50-334 P 50-390 G 50-275 G 50-10 P	Millb.L.M. Millb.L.M. Miner.B. Miner.B. Miner.B.	7811300198 7812190098 7812010095 7812060133 7812060187	50-327 K 50-390 K 50-367 A 50-387 A 50-387 F	HOORE, V. A HOORE, V. A. HOORE, V. A. HOORE, V. A. HOORE, J. B.	7612120110* 7812120110* 7812120124* 7812120128* 7812210263*	50-518 50-518 50-518 50-318 50-361
NILLER JR MILLER JR MILLER JR MILLER JR MILLER JR.	7812150088 7812150092 7812150097 7812150106 7812150109	50-3 P 50-29 P 50-245 P 50-317 P 50-289 P	MINNICA, L.E. MITCHELL D.O. MITCHELL D.O. MITCHELL D.O. MITCHELL D.O. MITCHELL D.O.	7811020246 7810100099* 7811210186* 7812190170* 7810130134	50-29 P 50-289 8 50-289 8 50-289 8	MOORE, J. B. MOORE, J. B. MOORE, D. E. MOORE, V. A. MOORE, V. A.	7812210388* 7812130177 7812210287* 7812210102* 7812210104*	50-206 50-361 50-274 50-324 50-324
Miller JR. Miller JR. Miller JR. Miller JR Miller JR	7812150113 7812150116 7812150118 7812150120 7812150123	50-309 P 50-335 P 50-333 P 50-302 P 50-269 P	MITTL+R.C MITTL+R.C. MITTL+R.C. MITTL+R.C. MITTL+R.C.	7810170132 7810240149 7810250069 7810250063 7811030119	50-272 P 50-311 A 50-311 A 50-313 F 50-311 K	Moreau. W. N. Moreau. W. N. Moreau. W. N. Morgengtern. L. Moriarty. J. M.	7810120068 7810240132 7811060092 7810300257 7811090134*	50-219 50-219 50-320 50-496 50-423
MILLER-J R. MILLER-J R. MILLER-J R. MILLER-J R. MILLER-J R.	7812150124 7812150130 7812150132 7812150134 7812150135	50-312 P 50-277 P 50-220 P 50-133 P 50-263 P	BITTL+R.L. BITTL+R.L. BITTL+R.L. BITTL+R.L. BITTL+R.L.	7811080102 7811080227 7811090084 7811200152 7811240141	50-311 A 50-311 A 50-311 A 50-311 A	MORIARTY, J M. MORIARTY, J M. MORRIL, P. J. MORRISSEY, J. C. MORRISSEY, J. C.	7811090135* 7811090136* 7811130231* 7810240113* 7810300330	50-423 50-423 50-344 50-133 50-275
MILLER, J R. MILLER, J R. MILLER, J R. MILLER, J R. MILLER, J R	7812150139 7812150141 7812150145 7812150147 7812150148	50-293 P 50-334 P 50-315 P 50-348 P 50-259 P	MITTL+R.L. MITTL+R.L. MITTL+R.L. MITTL+R.L. MITTL+R.L.	7811240225 7812200072 7812270248 7812280200* 7812220143	50-311 A 50-311 A 50-477 A 50-477 Q 50-311 A	MORRILL-P. J. MORRILL-P. J. MORRILL-P. J. MORRILL-P. J. MORRILL-P. J. MORRISSEY, J. C.	7812070246* 7812070045* 7812270456* 7812280358* 7812140085	50-361 50-106 50-133 50-344 50-275
MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, J. R.	7812150157 7812150159 7812150161 7812150164 7812150167	50-324 P 50-298 P 50-331 P 50-321 P 50-271 P	MITTNESS.L.T. MITTNESS.L.T. MJERNICKI, M. J. MLYNCZAK, M. M. MLYNCZAK, M. M.	7812130087* 7811200040 7810110174* 7810300116 7811010204	50~502 0 50~484 0 50~317 8 50~305 F 50~315 P	Morrill.P. J. Morbe.A.K. Morbley.N. C. Morbley.N. C. Monry.W. R.	7812270436# 7810110042 7810270246# 7810300006 7810270104	50-243 50-409 50-329 50-316 50-163
MILLER. J R. MILLER. J R	7812150173 7812150176 7812150181 7812150193 7812150197	50-155 P 50-244 P 50-409 P 50-219 P 50-206 P	MLYNCZAH, M. M. MLYNCZAK, M. M. MLYNCZAK, M. M. MODENOS, L. MODENOS, L.	761 1060339 761 1200373 761 201 0365 761 2060035* 761 2060362*	50-305 P 50-305 P 50-315 P 50-395 Q 50-369 0	MOURY, M.R. MOURY, M.R. MULKEY, M. MULKEY, M.E. MULLER, D. R.	7810270107# 7812190145 7810230168 7812280262 7811200162*	50-163 50-89 50-443 50-247 50-437
MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	781 2150198 781 2150203 781 2150203 781 2150209 781 2150212	30-303 P 30-266 P 30-280 P 50-344 P 30-272 P	HOELLER, D. HOFFATT, D. W. MOHR, T. MOLLERUB, F. J. HONTPOMERY, C. R.	7811100051 7811240188 7810170216* 7812270172 7812010127	30-280 T 30-329 A 50-10 8 30-447 A 30-146 J	MUNRO, B. MUNTZINO, L. M. MUNTZINO, L. M. MUNTZINO, L. M. MUNTZINO, L. M. MURHPY, C. E.	7810140123+ 7811200434+ 7811200086+ 7811200279+ 7812130269+	50-344 50-437 50-437 50-437 50-491
MILLER, J R MILLER, J R. MILLER, J R. MILLER, J R. MILLER, J R.	7812180021 7812180028 7812180033 7812180035 7812180038	50-295 P 50-333 P 50-261 P 50-255 P 50-250 P	HONTI, W.A. HONTI, W.A. HONTI, W.A. HONTI, W.A. HONTI, W.A. HONTI, W.A.	7810240108 7811170160 7812010206 7812040229 7812180152	50-3 P 50-3 P 50-3 R 50-247 S 50-3 R	MURPHY, C. E.	7810110190 7810140075 7811030084* 7811030089* 7810120087	50-438 50-370 50-438 50-438 50-339
MILLER. J. R. MILLER. J. R. MILLER. J. R. MILLER. M. I. MILLER. C. K.	7812180039 7812180044 7812180050 7812050347 7811240226	50-213 P 50-254 P 50-282 P 50-556 Q 50-267 E	MOODY, D. E. MOODY, D. E. MOODY, D. E. MOODY, D. E. HOODY, D. E.	7811020175* 7811150095* 7810170150 7810170192 7810170176	50-271 G 50-307 G 50-309 R 50-271 R 50-29 R	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. HURPHY, C. E. MURPHY, C. E.	7810110298 7810230236 7810240204 7810250074 78110802134	50-566 50-553 50-370 50-424 50-369
MILLER, ME. MILLER, W. Q. MILLER, R. B. MILLER, M. I. MILLER, M. I.	7812040183 7811270260 7812060166 7812140087 7812140362	50-266	MOODY, D. E.	7810180137 7810200090 7810200051 7812010093% 7810270077	50-309 P 50-271 F 50-29 F 50-309 Q 50-309 P	MURPHY: C. E.	7811080215+ 7811080314+ 7810130098+ 7811080154+ 7811080294+	50-369 50-369 50-413 50-395 50-438
MILLER, N. O.	7812040334 7812070278 7812110248 7812080132 7812080212	50-250 P 50-333 P 50-289 H 50-260 P 50-289 H	MODDY, D. E.	7811140112 7811140123 7811140120 7812050210 7812150353	50-309 R 50-271 R 50-29 R 50-29 F 50-309 R	MURPHY, C. E.	7811080294* 7810310081 7810230221* 7810230217 7811039047*	50-369 50-339 50-413 50-413 50-424
MILLER, M. D. MILLER, M. E. MILLER, M. D. MILLEN, G. K. MILLER, M. E.	7812110245 7812270144 7812140343 7812130164 7612130003	50-259 P 50-344 0 50-255 P 50-267 P 50-445 N	HOODY, D. E. HOON, B. T.	7812150290 7812150286 7812150087 7812270276 7810310116*	50-271 R 50-29 R 50-29 F 50-271 P 50-338 G	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, P. M.	7811090266 7811130095 7812050140* 7811130113 7810190216	50-332 50-327 50-327 50-438 50-556

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	-	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	
HURPHY, C. E.	7611090235 m		0	HURRAY, R.	7811240181*	50-234	9	NEWMAN, J. R	781212004B	50-466	G
HURPHY, C. E.	7811140090			MURRAY, T. D.	7811090131	50-346	8	NEUMAN, J R.	7812040274	90-466	Ö
MURPHY, C. E. MURPHY, C. E.	7811150064 7811020355#		a a	MURRAY, T. D.	7810310194	50-346	В	NEWMAN, J. R.	7812040329	50-466	0
MURPHY, C. E.	7811210083		ŏ	MURRAY, B. MURRAY, T. D.	781213033&+ 7811030157	50-313 50-346	8 0	NEWMAN, J. R. NEWMAN, J. R.	7812040333 7812040343	50-466 50-466	G
MURPHY, C E.	7811200029	EO 074	•	_							
MURPHY, C. E.	7811200027		Q Q	HURRAY, T. D. HURRAY, T. D.	7811070184 78110 <b>70</b> 264	50-346 50-346	5 6	HEWMAN, J.R.	7812040350	30-466	G
MURPHY, P. M.	7810260199		Ğ	HURRAY, T. D.	7811070204	50-346	8	NEWMAN, J. R. NEWMAN, J. R.	7812040367 7812050037	50-498 50-466	0
MURPHY, C E.	7812040059*		Q	HURRAY, T. D.	7811090178	50-346	8	NEWMARK.N M	7812040321	50-275	Ğ
MURPHY, P. M.	7811010433	30-35A	0	MURRAY. 9.	7812190193*	50-267	Q	NEWMAN, J. R.	7812110256	90-466	O
MURPHY, C. E.	7812060029 <b>4</b>	50~395	Q.	HURRAY. T. D.	7811140135	50-346	R	NEWHAN, J. R.	7812040024	50-466	o
HURPHY, C. E.	7811240027*		Q.	MURRAY. T. D.	7811210347	30-346	ä	NEUMAN, J R.	781207005B	50-466	Ğ
MURPHY.C E. MURPHY.C E.	7811300334 7812010038		0 0	MURRAY, T. D.	7811210372	50-346	9	NEWHAN, J. R.	7812120224	50-465	0
MURPHY, C. E.	7811240065		a	MURRAY, T. D. MURRAY, T. D.	7811200209 7811280198	50-346 50-346	8	NEWMAN, J. R. NEWMAN, J. R.	7812040331 7812050046	50-466 50-466	0
					70	50 510			7212030040	30-400	
HURPHY, C. E. HURPHY, C. E.	7811290321 7811220282*		G G	MURRAY, T. D.	7812010207	50-346	8	NEWMAN, J.R.	781.1130020	30-466	0
MURPHY, C. E.	7811030057		ā	HURRAY, T. D. HURRAY, T. D.	7812050157 7812050204	50-346 50-346	8	NEWMAN, J. R. NEWMAN, J. R.	7812130025 7812130219	50-466 50-466	9
MURPHY, C. E.	7812030303	50-327	Q	HURRAY, T. D.	7812050217	50-346	8	NEWMAN, J R.	7812280308	50-582	Ğ
MURPHY, C. E.	7812050169	50-296	a	HURRAY, T. D.	7812150278	50-320	8	NEWTON, R. A.	7811150262	50-266	O
MURPHY, C. E.	7811300167*	50~400	0	MURRAY. B.	7812290244*	50-267	œ	NEWTON- R. A.	7811240119	50-266	ø
MURPHY, C. E.	7B12070024*	50-364	G	HURRAY, T. D	7812070196	50-346	8	NEWTON, R. A.	7812030049	30-266	č
MURPHY, P. M.	7811130040	50-556	0	MURRAY. T. D.	7812070198	50-346	8	NICHOLAS H	7811080292*	50-311	0
MURPHY, P. M. MURPHY, C. E.	7811140047 7811080147	50-556 50-395	0	MURRAY, T. D. MURRAY, T. D.	7812120165 7812120140	50-346 50-346	<b>9</b> 8	NICHOLAB. H NICHOLAB. H	7811100102* 7811100164*	50-311 50-311	0
		00 070	•	HOME IT I. U.	7012180140	30-340	4	WICHOLAS II	70111001044	30-311	G
MURPHY, C. E.	7611080205	90-369	0	MURRAY, T. D.	7812120172	50-346	8	NICHOLB.T. C.	7810190239+	50-395	0
MURPHY.C.E. MURPHY.C.E.	7811080250 7811080251	50-369 50-438	0	MURRAY, T. D.	7812140137	50-346	8	NICHOLAB, H. NICHOLAB, H.	7811140043* 7612060355*	50-311	g
MURPHY, C. E.	7812070016	50-43B	œ.	MURRAY, T. D. MURRAY, T. D.	7812150296 7812150115	50-346 50-346	8 8	NI CHOLABIH.	7812290044*	50-311 50-311	G
MURPHY. E.	7811210312	50-275	Ĥ	HURRAY: T. D.	7812290200	50-346	8	NICHOLS. T. C.	7812200288	50-395	J
MIDDLY . D M	7611210107	50-536	0	MYGATT. S. C.	70101-0100	80-840	A	NIELBEN.D.	7010010075	50275	٨
MURPHY, P. M. MURPHY, C. E.	1815090598	50-327	ā	MYRABO, A.L.	7810110109 7810120032*	50-563 50-568	A R	NIELBEN.D.	7812210235# 7812210209#	50-275 50-275	A
MURPHY, C. E.	7812060287	50-327	a	MYRABO. A L.	7811160117*	50-263	R	NIELBEN. D	7812210225*	50-275	Α
MURPHY. C. E.	7812130001	50-327	9	MYRABO, A. L.	7812110140*	50-263	R	NIELSEN.E. S	7812260194	50-289	8
MURPHY. C. E.	7812070319*	80-269	a	NAIDU, K.R.	7811140269+	50-341	0	NILSON, R.	7811130179	50-964	J
MURPHY, C. E.	7812080046	50-518	a	NAIDU.K.R.	7812040163*	50-546	G	NIX. R. T.	7810180033*	50-366	8
MURPHY, C. E.	7812120033*	50-395	a	NAPUDA. Q.	7810260028*	20-550	g	NIX, R. T.	7810180114*	50-321	8
MURPHY, C. E.	7812150192 7812050281	50-370 50-556	0	NAPUDA, G. NAPUDA, G.	7811090017* 7811100148*	50-247 50-311	a a	NIX.R.T. NIX.R.T.	7810170315* 7810180014*	50-366 50-321	8
MURPHY, P. M MURPHY, C. E.	7811150058	50-395	å	NAPUDA: O	7812290053+	30-271	ä	NIX, R. T.	7810170313	50-366	8
			_				_	MAN T	7010170014	** ***	
MURPHY, C. E. MURPHY, T. D.	7812150030 7811220084*	50-327 50-549	G T	NARBUT.P.P.	7811270058* 7811080200*	50-312 50-363	g g	NIX.R.T. NIX.R.T.	7810170314* 7810310214*	50-366 50-366	8
MURPHY, C. E.	7812180349	50-416	Ġ	NARROW L.	7810270392*	50-363	ă	NIX. R. T.	7810310154*	30-366	3
MURPHY. C. E.	7812040170*	50-395	Q.	NARROW. L	7811300387	50-410	g.	NIX.R.T.	7810310166*	20-351	9
MURPHY, P. M.	7012040235	30-336	Ģ	NABH. E. J.	7812270033*	20-350	0	NIX.R.T.	7810310181*	50-366	8
MURPHY, C. E.	7811290322*	50-389	Q	NASH. E. J.	7811030174	50-320	P	NIX. R. T.	7811060153*	50-366	8
MURPHY, C. E.	7812270364*	50-369	œ.	NAUGHTON, W. F.	7810120080	50-237	F	NIX.R.T.	7811140162	50-321	8
MURPHY, C. E.	7612290109	50~553	9	NAUGHTON H. F.	7810100025	50-295 50-295	P P	NIX.R. T. NIX.R. T.	7811140211# 7811140204#	30-366 30-356	8
MURPHY.C.E. MURPHY.C.E.	7812180336 <b>*</b> 7812110309*	50~400 50~364	0 Q	NAUGHTON W.F.	7810180060 7810200113	30-275	P	NIX.R. T.	7811210253*	50-366	8
nontrille o. a.	7014110007						_		~~		_
MURPHY, C. E.	7812290045*	50~390	0	NAUGHTON W. F.	7810230194 7810300097	50-295 50-295	P	NIX,R,T. NIX,R.T.	7811210404* 7811210370*	50-366 50-366	S
MURPHY, C. E. MURPHY, G. E.	7812290064* 7812290122*	50~43Ø 50~327	O O	NAUGHTON W. F. NAUGHTON W. F.	7810300047	50-275	P	NIX. R. T.	7811210243*	90-366	8
MURPHY, P. M.	7812050347	50-556	ō	NAUGHTON, W. F.	7811210410	50-295	P	NIX, R. T.	7611220028*	50-321	8
MURPHY, C. E.	7812280070*	50-424	g .	NAUGHTON W. F.	7812070172	50-237	F	NIX. R. T.	7811210366*	50-321	8
MURPHY, C. E.	7812040049	50-390	g	NAUGHTON, W. F.	7812120195	50-237	F	NIX, R. T.	7811280242*	50-321	8
MURPHY, C. E.	7812050111	50-327	ā	NAUGHTON W. F.	7812070211	50-295	P	NIX.R. T.	7812180234*	50-366	9
MURPHY, C. E.	7812060357×	50~389	a	NAUGHTON, H. F.	7812150230	50-454	K	NIX,R.T. NIX,R.T.	7812180167* 7812180183*	50-366 50-366	8
MURPHY, C. E.	7812280306×	50~395 50~364	0	NAVENTI.R. NAVENTI.R.	7810130182 7810260030	50-445	A	NIX.R.T.	7812180169*	50-321	8
MURPHY. C. E.	7812070019	30-364	•	MATERIAL .				4144 6 7	-0131003354	40-744	
MURPHY, C. E.	7812060025	50-398	0	NAVENTI.R.	7810260032+	50-445 50-445	A	NIX.R.T. NIX.R.T.	7812190225* 7812270296*	50-366 50-321	8
MURPHY, C. E.	7812060065	50-327 50-488	0 0	NAVENTIAR.	7812050339 7812110244	50-445	Â	NIX. R. T.	7812270318*	50-021	8
MURPHY, C. E. MURPHY, C. E.	7812200315* 7812210061*	50-413	Q.	NAVENTI.R.	7812080139	30-445	A	NIX.R.T.	7812270329*	50-366 50-366	S
MURPHY, C. E.	7812210324*	50-400	Q	NAYLOR. R.	7812290208*	50-346	8	NIX. R. T.	7812270273*	JO-700	۰
****	98.4815648	50-400	0	NEELY. D. R.	7810250138*	50-286	Q	NIX, R. T.	7812270317*	50-366	8
MURPHY, G. E. MURPHY, G. E.	7812210345* 7812210039*	50-400	Q.	NEIL, R. M.	7811300219	50-338	•	NIX, R. T.	7812270321*	50-366	8
MURPHY, P. H.	7812270255	50-556	ō	NEIBLER, J. H.	7811210013*	50-456 50-440	G Q	NIX,R.T. NOLAN, L.L.	7812270331* 7811280256*	50~3&6 50~263	8
MURPHY, C. E.	7812180333	50-400	0 0	neibler.j. H. Nelbon.p. r.	7812280314* 7810300343*	50-201	ő	NOONAN, V. S.	7811020343*	50-344	G
MURPHY, C. E.	7819270357	50-369	u	MELBOW F. N.					7812200307#	50-280	0
MURPHY, C. E.	7812280088	50-424	a	NELBON, Q. E.	7810190216	50-556 50-70	Q P	NOONAN, V. S. NORDERHAUG, L. R.	7812200307	50-344	0
MURPHY, C. E.	7812290038	50-390	0 0	NELBON, C. C. NELBON, G. E.	7810240206 7810260199	50-336	G .	NORDERHAUG, L. R.	7810190135	50-206	Q
MURPHY, C. E. MURPHY, C. E.	7812290055 7812270272*	50-438 50-31 <i>6</i>	8	NELBON, Q. E.	7811010433	50-356	Q	NORDERHAUG. L. R.	7810200255 7811210244	50-133 50-312	0
MURPHY, C. E.	7812290114	50-327	ă	NELSON, E. S.	7811150150	50-275	Н	NORDERHAUG, L. R.	-		
		60.245	q	NELBON, C. C.	7812180293	50-70	P	NORDERHAUG, L. R.	7812140051	30-394	0
MURRAY, B. MURRAY, T. D.	7811210121# 7810180041	50-313 50-346	9 8	NELBON, C. C.	7812190373	50-309	P	NORDERHAUG.L.R.	7812040202 7812040203	50-312 50-344	G
HURRAY, T. D.	7B10310303	50-346	8	NELBON, J.	7811210379*	50-346 50-309	8 P	NORDERHAUGILIR.	7812270421	50-142	Ğ
HURRAY, T. D.	7810100060	50-346	8	NELBON, C. NELBON, C.	7812180012 7812270489	20-305	P	NORELIUS C. E.	7811300117#	50-255	Q
HURRAY, T. D.	7810120074	50-346	8	MELDONI 4.			^	NOREL TUB, C. E.	7812140263*	50-366	e
MURRAY. B.	7811170119#	50-128	Ω	NEPOM. D. L.	7812040118	50-397 50-548	O A	NOREL TUBIC. E. NORRHOLM L. J.	7811300298*	50-272	o
MURRAY, T. D.	7810130142	50-346	R	NEVILLE.D. C.	7810230267 7810130195	50-466	C	NORRHOLM L. J.	7812270423*	50-272	a
MARRAY, T. D.	7810150124	50-346 50-346	8	Newman, J. R. Newman, J. R.	7810130071	50-466	0	NORRHOLM L. J.	7812280012* 7811010058*	50-272 50-414	A
MURRAY: T. D. HURRAY: T. D.	7810160137 7810230269	50-346	8	NEWMAN, J. R.	7811080054	50-466	a	NORRIE, J. A.	10114160194		
								•			

	NORRIS. J A	7017070177	50-556	 L	D'REILLY, J. P.	3011710004	50-269	 P	OPEKA, J.F.	7812120116
	NORTH. H B.	7812070162+ 7811270107+	50-344	Q	D'REILLY, J. P.	7811210306 7811240021	50-280	P	GPEKA. J.F.	7812150301
	NORTON. B	7810300350 7811010039	50-275 50-275	0	O'REILLY, J. P. O'REILLY, J. P.	7811290406 7811300033	50-261 50-302	P P	OPEKA, J. F. OPEKA, J. F.	7812260213 7812290169
	NORTON, B	7812140085	50-275 50-322	A	D'REILLY, J. P.	7611300035	50-269	p	OPEKA, J. F.	7812290205
	NOVARRO, J. P. NOVARRO, J. P.	7810100017 7810270190	50-322	8	O'RETLLY, J. P. O'RETLLY, J. P.	7811300041 7811300049	50-250 50-259	P P	OPLINGER, O. O.	7811130288 7812040243
	NOVARROUJP. NOVARROUJP. NOVARROUJP.	7810180074 7812070115+ 7812140166	20-355 20-355 20-355	0 8 F	O'REILLY, J. P. O'REILLY, J. P.	7811300057 7811300066	50-280 50-321	P P P	OPLINGER O. O. OPLINGER O. O.	7812040249 7812190072
	NOVARRO J P	7812260196	50-322	A	O'REILLY, J. P. O'REILLY, J. P.	7811300353	50-348	0	OPLINGER O. O.	7812190074
	NOVARRO, J P NOVARRO, J P	7812260211	20-355 20-355	8	D'REILLY, J. P.	7812040306 7812040308	50-302 50-250	0	OPREA, Q.W. OBANN, E.W.	7810120061 7811160050
	NOVARRO, J. P	7812260215	50-322	8	O'REILLY, J. P. O'REILLY, J. P.	7812040310 7812040312	50-321 50-416	0	OST, F. OSTER, J.	7612180210
	NOVARRO, J. P.	7812260221	50-322 50-219	A	O'REILLY, J. P.	7812040314	50-437	G.	OSTRANDER, F. W.	7811080062
	NONICKI.B J.	7811140014 7811140072	50-219	P	O'REILLY, J. P. O'REILLY, J. P.	7812040318 7812040320	50-395 50-280	0	OSTRANDER, F. W.	7811100174 7812110321
	NONICKI.B J	7812080214 7812080239	50-219 50-219	P	O'RETLLY, J. P.	7812040357 7812040359	50-348 50-261	0	OSTRANDER, F. W. OSHALD, P. I.	7811150140 7811060082
	NONICKI B.J	7812270459	50-219	P	O'REILLY, J. P.	7812040363	50-269	Q .	OTTERBERG. J.	7810110103
	NOWICKIPB. J NUTANT, J. A.	7812220108 7812060155	50-219 50-437	P A	O'REILLY, J. P. O'REILLY, J. P.	7812040369 7812050230	50-259 50-413	0	OTTOBON, H. L. OUBRE, R. P.	7812270195 7810310087
	NYOAARD+O.R NYOAARD+O.R	7810110042 7810110288	50-409 50-409	٥	O'REILLY, P. D. O'REILLY, J. P.	7812080218 7812270229	50-572 50-327	A Q	DUZTB, J. E. DUZTB, J. E.	7810110262 7810310134
	MYOAARD.O R	7810200134	30-409	٥	O'RETLLY, J. P.	7612280007	50-413	Q	DUZTB, J.E.	7811130229
	NYGAARD-G.R. NYGAARD-G.R.	781 1200395 781 2040263	50-409 50-409	0	O'REILLY, J. P. O'REILLY, J. P.	7812280014 7812280020	50-259 50-348	0 0	DUZTS, J.E.	7812050057 7812140156
	NYGAARD: O. R NYGAARD: O. R	'812270337 '812270339*	50-409 50-409	0	O'REILLY, J. P. O'REILLY, J. P.	7812280022 7812280024	50-321 50-324	G G	OVERLIDIT. W.	7819200287 7819270245
	NYOUIST. R. O	7811070149	50-329	A	O'RETLLY, J. P.	7812280025	90-305	ā	OWEN, W. H.	7810140063
	O 'CONNOR, P. W O 'CONNOR, P. W.	7810250165 7811150246	50-237 50-237	P P	O'REILLY, J. P. O'REILLY, J. P.	7812280027 7812280030	50-424 50-416	Q Q	OWEN, W. H. OWBLEY, Q. F.	7810140066 7810270108
	0 *DONNELL . E. P. O *DONNELL . E. P	7810170165 7810170168*	50-591 50-591	K K	O'REILLY, J. P. O'REILLY, J. P.	7812290034 7812290040	50-395 50-280	o o	DWBLEY, 9. F.	7811130249
	D*DONNELL+E.P.	7811300203	50-591	К	O'RETLLY, J. P.	7812290081	50-261	ŏ	PADHANABHAN, H. PAGE, B. H	7812270181 7811010220
	O'HARA, J C	7812210066 7810190199	50-245 50-522	P Q	O'REILLY, J. P. O'REILLY, J. P.	7812290087 7812290092	50-250 50-269	Q. Q	PAILY, P.P.	7812010122
	O'LEARY+J.F. O'LEARY+J.F.	7810300362+ 7811200039+	50-201 50-437	Q A	DBERG, C.R. OBERG, C.R.	7811020369* 7811270181*	50-45B 50-482	9	PANZARELLA. J. PAOLINA.R. J.	7811200327 7811170299
	O'LEARY, J. F	7811200053+	50-437	Ä	DBERG, C.R.	7812060112*	50-483	Q Q	PADLING.R. J. PAPALOB.F. A.	7812010111 7811140123
	O'LEARY.J.F.	7811200075* 7811200069*	50-437 50-437	A	DBERG. C. DBL1GADD. A.	7812290253* 7810100004*	50-485 50-409	Q P	PAPPAS. H	7812050240
	O'LEARY, J. F. O'LEARY, J. F.	7811200220+ 7811200348+	50-437 50-437	A	DESTHANN M. J. DESTHANN M. J.	7811300401+	50-263	Q	PAPHORTH L. G. PAPHORTH L. G.	7811130209 7812120132
	O'LEARY.J F	7811200247+	50-437	Ä	CHANTANIM. J.	7811300402+ 7810110196+	50-373 50-83	o o	PARADISO, P. J. PARADISO, J. W.	7811240044 7812270164
	O'LEARY, J. F. O'REELLY, J. P.	7811200285+ 7810230230+	50-437 50-259	A Q	DHANTANIM. J. DLDHAMI W. A.	7812060149 7811270290	50-83	P P	PARCELL	7811030145
	O'REJLLY, J.P. O'REJLLY, J.P.	7810110056 7812050029*	50-259 50-269	9	OLDHAM, N. A. DLDHAM, N. A.	7811270257	50-201 50-201	R	PARCELL PARDUE, L. W.	7812150272 7812130145
	O'REILLY, J. P.	7810230226	50-259	õ	DLMSTEAD, W. J.	7812150036 7810130111	50-201 50-316	R	PARKER, N. O. PARKER, N. O.	7810260106
	O'REILLY, J. P. O'REILLY, J. P.	7810230284 7810230287	50-413 50-269	0	OLMSTEAD, N. J. OLMSTEAD, W. J.	7810130259	50-516	0	PARKER N. O.	7810180076
	O'REILLY, J. P. O'REILLY, J. P.	7810230290 7810230294	50-302 50-416	Q Q	OLMSTEAD, W. J.	7810140027 7812080005	50-329 50-329	9	PARKER, N. O. PARKER, N. O.	7810130056 7810110090
	O'RETLLY, J. P.	7810230297	50-437	q q	DLMSTEAD, W. J. DLMSTEAD, W. J.	7812260298 7812260305+	50-329 50-329	9	PARKER, N. D. PARKER, N. D.	7811030221 7810230158
	O'RETLLY, J. P. O'RETLLY, J. P.	7810230300 7810230303	50-259 50-395	9	DLMSTEAD, W. J.	7812140223	50-329	•	PARKER, H. O.	7810190027
	O'REILLY, J. P.	7810230361 7810230366	50-348 50-261	Q	OLMSTEAD, W. J. OLSHAN, L.	7812280325 7810300061	50-229 50-286	P	PARKER, N. O. PARKER, N. O.	7810200162 7810230038
		7810250004	20-520	9	OLBHAN, L OLBHAN, L	7811010001 7812190182	50-247 50-286	P	PARKER, N. O. PARKER, N. O.	7810110084 7810110145
		7810270018 7810300321	50-321	9	DLBON. R. C.	7811170121	50-317	P	PARKER, N.O.	7810130136
	A. B. B. A.	7810270252	50-250 50-324	9	OLBON, R. C. OLBON, J. F.	7811240214 7812260044	50-317 50-263	P 0	PARKER, H. O. PARKER, H. O.	7810130174
		7811150073 7811150081	30-239 50-413	0	OPEKA, J. F.	7811290292* 7810110125	50-245 50-336	R	PARKER, H. O. PARKER, H. O.	7810160101 7810180126
	O'REILLY, J.P.	7811150085	30-249	Q	OPEKA, J.F.	7810120089	50-245	8	PARKER, N. O.	7811100115
	D'REILLY, J. P.	78111500B7 7811150094	50-241 50-416	0	OPEKA, J. F. OPEKA, J. F.	7810160117 7810160126	50-245 50-336	8 R	PARKER, N. D.	7810230029 7810250200
		7811150098 7811150103	50-302 50-250	Q Q	DPEKA, J.F. DPEKA, J.F.	7810200087 7810230207	50-245 50-245	R	PARKERINO. PARKERINO.	7810310302 781020006
		7811150110	50~280	0	OPEKA, J.F.	7811080143	50-336	9	PARKERIN O.	7810200082
	O'REILLY, J. P.	781 1150114 781 115011B	50-34B 50-321	Q	OPEKA, J. F. OPEKA, J. F.	7811080155 7811140187	50~336 50~245	8	PARKER, N. O. PARKER, N. O.	7810240002 7810310259
		7811150122 7811150125	50-395 50-437	Q	OPEKA, J. P. OPEKA, J. F.	7811140202 7811140167	50-245 50-245	8	PARKER, N. O. PARKER, N. O.	7810310336 7811080211
		7812130300+	50-324		OPEKA, J. F.	7811140089		8	PARKER, H. O.	7811100110
	O'REILLY, J. P.	7811210256 7811210270	50-250 50-302	P	OPEKA. J.F.	7811140110	50-245 50-336	R	PARKER, N. O. PARKER, N. O.	7810270079 7810300377
		7811210273 7811210279	50-261 50-416	P	OPEKA, J.F. OPEKA, J.F.	7811170104 7811210268	50-245 50-336	R B	PARKER, R. PARKER, M. O.	7812130090 7811080107
	D'RETLLY, J. P.	7811210288			DARUA		50-248	8	PARKER, L. O.	7810240147
- 1	D'REILLY, J. P. D'REILLY, J. P.	7811210295 7811210296	50-395	٨	OPEKA, J. F.	7812050153	50-336 50-336	8	PARKER, N. O. PARKER, N. O.	7810250089
- 1	O'REILLY, J. P.	7811210297 7811210298	50-321	P	DPEKA, J. F.	7812080117 7812080126	50-245 50-245	B B	PARKER, L. O. PARKER, L. O.	7810250153 7810310008
		f 5 + 1 x + 4 5 7 4	3U=407	,			50-336	8	PARKER, U. O.	7811010160 7811010162

;

A	ACCESSION	SUBJECT		ACCESSION	SUBJECT		40000010	
PARKER, N. O.	NUMBER	CATEQURY	AUTHOR	NUMBER	CATEOORY	AUTHOR	ACCESSION NUMBER	CATEC
PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O.	7810300182 7811010412 7810270129 7811130354 7812050025»	50-269 P 50-369 P 50-369 P 50-369 Q 50-269 Q	PARR, CL. D. PARR, CL. D. PARR, CL. D. PARR, CL. D. PARR, C. D.	7812130370 7812180240 7812130149 7812190030 7812200107	50-311 A 50-311 A 50-373 A 50-471 I 50-338 P	PFEFFERVORN, W. PFEFFERVORN, L. PFEFFERVORN, W. PFEFFERVORN, W. PFEFFERVORN, W.	7810260063 7811150101 7810300332 7810300336 • 7812040297	50-488 50-488 50-488 50-488 50-488
PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O.	7811010104 7811130374 7811020255 7811070214 7811080137	50-269 P 50-369 Q 50-269 P 50-270 P 50-270 B	PARR, O. D. PARR, O. D. FARR, O. D. FARR, D. D. PATE, R. J.	7612260280 7612270027 7612290269 7612270155 7810210212#	50-404 A 50-311 F 30-387 A 50-508 A 50-361 G	PHELAN, J. F. PHELAN, J. F. PHELAN, J. F. PHILL IPS, H. S. PHILL IPS, D. L.	7810180104+ 7811140169+ 7812130186+ 7810260184+ 7810300177+	50-10 50-10 50-10 50-341 50-296
FARKER, W.O. PARKER, W.O. PARKER, W.O. PARKER, W.O. PARKER, W.O.	7811070110 7811140114 7811150179 7812040328# 7811140065	50-369 F 50-269 P 50-270 P 50-269 G 50-269 P	PATE: R. J. PATON: W. D.	7811270046+ 7812110240+ 7812210380+ 7812280224+ 7811290026	50-361 G 50-361 G 50-706 G 50-361 G 50-556 G	Phillips.O.L Phillips.H.S Phillips.J. Phillips.J.P. Phillips.J.P.	7810300229+ 7810300113+ 7810160155 7810190262+ 7810190267+	50-298 50-341 50-275 50-275 50-275
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7811160079 7811160134 7811160183 7811180378 7818010162	50-269 P 50-269 P 50-369 A 50-269 G 50-369 A	PATON: W. D.	7810300302 7811040054 7811080204 7811150034 7811150264	50-536 Q 50-518 Q 50-518 Q 50-397 H 50-397 H	Phillips, J.P. Phillips, J.P. Phillips, H.B. Phillip., A. Pieck, T.A.	7810190269* 7810270294 7812280244* 7812140263* 7811240220*	50-275 50-275 50-367 50-366 50-304
PARKER, M. O.	7811220185 7811270145 7811270168# 7811270157 7812060320	50-267 8 50-367 K 50-367 K 50-367 A 50-269 G	PATON, W. D. PATON, W. D. PATON, W. D. PATON, W. D. PATON, W. D.	7812040003 7811290305 7812070235 7812070240 78120800154	50-389 G 50-397 G 50-518 G 50-389 G 50-356 G	PIERCE, J. W. PIERCE, A. C. PIGOTT, D. R. PIGOTT, U. R. PILANT, J. H.	7810270197 7811280118 7811080050 7812010142 7810230213*	50-94 50-201 50-361 50-206 50-298
PARKER, U. O. FARKER, U. O. FARKER, U. O. FARKER, U. O. FARKER, U. O.	7811300178 7818130369 7818010244 7818040147 7818040831	50-270 8 50-369 0 50-269 8 50-287 P 50-269 P	PATON, W. D. PATON, W. D. PATON, W. D. PATTERSON, M. PATTON, H. C.	7812180104 7812210239 7812280317 7812210200+ 7811020379	50-397 H 50-397 Q 50-397 Q 50-397 A 50-344 T	PILANT, J. M.	7811080112* 7810170152 7810120037 7811270129* 7811020253	50-298 50-298 50-298 50-298 50-298
PARKER, IL O.	7812070317 7812180131 7812130306 7812140041 7812140053	50-269 0 50-269 p 50-269 0 50-269 0	PAULUB, R. C. PAXTON, H. C.	7810300334 7811100054 7811100050 7811130305 7811100038	50-201 G 50-344 T 50-344 T 50-344 F 50-344 T	PILANT, J. M.	7811140130 7811200115 7812040052* 7812040196 7812040148	50-298 50-298 50-298 50-298 50-298
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7812180188 7812270359* 7812130149 7812130175 7812190153	50-270 8 50-349 G 50-287 8 50-269 P 50-287 8	PAXTON, H. C.	7811100024 7811100111 7811100019 7811130380 7812280003	50-344 T 50-344 T 50-344 T 50-344 T 50-344 T	PILANT, J. H. PILANT, J. H. PITTMAN, J. R. PLANCK, C. PLAGKON, R. E.	7619130166 7819270328 7810100006+ 7811080345 7810230274	50-298 50-298 50-296 50-18 50-516
PARKER, W. O.	7612190127 * 7812210187 7612270211 7612260133 7612270244	50-249 8 50-249 R 50-369 A 50-369 K 50-249 P	Paxton, H. C. Pearbon, Y. R. Pearbon, S. L. Pearbon, S. L. Pederben, D. E.	7812280004 7810170040+ 7810300176+ 7811240126+ 78112401249+	50-344 T 50-305 Q 50-263 B 50-263 B 50-263 B	Plettinger, H. A. Plumlee, K. E. Plumlee, K. Plumlee, K. E. Plumlee, K. E.	7812200175 7812060316* 7811150049* 7811300380* 7812270057*	50-458 50-184 50-220 50-20 50-289
PARKER, M. O. PARKYN, J. D. PARMENTER, F. H. PARR, O. D. PARR, O. D.	7819290209 78121101884 7812190412 78112001834 78101300334	50-287 8 50-409 8 50-498 M 50-437 A 50-341 A	PEDERBEN, D. E. PEERY, W. H. PEERY, W. H. PELLUSCH, J. PELTIER, I. A.	7812260258+ 7810260067+ 7811130419+ 7812280331 7810190099	50-263 8 50-261 Q 50-338 Q 50-466 9 50-358 A	PODHAL+8. E POIRIER+D. A. POLLOCK-8. L. PDOLE+R. D. POOLE+R. D.	7812030336* 7810270137 7811240029 7810180086 7810300130	50-549 50-443 50-363 50-373 50-373
PARR, O. D. PARR, O. D. PARR, O. D. PARR, O. D. PARR, O. D.	7810170134# 7810230178 7810130037 7810110045 7810120002	50-311 A 50-367 A 50-373 A 50-373 A 50-528 A	PELTIER, I. A.	7811020097 7811120360 7812110285 7812140261 7812140082	50-522 A 50-322 A 50-358 A 50-359 A 50-522 A	POOLE, R. D. POOLE, R. D. POPDVICH, M. PORTER, E. O. PORTER, E. D.	7812040190 7812190109 7812270193 7811030092* 7810130113*	50~373 50~10 50~106 50~438 50~375
PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D.	7810120079 7810120110 7810140040 7811020030 7810240175	50~373 A 50~404 A 50~311 K 50~598 A 50~367 A	Peranich M. W. Perdikie. O. C. Perkinsit. J. Perkinsit. J. Perkinsit. J.	7812210401* 7811240208* 7810160121* 7811130319 7811030141	50-482 B 50-295 B 50-220 R 50-220 B 50-220 S	PORTER: W. L. PORTER: M. L. PORTER: M. C. PORTER: M. L. PORTER: M. L.	7810230049 7810200007 7811130120# 7810200076 7810230119	50-48E 50-369 50-43E 50-369 60-413
PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D.	7810250172 7810250201 7810310360 7811010213 7811020272	50-070 E 50-569 A 50-280 M 50-447 A 50-038 M	Perking.t. J. Perking.t. J. Perking.t. J. Perditi.d J. Perrotti.d. J.	7811130400 7811210303* 7812120103* 7812290088* 7810110286*	50-220 8 50-220 R 50-220 R 50-290 Q 50-259 Q	PORTER, W. L. POTTER, W. P. POTTER, R. W. POTTHOFF, F. H. POTTHOFF, F. H.	7812120230 7811130014* 7812010259 7810190215 7811200073	50-486 50-332 50-272 50-466 50-466
PARR, D. D. PARR, D. D. PARR, G. D. PARR, G. D. PARR, G. D.	781 101 0224 781 102 0003 781 107 0362 781 113 0107 781 113 0348	50-502 A 50-502 E 50-397 A 50-483 H 50-346 A	PERROTTI, D. J. PERROTTI, D. J. PERROTTI, D. J. PERROTTI, D. J. PERRY, W. W. PERSON, L. B.	7810250209* 7812070075* 7812050005* 7812060010* 7811170045	50-369 Q 50-261 Q 50-13 Q 50-280 Q 50-201 P	Potthopp, F. H. Potthopp, F. H. Prasaelvicz, J. Pratt, K. Pratt, C. H.	7812050352 7812040362 7810200130 7811020378 7812050350	50-466 50-466 50-341 50-445 50-549
PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D. PARR, C. D.	7811150029 7811200199 7811200358 7811280492 7811300344	50-367 A 50-528 A 50-502 A 50-373 A 50-372 M	Peterbon, g. Peterbon, g. Peterbon, g. Peterbon, g. Peterbon, g. Peterbon, g.	7810110117+ 7810110103# 7810180162* 7810250100# 7811210371*	50-285 E 50-285 S 50-285 S 50-327 A 50-285 B	Pratt.C.M. Pratt.C.M. Prentiss.R.D. Prentiss.R.D. Prevenblik.T.V.	7811280297 7811280302* 7811010436 7812010335* 7812200251*	30-349 30-349 50-366 50-366 50-332
PARRI D. D. PARRI D. D. PARRI D. D. PARRI D. D. FARRI D. D.	7811300352* 7812050048 7812060073 7812110042* 7812110240	50-392 M 50-387 A 50-387 F 50-546 A 50-400 A	Peterbon R. S. Peterbon O. Peterbon O. Peterbon O. Peterbon O. Peterbon G.	7812080202 7812200267 7812200231* 7812270217* 7812270224*	50-544 A 50-285 B 50-285 B 50-285 B 50-285 B	PRIETO R. PRIETTO R. PRIETTO R. PRIETTO R. PRIETTO R.	7811080030* 7811240125 7812190103 7812290138 7812290143*	30-384 50-384 50-384 50-384 50-384
PARR, C. D. PARR, C. D. PARR, D. D. PARR, C. D. PARR, C. D.	7818190171 7818190055 7818110195 7818190007 7818130347	50-400 A 50-311 A 50-338 P 50-438 A 50-311 A	Peterson O. Petitjem, H. R. Petitjem, H. R. Petrick, N. A. Petpermorn, U.	7812270228* 7811210353 7811210418 7812270058 7810300389	50-285 9 50-255 8 50-255 9 50-482 F 50-480 0	Proffit, W. L. Proffit, W. L. Promire W. Priybyb R. Priybyb R.	781\$220\$45 781\$220\$48* 781\$280\$48 7810\$90\$40* 7810\$90\$37*	50-336 50-336 50-501 50-251 50-251

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
PUOH. R. PULLO. R. E PULLO. R. PULS. K PUROOH. P. N.	781:210329 7810270236» 781:2040193» 781:2180323» 781:2130056	50-331 P 50-237 S 50-237 S 50-267 P 50-556 T	REED. C. REED. C. REED. C. REED. C. REED. C.	7812080093 7812040201 7812040208 7812040212 7812070121	50-295 P 50-454 K 50-454 C 50-456 C 50-454 K	REID, R. W. REID, R. W REID, R. W. REID, R. W. REID, R. W.	7811070061 7810300235 7811030076 7811030080* 7811030088*	50-317 P 50-336 P 50-318 P 50-318 P
PURDON, P. N. PURDON, P. N. PURDON, P. N. PURDON, P. N. PURDON, P. N.	7812130060 7812150364 7812200325 7812200320 7812200324	30-336 T 30-336 T 30-336 T 30-336 T	REED, C. REED, C. REED, C. REEVEB, E. A REGAN, W. H.	7812070185 7812080114 7812110109 7812130277 7810250205	50-454 K 50-10 P 50-373 A 50-348 F 50-556 A	REID.R. W REID.R. W REID.R. W REID.R. W REID.R. W	7811070013 7811070055* 7811070057* 7811070060* 7811070071*	50-249 P 50-249 P 50-249 P 50-249 P
PURDOM.P. W PYLE, R. B OUEENER, R. F. GUENNOZ, B. M GUICK, D. R.	7812200321 7812140247 7812010263+ 7811090179+ 7811100030+	50-556 T 50-518 9 50-338 R 50-346 B 50-302 0	REGAN, W. H. REGAN, M. H. REGAN, M. H. REGAN, M. H. REGAN, M. H.	7810120101 7810130009 7810130255 7810130012 7811140023	50-387 A 50-361 A 50-387 A 50-387 A	REID, R. W. Reid, R. W. Reid, R. W. Reid, R. W. Reid, R. W.	7811170324 7811030166 7811080013 7811080018* 7811130330	50-267 P 50-13 P 50-157 P 50-157 P 50-284 P
QUICK, D. R. QUICK, D. R. QUINTENI, T. E QUINTENI, T. E QUIRK, J. F.	7812050076* 7812180317* 7812110097* 7812296097* 7810310187	50-302 0 50-302 0 50-219 8 50-219 5 50-447 A	REQAN, W. H. REQAN, M. H REQAN, M. H REQAN, W. H. REQAN, W. H.	7810160006 7810160009 7810160011 7810160020 7810200128	50-387 A 50-387 A 50-387 A 50-387 A 50-329 A	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812140065 7812140069* 7811140045 7811150247 7811170029	50-97 P 50-97 P 50-317 Q 50-106 H 50-269 P
Guirk. J F Guits. J E Raad. J H Rae. J J Raiche. B J	7812130132 7810310116+ 7811090159+ 7811240199 7810240159	50-447 A 50-338 Q 50-329 A 50-329 A 50-549 A	REGAN, W. H REGAN, W. H REGAN, W. H. REGAN, W. H.	7810240225 7810240230* 7810250131 7810300027 7810310293	30-348 P 50-348 P 50-327 A 50-553 A 50-329 A	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7811200009 7811200394 7811210212 7811210310 7811290315*	50-106 A 50-302 F 50-112 P 50-112 P 50-112 P
RALPH, R. RALPH, R. RALPH, R. RALPH, R. RAMEY, J. T.	7810240121+ 7811070126+ 7812120134+ 7812210252+ 7811200248*	50-249 8 50-249 8 50-249 8 50-249 8 50-437 A	REGAN, W. H. REGAN, M. H REGAN, W. H. REGAN, W. H.	7811100135 7811130328 7811130332* 7811170016 7811130145	30-582 D 30-382 A 30-582 A 30-382 30-472 A	REID.R.W. REID.R.W. REID.R.W. REID.R.W. REID.R.W.	7811200404 7811210002 7811280389 7811280346 7811270118	50-312 P 50-73 P 50-289 P 50-312 P 50-269 P
RAMBEY, O. F. RANDOLPH, J. M.	7812070202 7810180109+ 7810270193+ 7811300185+ 7812120186+	50-284 P 50-315 S 50-315 S 50-316 S 50-316 S	regan, H. H. Regan, H. H. Regan, M. H. Regan, M. H. Regan, H. H.	7811270097 7811300019* 7812110060 7812060381* 7812060376	30-329 A 30-329 A 30-397 30-361 A 30-361 A	RELD, R. W. Reid, R. W. Reid, R. W. Reid, R. W. Reid, R. W.	7811290317 7811290318+ 7811290319+ 7811280450 7811270169	50-309 P 50-309 P 50-309 P 50-336 P 50-70 P
RANDOLPH J. M. RANBONE, N. O RATHBUN, K. J. RAUCOM, T. L RAUSCH, J. K	7812270260+ 7810310098 7811240190 7811060217+ 7811130108+	50-316 8 50-518 A 50-329 A 50-281 8 50-327 Q	regan, M. H. Regan, M. H. Regan, W. H. Regan, W. H. Regan, W. H.	7812070034 7812120093 7812120139• 7812140293 7812140294	50-361 D 50-518 A 50-518 A 50-438 A 50-438 A	RE1D, R. W. RE1D, R. W. RE1D, R. W. RE1D, R. W. RE1D, R. W	7811280092 7612010370 7812010374* 7812010381* 7811280210	50-57 P 50-313 P 50-313 P 50-313 P
RAUSCH, J. K. RAUSCH, J. K. RAUSCH, J. K RAUSCH, J. K RAUSCH, J. K.	7811200188+ 7811240068+ 7812130005+ 7812080052+ 7812180353+	50-518 Q 50-424 Q 50-327 Q 50-518 Q 50-416 Q	regan, H. H. Regan, M. H. Regan, H. H. Regan, H. H. Reid, R. H.	7812140303 7812140296 7812150003 7812210023 7812130368+	50-438 A 50-572 A 50-397 Q 50-361 A 50-344 P	REID, R. H. REID, R. M. REID, R. M. REID, R. M. REID, R. M.	7811280382 7812010344 7812010347* 7812010362* 7812040071	50-302 P 50-312 P 50-312 P 50-312 P 50-149 P
RAUSCH, J. K. RAUSCH, J. K. RAYHOND, H. J. RAYHOND, H. A. RAYHOND, H. A. RAYHOND, H. J.	7812130298+ 7812200318+ 7811130275+ 7810180123 7812060304+	50-491 0 50-488 0 50-334 0 50-133 R 50-244 0	REID, R. W. Reid, R. W. Reid, R. W. Reid, R. W. Reid, R. W.	7812130376+ 7810250211 7810230144 7810230141 7810200017	50-344 P 50-302 P 50-70 A 50-87 F 50-193 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812040074* 7811200350 7812010005 7812010152 7812210453	50-148 P 50-313 P 50-289 Q 50-312 P 50-302 F
RAYMOND, H. J. RAYMOND, H. A. RAYMOND, H. A. READ, J. READ, J. B.	7812270153* 7811150146 7812150310 7811130421 78111220088*	50-334 G 50-133 R 50-133 R 50-549 A 50-549 T	REID, R. W REID, R. W REID, R. W REID, R. W REID, R. W	7810200021# 7810200079 7810200102 7811020084 7811020087#	50-193 P 50-313 F 50-270 P 50-312 P 50-312 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812180045 7812180047* 7812180051* 7812140040 7812180072	50-287 P 50-287 P 50-287 P 50-27 P 50-285 P
REAVES, T. E. REAVIS, J. E. REAVIS, J. REBELOWSKI, T. REBELOWSKI, T.	7812050191 7810200083* 7812210160* 7811080248* 7811300340*	50-416 A 50-269 R 50-269 R 50-286 Q 50-247 G	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7811020098* 7810230271 7810230273* 7810230281* 7811020014	50-312 P 50-313 P 50-313 P 50-313 P 50-267 E	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812180075* 7812180083* 7812140095 7812140098* 7812140379	50-285 F 50-285 F 50-20 F 50-20 F 50-317 F
REBELONDAI, T. REDEWER.S. J. REED. C. REED. C. REED. C.	7812010062+ 7810180035+ 7810190136+ 7810110277 7810120036	50-286 Q 50-133 8 50-286 P 50-10 Q 50-295 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7810230147 7810230163 7810310297 7810240006 7811030079	50-99 F 50-2 F 50-112 P 50-72 P 50-317 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812180076 7812180079* 7812150070 7812150076 7812150078	50-182 P 50-235 P 50-235 P 50-302 P
REED. C. REED. C. REED. M. REED. C.	7811010009 7810250102 7810230181 7811240224• 7810270180	50-10 Q 50-295 P 50-373 A 50-265 B 50-237 P	REID.R.W. REID.R.W. REID.R.W. REID.R.W. REID.R.W.	7811080036 7811080038* 7811020140 7811020146* 7811020272	50-284 P 50-284 P 50-2 P 50-2 P 50-59 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812150079 7812150083 7812150084 7812150087 7812150071	50-317 F 50-269 F 50-313 F 50-289 7 50-336 F
REED. A. REED. C. REED. C. REED. C.	7810270283* 7811020322 7811030161 7811020258 7811070168	50-267 8 50-10 P 50-10 P 50-373 K 50-295 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7811020274* 7811020277* 7811030222 7611030224 7811030226*	50-59 P 50-59 50-59 F 50-113 P 50-113 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812130098 7812130100 7812130102 7812180060 7812180064*	50-309 F 50-346 F 50-312 F 50-13 F 50-13 F
REED. C. REED. H. REED. C. REED. C.	7812050059 7811210314 78121101834 7811270091 7811270170	30-456 G 30-454 A 30-254 B 50-295 P 50-254 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7811070376 7811010233 7811060013 7811060015# 7811020228	50-83 F 50-317 P 50-2 P 50-2 F 50-289 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812140383 7812180376 7812180380+ 7812180390+ 7812260288	50-309 50-265 50-265 50-265 50-265
REED, C. REED, C. REED, C. REED, C. REED, C.	7811290213 7812060020 7811280278 7812130126 7811280264	50-10 P 50-254 D 50-275 P 50-456 Q 50-373 X	REID, R. W. Reid, R. W. Reid, R. W. Reid, R. W. Reid, R. W.	7811030063 7810240021 7811010363 7811030009 7811030014	50-62 P 50-97 F 50-313 P 50-224 P 50-27 F	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812150082* 7812150107 7812150114* 7812150119* 7812180303	20-119 20-582 20-582 20-582

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REID, R. W REID, R. W REID, R. W REID, R. W REID, R. W	7812180371 7812180371 7812210391 7812260295* 7812260396*	50-131 P 50-289 P 50-312 P 50-245 P 50-245 P	RHODE, O. K. RHODE, O. K. RHODE, O. K. RHODE, O. K. RICE, R. M	7812070192 7812070219 7812280196 7812200202 7810250100*	50-410 8 50-410 A 50-410 0 50-410 A 50-329 A	ROISMAN.A 2 ROISMAN.A Z ROISMAN.A Z ROISMAN.A Z ROISMAN.A Z	7812270036 7812110070 7812110074* 7812280271 7812280280*	50-437 50-437 50-437 50-237 50-237
REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812260062 7812270116 7812270401 7812270409* 7812280238	50-269 P 50-312 F 50-73 P 50-73 P 50-269 P	RICE, L. RICHARDS, W. RICHARDS, B. R. RICHARDSON, C. K. RICHARDS, B.	7812080024 7811020278* 7810270097* 7812110164* 7812140153	50-275 Q 50-59 P 50-219 R 50-295 B 50-252 J	ROKASY, J S. ROKASY, J S. ROMNEY, K, H ROMNEY, K, M. ROMNEY, K, M.	7811080045 7811130344# 7810310105# 7810310216# 7811170171#	50-580 50-580 50-317 50-318 50-318
REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812280247* 7812280297 7812290007 7812290008* 7812290188	50-269 P 50-70 P 50-62 P 50-62 P 50-346 P	RIDEN, M. D. RIDEN, M. D. RIDGWAY, K. R. RIDGWAY, K. R. RIEDLINGER, B. A.	7811080074+ 7812210054+ 7811300141+ 7812060077+ 7812140072+	50-295	ROMNEY, X. ROMNEY, K. H RONE, A. H ROOD, H ROOD, H.	7811170187 * 7811290267 * 7812200240 * 7811200063 * 7811200396 *	50-318 50-317 50-219 50-437 50-437
REINERT.S. REINERT.S. REINERT.S. REINMUTH.Q.W. REIS.E.J.	7811010267 7810300055 7811210467 7810130167* 7811270264	50-443	RILEY, B. W. RILEY, B. W. RILEY, J. RINGLE, J. C. RIBCHLING, J.	7810110302* 7811280012* 7811080040 78122701974 7810180018*	50-324	ROOD, H. ROOD, H. ROOD, H. ROOD, H ROOD, H	7811200360 + 7811200343 + 7811200359 + 7811200361 7811280001	50-437 50-437 50-437 50-361 50-361
REIB, E. J. REIB, E. J. REIB, E. J. REIB, E. J. REIB, E. J.	7811290345 7812120228 7812040005 7812140365 7812150340	30-400 P 50-409 P 50-485 P 50-566 P 50-400 P	rischling, J. Rischling, J. L. Rischling, J. Rischling, J. L. Rischling, J.	7810180005* 7810180030* 7810310195* 7810310199* 7811090153*	50-316 8 50-316 8 50-316 8 50-316 8 50-316 8	ROOD, H ROOD, H. ROONEY, V. L. ROONEY, V. L. ROBA, F.	7812050367 7812180450 7811280439 7812070314 7812040327+	50-341 50-341 50-133 50-133 50-275
REIB, E. J. REIB, E. J. REIBB, J. REIBB, J.	7812150344* 7812270424 7812280278 7810170222* 7810170242*	50-400 0 50-247 0 50-400 0 50-304 8 50-304 8	Ribchling, J. Ribchling, J. Ribchling, J. L. Ribchling, J. L. Bibchling, J. L.	7811090158+ 7811140218+ 7812080070+ 7812180212+ 7812270255+	50-316 8 50-316 8 50-316 8 50-316 8 50-316 8	ROSE, D. O ROSE, D. O ROSE, D. O. ROSENBERG, A. B. ROSENBERG, A. S	7811170297 7811220012 7812140105 7810230015* 7811060105*	50-266 50-358 50-322 50-445 50-382
REIBB. J. F. REMICK. F. J. REMICK. F. J. REMICK. F. J. RENAUD, J.	7812210239* 7811080219 7812040047 7812040045 7810250006	50-275 8 50-318 G 50-275 T 50-275 T 50-466 G	Ribchling, J, L Ribley, J Ribtgvich, B, Ritbher, J, A. Ritbher, J, A.	7812270264* 7810160146* 7810190267* 7811010244 7811080195	50-316 8 50-409 P 50-279 Q 50-443 Q 50-568 Q	ROSENBERO. A. B ROSENTHAL. J E ROSENBERO. A. B ROSENBERO. A. B. ROSENBERO. H.	7611200218+ 7610310016 7812060342+ 7812210179+ 7812110219	50-498 50-266 50-445 50-445 50-275
RENBERGER, D. L.	7811070147* 7810110206* 7811010119 7811020245 7811020247*	50-397 G 50-460 G 50-397 A 50-460 I 50-460 I	RITHHER.J.A. RITHHER.J.A. RITHS.F.H. ROBERGE,J.C. ROBERTHON.R.C	7810310185 7811070138 7812140244 7811090149+ 7811270054+	50-443 A 50-443 I 50-445 M 50-329 A 50-488 A	ROSENTHAL, A B. RDBOLLE.E. ROSS, D. A ROSS, D. A ROSS, D. A	7812130053 7811020037 7810100070 7810100075* 7811080258*	50-554 50-344 50-219 50-219 50-219
RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L. RENBERGER, D. L.	7811070269 7811220177* 7811260265 7812070209 7812130110	50-397 C 50-397 8 50-397 A 50-397 8 50-397 C	ROBERTS,M. ROBERTS,C.P. ROBINSON J.X. ROBINSON J.X. RODOER,M.A.	7812270335 7812210374 7811300100 7812060216 7812050354#	50-295 0 50-395 M 50-338 A 50-338 H 50-549 T	R088, D. A. R088, D. A. R088, D. A. R088, D. A. R088, D. A.	7810120071 7810120076* 7811080234* 7810180006 7810180007*	50-219 50-219 50-219 50-219 50-219
RENBEROER, D. L. RENBEROER, D. L. RENBEROER, D. L. RENBEROER, D. L. RENBEROER, D. L.	7812130180 7812210161* 7812290149 7812270183 7812280144	50-397 R 50-460 Q 50-50R A 50-397 A 50-397 C	RODI, J. P. RODRIGUEZ, R. J. RODRIGUEZ, R. J. RODRIGUEZ, R. J. ROE, L. E.	7810190156 7810110124 7811160076 7818200196 7810270171	50-393 A 50-312 R 50-312 R 50-312 R 50-346 P	Rober D. A Rober D. A Rober D. A Rober D. A Rober D. A	7810230259 7810240105 7810240107* 7812070288* 7812010131*	50-219 50-219 50-219 50-219 50-219
Rentfro.H.E. Rescex.f. Resnikdff.M. Reuter.f. Reuter.A.L.	7810110238* 7819110182* 7819270009* 7819010249* 7819130199	50-466 0 50-295 8 50-220 P 50-447 A 50-549 0	ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E.	7810270177 7811010066 7811010129 7811060118 7811170100	50-344 P 50-500 A 50-500 I 50-346 P 50-346 F	ROSS. D. A. ROSS. D. A. ROSS. D. A. ROSS. D. A. ROSS. D. A.	7811210239 7811200204 7811200207 * 7811210321 7811210324 *	50-219 50-219 50-219 50-219 50-219
REUTER, D.A. REUTTER, J. M. REUTTER, J. H. REUTTER, J. M. REVELEY, N. T.	7811210187 7811200095* 7811200098* 7811200100* 7810240038	50-368 R 50-346 R 50-346 R 50-346 R 50-516 0	roe. L. e. roe. L. e. roe. L. e. roe. L. e.	7811200178 7811220174 7811220158 7812040228 7812050143	50-346 F 50-346 F 50-500 E 50-346 F 50-346 P	R088. D. A R088. D. A R088. D. A R088. D. A R088. W. J.	7811280193 7811280196# 7812070220# 7812070218 7812130323	50-219 50-219 50-219 50-219 50-302
REVELEY, W. T. REVELEY, W. T. REYES, L. A. REYES, L. A. REYES, L. A.	7811200307 7811290087 7811010029* 7811090189* 7812010129*	50-516 0 50-516 0 50-10 0 50-315 0 50-255 0	ROE.L. E. ROE.L. E. ROE.L. E. ROE.L. E. ROE.L. E.	7812190081 7812180206 7812180134 7812200166 7812270256	50-346 P 50-346 F 50-346 P 50-500 A 50-346 F	RDSS, W. W. RDSS, D. A. RDSS, D. A. RDSS, D. A. RDSS, D. A.	7812180246 7812190107# 7812200190 7812270314 7812270323#	50-327 50-217 50-217 50-217 50-217
REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, N. B. REYNOLDS, H. S. REYNOLDS, H. S.	7810110064 7810110279 7810200001 7810200177 7810200182*	50-397 Q 50-445 Q 50-397 Q 50-483 Q 50-483 Q	ROGERB. R. F. ROGERB. K. ROGERB. V. C. ROGERB. V. C. ROGERB. R.	7811010428* 7810170187* 7811080245* 7810170056 7810110092*	50-295 B 50-271 G 50-201 P	ROSS, D. A ROSS, D. A ROSZTOCZY, Z R. ROSZTOCZY, Z R. ROSZTOCZY, Z R.	7812270213 7812270217+ 7810300174+ 7810300167 7812310022	50~219 50-219 50-277 50-277 50-330
REYNOLDS, W. S. REYNOLDS, W. S. REYNOLDS, W. B. REYNOLDS, W. S. REYNOLDS, W. S.	7810240227 7811010285 7811070137 7811130071 7811130144	50-483	ROGERB. C. L. ROGERB. G. L. ROGERB. M. H. ROGERB. C. L. ROGERB. C.	7810170234* 7811240213* 7810230176* 7811240147* 7811240229*	50-295 B 50-321 B 50-304 B	ROTH, J. M. ROTH, A. J. ROTTAN, J. J. ROHE, J. K. ROHLAND, F. S	7810190248 7811030245 7812010036* 7812040311 7812060145	50-87 50-592 50-333 50-295 50-326
REYNOLDS H. B. REYNOLDS H. B. REYNOLDS H. B. REYNOLDS H. B. REYNOLDS H. B.	7811130230* 7811130230* 7811130230* 78111270048 7811270050*	0-346 M 50-346 M 60-346 H 50-483 0	ROGERS, R. F. ROGERS, C. L. ROGERS, M. H. ROGERS, R. F. ROHNER, M. M.	78120403504 78121101294 78112802244 78122802944 78122100744	50-295 8 50-366 8 50-321 0	RUETER, D. A. RUGTER, D. A. RUFF, A. RUFF, E. J. RUHLMAN, W. A.	7811220134 7812180163 7812060274# 7812150226 7811080097*	50-368 50-368 50-327 50-413 50-286
REYNOLDS. M. S. REYNOLDS. N. S. REYNOLDS. N. S. REYNOLDS. M. S. REYNOLDS. M. S. RHYNOLDS. J. G.	7812110254 7811300008 7812270141 7812130057 7810300167*	50-483 9 50-445 M 50-397 9 50-483 9	RDIBMAN, A. I. RDIBMAN, A. I. RDIBMAN, A. I. RDIBMAN, A. I. RDIBMAN, A. I.	7810120088 7810300063 7810300268 7811150223 7811150227	50-349 50-237 0 50-437 0 50-237 0 50-437 0	RUHLMAN, W. RUITER, O. H. RUITER, O. H. RUITER, O. H. RUITER, O. H.	7812010103+ 7810100042+ 7810230251+ 7810240138+ 7811220177+	50 - 30 9 50 - 30 5 50 - 30 5 50 - 30 5 50 - 30 5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEGOR		AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
RUITER.O H RUITER.O H RUSSELL.T W	7811280309# 7811280310# 7810230145	50-305 B 50-305 B 50-98 P	SCHNE I DER. R. R. SCHNE I DER. R. R. SCHNE I DER. R. R.	7811150041* 7811150188* 7810300146	50-220 50-220 50-220	G G P	BCHWENCER. A BCHWENCER. A BCHWENCER. A	7811150249 7811170141 7811170143*	50-247 F 50-344 P 50-344 P 50-247 P
RUSSELL.L. 8 RUSSELL.L 8	7811170165 7811170179	50-318 8 50-318 8	SCHNEIDER, R. R SCHNEIDER, R. R	7811090155 7811090206	50-220 50-220	8	SCHWENCER. A SCHWENCER. A	7811150171 7811170082	50-280 P
RUSSELL.L. B RUSSELL.L B RUSSELL.L B	7811210407 7811300196 7811290264	50-317 8 50-317 8 50-317 8	SCHNETDER, R. R. SCHNETDER, R. R. SCHNETDER, R. R.	7811090271 7811210302 7811210281	50-220 50-220 50-220	8 R 8	BCHWENCER. A BCHWENCER. A BCHWENCER. A.	7811210200 7811210205* 7811210213*	30-286 P 30-286 P
RUSSELL.L B RUSSELL.H K	7811300211 7812270025	50-318 8 50-275 0	SCHNE 10ER R R	7812120102 7812140149	50-220 50-220	8 8	BCHWENCER A. BCHWENCER A.	7811290152 7811290166*	50-280 P
RUSSELLIL B	7812130170 7812130183 7812130189	50-318 8 50-318 8 50-317 8	SCHOCK, D. SCHOCK, O SCHOPPHAN, M. A	7811010132 7812010204 7810100102*	50-568 50-368 50-335	A A B	BCHWENCER, A. BCHWENCER, A. BCHWENCER, A.	7811290168* 7811290175* 7811280344	50-280 P 50-280 P 50-315 P
RUSSELLIL B RUSSELLIL B RYANIL J	7812250244 7811070355+	50-317 B 50-318 S 50-70 P	SCHOPPMAN, M A SCHOPPMAN, M A	7810100092+ 7810100093+	50-335 50-335	8	SCHWENCER. A SCHWENCER. A.	7811270018 7811270019#	50-315 P 50-315 P
RYAN, L. J. RYAN, J. D.	7810300272 7811070283	50-556 0 50-341 0	SCHOPPHAN, H A	7810120052* 7810120051*	50-251 50-335	8 8	SCHWENCER, A.	7811270020* 7811270021*	50-315 P 50-315 P 50-315 P
RYAN, T. O. BACK, E. J BAHM, J. H	7812280338 7812270060 7810300166•	50-445 M 50-247 Q 50-267 B	SCHOPPHANIM A. SCHOPPHANIM A SCHOPPHANIM A	7811080150+ 7810170245+ 7810200096+	50-251 50-235 50-251	8 8	SCHWENCER, A. SCHWENCER, A. SCHWENCER, A	7811270023* 7811280170 7811280172*	50-315 P 50-250 P 50-250 F
SALTZMAN J. SALTZMAN J.	7809150539+ 7810110146+	50-13 J 50-331 J	SCHOPPMAN M. A SCHOPPMAN M. A	7810200117¢ 7810230169*	50-251 50-335	5 8	SCHWENCER, A. SCHWENCER, A	7811280174* 7811280178*	50-250 F 50-250 F
SALTZMAN: J SALTZMAN: J. BALTZMAN: J.	7810110101+ 7811210173+ 7810180140+	50-264 J 50-358 J 50-338 J	SCHOPPHANIM A. SCHOPPHANIM A SCHOPPHANIM A	7811040148+ 7811040152+	50-250 50-250	8 8	SCHWENCER, A. BCHWENCER, A. BCHWENCER, A.	7811290069 7811220113 7811220118*	50-250 P 50-348 P 50-348 P
SALTIMAN J SALTIMAN J	7811300218+ 7811280274+	50-433 J 50-272 J	SCHOPPMAN, N. A.	7811060163+ 7811080217+	50-251 50-335	8	SCHWENCER. A SCHWENCER. A.	7811220125* 7811220239	50-348 P 50-334 P
SALTZMAN J BALTZMAN J BAMMONS R P.	7812130008* 7812140157*	50-133 J 50-232 J 50-315 8	SCHOPPMAN, M. A. SCHOPPMAN, M. A. SCHOPPMAN, M. A.	7811220203+ 7811300190+ 7812040222+	50-250 50-335 50-251	8 8 8	SCHWENCER. A. SCHWENCER. A BCHWENCER. A	7811270136 7611280403	30-261 F 50-282 P 50-282 P
SANDERS. W.	7812130112*	50-352 0	SCHOPPMAN, M. A.	7812040189+	50-250	8	SCHWENCER, A	7811290010 7811270059	50-348 P
BANDERS W F.	7812060346* 7812180082*	50-271 0 50-20 0	SCHOPPHANIM A.	7812050133+ 78120501B1+	50-335 50-251	8 8 8	BCHWENCER, A. BCHWENCER, A.	7811270061* 7811270066*	50-348 P
SANDVIKAR M. SANOVIKAR. H	7810270354+ 7810300162	50-344 0 50-514 0	SCHOPPHANIM A. SCHOPPHANIM A	7812050198• 7812270312•	50-335 50-251	8	SCHWENCER A. SCHWENCER A.	7811280385 7811280079	50-334 P 50-305 P
GANDVIK-R, M SANDVIK-R, M	7811080062 7812110321	50-344 0 50-344 0	SCHR1EBER D.L. BCHULMAN J.M.	7810230156 7812150279	50-327 50-346	A M	BCHWENCER, A. SCHWENCER, A.	7811280359 7811300022	50-305 P 50-272 F
BANGER. H. S SAUBER. J	7810240037 .7810240077*	50-566 G 50-269 R	BCHUMACHER, K. B BCHUMACHER, K. B	7811270166 7812130387	50-317 50-344	P	SCHWENCER, A. SCHWENCER, A	7812040224	50-272 F 50-282 F
SCHACKLEFORG, B.	78112201824	30-275 A	BCHUNACHER M. C.	7810260183#	30-133	a	SCHWENCER A.	7811290365 7812140062	50-262 P
SCHAEFER, W. SCHAEFER, W.	7811200275 7812180267	50-266 0 50-305 0	SCHUMACHER M.C. SCHWARZ M.D.	7811140189+ 7812040367	50-315 50-498	0	SCHWENCER, A.	7812080148 7812110085	50-250 F 50-344 P
SCHEID.K	7812200127 7811130202	50-546 8 50-295 0	SCHWAN, C. A. SCHWENCER, A.	7812140086+ 7812150069	50-10 50-70	0 P	SCHWENCER, A SCHWENCER, A	7812140332 7812140351	50-272 P
BCHERER, A. E.	7810300244	50-470 K	BCHWENCER, A.	7812180411	50-70	P	ECHWENCER, A.	7812140357	50-250 P
SCHERERIA E.	7811300213* 7811160077	50-361 Q 50-470 A	BCHWENCER. A.	7809270023 7812010382	50-70 50-250	P P	SCHWENCER.A. SCHWENCER.A.	7812140364 7812150006	50~348 ₽ 50~305 ₽
SCHERERIA E	7811290143 7812120074	50-470 A 50-470 K	SCHWENCER, A SCHWENCER, A	7810250175 7811130175+	50-250 50-250	P P	SCHWENCER.A SCHWENCER.A	781215000B 781215001B	50-266 P 50-344 P
SCHERER A. E	7812270163	50-470 K	SCHWENCER, A	7811210191	50-250	P	SCHWENCER, A	7812150026	50-3 P
SCHINK, D, R SCHHIOT, A. D	7812290281 7810100091	50-341 T 50-335 B	BCHWENCER A BCHWENCER A	7810110041 7810110044+	50-281 50-281	P P	BCHWENCER A. BCHWENCER A.	7812150059 7812150061	50-280 P
SCHMIOT.A.D. SCHMIOT.A.D.	7810100094+ 78101000974	50-335 B 50-335 B	SCHWENCER, A. SCHWENCER, A	7810120098 7810250016	50-266 50-266	P P	SCHWENCER, A. SCHWENCER, A	7812150064 7812150066	30-261 P 30-334 P
SCHMIDT, A. D SCHMIDT, A. D	7810120050 7810120049	50-251 8 50-335 8	SCHWENCER, A	7810130110 7810310233	50-305	F	SCHWENCER. A.	7812180113	50-318 F
SCHMIDT.A.D BCHMIDT.A.D.	7810120054	50-335 9	SCHWENCER, A SCHWENCER, A	7810310237+	50-261 50-261	P	ECHWENCER, A BCHWENCER, A	7812180116 7812180234	50-275 P
SCHMIDT.A.D	7810170243 7810200093	50-335 B 50-251 B	BCHWENCER A. BCHWENCER A	7810310244+ 7810200194	50-261	P P	SCHWENCER, A. SCHWENCER, A.	7812180239 <b>*</b> 7812180240*	50-295 P 50-295 P
SCHMIDT.A.D.	7810200114 7810230166	50-251 B 50-235 B	BCHWENCER A. SCHWENCER A.	7810200199+	50-261	P	BCHWENCER, A.	7812180242*	50~295 F
SCHMIDTA D. BCHMITTAR P	7810230250 7810310170*	50-251 8	SCHWENCER. A.	7610200201• 7610190101	50-241 50-266	P	SCHWENCER, A SCHWENCER, A	7812180244* 7812080188	50-295 P 50-305 P
BCHMI OT. A. O.	7811060142	50-230 8	BCHWENCER, A. BCHWENCER, A.	7810250215 7810300325	50-280 50-250	P P	schwencer. A Schwencer. A	7812110010 7812120227	50~250 F 50-334 F
SCHMIDT, A. D SCHMIDT, A. D	7B11060144	50-250 B	SCHMENCER, A.	7811140030	50-250	P	SCHWENCER, A.	7812120059	50-280 F
SCHMIDT.T.H. SCHMIDT.A.O	7811060157 7812010079	50-251 B 50-305 e	SCHWENCER. A SCHWENCER. A	7811140033* 7811140039*	50-250 50-250	P P	SCHWENCER. A. SCHWENCER. A.	7812130101 7812130363	50-266 0 50-344 F
SCHHIOT.A.D	7811080148 7811080208	50-251 B 50-335 B	BCHWENCER A. BCHWENCER A	7810310299 7810310304•	50-247 50-247	P P	SCHWENCER, A. SCHWENCER, A.	78122J0320 7812130215	50-266 F
BCHMIDT.A.D.	7811220201 7811300184	50-250 g	BCHWENCER.A. BCHWEIBINZ.E.R.	7811130175+	50-247	P	SCHWENCER, A.	7812270486	50-286 P
SCHMIDT.A.D.	7812040221 7812040187	50-251 8 50-250 8	SCHWENCER, A. SCHWENCER, A.	7811270181 • 7810270380	50-482 50-260	Q P	BCHWENCER, A. BCHWENCER, A.	7812280011 7812280015*	50-305 F 50-305 F
SCHMIDT, A. D. SCHMIDT, A. D.	7812050131 7812050176	50-233 8 50-251 8	SCHWENCER. A. SCHWENCER. A. SCHWENCER. A	7811030203 7811090015	50-250 50-250	ያ P P	SCHWENCER, A. SCHWENCER, A.	7812280018* 7812280284	50-305 F 50-280 E
SCHMIDT.A. O.	7812050175	50-335 B	BCHWENCER, A.	7811090016* 7811090021*	50-250 50-250	P	SCIBINICO, M. J.	7812260286	50-450 6
SCHMIDTAH, C. SCHMIDTAA, O.	7812190070 7812270307	50-445 K 50-251 B	SCHWENCER, A SCHWEIBINZ, E. R	7811070021* 7811130073 7812190135*	50-250 50-483	P G	BCINTO, J. F. BCINTO, J. F.	7810240209 7811290007	50-516 <b>6</b> 50-488 <b>6</b>
SCHNETDER, F. W.	78112003524 7811130233	50-437 A 50-311 A	SCHWENCER. A SCHWENCER. A	78121401354 7811060060 7812140180	50-483 50-280 50-280	P E	SCINTO, J. F. SCOTT, J. S. SCOTT, J.	7812270114 7810110241* 7810160134*	50-320 50-466 50-466
SCHNETDER, R. R. SCHNETDER, R. R.	7810260022* 7810100054	50-220 8	BCHHETBINZ, E. R.	78120601124	50-483	Q.	SCOTT, D. M.	7810240145	50-271 1
SCHNEIDER, M. F. SCHNEIDER, H. L.	7811120119* 7810180049*	30-272 a	BCHWENCER, A. BCHWENCER, A.	7811170254 7811170259*	20-585 20-585	P P	SCOTT, J. SCOTT, J.	7811140194 7811210038	50-466 50-466
SCHNE I DER. R. R.	7810160119	20-550 8 20-532 8	Schwencer, A. Schwencer, A.	7811170265+ 7811170268+	50-282 50-282	5 b	BCOTT, J. BCOTT, J.	7812040302* 7812040301	50-466 50-466

Page	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR	ACCESS I DN NURSER	T DELEUB
ECOLOR   1.	Beed, H. B. Beegert, G. L. Beelinger, J. L.	7810110143 781206086 7811200092* 7811070247	50-331 J 50-206 D 50-346 R 50-320 8	SHAFER, W. D. SHAFER, W. D. SHAH, M. R.	7811210220+ 7812120226+ 7810200075+	50-331 50-331 50-250	Q O P	SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N.	7810170149* 7810200070* 7811060149* 7811060151*	50-313 50-313 50-368 50-368 50-368
## STATE OF THE PROPERTY OF TH	BEIDLE: N. C. BEIDLE: N. C. BEIDLE: N. C.	7812180142 7010250007 7810240233 7811020048	50-213 J 50-445 G 50-498 G 50-445 G	EHALLERID. V. EHALLERID. V. EHALLERID. V.	7810180106 7810100044 7810100024	50-315 50-316 50-315	8 8 9	SHIVELY.C.N SHIVELY.C.N. SHIVELY.C.N	7811060180* 7811060183* 7811060189*	50-368 50-313 50-313 50-313 50-313
## STATE OF THE PROPERTY OF TH	SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C.	7811030035 7810110267 7811060098	50-466 0 50-458 0 50-382 0	SHALLERID V SHALLERID V SHALLERID V	7810110188 7810188002 7810200053	50-316 50-316 50-31 <i>6</i>	5 9 R	SHIVELY.C N SHIVELY.C N SHIVELY.C.N	7811200180* 7811280211* 7811270142*	50-348 50-313 50-348 50-348 50-348
BEDLE, M. C. 7931270039 20-45 0 BMALED. DV 791107029 30-15 0 BMIVELV.C N 7912700394 30-16 BMIVELV.C N 7	BEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C.	7811070305 7810250027 7811200216	50-445 G 50-462 G 50-498 G	SHALLER, D. V SHALLER, D. V SHALLER, D. V	7810230198 7810270191 7810270309	50-315 50-315 50-316	8 8	SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N	7811270149+ 7812120142+ 7812190152+	50-368 50-368 50-313 50-368 50-368
BEJOLE, M. C. 79110003039 30-490 0 SMALER, D. V. 7911100210 30-310 8 SMOR, P. J. 7910200107 30-318 ELEMENT P. J. 7910200207 30-328 ELEMENT P. J. 7910200207 30	SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C.	7811270039 7811280050 7811170168	50-445 Q 50-556 Q 50-556 Q	SHALLERID V SHALLERID V SHALLERID V	7811020252 7811090151 7811140154	50-315 50-316 50-315	ន ៩ 5	BHIVELY, C. N SHIVELY, C. N SHIVELY, C. N.	7812270249* 7812270304* 7812270310*	50-368 50-313 50-368 50-368 50-266
BEIDLE, M. C. 7811170087 50-302 0 SMALER, D. V. 7811200177 50-316 8 SHOW, F. J. 7812100203 30-32 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812100203 30-32 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812100203 50-32 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107016 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812200000 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107017 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 7812107017 50-313 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 781220019 50-310 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 781220019 50-315 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 781220019 50-315 P SHOW, F. J. 7812200202 50-35 0 SMALER, D. V. 781220019 50-315 P SHOW, F. J. 781220019 50-315 P SHOW, F.	BEIDLE, W.C. BEIDLE, W.C.	7812060338 7811030244 7811070254	50-445 G 50-445 Q	SHALLERID V SHALLERID V. SHALLERID.V.	7811140210 7811170204 7811210383	50-316 50-315 50-315	8 F R	SHON, P. J SHON, F. J SHON, P. J	7810160221 7810230109 7811170003	50-344 50-344 50-344 50-356 50-356
BETILE, H. C. 781200122 50-499 0 BINLLER, D. V. 781200073 50-316 BINN, F. J. 7812200231 50-35 BINN, F. J. 7812200231 50-35 BINN, F. J. 7812200231 50-35 BINN, F. J. 7812200231 50-36 BINN, F. J. 7812200321 50-36 BINN, F.	SEIDLE, M.C. SEIDLE, M.C.	7811170087 7811170085 7811170247	50-466 G 50-382 G 50-482 G	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V	7811300177 7812010210 7812070216	50-316 50-316 50-315	8 9 P	SHON, F. J SHON, F. J SHON, F. J	7812130040 7812150364 7612200325	50-556 50-556 50-556 50-556 50-556
BENLER.B. N	BEIDLE, H.C. Beidle, H.C. Beidle, H.C.	7812040122 7811300105 7812110220	50-498 @ 50-445 @ 50-382 @	SHALLERID. V. SHALLERID V SHALLERID V	7812080075 7812080086 7812110137	50-315 50-316 50-315	8 B R	SHON, F. J SHON, F. J SHORB, E.M.	7812200321 7812290281 7812050184	50-396 50-356 50-341 50-367 50-367
SERABIAN J. A	BEKULER, B. N BEKULER, B. N. BEKULER, B. N.	7811240022 7812050047 7812050051*	50-295 0 50-295 0 50-295 0	SHALLERID V SHALLERID V SHALLERID V	7812120178 7812180207 7812200173	50-316 50-316 50-315	8 9 R	BHORT, T.E. SHORT, T.E. SHORT, T.E.	7810110189 7810130151 7810130125	50-285 50-285 50-285 50-285 50-285
SEYFRIT.K.V. 781010011 30-299 0 SHAPAR.H.K. 781100008° 30-477 A SHORT.T.E. 7812060048° 30-88 SEYFRIT.K.V. 781010011 30-299 0 SHAPAR.H.K. 781010009° 30-471 A SHORT.T.E. 7811070180 30-88 SEYFRIT.K.V. 7810200218 50-482 0 SHAPAR.H.K. 7810200231 30-352 0 SHORT.T.E. 781140197 30-38 SEYFRIT.K.V. 7810200220 50-482 0 SHAPAR.H.K. 7810200231 30-352 0 SHORT.T.E. 781140197 30-38 SEYFRIT.K.V. 7810200220 30-445 0 SHAPAR.H.K. 78110100000 30-349 H SHORT.T.E. 7811150132 30-38 SEYFRIT.K.V. 7810200226 30-449 G SHAPAR.H.K. 78110100000 30-349 H SHORT.T.E. 7811150132 30-38 SEYFRIT.K.V. 7810200226 30-449 G SHAPAR.H.K. 78110100000 30-349 H SHORT.T.E. 7811150132 30-38 SEYFRIT.K.V. 7810200226 30-449 G SHAPAR.H.K. 781220038 30-380 H SHORT.T.E. 7811150132 30-38 SEYFRIT.K.V. 7810230026 50-449 G SHAPAR.H.K. 781220038 30-380 H SHORT.T.E. 781120139 30-38 SEYFRIT.K.V. 7810230027 50-249 G SHAPAR.H.K. 781220037 30-445 H SHORT.T.E. 781020037 30-28 SEYFRIT.K.V. 7810230027 50-249 G SHAPAR.H.K. 781220037 30-445 H SHORT.T.E. 781020037 30-28 SEYFRIT.K.V. 7810230365 30-213 0 SHAPAR.H.K. 781220037 30-244 P SHORT.T.E. 7810200829 30-28 SEYFRIT.K.V. 7810230365 30-213 0 SHEA.J.J 781220017 30-244 P SHORT.T.E. 7812000829 30-28 SEYFRIT.K.V. 7810230365 30-213 0 SHEA.J.J 781220017 30-244 P SHORT.T.E. 781200082 30-28 SEYFRIT.K.V. 781120015 30-247 D SHEA.J.J 7812200107 30-244 P SHORT.T.E. 7812000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 7812200107 30-244 P SHORT.T.E. 7812000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 7812200107 30-244 P SHORT.T.E. 7812000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 7812200107 30-244 P SHORT.T.E. 7812000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 7812200107 30-244 P SHORT.T.E. 7812000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 7812200107 30-244 P SHORT.T.E. 78122000282 30-28 SEYFRIT.K.V. 781120015 30-489 G SHEA.J.J 78122000082 30-340 G SHORT.T.E. 7812200039 30-340 G SHEA.J.J 7812200009 30-340 G SHEA.J.J 7812200009 30-340 G SHEA.J.J 7812200009 30-340 G SHEA.J.J 7812200009 30-340 G SHEA.D.J.R. 78120	BERABIAN J. A. BERABIAN J. A. BEYFRITIK, V.	7811300380* 7812270057* 7811160182*	50-20 0 50-289 0 50-482 B	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V.	7812270220 7812270252 7812290083	50-315 50-316 50-316	8 8	SHORT, T. E. SHORT, T. E. SHORT, T. E.	7810250101 7810250063• 7811060079	50-265 50-265 50-265 50-265
SEYFRIT, N. V.   7810200225   30-445   0   SHAPAR, H. N.   7812120038   50-580   H. SHORT, T. E.   7811130132   30-28   SEYFRIT, N. V.   7810200226   50-445   B. SHAPAR, H. N.   781220038   50-580   H. SHORT, T. E.   781120133   30-28   SEYFRIT, N. V.   7810230276   50-298   0   SHAPAR, H. N.   781220037   50-445   H. SHORT, T. E.   781120037   30-28   SEYFRIT, N. V.   7810230276   50-298   0   SHAPAR, H. N.   781220037   50-445   H. SHORT, T. E.   781120027   50-298   SHAPAR, H. N.   781220017   50-97   O   SHORT, T. E.   781120028   50-28   SEYFRIT, N. V.   7810230276   50-285   O   SHAPAR, H. N.   78122017   50-97   O   SHORT, T. E.   7811200280   50-28   SEYFRIT, N. V.   7810230240   50-245   O   SHAPAR, H. N.   7811200204   50-245   O   SHORT, T. E.   7812040161   50-28   SEYFRIT, N. V.   7811130001   50-267   P   SHAPAR, H. N.   7811220010   50-244   P   SHORT, T. E.   7812040161   50-28   SEYFRIT, N. V.   7811170145   50-488   O   SHELDON, N. P.   781220010   50-245   O   SHORT, T. E.   781210111   50-28   SEYFRIT, N. V.   7811170145   50-488   O   SHELDON, N. P.   7812100273   50-443   O   SHORT, T. E.   781220010   50-28   SEYFRIT, N. V.   7811170181   50-489   O   SHELDON, N. P.   781210273   50-443   O   SHORT, T. E.   781220016   50-245   O   SHORT, T.	SEYFRIT, K. V. BEYFRIT, K. V. BEYFRIT, K. V.	7810140131 7810110011 7810160215	50-313 @ 50-298 @ 50-285 @	SHAPARIN K. SHAPARIN K. SHAPARIN K	7811200089* 7810140009 7810230231	50-437 50-471 50-522	A A O	SHORT, T. E. SHORT, T. E. SHORT, T. E.	7812060048+ 7811090180 7811140107	50-285 50-285 50-285 50-285 50-285
BEYFRITIK.V. 7810230360 50-267 Q SHEA, J. J 7811060172 50-244 P SHORT, T. E. 7812060282* 50-28 SEYFRITIK.V. 7810230363 50-213 Q SHEA, J. J 7812270462 50-245 P SHORT, T. E. 7812130113 50-28 SEYFRITIK.V. 7811130001 50-267 P SHEA, J. J 7812270462 50-245 P SHORT, T. E. 7812130117 50-28 SEYFRITIK.V. 7811170145 50-482 Q SHEDLOBKY, J. T. 7811300306* 50-322 Q SHORT, T. E. 7812130117 50-28 SEYFRITIK.V. 7811170145 50-482 Q SHEDLOBKY, J. T. 781210316* 50-245 Q SHORT, T. E. 7812230178 50-28 SEYFRITIK.V. 7811170151 50-485 Q SHELDON, K. P. 7812130283* 50-443 Q SHORT, T. E. 7812200203* 50-28 SEYFRITIK.V. 7811170246 50-445 Q SHELDON, K. P. 7812130273* 50-443 Q SHORT, T. E. 78122002049 50-28 SEYFRITIK.V. 7811170245 50-352 Q SHENEFIELD, J. H. 781220127 50-443 Q SHORT, T. E. 78122002049 50-48 SEYFRITIK.V. 7811220117 50-313 Q SHERDON, K. P. 7812130273* 50-443 Q SHORT, T. E. 78122003049 50-28 SEYFRITIK.V. 7811220117 50-313 Q SHERDOD, C. D. 781040026* 50-556 Q SHREVE, J. R. 7812203034* 50-28 SEYFRITIK.V. 7811220117 50-313 Q SHERDOD, C. D. 781010026* 50-556 Q SHERVE, J. R. 7812050354* 50-58 SEYFRITIK.V. 7811220124 50-287 Q SHERMODD, C. D. 7812010248 50-447 A SHROPSHIRE, R. 7812050356* 30-54 SEYFRITIK.V. 7811220124 50-287 Q SHERMODD, C. D. 7812010248 50-447 A SHROPSHIRE, R. 7812050356* 30-54 SEYFRITIK.V. 7812060264 50-285 Q SHERMODD, C. D. 7812050220* 50-447 A SHROPSHIRE, R. 7812050356* 30-54 SEYFRITIK.V. 7812060264 50-285 Q SHERMODD, C. D. 7812050220* 50-447 A SHROPSHIRE, R. 7812050356* 30-54 SEYFRITIK.V. 7812060269 50-313 Q SHERMODD, C. D. 78122101013 50-447 A SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 A SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 A SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 A SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 B SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 B SHLBERO, J. E. 7810310078 50-485 SHERMODD, C. D. 78122801009 50-447 B SHLBERO, J. E. 7810310078 50-385 SHERMODD, C. D. 78122801009	BEYFRITIK, V. BEYFRITIK, V. BEYFRITIK, V.	7810200225 7810200226 7810250026	50-445 G 50-496 G 50-445 B	BHAPAR H. K. BHAPAR H. K. BHAPAR H. K.	7811010202 7812120038 7812280072	50-549 50-580 50-443	н н м	SHORT, T.E. SHORT, T.E. SHORT, T.E.	7811150132 7811170193 7812050193	50-387 50-285 50-285 50-285 50-285
BEYFRIT.K.V. 781170246 50-458 0 SHELDON.K.P. 7812190273 50-443 0 SHREFFLER.J.R. 7810200349 50-48 SEYFRIT.K.V. 7811170250 50-582 0 SHELDON.K.P. 7812190273 50-443 0 SHREFFLER.J.R. 7810200349 50-48 SEYFRIT.K.V. 7811170250 50-582 0 SHERDON.B.W. 7810140026 30-356 0 SHREFFLER.J.R. 781020032 30-48 SEYFRIT.K.V. 7811220117 50-313 0 SHERDON.B.W. 7810140026 30-356 0 SHREVE.J. 7812270168 30-25 SEYFRIT.K.V. 7811220119 50-285 0 SHERHOOD.O.D. 7810180109 50-447 A SHROPSHIRE.R. 7812030336 30-34 SEYFRIT.K.V. 7811220124 50-287 0 SHERHOOD.O.D. 7812010248 50-447 A SHROPSHIRE.R. 7812030336 30-34 SEYFRIT.K.V. 781120012 50-298 0 SHERHOOD.O.D. 7812030220 50-447 B SHERDOL.W.C. 781210178 50-44 SEYFRIT.K.V. 7812060261 50-298 0 SHERHOOD.O.D. 7812030220 50-447 B SILBERO.J.E. 7810300267 50-58 SEYFRIT.K.V. 7812060261 50-285 0 SHERHOOD.O.D. 7812110113 50-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812060264 50-285 0 SHERHOOD.O.D. 7812110113 50-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812060269 50-313 0 SHERHOOD.O.D. 7812110113 50-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130307 50-382 0 SHERHOOD.O.D. 7812210162 50-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130307 50-382 0 SHERHOOD.O.D. 7812210179 30-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130310 50-482 0 SHERHOOD.O.D. 7812210179 30-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130310 50-482 0 SHERHOOD.O.D. 7812210179 30-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130312 50-480 0 SHERHOOD.O.D. 7812210179 30-447 A SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130313 50-482 0 SHERHOOD.O.D. 7812280099 50-447 B SILBERO.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130313 50-482 0 SHERHOOD.O.D. 78122101679 30-409 B SILVER.H. 7810310078 50-38 SEYFRIT.K.V. 7812130313 50-482 0 SHERHOOD.O.D. 78122110179 30-409 B SILVER.H. 78103100205 50-38 SEYFRIT.K.V. 7812130313 50-482 0 SHERHOOD.O.D. 781221101679 30-409 B SILVER.H. 78103100205 50-38 SEYFRIT.K.V. 7812130313 50-482 0 SHERHOOD.O.D. 781221101679 30-409 B SILVER.H. 78103100205 50-38 SEYFRIT.K.V. 78	BEYFRITIK. V. BEYFRITIK. V. SEYFRITIK. V.	7810230360 7810230363 7811130001	50-267 Q 50-313 Q 50-267 P	HEA, J. J HEA, J. J BHEA, J. J	7811060172 7812260010 7812270462	50-244 50-245	P P	SHORT, T.E. SHORT, T.E. SHORT, T.E.	7812060282* 7812040161 7812130111	50-285 50-285 50-285 50-285 50-285
BEYFRIT.K.V. 7811220121 50-287 0 SHERHOOD. 0.0 7812010248 50-447 A SHEOPSHIRE.R. 7812030336* 30-348 SEYFRIT.K.V. 7811220124 50-298 0 SHERHOOD. 0.0 7812030220 50-447 B SIEDLE.W.C. 7812210178 50-44 SEYFRIT.K.V. 7812060261 50-298 0 SHERHOOD. 0.0 7812030220 50-447 A SILBERG.J.E. 7810300267 50-58 SEYFRIT.K.V. 7812060264 50-285 0 SHERWOOD. 0.0 781210113 50-447 A SILBERG.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812060264 50-285 0 SHERWOOD. 0.0 781210113 50-447 A SILBERG.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130307 50-392 0 SHERWOOD. 0.0 78122800099 50-447 B SILBERG.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130307 50-392 0 SHERWOOD. 0.0 78122801009 50-447 B SILBERG.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130303 50-445 0 SHERWOOD. 0.0 78122801009 50-447 B SILBERG.J.E. 7810310078 50-48 SEYFRIT.K.V. 7812130312 50-458 0 SHERWOOD. 0.0 78122801009 50-447 B SILBERG.J.E. 78103100306 50-32 SEYFRIT.K.V. 7812130312 50-458 0 SHIDELER.J.J. 7812110279* 50-409 B SILVER.H. 78103100306 50-32 SEYFRIT.K.V. 7812130313 50-482 0 SHIMSHAK.R.E. 7812110167* 50-409 B SILVER.H. 78103100098 50-32 SEYFRIT.K.V. 7812130313 50-482 0 SHIMSHAK.R.E. 7812110167* 50-409 B SILVER.H. 78103100098 50-32 SEYFRIT.K.V. 7812130313 50-482 0 SHIMSHAK.R.E. 7812110167* 50-409 B SILVER.H. 78103100028 50-32 SEYFRIT.K.V. 7812130313 50-482 0 SHIMSHAK.R.E. 7812110167* 50-409 B SILVER.H. 78103100028 50-32 SEYFRIT.K.V.	SEYFRITIK. V. SEYFRITIK. V. BEYFRITIK. V.	7811170131 7811170246 7811170250	50-456 G 50-445 G 50-362 G	BHELDON, K. P. BHELDON, K. P. BHENEFIELD, J. H.	7812150283* 7812150273* 7812260137	50-443 50-443 50-443	<i>Q</i> О Н	SHORT, T.E. SHREFFLER, J. R. SHREFFLER, J. R.	7812290176 7810230349 7811200132	50-285 50-285 50-466 50-466 50-250
BEYFRIT.K.V. 7812130307 50-382 G SHERHOOD, G. G. 78122800099 50-447 B SILBERG, J. E. 7810310078 50-488 BEYFRIT.K.V. 7812130308 50-445 G SHERHOOD, G. G. 78122801009 50-447 B SILBERG, J. E. 7810310078 50-488 BEYFRIT.K.V. 7812130312 50-459 G SHIDELER, J. J. 7812110279* 30-482 A SILVER, H 7810310306 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V. 7812130313 50-482 G SHIMSHAK, R. E. 7812110167* 50-409 B SILVER, H 7810300235 50-32 SEYFRIT.K.V.	BEYFRITIK. V. BEYFRITIK. V. BEYFRITIK. V.	7811220121 7811220124 7812060261	50-267 G 50-298 G 50-298 G	SHERWOOD, O. O. SHERWOOD, O. O. SHERWOOD, O. O.	7812010248 7812050220 7812050221*	50-447 50-447 50-447	A B A	SHROPSHIRE.R. SIEDLE.W C. SILBERG.J.E	7812050356• 7812210178 7810300267	50-549 50-549 50-445 50-580 50-484
70.400 G STUUED H 79.100.0554 50-41	BEYFRIT.K.V. BEYFRIT.K.V. BEYFRIT.K.V.	7812130307 7812130308 7812130312	50-382 G 50-445 G 50-458 G	Sherwood, O. O. Sherwood, O. Q. Shideler, J. J.	7812280099 7812280100+ 7812110279+	50-447 50-447 50-492	B A	BILBERO, J. E. BILBERO, J. E. BILVER, H	7810310078 7812080233 7810310306	50-482 50-484 50-580 50-320 50-327
BEYFRIT.K.V. 7612130333 50-482 H BHIPMAY.G.D. 7612130390% 30-275 A BILVER.H 7611010246 50-28 BHACKLEFORD B. 7610240113% 50-133 P SHIPMAY.G.D. 7612130390% 30-275 A BILVER.H 78111402451 50-41	BHACKLEFORD, B. BHACKLEFORD, B.	7810240113# 7811140145#	50-133 P 50-275 K	. A. J. BALEBIHE	7812210200* 7812080113	50-275 50-272	A R	SILVER.H SILVER.H	7811140261# 7811100154	50-414 50-289 50-410 50-315 50-327

SILVER, R. D. SILVER, H. SILVER, H.	7812130353* 7812130109 7812180374	50-219 50-320 50-327	b b	98174, 0. H. 98174, J. 98174, I. H.	7812270070 7812270070* 7812010028	50-346 50-400	0	SPENCER. Q. S. SPENCER. Q. S.	7811270044 7810310284
SIMMONS, D.E. SINCLAIR, M.P. SINKIN, L. SINKIN, L. SINKULE, M. V.	7812050200 7811210493 7812110057* 7812110054 7810230072*	50-466 50-329 50-498 50-498 50-335	B C C C	Smith, J. D. Smith, F. W. Smith, J. D. Smith, O. H. Smith, J. D.	7811220139 7811300267 7812290074 7812270047 7812270014#	50-368 50-484 50-266 50-289 50-303	D G G	Spencer. O. S. Spencer. O. B. Spencer. O. B. Spencer. O. B. Spencer. O. B.	7611270121 7811270036 7812110237 7812110239* 7812210143
BINKULE, M. V. BINKULE, M. V. BINKULE, M. V BINKULE, M. V. BJOGREN, R. M.	7810310319* 7811130381* 7811130364* 7811220005* 7810170178*	50-369 50-369 50-369 50-335 50-29	0 0 0 8	emith, I.W. emith, B.H. emith, B.H. emith, G.H. emith, B.H.	7812010257 7812180394 7812130070 7812040242 7812140227	50-329 50-471 50-471 50-317 50-272	0 0 0 0	SPENCER.O. B. SPENCER.O. B. SPENCER.O. B. SPENCER.O. B. SPENCER.O. B.	7812210370 7812280241 7812270387 7812280223 7812210081
SJOGREN. R. M. SJOGREN. R. M. SJOGREN. R. M. SJOGREN. R. M. SJOGREN. R. M.	7810170151# 7810170193* 7811140166* 7811140127* 7811140122*	50-309 50-271 50-309 50-271 50-29	R R R R	SMITH, B. H. SMITH, A. F. SMITH, I. W. SMITH, I. W. SMITH, I. W.	7812270468 7812180226 7812140108 7812270055 7812270093	50-549 50-595 50-400 50-400 50-395	6 6 9	SPENCER, Q. B. SPENCER, Q. B. SPESSARD, R. L. SPESSARD, R. L. SPESSARD, R. L.	7812210166* 7812210379* 7810110184* 7811020168* 7811070003*
BJOGREN, R. M. BJOGREN, R. M. BJOGREN, R. M. BKLAR, D. R. BKOLDB, J. L.	7812150357* 7812150292* 7812150288* 7812290245* 7810110290*	50-309 50-271 50-29 50-498 50-338	R R R A G	SMITH, T. T. SMITH, T. T. SMITH, J. K. SNOW, B. SOBON, L. J.	7812210306 7812210311* 7812270268* 7810170213 7811210367	50-247 50-247 50-316 50-244 50-220	9 8 R P	BPESBARD, R. L. BPESBARD, R. L. BTAENBERG, M. R. BTAENBERG, M. R. BTAENBERG, M. R.	7812060230* 7812190160* 7811010318 7811130199 7812180416
SKOLDS: J L SKOLDS: J L SKOLDS: J L SKOLDS: J L SKOLDS: J L	7810250140+ 7811080166+ 7811130286+ 7812040181+ 7812060262+	50-280 50-395 50-321 50-395 50-280	0 0 0 0	8080N+L, J. 80COLOFSKY+J, H 80COLOFSKY+J, H, 80HINKI+S, K. 80HINKI+S, K.	7812140176 7810140023 7812110217 7810110241# 7810110250*	50-219 50-344 50-344 50-466 50-466	P	BTAFFA: R. W. BTAFFA: R. W. BTAFFA: R. W. BTAFFA: R. W. BTAFFA: R. W.	7810130043 7810130092 7811010062 7811150093 78111500163
SKOVHOLT, D. J SKRUTSKI. R. M. SKRUTSKI. R. M SKRUTSKI. R. M. SKRUTSKI. R. M.	7810140101 7810130244 7811290249 7811290002 7812040317	50-309 50-354 50-450 50-485 50-556	H 0 0 0 0	GOHINKI: B. M. BOHINKI: B. M. BOHINKI: B. N. BOHINKI: B. M. BOHINKI: B. M.	7810110037 7810110234 7810110238* 7810140056* 7810140064*	50-466 50-466 50-466 50-466 50-466	0 0 0	STAFFA: R. W. STAFFA: R. W. STAFFA: R. W. STAFFA: R. H. STAFFA: R. W.	7811100168* 7811030044 7811130261* 7811220054 7811240061
SLAPER H W. SMARRELLA E. A. SMITH R. H. SMITH J. O.	7810160197* 7810120067* 7810190116* 7811010135* 7811010029*	50-329 50-316 50-57 50-443 50-10	0 P 0 0	SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M.	7810130242 7810140096 7810140098 7810190271 7810200141	50-452 50-437 50-465 50-592 50-392	0 0 0 A A	STAFFA, R. W. STAFFA, R. W. STAFFA, R. W. STAFFA, R. W. STAFFA, R. W.	7811280006 7812070082 7812060343 7812280069+ 7812280286
SMITH. T.H SMITH. O.H. SMITH. S.H. SMITH. O.H. SMITH. O.R.	7812010303* 7811100092 7810200055 7812010081* 7810110193*	50-317 50-213 50-471 50-296 50-263	0 0 .T. 0	BOHINKI.B.M. BOHINKI.B.M. BOHINKI.B.M. BOHINKI.B.M.	7810200143 7810200144 7810230012 781024030 7810300252	50-592 50-592 50-592 50-466 50-466	A A Q Q	STAHL D.M. STAHL D.M. STAHL R.F. STAIR J.R. STAIR J.R.	7811020467 7812150029 7812210413 7810240129* 7810240134*
SMITH, I. W. SMITH, I. W. SMITH, I. W. SMITH, I. W. SMITH, Q. H	7810230015 7810270227 7810240157 781025018B 7810250134	50-484 50-400 50-329 50-329 50-286	0 0 0 0	SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M. SCHINKI.S.M.	7811070172 7811100134 7811140094 7811130038 7811100151	50-455 50-456 50-456 50-465 50-485	0 H 0 G O	STAIR: J.R. STAIR: J.R. STAIR: J.R. STAIR: J.R. STALEY: Q. S.	7811090174+ 7811090278+ 7812200278+ 7812260261+ 7811080199
SMITH, Q. H. BMITH, T. H. BMITH, B. H. BMITH, J. D. BMITH, Q. H.	7611020170 7811290339• 7810270384 7810310273 7611300366	50-271 50-336 50-471 50-568 50-20	0 0 A D	SOHINKI.B. M. SOHINKI.B. M. SOHINKI.B. M. SOHINKI.B. M. BOHINKI.S. M.	7811100170 7811100171 7811140048 7811150084 7811150090	50-592 50-452 50-466 50-437 50-477	0 9 F F	BTALLINGS; C. M. BTALLINGS; C. M. BTALLINGS; C. M. BTALLINGS; C. M. BTALLINGS; C. M.	7811010415+ 7810250232 7811060038+ 7810100057 7810100074
Shith, O. H. Shith, O. H. Shith, O. H. Shith, O. H. Shith, R. H.	7812010147 7811080253 7812010034 7812010037 7812010274*	50-244 50-219 50-333 50-220 50-245	0 0 0 0	SCHINKI.B. M. BCHINKI.B. M. BCHINKI.B. M. BCHINKI.B. M. BCHINKI.B. M.	7811160024 7811280070 7811280143 7812110286 7812130051	50-437 50-485 50-486 50-486 50-486	0 0 0 0	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7810110149 7810110127 7810120034 7810130140 7810130141
SMITH, I.W. SMITH, S.H. SMITH, S.H. SMITH, Q.H. SMITH, S.H.	7811010004 7811080337 7811090188 7811300341 7811070209	50-329 50-272 50-3 50-213 50-471	0 0 0	BOHINKI, B. M. BOHINKI, B. M. BOHINKI, B. M. BOHINKI, B. M. BOHINKI, B. M.	7812130335 7812130365 7812140349 7812180434 7812270142	50-466 50-466 50-466 50-437 50-485	0 0 0 A	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7810140139 7810140198 7810230237 7810230283 7810170163
BMITH-I.W, BMITH-Q.H. BMITH-Q.H. BMITH-I.W. BMITH-I.W.	7811070335 7811090025 7811130041 7811070349 7811080342	50-389 50-317 50-220 50-392 50-592	M Q P H	SDHINKI: S. M. BOHINKI: B. M. BOHINKI: B. M. SOKOLOFSKY: J. H. BOUDER: J. L.	7812280351 7812280354* 7812280356* 7812010361 7811290254	50-466 50-466 50-466 50-344 50-572	9 9 9 0	STALLINGS.C.M. STALLINGS.C.M. STALLINGS.C.M. STALLINGS.C.M. STALLINGS.C.M.	7810230184 7810230171 7810230254 7810250121 7810200073
SMITH, T. H. SMITH, I. W. SMITH, I. W. SMITH, B. H. SMITH, Q. H.	7812040347+ 7811070347 7811130189 7811150060 7811150038	50-333 50-395 50-329 50-349 50-220	G G G	Souder, J. L. Souder, J. L. Spangler, R. O. Spangler, R. O. Spangler, R. O. Sparke, E.	7812060383 7812190108 7812210169* 7812190061* 7811200371	50-592 50-454 50-368 60-313 50-446	A G G	Stallings, C, M. Stallings, C, M. Stallings, C, M. Stallings, C, M. Stallings, C, M.	7810200109 7810200110 7811200133+ 7810270153 7810240121
Brith, Q.H. Brith, Q.H. Brith, Q.H. Brith, Q.H. Brith, I.W.	7812110232 7811140252 7811300241 7812180057 7811200864	50~334 50~3 50~334 50~3 50~395	0 9 0 0	Sparks, E. Spencer. O. S.	7811200376 7811070164* 7811070133 78103103064 7810310318*	50-389 50-397 50-397 50-528 50-528	A Q Q Q	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7810270174 7810300022 7811130238# 7810310089 7810310238
Brith, I. W. Brith, I. W. Brith, O. H. Brith, O. H. Brith, T. T.	7811200294* 7811210130 7812010033 7812280199 7812260307	50~395 50~395 50~286 50~220 50~247	0 0 0	Spencer, Q. S. Spencer, Q. B. Spencer, Q. B. Spencer, Q. B. Spencer, Q. S.	7810310301 * 7810110255 7810110208 7810170091 7811010032	50-528 50-344 50-361 50-377 50-361	0 0 0 0	BTALL INOB, C, M. BTALL INOB, C, M. BTALL INOB, C, M. BTALL INOB, C, M. BTALL INOB, C, M.	7811030140 7811040211 7811040233 7811040078 7811070228
	SILVER, M. SILVER, M. SILVER, M. SIMMONS, D. E. SINKIN, L. SINKIN, L. SINKIN, L. SINKIN, L. SINKIN, L. SINKULE, M. V. SINKULE, M. M. SINGREN, R. M. SINCLOS, J. L. SKOLDS, J. L.	SILVER, H. 7812130109 SILVER, H. 7812130374  SIMMONS, D. E. 7812180374  SIMMONS, D. E. 7812100320  SINKLAIR, M. P. 7811210493 SINKIN, L. 78121100378  SINKULE, M. V. 78103200728  SINKULE, M. V. 78103200728  SINKULE, M. V. 7811303818 SINKULE, M. V. 7811303818 SINKULE, M. V. 7811303818 SINKULE, M. V. 78113003818 SINKULE, M. V. 78111401220  SINKULE, M. V. 78111401620  SINKULE, M. V. 78111401620  SUGGREN, R. M. 7810170179 SUGGREN, R. M. 7810170179 SUGGREN, R. M. 78111401220  SUGGREN, R. M. 78111401220  SUGGREN, R. M. 78121503570 SUGGREN, R. M. 78121502822 SUGGREN, R. M. 7812102602622  SKOLDB, J. L. 78110801668 SKOLDB, J. L. 7811080168 SKOLDB, J. L. 78110801668 SKOLDB, J. L. 78111601668 SKOLDB, J. L. 78	SILVER. H	SILVER. H.   7812100109   50-220   P   SILVER. H.   781210037   50-227   P   SILVER. H.   781210037   50-227   P   SILVER. H.   781210037   50-446   B   SILVER. H.   7812110037   50-446   C   SILVER. H.   7812110037   50-449   C   SILVER. H.   7812110037   50-449   C   SILVER. H.   7812110034   50-449   C   SILVER. H.   781020007   50-239   C   SILVER. H.   781120008   50-239   C   SILVER. H.   781120008   50-239   C   SILVER. H.   781120008   50-233   C   SILVER. H.   781120008   50-233   C   SILVER. H.   781120008   50-237   C   SILVER. H.   781120008   50-237   C   SILVER. H.   7811140146   50-209   C   SILVER. H.   7811140127   50-271   C   SILVER. H.   7812150289   50-298   C   SILVER. H.   781250289   50-298   C   SILVER. H.   78125029   50-299   C   SILVER. H.   78125029	SILVER.H  781210079  SILVER.H  78120079  SILVER.H  781210079  SILVER.H  78120079  SILVE	SILVER, H.    781210074   30-227 P.   981114-J.   7812270078	STATE   Part   Part	SILVER, I.    7912/20070   30-200   P.   SITH-I. II.   7912/20070   30-240   0	SILVER, M. 7812/20197 50-500 P SOURCE P



ļ

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION REBMUN	SUBJECT CATEGORY
STALL INGS, C. M STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7811070130 7811070190 7811070258 7811240050* 7811090177	50-280 P 50-280 P 50-338 8 50-338 0 50-280 8	STELLO, V. 9 STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7810140016* 7811020332* 7810110043* 7811070063* 7811150133	50-553 0 50-344 0 50-281 0 50-269 P 50-269 A	Sternberg. D M.	7811220267+ 7811220267+ 7811270113+ 7812130350+ 7812070045+	50-275 Q 50-275 Q 50-344 Q 50-187 Q 50-106 Q
BTALLINGS, C. M STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. BTALLINGS, C. M.	7611070236 7611140101 7611140128 7611170107 7611170162	50-281 B 50-338 P 50-280 P 50-338 R 50-338 B	STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7811150052 7811290392 7811200356* 7812110063 7812180386	50-313 P 50-271 E 50-313 P 50-280 P 50-160 E	STERNBERG, D. M. STERNBERG, D. M. STERNBERG, D. M. STETKA, T. STEVENSON, D.	7812130004+ 7812280338+ 7812270382+ 7812060219+ 7810240077+	50-275 Q 50-344 Q 50-397 Q 50-20 Q 50-269 R
STALLINOS, C. M. STALLINOS, C. M. STALLINOS, C. M. STALLINOS, C. M. STALLINOS, C. M.	7811170183 7811200194 7811210259 7811210290 7811210313	50-280 8 50-280 R 50-281 8 50-338 8 50-338 8	stello, V. Btello, V. Stello, V Btensvaag, J. M Stensvaag, J.	7812280261* 7812280285 7812220032 7812260044 7812260323	50-269 P 50-220 0 50-280 P 50-243 0 50-243 P	STEVENS.J R STEWART.W.P STEWART.R.C STEWART.W.P STEWART.W.P	7812080104 7810200152 7811060105* 7810110151 7810110116	50-302 8 50-302 8 50-302 8 50-302 8
BTALLINGS.C.M. BTALLINGS.C.M. BTALLINGS.C.M. BTALLINGS.C.M. BTALLINGS.C.M.	7811280286 7811280222 7811280236 7811280247 7811280308	50-281 8 50-338 8 50-280 8 50-280 P 50-338 P	BTEPHENBON, B. B. STEPHENBON, B. B. BTEPHENBON, B. B. BTEPHENBON, B. B. STEPHENBON, B. B.	7810170185 7810130165 7811210356 7810170204 7810170148	50-237 P 50-237 8 50-237 8 50-10 8 50-10 P	STEWART.W P. STEWART.W.P. STEWART.W.P. STEWART.W.P. STEWART.W.P.	7810110170 7810110097 7811010299 7810130130 7810160081	50-302 8 50-302 P 50-302 Q 50-302 P 50-302 R
STALL INCO. C. M. STALL INCO. C. M. STALL INCO. C. M. STALL INCO. C. M. STALL INCO. C. M.	7811280314 7811300222 .7812060134 7812180302* 7812130381	50-338 8 50-280 P 50-338 8 50-338 Q 50-280 Q	Stephenson, B. B. Stephenson, B. B. Stephenson, B. B. Stephenson, B. B. Stephenson, B. B.	7610170175 7810180101 7810240100 7810240116 7810240148	50-249 & 50-10 R 50-249 S 50-249 B 50-10 B	STEWART, W. P STEWART, R. C. STEWART, W. P. STEWART, W. P. STEWART, W. P.	7810170249 7811270209• 7810180103 7810180147 7810180133	50-302 8 50-302 8 50-302 8 50-302 8
STALL, INGS, C. M. STALL INGS, C. M. STALL, INGS, C. M. STALL, INGS, C. M. STALL, INGS, C. M.	7812180358* 7812010264 7812040209 7812040230 7812200169	50-280 G 50-338 R 50-338 B 50-280 B 50-280 P	STEPHENSON, 8 B. STEPHENSON, 8 B. STEPHENSON, 8 B. STEPHENSON, 8 B. STEPHENSON, 0 B.	7810200092 7810240136 7810270229 7810270234 7810270302	50-237 8 50-249 8 50-249 8 50-237 8 50-237 8	BTEWART.W P. BTEWART.D. L. BTEWART.W. P. BTEWART.W. P. BTEWART.W. P.	7810180110 7810230187* 7810240118 7810240160 7810270163	50-302 B 50-280 R 50-302 B 50-302 B 50-302 P
BTALL INGB. C. M. BTALL INGB. C. M. BTALL INGB. C. M BTALL INGB. C. M BTALL INGB. C. M.	7812050208 7812050223 7812070189 7812070193 7812120083	50-290 8 50-338 8 50-338 8 50-339 8	BTEPHENBON, B. B. BTEPHENBON, B. B. BTEPHENBON, B. B. BTEPHENBON, B. B. BTEPHENBON, B. B.	7811240210 7810270287 7811090125 7811030143 7811030184	50-237 8 50-237 8 50-249 8 50-237 8 50-249 8	BTEWART.W.P. STEWART.W.P. BTEWART.W.P. STEWART.W.P. STEWART.W.P.	7810310136 7810310164 7811100021 • 7811240074 • 7811090165	50-302 P
BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M.	7612180433 7612110149 7612110204 7812110191 7612110193	50-280 P 50-338 P 50-338 8 50-338 8 50-338 8	BTEPHENBON, B. B. 81EPHENBON, B. B. BTEPHENBON, B. B. STEPHENBON, B. B. BTEPHENBON, B. B.	7811090116 7811090129 7811090138 7811140160 7811060139	50-237 8 50-237 8 50-237 8 50-237 8 50-237 8	STEWART D. L. STEWART W. P. STEWART W. P. STEWART W. P. STEWART W. P.	7811170192• 7811070136 7811070204 7811070208• 7811070226	50-302 8 50-302 8 50-302 8 50-302 8
Stallings, C. M. Stallings, C. M Stallings, C. M. Stallings, C. M. Stallings, C. M.	7812130277 7812140125 7812140224 7812130282 7812130289	50-338 P 50-280 8 50-281 8 50-280 P 50-338 P	STEPHENDON, B. B. STEPHENDON, B. B. STEPHENDON, B. B. STEPHENXIN, B. B. STEPHENDON, B. B.	7811090113 7811210301 7811140193 7811140222 7811210333	50-10 9 50-237 8 50-237 8 50-249 8 50-249 B	STEWART, W. P. STEWART, W. P. STEWART, W. P. STEWART, W. P. STEWART, W. P.	7811160136 7611130181 7811140109 7811170103 7811200184	50-302 S 50-302 P 50-302 P 50-302 F 50-302 R
BTALLINGB.C.M. BYALLINGB.C.M. BYALLINGB.C.M. BYALLINGB.C.M. BTALLINGB.C.M.	7812200212 7812200253 7812200260 7812130304 7812200204	50-338 8 50-338 R 50-280 R 50-338 P 50-280 8	Stephenson, B. B. Stephenson, B. B. Stephenson, B. B. Stephenson, B. B. Stephenson, B. B.	7811140203 7811140215 7811160122 7811140119 7811160112	50-237 B 50-237 B 50-237 B 50-10 R 50-237 B	BTEWART.W.P. STEWART.W.P. STEWART.W.P. STEWART.W.P.	7812050067* 7811240216 7811280268 7811280303 7812010246	50-302 0 50-302 P 50-302 R 50-302 B 50-302 B
BYALL INGS, C. M BYALL INGS, C. M. BYALL INGS, C. M. BYALL INGS, C. M. BYALL INGS, C. M.	7812170079 7812200234 7812170088 7812170070 7812170148	50-280 P 50-238 8 50-280 P 50-280 P 50-280 P	Btephengon, B. B. Btephengon, B. B. Stephengon, B. B. Btephengon, B. B. Btephengon, B. B.	7811210177 7811210388 7811280301 7811280194 7812040191	50-237 8 50-10 8 50-249 8 50-249 8 50-237 8	BTEWART, M. P. STEWART, P. P. STEWART, H. D. STEWART, H. P. STEWART, H. P.	7812040199 7812210337+ 7812270027 7812140127 7812180150	50-302 P 50-302 G 50-272 G 50-302 F 50-302 B
BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M. BTALL INGB, C. M.	7812220078 7812240252 7812270235 7812270270 7812270270	50-339 A 50-280 P 50-338 8 50-281 8 60-280 8	BTEPHENSON D. B. STEPHENSON B. S. STEPHENSON B. S. STEPHENSON B. S. STEPHENSON B. S.	7812120130 7812210242 7812210244 7812180175 7812130184	50-249 8 50-249 8 50-249 8 50-249 8 50-249 8	STEWART, N. P.	7812200176 7812200178 7812200270 7812200284 7812220081	50-302 R 50-302 B 50-302 B 50-302 B
BTALL INGS, C. M. BTALL INGS, C. M. BTALL INGS, C. M. BTALL INGS, C. M. STAMPLEY, N.	7812270320 7812260195 7812280132 7812280136 7811150164	50-280 8 50-338 P 50-280 P 50-338 P 50-416 F	STEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B.	7812150270 7812180145 7812180174 7812180223 7812270300	50-237 8 50-249 8 50-10 8 50-237 8 50-237 8	BTEWART, W. P. BTEWART, W. P. BTEWART, W. P. BTEWWARD, D. L. STOBER, Q. J.	7812220102 7812270239 7812270291 7811200198* 7812180418	50-302 8 50-302 8 50-302 8 50-280 R 50-338 9
BTAMPLEY, N. L. BTAMPLEY, N. L. BTAMPLEY, N. L. BTAMLEY, H. B. BTARKEY, R. B.	7811170198 7812010223 7812270209 7810310192* 7810100048*	50-416 A 50-416 N 50-416 A 50-289 B 50-261 8	STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPP, J. C.	7812270284 7812210189 7812270261 7812270210 7812180355	50-249 8 50-237 8 50-237 8 50-237 8 50-207 P	BTODDART, P. O. STOHR, J. P. STOHR, J. P. STOHR, J. P.	7810130186 7811100181* 7811060244* 7811020188* 7811100094*	50-395 0 50-286 0 50-3 G 50-271 G 50-213 0
STARKEY, R. B. STARKEY, R. B. STARKEY, R. B. STARKEY, R. B. STARKEY, R. B.	7810190270 7810270225* 7810310127* 7810310153* 7810310219*	50-261 R 50-261 B 50-261 B 50-261 B	BTEPP, J. C. STEPP, J. C. STEPP, J. C. STEPP, J. C. STEPP, J. C.	7812190925 7812010014* 7810120111* 7812040324* 7811300279	- 50-549 A	STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P.	7812010150+ 7812010036+ 7812010041+ 7812060244+ 7812180058+	50-233 0 50-220 0 50-317 0 50-3 0
STARKEY, R. B. STARK, F. H. STARKEY, R. B. STARKEY, R. B. STAROSTECKI, R.	7811070191* 7812180229 7812140165* 7812270263* 7811200108*	50-261 B 50-70 H 50-261 B 50-261 B 50-437 A	BTEPP, J. C. BTEPP, J. C. BTEPP, J. C. BTEPP, J. C. BTEPTOE, P. P.	7811290201 7812190314 7812190183 7812190101 7810120112	50-400 A 50-553 A 50-554 A 50-334 P 50-237 9	STOHR, J.P. STOLZ, J.F. STOLZ, J.F. STOLZ, J.F. STOLZ, J.F.	7812290078* 7811010387 7810110006 7810230296* 7810230293	50-224 A 50-346 F 50-368 P 50-368 P
STAVELY, J. M. STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7811(50105# 7811200105# 7811200192# 7812210127 7810230134	50-309 0 50-437 A 50-437 A 50-70 P 50-280 P	Steptoe.p. P. Steptoe.p. Steptoe.p. P. Steptoe.p. P. Steptoe.p. P.	7810190131 7811130202 7811200070 7812040311 7812280280	50-237 0 50-275 0 50-237 0 50-237 0 50-237 0	8TOL 2, J.F. 8TOL 2, J.F. 8TOL 2, J.F. 8TOL 2, J.F. 8TOL 2, J.F.	7810230307* 7810130029 7810140045 7810250206	50-368 P 50-341 A 50-356 A 50-275 A

E 6	E E	8	£	8	E 8	6	8	8 8	8	8	9 8	8	8	8	8	8 8 8	8 8 9	9 9 8	6 8	8	9 9 8	8	
BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T.	BUTHERLAND. J. T. BUTHERLAND. J. T. BUTHERLAND. J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUNNERS, R. J. BUTHERLAND, J. T. BUTHERLAND, J. T.	BULLIVAN, W. F. BULLIVAN, R. F. BUMMA, J. BUMMERB, R. J.	BULLIVAN, R. F. BULLIVAN, R. F.	3TR19HT,R.L 3TR19HT,R. 3TR19HT,R.L. 3U,9.T.	STRIGHT.R.L. STRIGHT.R.L.	BTRIGHT,R.L. BTRIGHT,R.L. BTRIGHT,R.L.	BTREETER, J. F.	BTREETER, J. F. BTREETER, J. F. BTREETER, J. F. BYREETER, J. F.	BTOLZ, J. P. BTOLZ, J. F. BTOCOLEY, D. G. BIRATHAN, R. A	810LZ+J. F. 810LZ+J. F. 810LZ+J. F.	OTOLŽIJ.F. OTOLŽIJ.F. OTOLŽIJ.F.	RTOLZ, J.F. RTOLZ, J.F. RTOLZ, J.F. RTOLZ, J.F. RTOLZ, J.F.	STOLZ: J. F. STOLZ: J. F. STOLZ: J. F.	STOLZ: J. F. STOLZ: J. F.
7811130395 7811130009 7811130410 7812070059* 7811240077*	7811240009+ 7811240011+ 7811240013+ 7811030231+	7810250246* 7811080187	7810300380* 7810110240 7810250239*	7810310048 7811010186 7811010407	7810250203+ 7810130060+ 7811170240+	7811020440# 7811130016# 7810230033#	7810270213 7810260063	7810110263 7810110283 7810190037 7810180189 7810190030	7911030171* 7811030175*	7812050304* 7810260010* 7810110245*	7812070054* 7812180325* 7812210070* 7812050304*	7811010280* 7812050057*	7811090260 7812050321 7812010101 7812060253	7810270323 7811020426 7811070129	7810120126 7810110021 7810230323	7812140147* 7812290074 7812290014* 7810300138*	7810270376* 7811010029* 7811290326* 7812010129*	7812130391 7812140283* 7812180394 7811070004* 7811210275*	7812120208 7812140017* 7812140020*	7812080222 7812120016 7812070265	7812080023* 7812080025* 7812080029* 7812010010 7812080155	7811210113 7812070063* 7812080013	7812010370 7812010377 •
50-364 50-332 50-338 50-261 50-302	50-335 50-335 50-335 50-335	50-348 50-327	50-349 50-324 30-348	50-280 50-338 50-250	50-369 50-269 50-324	50-160 50-259 50-369	30-327 50-261	50-259 50-259 50-390 50-335 50-369	50-250 50-250	50-97 50-250 50-324	50-373 50-259 50-245 50-97	50-259 50-259	50-592 50-592 50-592 50-502	50-592 50-592 50-392	50-548 50-592 50-592	50-266 50-266 50-303 50-447	50-301 50-10 50-320 50-253	50-358 50-275 50-275 50-471 50-336	50-275 50-368 50-368	50-368 50-368 50-358	50-368 50-368 50-368 50-275 50-341	50-275 50-275 50-360	50-313 50-313
0 0 0	a a a	a a	0 0	a a	g g	0 0	Q Q	0 0 0	0 a	0 0 0	A G P	œ œ	A A A	A	A	Q Q Q A	9 0 0	A 0 0 8	P P	B P 1	P P A A	A E P	p P
Tedesco.r. L. Tedesco.r. L. Tedesco.r. L. Tedesco.r. L. Tedesco.r. L.	TEDESCO,R.L. TEDESCO,R.L. TEDESCO,R. TEDESCO,R.L.	TAYLOR, Q. T. TEDEBCO, R. L.	TAYLOR, P. A. TAYLOR, P. A. TAYLOR, Q. T.	TAYLORIP. A. TAYLORIR. Q. TAYLORIA	TAYLOR, R. O. TAYLOR, R. O. TAYLOR, R. O.	TANBLING, T. N <u>.</u> TAP 1A+J. I. TAP 1A+J. I.	TAGLIAMONTE, H. TALHANI, P.	BWANBON, D. T. BWANBON, D. T. BWART, F. E. BWEENEY, B. TAGL I AMONTE, M.	SHANSON, D. T. BHANSON, D. T.	SHANBON, E. R. SHANBON, D. T. SHANBON, D. T.	BUANGON D. T.  BUANGON D. T.  BUANGON D. T.  BUANGON D. T.  T.  BUANGON D. T.	SHANBON.O.T. SHANBON.D.T. SHANSON.D.T.	SWALES, J. SWAN, W. B. BWAN, W. B. SWANDON, O. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. Y. SUTHERLAND, J. Y. SUTHERLAND, J. T. SUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T.
7811200130+ 7811200439+ 7811200232+ 7810270024 7811060106=	7811200263* 7811200142* 7811200138* 7811200134*	7812260067* 7811200261*	7812180317* 7812210350* 7812260065	7811220064* 7812060341* 7812120044*	7811020055* 7811020449* 7811070308*	7812270070* 7811270209* 7812060307*	7811140106* 7810240077*	7812270381 7812290072 7812180243 7810120057* 7810130180*	7812180292 7812220009	7812290025+ 7812150359 7812140111	7811200064 7812040360 7812040251 7812110331	7810250009 7810240089 7811070186	7611240154* 7812180343* 7812280080*	7812070059 7812130241 7812280328	7812210071* 7812290056 7812060015	7812050021 7812010139 7812040326 7812140118+	7812010125 7812140119+ 7812290082 7812010261	7812210152 7811240001 7811240071 7811240046 7812010116	7811200421 7611200422 7811200423	7811200413 7811200417 7811200418	7812080006 7812280342* 7811170232 7811200406 7811200409	7811130004 7812110222 7812030242*	7812070301 7812080215
50-437 50-437 50-437 50-329 50-556	50-437 50-437 50-437 50-437	50-329 50-437	50-302 50-302 50-329	50-321 50-445 50-580	50-445 50-445 50-445	50-346 50-382 50-856	50-266 50-269	50-70 50-339 50-267 50-335 50-286	50-338 50-338	50-255 50-522 50-70	50-70 50-70 50-338 50-338	50-70 50-50B 50-338	50-265 50-400 50-424 50-70	50-261 50-261 50-250	50-250 50-339 50-259	50-269 50-338 50-269 50-348	50-250 50-348 50-280 50-280	50-324 50-325 50-302 50-338	50-369 50-302 50-348	50-335 50-250 50-369	50-280 50-250 50-324 50-257 50-321	20-520 20-580 20-523	50-261 50-13
A A Q	A A A	ō A	0	Q Q Н	0 0 0	0 @ @	R R	Q R B R	0	0	0	0	9 0 0	0 0	<i>e</i> e e	0 0 0	0 0 0 0	9 9 9	P P	P P	0 0 P P	0 0	a a
TOTH, A. D. TOURTELLOTTE, J	TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C. TOMONTO, J. R.	TOLLIBON A. C.	TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C.	TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C.	TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C.	TOLLIBON A. C. TOLLIBON A. C. TOLLIBON A. C.	TOLLIBON, A. C. TOLLIBON, A. C.	TOLLIBON A. C.	7000, 0, A TODD, M. A	TOBIN, P. A. TOBIN, P. A. TOBIN, P. A.	TOALSTON A. TOALSTON A. TOALSTON A. TOALSTON A. TOALSTON A.	TILLINGHAST, J. TILLINGHAST, J. TILLY, D. D.	TILLINGHABT, J. TILLINGHABT, J. TILLINGHABT, J.	Tillinghast, J. Tillinghast, J. Tillinghast, J.	TIETZ, O. TILLINGHABT, J. TILLINGHABT, J.	THRASH.C.Q. T1881TTS,D.L. T1EDKE.J.H. T1ERNEY.F.P.	THRAILKILL, K. THRABH, C. Q. THRABH, C. Q. THRABH, C. Q. THRABH, C. Q.	THOMBEN.F. T. THONUB.L. H. THONUB.L. THORNBURO.H. THORNBURO.H.	THOMSEN.F. T. THOMSEN.F. T. THOMSEN.F. T.	THOMPSON G. A. THOMPSON G. THOMPSON G. O.	Thomas, E. B. Thomas, E. B. Thomas, E. B. Thomas, E. B. Thompson C. R.	Thomab, R. D. Thomab, C. D. Thomab, C.	THOMAS, E. S. THOMAS, E. S.
7811140249 7811140280 7811170299 7812120026	7812210222 7812270242 7812270303 7812140152	7812210185 7812210192	7812070181 7812080130 7812200199 7812200201	7812070217 7812070169	7811160092 7811160133 7812180335	7811090197 7811160141 7811160144	7810310142 7810310222	7810100032 7810100053 7810130181 7810130156 7810130162	7812200213 7812010182 7812200251	7811280239 7811280244	7810200057 7810200146 7810230074 7811070100	7812290179 7812260242 7812270251	7811290247 7812260198 7812270178	7810310090 781031020 7811210260	7811240204 781023024 781103010	781212022 781027014 781102007 781205017	781013018 781108003 781013019 781211025 781207005	781213022 781201009 781114026 781205001	781019019 781030010 781107035	781102031 781204000 781228032	781121029 781124010 781205034 781226020 781127016	781127009 781102041 781113032	78102703B 781027040

TOURTELLOTTE, J. TOURTELLOTTE, J. TOURTELLOTTE, J. TOURTELLOTTE, J. TOURTELLOTTE, J.	7810300082 7811060058 7811108014 7812140373 7810110205+	30-275 50-275 50-275 50-275 50-70	0 0 0 0	UHRIGOR.E. UHRIGOR.E. UHRIGOR.E. UHRIGOR.E. UHRIGOR.E.	7810110251* 7811030168* 7810230052* 7810240071* 7810120075	50-250 50-250 50-335 50-250 50-250	0 0 0 0	UTLEY, E. E.	7810110108 7810130122 7810130143 7810240127 7810260249	\$0-261 \$0-324 \$0-324 \$0-324 \$0-324
TOHER, J. TRAINA. P. J. TRAINA. P. J. TRAINA. P. J. TRAINA. P. J. TRAHMELL. C. M.	7810110203* 7812280026* 7812010243 7812280040* 7810120120	50-70 50-250 50-390 50-250 50-344	P P A P	UHR 10 - R. E. UHR 10 - R. E. UHR 10 - R. E. UHR 10 - R. E. UHR 10 - R. E.	7810110121 7810240075* 7810200252 7810230329 7810200188	50-335 50-230 50-335 50-335 50-250	P G G G	UTLEY, E.E. UTLEY, E.E. UTLEY, E.E. UTLEY, E.E.	7810270147 7810270111 7810310122 7811090109 7811160135	50-261 50-324 50-261 50-324 50-324
TRAMMELL C. M TRAMPLEABURE, L. TRAXLER, D. V. TRAXLER, D. V. TREBY, S. A.	7812160009 7810140100 7810240150¢ 7811090124¢ 7810120019	50-344 50-70 50-10 50-10 50-70	P 0 8 9 0	UHR [O. R. E. UHR [O. R. E. UHR [O. R. E. UHR [O. R. E. UHR [O. R. E.	7810110077 7810120022 7810110159 7810110123 7810120028	50-335 50-250 50-250 50-251 50-250	5 5 5 5	UTLEY, E. E.	7811170127 7812110133 7812130115 7812270192 7812270207	50-261 50-261 50-324 50-324 50-324
TREBY, B. A.	7810230218 7811060167 7811080029 7811200137 7812040371	50-338 50-344 50-275 50-338 50-338	G 0 0 0 F	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7810180115 7810230140 7810300107 7810170191* 7810200045	50-335 50-250 50-250 50-250 50-250	<b>3</b> 3 5 5 6	VAHRENWALD.J. VAHRENWALD.J. VALENTINE.P.C. VALENTINE.P.C. VALENTINE.P.C.	7810170235* 7811240240* 7811010324 7810300008 7811070358	30-254 30-254 90-275 30-275 30-275
TREBY, S. A. TREBY, S. A. TREBY, S. A. TREBY, S. A. TREBY, B. A. TROFFER, O. J.	7812050342 7812130079 7812280195 7812270114 7810240119	50-338 50-522 50-395 50-320 50-289	0000	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7610240066 7610270182 7611090242 7611100083+ 7611030226	50-399 50-250 50-335 50-250 50-335	A P B O O	VALENTINE.P.C. VALLADE.B. VALLIBH.E.J. VALLIBH.E.J. VALLIBH.E.J.	7612180309 7810310309* 7812070030* 7812280315* 7812060362*	50-275 50-346 50-364 50-395 50-389
TROFFER, Q. J. TROFFER, Q. J. TROFFER, Q. J. TROBTEN, L. M. TROUP, Q. L.	7811140103 7811160145 7812290129 7812260014 7811130049*	50-289 50-289 50-289 50-247 50-259	P P P	UHRIO, R. E.	7811070309 7811240007+ 7810310002 7810310121 7812010043	50-250 50-335 50-335 50-250 50-250	0 F F 0	VALLISH.E.J. VALORE.C. VAN ART.A.E. VAN BRUNT.E.E. VAN BRUNT.E.E.	7812040175* 7811280089 7810300204 7810310294* 7810250056	50-395 50-437 50-409 50-528 50-592
TROUP.O.L. TROUP.O.L. TROUP.O.L. TROUP.O.L. TROUP.O.L. TROWBRIDDE.Q.F.	7810230036* 7811170245* 7812060033* 7812210155* 7810130225	50-369 50-324 50-239 50-324 50-266	0 0 0	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7812010119* 7811060095 7811070144 7811070180 7811210188	50-250 50-335 50-250 50-250 50-250	Q P I P Q	VAN BRUNT, E. E.	7810310288# 7810310365# 7810180091 7811060087 7810310140	50-528 50-528 50-592 50-592 50-592
TROWER IDOE, O. F.	7810200034 7810230325 7812010316 7812210456 7812280079	50-320 50-266 50-400 50-320 50-400	0	UHR19, R.E. UHR19, R.E. UHR19, R.E. UHR19, R.E. UHR19, R.E.	7812010128+ 7811130221 7811140219 7811160107 7811220002	50-250 50-250 50-335 50-335 50-335	G Р Р С	VAN BRUNT, E. E.	7811090086 7811290130 7812210132 7612210114 <del>*</del> 7812110126	50-392 50-592 50-592 50-528 50-528
Trubatch 8. L. Trubatch 8. L. Trubatch 8. L. Trzyna: 0. Trzyna: 0.	7812110224 7812110226 7812110228 7810170211* 78111240206*	50-247 50-247 50-247 50-304 50-295	о о в в	UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7811240025 7811160139 7811290320 7811290004+ 7811210338	50-250 50-250 50-369 50-335 50-250	G P G G P	VAN BRUNT, E. E. VAN BICKEL J. VAN BICKEL, J. VAN BICKEL, J. VAN BICKEL, J.	7812190071 7810200063* 7811210394* 7811280206* 7812190139*	50-528 50-331 50-331 50-331 50-331
TRZYNA: Q. TURBAK: M. S. TURBAK: M. S. TURBAK: M. S. TURBAK: M. S.	7812210219* 7810100027 7810100078 7810200086 7810240158	50-295 50-237 50-10 50-10 50-10	8 P R P	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7812010100 7811210327 7811210328 7811210328 7811240209 7811290229	50-250 50-335 50-335 50-335 50-335	G P P P	VANDEL, T. E. VANDENBURGH, D. VANGENBURGH, D. VANDENBURGH, D. VANDENBURGH, D.	7811010057* 7810110177 7810140135 7810260160 7811020247	50-358 50-29 50-271 50-29 50-29
Turbak, M.B. Turbak, M.B. Turbak, M.B. Turbak, M.B. Turbak, M.B.	7810210093 7810260183 7811060180 7811140105 7811140099	50-10 50-10 50-254 50-237 50-10	0 P 0 P R	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7812050240 7811270161 7811280228 7812060356 7812180316#	50-250 50-250 50-250 50-389 50-335	0 P P 0 0	VANDENBURGH, D VANDENBURGH, D, VANDENBURGH, D, VANDENBURGH, D, VANDENBURGH, D,	7011140224 7011140190 7011240167 7011240230 7011290243	50-271 50-27 50-27 50-27 50-307
Turbak, M. S. Turbak, M. S. Turbak, M. S. Turbak, M. S. Turbak, M. S.	7811210257 7812050107 7811270158 7811280244 7812120153	50-237 50-10 50-10 50-237 50-10	P V P P	UHRIG:R.E. UHRIG:R.E. UHRIG:R.E. UHRIG:R.E. UHRIG:R.E. UHRIG:R.E.	7812270275# 7812140195 7812280339# 7812120239# 7812120145	50-335 50-335 50-250 5 <i>0-250</i> 50-367	P G G G A	VANDENBUROH, D. VANDENBUROH, D. VANDENBUROH, D. VANDEL, T. E. VANDOORN, P. K.	7811270255 7812040234 7812090116 7812270247* 7811080158*	50-29 50-29 50-441 50-395
Turbak, M. B. Turbak, M. B. Turbak, M. B. Turbak, M. B. Turdera, J. L.	7812120070 7812220093 7812200219 7812270327 7812110273*	50-237 50-237 50-254 50-10 50-482	P P P A	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7812170235 7812210138 7812280019 7812140146 7812140150	50~250 50~335 50~250 50~251 50~250	G G P P	VANDOORN P. K. VANDOORN P. K. VANDOORN P. K. VANDOORN P. K. VANDOORN P. K. VANDOORN P. K.	7811080302* 7812050307* 7812180343* 7812290128* 7811270150*	50-438 50-327 50-400 50-327 50-331
TURI, 9, TURI, 9, TURNER, E. A. TURNER, E. A. TURNER, E. A.	7811220040* 7811220048* 7810300088 7811020387* 7810120024	50-549 50-549 50-498 50-498 50-498	T T A G K	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7612160136 7812210968 7812210196 7812270190 7812270267	50~250 50~250 50~251 50~250 50~335	9 9 4 9	VANTHIEL M. VARELA, A. A. VARELA, A. A. VARGA, B.A. VARGA, B.A.	7811020033 7812120246* 7811300347* 7810140083 7810110211	50-70 50-363 50-412 50-390 50-556
Turner, E. A. Turner, E. A. Turner, E. A. Turner, E. A. Turner, E. A.	7811020393* 7811170090* 7811010144 7811090106 7811300382*	50-498 50-466 50-498 50-498 50-498	0 A 8 0	UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7812270147 7812270195 7812270187 7812280139 7812270221	50-335 50-250 50-250 50-250 50-250	р Р Р	VARQA; B. A. VARQA; B. A. VARQA; B. A. VARQA; S. A. VARQA; B. A.	7810140079 7810140006 7810230063 7810240213 7811010342	50-443 50-413 50-556 50-329 50-320
TURNER, A. J., TURNER, E. A. TURNER, E. A., TURNER, E. A., YURNER, E. A.	7612130006 7613160131 7811300216 7811240114 7812190147	50-975 50-498 50-498 50-498 50-498	e B C A	ULLRICH, M. T. ULLRICH, M. T. ULLRICH, M. T. UPTHEOROVE, H. R. UPTHEOROVE, H. R.	7811080094 781114086 7811280470 7810110167 7811070082	50-277 50-278 50-278 50-112 50-112	8 8 8 9 9	VARDA, B.A. VARDA, B.A. VARDA, B.A. VARDA, B.A. VARDA, B.A.	7810300340 7811010055# 7811010068# 7810310364 7811140861#	50-556 50-414 50-414 50-327 50-410
Turner, E. A. Tuthill 8, J. Ugolinid, J. Uhrio, R. E. Uhrio, R. E.	7810240101 7810240104 7811240198 7810260007 7810260070	50-466 50-331 50-295 50-250 50-389	B P 8 0	Urban, J. R. Urban, J. R. Utley, E. E. Utley, E. E. Utley, E. E.	7812040032 7812140209 7811220180* 7811220177 7810110110	50-346 50-346 50-325 50-325 50-324	M P P	Varga, B.A. Varga, B.A. Varga, B.A. Varga, B.A. Varga, B.A.	7811140264# 7811150109# 7811080249 7811130055 7811140059	50-410 50-329 50-488 50-556 50-329

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGOR'	r	AUTHOR	ACCESSION NUMBER	EUBJEC1 CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
	7011100777	50-491	 A	HALLACE, E. O.	7810300146	50-219	н	HAREHBOURG. D	7810300179	50-267
VARGA.S A.	7811130377 7811150010	50-445	Ä	HALLACE, H V.	7810300153*	50-289	H	WAREHBOURG. D.	7810300309	50-267
VAGAL B.	7811170073	50-397	A	HALLACE.E. O.	7810300157*	50-219	P	WAREHBOURG. D.	7810160100	50-267
VARQA: 8. A	7811150032	50-466 50-572	A	WALLACE.J. A WALLACE.J. J.	7811210090 7811140118*	50-331 50-305	Q R	HAREMBOURG. D WAREMBOURG. D	7810230165	50-267
VARGA-8 A.	7811290003	20-272	-	MALLACETY. D.	/01114011dw	30-305	n	MAKENBUOKALD	7810270228	30-267
VARQA. B. A	7811240073	50-390	Ą	WALLACE, T.	7812070055	50-223	P	WAREHBOURG. D.	7810270276	50-267
VARQA, B A.	7811240078	50-445 50-329	A	WALLIN. O. WALSH. P.	7812290233 7810190085	50-331 50-246	0	HAREMBOURG, D. HAREMBOURG, D.	7810310225	50-267
VARGA, S. A. VARGA, S. A	7811300007 7812050094#	50-327	Â	WALSH, P.	7810190083	20-599	Č	WAREMBOURQ. D.	7811070234 7811160071	90-267 90-267
VARGA, B. A.	7812010343	50-445	A	WALSH. P.	7812270050	50-266	ö	WAREHBOURG. D.	7811270154	30-267
				1141 CH D	30.000000			*********		
VARQA. S. A.	7812110100 7812080009	50-556 50-556	A	WALSHIP.	781222002 <i>7</i> 7812220029*	50-305 50-305	0	WAREMBOURG.D WAREMBOURG.D	7811280285 7811280312	50-267 50-267
VAROA, B. A	7812190184	50-454	A	WALSH. P.	7812220031*	50-305	ŏ	HAREMEDURO, D	7812130163	50-267
VAROA, B. A.	7812190185+	50-454	A	HALTERS O. X.	7812150199*	50-390	Q.	WAREHEDURG, D.	7812130135	50-267
VARGA. S A	7812180391	50-329	A	WALTON: Q. A.	7811130285+	50-334	<b>G</b>	HAREMBOURG. D.	7812130190	50-267
VARGA, S. A.	7812140242	50-327	A	HALTON, Q. A.	7812290220#	50-334	g	WAREMBOURG, O.	7812130176	50-267
VARGA. S. A.	7812200351	50-397	A	WAMBACH, T. V.	7810110075*	50-245	P	WAREMBOURO, O.	7812130179*	50-267
VARIN-D. H.	7810180084	50-568 50-471	Q .	WAMBACH, T. V. WAMBACH, T. V.	7811020408* 7810300125	50~409 50~213	P P	Warehbourg, D. Warehbourg, D.	7812200209	50-267
VASSALLO D B.	7812130072* 7811060100*	50-556	ŏ	WAMBACH, T. U	7811280084*	50-27	P	MAREMBOURG, D.	7812200164 7812270201	50-267 50-267
			_							
VASSALLO D 8.	7811030194 7811010189		p A	WAMBACH. T. V. WANDE. N. E.	7812040020* 7812210203	50-206 50-295	P 8	WAREB, C. S. WARNICK, R. F.	7811210478*	50-556 50-305
VASSALLO D 8	7611080241		Ä	WANDKE N E.	7810170208	50-245	8	WARNICKIR. F.	7810110185* 7811210436*	50-266
VASSALLO, D. B	7811200056	50-416	A	HANDKE, N. E.	7810170184	50-275	9	WARNICKIR. F.	7811300141*	50-155
VABBALLO D B	7812070056	50-275	E	WANDKE, N. E.	7810170191	50-295	8	WARNICK.R.F.	7812060128#	50-305
VASSALLO D. B	7811280081	50-327	A	HANDKE N E.	7810170207	50-295	8	WARNICKIR. F.	7812140016+	50-263
VABBALLO, D. B	7811280086		A	HANDKE, N. E.	7810180050	50-275	8	WARNICK R. F.	7812040077*	50-409
VASSALLO D B	7811280098		Ą	WANDKE, N. E.	7810170219	50-295	8	HARNICK . R. F.	7812200099*	20-585
VASSALLO D. B.	7811280091		A A	WANDKE, N. E. WANDKE, N. E.	7810170251	50-304	8	HARNICKIR. F.	7812130045*	30-315
VABBALLO D. B	7811280094	30-377	-	WANDAEIN E.	7810170253*	50-304	8	WARNICK-R. F.	7812200295*	50-35B
VABSALLO D B.	7811200097		A	WANDKE, N. E.	7810170225	50-295	8	WARNICKIR. F.	7812290032×	50-266
VABBALLO D. B.	7811260101		A	WANDKE N. E.	78101702284	50-295	8	WATFORD.M. L.	7810160149*	50-241
VASSALLO D. B. VABSALLO D. B.	7811260106 7811260109		A	WANDKE, N.E. WANDKE, N.E.	7810170214 7810170223*	50-295 50-295	8	WATFORD, M. L. WATFORD, M. L.	7811160120x	30-261
VASSALLO D. 8	7811280117		Ä	WANDKE, N. E.	7810170223	50-275	8	WATKINBIR. V.	7812150351* 7810250046	50-261 50-502
VASSALLO D. B. VASSALLO D. B.	781128011A 7811280122		A A	HANDKEIN E. WANDKEIN E.	7910170218	50-304	8	HATKINS, K. B.	7811140170*	50-31B
VASSALLO D. B.	7811260125		Ä	WANDKE N E.	7810170231 7810170239	50~295 50~304	8	WATKINS.K. B. WATKINS.R. V.	7811300199* 7812200303	50-317 50-502
VASSALLO D 8.	7811280132	50-49B	A	HANDKE, N. E.	7811240127	50-295	š	WATKINB.K. B	7812130174	50-318
VASSALLO D. B.	7812010342	50-341	A	WANDKE, N. E.	7611240197	50-295	8	WATKINBIR. V.	7812270047	50-327
VABSALLO D 8	7812010346	50-416	A	WANDKE, N. E.	7811240200	50~275		WATBON, K. B.	7812180246	50-329
VASSALLO D. B.	7812010349		A	HANDKE, N. E.	7811240212	50~295	8	HATT, J. J.	7811220070*	50-549
VASSALLO D. S.	7812050080		Ą	WANDKE, N. E.	7811240218	50-304	9	WATT, J. J.	7811220077+	50-549
VASSALLO D. S. VASSALLO D. S.	7812030083 7812030084		A P	WANDKE, N.E.	7811240221	50-295	8	WATTS, A. R.	7811200411	50-592
VADOREEU D. O.	7012030004	30-386		WANDKE, N.E.	7811240145	50~304	8	WATTS, M. J.	7812150054	50-133
VABBALLO, D. B.	7812280343*		•	WANDKE, N	7811010141	50~295	R	WEBB, J. D.	7811070143+	50-443
VASSALLO D. B. VASSALLO D.	7812130011 7812190213		P .	WANDKE, N. E.	7811240195	50~304	8	WEBSTER.E. H.	7811220005+	50-335
VELO, D. J.	7812170213		<b>A</b> 8	WANDKE, N. E. WANDKE, N. E.	7811240227 7811240203	50~295 50~295	8 9	WEBBTER.E. H WEIDNER.R.	7812060228*	50-338
VENN LEEDS, J.	7811080219		ō	HANDKE, N. E.	7811240207	50-295	8	WEINER R. H.	7812210195# 7810110142	50-237 50-498
			_							
VERDERY E. H.	7811070320* 7812010109*		o o	WANDKE, N. E. WANDKE, N. E.	7811240135 7811240176	50~304 50~304	8	HE188ARD, A. J.	7812220141	50-320
VERDERY-E. H.	7812190243*		ă	WANDRE, N. E.	7812110124	50-295	8	WE188, E.R. WE188, E.R.	7810300039 7810300057*	50-338 50-338
VERDUZCO G. H,	7811060055*	50-298	q	WANDKE, N. E.	7812110144	50-295	8	WE188, E.R.	7810300065+	50-33B
VEZEY, E.E.	7812110114*	50-447	A	HANDKE, N. E.	7812110157	50-295	8	WEISB, E.R.	7612110101	50-33B
VISSCHER, H. B.	7812010205	50-395	A	HANDKE, N. E.	7812110161	50-295	8	WEIBS, E.R.	7812280158	50-339
VOOT-LOVELL, R.	7810130051*	50-366	Q .	HANDKE, N. E.	7812110151	50~295	8	WELLER, R. A.	7811290046*	50-514
YOOT-LOWELL, R. YOOT-LOWELL, R.	7810130099*	50-321	9	HANDKE, N. E.	7812110175	50-295	8	WENSLAWSKI, F. A.	7811270107*	50-344
VOOTLE, A. W.	7811220099# 7811030054#	50-260 50-424	G G	HANDKE, N. E. HANDKE, N. E.	7812110160	50-295	8	WERLING, J. A	7810100030	50-334
			•	WINDHALL C.	7812110179	50-295	6	WERLING. J. A.	7810100034*	50-334
VOIGHT, H. H.	7811130399	50~548	•	HANDKE, N. E.	7812210214	50~295	8	WERLING, J. A.	7810100084	50-334
V010T, H. H. V010T, H. H.	7810140028 7811010136	50-452 50-546	0	HANDKE, N. E.	7812210227	50-295	8	WERLING, J. A.	7811030144	50-334
VOLLEN, R J.	7811160050	50-347	5	WANDKE, N. E. WANDKE, N. E.	7812210217 7812210234	50~304 50~295	8 8	WERLING, J. A. WERLING, J. A.	7811130218 7811130220+	50-334
VOMACKA,A.	7811020169	30-466	ō	HANO, C. H.	7812270193	50~106	P	WERLING, J. A.	7811170214	50-334 50-334
VOHACKA, A.	1011000171		•							
VOMACKA, A.	7811020176+ 7811020181+	50-466 50-466	0	HARDIJ. J. HARDIK. D.	7810240236* 7811010059*	50~49B 50~373	Q Q	WERLING, J. A.	7811170219	50-334
VORDERBRUEGGEN	7811270058*	50-312	ğ	WARD, K. D	7811010037*	50-358	ă	WERLING, J. A. WERLING, J. A.	7811170172 7811170178*	50-334 50-334
VOTH, M. H	7811160147	50-54	P	HARD, E. C.	7810170224	20-585	8	WERLING, J. A.	7811170221	50-334
VOTH, H. H.	7612290157	50-54	J	WARD, W. H.	7811160181	50~482	8	WERLING, J. A.	7811170234*	50-334
VOZENILEK, H	7811100018	50-397	0	WARD, K. D.	78112800324	50~331	a	HERLING. J. A.	7812120143	50-334
HACHTER.L. J.	7810170262*	50-243	P	WARD, J. J	7811200330+	50-278	ŏ	WERLING, J. A.	7812120148»	50-334
WACHTERIL, J. WACHTERIL, J.	7810200080+	50-263	P	WARD, K. D.	7811210024+	50-331	G	WERLING, J. A	7612180180	50-334
WACHTERIL. J	7811280338 7812210036	50-263 50-282	P 0	HARD, J. J. HARD, K. D.	7812060341* 7812140028*	50~445 50~30B	Q Q	WERLING, J. A.	7812190194*	50-334
					/ U : # ! T ! ! ! # ! !	50-329	·	WERLING, J. A.	781 2270222	50-334
HACHTERIL. J. HAONERIA G.	7812070222*	50-263	P	HARD, K. D.	7812060178*	50-266	a	HERLING, J. A.	7812270224*	30-334
HAGNER, A D.	7811090279* 7812270386*	50-390 30-390	0	WARD, E. C. WARD, K. D.	7811070215	20-585	8	WERLING, J. A.	7812270216	50-334
WALDNER P. F.	7812040316	30-466	¢	WARD, K. D.	7812080057* 7812270078*	50~35B 50~409	a a	WERLING, J. A. WERLING, J. A.	7812290223* 7812290227*	50-334
HALKER, R	7812060340+	50-231	à	HARD, J. J.	7812070002+	50-128	ā	WERLING, J. A.	7812270227#	50-334 50-334
HALKER, R. D.	7811140267+	50-373	0	WARD C A			_			_
HALKER, R.	7811210220+	50-373	Ö	HARD, E. C. HARD, J. J.	7812060141 7812180424+	50-282 50-59	P G	WERNER, L. WERNER, L.	7811020275* 7810270341	50-344 80-344
HALLACE, J. J.	7810170159*	30-305	R	HAREMBOURO, D.	7810300164	50-267	8	WERNER, R.	7812210150	50-344 50-445
HALLACE: L. E. HALLACE: J. A	7810240037 7811080002	50-566 50-331	Q Q	HAREMBOURG, D.	7810300189	50-267	8	WEBCOTT, H. M.	78122902474	50-461
	>21100000S	20-331	· ·	HAREMBOURG, D.	7810160131	30-267	8	WESSMAN, R. H.	70120501654	50-327

## PERSONAL AUTHOR INDEX

BUBJECT

ACCES910N

7811060344 7811200007 7811170003 7811200420 7811200413 50-554 50-464 50-554

50~556 50~556

WOLFE.S.J. WOLFE.S.J. WOLFE.S.J.

HOLFE, B. J.

50-62 50-313 50-368 50-313

50~62

7812200232

7812200222 7812200224 7812210135 7812200221 P 8 0 P

BUBJEC

ACCESSION

AUTHOR	NOWBER	CATEODRY	, . <b>-</b>	AUTHOR	ACCESSION NUMBER	CATEOUR	<b>Y</b>	AUTHOR	ACCESSION NUMBER	CATEOC
HEBBKAN. O. L.	7811060113		P	HIGGINTON, D	7812080143	50-334	 P	WILLIAMSON, T. O.	7812260144	50-62
WESSMAN, O. L	7811130200		P	HIONT. J. B.	7812040031*	50-344	0	HILL IAMB, D. H.	7812270247	50-313
HEBBMAN, G. L. HEBTERMAN, T. F.	7811240232 7810130053*		K O	HIGHT, J. B. HILBUR, L. C.	7812280266 7811240038	50-344 50-134	V	HILL IAMS, D. H. HILL IAMS, D. H.	7812270299 7812280127	50-348 50-313
WESTERMAN, T. F.	7810140092*		ā	WILLEMSEN. B.	7811240241	50-265	B	WILLBEY, W B.	7810270186	50-277
WESTERMAN, T. F.	7811210501+		Q.	WILLIAMSON T Q.	7812200222	30-62	P	WILLBEY, H. B.	7811170130	50-277
WESTERMAN, T. F. WESTERMAN, T. F.	7812210169* 7812190061*		0	WILLIAMSON, T. G.	7611010102	50-62	P	WILLSEY. W. B.	7812080109	50-277
HESTERMAN, T. F.	7812270020*		g g	NILLIAMBID. H WILLIAMBIO. H.	7810110301+ 7810190096	50-313 50-368	O P	WILLBEY, W B. WILBON, J N.	7812180154 7810180175	50-277 50-322
WETHY, C. M.	7812080200		8	WILLIIAMS D W.	7610120114	50-368	8	WILSON, K. R.	7810200170*	20-59
WETTERHAIN, M. J.	7810270313	50-395	0	WILLIAMS D H	7810100018	50-368	8	WILSON, B. M.	7810170141	30-021
WETTERHAHNIN J. WETTERHAHNIM J.	7810310017 7811220157	50-395 50-510	0	WILLIAMS D.H. WILLIAMS D.H	7610100023 7810110137	50-368 50-368	8 9	WILBON, B. M. WILBON, J. N.	7810170142 7810200231	50-346
WETTERHAHNIM. J.	7812040351	50-272	0	WILLIS, E	7810130124#	50-324	Ř	WILSON, F. R.	7811070152	50-344
HETTERHAHNIM. J.	7012130025	50-395	0	WILLIAMS, D. H.	7810170143	50-313	8	WILBON. B. D.	7811170157	50-352
HETTERHAHNIH. J. WETTERHAHNIM. J.	7612130299 7612160400	50-356 50-395	0	WILLIAMS D. H. WILLIAMS D. H	7810170190	50~348 50~313	8	WILSON, N. R.	7811080141*	50-270
WETTERHAHNIM J.	7812180301	50-272	•	WILLIAMS, O. H.	7811210125 <b>-</b> 7810200067	20-313	G R	W1Ľ80N, 8. W1Ľ80N, 8.	7811160068* 7811160110*	50-321 50-346
WHARTON: A. WHARTON: A.	781116001B 7811160155	50-466 50-466	0	HILLIAMS P. M HILLIAMS D. H	7810190014	50-267	P	WILBON, K. R.	7811220168*	20-548
					7810230200	50-313	J	WILBON, K.R.	7811300174*	50-270
WHEELER, J. R. WHIDDON, D.	7812170112 7810310025	50-16	H P	WILLIAMS C. C. WILLIAMS D. H.	7811200034* 7810190039	50-324 50-368	Q P	WILBON, K. R. WILBON, T. R.	7812010245* 7812050101	50~249 50~246
HHITAKER, M. S.	7811210397	50-395	A	WILLIAMS D. H.	78101900B7	50-368	P	WILGON, F. R.	7812110169	50-344
WHITENER, H. L. WHITENER, H. L.	7811010428* 7810130051*	50-280 50-366	0	WILLIAMS D. H. WILLIAMS D. H	7811060145 7811060175	50-36B 50-313	8	WILSON-K.R. WILSON-B	7812180196* 7812150294*	50-270 50-321
WHITE, J. R.	7811090038*	50-317	a	WILLIAMS D. H	7811080303	50-368	P	WILSON, B.	7812150347*	50-366
WHITE, J.R.	7811300250*	50-334	Q	WILLIAMS O. H.	7810240130	50-368	P	WILSON, K. R.	7812130172+	50-267
HHITE, L.D. White, L.D.	7810160111* 7810160129	50-244 50-244	P P	WILLIAMS, D. H. WILLIAMS, D. H.	7810240098 7810240135	50-313 50-368	P P	HILBON, K. R. HILBON, J. N.	7812190156# 7812200134	50-287 50-322
WHITE, L. D.	7810230256	50-244	Ö	WILLIAMS D. H.	7810250098	50-313	P	WILBON, K. R.	7812190134	50-269
HHITE.L.D.	7810170182	50-244	P	WILLIAMS, D. H.	7810310075	50-368	Ρ	WILEON, J. N.	7812200131	50-355
WHITE, L. D. WHITE, L. D.	7810170257 7810170263*	50-244 50-244	F	WILLIAMS D. H. HILLIAMS D. H	7811070010 7810250149	50~36B 50~36B	9 F	WILBON, K.R. HILT, D.D.	7812270218* 7810240016*	50-287 50-440
WHITE, L. O.	7810180150*	50-244	P	WILLIAMB, C. C.	7811280032*	50-331	a	WILT, D. O.	7811240072#	50-440
HHIYE, L. D.	7810190069*	30-244	P	WILLIAMS, C. C.	7811210024*	50-331	O	WIBNER. C. E.	7811070308#	30-445
MHITENER, H. L.	78121202374	50-250 50-549	0	WILLIAMS O. H	7812010182*	30-160	Q.	WIBNER.C. E.	7812270020*	50-313
WHITE, A. WHITE, A.F.	7811160048 7811200150	50-549	ŏ	WILLIAMS D. H. WILLIAMS D. H.	7810310119 7811130327#	50-313 50-313	R	WITHERS, B. D. WITHERS, S. D.	7811070286 7810170144	50-344 50-344
WHITE, L. D.	7811060088	50-244	F	WILLIAMS. D. H	7811060075	50-313	P	WITHERS.B. D.	7810200107	50-344
WHITE, L. D.	7811070142	50-244	P	WILLIAMB, D. H.	7811030104	50-313	P	WITHERS, B. D.	7810310167	50-344
WHITE, L.D. WHITE, L.D.	7811070182 7811130232	50~244 50~244	P	WILLIAMS D. H. WILLIAMS D. H.	7811030159 TRI1060154	50-313 50-313	P 8	Withers.B.D. Withers.B.D.	7811070193 7811140139	50-344 50-344
HHITE, A.F.	7812040133	50-549	0	HILLIAMB, D. H.	7811080134	50-313	P	WITHERS, B. D.	7812080078	50-344
WHITENER, H. L. WHITE, L. D.	7812140277* 7811140241	50~335 50~244	G P	WILLIAMS.D.H. WILLIAMS.D.H.	7811080174 7811130264	50-349 50-313	P P	Witherb.B.D. Witkowsky.F.P.	7812120149 7810160116*	50-344
WHITENER H. L.	7812180345*	50-324	0	HILLIAMSON, T. O.	7811080179	50-62	P	WITKOWSKY, F. P.	7811160111*	50-334
HHITE, L.D.	7811290245	50-244	J	HILLIAMB, D. H.	7811170065	50-313	F	WITKOWSKY. F. P.	7812110132#	50-334
WHITE, L. D. WHITENER, H. L.	781128021 <i>6</i> 7812070148*	50-244 50-321	P	WILLIAMS D.H. WILLIAMS D.H.	7811030151 7811130190	50-313 50-313	R	HITTEN, A. J. HIZNER, D. Q.	7810140076 7811140232*	50-395 60-316
WHITE, L.D.	7811290179	50-244	P	WILLIAMS D. H.	7811200145	84E-08	В	WIZNER, D. Q.	7812270226+	50-315
MHITE.L.D.	7812050152	50-244	P	WILLIS, E	7811160094*	50-324	R	HOESBNER, J. D.	7810240094*	50-133
WHITE, L.O. WHITE, L.D.	7812050187 7812080123	50-244 50-244	P	WILLIAMS D.H. WILLIAMS D.H.	7811200189 7811090160	50-368 50-368	8 P	WORSENER, J. WOEBBHER, J. D.	7612070296* 7812140039*	50-206 50-312
WHITE, L. D.	7812080128	50-244	P	WILLIAMS, D. H.	7811090170	50-313	F	HOESBNER, J. D.	7812270456*	50~133
SHITE, A.F.	7812270454	50-549	•	WILLIAMS, D. H.	7811200176	50-313	8	WOESSNER, J. D.	7812280358*	50-344
WHITE:L.D. WHITE:L.D.	7812220118*	50-244 50-244	P F	WILLIAMS, D. H.	7811160061	50-348 50-313	8 P	HOFFORD: A. W.	7810230133* 7811140234*	50-322 50-322
HHITE, L.D.	7812290090	50-244	P	Williams D. H. Williams C. C.	7811160129 7812130134*	90-331	a	HOFFORD, A. H.	7811280044	50-322
WHITLER, J. D. WHITLOW, M.	7810240214 7811080068	50-47B 50-55&	H A	WILLIAMB, D. H.	7812060211*	50-349 50-349	G P	HOFFORD, A. H. HOFFORD, A. H.	7812290258+ 7812270478+	50-322 50-322
				NILLIAMB. D. H	7811170207					
WHITMER.C.F. WHITMER.C.F.	7810100039 7810170166	50-321 50-366	F	Williams, D. H. Williams, D. H.	7811210331 7811280209	50-348 50-348	P B	WOFFORD, A. W. WOLCH, H.	7812260136 7811080056*	50-722 50-70
WHITHER, C. F.	7810170170*	50-366	K	HILLIAMB, D. H.	7812210518	50-348	Q	HOLCH, H.	7812140302*	50-70
WHITMER.C.F. WHITMER.C.F.	78101100B9 7810110135	50-321 50-346	Q P	WILLIAMS, D. H. WILLIAMS, D. H.	7811270138 7812130321#	50-348 50-313	8 0	HDLF, J. F. HDLF, J. F.	781 1080219 781 21 400	20-591 20-218
MHITMER, C. F.	7810160104	50-321	P	WILLIAMS, D. M.	7811280232	50-348	P	WOLFE: 8. J.	7810270345+	50-344
WHITMER, C. F.	7810240110	50-321	P	WILL TAMB, D. H.	7811300244	50-348	P	NOLFE, S. J.	7810140033	50-437
WHITMER, C. F. WHITMER, C. F.	7810270101 7811170205	50-366 50-321	J	HILLIAMS, D. H. WILLIAMS, D. H.	7812210220* 7812210226*	50-313 50-34B	a 0	WOLFE, 8, J, WOLFE, 8, J,	7810160221 7810230109	50-344 50-344
WHITHER, C. F.	7811280223	50-321	F	WILLIAMS, Q. H.	7812140059w	50-249	ā	HOLFE . B. J.	7810230240	50-356
WHITMER, C. F.	7811300192	50-424	A	WILLIAMS, D. H.	7812040236	50-313	p p	WOLFE S. J.	7810200243	50-556
WHITMER, C. F. WHITMER, C. A.	7812080098 7812270274	50~366 50-321	A P	WILLIAMS, D. H. WILLIAMS, J. L.	7812120131 7812120105	50-313 50-514	B <b>A</b>	WOLFE, 8. J. WOLFE, 8. J.	7810200239 7810200236	50-556 50-556
WHITTEMORE, F. C.	7810160201	50-322	o .	WILLIB, E	7812150332#	30-324	R	HOLFE, S. J.	7811030258	50-556
HHITTEMORE, F. C.	7810270394	50-322	٨	WILLIAMS, D. H.	7812140124	50-313	P	HOLFE, S. J.	7811010227	50-437
MHITTEMERE, F. C. MHITTEMERE, F. C.	7810200059* 7810230130	50-51 <i>6</i> 50-322	0	WILLIAMS, D. H. WILLIAMS, D. H.	7819280125 7819120136	50-313 50-313	И R	HOLFE, B, J.	7811010413 7811070330	50-466 50-556
HHITTEMORE, F. C.	7810240042	50-511	0	WILLIAMS, D. H.	7819140133	30-368	s	WOLFE, S. J.	7811200129	50~344
HHITTEMORE, F. C. HHITTEMORE, F. C.	7812110201 7812280333	50-322 50-322	9	WILLIAMS D.H. WILLIAMS D.H.	7812190151 7812290160	50-368 50-368	R B	WOLFE, B. J. WOLFE, B. J.	781109020B	30~466 30~466
Will in the control P. V.	(0, ==00000		-	RILLIANION U. M.	LETERALOIDA	40 -m66	9	-140) to a. A.		

ACCE8810N

WICKSTROM 8. WICKSTROM 8. WIESEMANN R. A. WIESEMANN R. A. WIESEMANN R. A. 7811220141 7811220172 7812200145 7812200190 7812200249 50-463 50-463 50-395 50-568 50-582

HHH

WILL IAMBON, T. O.

WILLIAMS, D. H. WILLIAMS, D. H. WILLIAMS, D. H. WILLIAMS, D. H. WILLIAMSON, T. O.

BUBJECT

AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEOORY	<u>'</u>	AUTHOR	ACCESSION NUMBER	
HOLFE.S J.	7811200312	50-437 0	YORE, J. R. YORE, J. R.	7812140315	50-514		ZIEMANN, D. L	7811130297	
WOLFE S J	7811290301 7812010375	50-556 G 50-556 G	YORE, J. R.	7812210306 7812280086	50~592 50~514		ZIEMANN.D.L. ZIEMANN.D.L.	7811140053 7811140055*	
HOLFE, 8 J. HOLFE, 8. J.	7812060047	50-437 G	YORK, R N	7811240048*	50-29	J	ZIEMANN.D. L	78111400574	
MOLFE, B. J	7812110266	50-466 <b>0</b>	YOUNG DAHL R C.	7812040174+	90-255	0	Z1EMANN, D. L.	78111400630	
HOLFE 6. J.	7812130056 7812130060	50-556 T	YOUNG C. YOUNG R.H	7812290268# 7810120096#	3D-336 30-243		ZIEMANNID. L ZIEMANNID. L	7811130321 7811130441	
IOLFE, 9 J IOLFE, 8 J	7812130060 7812130364	50-556 T	YOUNO. R. H	70101601234	30-243	8	ZIEMANNID. L	7811130441 7811150270	
HOLPE, S. J	7812200325	50-556 T	YOUNG R. H YOUNG R.	7810200072* 7810200088*	30-245 50-245	8	ZIEMANNID L.	7811240090	
HOLFE, B J	7812200320	•					ZIEMANN.D L	7811170287	
WOLFE, B. J WOLFE, B. J	7812200324 7812200321	50-556 T 50-556 T	YOUNG R.H YOUNG T	7810230210* 7811220267*	50~245 50~275		ZIEMANN.D.L. ZIEMANN.D.L	7811210223 7811270071	
HOLFE, S. J.	7812280359	30-556 C	YOUNG R. YOUNG R.H.	7811170115	50-245	R	ZIEMANN.D L	7811270D73*	:
WOLF INGER, P. A HONG, H. J	7810170321+ 7812010303+	30-366 9 50-317 0	YOUNG R.H.	7811140191 <b>+</b> 7811160093 <b>+</b>	50-245 50-245		ZIEMANN.D.L ZIEMANN.D.L	7811270081 <b>+</b> 7811270132	:
WONG, H J.	781201D136*	50-219 Q	YOUNG, T.	7812150004+	30-273	0	ZIEMANN.D.L	7811290095	
NONG, H. D	7812060367*	50-333 @	YOUNG R.H. YOUNG R.H.	7811210271* 7812080118*	50-245	8	ZIEMANN.D. L	7811290099*	
HOOD, H HOOD, E. C.	7810300165* 7811030137	50-514 Q 50-309 B	YOUNG + R. H.	7812080118* 7812080129*	50-245 50-245		ZIEMANN.D.L. ZIEMANN.D.L.	7811290104 <b>*</b> 7811280080	
HOOD, J. C.	7810230007	50-498 M	YOUNG R A.	7812210225+	50-275		ZIEMANN. D. L	7811280082	
MOOD, E C	7811030131	50-309 9	YOUNG BLOOD, J.	7812140138	50-592		ZIEHANN D. L.	7811240D86	
HOOD, E. C. HOOD, J. C	7811220233 7812130104	50-309 8 50-498 M	YOUNG R.H.	781224D219+ 781229D212+	50-245 50-245		ZIEMANN.D.L ZIEMANN.D.L.	781127D140 7811290148	
MD00, E. C.	7811220200	50-309 S	ZARAKAB.P.	781106023B*	50-3	0	ZIEMANN. D. L.	7812D6DD69	
H000, J. C	7812280176	30-498 M	ZARAKAS.P.	7812070180	50-3	P	ZIEHANN.D.L.	7812040D07	
WOOD, E. C WOOD, E. C	7812200213 7812200252	50-309 6 50-309 8	ZAVADOBKI.R.W. ZAVADOBKI.R.W.	7811240081 • 7812280348 •	50-302 50-250		ZIEMANN, D. L. ZIEMANN, D. L.	7812040D12*	
HDODARD.J	7811130232	50-556 G	ZECH. @ 0	781122D259	50-272	P .	ZIEMANN, D. L.	7812060377 781206D420	
WOODARD, J. B WOODHEAD, C. P.	7811240D83 7811290D26	50-556 G 50-556 G	zelinbky, W. M Zelli J.	781215D183 7810230275*	50-387 50-346		ZIEMANNID.L. ZIEMANNID.L.	781206D297 781211D135	
HOODHEAD, C. P.	7810110035	50-409 Q	ZELL. J.	7612190116*					
HOODHEAD, C. P.	7810140025	50-556 0	ZIEMANN.D. L	761D25D198	50-346 50-237	P	ZIEMANN.D.L. ZIEMANN.O.L.	7812110139* 781213D156	
HODDHEAD, C. P. HODDHEAD, C. P	781D240036 7811060083	50-409 G 50-556 G	ZIEMANNID L. ZIEMANNID. L	781110DD10 7811100D13#	50-219 50-219	P	ZIEMANN, D. L	781213D334	
WOODHEAD, C. P	7811150229	30-409 0	ZIEMANN.D. L.	78110 <del>9</del> 02D2	50-219		ZIEMANN, D. L. ZIEMANN, D. L.	781213D345 <del>9</del> 7812D7DD28	
WOODHEAD. C. P	7811150277	50-409 0	ZIEMANN.D. L.	7811130304	50-244	P	ZIEMANN.D.L.	781214D316	
HOODHEAD, C. P.	7811280483 7812050D85	50-219 0 50-219 0	ZIEMANNID. L. ZIEMANNID. L.	7810130236 781020D026	20-509 20-509	P	ZIEMANN.D. L.	781214D318*	
ODDHEAD C. P.	7812050254	50-510 0	ZIEMANN.D. L.	781020DD29*	30-206	P	ZIEMANN.D.L. ZIEMANN.D.L.	781214D339+ 7812110004	
HOODHEAD. C. P	7812040319	30-409 0	ZIEMANN.D. L.	7810110070	5D-245	Р	ZIEMANN, D. L.	7812110011	
VOODHEAD, C. P. VOODHEAD, C. P.	7812110286 7812130051	50-466 G 50-466 G	ZIEMANN.D.L. ZIEMANN.D.L.	781D110073# 781D190045	50-245		ZIEMANN, D. L.	781211DD19	
HOODHEAD, C. P	7812130365	30-466 G	ZIEMANN.D. L.	7810270404	50-219 50-213	P	ZIEMANN.D.L ZIEMANN.D.L.	7812110038 781211DD41	
HOODHEAD, C. P. HOODRUFF, R. W.	7812180407 7811280016	50-556 0 50-331 P	ZIEMANN.D.L. ZIEMANN.D.L.	781D27D41D4 781D27D422*	50-213 50-213	P	ZIEMANN, D. L.	7812110D56	
							ZIEMANN, D. L.	7812110061	
10008, D.C.	7810230174÷ 7811020251÷	50-339 R 50-187 P	ZIEMANNIO, L. ZIEMANNIO, L.	7610190138 7610190169*	50-29 50-29		ZIEHANN, D. L. ZIEHANN, D. L.	781211D066 781211D326	
10008, D. C. 10008, D. C.	7811170109* 7812200257*	50-338 R	ZIEMANN.D. L. ZIEMANN.D. L.	7810190182* 7810250D18	50-29	P :	ZIEMANN. D. L.	7812110328	
0008. D. C.	7812200257*	50-33B R 50-33B R	ZIEMANN-D. L.	7810250018 7810250012	50-244 50-206	_ '	ZIEMANN.D.L. ZIEMANN.D.L.	781214D292 781214D304#	
HOODWARD, J. R	7811270193	50-556 G	ZIEMANNID. L	7810310019	30-409	P :	ZIEMANN, D. L.	781214030B+	
KOOLEVER, E. J. KOOLEVER, E. J.	7811280458* 7811070377*	50-412 B 50-412 B	ZIEMANN.D.L ZIEMANN.D.L.	7810310021 781031D024	50-213 50-10	H ;	ZIEMANN, D. L.	7812110055	
OOLEVER E J.	781214D109	50-334 F	ZIEHANNID, L.	781031DD27	50-155	P	ZIEMANN, D. L. ZIEMANN, D. L.	7812130281 781214D024	
KOOLEVER, E. J	7812190144	50-334 F	ZIEMANN.D. L.	781D31D034	50-219		ZIEMANN, D. L.	7912140D27*	
HORTHINGTON, J. D HRIGHT, R. W	7812210386 7810230239	5D-275 B 50-553 G	ZIEMANN.D.L. ZIEMANN.D.L.	7810310037 781031D159	50-245 50-29	H H	ZIEMANN.D.L.	7812140034+	
RIGHT, Q. C.	761113001D*	50-331 G	ZIEMANN.D.L.	7810310173	50-244	н ;	ZIEMANN.D.L. ZIEMANN.D.L.	7812130322 7812130072	
HRIORT, R. W. HRIOHT, Q. C.	7811290323* 7812070078*	5D-366 () 50-263 ()	ZIEMANN.D.L. ZIEMANN.D.L	7810310298 781101DD51	50-219 50-206	P	ZIEMANN.D.L. ZIEMANN.D.L	78121500774 7812150086#	
RIGHT. Q. C.									
4R10HT, R. W.	7812200109* 7812110313*	50-263 G 50-364 G	ZIEMANN.D.L. ZIEMANN.D.L.	7811020392 7811020395*	50-409 50-409		Z 1EMANN, D. L. Z 1EMANN, D. L	781213033D 781219D176	
RIGHT, R. W. WJCIOA, J.	781229007D* 7811090142*	5D-438 @ 50-237 B	ZIEMANN.D.L. ZIEMANN.D.L.	7811080275	50-10	P	ZIEMANN, D. L	7812210275	
NUCTOA, J.	7811090142* 7811090119*	50-237 B	ZIEMANN.D.L.	7811020053 7810270278	50-255 50-255		ZIEMANN.D.L. ZIEMANN.D.L.	781221D301* 781221D312*	
NUCIONIU.	781109D130+	50-237 8	ZIEMANNID.L.	7810270286+	50-255		ZIEMANN, D. L.	7812140279	
AUCIGALU, MUCIGALU,	7811140163+ 7811160125+	50-237 8	ZIEMANN.D. L.	7810270293*	50-255	Ρ ;	ZIEMANN, D. L.	7812140314	
UJCIGA-J.	7811210304*	50-237 B	ZIEMANN.D.L. Ziemann.d.L.	7810310147 781110D105	50-244 50-10	P	ZTEMANN, D. L. ZIEMANN, D. L.	781214D361 781227DD46	
MLLER, O. E.	781208D228	30-461 G	ZIEMANN.D.L.	7811D90039	50-155	P	ZIEMANNID. L.	7812210078	
ANICHKO B. E.	7812080142+ 7811140133+	3D-3D6 P 50-266 P	ZIEMANN.D.L. ZIEMANN.D.L.	7811070071	50-155		ZIEMANN, D. L.	781213DD85	
ELDERMAN, J. C.	7811200128	30-466 Q	ZIEMANNID, L.	781109D088* 7811070302	50-155 50-213	P ;	Z 1EMANN, D. L. Z IEMANN, D. L.	7812150093 7812150099	
/IN-1.T. /IN-1.T.	78110900064 7811090DD7*	50-341 G 50-341 G	ZIEMANN.D.L. ZIEMANN.D.L.	7811070307+ 7811070313+	50-213 50-213	P	ZIEMANN, D. L.	781215D1Q1	
IN: I. T.							ZIEMANN, D. L.	7812130105	
IN t. T.	7811020111+ 7811170264+	50-315 G 50-359 G	ZIEMANN.D.L. ZIEMANN.D.L.	7811080 <b>334</b> 7811100 <b>02</b> 7	50-237 50-29		ZIEMANN:D L. ZIEMANN:D.L.	7812150108 7812150111	
YIN, 1. T. Yin, 1. T.	7811140054* 7811300260*	50-329 O	ZIEMANN, D. L.	7811100141	50-206	è :	Z IEMANN, D. L.	7812150115	
YIN, 1, T.	78122101314	50-358 G 50-266 Q	ZIEMANN.D.L. ZIEMANN.D.L.	7811100152 7811100156	50-244 50-219		ZIEMANN, D. L. ZIEMANN, D. L.	781221001B 7812210D21	
YORE, J. R.	7810230030+	50-70 Q	ZIEMANN, D. L.	7811100162	50~409		ZIEMANN, D. L.	7812210031	
YORE, J. R. YORE, J. R.	781014012B 7810260195	30-358 Q	ZIEMANN.D.L.	7811130047	50-155	P	ZIEMANN, D. L.	7812210034	
YORE, J. R.	7811170009	30-341 Q 30-450 Q	ZIEHANN.D.L. Ziehann.d.L	7811140014 7811060164	50-10 50-219		ZIEMANN.D.L. ZIEMANN.D.L.	7812210047 7812210050+	
YORE, J. R.	7812040346	50-522 Q	ZIEMANN.D. L.						

EMANN, D. L	7812210095	20.514	P	ZUFELY. E	7810130132*	50~333	R	Ī
EMANN.D.L	7812260289*	50-249	Р	ZUFELT. E	7811140123*	50~333	R	
EMANN.D L	7812270048	50-219	P	ZUFEL T. E.	7812150274+	50~333	Ð	
EMANN. D. L.	7812270039	50-155	P	ZULL, L M	7810170114	50-333	P	
EMANN, D. L.	7812270147	50-255	P	ZULL. L. M	7812120082*	50-333	P	
MMERMANN, C. J.	7812010205	30-395	A	ZULLA, S 6	7812150241*	30-286	ĸ	
MMERMAN, R P	7811290389#	50-272	a	ZWETZIG.O B	7810200228	50-289	Q	

ZWETZIO.O B.

7812280267\* 50-269

## CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	Y	AUTHOR AFF IL IATION	ACCESSION NUMBER	CATEGOR	Y
	7812010042+	50-471	0		7811140152	50-34B	P
Abbatt, H. B	7812270075*	30-4B3	ā		7811140225	50-34B	8
Adams. D. B.	7812270076*	50-485	ë		7811140233*	50-348	8
	7812270081	50-485	ë		7811140237+	50-348	8
Advisory Council on Historic Preservation		50-546	A		7811140242+	50-348	8
Agriculture, Dept of	7812140168	50-361	$\mathfrak{p}$		7811140246*	50-348	8
Air Force Dept. of	7810260147	50-320	P		7811140251+	50-348	8 R
All forces pope, or	7811030174	50-320	P	•	7811160085	50-34B	R
	7812270033*	50-320	•		7811160090+	50-348	ā
Akin. Qump. Haver & Feld	781026000B	50-478	M		7811170038	50-340	
	7812040050	50-498	м		7811210176	50-348	R
	7812270416	50-498	H		7811210179*	50-34B	R
Alebama Power Co	7810100066	50-34B	8		781121025B	50-34B	9
Alegama rower co	7810100072*	50-348	8		7811210355	50-348 50-348	9
	78101000B5	50-348	B		7811210358+		
	7B101000B6*	50-348	8		7811270176	50-34B 50-34B	P
	7810110102	50-346	P		7811290258	50-348	8
	7810130068	50-348	0		7811280247 7811280272*	50-348	8
	7810180079	50-348	R		7811280283	50-348	P
	7810180082*	50-348	R				
	7810180097	50-34B	8		7811280336	50-34B	8
	7810180100*	50-348	8		7811280339+	50-348	8
	7810180145	50-349	8		7811280342*	50-348 50-348	8
	7810180149*	50-348	8		7811280348 7812010253	50-348	9
	7810180151	50-348	В		/815010833		
	7810180154#	50-34B	8		7812010254	50-34B 50-34B	9
	7810200077	50-348	8		7B12030010+	50-348	P
	7810200091*	50-348	9		7812050159	50-346	à
	7810200085	50-348	8		7812070022 <del>0</del> 7812080224	50-348	8
	7810200087#	50-34B	8		1818080114		
		50-348	8		7812110134	50-348	8
	7810250112	50-346	8		7812110138*	50-349	ō
	7810250114*	50-34B	8		7812110307	50-364 50-348	P
	7810250141 7810250145*	50-346	ŝ		7B12130131	50-348	á
	7810250229	50-348	ā		7812140117	20-346	
			_		7812180351+	50-348	a
	7810250239	50~348	0		7812200163	50-348	8
	7810270311	50-34B	8		7812200165+	50-348	8
	7810310070	50-348	ρ		7812210202	50-348	R
	7810310131 7810310135	50-348 50-348	8		7812210212+	50-348	R
	*=		•		7812270169	50-348	
	7811020351	50-364	0		7812270278	50-348	
	7811070229	50-34B	Đ.		7812270283+	50-348	
	7811080140	50-349	F		7812270306	50-348 50-348	
	7811080159 7811090111	50-348 50-348	F		7819270308	30-340	•
					7812270309+	50-348	
	7811090111	50-349	f		7B12270311+	50-34B	
	7811090183	50-348	8		78122703134	50-348 50-348	
	7811090187#	50-348	8		7812290127	50-392	
	7811090192* 7811090196*	50-348 50-348	8	Allen, D. R.	7B11070315		
		-		Allied General Nuclear Services	7812180144	50-332	
	7811090200*	50-348	8		7812180147	50-332	
	7811130204	50-364	G	American Electric Power Co Inc.	7810120062	50-316 50-314	
	7811130226	50-348	Q P	buttacen erretter	7810120067#	50-315	
	7811140111	50-348	P		7811080138	20-312	
	7811140152	30-348	•				

Author Affiliation	ACCEBBION NUMBER	BUBJECT CATEODRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY
American Nuclear Society Argonne National Laboratory	7811210446 7811020298• 7811130333• 7810230382 7812030222	50-315 ( 50-57 F 50-284 F 50-267 ( 50-329 I		7811050156# 7811050158# 7811050150# 7811050175 7811050180#	30-348 8 30-313 8 50-313 8 50-313 8
	7812050222 7812050225 7812050225 7812050227 7812050227	50-329 I 50-329 I 50-329 I 50-329 I 50-329 I		7811060183* 7811060189* 7811070010 7811080136 7811080176	50-313 8 50-313 8 50-368 8 50-313 P 50-368 P
	7812050232 7812050232 7812050239 7812050239 7812050244	50-329 1 50-329 1 50-329 1 50-329 1		7811080305 7811080310# 7811090160 7811090170 7811130190	50-368 P 50-368 P 50-368 P 50-313 F 50-313 P
	7812050244 7812050250 7812050250 7812050255 7812050255	50-329 1 50-329 1 50-329 1 50-329 1		7811130284 7811130284 7811130327* 7811140061 7811160062	50-313 P 50-313 P 50-313 0 50-368 8 50-313 P
Arizana Public Service Co.	7812200053 7810300181 7810310140 7810310140 7810310288•	50-70 50-528 50-592 50-592 50-528		7811160063* 7811160064* 7811160121 7811160129 7811170065	50-348 8 50-313 P 50-368 P 50-313 P 50-313 F
	7810310294• 7810310365• 7811060087 7811090086 7811090086	50-528 50-528 50-592 50-592 50-592		7811170207 7811200145 7811200149* 7811200174 7811200180*	50-368 P 50-368 8 50-368 8 50-313 8 50-313 8
	7811150130+ 7811270150 7811270150 7812110126 7812170071	50-528 6 50-592 6 50-592 6 50-528 6		7611200189 7611200191# 7611210125# 7611210167 7611210192#	50-368 8 50-369 8 50-313 0 50-368 8 50-368 8
	7812190071 7812190071 7812190073* 7812190073* 7812190073*	50-528   1 50-528   1 50-528   1 50-528   1		7811210331 7811220134 7811220130 7811270138 7811270142*	50-348 P 50-348 P 50-348 P 50-348 B 50-348 B
	7812210114+ 7812210114+ 7812210114+ 7812210119+ 7812210119+	50-528 6 50-528 6 50-528 6 50-528 6		7811270144* 7811270146* 7811270149* 7811280208 7811280211*	50-368 8 50-368 8 50-368 8 50-368 8
Arizona, State of Arkansas Power & Light Co.	7812210117> 7812210132 7812140138 7810100018 7810100023	50-528 8 50-592 8 50-592 8 50-368 8 50-368 8		7811280232 7811300244 7812040236 7812060211* 7812120131	50-368 P 50-368 P 50-313 P 50-368 0 50-313 B
	78101000B1 7810110137 7810110139* 7810110301* 7810120114	50-313 6 50-368 6 50-368 6 50-313 6		7812120137* 7812120138 7812120142* 7812130321* 7812140124	50-313 B 50-313 R 50-313 R 50-313 G 50-313 P
	7810170143 7810170146* 7810170149* 7810170190 7810170196*	50-313 8 50-313 8 50-313 8 50-368 8	3	7812140155 7812140164* 7812180120 7812180163 7812190151	50-348 8 50-368 8 50-313 P 50-368 P 50-368 R
	7810180091 7810180117 7810190039 7810190087 7810190096	50-572 / 50-368 / 50-368 / 50-368 / 50-368 /		7812190152* 7812200226 7812200229* 7812210135 7812210220*	80-368 β 50-368 β 50-369 β 50-313 0 50-313 0
	7810200067 7810200070* 7810230200 7810240098 7810240098	50-313 F 50-313 F 50-313 F 50-313 F		7812210226* 7812210318 7812270247 7812270249* 7812270299	50-368 0 50-368 0 50-313 9 50-313 9 50-368 8
	7810240130 7810240135 7810250056 7810250078 7810250149	50-368 F 50-368 F 50-572 E 50-313 F 50-368 F		7612270304* 7612270310* 7612280127 7612280127 7612270140	50-368 8 50-368 8 50-313 K 50-313 R 50-368 8
	7810310075 7810310119 7811030106 7811030151 7811030159	50-368 F 50-313 F 50-313 F 50-313 F	Armedillo Goslition of Texas	7812270164* 7812060038 7812060041 7811020381 7811280089	50-368 8 50-466 9 50-464 9 50-329 9 50-437 9
	7811060075 7811060145 7811060147• 7811060151• 7811060154	50-313 F 50-368 S 50-368 S 50-368 S 50-313 S	Baker & Botte	7810120077* 7812200136 7810130091 7810130195 7810270322	50-329 A 50-13 G 50-466 G 50-466 Q 50-468 Q

7812040024 7812040331 7812040367 7812050037	50-466 50-466 50-498 50-466	0000	
7812050046 7812070058 7812110256 7812120224 7812130026	50-466 50-466 50-466 50-466 50-466	00000	
7812130219 7812180258 7810300062 7810270297 7810100051	50-466 50-445 50-70 50-498 50-317	0 M 0 M 8	Bencroft, M. H
7810100058+ 7810110169 7810110174+ 7810130173 7810130176+	50-317 50-317 50-317 50-317 50-317	8 8	Bangor Hydro-Electric Co. Batto-lie Memorial Institute Batto-lie Memorial Institute. Columbus Laboratories Bechtel Corp.
7810170162 7810180073 7810230148 7810230162 7810230162	50-318 50-318 50-317 50-317 50-317	P P F F	Bechtel Power Corp. (subs. of Bechtel Corp.)
7610230178 7810230178 7610230162> 7610230182> 7810230246	50-317 50-317 50-317 50-317 50-318	R R R R	
7810250143 7810260202 7810270235 7810270240* 7810310102	50-317 50-317 50-317 50-317 50-317	P 9 9	Black & Veatch Blum & Bheely Boeing Co.
7810310105* 7810310197 7810310200> 7810310209 7810310216*	50-317 50-317 50-317 50-318 50-318	8 8 8	Boston Edison Co.
7810310271 7811010113 7811010116* 7811030112 7811030117*	50-317 50-317 50-317 50-317 50-317	F 8 6 8	
7811040133 7811040155 7811040161* 7811070030* 7811130144	50-318 50-318 50-318 50-317 50-318	8 9 9	
7811130211 7811130214* 7811140164 7811140170* 7811150155	50-319 50-318 50-318 50-318 50-317	9 9 8 <b>9</b> F	
7611150189 7611150269* 7811130269* 7811170121 7811170165	50-317 50-317 50-317 50-317 50-318	F Q P P	
7811170171* 7811170179 7811170187* 7811170197 7811200206	50-318 50-318 50-318 50-317	8 8 8 F	
7811200206 7811210407 7811210409* 7811240183 7811240183	50-317 50-317 50-317 50-317 50-317		
7811240214 7811240214 7811240215 7811240217* 7811290264	50-317 50-317 50-317 50-317	P R R	
7811290267* 7811300196 7811300197* 7811300211 7811300223*	50-317 50-317 50-318	8	
7812010295* 7812010295* 7812080096 7812080125 7812080125		9	

Baldwin, W. A. Balough, R. C.

Haltimore Oas & Electric Co.

7812130170

7812130174

7812130183

7812130187+

7812130189

7812130194+

7812200261 7812220076

7812220076

7812220077+

7812220077\*

7812260244 78122602484

7812220040+

7811070145+ 7810250121 7810270097+

78101601970

7810120083+

7810120091

7810170194

7810200075\* 7811090149\* 7811090149\*

7811090156\*

7811090136

7811100062+ 7812110273+

7B10310051

7811090060 7811290350

7812190112

7810170136

7810170160

7810170164\* 7810180113 7810180130 7810180131\* 7810230205

7810230203 7810250107

7810270105

7B1031013B

7810310163\*

7811070004+

7811070185 7811080152 7811080136\*

7811090140

7811090161 7811090168\*

7811140132

7811140193

7B11140168#

7811140200 7811140207 78111402124

7811130168 7811210263

7811210269# 7811210326

7811210341 7811210345# 7811270163

7811280333

78112803350

7812010050# 7812010059# 7812040173

7812040176\* 7812030183 7812030192\*

7812050228 7812060223

7812080185 7812110166 7812120135

78121201414

7812180168

78121801724

7812200183 7812200185#

50-318

50-318 50-318

50-318

50-317 50-317 50-317 50-317

50-317

50-317 50-317 50-318 50-318

30-358

50-360

50-329 50-387

50-344

50-250 50-250 50-329

50-329

50-327 50-387 50-482 50-556

50-369 50-369

50-320 50-293

50-471

50-471 50-293 50-293 50-293

50-293

50-273

50-293

50-293

50-471

50-293 50-293 50-293

50-471

50-293

50-293 50-293 50-293

50-293

50-471 50-293 50-293 50-293

50-293 50-471 50-293 50-293 50-293

50-293 50-293 50-471 50-471 50-293

50-293 50-293 50-293 50-293 50-293

50-293 50-293 50-293 50-293

50-293

50-293

8

8

8

8

8

R

R

8

8

J R

8

P

A

8

AB

e

0

HP

A

APARI

I P P

В

8

9981

8

9

K 9

8

9 F

R

9 8

8

0

g

P

9 9 9

A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR Appiliation	ACCESSION NUMBER	EUBJEC CATEGO	
Broothaven National Laboratory	7812210258 7812260218 7812260223• 7810110076• 7810270417•	50-293 50-293 50-293 50-245 50-213	P K K P		7811160072* 7811160094* 7811160094* 7811160119 7811160120*	50-325 50-324 50-324 50-261 50-261	8 R R R
Burndy Husty C-E Power Systems	7812120119 7812120123* 7812130386 7812270068 7811130099*	50-250 50-250 50-305 50-358 50-309	F P P A		7811140132 7811140133* 7811140135 7811140137 7811140138	50-325 50-325 50-324 50-325 50-325	8 8 8 8
California Polytech State Univ. California, State of California, Univ. of, Berkeley	78120700&& 78110&0044* 7811220094 7812270171 7811300215	50-394 50-582 50-592 50-275 50-433	9 9 1 1		7811160141* 7811160144* 7811170127 7811170209 7811170213*/	50-325 50-325 50-261 50-325 50-325	8 0 8
California, Univ. of, Davis California, Univ. of, Irvine California, Univ. of, Los Angeles California, Univ. of, Ban Diago Carolina Environmental Study Group	7810140045¢ 7812060145 7812080099 7811010388¢ 7811080060	50-213 50-326 50-142 50-275 50-369	U 8 P 0		7811170238* 7811170238* 7811220177 7811220160* 7811220183	50-324 50-324 50-325 50-325 50-325	9 9 9
Carolina Power & Light Co.	7810100029 7810100032+ 7810100043 7810100048+ 7810100049	50-324 50-324 50-261 50-261 50-325	8 8 8		7811220187* 7811280226 7811300165 7812010232 7812070065*	50-324 50-400 50-400 50-261 50-261	8 6 8 9
	7810100053# 7810110108 7810110110 7810110110 7810110227#	50-325 50-261 50-324 50-324 50-261	8 P P P		7812070165 7812070168* 7812070175 7812070181* 7812070187	50-325 50-325 50-324 50-324 50-400	9 8 8
	7810110242* 7810130121 7810130121 7810130122 7810130122	50-324 50-324 50-324 50-324 50-324	Q R R		7812070188* 7812070188* 7812070188* 7812070188* 7812070214	50-400 50-400 50-400 50-400 50-325	8 8
	7810130124* 7810130143 7810130143 7810130152 7810130156*	50-324 50-324 50-325 50-325	R P B B		7812070217* 7812080127 7812080130* 7812110133 7812130115	50-325 50-325 50-325 50-261 50-324	8 8 F Q
	7810130158 7810130162* 7810130177 7810130181* 7810130189	50-325 50-325 50-324 50-324 50-325	9 8 8		7812130251* 7812130296* 7812130383 7812140158 7812140160*	50-261 50-324 50-400 50-325 50-325	9 9
	7810150147 7810150149* 7810190270 7810230020* 7810230243	50-261 50-261 50-261 50-261 50-324	R R G B		7812140143 7812140145# 7812150330 7812150332#	50-261 50-861 50-324 50-324 50-324	8 8 8 R
	7810230146# 7810230193 7810230193= 7810240127 7810260249	50-324 50-324 50-324 50-324 50-324	8 8 6 0		7812150348 7812150351+ 7812180334+ 7812180334+ 7812180334+	50-261 50-261 50-400 50-400 50-400	R Q Q Q
	7810260249 7810270111 7810270111 7810270123 7810270147	50-324 50-324 50-324 50-400 50-261	9 9 4 F		7812180334* 7812180335 7812170118 7812170123* 7812200178	50-400 50-324 50-261 50-261 50-324	0 J J
	7810270215 7810270226* 7810300140 7810310122 7810310123	50-261 50-261 50-400 50-261 50-261	8		7812200199# 7812200200 7812200201# 7812210181 7812210185#	50~324 50-324 50-324 50-325 50-325	6 8 8
	7810310127* 7810310139 7810310142* 7810310143 7810310153#	50-261 50-324 50-324 50-261 50-261	8 8 8		7812210187 7812210192* 7812210218 7812210222* 7812210319	50-325 50-325 50-325 50-325 50-400	8 8 9
	7810310210 7810310217 7810310219* 7810310222* 7810310232	50-261 50-324 50-261 50-324 60-324	8 8 8		7812210319 7812270192 7812270207 7812270257 7812270263*	50-400 50-324 50-324 50-261 50-261	9 8 8
	7810310236* 7811090013* 7811090109 7811090186 7811090191*	50-324 50-324 50-324 50-241 50-261	8 9 8 8	Cathey, Goodwin & Hamilton	7812270288 7812270292* 7812270298 7812270303* 7810240001	50-325 50-325 50-324 50-324 50-313	9 8 8 8
	7811090194 7811090197* 7811140216 7811140088 7811160091	50-325 50-325 50-400 50-325 50-324	9 8 8 8 8	Cetholic Univ. Center for Lew in the Public Interest	7810170186 7810160135 7810190262* 7810190262* 7810190267*	50-77 50-275 50-275 50-275 50-275	P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT	<u>′</u>	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOUR	
Charry, M. M./Cherry, Flynn & Kanter	7810190267* 7810190269* 7810190269* 7812010048 7812060126	50-275 50-275 50-275 50-275 50-279	e 0 0 0	Commerce Dept. of. National Bureau of Standards Commonwealth Edison Co.	7812060286* 7810100025 7810100027 7810100035 7810100078	50-184 50-295 50-237 50-373 50-10	PPAR
Chickering & Gregory	7812060126 7812060172+ 7812060172+ 7812280340+ 7811060050	50-329 50-329 50-329 50-329 50-361	0 0 0 0 0		7810110277 7810110291* 7810120034 7810120080 7810120080	50-10 50-324 50-295 50-265 50-237	9977
Cincinneti gas & Electric Co.	7812010142 7812130093 7810110157 7811010169 7811010171	50-206 50-206 50-358 50-358 50-358	F Н А К		7810120080 7810120080 7810130165 7810130170* 7810170172	50-245 50-245 50-237 50-237 50-255	F F B B
	7811070370 7811090049 7811210170 7811220008 78122060016	50-358 50-358 50-358 50-358 50-358	0 К Ј О		7810170180# 7810170181 7810170184 7810170184 7810170185	50-265 50-295 50-295 50-295 50-237	9 9 B P
	7812070119 7812070147 7812150306 7812190084 7812190146	50-358 50-358 50-358 50-358 50-358	К К Г А		7810170187* 7810170187* 7810170187* 7810170197 7810170193	50-295 50-295 50-295 50-247 50-245	8888
	7812200148 7812200214 7812200218• 7812200228 7812210163	50-358 50-358 50-358 50-358 50-358	A K G		7610170202* 7810170203* 7810170204 7810170207 7810170208	50-265 50-249 50-10 50-295 50-304	8 8 8
Citizens Against Nuclear Dangers	7812270191 7612270305 7811010435* 7812260003 7612260008*	50-358 50-358 50-387 50-387 50-387	K Q Q		7810170211* 7810170212* 7810170214 7810170216* 7810170218	50-304 50-295 50-295 50-10 50-304	8 8 8
Citizens Concerned About Nuclear Power. Inc.	7812110054 7812110054 7812110057* 7812110057*	50-498 50-498 50-498	o o o		7810170219 7810170222* 7810170223* 7810170225 7810170227*	50-298 50-304 50-295 50-295 50-295	8 8 8
Citizens United for Responsible Energy Citizens for Energy & Employment	7810240023 7810240023 7811080282 7812130191 7812130202*	50-331 50-341 50-341 50-341 50-341	0		7810170228* 7810170231 7810170232 7810170234* 7810170235*	50-295 50-295 50-254 50-295 50-254	8 8 8
Citizens to Preserve the Hudson Valley Cleveland Electric Illuminating Co.	7810100007 7810100007 7810110261* 7811130230* 7811130230* 7811270022	50-549 50-440 50-440 50-346 50-346 50-440	A G M M		7810170239 7810170241 7810170242* 7810170246* 7810170231	50-304 50-275 50-304 50-275 50-304	8 8 8 8
Cleveland, OH	7811270281 7811270281 7811270281 7812070230# 7812150279 7811020037	50-440 50-440 50-440 50-346 50-344	G G B M		7810170253* 7810180049* 7810180050 7810180060 7810180086	50-304 50-295 50-295 50-295 50-373	8 8 9 9
Consistion for Safe Power  Const Guard, Transportation, Dept. of	7811020235 7812260332 7810240003 7810240086 7811200083*	50-344 50-344 50-437 50-437 50-437	Q Q A A		7810180090* 7810180101 7810180104* 7810190148 7810190148	50-373 50-10 50-10 50-10 50-10	JRRPP
	7811200102* 7811200276* 7811270166 7811270261 7812130387*	50-437 50-437 50-317 50-437 50-344	A P A P		7810200086 7810200092 78102000974 7810200113 7810200113	89-10 50-237 50-237 50-295 50-295	9 8 9
Colt Industries, Inc.  Combs.Archer & Peterson	7811090134* 7811090135* 7811090136* 7811220237	50-423 50-423 50-423 50-466	8 9 8		7810230181 7810230181 7810230194 7810230256#		A A A A
Combustion Engineering, Inc.	7812040316 7810190089* 7810190090* 7810190092* 7810300244	50-466 50-368 50-368 50-368 50-470	9 P P X		7810230238* 7810240100 7810240101 7810240102* 7810240116	50-247 50-373 50-249 50-249	. 6
	7811160077 7811290143 7811300213+ 7812120074 7812120152+		A G K K P		7810240124 7810240134 7810240141 7810240148 78102401504 7810240158	80-249 50-249 50-10	
Cammerce, Dept. of	7812270163 7812270166* 7812290278* 7812290278*	50-470 50-407	К К		7810250102 7810250102 7810250111 7810250153	50-295 50-295 50-254 50-10	

AUIHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTI AFFILI	ACCESSION NUMBER
	7810270180 7810270229 78102702314 7810270234 7810270236	50-237 50-249 50-249 50-237 50-237	9 8 8 8		 781121038B 7811210392* 7811210410 7811220031 7811220033*
	7610270287 7610270296+ 7610270302 7610270303+ 7610300097	50-237 50-237 50-249 50-249 50-295	00000		7811220033+ 7811240127 7811240129+ 7811240135 7811240139+
	7810300097 7810300150 7810310093 7811010009 7811010009	50-295 50-373 50-10 50-10 50-295	9 0 9 P		7811240145 7811240147* 7811240153 7811240156* 7811240175
	7811010049 7811010131+ 7811010141 7811010141 7811020258	50~295 50~295 50~295 50~295 50~373	P R R R K		7811240176 7811240177* 7811240178* 7811240179 7811240181*
	7611020259+ 7811020322 7811020322 7811020322 7811020322	50-373 50-10 50-10 50-10 50-10	K P P P		7811240192 7811240193* 7811240195 7811240196* 7811240197
	7811020322 7811020375# 7811020375# 7811030143 7811030145#	50-10 50-254 50-254 50-237 50-237	P F S S		7811240178* 7811240200 7811240201* 7811240203 7811240204*
	781 1030161 781 1030161 781 1030161 781 1030161 781 1030161	50-10 50-10 50-10 50-10 50-10	P P P P		7811240205 7811240204* 7811240207 7811240208* 7811240210
	7811030184 7811030191# 7811060180 7811060189 7811060162#	50-249 50-249 50-254 50-249 50-249	8 9 8 8		7811240211* 7811240212 7811240213* 7811240218 7811240220*
	7811070118 7811070118 7811070148 7811070168 7811090113	50-254 50-254 50-275 50-275 50-10	8 8 8		7811240221 7811240222 7811240223* 7811240224* 7811240227
	7811090116 7811090119# 7811090124# 7811090125 7811090126#	50-237 50-237 50-10 50-249 50-249	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		7811240229* 7811240237 7811240239 7811240240* 7811240241*
	7811090129 7811090130* 7811090138 7811090142* 7811130202	50-237 50-237 50-237 50-237 50-295	9 9 9 0		7811270091 7811270158 7811270170 7811280194 7811280149*
	7811130202 7811140099 7811140109 7811140119 7811140119	50-295 50-10 50-237 50-10 50-10	0 R P R		7611280213 7811280213 7811280213 7811280213 7811280213
	7811140160 7811140163* 7811140169* 7811140173 7811140173	50-237 50-237 50-10 50-373 50-237	8 8 R H 9		7811280213 7811280244 7811280244 7811280244 7811280244
	7811140199# 7811140203 7811140213# 7811140215 7811140220#	50-237 50-237 50-237 50-237 50-237	! 8 9 9		7811280264 7811280264 7811280269* 7811280269* 7811280278
	7611140222 7611140227# 7611160112 7811160113# 7811160122	50-249 50-249 50-237 50-237 50-237	6 3 8 9		7811280301 7811280309* 7812040190 7812040191 7812040195*
	7811160125* 7811210177 7811210181* 7811210257 7811210301	50-237 50-237 50-237 50-237 50-237	\$ 8 8 P 9		7812040201 7812040201 7812040201 7812040201 7812040204+
	7611210304# 7611210314 7611210333 7811210339# 7811210356	50-237 50-454 50-249 50-249 50-237	S A S C S		7812040204* 7812040204* 7812040204* 7812040207* 7812040208
					•

CAT

20-5 20-5 20-1 20-1

50-2

50-2 50-2 50-2

50-3 50-3

50-3 50-3 50-2 50-2

50-2 50-3

50-2 50-2

20-5

50-2

50-3 50-3

50-2

50-2 50-2 50-2

50-2

50-2 50-2 50-2 50-2

50~2 50~2 50~2 50~3

50~2 50~2 50~2 50~2

50-2 50-2 50-2 50-2 50-2

50-2 50-1

50-2 50-2

50-1

50-1 50-1

50-1

50-1

50-1 50-2 50-2 50-2

50-2 50-2 50-2 50-2

50-2 50-2 50-2 50-2

50-4 50-4 50-4

30-4

50-4 50-4 50-4 50-4

AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCEBBION REMUN	SUBJE
AFFILIATION	7812040208 7812040210* 7812040210* 7812040212 7812040212	50-454 C 50-454 C 50-454 C 50-456 C			7812200219 7812200235 7812200241* 7812200241* 7812210189	50-254 50-254 50-254 50-254 50-237
	7812040214* 7812040214* 7812030100 7812030100 7812030107		; (		7812210195# 7812210203 7812210213* 7812210214 7812210217	50-237 50-275 50-275 50-295 50-304
	7812050107 7812050107 7812050107 7812060020 7812060020	50-10 50-10 50-254	P P Q Q		7812210219# 7812210221# 7812210227 7812210228# 7812210234	50-295 50-304 50-295 50-295
	7812040059 7812040153 7812040153 7812070121 7812070121	50-373 50-373 50-454	G F F K K		7812210239* 7812210242 7812210244 7812210245* 7812210252*	50-249 50-249 50-249 50-249
	7812070121 7812070121 7812070172 7812070172 7812070185	50-454 50-237 50-237	K K F K		7812220093 7812220093 7812270225 7812270225 7812270261	50-23 50-25 50-25 50-25
	7812070185 7812070185 7812070185 7812070211 7812070211	30-454 50-454 50-295	K K K P P		7812270271* 7812270284 7812270289* 7812270300 7812270302#	50-23 50-24 50-23 50-23
	7812070223 7812080095 7812080114 7812110109 7812110109	50-440 50-295 50-10 50-373 50-373	8 P P A A	Connecticut Yankee Atomic Power Co.	7812270327 7612280280* 7812270210 7812270215* 7810130166	50-10 50-23 50-23 50-23 50-21
	7812110124 7812110129* 7812110144 7812110147* 7812110131	50-295 50-295 50-295 50-295 50-295	8 8 8		7810130169* 7810180134 7810180136* 7810240093 7810250106	50-21 50-21 50-21 50-21
	7812110154* 7812110157 7812110159* 7812110160 7812110161	50-295 50-295 50-295 50-295 50-295	8 8 8 8		7810250110* 7810260171 7810260182 7811030097 7811060103	50-21 50-21 50-21
	7812110163# 7812110164# 7812110175 7812110176 7812110178#	50-295 50-295 50-295 50-254 50-254	8 6		7811060107# 7811170208 7811170217 7811210282 7811210284#	50-2 50-2 50-2 50-2
	7812110179 7812110180+ 7812110181 7812110182+ 7812110183+	50-295 50-295 50-254 50-295 50-254	8 8 8		7811210308 7811210311# 7811210315# 7811210385# 7811240163	50-2 50-2 50-2 50-2
	7812120070 7812120130 7812120134* 7812120155 7812120155	50-237 50-249 50-249 50-10 50-10	P 9 P P		7811300212 7812050134 7812050160 7812050164* 7812180142	50-2 50-2 50-2 50-2
	7812120195 7812120195 7812120195 7812130126 7812130184	50-237 50-237 50-237 50-456 50-10	# # # #	Connecticut, State of	7812210101 7812210201 7812210204* 7812220061 7810270157	50-2 50-2 50-2 50-2
	7812130186* 7812150230 7812150230 7812150270 7812150272*	50-454 50-454 50-237	R K K B	Conner, Maore & Corber	7810270313 7810310017 7811030038 7811220159 7811270066	50- 50- 50- 50- 50-
	7812180143 7812180148 7812180132 7812180174 7812180173	50-249 50-249 50-3 50-10 50-249	8 8 8		7812040351 7812130025 7812130279 7812180301 7812180400	50- 50- 50- 50-
	7812180177 7812180178 7812180210 7812180223 7812180228	50-249 50-10 50-237	8 C 2 8	Consolidated Edison Co. of New York	7812280197 7810100067 7810100071 7810110099 7810110153	50-
	7812170107 7812170107 7812170107 7812170107 7812270107	50-10	31118		78:0110155 78:10160105 78:10160110 78:10160113 78:10160138	* 50-

7810160165 7810200064 7810200064 7810200064	50-3 50-3 50-3	ड १ १	7810230192 7810230192 7810230192 7810230194#	50-329 50-329 50-329	K K K
7810230149 7810230150+ 7810240108 7810240108 7810240108	50-247 50-247 50-3 50-3 50-3	R P P	7810230196# 7810250065 7810250096 7810250099 7810250099	\$0-329 \$0-155 \$0-155 \$0-329 \$0-329	% P B A A
7811040238* 7811070120 7811070157 7811070163* 7811070221	50-3 50-3 50-247 50-247 50-247	Q P P P	7810250100* 7810250100* 7810270075 7810270142 7810270148	50-329 50-329 50-155 50-329 50-329	A A P R K
7811070230+ 7811070274 7811140255+ 7811170160 7811200155	50-247 50-247 50-3 50-3 50-247	8 F Q P F	7810310130 7810310133* 7811010165 7811020212 7811020218*	50-155 50-155 50-155 50-155 50-155	9996
7611200161 7811210340 7811210340 7811210344* 7611220076	50-3 50-3 50-3 50-3 50-3	F R R R J	7811030136 7811030139# 7811060084 7811070149 7811070183	50-155 50-155 50-155 50-329 50-255	8 6 C 8
7811220076 7811220153 7811220153 7811280260 7811280270*	50-3 50-3 50-3 50-247 50-247	ଧ ନ ଞ ଞ	7811070204* 7811070210 7811070217 7811070218* 7811070224*	50-255 50-255 50-155 50-255 50-155	8 8 8 8
7812010206 7812010206 7812040229 7812070180 7812070180	50-3 50-3 50-247 50-3 50-3	R R S P P	7811070336 7811080015 7811090143 7811090203 7811090205#	50-329 50-329 50-329 50-155 50-155	G A A 8
7812070180 7812070182* 7812070182* 7812070182* 7812070182*	50-3 50-3 50-3 50-3 50-3	P P P P	7811090223* 7811090226* 7811090229* 7811090234* 7811140146	50-155 50-155 50-155 50-155 50-155	8 8 8
7812190075 7812190102 7812190121 7812190131* 7812190174	50-247 50-247 50-247 50-247 50-247	P F S 9 P	7811140147 7811140148# 7811140150# 7811140151# 7811140223	50-255 50-255 50-155 50-155 50-255	R 8 8
7812190174 7812190174 7812190180# 7812190180# 7812190180#	50+3 50-3 50-3 50-3 50-3	P P P P	7811140228# 7811150080 78(1150080 7811150158 7811170212	50-255 50-329 50-329 50-155 50-329	8 9 9 8
7812200193 7812200206 7812200208* 7812210207 7812210211*	50-247 50-247 50-247 50-3 50-3	8 8 8 R R	7811170222 7811170222 7811170294 7811170294 7811170298	50-329 50-329 50-329 50-329 50-329	3 C C C
7812210211* 7812270040 7812270188 7812270188 7812270188	50-3 50-247 50-3 50-3 50-3	R Q R R R	7811170298* 7811200079 7811200112 7811200121 7811200139	50-327 50-255 50-255 50-327 50-329	C Q R A A
7810230156 7810100015 7810100019* 7810110104 7810110166*	50-327 50-255 50-255 50-165 50-165	A 8 8 8 8	7811210172 7811210990 7811210395* 7811210397* 7811210350	50-155 50-255 50-255 50-255 50-155	6 8 8 8
7810110111 7810110119 7810110122* 7810110164 7810180072	50-255 50-255 50-255 50-155 50-329	P R R P	7811210353 7811210369 7811210418 7811220176 7811240170	50-255 50-155 50-255 50-329 50-155	8 8
7810120072 7810130137 7810130171 78101301754 78101301794	50-327 50-255 50-155 50-155 50-155	A R B B B	7811240231 7811240235# 7811270094 7811270147 7811270147	50-155 50-155 50-155 50-329 50-329	8 8 A A
7810130183* 7810140097 7810140194 7810160196 7810170217	50~155 50~155 50~329 50~329 50~155	S P Q S	7811270151* 7811270151* 7811270152 7811270152 7811260052	50-329 50-329 50-329 50-329 50-155	4 4 6 0
7810170244 7810170248# 7810180095 7810190066 7810190218	50-255 50-255 50-329 50-329 50-155	6 6 8 A P	7811280124 7811280124 7811280282 7812010251 7812010252*	50-329 50-329 50-329 50-329 50-329	9 9 8 8

Consulting Engineering Geologist Consumers Power Co.



Covington & Burling Dairyland Power Cooperative	Coulee Region Energy Coalition	Cooper Industries, Inc. Cornell Univ.														
7819270307 78192703094 7819270193 7819280051 7810100003	7610110288 7610250041 7610300204 7611200395 76120403187	7812120121* 7708090484* 7810120038 7811040082 7812050290*	7812270284 7812280134 7812290146 7812290202 7812290207*	7812270144 7812270174 7812270180 7812270184 7812270198	7812220107* 7812260188 7612260188 7812260206 7812260212	7812210230 7812210232+ 7812220074 7812220075+ 7812220104	7812140080 7812140080 7812180261 7812180265* 7812190095	7812120182 7812120182 7812130133 7812130161 7812130161	7812120104 7812120109 7812120111+ 7812120112+ 7812120154	7812120068 7812120095 7812120097* 7812120100 7812120104	7812110171 7812110174 * 7812110206 7812110210 * 7812120068	7812070213 7812080192 7812080249 7812110122 7812110125*	7812050224	7812050142 7812050167 7812050175#	7812040220 7812040237 7812040239#	7812040164 7812040174# 7812040178#
50-409 50-409 50-389 50-389 50-409	50-409 50-409 50-409 50-409 50-409	50-295 50-295 50-97 50-157 50-97	50-329 50-155 50-329 50-255 50-255	50-255 50-255 50-155 50-329 50-155	50-255 50-329 50-329 50-255 50-155	50-255 50-255 50-155 50-155 50-255	50-329 50-329 50-255 50-255 50-329	50-155 50-155 50-155 50-155 50-155	50-329 50-155 50-329 50-155 50-329	50-329 50-255 50-255 50-255 50-329	50-155 50-155 50-255 50-255 50-327	50-155 50-155 50-329 50-255	50-155 50-255 50-255	50-229 50-255 50-255	50-155 50-155 50-155	50-255 50-255 50-255
H	0 0	9 9 P H	8 8 9	K G B R	8 A A P	8 9 9	G G 8 8 C	P P F	A R A R K	A 8 9 A	8 8	P G G R R	A p q 0 0 0	P 8 8 8	8 P 8 8	K P G O 8
Dial.Jemings.Hindham.Thomas & Roberts Ditterb. J. L. Doc-Bearch Associates Dow Chemical Co.			Onfense, Dept. of, Defense Nuclear Agency Delaware: Univ. of Detroit Edison Co.	Defanas-Dept. of			Depevoise & Liberman	Day, Berry & Howard Degraff, Foy, Conway & Holt-Herria	Dalton, A.T.  Dames & Moore  Darling Valve & Mêg.							
7812210374 7810140085 7812210004 7810110098 7810300037	7811090172* 7811210082 7811210299* 7811280231 7812260204*	7810310025 7811070096 7811070285 7811070076 7811070167	7810130227 7810230145 7810120021 7810130146 7810200111	7812180278 7812200224 7812270141 7812270123 7811070351	7810200001 7810200137 7810230389 7811070174 7811300008	7810140030 7810140030 7810140139 7810140139 7810140139	7812270454 7810110064 7810110279 7810120020 7810140030	7811010166 7811160048 7811200:50 7812040133 7812040137*	7812050052 7812130196 7812130341 7812010205 7812210396	7812120126 7812120132* 7812140162 7812200216 7812290161	7812080140* 7812110156 7812110158* 7812110165 7812110167*	7812010354 7812040216 7812040219# 7812070307 7812080137	7811130206 7811130209# 7811170220 7811240233 7811270109	7810270300 7810310066 7810310060 7811070034 7811070316	7810160146* 7810160151* 7810230136 7810240123 7810240143	7610100004* 7610120035 7610120039* 7610130229 7610160142
50-395 50-466 50-335 50-264 50-264	50-341 50-341 50-341 50-341 50-341	50-16 50-341 50-341 50-341 50-341	50-170 50-98 50-16 50-241 50-452	50-498 50-445 50-397 50-443 50-70	50-397 50-498 50-369 50-498 50-445	50-488 50-488 50-488 50-488 50-488	50-549 50-397 50-445 50-369 50-488	50-245 50-549 50-549 50-549 50-549	50-556 50-556 50-556 50-395 50-482	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409	50-409 50-409 50-409 50-409 50-409

.

Dute Power Co.	7812210077* 7810110084 7810110084 7810110090 7810180092*	50-245 50-369 50-369 50-287 50-287	Р А Р Р		7811020359 7811030221 7811030221 7811070214 7811080107	50-26 50-26 50-27 50-26
	7810110145 7810110145 7810110147# 7810130056 7810130096	50-369 50-369 50-369 50-269 50-413	A A G		7811080137 7811080141* 7811080211* 7811080211* 7811090110	50-27 50-27 50-36 50-36 50-36
	7810130136 7810130174 7810130174 7810130174 7810140063*	50-269 50-269 50-269 50-269 50-486	P P P P		7811100110* 7811100110* 7811100110* 7811100115* 7811100115*	50-26 50-26 50-26 50-26 50-26
	7810140066* 7810140127 7810140127 7810160101 7810160101	50-468 50-369 50-369 50-369 50-369	0 0 A A		7811100115* 7811130034 7811130354 7811130374 7811140114	50-26 50-36 50-36 50-36 50-26
	7810180076 7810180076 7810180126 7810180126 7810180126	50-369 50-369 50-269 50-269	A P F F		7811140114 7811140114 7811130177 7811140065 7811140065	50-26 50-26 50-27 50-26 50-26
	7810170027 7810200007 7810200068 7810200068 7810200076	50~369 50~369 50~369 50~369	0 0 A A M		7611140065 7811160079 7811160079 7811160079 7811160134	50-26 50-26 50-26 50-26 50-26
	7810200082 7810200082 7810200082 7810200083• 7810200083•	50-269 50-269 50-269 50-269 50-269	R R R R		7811160134 7811160134 7811160133 7811120185 7811220188	50-26 50-26 50-26 50-26
	7810200083• 7810200115 7810200132 7810200132 7810200162	50-269 50-369 50-369 50-369 50-269	H J T J		7811220231 7811220272 7811240063 7811270157 7811270157	50-46 50-36 50-46 50-36 50-36
	7810200170# 7810230029 7810230058# 7810230069 7810230158	50-269 50-369 50-369 50-488 50-269	8 9 9 9		7811270159# 7811270159# 7811270165 7811270165 7811270168#	50-36 50-36 50-36 50-36 50-36
	7810230214 7810230214 7810240002 7810240002 7810240002	50-413 50-413 50-269 50-269 50-269	9 0 R R		7811270168* 7811280378 7811270227 7811300172 7811300174*	50-34 50-26 50-41 50-27 50-27
	7810240147 7810240147 7810240147 7810250089 7810250089	50-269 50-269 50-269 50-369	р Р В В		7812010143 7812010162 7812010168* 7812010244 7812010245*	50-48 50-34 50-34 50-24 50-24
	7810250093* 7810250093* 7810250119 7810250153 7810250200	50-369 50-349 50-413 50-269 50-349	8 8 A P Q		7812040147 7812040231 7812040231 7812040277 7812040277	50-26 50-26 50-26 50-41 50-41
	7810250217 7810250217 7810250081 7810250106 7810270072	50-413 50-413 50-413 50-369 50-287	9 9 9		7812040281* 7812040281* 7812040328* 7812040328* 7812040328*	50-41 50-41 50-26 50-26
	7810270076+ 7810270199 7810300182 7810300330+ 7810300377	50-287 50-269 50-269 50-488 50-369	9 9 0		7612050025# 7812060272 7812060320 7812070317 7812070317	50-24 50-24 50-24 50-24
	7810310008 7810310008 7810310008 7610310239 7810310239	50-269 50-269 50-369 50-369	0 6 6 6		7812120230 7812130167 7812130172* 7812130175 7812130287	50-46 50-26 50-26 50-26 50-49
	7810310302 7810310336 7810310336 7811010104 7811010160	50-369 50-369 50-369 50-269 50-369	G G G P S	·	7812130306 7812130306 7812130306 7812130369 7812140041	50-26 50-26 50-26 50-26
	7811010160 7811010169# 7811010162# 7811010412 7811020255	50-369 50-369 50-369 50-369 50-269	8 8 F P		7812140041 7812140041 7812140053 7812140053 7812140053	50-26 50-26 50-26 50-26
	7 1					

ACCESSION NUMBER

AUTHOR AFFILIATION BUBJECT CATEPORY ACCESSION NUMBER

AUTHOR AFFILIATION BUBJ CATE

## CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT	\$¥	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT
	7812150226 7812150226 7812180131 7812180188 7812180196+	50-413 50-413 50-269 50-270 50-270	A A P B B	Ecalagy Action of Cowago	7811300203 7811300203# 7812210065 7810300055 7811010267	50-591 50-591 50-245 50-443 50-443
	7812190127 7812190130+ 7812190153 7812190156+ 7812200312	50-269 50-269 50-287 50-287 50-488	8 8 8 9	Eichborn Morrow & Eichborn Electric Power Research Institute	7811210467 7812150268# 7812280288# 7812180111 7812210183#	50-485 50-443 50-220 50-367 50-500
	7812210035 7812210059 7812210059 7812210157 7812210157	50-413 50-413 50-413 50-269 50-269	g g g R R	Ellis, L.J. Energy, Dept. of	7812140247 7810140123# 7810250062 7811210086# 7812110014	50-518 50-344 50-269 50-70 50-537
	7812210157 7612210160* 7612210160* 7612210160* 7612270211	50-269 50-269 50-269 50-269 50-369	R R R A	Energy, Dept. of, Clinch River Breeder Reactor Plant	7812150058 7812150293 7810170154	50-201 1 50-466 1 50-537 1
	7812270214# 7812270244	50-349 50-249	A P		7810170259* 7811170177	50-537
	7812270359± 7812280133 7812280133	50-349 50-349 50-349	G K K		7812050276 7812050280* 7812120070 7812200243 7812200247*	50-537 50-537 50-537 50-537 50-537
Duncen, Allen & Mitchell	7812280135# 7812280135# 7812290209 7812290214# 7812290218#	50-369 50-369 50-287 50-287 50-287	K 8 8	Environmental Coalition on Nuclear Power Environmental Protection Agency	7812200251* 7812280327 7810140048* 7810310273 7810310281*	50-537 50-387 50-213 50-568 50-568
Duquesne Light Co.	7811160036 7810100030 7810100034* 7810100084 7810110144	50-592 50-334 50-334 50-334 50-334	M 8 8 9		781031028&* 7811140138 7811220139 7811240169 7811240169	50~568 6 50~445 6 50~568 5 50~466 5
	7810160114 7810160116e 7810180072 7810200047 7810200050#	50-334 50-334 50-334 50-334 50-334	R R P P		7812050174 7812060157* 7812280026* 7812280040* 7812290268*	50-582 50-437 50-250 50-250 50-356
	7810200100 7810270189* 7810270195 7811030107 7811030164	50-334 50-334 50-334 50-334 50-334	8 G b	Evergreen Legal Services  Exxon Nuclear Co., Inc. (subs. of Esxon Corp.)	7811130128 7811200144 7810270108	50-522 ( 50-522 ( 50-277 (
	7811030169 7811070377* 7811070378* 7811130818 7811130820*	50-334 50-412 50-412 50-334 50-334	R 8 9 . 8	Fitchburg Qas & Electric Light Co. Fleischeter. D. B.	7811130179 7811130249+ 7811070148+ 7810190257	50-564 50-564 50-443 50-275
	7811160109 7811160111* 7811170172 7811170178*	50-334 50-334 50-334 50-334	R R 8		7810190257 7810190262* 7810190262* 7810190267*	50-275 50-275 50-275 50-275
	7811170214 7811170219 7811170221 7811170234*	50-334 50-334 50-334	9 9 8		7810190267* 7810190269* 7810190269* 7810270294	50-275 50-275 50-275 50-275
	7811280458* 7811200243* 7812080182	50-412 50-334 50-334	B Q P	Fiorida Power & Light Cp.	7810270274 7810300128 7810300128 7811130314 7810100091	50-275 50-275 50-275 50-275 50-235
	7812110128 7812110132* 7812120143 7812120148*	50-334 50-334 50-334 50-334	R R 9 8		7810100092* 7810100093* 7810100094* 7810100097*	50-335 50-335 50-335 50-335
	7812140109 7812180180 7812180184* 7812190144 7812210215	50-334 50-334 50-334 50-334 50-334	F 8 F P		7810100102* 7810110077 7810110121 7810110123	50-335 50-335 50-335 50-251
	7812220071 7812240214 7812240216#	50-334 50-334 50-334	ь ь		7810110159 7810110251# 7810110251#	50-250 50-250
	7812290222 7812290222 7812290223	50-334 50-334	8		7810120022 7810120022 7810120023* 7810120023*	50-250 50-250 50-250 50-250
ESS. Inc.	7812270226* 7812270227* 7812270235* 7810230375	50-334 50-334 50-334 50-206	8 8 8		7810180088 7810120049 7810120050 7810120051*	50-250 50-335 50-251 50-335
	7910930375	50-206	A		7810120031# 7810120031#	50-251

AUTHOR AFFILIATION	ACCESSION RABEMUM	SUBJECT CATEODRY	<u>'</u>		7811300190* 7812010043 7812010043 7812010100	50-250 50-250 50-250	0 0
	7810120075 7810120081* 7810120081* 7810170191* 7810170243	50-250 50-250 50-250 50-335	F F P 8		7812010100 7812010119* 7812010119* 7812010128* 7812010128*	50-250 50-250 50-250 50-250 50-250	0 0 0
	7810170245> 7810180115 7810200045 7810200093 7810200094>	50-335 50-335 50-250 50-251 50-251	8 7 8 8		7812040187 7812040189* 7812040221 7812040222* 7812050131	50-250 50-250 50-251 50-251 50-335	8 8 8
	7810200114 7810200117# 7810200168 7810200252 7810230052#	50-231 50-250 50-335 50-335	0 0		7812050133* 7812050176 7812050181# 7812050195 7812050198*	50-335 50-251 50-251 50-335 50-335	8 8 8 8
	7810230140 7810230140 7810230166 7810230169* 7810230250	50-250 50-250 50-335 50-335 50-251	J J 8 8 8		7812050240 7812060356 7812080200 7812120145 7812120239#	50-250 50-369 50-335 50-389 50-250	0 8 A 0
	7810230253* 7810230329 7810240071* 7810240075* 7810240088	50-251 50-335 50-250 50-250 50-369	8 Q Q Q		7812140146 7812140150 7812140150 7812140152* 7812140195	50-251 50-250 50-250 50-251 50-335	P P P
	7810260007* 7810260070 7810270182 7810270182 7810300107	50-250 50-250 50-250 50-250	0 P P J		7812180138 7812180141* 7812180316* 7812190235 7812210068	50-250 50-250 50-335 50-250 50-250	0 0 0
	7810300107 7810310002 7810310121 7810310121 7811030168#	50-250 50-335 50-250 50-250 50-250	F F Q		7812210068 7812210138 7812210196 7812270187 7812270190	50-250 50-335 50-251 50-250 50-250	0 0 P F
	7811030148* 7811030226 7811040095 7811040142 7811040144	50-250 50-335 50-335 50-250 50-250	Q Q P 8 8		7812270175 7812270267 7812270307 7812270312*	50-250 50-335 50-335 50-251 50-251	P
	7811060148* 7811060152* 7811060157 7811060163* 7811070144	50-250 50-250 50-251 50-251 50-250	8 8 9 1	and and	7812280019 7812280139 7812280339* 7812290147 7810110097	50-250 50-250 50-250 50-335 50-302	P P O P C
	7811070144 7811070144 7811070180 7811070180 7811070309	50-250 50-250 50-250 50-250 50-250	I I P P	Fiorida Power Corp.	7810110116 7810110120* 7810110151 7810110152* 7810110170	50-302 50-302 50-302 50-302	9999
	7811080148 7811080150+ 7811080208 7811080217+ 7811090242	50-251 50-251 50-335 50-335 50-335	9 9 6		7810110173* 7810110173* 7810160081 7810160094* 7810170249	50-302 50-302 50-302 50-302	8 P R R
	7811090246* 7811100083* 7811100083* 7811130221 78111140219	50-335 50-250 50-250 50-250 50-335	8 0 F P		7810170252* 7810180105 7810180107* 7810180110 7810180111*	50-302 50-302 50-302 50-302	9 9 8
	7811160107 7811160139 7811160142* 7811160142* 78111210188	50-335 50-250 50-250 50-250 50-250	P P P Q	•	7810180147 78101801524 7810180153 7810180155* 7810200155	50-302 50-302 50-302 50-302	9
	7811210186 7811210327 7811210328 7811210339 7811210338	50-250 50-335 50-335 50-250 50-250	Q P P P		7810200152 7810200160 7810240118 7810240124* 7810240160	50-302 50-302 50-302 50-302 50-302	9 9
	7811210338 7811220002 7811220201 7811220203* 7811240007*	50-250 50-335 50-250 50-250 50-335	P Q B Q		7810240162* 7810270165 7810310136 7810310141* 7810310164	50-302 50-302 50-302 50-302	9
	7811240025 7811240209 7811270161 7811270161 7811280228	50-250 50-335 50-250 50-250 50-250	야 P P P		7810310164 7811010299 7811070136 7811070137* 7811070204	50-302 50-302 50-302 50-302 50-302	6
	7811280228 7811290229 7811290235* 7811290320 7811300004*	50-250 50-335 50-335 50-369 50-335	P 8 8 0 0		\8110\0X04	20-302	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR
	781 1 070208* 781 1 070276 781 1 070235* 781 1 080165 781 1 1 00021*	50-302 50-302 50-302 50-302		<b>-</b>	7811200392* 7811210231 7811210247 7811270099* 7812010248	50-275 50-344 50-220 50-155 50-447
	781 1 130181 781 1 1 40109 781 1 1 40123 781 1 1 40134 781 1 1 40140+	50-302 50-302 50-302 50-302	P J B B		7812010249# 7812040018# 7812050220 7812050221 # 7812050231#	50-447 50-556 50-447 50-447 50-257
	781 1 1 70103 781 1 200184 781 1 200187• 781 1 240074= 781 1 240216	50-302 50-302 50-302 50-302	F R R O P		7812080131 7812110113 7812110113 7812110113 7812110116#	50-70 50-447 50-447 50-447 50-447
	781 1280268 781 1280271# 781 1280303 781 1280307* 781 2010246	20-305 20-305 20-305 20-305 20-305	R R B B		7812110116# 7812110116# 7812110272 7812110274# 7812110277#	50-447 50-447 50-277 50-277 50-277
	781 2010247* 781 2040199 781 2050067* 781 21 40127 781 21 80150	50-302 50-302 50-302 50-302	8 P Q F 8		7812120082+ 7812130132 7812140121 7812140176 7812180401+	50-333 50-447 50-70 50-219 50-70
	781 21 60153+ 781 2200176 781 2200178 781 2200179+ 781 2200181+	20-305 20-305 20-305 20-305 20-305	8 R B R		7812180439 7812210331 7812270162 7812270172 7812270172	50-30 50-70 50-447 50-447 50-447
	781 2200270 781 22002734 781 2200284 781 22103374 781 2220081	50-302 50-302 50-302 50-302	8 6 0	General Physics Corp. General Public Utilities - GPU Barvice Corp.	7812280099 7812280100# 7812280275 7810200130 7810120068	50-447 50-447 50-70 50-341 50-219
	781 2220084• 781 2220102 781 2220105• 781 2270239 781 2270243•	50-302 50-302 50-302 50-302	5 6 8 8 8		7810240132 7810300148 7810300153# 7810300157# 7811060092	30-219 50-219 50-269 50-219 50-320
Floride State Univ. Floride, State of Floride, Univ. of, Cainesville	781 2270291 781 2270293* 781 0240003* 781 2270168 781 01 10198*	50-302 50-302 50-437 50-250 50-83	8 8 A H Q	Georgia Power Co.	7812010127 7810100039 7810100039 7810100045# 7810100045#	50-146 50-321 50-321 50-321 50-321
Fontana. L. Ford Bacon & Davis Utah. Inc.	781 0 1 8081 781 2040149 781 1 0 80180 781 0 1 70035 781 1 2002210	50-83 50-83 50-382 50-201 50-201	P P A P		7810110089 7810110135 7810130043 7810130092 7810130092	50-321 50-386 50-386 50-321 50-321
Friends of the Earth	781 O1 90193 781 O2 30084 781 RO40348 781 R1 10278 781 R210512	50-70 50-70 50-70 50-70 50-70	0 0 0		7810160104 7810160104 7810170141 7810170142 7810170166	50-321 50-321 50-321 50-355 50-356
Ft. Collins, CA Gaja-Babcock Associates, Inc. General Atomic Co. (mubs. of Qulf Dil Co.)	7812150279 7812270102+ 7810270107+ 7811130200		F A P		7810170170# 7810170226 7810170230# 7810170233	50-366 50-366 50-365 50-321
General Abomic Co. (wubs. of Gulf Oil) Corp.)	781 1240232 781 1240234+ 781 21 90145 781 0270104	50-247 50-257 50-89 50-163	3 F		7810170236 7810170238* 7810170255 7810170256 7810170258#	50-366 50-366 50-321 50-366
General Electric Co.	7811Q60115 7810110165	50-237 50-70			7810170261# 7810170291	50-321
	7810170114* 7810180108 7810300138* 7810300138* 7810300138*	50-447 50-447 50-447	Å		7810170298# 7810170309 7810170311 7810170312	50-321 50-344 50-346 50-346
	78 10310187 78 10310187 78 10310187 78 1 1030236	50-447 50-447 50-447 50-70	A A O		78101703134 78101703144 78101703154 7810170318 78101703214	50-366 50-366 50-366 50-366
	7811040122 7811070115 7811070140 7811070340	50-558 50-558 50-70 50-558 50-558	. 0 P		7810170322 7810170326* 7810170327 7810180001 7810180003*	50-346 50-366 50-366 50-366
	78 1 1 060008* 78 1 1 130177 78 1 1 170157 78 1 1 200384*	50-18 50-552	P . A		7810180010 7810180011# 7810180014# 7810180019	50-321 50-321 50-321 50-366

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGORY	<u>′</u>	AUTHOR AFFILIATION	ACCESSION NUMBER
	7810180020 7810180022* 7810180023 7810180024* 7810180026*	50-366 50-366 50-366	8 8 8 8		7811220026 7811220028* 7811220034 7811220034 7811240061
	7810180029 7810180031 7810180033* 7810180037 7810180039*	50-366 50-366 50-366	8 9 8 8		7811240061 7811280006 7811280006 7811280217 7811280220*
	7810180112 7810180314* 7810180114 7810180118* 7810180120	50-321 50-321 50-366 50-366	8 8 9 8		7811280222 7811280223 7811280223 7811280224* 7811280235
	7810180122* 7810230175 7810230176* 7810230188 7810230190*	50+366 50-321 50-366 50-366	8 8 8		7811280242* 7811280288 7811280293* 7811300192 7812060343
	7810230206 7810240110 7810270101 7810270117 7810310146	50-366 50-321	9 P 8 3		7812060392 7812070033 7812070035 7812070038 7812070082
	7810310150* 7810310151 7810310154* 7810310157 7810310160	50-321 50-366 50-386 50-321 50-321	8 9 9 8		7812070082 7812080098 7812150287 7812150294* 7812150334
	7810310162* 7810310165 7810310166* 7810310171* 7810310175	20-366 20-351 20-351 20-351 20-351	8 8 9 5		7812150347* 7812180133 7812180162 7812180164 7812180163
	7810310181* 7810310182* 7810310203 7810310214* 7811010062	50-366 50-321 50-366 50-366 50-321	8 8 8 P		7812180167* 7812180169* 7812180170* 7812180179 7812180182
	7811020163 7811030044 7811060131 7811060135 7811060138+	50-424 50-424 50-321 50-321 50-321	0 0 8 8		7812180183* 7812180186* 7812180198 7812180201 7812180202*
	7811060140* 7811060150 7811060152* 7811080162 7811080162	50-321 50-366 50-366 50-424 50-424	8 9 9 A		7812180205* 7812180214 7812180217* 7812180220 7812180225*
	7811100168* 7811130261* 7811130261* 7811140156 7811140162*	50-321 50-321 50-321 50-321 50-321	0 0 9 8		7812180231 7812180234* 7812260154 7812260156* 7812270266
	781114019B 7811140204+ 7811140209 7811140211+ 7811140245		6 9 9		7812270273# 7812270274 7812270280 7812270285# 7812270295
	7811140254* 7811150093 7811160066 7811160068* 7811160106	50-366 50-321 50-321 50-321 50-366	B P R R		7812270276* 7812270314 7812270317 7812270317* 7812270318*
	7811160110# 7811170205 7811200173 7811200259# 7811200259#	50-366 50-321 50-424 50-424 50-424	R J A A		7612270319 7612270321* 7612270325 7612270326 7612270329*
	7811210217 7811210217 7811210226 7811210238 7811210243	50-424 50-424 50-424 50-366 50-366	A A B B		7812270331 x 7812280069* 7812280286 7812290139 7812290145
	7811210246 7811210253* 7811210342 7811210346* 7811210351	50-366 50-364 50-321 50-321 50-366	8 8 8 8	Gaorgia, State of Gibbs & Hill, Inc. (subs. of Dravo Corp.)	7812290145 7812290152* 7812290152* 7810230104 7811080030*
	7811210361 7811210366* 7811210370* 7811210398 7811210404*	59-321 59-321 59-366 50-366 50-366	6 8 8 8		7811080033+ 7811240125 7811240128+ 7812170103 7812270138

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOURY
Oilbert/Commonwealth Cas.	7812290143* 7812180226		A F		7810240042 7810270394	50-511 G 50-322 A
Gordon, Walter J Graham: R L	78121802324 7810110025 7811160050	30-249	F P 0		7811130435 7811200307 7811290087	50-450 Q 50-516 Q 50-516 Q
Oreen Bay Packing, Inc. Oreen, Feldman, Hall & Woodard	7810160017 7810230075 7811150232 7811240083 7811270193	50-556 50-556 50-556	0 0 0 0		7812080171 7812110281 7812130212 7812210305 7812210311+	50-338 G 50-322 G 50-463 G 50-247 G 50-247 O
Quif States Utilities Co	7812110215 7812130193 7810110272* 7811070246 7811070252*	50-556 50-458 50-510	G Q Q A A	Idaho State Univ. Ihrig, R.	7812260307 7812280333 7812070202 7812070204* 7810190202	50-247 G 50-322 G 50-284 P 50-284 P 50-484 G
	7812260148 7812260148 7812260148 7812260166 7812260166	50-458 50-458 50-458 50-458 50-458	A A A A	Illinois Power Co.	7810190220* 7810300369 7810110037* 7812080226 7812260141	50-484 Q 50-484 Q 50-461 Q 50-461 A
Hanford Conversion Project  Harvard Univ.	7812260170+ 7811100018 7812040072 7812040084+ 7810160013+	30-438 30-397 30-397 30-397 30-471	A G G G G A	Illinois. State of	7811130202 7811240022 7812050047 7812050047 7812050051*	50-295 @ 50-295 @ 50-295 @ 50-295 @
Hazelton Environmental Sciences Corp. Hetzel, W.C House of Rep.	7812010122 7811220198 7810110248 7810110271 7810230042+	50-298 50-352 50-70 50-70 50-275	P	indiana & Michigan Power Co.	7812030051* 7812080026 7812120211 7810100024 7810100044	50-275 0 50-249 P 50-295 0 50-315 8 50-316 8
	7810230084 7810300272 7811070355* 7811130246 7811290297	50-70 50-556 50-70 50-70 50-70	Q Q P Q Q		7810100064* 7810100068* 7810110080 7810110154 7810110188	50-316 8 50-316 8 50-315 P 50-315 8 50-316 8
	7811300100 7811300100 7812010046* 7812050044* 7812060216	50-338 50-338 50-471 50-213 50-338	A Q U H		7810110192* 7810180002 7810180004* 7810180005* 7810180016	50-315 8 50-316 8 50-316 9 50-316 8 50-316 8
Houston Lighting & Power Co.	7812060216 7812180229 7812180269 7812210171 7810110294	50-308 50-70 50-275 50-70 50-466	н н о о		7810180018* 7810180027 7810180030* 7810180032* 7810180104	50-316 8 50-316 8 50-316 8 50-316 8 50-315 8
	7810120024 7810120024 7810120061 7810120061 7810140062*	50-498 50-498 50-498 50-498 50-498	X H A A K		7810180109* 7810180188* 7810200053 7810200056* 7810230177	50-315 8 50-315 8 50-316 R 50-316 8
	7810140159 7810300088 7810310179* 7811010144 7811020387*	50-466 50-498 50-498 50-498 50-498	0 A H A Q		7810230183+ 7810230185+ 7810230159 7810230202+ 7810230242	50-316 9 50-316 8 50-315 9 50-316 P
	7811020387* 7811020393* 7811020393* 7811030214 7811090106	50-478 50-478 50-478 50-478 50-478	Q Q B B		7810250117+ 7810270191 7810270193+ 7810270309 7810270314+	50-315 8 50-315 8 50-315 8 50-316 8
	7811160131 7811170090* 7811240114 7811240114 7811240116*	50-498 50-466 50-498 50-498 50-498	A C C C	•	7810310090 7810310090 7810310145 7810310155* 7810310190	50-315 P 50-315 P 50-315 E 50-316 E
	7811240114* 7811300216 7811300382* 7812040127* 7812040301	50-498 50-498 50-498 50-498 50-498	0 0 0 0		78103101994 7810310204 7810310204 7811030232 7811030103	50-316 E 50-315 F 50-315 E 50-315 E
	7812040302* 7812050200 7812050203* 7812190147 7812210029*	50-498	G B A		7811070151 7811070153* 7811070158* 7811070225 7811140154	50-316 £ 50-316 £ 50-316 £ 50-315 £
Hudson Light & Power Dept Hunton & Williams	7812280151 7612280152* 7611070150* 7810160201 7810190223		B I O O		7811140210 7811140218* 7811140226* 7811140232* 7811170204	50-316   50-316   50-316   50-315   50-315
	7810200059* 7810200059* 7810230130 7810240038 7810240038		g g g g		7811210260 7811210265• 7811210271 7811210278• 7811210383	50-315 F 50-315 F 50-315 F 50-315 F 50-315 F

AUTHOR AFFIL (AT10)	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER
		50~315 50~316 50~316 50~315 50~315		***************************************	7810240112 7810310220 7810310227* 7811070121 7811080002
	7811240)74* 7811270069 7811270080* 7811270171 7811270136	50-315 50-315 50-315 50-315 50-316	8 8 9 P F		7811170139 7811210090 7811210354 7811210390 7811210394*
	78)1290247 7811290247 7811290251+ 7811290251+ 7811300177	50-315 50-315 50-315 50-315 50-316	8 K K K		7611270148 78112701504 7811270160 7811270202 7811280036
	7811300181# 7811300185# 7811300168# 7811300193# 7812010210	50-316 50-316 50-316 50-316 50-316	8 8 8 8		7811280204 7811280206* 7811280237 7811290258 7812050132
	7812070215 7812070215 7812080051 7812080058⇒ 7812080070≠	50-315 50-315 50-316 50-316 50-316	P S S S S	•	7812050156 7812110106 7812130136 78121301404 78121301454
	7812080075 7812080086 7812080087* 7812080089* 7812080119	50-315 50-316 50-315 50-316 50-316	8 8 9 8		7812190137 7812190139* 7812270297 7812270301* 7812290130
	7812080120+ 7812080122+ 7812110137 7812120162 7812120167+	50-316 50-316 50-315 50-315 50-315	8 8 8 9	Iowa State Univ. Iowa-filinois Gas & Electric	7811060073 7811060074 7810250111 7812060166 7812200188
	7812120178 7812120186+ 7812130384 7812180207 7812180212+	50-316 50-316 50-315 50-316 50-316	8 9 9 8	lahem, Lincoln & Beele	7810110309 7810120112 7810160202 7810190131 7810190216
	7812200173 7812200174* 7812200203 7812200203* 7812240198	50-315 50-315 50-316 50-316 50-315	R R R R	•	7810250021 7810260199 7810300311 7811010433 7811020467
	7812260198 7812260242 7812270178 7612270178 7812270181*	50-315 50-315 50-315 50-315 50-315	K P P P		7811130060 7811130060 7811130252 7811140047 7811140047
	7812270220 7817270226* 7812270232 7812270233 7812270250*	50-315 50-315 50-316 50-316	8 8 8		7811200070 7811210036 7811210107 7811240074 7812040014
	7612270264* 7612270266* 7612270272* 7612270277* 7612270292*	50-316 50-316 50-316 50-316 50-316	8 8 8		7612040235 7612040235 7612040311 7612050281 7612050347
	7612270286# 7612280145 7612290083 7612290179 7612290182	50-316 50-316 50-316 50-315	8 8 P P		7812070008 7812070008 7812110107 7812120223 7812130122
Indians, State of Interior, Cept. of	7812270185+ 7612010185 7810110142 7810230134 7810240142	50-315, 50-546 50-498 50-274 50-582	P A C P D		7812140078 7812140087 7812140087 7812140285 7812140362
	7810270134 7810310092 7811070123 7811090063 7811200109	50-568 50-568 50-568 50-274 50-546	A A P P		7818140362 7812150029 7812180383 7812270010 7812270127
interior.Dept. of, Geological Survey Iowa Electric Light & Power Co.	7811220151 7812180431 7812200236 7810110141 7810110143	50-592 50-70 50-274 50-331 50-331	A P H B J	Jersey Central Power & Light Co.	7812280338 7812280350 7812290013 7812290255 7810100070
	7810120047 7810200061 7810200063+ 7810230173 7810240104	50-331 50-331 50-331 50-331 50-331	P R R P		7810100076* 7810110118 7810120071 7810120076* 7810160115

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC
	7810160120* 7810160143 7810170200 7810170240 7810180006	20-514 20-514 20-516 20-516 20-516	P R P B		7810300359 7811030217 7811160186* 7811160189* 7811170249*	50-482 50-482 50-482 50-482 50-482
	781 0180007* 781 0230259 781 0230261* 781 0240105 781 0240107*	50-219 50-219 50-219 50-219	6 R R 8		7812110271+ 7812110276+ 7812110282+ 7812200348 7812200349+	50-482 50-482 50-482 50-482 50-482
	7810270094 7811030114 7811070105 7811070304 7811080100	50-219 50-219 50-219 50-219	R P 8 P	Kansas State Univ. Kansas, Univ. or Kesler & Buckley Kudzu Allience	7810110029 7811170293* 7812060319* 7811010389* 7811140034	50-188 50-148 50-148 50-524 50-400
	7811080189* 7811080234* 7811080258* 7811200160 7811200164*	50-363 50-219 50-219 50-219 50-219	G G P P	Lake County, OH Lakeshore Citizens for Bafe Energy	7811290J39 7812140114* 7812220121 7811160160* 7811200268	50-400 50-400 50-400 50-440 50-266
	7811200204 7811200207* 7811210239 7811210241* 7811210321	20-518 20-518 20-518 20-518	8 8 R R		7811200275 7812110306 7812140359 7812140359 7812140368#	50-266 50-305 50-266 50-266 50-266
	7811210324# 7811220129 7811240194 7811280193 7811280196#	50-219 50-219 50-219 50-219 50-219	\$ F 8	Legosuf, Lamb, Leiby & MacRee	7812140368* 7812270452 7810140028 7810160108 7810180148	50-266 50-266 50-452 50-244 50-244
	7811280262 7812010131+ 7812070218 7812070220+ 7812070288+	50-219 50-219 50-219 50-219	P G 8 8		7810190068 7810230238 7810250060 7810270368 7810270387	50-244 50-244 50-285 50-341 50-341
	7812110093 7812110097* 7812120123 7812120127* 7812120133	50-219 50-219 50-219 50-219 50-219	8 8 8		781027040&* 7811010136 7811050099 7811050241 7811130399	50-341 50-546 50-285 50-485 50-548
	7812120136* 7812180161* 7812180208* 7812180208* 7812190105	50-219 50-363 50-219 50-219 50-219	8 9 8 8		7811210293 7811240102 7812040283 7812050340 7812220002	30-341 50-220 50-485 50-341 50-341
	7812190107* 7812200180 7812200182* 7812200236 7812200240*	50-219 50-219 50-219 50-219 50-219	8 R R B	League of Women Voters of Lancester Co.,	7812220113 7812240014 7812240202 7812270138 7811220141	50-244 50-247 50-341 50-247 50-463
	781 2270185 781 2270316 781 2270323* 781 2280231 781 2280236*	50-219 50-219 50-219 50-219 50-219	P 8 8 8	League of Homen Voters of Suffolk Co., NY Leed, R. M	7811220172 7811020077 7811300400 7812080165 7812110199	50-463 50-516 50-522 50-522 50-522
oustice.Dept. of	7819290089 7819290097* 7819290213 7819290219* 7810200120	50-219 50-219 50-219 50-219 50-498		Long Island Lighting Co.	7810100017 7810160074 7810200091 7810230133* 7810230274	50-322 50-322 50-322 50-322 50-516
	7810240214 7810270354 781120050 7811200103 7812040032	50-498 50-344 50-498 50-389 50-346	н о н н		7810270190 7811140234* 7811280044 7812070115* 7812140166	50-322 50-322 50-322 50-322 50-322
	7812040260 7812130235 7812140209 7812140280 7812180410	50-369 50-369 50-346 50-498 50-498	М		7812260126 7812260129* 7812260136 7812260139* 7812260196	50-322 50-322 50-322
	7812180410 7812180412 7812180412 7812260137 7812280177	50-499 50-498 50-498 50-443 50-498	н н н		7812260211 7812260215 7812260221 7812270478* 7812270258*	50-322 50-322 50-322 50-322
Justics.Dept. of, Attorney General's Office KMC, Inc. Kafin.R.J.	7810140023 7811290304* 7812210210* 7810200136 7810270285	50-344 50-70 50-272 50-349 50-549	Q F Q	Looney, Nichols, Johnson & Hages Los Alamos Beientific Laboratory Lauisiana Power & Light Co.	7811080225 7811170297 7811220012 7812140105 7810110115	50-445 50-266 50-356 50-322 50-362
Kafoury & Hagan Kansas Qas & Electric Co.	7812180405 7811140027 7810250031# 7810270320	50-549 50-244 50-482 50-482	0 0 0	•	7811010004 7811010033* 7811170086* 7811300233	20-385 20-385 20-385 20-385
					•	

MANAGEMENT OF THE PROPERTY OF	NUNDER	CHIERON		AFFICIATION	NUMBER
	7812050182 7812110155 7812110230* 7812120115 7812130152	20-385 20-385 20-385 20-385 20-385	A M Q 9 9		7812010216 7812150355 7812150357 7812200213 7812200217
	7812190092 7812200133 7812200133 7812200242 7812200245		A A C C	Mapleton Intervenors	7812200220 7812200252 7812200254 7811010014 7811100146
Lowell, Univ. of	7612200246 7612200250+ 7612290175 7611020177+ 7612070455	50-382 50-382 50-223	አ ዩ ያ ያ	Marsh & McLennan-Inc., M & M Nuclear	7811100146 7811150039 7811210040 7811210040 7811240044
Lowenstein: Newman, Rais, Azelrad & Toll	7810130091 7810130193 7810140017 7810140019 7810200003	50-466 50-498 50-344	о е н о о	Consultants, Inc. Div.  Maryland, State of Massachusetts Institute of Technology  Massachusetts Municipal Wholesaie Co.	7812240284 7812040185 7812080073 7811070153
	7810230324 7810270322 7810270386 7811020041 7811020047+	50-498 50-344 50-376	0 0 0 0	Massachusetts. State of	7810110109 7810110310 7810230197 7810300237 7811160126
	7811080021 7811080054 7811130259 7811130404 7811130431	50-466 50-367 50-398	м о и и и	Matthews, Nowlin, Macfarlane & Barrett	7811200146 7812010044 7810230007 7812130104 7812280176
	7812040024 7812040028 7812040031* 7812040274 7812040329	50-344 50-344 50-466	0 0 0 0	McCutchen, Doyle, Brown & Emersen Means, Donald B. Metford & Dattilo Metropoliten Edison Co.	7812130054 7811130128 7810230229 7810100046 7810100076
	7812040331 7812040333 7812040343 7812040350 7812040367	50-466 50-466 50-466	Q Q Q Q		7810100080 7810100088 7810100090 7810100095 7810100099
	7812050037 7812050046 7812070058 7812110256 7812120048	50-466 50-466 50-466	0 0 0		7810110082 7810110083 7810110130 7810110134 7810110148
	7812120224 7812130020 7812130026 7812130219 7812180258	30-466 30-466 80-466	0 9 9 8 N		7810170147 7810170148 7810180132 7810180165 7810180168
	7812180438 7812270405 7812270410 7812270485 7812280266	50-498 50-389 50-344	9 M M 9 9		7810180174 7810180174 7810190001 7810240097 7810240119
HHB Technical Associates Hains Public Bervice Co. Hains Yankes Atomic Power Co.	7812280269 7812280308 7812210521 7811070169* 7810110171	50-582 50-275 50-443	M 0 0 1 1		7810240119 7810240120 7810240125 7810240129 7810240131
	7810120066 7810170150 7810170151* 7810180137 7810190056	50-309 50-309 50-309	) a a a a a		7810240134 7810300137 7810310184 7810310192 7811070101
	7610230137 7610230153 7610260160 7610270077 7811030131	50-309 50-29 50-309	) p p 6		7811070191 7811070191 7811080204 7811090048 7811090054
	7811030135* 7811030137 7811030140* 7811140112 7811140166*	50-309 50-309 50-309	e e e r r		7811090114 7811090171 7811090174 7811090247 7811090274
	7811150091 7811150095* 7811920200 7811920202* 7811920213	50-307 ( 50-309 ( 50-309 (	P G B B		7811070278 7811140103 7811140172 7811150145 7811150241
	7811270217+ 7811270086 7811290243 7812010093+ 7812010214	50-309 F 50-309 F	<b>h</b> 9 9 9		7811160145 7811210164 7811210186 7811210332 7811210336

	7811210380 7811210384* 7811240110 7811240110 7811240110	50-320 50-320 50-289 50-289	R R P P	Morgan, Lewis & Bockius	7810140029 7810140104 7811080329 7811160147 7811210451	50-409 50-409 50-556 50-409 50-70
	781 1280243 7812050098	20-583 20-583	P P	N.M. Newmark Consulting Engineering	7811300055 7812040321	50-70 50-275
	7812040161 7812040168 7812060171	20~350 20~384 20~384	P F 8	Bervices NUB Carp.	7811130336 7811150127	50-341 50-592
	7812060177* 7812070203 7812070206* 7812080090 7812110146	50-320 50-320 50-320 50-287 50-289	8 P P B	National Lawyers Guild, Houston Chapter  Natural Resources Defense Council	7811020169 7811020176* 7811020181* 7810120088 7810300063 7810300268	50-466 ( 50-466 ( 50-466 ( 50-369 ( 50-237 ( 50-437 (
	7812120092 7812130195 7812130197* 7812180187 7812190096	50-289 50-320 50-320 50-320 50-320	H B P P		7811130391# 7811150223 7811150227 7812110070 7812110074*	50-220 5 50-237 6 50-437 6 50-437 6
	7812190113 7812190132 7812190134* 7812190166 7812190170*	50-289 50-320 50-320 50-289 50-289	F R R R	Nebrasia Public Power District	7812260002 7812270036 7812280271 7812280280* 7810180037	50-247 6 60-437 6 50-237 6 50-237 6
	7812200171 7812200275 78122002784 7812260191 78122601944	50-269 50-320 50-320 50-289 50-289	0 6 8 8		7810170152 7810170268 7810170299* 7810230213* 7810230173	50-278
	7812260259 7812260261* 7812280116 7812290086 7812290093	50-320 50-320 50-320 50-269 50-320	8 8 0 P 8		7810300177* 7810300207* 78103002253 7811080110*	50~298 6 50~298 6 50~298 6 50~298 6 50~298 6
Miami, FL. Univ. of Michigan. State of	7812290129 7812290131 7811160001 7810190237* 7810190240*	50-289 50-320 50-463 50-255 50-255	P P የ R R		7811140130 7811160113 7811160114* 7811170810 7811200115	50-298 6 50-298 6 50-298 1 50-336 1 50-298 1
	78110901594 7811240190 7812040152 7812240065 7812240045	50-329 50-329 50-329 50-329 50-329	A G O		7811270129* 7812040196 7812050135 7812050138* 7812050144	50-298 ( 50-298 ( 50-298 ( 50-298 (
Hichigam, Univ. of Mid-America Coalition for Emergy Alternatives Midland City, Mi	7812260067* 7812260067* 7811080135 7811160181 7811240184	50-329 50-329 50-2 50-462 50-329	0 0 8		7812050145* 7812050166 7812050170* 7812060524 7812060148	50-298 1 50-278 1 50-278 1 50-278 1
Midland County, MI	781 1240186 781 1240188 781 1240199 781 0210061 781 1240166	50-329 80-329 50-329 50-329 50-329	A A A		7812130158 7812130160* 7812130166 7812200359 7812200271	50-278   50-278   50-278   50-278   50-278
Minnesute Pollution Control Agency Minnesute: Btate of Mississippi Power & Light Co.	7811240185 7812260044 7812260323 7812260328* 7811150097	50-329 50-263 50-263 50-263 50-416	A Q P P Q	Neil, R. M.	7812200274+ 7812270328 7812290197 7812290201+ 7811200219	50-278 50-278 50-278 50-278 50-278
	7811150164 7811160073 7811160073 7811170198	80-416 80-416 80-416 80-416	A A	Nepom & Ross New Bedford Que & Edison Light Co. New England Coalition on Nuclear Pollution	7812040118 7811070171* 7812150273*	50-397 50-443 50-443
	7812010223	50-416	К	New England Legal Foundation	7812150283* 7811170173	50-443 50-568
	7812010223 7812010229* 7812010229* 7812050191 7812060400	50-416 50-416 50-416 50-416 50-416	K K A	New England Power Co,	7810110078 7811040097 7811080195 7811210344 7811240048*	50-568 50-568 50-568 50-568 50-768 50-27
	7812060400 7812070179 7812120098 7812140133 7812270209	50-416 50-416 50-416 50-416 50-416	A Q	New Hampubire, State of	7811280040 7812040151 7812080104 7810180077 7810230267	50-568 50-568 50-568 50-443 50-668
	781 2270209 781 2290133 781 2290256 781 2290260 781 2290260	50-416 50-416 50-416 50-416 50-416	A 0 0	New Jersey, State of	7810270147 7811130254 781210259 7812180233 7812270227	50-443 50-345 50-272 50-354 50-272
Missouri, Univ. of, Ralla Montaup Electric Co.	7810110079 7811060076 7812290080 7811070166*	50-186 50-186 50-186 50-443	B P	New Merico, Univ. of New York State Electric & Gas	7812140153 7811270077+ 7812290264	50-252 50-495 50-596

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEO		AUTHOR AFFILIATION	ACCESS ION NUMBER	BUBJE	CT ORY
	7812290264 7812290265 7812290265 7812290266 7812290266	50-596 50-596 50-596 50-596	F B		7810160123* 7810160126 7810160130* 7810170140 7810170140	50-245 50-336 50-336 50-245 50-245	R R P
	7812290267+ 7812290267+ 7812290271+ 7812290271+ 7812290275+	50-596 50-596 50-596 50-596 50-596	8 8		7810170210 7810200040 7810200071 7810200072* 7810200087	50-336 50-336 50-245 50-245 50-245	P P 8 8
	7812290275+ 7812290275+ 7812290278+ 7812290278+ 7812290278+	50-596 50-596 50-596 50-596 50-596	8		7810200088* 7810230207 7810230210* 7810240099 7810270203	50-245 50-245 50-245 50-245 50-245	R B B P P
New York, State Univ. of, Suffelo New York, State of Newport News Industrial Corp. (subs. of Newport News Bhipbuilding & DryDock Co.	7810300187 7810120055 7810240159 7812210517 7811220191•	50-57 50-333 50-549 50-97 50-220	H A O P		7810310073 7810310077 7811070196 7811080143 7811080146*	50-245 50-336 50-336 50-336	р 9 8
Niegara Hohaut Power Corp.	7810100034 7810100059* 7810110088 7810160119 7810160121*	50-220 50-220 50-220	8 8 P R		7811080155 7811080161* 7811090132 7811090133* 7811130193	50-336 50-336 50-423 50-423 50-213	8 8 8
·	7810170188 7810260022* 7810300146 7811030141 7811070114	50-220 50-220 50-220 50-220	F 9 P		7811140110 7811[40[13* 7811140155 7811140155 7811140167	50-336 50-336 50-213 50-213 50-245	R P P
	7811090155 7811090165+ 7811090206+ 7811090271 7811090273+	50-220 50-220 50-220 50-220	8 8		7811140187 7811140191* 7811140202 7811140203* 7811140089	50-245 50-245 50-336 50-336 50-245	8 8 8
	7811130319 7811130400 7811150041* 78111150188* 78111210281	20-550 20-550 20-550 20-550 20-550	9 9		7811160093* 7811160152 7811170104 7811170115* 7811210178	50-245 50-245 50-245 50-245 50-476	g R R
	7811210283* 7811210287* 7811210292* 7811210302 7811210303*	20-550 20-550 20-550 20-550 20-550	8 8 8 8		78112101834 7811210232 7811210268 7811210275* 7811210280	50-476 50-336 50-336 50-336 50-248	8 6 6
	7811220193* 7811240103* 7811290192 7812050148 7812070192	50-220 50-220 50-220 50-220 50-210	P F P		7811210291* 7811240187 7811240187 7811240187* 7811240189*	50-245 50-245 50-245 50-245 50-245	8 K B B
	7812070219 7812120102 7812120103+ 7812140136 7812140149	50-410 50-220 50-220 50-220 50-220	A R R F		7811270183 7811280275 7811280300+ 7812050153 7812050161+	50-213 50-336 50-336 50-336 50-336	P B B B
	7812140154+ 7812200194 7812200202 7812270176 7812270240	50-220 50-220 50-410 50-220 50-220	8 P P		7812070184 7812080117 7812080118* 7812080121 7812080126	50-245 50-245 50-245 50-245 50-245	8 8 9 9
North Anna Environmental Coalition North Carolina. State of Northcutt Ely	7812270287 7812280196 7812060220# 7811080230 7812140244	50-220 50-410 50-338 50-488 50-445	P O H A M		7812080127# 7812120108 7812120113# 7812120116 7812120129#	50-245 50-336 50-336 50-336 50-336	8 8
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	7812140244 7812140244= 7812140244= 7811290292= 7811290332=	50-445 50-445 50-445 50-245	M M R		7812150301 7812150308# 7812190083 7812200187 7812260168	50-336 50-336 50-245 50-336 50-496	R P P
	7812180143 7812210056+ 7812210070+ 7812240012 7812290061+	50-336 50-245 50-245 50-245 50-245 50-336	9 9 9 9		7912260174* 7912260213 7812260219* 7812280137 7812280142*	50-496 50-245 50-245 50-336 50-336	8 8 0
Northeast Utilities	7810110125 7810110127* 7810110140 7810110176 7810120089	50-336 50-336 50-245 50-245 50-245	0 8 8 P	Northern Indiana Public Bervice Co.	7812270149 7812270173* 7812270273 7812270212* 7810130139	50-245 50-245 50-245 50-245 50-347	R 8 8
	7810120096# 7810130138 7810160117	50-245 50-245 50-245	8 8		7810140136 7810270091 7811030144 7811030147 7811080224	30-367 80-376 50-367 80-367 50-367	A R A P

	7811140208 7811170106 7811210360 7811270178 7812050183	50-367 50-367 50-367	А А А Я		7812120094* 7612120094* 7812140143 7812140159 7812140161*	50-292 50-292 50-263 50-304 50-304
	7812050184 7812110119 7812200142 7812210174 7812280120	50-367 50-367 50-367	A R A R R		7812200211 7812200215= 7812200283 7812200287= 7812210036	50-263 50-263 50-263 50-262
Northern States Power Co	7810110180 7810110183• 7810120029 7810120020 7810120031•	50-262 50-263 50-263 50-263	8 8 8 8		7812210036 7812210190 7812260193 7812260207 7812260209*	50~282 50~263 50~282
	7810120032* 7810120033* 7810140116 7810160122 7810170099	50-263 50-282 50-484 50-263 50-263	R R A F		7812260222 7812260237 • 7812260236 7812260238 • 7812270232	50-263 50-263 50-263
	7810170220 7810170224 7810170262# 7810180012 7810180013#	20-583 20-583 20-593 20-583 20-583	5 5 6 8		7812270237* 7812270241 7812270245* 7812270246 7812270251*	50-263 50-263 50-263 50-263
	7810180021 7810180023* 7810180034 7810180036* 7810200078	50-306 50-306 50-306 50-306 50-863	8 8 8	Northrop Corp	781 1020249 781 1020251+ 781 1140149 781 2130342+ 781 0120042+	50-187 50-187 50-187 50-187 50-305
	7810200080> 7810240117 7810250076 7810250076 78103300145	50-263 50-263 50-263 50-263	<b>Ե</b> Ե Ց	(subs. of Control Data Corp.)  Nuclear Energy Liability Insurance Association	7811220075 7811220075 7811220081	50-259 50-3 50-3
	7810300156 7810300156 7810300191 7810300196• 7810300237	50-263 50-263 50-263 50-263	1 1 9 8 P	Nuclear Fuet Bervices, inc. (subs. of	7812110172= 7812110177* 7812180131= 7812180218= 7810300338=	50-344 50-344 50-213 50-10 50-201
	7810310078 7811070215 7811070215 7811070247	50-484 50-282 50-282	8 8 0	Getty Gil Co. )	781 1 100125 701 1 1 70233 781 1 2 70237	50-201 50-201 50-201
	7811140115 7811140117# 7811140117# 7811140117#	90-583 90-583 90-583 90-583	R R	Nuclear Insurance Consultants	7811270290 7811280118 7812150036 7810130223 7811070159	50-201 50-201 50-201 50-375 50-272
	7811140143 7811140180 7811140194 7811150115 7811140116	20-583 20-583 20-593 20-593	р Ј Р Р		7812010256 7812010256 7812040223 7812040223	50-259 50-259 50-272 50-272
	7811140117* 78111210307 7811210334 7811240124	50-263 50-263 50-263 50-263	R P P G	Nuclear Safety Associates Nygaard, G. R. O'Kelly, A. P. O'Nell & Backus	7812050354+ 7810200134 7810170199 7810170060 7812260087	50-549 50-409 50-522 50-443 50-443
	7811240126# 7811240162 7811280195 7811280195	50-282 50-583 50-873	8 B P	Cat Ridge National Laboratory	7812240087 7812240092+ 7812240092+ 7810140084-	50-443 50-443 50-443 50-395 50-468
	7811280234 7811280239* 7811280244* 7811280249*	50-263 50-263 50-263	8 8	Ocean County, NJ	7811270054*  7812080097 7813270182 7811240029 7811240032*	50-395 50-267 50-363 50-363
	7811280253* 7811280256* 7811280263* 7811280279 7811280279	50-263 50-263 50-247 50-282 50-282	8 8 P P	Ditahors Power Bystams (auba. of Westinghouse Electric Corp.)	7810160112 7810230383 7810240103	50-437 50-437 50-437
	7811280338 7812010218 7812050177 7812050141	50-263 50-263 50-262 50-282	ታ B b b		7811090163 7811130857 7811200058# 7812040155	50-497 50-497 50-497
	7812040141 7812040318 7812070221 7812070222> 7812070311	50-263 50-263 50-263 50-263	P P		7812070176 7812200160 7812210451 7812220097	50-437 50-437 50-437 50-437
	7812080135 7812080138* 7812110118	50-306 50-306 50-263 50-263	P P	Uhio Edison Co.	7812270019 7810130137 7810140128 7810230201 7810230201	50-437 50-560 50-560 50-560 50-580
	781211013 <i>b</i> 7812110140* 7812120091		Ř		7010250113	50-580

ì

	7811150128 7811150126	50-580	0	PMB Systems Engineering, Inc.	78102402
Ohio State Univ	7811150131# 7812050194 7812270204 7811200095# 7811200098#	50-580 50-580 50-580 50-346 50-346	8 A A R	Pacific Gat & Electric Co	78101300 78101401 78101601 78101601 78101701
Otlahoma, Univ of Omaha Public Power District	7810110167 7811090082 7810100010 7810100014#	50-112 50-112 50-285 50-285 50-285	P 9 9		78101701 78101702 78101702 78101702 78101702
	7810110100 7810110103* 7810110112 7810110113 7810110114* 7810110117*	50-285 50-285 50-285 50-285 50-285	8 8 8		78101800 78101800 78101801 78101801 78101900
	7810110189 7810110193* 7810110223* 7810130125 7810130126*	50-285 50-285 50-285 50-285 50-285	R R G R		78102401 78102401 78102602 78103003 78103103
	7810130131 7810180159 7810180162# 7810230063# 7810230079	50-285 50-285 50-285 50-285	P 8 8 P F		78103103 78103103 7811010 7811070 7811070
	7810250101 7811060079 7811060200 7811060204* 7811070099	50-285 50-285 50-285 50-285 50-285	F 9 8 9		7811070 7811070 7811080 7811080 7811140
	7811070180 7811130184 7811140107 7811140161# 7811140197	50-285 50-285 50-285 50-285 50-285	P 0 R R		7811140 7811140 7811140 7811150 7811150
	7811150132 7811170193 7811210368 7811210371* 7811280257	50-285 50-285 50-285 50-285 50-285	P 9 8 0		7811210 7811210 7811210 7811210 7811220
	7811280280 7811290390 7812010238 7812010240* 7812040161	50-205 50-285 50-285 50-285 50-285	H 8 8 8		7811220 7811280 7812050 7812050 7812060
	7812030173 7812030179* 7812030193 7812060048* 7812060282*	50-285 50-285 50-285 50-285 50-285	8 8 F 0 Q		7812120 7812120 781213 781213 781214
	7812130111 7812130178 7812130181* 7812200227 7812200231*	30-283 30-283 50-283 30-283 30-283	0 R R B		781214 781215 781215 781219 781219
	7812200264 7812200265 7812200267 7812200272* 7812260203*	50-285 50-285 50-285 50-285 50-285	8 8 8 9		781221 781221 781221 781221 781221
	7812270213 7812270217* 7812270219 7812270224* 7812270238	50-285 50-285 50-285 50-285	8 8 8 8		781221 781221 781221 781221
	7812270262+ 7812270332 781227033+ 7812290176 7812290225	50-285 50-285 50-285 50-285	8 8 8		781221 781221 781221 781221 781221
Oregon State Univ. Oregon, State of	78122702284 7812270193 78122701974 7810300162 7810300165#	50-285 50-106 50-106 50-514 50-514	8 P P O	Parsons, Brinkerhoff, Quade & Dougles, Inc. Pearce & Brand	781221 781224 781205 781221
	7810300167* 7811080062 7811100174 7811150140 7812010361	50-514 50-344 50-344 50-344 50-344		Pannsylvania Power & Light Co.	781011 781011 781021 781021

7811150126 7811150126 30-580 50-580 Oswego, NY PMB Systems Engineering, Inc. 7811040092 7810240203

	7811130073* 7811130077* 7811170123 7811200165 7811200165	50-387 50-387 50-387 50-387 50-387	8 8 8		7812110213 7812130083# 7812130098* 7812130130 7812130162	50-35 50-35 50-35 50-27 50-27
	7811200190# 7811270114 7812050178 7812120096 7812130118	50-387 50-387 50-387 50-387 50-387	X A A A		7812180154 7812180154 7812180157# 7812180160 7812180221	50-27 50-27 50-27 50-27 50-27
	7012210168 7012210168 7812210173 7812210173 7812210177	50-387 50-387 50-387 50-387 50-387	A A A		7812210074* 7812210165 7612220063 7812220063 7812220064*	50-24 50-27 50-27 50-27 50-27
Perkins, Coie, Stone, Disen & Williams	7812210177 7812270221 7810130087 7810300109 7811070357	50-387 50-250 50-322 50-522 50-522	A P O O	Portland Coment Association	7812220064* 7812260192 7812290198 7812110279* 7810110161	50-27 50-27 50-27 50-48 50-34
Pfefferkorn & Cootsy: P.A.	7812130227 7810260065 7810300332 7810300332 7810300332	50-522 50-488 50-468 50-468 50-488	0		7810120009 7810120026 7810120106 7810130147 7810130150+	50-344 50-344 50-344 50-344
	7810300334* 7810300334* 7810300334* 7810300389 78103040297	50-488 50-488 50-488 50-488 50-488	0 0 0		7810140087 7810140122 7810170144 7810170145+ 7810180070	50-344 50-344 50-344 50-344
Philadelphia Electric Co.	7810100038 7810100082 7810100096 7810100101 7810110103	50-277 50-277 50-278 50-277 50-277	8 8 8 8 9		7810170184 7810170217 7810200013 7810200107 7810200108#	50-344 50-344 50-344 50-344
	7810130155 7810130155 7810130163+ 7810200094 7810230164	50-277 50-277 50-277 50-277 50-277	8 8 8		7810240091 7810310167 7810310170• 7811010075 7811010149	50-344 50-344 50-344 50-34
	7810230167• 7810240164 7810270007 7810270186 7810270186	50-277 50-277 50-463 50-277 50-277	R 9 9 P		7811020103 7811070112 7811070152 7811070162 7811070193	50-34- 50-34- 50-34- 50-34- 50-34-
	7810270188+ 7810270261 7810270270+ 7811010089+ 7811080094	50-277 50-278 50-278 50-277 50-277	P 8 0 8		7811070198= 7811070286 7811070364 7811080228 7811100114	50-34- 50-34- 50-34- 50-34-
	7811090137 7811090141* 7811090146 7811090152* 7811140086	50-277 50-277 50-277 50-277 50-278	8 8 8		7811100121# 7811100126# 7811100128# 7811100133# 7811140139	50-34- 50-34- 50-34- 50-34- 50-34-
	7811140142 7811140144* 7811130116 7811130117* 7811160004	50-277 50-277 50-171 50-171 50-277	R H H R		7811140141# 7811140141# 7811140159 7811140101# 7811280315	50-34 50-24 50-34 50-34 50-34
	7811160084 7811160086* 7811160095 7811170130 7811170130	50-277 50-277 50-277 50-277 50-277	R R B R		78112803174 7811280324 7811280327* 7811300374 7812040031*	50-34 50-34 50-34 50-34
	7811170131 • 7811170131 • 7811280225 7811280227 7611260230 •	50-277 50-277 50-277 50-278 50-278	R R 8 8		7812080078 7812110006 7812110169 7812120105 7812120149	50-34 50-34 50-34 50-31 50-34
	781128024B 781128024B 7811280254* 7811280254* 7811280470	50-352 50-352 50-352 50-352 50-278	8 8 9 8		7812120153* 7812140211 7812140267 7812140377 7812270096	50-34 50-31 50-34 50-34 50-34
	7811300217 7811300220+ 7812010012+ 7812070173 7812070210	50-277 50-277 50-277 50-277 50-277	0 0 8 9		7812280128 7812280130* 7812280177 7810100022 7810100024*	50-34 50-34 50-34 50-33 50-33
	7812070213* 7812080109 7812080111* 7812080112* 7812110213	50-277 50-277 50-277 50-277 50-352	Ħ		781010009B 7810100100* 7810110085 7810110074 7810110154	50-28 50-28 50-28 50-28 50-33

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOD!	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CAT
	7810110160 7810120045 7810120046* 7810120058 7810120060*	50-286 50-333 50-333 50-286 50-286	P 8 8 8 8		7812030354* 7812050354* 7812060113 7812070174 7812070178*	50-5 50-5 50-2 50-3
	7810120073 7810120079* 7810130128 7810130132* 7810130167	50-333 50-333 50-333 50-333 50-286	9 8 8 8 8		7812110153 7812120080 7812130168 7812130171* 7812150237	50-2 50-2 50-2 50-2
	7810130180+ 7810170108 7810170111+ 7810170175 7810180075	50-286 50-333 50-333 50-333 50-333	R P P P		7612150241* 7812150274* 7812150274* 7812180368 7812190114	50-3 50-3 50-3 50-3
	7810230186 7810230189• 7810230191 7810230263 7810230265•	50-333 50-333 50-286 50-333 50-333	8 9 8 8		7812220095 7812220098* 7812220099 7812220100* 7812260019*	50-2 50-2 50-2 50-2
	7810230308 7810230310• 7810240080 7810240122 7810240126•	\$0-333 \$0-333 \$0-549 \$0-333 \$0-333	8 8 8		7812260023* 7812260130 7812260189 7812270242 7812270250*	50-2 50-2 50-3 50-3
	7810240133 7810240139• 7810250135• 7810260109 7810270149	50-333 50-333 50-284 50-333	9 6 0 F	Public Citizen Litigation Group	7812290140 7812290170 7812290246 7811270009 7812010357	30-2 30-2 30-4 30-4
	7810300275 7810300280* 7811010111 7811030099 7811040210	50-333 50-333 50-333 50-549 50-286	e o P A B	Public Interest Research Oroup  Public Bervice Co. of Colorado	7812180077 7810270201 7811010010* 7811010013* 7810100005	50-4 50-3 50-3 50-3
	7811050215* 7811070126 7811070244 7811070248* 7811070253	50-286 50-333 50-333 50-333 50-286	9 F 8 B P		7810100012 7810110134 7810110264* 7810120063 7810120064*	50-2 50-2 50-2 50-2
	7811070254* 7811070318 7811070323* 7811080086* 7811080110	50-286 50-333 50-333 50-286 50-286	P 8 9 0 P		7810160100 7810160103* 7810160131 7810170139 7810170174	50-2 50-3 50-3 50-3
	7811080111# 7811080123 7611080127# 7811080127# 7811080183	50-286 50-286 50-286 50-286	P P P P		7810180141 7810230165 7810250067 7810260205 7810270228	50-2 50-2 50-2 50-2
	7811080184* 7811100129* 7811100138* 7811100145* 7811100158*	20-589 20-589 20-589 20-589 20-569	P Q Q Q		7810270232* 7810270276 7810270283# 7810300164 7810300166*	50-2 50-2 50-2 50-2
	7811140104 7811140104* 7811140121 7811140123* 7811140238	50-286 50-286 50-333 50-333	A A A B		7810300179 7810300180* 7810300189 7810300194* 7810300309	50-2 50-2 50-2 50-2
	7811140247 7811140248* 7811140250* 7811160069 7811170110	50-286 50-333 50-286 50-333 50-333	8 8 9		7810300313* 7810310085 7810310094 7810310225 7810310230*	50-2 50-2 50-2 50-2
	7611200023 7611210274 7611210300 7611210389 7611210414	50-549 50-247 50-333 50-333 50-333	<b>P</b> P P B		7811070234 7811070238* 7811160071 7811160096 7811240226	50-2 50-2 50-2 50-2
	7811210422* 7811220169 7811220192* 7811280291 7811280297	50-333 50-286 50-286 50-333 50-549	8 8 P		7811240228* 7811270154 7811270156* 7811280285 7811280289*	50-4 50-4 50-4 50-4
	7811280302+ 7811290182 7812010076+ 7812010085+ 7812040156	50-549 50-286 50-286 50-285 50-333	С Р О В		7611280312 7811280318* 7612070186 7812120089 7812130138	50-1 50-1 50-1 50-1
	7812040159> 7812040203 7812050139 7812050316 7812050350	50-333 50-549 50-549 50-549 50-549	8 A A T		7812130141* 7812130163 7812130164 7812130167* 7812130176	50-2 20-2 50-2 50-2

:

AUTHOR AFFILIATION	ACCEGSION NUMBER	SUBJECT CATEODRY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	7812130177* 7812130165* 7812130190 7812130192* 7812180243	50-267 50-267 50-267 50-267 50-267	8 8		7810250069 7810250083 7810250083 7810250103 7810250104	50-311 50-311 50-311 50-272 50-272	A F R R
	7612180245# 7812200164 7812200209 7812200210# 7812220062	50-267 50-267 50-267 50-267 50-267	R 9 9 F		7810250118 7810250252* 7810250252* 7810310137 7810310180	50-272 50-354 50-354 50-272 50-272	P 8 8 8
	7812220069# 7812270177 7812270201 7812270206# 7810110138	50-267 50-267 50-267 50-267 50-546	F 9 8 A		7810310254 7810310260* 7811030119 7811030120* 7811030124*	50-272 50-272 50-311 50-311 50-311	K K K
	7810300184 7810300365 7811130196 7812080202 7812130128	50-546 50-546 50-546 50-546 50-546	A A Q		7811060099 7811060091 7811070178 7811070181+ 7811070262	50-272 50-272 50-272 50-272 50-272	20000
Public Bervice Co. of New Hampshire	7812290124 7810310189* 7810310189* 7811010244 7811070140*	50-546 50-443 50-443 50-443	A A G 1		7811070265# 7811070266 7811070268* 7811080102 7811080227	50-272 50-272 50-272 50-311 50-311	8 8 8 8 4 4
	7811070140* 7811090147 7811090147 7811090286 7811290341*	50-443 50-443 50-443 50-443	8 8		7811090084 7811130119* 7811130233 7811130263 7811130266	50-311 50-272 50-311 50-272 50-272	A 9 8
Public Service Co. of Gklahome	7811290341* 7810180146 7810240095 7811130066 7811130222	50-443 50-554 50-556 50-556 50-556	8 8		7811140274# 7811160074 78111600754 7811170181 7811170182	50-311 50-272 50-272 50-272 50-311	Q R R R
	7811130222 7811140192 7811140192 7811140214 7811150135	50-556 50-556 50-556 50-556 50-556	F F E		7811200201 7811200203+ 7811200352+ 7811200437+ 7811210323	50-272 50-272 50-437 50-437 50-272	S S A A R
	7811150136° 7811160081 7811160081 78111800230 7812050285°	50-554 50-554 50-554 50-554 50-554	& A B Q		7811210343 7811240132 7811240137+ 7811240141 7811240142+	50-272 50-272 50-272 50-311 50-311	R B B A A
	7812130138 7812220115 7812220115 7812270200 7812270200	50-554 50-554 50-554 50-554 50-554	****		7811240219 7811240225 7811280275 7811280304 7811280313*	50-272 50-311 50-272 50-272 30-272	P & J 8 6
Public Service Electric & Gas Co. of New	7819290231 7810100020	50-556 50-354	A		7811280460 7812050229	50-272 50-272	8 9
Jersey	7810100020 7810100028 7810100033*	50-354 50-979 50-979	8		7812070224 7812080113 7812080115*	50-354 50-272 50-272	R R
	7810100037 7810100041* 7810100087 7810100089* 7810110091	50-272 50-272 50-272 50-272 50-272	8 9		7812080134 7812080136= 7812110150 7812120151 7812140167	50-272 50-272 50-272 50-272 50-272	R Q R B
	7810130134 7810160084 7810160090» 7810170132 7810170132	50-311 50-272 50-272 50-272 50-272	ARREP	•	7812140169* 7812150242 7812150244* 7812200072 7812210206	50-272 50-272 50-272 50-311 50-272	8 R R A
	7810170133* 7810170133* 7810170135* 7810170135*	50-272 50-272 50-272 50-272 50-272	p p p		7812220085 7812220086* 7812220143 7812270194 7812270248	50~272 50~272 50~211 50~339 50~477	9 4 8
	7810180092 7810180128 7810180128 7810180144 7810180144	50-272 50-272 50-272 50-272	A A A A		7812270248 7812280346 7812280200* 7812280200* 7812280204*	50-477 50-272 50-477 50-477 50-477	4000
	7810200117 7810200195* 7810230243 7810230249* 7810230252	50-27 <i>2</i> 50-27 <i>2</i> 50-27 <i>2</i>		Puget Sound Pawer & Light Co.	7812280204* 7812280216* 7812290161 7812290161 7811080142 7811080153	50-477 50-311 50-272 50-522 50-522	O O P F A
	7810230295 7810230295 78102303044 7810240083 7810240149	50-272	8 8 P	Pylm, R.S. Rand Corp. Reilly & Like	7812050180 7812140247 7811200018# 7811200019# 7810110307	50-522 50-518 50-437 50-437 50-322	4044

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCEBSION RAGMUN	SUBJECT CATEODRY
	7810190226 7810190226 7810190235 7810200156 7810200156	50-516 50-516 50-516 50-516 50-516	0000		7811160078* 7811170117 7811210261 7811210319 7811270096*	50-312 R 50-312 P 50-312 F 50-312 P 50-312 Q
	7810240097 7810270301 7810310374 7811200002 7811200020	50-516 50-322 50-516 50-322 50-516	0 A 0		7811280209 7812050114 7812050146 7812080094 7812110170	50-312 P 50-312 P 50-312 P 50-312 B
Rensselaer Polytechnic Inst. Rhode Island, Otate of	7812110012 7812150019 7812210471 7811010071 7810180084	30-322 30-314 30-322 50-223 50-568	0 0 0 7 A		7812110173+ 7812120147 7812130107 7812140142 7812180159	50-312 8 50-312 8 50-312 P 50-312 0 50-312 F
Rochester Gas & Electric Corp.	7811010132 7811010436 7812010204 7812010335+ 7810160111+	50-568 50-568 50-568 50-568 50-244	A Q Q P	Bafe Energy for New Haven	7812200159 7812200196 7812200197* 7811010310 7812130084*	50-312 P 50-312 R 50-312 R 50-502 Q 50-502 Q
	7810160129 7810170182 7810170213 7810170215* 7810170257	50-244 50-244 50-244 50-244 50-244	P R R F	Baginaw Archaeological Commission San Diego Cae & Electric Co. Ban Luis Obispo Mothers for Peace	7810130231 7810260118* 7811280007* 7810300008 7811010324	50-329 A 50-361 K 50-206 P 50-275 0 50-275 0
	7810170263* 7810180150* 7810190069* 7810230256 7811010376	50-244 50-244 50-244 50-244 50-485	P P 9 9	Sargent & Lundy, Inc. Scribe, NY Senate	7812180309 7812050190* 7812130090 7810110203* 7810110205*	50-275 Q 50-367 A 50-220 Q 50-70 P 50-70 P
	7811040088 7811070142 7811070182 7811130232 7811140241	50-244 50-244 50-244 50-244 50-244	F P P		7810240011* 7810240137* 7811080039 7811220132 7811240094*	50-440 A 50-480 H 50-70 P 50-267 U 50-70 U
	7811280216 7811290179 7811290245 7812050152 7812050187	50-244 50-244 50-244 50-244 50-244	P P P P		7812080211* 7812130326 7812140331* 7812190236 7812280248	50-302 U 50-400 U 50-437 H 50-440 Q 50-502 H
	7812080123 7812080126 7812130012 7812220116+ 7812280191	50-244 50-244 50-244 50-244 50-485	P P F P	Senate, Governmental Affairs Shaw, Pittman, Potts & Trowbridge	7812260254 7812120041* 7810130225 7810140022 7810140091	50-338 H 50-580 H 50-266 Q 50-484 Q
Rockwell International Corp. Ropes & Gray	7812290090 7810270197 7810310185 7811070001 7811070004+	50-244 50-94 50-443 50-471 50-471	P J A Q Q		7810190210 7810190230 781 <i>020003</i> 4 7810200177 7810200177	50-484
Bacramento Municipal Utility District	7811070138 7812010057# 7810100016 7810100021# 7810100050	50-443 50-471 50-312 50-312 50-312	1 9 8 8		7810200182* 7810200182* 7810230326 7810240227 7810240227	30-483 Q 50-483 Q 50-246 Q 50-493 Q 50-483 Q
	7810100056* 7810100061 7810100069* 7810100073 7810100077*	50-312 50-312 50-312 50-312 50-312	8 8 8 8		7810270005 7810300267 7810310078 7811010080 7811010285	50-484 Q 50-580 Q 50-484 Q 50-484 Q 50-436 M
	7810110124 7810110126+ 7810120027 7810130131 7810130135=	50-312 50-312 50-312 50-312	R R P B		7811010285 7811070137 7811070322 7811130071 7811130146	50-346 M 50-440 A 50-502 0 50-483 0 50-346 M
	7610130178 7610170199 7610170201# 7610200104 7610200106#	50-312 50-312 50-312 50-312	8 8 8		7811130146 7811130146 7811130146 7811130230* 7811130230*	50~346 M 50~346 M 50~346 M 50~346 M
	7810230079 7810230160 7810230277 '7810230285* 7810230184	50-312 50-312 50-312 50-312	F 8 8 9		7811130230# 7811270048 7811270048 7811270050# 7811270050#	50~346 M 50~483 G 50~483 G 50~483 G 50~483 G
	7810310087 7811030149 7811030152* 7811030153 7811030156*	50-312 50-312 50-312 50-312	e e 8 8		7812010314 7812080233 7812110254 7812130087 7812210486	50-400 Q 50-580 Q 50-483 Q 50-483 Q 50-020 Q
	7611070201 7811130089 7811140230 7811140236* 7811160076	50-312 50-312 50-312 50-312	P Q B B R		7812220109 7812220141 7812280079 7812280345 7812290100	50~502 Q 50~320 Q 50~400 Q 50~440 Q 50~502 Q

AUTHOR AFFILIATION	ACCERSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCEBBION NUMBER	SU CA
Sheldon, Harmon & Weiss	7812290105* 7810300039 7810300039 7810300057* 7810300057*	50-502 50-338 50-338 50-338	0 P G 0		7811080103 7811100043 7811100045 7811100045 7811100047	50- 50- 50- 50-
Bierra Club	7810300065+ 7810300065+ 7812110101 7812280158 7811280157+	50-338 50-338 50-338 50-338 50-458	0 0 0		7811100048 7811140177 7811140181* 7811160080 7811160082*	50- 50- 50- 50-
Bimmonds, Winslow, Willis & Abbott Biagitonians Concerned About Nuclear Power	7812270009+ 7811210140 7810120089	50-220 50-471 50-522	A Q		781 1210316 781 1210377 781 1220146 781 1220148	50- 50- 50-
	7812150259 7812190080	50-443 50-522	0		7811220169* 7811220169*	50. 50.
Snell & Wilmer South Carolina Electric & Gas Co	7811020082 7810120070* 7810120137 7810130046 7810130108*	50-592 50-395 50-395 50-395 50-395	A A Q C		7811280212 7811280217 7811280217 7811280257	50 50 50 50
	7810170105 7810170163 7810170227 7810170239* 7810230161	50-395 50-395 50-395 50-395 50-395	A 0 0 0 4		7811260277 7811280281* 7811300209 7812040193 7812050186	50 50 50 50
	7810300217 7810300384 7810300387* 7810310083 7811010120	50-395 50-395 50-395 50-395 50-395	A 0 0 A K		7812050219 7812060069 7812120101 7812130177 7812130210+	50- 50- 50- 50-
	7811010125* 7811010173 7811070128 7811080151* 7811080232	50-395 50-395 50-395 50-395 50-395	K C A Q		7812130280 7812190150 7812190120 7812190124 7812190124	50 50 50 50
	7811150062* 7811150161 7811210286 7811210397 7811220164	50-395 50-395 50-395 50-395 50-395	Q F K A		7812190150 7812190157 7812190159* 7812200132 7812210098*	50 50 50 50
	7811220280 7812010329 7812040167 7812050231 7812050028#	50-395 50-395 50-395 50-395 50-395	0 8 0		7812210263* 7812210263* 7812210265* 7812210265* 7812210388*	50 50 50 50
	7812040374 7812120029 7812120156 7812120200 7812120206*	50-395 50-395 50-395 50-395 50-395	Q Q A R R		7612220082 7612270165 7612270196 7612270199* 7612270205	50 50 50 50 50
	7812130364 7812140037 7812200288 7612200289* 7812280302	50-395 50-395 50-395 50-395 50-395	0 B J J 0	Bplegel & McDtaratd	7812290113 78122901154 7810270390 7811030245 7811080064	50 50 50 50
Bouth Carolina, Univ. of Southern Gelifornie Edison Co.	7810240077# 7810110096 7810130159 7810130160# 7810170103	50-269 50-206 50-206 50-26	R P R R		7811100163 7811100180 7812040260 7812180246 7812180334	50 50 50 50
	7810180083 7810180089 7810180184 7810180187 7810230101	50-361 50-206 50-361 50-206 50-361	A 8 A 8 B	Bisndardited Nuclear Unit Power Plant Bystem Stanford Univ.	7812180342* 7812270063 7812270071 7812270038 7811010220	50 50 50 50
	7810230101 7810230105 7810230135 7810230268 7810250039 7810250066	50-204 50-204 50-204 50-204 50-204	P	Stempord Univ. Stome & Webster, Inc.	7811020313 7811240072* 78122050354* 7812200177* 7812290275*	50 50 50 50
	7810250123 7810240115 7810240118# 7810240118# 7810270214	30-206 30-361 50-361 50-361 50-206	8 K K	Buffolk County, NY	7810140107 7811210110 7811290311 7811300373 7819210411	50 50 50 50
	7810270214* 7810300098 7810310132 7811010167 7811010167	50-205 50-206 50-206 50-351 50-361	P H	Sullivan W. F. Taunbon Municipal Lighting Plant Tennessee Valley Authority	7812260322 7812070054* 7811070156* 7810100002 7810100006*	50 50 50 50
	7811060050 7811060086 7811060104 7811070243	50-361 50-206 50-206 50-206	F		7810100036 7810100040+ 7810100042 7810100047+	50 50 50

ţ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO!	
	7810110107 7810110107 7810110158 7810120065 7810160106	50-259 50-259 50-327 50-259 50-259	P A P R		7811060090 7811060094 7811060094 7811060096 7811060096	50-390 50-327 50-327 50-390 50-390	9 A A 6 S
	7810160106 7810160106 7810160109# 7810170161# 7810170197	50-259 50-259 50-259 50-259 50-327	2 2 3 3		7811070109 7811070132 7811070236 7811070236 7811070240#	50-438 50-296 50-327 50-327 50-327	K P 8 9
	7810170206 7810170206 7810170237# 7810180093 7810180093	50-390 50-390 50-321 50-327 50-327	8 8 8		7811070240+ 7811070245 7011070245 7011070249+ 7811070249+	50-327 50-518 50-518 50-518 50-518	A 8 9
	7810180138 7810180142* 7810190164 7810190164 7810190228	50-260 50-260 50-327 50-327 50-390	8 9 8		7811070276 7811070277 7811070277 7811070277 7811070277	50~327 50-327 50-327 50-327 50-327	8 A A A
	7810230135 7810230135 7810230227* 7810230244 7810230244	50-327 50-327 50-259 50-259 50-259	F 0 P P		7011070277 7011070277 7011070277 7011070277 7011070201	50-327 50-327 50-327 50-327 50-327	A A A
	7810230244 7810240037 7810240144 7810240144 7810240146	50-259 50-564 50-259 50-259 50-296	P 0 P 2	•	7811070281* 7811070281* 7811070281* 7811070281* 7811070281*	50-327 50-327 50-327 50-327 50-327	A A A A
	7610240151+ 7810240153 7810250035 7810250080 7810250082	50-296 50-259 50-260 50-296 50-260	8 8 8		7811070281* 7811070281* 7811080114 7811080132	50-327 50-327 50-390 50-390 50-390	۸ ۸ ۸
	7810250085# 7810250089 7810250088 7810250095 7810250095	50-240 50-566 50-566 50-327 50-327	Р F Q		7811080132 7811080134* 7811080134* 7811080160 7811080164	\$0-390 \$0-390 \$0-390 \$0-390 \$0-518	K K K F
	7810250120 7810250120 7810250122* 7810250122* 7810300103	50-327 50-327 50-327 50-327 50-259	A A A R		7811080]64 7811080164 7811080164 7811080167* 7811080234*	50-518 50-518 50-518 50-518 50-438	A A O
	7810300103 7810300169 7810300171* 7810310064* 7810310076	50-259 50-260 50-260 50-259 50-259	8 9 0 F		7811090204* 7811130013* 7811130013* 7811130013* 7811140134	50-259 50-259 50-259 50-259 50-327	0 0 0 0 F
	7810310076 7810310113 7810310113 7810310183 7810310186*	50-259 50-327 50-327 50-259 50-259	F F 8		7811140134 7811140137 7811140140* 7811140140* 7811140165	50-327 50-259 50-259 50-259 50-294	F R R B
	7811010073 7811010073 7811020074 7811020231 7811020231	50-327 50-327 50-438 50-438 50-438	A A K K		7811140168 7833140186 7831140193* 7831140201 7831140206*	50-296 50-296 50-296 50-296 50-296	8 8 8
	7611020234 # 7611020234 # 7611020362 7811030078 # 7611030101	50-438 50-438 50-259 50-438 50-390	К 8 0 Р		7811140217 7811140221* 7811140240 7811140244* 7811150120	50-259 50-259 50-259 50-259 50-390	8 8 8
	7811030104# 7811030257 7811030257 7811030260# 7811030260#	50-390 50-438 50-438 50-438 50-438	A 8 8 8		7811150120 7811150123 7811150123 7811150128 7811150129*	50-390 50-327 50-327 50-260 50-260	H F P
	7811030243 7811030243 7811030245* 7811030245* 7811040043	50-327 50-327 50-327 50-327 50-370	8 9 8 A		7811150137 7811150152 7811150152 7811150176# 7811150176#	50-327 50-327 50-327 50-327 50-327	A A A A
	7811040063 7811040063 7811040063 7811040063 7811040063	50-327 50-390 50-327 50-390 50-390	8 4 8 4 8		7811150196# 7811150199# 7811160067 7811160067 7811160072#	50-327 50-327 50-438 50-438 50-438	A B 8
	7811060063 7811060063 7811060069* 7811060069* 7811060090	50-327 50-327 50-390 50-390 50-390	8 8 8 8		78111600724 7811160098 7811160098 7811160099 7811160104#	50-438 50-327 50-327 50-296 50-296	8 4 8

### CORPORATE SOURCE INDEX

AUTHOR AFF IL I AT I ON	ACCEBBION NUMBER	BUBJECT CATEOGR	lY .	AUTHOR AFFILIATION	ACCESSION NUMBER	SUB JEC CATEGO	RY
	7811140148 7811140148 7811170113 7811170113 7811170113	50-327 50-327 50-259 50-259 50-259	A A P P		7812080213 7812080213 7812080213 7812080221+ 7812080221+	50-518 50-518 50-518 50-518 50-518	9 9 8 8
	7811170175 7811170175 7811170215 7811170215 7811170215	50-259 50-259 50-259 50-259 50-259	P P P P		78120902214 7812080221* 7812080221* 7812080221* 7812080229	50-518 50-518 50-518 50-518 50-390	8 8
	7811200200 7811200200 7811210305 7811210310* 7811210406	50-259 50-259 50-327 50-327 50-518	F F A A		7812110017 7812110017 7812110142 7812110148 7812120075	50-390 50-390 50-327 50-296 50-390	8 4 8
	7811210406 7811220091* 7811220147 7811220147 7811220211	50-518 50-260 50-390 50-390 50-553	A 0 A A A		7812120099 7812120099 7812120158 7812120158 7812120166	50-390 50-390 50-327 50-327 50-327	0 A A K
	7811280187 7811280191• 7811280201 7811280203• 7811280205	50-259 50-259 50-260 50-260 50-259	8 8 8		7812120166 7812120170 7812120170 7812120174 7812120177#	50-327 50-327 50-327 50-260 50-260	8 8
	7811280207+ 7811280214 7811280251 7811280255 7811280294	50-259 50-259 50-438 50-296 50-296	8 8 A P 8		7812130372 7812130372 7812130372 7812140286 7812140286	50-259 50-259 50-259 50-327	9 9 9
	7811280298+ 7811290248 7811290248 7811290252+ 7811290252+	50-296 50-390 50-390 50-390 50-390	8 K K K		7812140288* 7812140288* 7812180248 7812180350 7812180130	50-327 50-327 50-296 50-327 50-327	8 0 A A
	7811300198 7812010266 7812010266 7812010268* 7812010268*	50-327 50-327 50-327 50-327 50-327	8 8 8		7812180130 7812190098 7812190110 7812190111* 7812190119	50-327 50-390 50-296 50-296 50-296	8 8 8
	7812040055* 7812040055* 7812040192 7812040197* 7812040226	50-390 50-390 50-327 50-327 50-390	0 8 8		7812190122* 7812190161 7812190161 7812190161 7812190162*	50-276 50-257 50-257 50-257 50-257	2 R R R
	7812040226 7812040227* 7812040227* 7812050117* 7812050117*	50-390 50-390 50-390 50-327 50-327	B B G		7812190162# 7812190162# 7812200184 7812200184 7812200184	50-259 50-259 50-259 50-259 50-259	R R P P
	7812050125# 7812050171 7812050189 7812050199 7812050201#	50-327 50-296 50-259 50-296 50-296	Q P B B		7812200244 7812200244 7812200244 7812200246* 7812200246*	50-259 50-259 50-259 50-259 50-259	K K K K
	7812050243 7812050265 7812050265 7812050266 7812050266	50-259 50-327 50-327 50-390 50-390	P 8 8 8		7812200246#* 7812200256 7812200256 7812200256 7812210248	50-259 50-259 50-259 50-259 50-257	K P P P
	7812050268+ 7812050268+ 7812050270+ 7812050270+ 7812060021+	50-390 50-390 50-327 50-327 50-259	8 8 8 0		7819210248 7819240131 7819240131 7819240134+ 7819240134+	50-327 50-327 50-327 50-327 50-327	FKKK
	7812060074* 7812060074* 7812060121 7812060121 7812060127*	50-327 50-327 50-327 50-327 50-327	0 8 8 8		7812240163 7812270175 7812270175 7812270202 7812270202	50-259 50-259 50-259 50-327 50-327	PPAA
	7812050129# 7812070170 7812070177 7812070183 7812070250	50-327 50-259 50-327 50-566 50-390	8 P Q A B		7819270265 7819270269* 7819270043* 7819290043* 7819290056*	50-259 50-259 50-390 50-390 50-438	8000
	7812070250 7812070259* 7812070259* 7812070264 7812080091	50-390 50-390 50-390 50-260 50-327	8 8 8		781 0290117* 781 0290117* 781 0290104 781 0290217 781 0290217	50-327 50-327 50-390 50-259 50-259	0 4 4 4
	7812080101 7812080103*	90-860 90-860	8 8	Tannesess Shaka ad	7812270221 7812270224*	80-240 80-240	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	8/
Texas Public Interest Research Group	7812220080> 7810140132 78101401344 7811140196 7811210038	50-59 F 50-466 H 50-466 H 50-466 Q		7811070273 7811070275* 7811070131 7811070178 7811070179*	50- 50- 50- 50-
Texas Tech Univ. Texas Utilities Co.	7811210044* 7812180306 7811210046 7810140141 7810240221*	50-466 G 50-466 G 50-416 A 50-445 M 50-445 G		7811130230# 7811140135 7811140136# 7811150124 7811170100	50- 50- 50- 50-
Texas Utilities Ganerating Co.	7811170133 7812190070 7812210130 7812270259 7810240161	50-445 A 50-445 K 50-445 A 50-445 K 50-445 A		7811200087 7811200100* 7811200106* 7811200178 7811200209	50- 50- 50- 50-
	7810240186 7811030249# 7811070134 7811070260# 7811070260#	50-445 A 50-445 Q 50-445 B 50-445 Q 50-445 O		7811200212# 7811210347 7811210352# 7811210357# 7811210359#	50- 50- 50- 50-
	7811080031 7811210348 7811210401 7811280183 7811280218	50-445 G 50-445 A 50-445 B 50-445 B 50-445 A		7811210362* 7811210372 7811210374* 7811210375* 7811210379*	50- 50- 50- 50-
	7811280367 7811280367 7811300020# 7811300109* 7812070111	50-445 8 50-445 8 50-445 0 50-445 0		7811210382* 7811220158 7811220174 7811240159 7811280198	50- 50- 50- 50-
	7812070111 7812070116# 7812070116# 7812150264 7812150266#	50-445 K 50-445 K 50-445 K 50-445 C 50-445 C		7811280202* 7812010207 7812010213* 7812040228 7812030157	50- 50- 50- 50-
	7812190142# 7812190142# 7812190232 7812190232 7812200184	50-445 G 50-445 G 50-445 G 50-445 G 50-445 A		7812050162* 7812050163 7812050204 7812050206* 7812050217	50- 50- 50- 50- 50-
	7812200184 7812200186* 7812200186* 7812280109 7812280109	30-445 A 50-445 A 50-445 A 50-445 B 50-445 B	·	7812050218* 7812070196 7812070198 7812070199* 7812070201*	50- 50- 50- 50-
Texas Utilities Bervices, Inc. Texas, State of Thomsen, F. T.	7811220083 7811020378 7811290014 7812130231 7810190199	50-445 A 50-445 M 50-478 G 50-478 M 50-522 G		7812120140 7812120146* 7812120145 7812120172 7812120173*	50- 50- 50- 50- 50-
Taledo Edison Cp.	7810100060 7810100063* 7810120074 7810120078* 7810120084*	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8		7812120181* 7812140137 7812140140* 7812150278 7812150278	50- 50- 50- 50- 50-
	7810130142 7810130144* 7810160127* 7810160127* 7810160137	50-346 R 50-346 R 50-346 B 50-346 S 50-346 B		7812130276 7812130278* 7812180134 7812180206 7812190081	50- 50- 50- 50-
	7810160140* 7810180041 7810180042* 7810230269 7810230275*	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8		7812190115 7812190116* 7812200166 7812270256 7812290200	50- 50- 50- 50- 50-
	7810270171 7810270177 7810310194 7810310201# 7810310303	50-346 P 50-346 P 50-346 9 50-346 8 50-346 8	Trans-Eastern Inspection Services, Inc. Transportation, Dept. of Trassury, Dept. of Trojan Decommissioning Alliance	7812290208* 7812200127 7810230170 7812140325 7812080156*	50 50 50 50
	7810310309* 7810310330* 7810310342* 7810310346* 7811010066	50-346 S 50-346 S 50-346 S 50-346 S 50-500 A	Union Carbide Corp.  Union Electric Co.	7811160147 7812190091 7812270164 7812290157 7812200237	50 50 50 50
	7811010066 7811010129 7811010129 7811030137 7811030138*	50-500 A 50-500 I 50-500 I 50-346 B 50-346 B	Valentine, P. C. Varmont Electric Cooperative, Inc. Varmont Electric Power Co., Inc.	7812290277 7811070358 7811070143* 7811070141* 7811070143*	50- 50- 50- 50-
	7811060118 7811070184 7811070188* 7811070264 7811070267*	50-346 P 50-346 B 50-346 B 50-346 B 50-346 B	Vermont Yankee Nuclear Power Corp.	7810160133 7810170192 7810170193* 7810200090 7810310244	50 50 50 50

AUTHOR AFFIL 1ATION	ACCEBBION NUMBER	EUBJECT CATEOORY		AUTHC AFFILIAT	ACCEBSION NUMBER	CATEODR	
	7810310246+ 7811020173+ 7811090166 7811140125 7811140127+	50-271 5 50-271			 7810270112 7810270153 7810270153 7810270174 7810270174	50-404 50-338 50-338 50-280 50-260	APPP
	7811140224 7811160102 7811160103# 7811160128 7811160130#	50-271 50-271 50-271	P 8 8 8 9		7810270223+ 7810270223+ 7810300022 7810300022 7810310089	50-280 50-280 50-280 50-280 50-338	PFFG
	7811270130 7811270134* 7812050130 7812150290 7812150292*	50-271 50-271 50-271	ዎ ዎ F R R		7810310238 7810310242* 7810310252* 7811010415* 7811020306	50-338 50-338 50-338 50-280 50-338	8 9 0 R
	7812180173 7812180176# 7812180190 7812180193 7812180194#	50-271 50-271 50-271	8 8 8 8		7811020306 7811020305 78110203124 7811030160 7811030160	50-338 50-338 50-338 50-338 50-338	R R P P
	7812180199# 7812180213 7812180216# 7812180219 7812180222#	50-271 50-271 50-271	e 8 8 8 8		7611060038* 7611060078 7611060102 7611060211 7611060213*	50-338 50-338 50-339 50-261 50-261	9 A 8
Varmont, State of Virginia Electric & Power Co.	7812180237 7812180241# 7812270274 7810240145 7810100057	50-271 50-271	8 8 F P B		7811060217# 7811060233 7811060237# 7811060240# 7811060242#	50-281 50-338 50-338 50-338 50-338	9 8 8 8
	7810100045* 7810100074 7810100079* 7810110127 7810110132*	50-280 50-280 50-280 50-280 50-280	8 9 9		7811060245* 7811070130 7811070130 7811070146 7811070146	50-338 50-280 50-338 50-338	81 P P P
	7810:10149 7810:10:49 7810:10162 78101:0162 78101:200:34	50-238 50-338 50-338 50-338 60-280	р Р Р		7811070151* 7811070151* 7811070190 7811070190 7811070228	50-338 50-338 50-280 50-280 50-338	6 6 8
	7810130140 7810130141 7810130146* 7810130146* 7810160139	50-338 50-338 50-338 50-338 50-280	8 9 8 8 P		7811070233+ 7811070237+ 78110702414 7811070258 7811070261+	50-338 50-338 50-338 50-338 50-338	8 8 8
	7610160198 7810170109 7810170160 7810180119 7810180119	50-280 50-404 50-338 50-280 50-280	P P P		7811070326 7811070367 7811070367 7811070177 7811090210*	50-339 50-338 50-338 50-280 50-280	80088
	7810180121# 7810180139 7810200034 7810200038# 7810200073	50-280 50-339 50-339 50-339 50-338	P J A A P		7811090215# 7811090217# 7811090219# 7811090236 7811090240#	50-281 50-280 50-280	8 8 8
	7810200109 7810200110 7810200112* 7810200118* 7810230171	50-281 50-280 50-281 50-280 50-338	8 8 8 R		7811070243 7811130149 7811130238# 7811140101 7811140128	50-339 50-338 50-280 50-336 50-280	9 9 9
	7810230174* 7810230184 7810230184 7810230187* 7810230187*	50-338 50-280 50-280 50-280 50-280	R R R R		7611140129 7611140087 7811170107 7811170109* 7811170182	50-339 50-339 50-338 50-338 50-338	9 A R R B
	7810230254 7810230257 7810230260* 7810230262* 7810230264	50-338 50-281 50-338 50-281 50-339	8 8 8 8		7811170183 7811170183 7811170184» 7811170185» 7811170185»	50-260 50-260 50-238 50-260 50-260	888888
	7910230283 7810230291* 7810230297 7810230307 7810240140	50-338 50-338 50-339 50-404 60-339	8 A A		7811170189# 7811170192* 7811170192* 7811200133* 7811200194	50-338 50-280 50-280 50-280 50-280	B R R G
	7810250232 7810260121 78102601284 78102601274 7810260130#	50-336	P	•	7811200194 7811200198* 7811200198* 7811210259 7811210254*	50-260 50-260 50-260 50-261 50-261	RRRB
	7810240131# 7810240132# 7810240133# 7810240135# 7810240144#	50-338 50-338 50-338			7811210290 7811210294* 7811210309 7811210313 7811210315*	50-338 50-338 50-339 50-338 50-338	8 8

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT		AUTHOR Affiliation	ACCEBBION NUMBER	SUBJE
	7811210399 7811220145 7811220145 7811220145 7811220148+	50-339 50-338 50-338 50-338 50-338	9 P P P		7812180433 7812190079 7812190088 7812190088 7812190090	50-280 50-280 50-280 50-280 50-280
	7811240050+ 7811240111 7811240111 7811280200 7811280236	50-338 50-338 50-338 50-404 50-280	Q P A 8		7812190090 7812190148 7812190148 7812190149# 7812190149#	50-280 50-280 50-280 50-280 50-280
	7811280238* 7811280247 7811280247 7811280286 7811280292*	50-280 50-280 50-281 50-281	\$ P & \$		7812200169 7812200169 7812200204 7812200204 7812200207#	50-280 50-280 50-280 50-280 50-280
	7811280308 7811280316 7811280320• 7811280321• 7811280322	50-338 50-338 50-338 50-338 50-338	P 8 8 8		7812200207* 7812200212 7812200225 7812200234 7812200239*	50-280 50-338 50-339 50-338 50-338
	7811280325+ 7811280326+ 7811280330+ 7811300222 7811300222	50-338 50-338 50-338 50-280 50-280	8 8 9 P	•	7812200253 7812200255* 7812200257* 7812200260 7812200260	50-338 50-338 50-338 50-280 50-280
	7812010255 7812010255 7812010255 7812010264 7812010265*	50-338 50-338 50-338 50-338 50-338	A A A R		7612200262# 7812220076 7612240195 7612240195 7612240252	50-280 50-339 50-338 50-338 50-280
	78:201032: 78:2040209 78:2040211+ 78:2040213+ 78:2040215+	50-339 50-338 50-338 50-338	8 8 8		7612260255 7612270170 7812270170 7812270189 7612270189	50-339 50-338 50-338 50-338 50-338
	7812040217* 7812040230 7812040233* 7812050208 7812050209*	50-280 50-260 50-260 50-280	9 8 8 8		7812270235 7812270238* 7812270270 7812270281* 7812270290	50-338 50-338 50-281 50-281 50-280
	7812050211* 7812050214* 7812050223 7812050226* 7812060134	50-338 50-338 50-338	8 8 8		7812270274# 7612270320 7812270324# 7812280132 7812280136	50-338 50-280 50-280 50-338
	7812060134 7812060142* 7812060142* 7812070169 7812070190*	50-338 50-338 50-338 50-338 50-338	8 8 8	Virginia. State of Virginia. Univ. of	7812280259 7812280259 7810180143 7811080035 7811010102	50-338 50-338 50-437 50-338 50-62
	7812070193 7812070195* 7812070271 7812110090 7812110149	50-338 50-338 50-338 50-338 50-338	8 8 9 8 P		7811080179 7812200221 7812200222 7812200232 7812260144	50-62 50-62 50-62 50-62
	7812110191 7812110192* 7812110193 7812110196* 7812110204	50-338 50-338 50-338 50-338	9 9 9 8 8	Vollen, R. J. & Whicher, J.M. Wald, Herkrader & Ross Washington Public Power Bupply Bystem	7811160050 7812180246 7810110206* 7811010119 7811020245	50-367 50-329 50-460 50-397 50-460
	7612110206* 7612120063 7612120117 7612130361 7612130361	50-338 50-339 50-339 50-260 50-260	A A Q Q		7811020245 7811020249* 7811020249* 7811070147* 7811070269	50-460 50-460 50-460 50-397 50-397
	7612130381 7612130381 7612140125 7612140126# 7612140129#	50-260 50-260 50-260 50-260 50-260	8 8 8		7811070270* 7811150021 7811220197* 7811280265 7812070208	50-397 50-397 50-397 50-397 50-397
	7812140131* 7612140224 7812140227* 7612140234* 7612150094	50-280 50-281 50-281 50-281 50-338	8 8 8		7812130110 7812130180 7812210141* 7812270183 7812280144	50-397 50-397 50-460 50-397 50-397
	7812150277 7812150282 7812150289 7812150304 7812180302*	50-338 50-338 50-338	P P P Q	Washington, State of	7812290148 7812290151* 7905090295 7811080088 7811140279	50-508 50-508 50-397 50-397 50-522
	7812180358* 7812180358* 7812180432 7812180433 7812180433	50-280 50-280 50-280 50-280	G G P P	Watts, A. R. Hestinghouse Electric Corp	7811140279 7811160042 7811160042 7811200411 7810190186	50-522 50-522 50-522 50-572

:

	7810190248 7811030146 7811140131= 7811140131= 7811140133=	50-87 50-22 50-266 50-266 50-266	0 0 P P		7810100062* 7810110073 7810110130 7810120041 7810120149	50-205 50-305 50-305 50-305 50-305
	7811140133# 7811160127 7811210234 7811240164 7811240165	50-266 50-572 50-275 50-445 50-445	P 8 A A		7810170155 7810170159* 7810230247 7810230231* 7810240128	50-305 50-305 50-305 50-305 50-305
	7812080039 7812080039 7812080043+ 7812080043+ 7812080142+	50-272 50-272 50-272 50-272 50-306	р Р		7810240138• 7810270139 7810300105 7811070727 7811140116	50-305 50-305 50-305 50-305 50-305
	7812190140 7812200145 7812200190 7812200249 7812200251+	50-545 50-395 50-568 50-582 50-537	A H A H A		7811140118* 7811140196 7811220196 7811220197 7811220197	50-305 50-305 50-305 50-305 50-305
Wilt, D.O Wisconsin Electric Power Co.	781 2290136 781 2290141* 781 0240016* 781 0170153 781 0170153	50-480 50-480 50-440 50-266 50-266	A A P P		7811280305# 7811280310# 7812080108 7812130220 7812150232	50-305 50-305 50-305 50-305 50-305
	7810170171 7810170173* 7810180038 7810180040* 7810180043	50-266 50-266 50-266 50-266	8 8 8	Wisconsin, State of	7812150234* 7812210194 7812270171 7810190085 7810190085	50-305 50-305 50-305 50-266 50-266
	7810180046+ 7810180099 7810180102+ 7810190126+ 7810230272	50-266 50-301 50-301 50-266 50-266	8 R R P		7810170088* 7810170088* 7811200040 7812130087* 7812220027	50-266 50-266 50-484 50-502 50-305
	7810230272 7810250086 7810250108 7811070374 7811130203	50-266 50-502 50-266 50-266	P A A Q P	Hisconsin, Univ. of, Milwaptee Worcester Polytechnic Inst.	7812220029 7812220031# 7812270050 7811200092* 7811240038	50-305 50-305 50-266 50-346 50-134
	7811140102 78111401081 7811140124 7811140124 7811140171	20-203 20-369 20-369 20-203	ለ A P P B	Y 1, Inc. Yankme Atomic Electric Co.	7812080203* 7810110163 7810110177 7810130127 7810170176	50-546 50-29 50-29 50-29 50-29
	7811140173+ 7811140174 7811140178+ 7811150167 7811150173+	20-599 20-599 20-599 20-599	8 8 8 F		7810170178* 7810180008 7810180009* 7810180015 7810180017*	50-29 50-29 50-29 50-29 50-29
	7611150262 7811210349 7811210393 7811240119 7811240130	50-266 50-266 50-266 50-266	8 8 9		7810200051 7810240085 7810240152 7810240154 7810240154	50-29 50-29 50-29 50-29
	7811240131 7811240134* 7811240136* 7811240149 7811240155	50-301 50-301 50-301 50-266 50-266	8 8 8 8		7810240165* 7811020246 7811020247 7811090145 7811090150*	50-27 50-27 50-27 50-27 50-443
	7811240150# 7811280229 7811280240 7811300179 7812010225	50-266 50-362 50-502 50-502	P B A		7811090150* 7811140120 7811140122* 7811140190 7811170200	50-443 50-29 50-29 50-29 50-29
	7812050049 7812050049 7812050101 7812050188 7812060253	50-246 50-246 50-266 50-301 50-502	9 P		7811170201 7811170211 7811210317 7811210325 7811240167	50-29 50-29 50-29 50-29 50-29
	7812110110 7812110189 7812120085 7812120087: 7812130084:		8 R R		7811240238 7811280221 7811280284 7811280290 7811280314	50-29 50-29 50-29 50-29
	7812150305 7812260169 7812260169 7812260172* 7812260172*		F F		7811280323+ 7811280328 7811280332+ 7811280473 7811290198	50-29 50-29 50-29 50-29 50-29
Wisconsin Paper Council Wisconsin Public Bervice Corp.	7812270157 7812270158* 7812270452 7812010079 7810100055	50-303 50-303 50-266 50-305	C		7811270203> 7811270255 7811270344* 7811270344* 7811300378	50-29 50-29 50-443 50-443 50-29

SPFOR

AUTHOR AFFILIATION	ACCESSION SUBJECT NUMBER CATEGORY		RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEO	DRY
	7812010145 7812010224 7812040171 7812040234 7812050128	50-29 50-29 50-29 50-29 50-29	9 9 P F		7812080116 7812140145 7812150286 7812150288* 7812150288* 7812170087 7812200230	50-29 50-29 50-29 50-29 50-29 50-29	P P R R F P

### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCEBBION NUMBER	SUBJECT CATEGORY	NUMBER
108-78/ML78PF	7812270181*	50-315 F	
5182-087-09	7810120070*	50-395	
7811210046	7811210046	50-416 A	
7812130388	7812130396	50-305 F	>
BAH-1504	7811160064#	50-313 P	)
CEN-039(A)-NP	7810190089*	50-368 F	•
CEN-039(A)-NP/I	7810190090#		
CEN-Q71(A)-NP/1	7810190092#	9 BAE-06	,
CEN-077(M)-NP	7612200223*	50-309 F	י
CEN-093(M)-NP	7811150099#	50-309 F	•
CEN-1-4(N)-NP	7812280142+	50-336 C	)
E2A4365	7012010249*	30-447 6	4
FBDU-247-01	7811200221*		
IHL-6343-432	7811020312#	50-338 f	₹
NEDC-21974	7811270099#	50-155 F	า พบธวรว4
NEDD-23978	7812110116*	30-447	4
NEDO-24048	7810300138*	30-447	A
NE00-24083	7812270172	50-447	A 78MED282
NEDO-24129-1 BO1	7810170114*	50-333 (	<b>&gt;</b>
NEDO-24129-2 802	7812120092*	50-333 F	•
NEDO-24136 RO1	7812050251*	50-259 f	ח
NEB 61A0093 ROI	7810160146#		7
NEB 01A054B RO1	7810160151#		Þ
NE881A0002	7812080140*		P
NN1-77-7NP	7811220171*	50-220 F	<b>D</b>

REPORT NUMBER	ACCEBSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
NUREQ-0034 ADD DRFT	7811170341	50-437 E	
NUREQ-0309 801	7811040070*	50-522 E	
NUREO-0428	7811210199	50-466 I	•
NUREO-0437	7811210069	50-373 I	)
NUREQ-0455	7811210428	50-582	)
NURE9-0469	7811020010#	50-5B2 E	:
NUREG-0470	7812270414	50-466 1	<b>)</b>
NUREQ-0473 DRFT	7811280104#	50-373	•
NUREO-0485 VO1	7811100109#	50-10 F	•
NUREO - 0 486	7811100035	50-373 1	)
NUREQ-0490	7812040263	50-361 1	)
NUREQ-0471	7811280090	50-672 6	
P77-54-19	7812080136*	50-272 1	₹
RH-78-4-801	7810280122*	50-327	4
8CE-1-A	7812130210*	50-361	<b>\</b>
8ECY-78-553	7811200239+	50-437	1
SECY-R-73-684	78112000B&*	50-437	4
SECY-R-74-072	7811200279*	50-437	4
WARD-D-0165 RO1	7810170259*	50-537	4
WARD-D-0178	7819200251	50-537	١
WARD-0-0218	7812200247+	50-537	<b>\</b>
HCAP-6587 BOL ROI	7811240165	50-445	4
HCAP-9212	781208014Q+	80-30A	•
HCAP-9331	78111401310	50-266	E116-105
HCAP-9357	7811140133*		,
MM28-1-45-102	78111501960	50-322	4

# TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION	NUMBER			
ENCLOBURE	PRINCIPAL DECUMENT	DATE	EUBJECT	
7807180839	7809180532	78/09/05	50-13	J
7810100004	7810100003	78/09/86	50~409	P
7810100004	7810100002	78/09/29	50-296	8
7B10100014	7810100010	78/10/03	50-285	8
7810100019	7810100015	78/10/02	50-255	8
7910100021	7810100016	78/07/20	20-375	8
7810100026 7810100002	7810100022 7810100029	78/10/03 78/10/03	50-333 50-324	8
7810100033	7810100029	78/10/03	50~272	ê
7810100034	7810100030	78/09/25	50~334	В
7810100040.	7810100036	78/10/02	80-259	9
7810100041	7810100037	78/10/03	50-272	8
7810100045	7810100039	78/09/E1	50-321	F
7810100047	7810100042	78/09/29	60-247	8
7810100048	7810100043	78/10/02	80-241	В
7810100053	7810100049	78/10/03	50-325	8
7810100056	7810100080	78/07/05	50-312	9
7810100038	7810100051	78/09/26	60-317	9
7810100009 7810100062	7810100084 7810100055	78/09/29 78/10/02	<i>50-220</i> 50-305	8
				-
7810100063	7810100040	78/09/29	30-246	В
7810100064	7810100044	78/09/29	30-314	6
7810100066	7810100057	78/10/03	50-281	8
7810100068	7810100044	78/09/29	90-314	8
7810100049	7810100061	78/08/15	50-312	В
7810100071	7810100047	78/09/97	60-247	8
7B10100072	7810100066	78/10/02	50-348	8
7810100075	7810100070	78/09/29	50-219	8
7810100077	7810100073	78/07/17	50-312	6
7810100079	7810100074	78/10/03	50-280	B
7810100080	7810100076	78/09/27	50-320	2
7810100086	7810100085	78/10/02	50-348	Ð
7810100089	7810100087	78/10/03	50-272	8
7810100092	7810100091	78/09/27	50-335	B
7810100093	7810100091	78/09/27	50-335	В
7810100074	7810100091	78/09/27	50-035	8
7810100095	78101000BB	79/09/96	50-020	8
7810100097	7810100091	78/09/27	50-335	8
7810100099	7810100090	78/09/28	50-289	8
7810100100	7810100098	78/10/03	30-286	8
7810100102	7810100091	78/09/25	50-335	8
7810110043	7810110041	78/10/03	50-281	0
7810110044	7810110041	78/10/03	40-58F	P
7B1011004B	7810110041	78/10/03	50-261	P
7810110054	7810110052	78/09/08	50-10	۵
7810110057	7810110053	78/09/29	50-461	Q
7810110059	7810110056	78/09/24	50-259	Q.
7810110062	7810110052	76/09/08	50-10	9
7810110073	7810110070	78/09/28	50-245	P
7810110074	7810110070	78/09/24	50-246	þ

ACCESS 10	NUMBER			
	PRINCIPAL	DATE	BUBJECT	
ENCLOBURE	DOCUMENT	ISSUED	CATEOD	
7810110075	7810110070	78/09/26	50-243	P
7810110076 7810110083	7810110070 7810110082	78/09/26 78/10/02	50-245 50-320	P
7810110092	7810110090	78/09/29	50-287	P
7810110101	7810110098	78/10/05	50-264	ij
701011010				_
7810110103 7810110104	7810110100 7810110104	78/09/29 78/10/03	50-285	8
7810110114	7810110112	78/10/06	50-265	B
7810110117	7810110113	78/09/21	50-285	B
7810110120	7810110116	78/10/03	205-06	8
7810110122	7810110119	78/10/04	50-255	R
7810110126	7810110124	78/09/30	50-318	R
7810110129	7810110125	78/10/04	50-336	8
7810110132	7810110127	78/10/06	50-280	8
7810110134	7810110130	78/10/04	20-380	8
7810110139	7810110137	78/09/28	50-348	8
7810110146	7810110143	78/10/04	50-331	J
7810110147	7810110145	78/10/03	30-369	A
7810110162	7810110151	78/10/02	20-305	6
7810110155	7810110153	78/10/04	50-247	8
7810110173	7810110170	78/10/03	50-302	8
7810110174	7810110169	78/10/06	50-317	B
7810110181	7810110178	78/09/07	50-347	Q
7810110193	7810110180	78/10/06	20~873	8
7810110184	7810110178	78/09/07	50-367	Q.
7610110185	7810110182	78/09/06	50-305	G
7810110172	7810110154	78/10/03	50-315	8
7810110193	7810110189	79/10/03	50-285	R
7810110174	7810110190	78/08/28	50-43B 50-83	9
7810110195	7810110187	78/10/02	30-03	•
7810110198	7810110187	78/10/02	50-83	a
7810110201	7810110187	78/10/02	50-83	a
7810110203	7810110200	78/10/04	50-70	P
7810110204	7810110167	78/10/02	50-83 50-70	Q P
7810110205	7810110200	76710704	50-70	
7810110206	7810110202	76/09/28	30-460	æ
7810110207	7810110200	78/10/04	50-70	þ
7810110212	7810110209	78/09/08	50-341	9
7810110223 7810110229	7810110219 7810110226	78/09/27 78/09/28	50-265 50-261	ä
/61011012	,81011044	, , , , , , , ,		_
7810110231	7810110226	78/09/28	50-241	0
7810110233	7B10110226	78/09/28	50-241	9
7810110235 7810110237	7810110226 7810110235	78/09/29 78/09/30	50-241 50-445	Q.
7810110237	7810110236	78/09/29	50-466	ŏ
7810110241	7810110234	78/09/29	50~466	0
7810110242	7810110240	78/09/97 78/09/97	50-324 60-324	0
7810110245 7810110245	7810110240 7810110240	78/09/27	50-324	ä
7810110250	7810110234	78/09/29	50-466	ĕ

50-271

78/10/10

7810170193

7810170192

78/10/02

50-155

8

7810130165

7810130171

7810130170

7810130175

ACCESSION	NUMBER					UN NOTES:				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	6U9JECT CATEGOR		ENCLOSU	IRE DI	INCIPAL DCUMENT	DATE 188UED	SUBJECT CATEGOR	
7810170194 7810170196 7810170201 7810170202 7810170203	7810200045 7810170190 7810170199 7810170198 7810170195	78/10/16 78/10/06 78/10/05 78/09/26 78/10/06	50~250 50~36B 50~312 50~265 50~249	P 8 8 8	7810180 7810180 7810180 7810180 7810180	154 78 155 78 158 78 1162 78	0180131	78/10/12 78/10/12 78/09/27 78/10/11 78/09/29	50-348 50-302 50-315 50-285 50-320	8888
7810170211 7810170212 7810170215 7810170216 7810170222	7810170208 7810170207 7810170213 7810170204 7810170218	78/09/08 78/09/22 78/10/05 78/10/03 78/10/03	50-304 50-245 50-244 50-10 50-304	8 8 8	7810180 7810180 7810180 7810180 7810180	1179 78 1181 78 1192 78	10180171 10180177 10180178 10180189 10180206	78/10/05 76/09/05 76/09/06 78/09/08 78/08/25	50-320 50-244 50-20 50-335 50-368	8 0 0 0
7810170223 7810170227 7810170228 7810170230 7810170234	7810170214 7810170219 7810170225 7810170226 7810170231	78/09/29 78/09/25 78/09/25 78/09/25 78/10/06	50-295 50-295 50-295 50-366 50-295	8 8 8	7810180 7810180 7810190 7810190 7810190	0217 78 0001 78 0005 78	10180221 10180221 10180210 10180210	78/09/28 78/09/28 78/10/03 78/10/03 78/10/03	50-334 50-334 50-320 50-320 50-320	G G G
7810170235 7810170237 7810170238 7810170242 7810170245	7810170232 7810170233 7810170236 7810170239 7810170243	78/10/03 78/09/25 78/09/20 78/10/06 78/10/05	50-254 50-321 50-344 50-304 50-335	8 8 8	7810190 7810190 7810190 7810190 7810190	0015 78 018 78 0021 78	0190015	78/10/03 78/10/02 78/10/02 78/10/02 78/10/02	50-320 50-549 50-549 50-549 50-549	0 0 0 0
7810170246 7810170248 7810170252 7810170253 7810170258	7810170241 7810170244 7810170249 7810170251 7810170255	78/10/02 78/09/29 78/10/11 78/09/25 78/09/25	50-295 50-255 50-302 50-304 50-366	8 8 8	7810190 7810190 7810190 7810190 7810190	030 78 061 78 067 78	10190027 10190057 10190068	78/09/12 78/10/04 78/09/05 78/10/18 78/10/02	50-305 50-369 50-390 50-244 50-266	9996
7810170259 7810170261 7810170262 7610170263 7810170298	7810170154 7810170255 7810170099 7810170162 7810170291	78/10/06 78/09/25 78/10/12 78/10/11 78/09/25	50-537 50-321 50-263 50-244 50-321	A B P P S	7810190 7810190 7810190 7810190 7810190	1090 78 1092 78 1093 78	10190087 10190087 10190091	78/10/12 78/10/12 78/10/12 78/10/12 78/09/14 78/09/29	50-368 50-368 50-368 50-397 50-57	P P 0
7810170279 7810170313 7810170314 7810170315 7810170321	7810170268 7810170309 7810170312 7810170311 7810170318	78/10/05 78/10/04 78/10/04 78/09/29 78/10/03	50-298 50-366 50-366 50-366 50-366	R 6 9 8 8	7810190 7810190 7810190 7810190 7810190	1133 78 1136 78 1169 78	10190130 10190130 10190158	78/09/29 78/10/11 78/10/11 78/10/06 78/10/06	50-57 50-266 50-266 50-29 50-29	0 P P
7810170326 7810180003 7810180004 7810180005 7810180007	7810170322 7810180001 7810180002 7810180002 7810180006	78/10/03 78/10/06 78/10/03 78/10/03 78/10/12	50-366 50-366 50-316 50-316 50-219	9 9 8 8	7810190 7810190 7810190 7810190 7810190	192 78 198 78 200 78	10190158 10190197 10190197	78/10/04 78/10/06 78/09/29 78/09/29 78/09/29	50-369 50-29 50-549 50-549 50-549	0 P G G
7810180009 7810180011 7810180013 7810180014 7810180017	7810180008 7810180010 7810180012 7810170227 7810180015	78/10/13 78/10/06 78/09/26 78/09/29 78/10/13	50-29 50-321 50-282 50-321 30-29	9 8 9 9	7810190 7810190 7810190 7810190 7810190	)214 78 )220 76 )236 78	0190234	78/09/29 78/09/29 78/09/08 78/10/10 78/10/04	50-549 50-549 50-484 50-155 50-255	G G G R
7810180018 7810180022 7810180024 7810180025 7810180026	7810180016 7810180019 7810180020 7810180021 7810180023	78/09/27 78/10/02 78/10/09 78/10/12 78/10/05	50-316 50-386 50-386 50-308 50-388	8 8 8	78101 90 78101 90 78101 90 78101 90 78101 90	)240 78 )245 78 )247 78	10190233 10190219 10190234	78/10/02 78/10/04 78/08/31 78/10/10 78/08/31	50-395 50-255 50-454 50-155 50-454	0 R Q Q
7810180030 7810180032 7810180033 7810180035 7810180036	7810180027 7910180030 7810180031 7810180028 7810180034	78/10/11 78/10/11 78/09/27 78/10/11 78/09/12	50-316 50-316 50-366 50-133 50-306	8 8 8	78101 90 78101 90 78101 90 7810200 7810200	267 78 269 78 021 78	10190257 10190257 10200017	78/07/28 78/07/28 78/07/28 78/10/02 78/10/02	50-275 50-275 50-275 50-173 50-173	0 0 P P
7810180039 7810180040 7810180042 7810180046 7810180049	7810180037 7810180038 7810180041 7810180043 7810130164	78/10/03 78/10/04 78/09/27 78/09/12 78/10/06	50-366 50-266 50-346 50-266 50-295	9 8 8 8	7810200 7810200 7810200 7810200 7810200	0031 78 0050 78 0056 78	0500059	78/09/25 78/09/25 78/10/17 78/10/10 78/10/16	50-206 50-206 50-334 50-316 50-339	PPPRA
7810180082 7810180070 7810180100 7810180102 7810180104	7810180079 7810180084 7810180097 7810180099 7810180101	78/10/12 78/10/13 78/10/10 78/10/05 78/10/12	50-348 50-373 50-348 50-301 50-10	A J B R R	7810200 7810200 7810200 7810200 7810200	1063 78 1070 78 1072 78	10200061 10200067 10200071	78/10/05 78/10/11 78/10/10 78/10/12 78/09/13	50-516 50-331 50-313 50-245 50-250	0 R R 8
7810180107 7810180109 7810180111 7810180114 7810180118	7810180105 7810180106 7810180110 7810180112 7810180116	78/10/12 78/09/27 78/10/13 78/09/27 78/09/29	50-302 50-315 50-302 50-321 50-366	8 8	7810200 7810200 7810200 7810200 7810200	0091 78 0093 78 0095 78	10200077 10200082 10200077	78/10/13 79/10/16 78/10/16 78/10/16 78/10/13	50-263 50-348 50-269 50-348 50-245	P 8 R 8
7810180121 7810180122 7810180125 7810180131 7810180134	7810180119 7810180120 7810180123 7810180130 7810180134	78/10/13 78/10/03 78/10/09 78/10/01 78/10/13	50-280 50-366 50-133 50-293 50-213	P 6 R A	7810200 7810200 7810200 7810200 7810200	076 78 077 78 105 78	10200093 10200092 10200104	78/10/16 78/10/11 78/10/13 78/10/16 78/10/16	50-348 50-251 50-237 50-312 50-344	8888
7810190140 7810180142 7810180149 7810180150 7810180152	7810180139 7810180138 7810180145 7810180149 7810180147	78/10/11 78/10/13 78/10/11 78/10/16 78/10/12	50-339 50-260 50-348 50-244 50-302	у 8 Р 8	7810200 7810200 7810200 7810200 7810200	)117 78 )118 78 )125 78	10200114 10200110 10200119	78/10/17 78/10/11 78/10/17 78/10/16 78/08/09	50-281 50-251 50-280 50-272 50-302	88888

ACCESSION	NUMBER				ACCE8810	N NUMBER			
	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT	,	ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	
ENCLOBURE		78/10/04	50-269	B	7810240035	7810240032	78/01/19		a
7810200170 7810200182	7810200162 7810200177	78/10/06	50-483	Ö.	7810240071 7810240075	7810240067 7810240067	78/10/10 78/10/10	50-250	G G
7810200199 7810200201	7810200194 7810200194	76/10/10 78/10/10	50-261 50-261	P P	7810240077	7810240002	78/10/16 <b>7</b> 8/09/18		R O
7810230016	7810230011	78/10/10	50-277	P	7810240094	7810240092	•	50-247	8
7810230018	7810200240	78/10/0B	30-466	G P	7810240102 7810240107	7810240100 7810240103	78/10/12 78/10/16	50-219	8
7810230019	7810230011 7810230013	78/10/10 78/10/11	50-277 50-261	٥	7810240113 7810240121	7810240111 7810240116	78/10/20 78/10/12	50-133 50-249	P 8
7810230023	7810230013 7810230011	78/10/11 78/10/10	50-261 50-277	9	7810240124	7810240118	78/10/17	50-302	8
	7810230013	78/10/11	30-261	Q	7810240126	7810240122	78/10/19	50~333	8
7810230025 7810230027	7810230013	78/10/11	50-261	9	7810240129 7810240134	7810240125 7810240131	78/10/13 78/10/16	50-320 50-320	8 8
7810230026 7810230030	7810230011 7810230026	78/10/10 77/11/11	50-277 50-70	P	7810240137 7810240138	7810240115 7810240128	78/10/17 78/10/18	50-488 50-305	H 8
7810230033	7810230029	78/10/10	50-369	q				50-333	8
7810230036	7810230029	78/10/10	50-369 50-275	Q A	7810240139 7810240141	7810240133 7810240136	78/10/19 78/10/17	50-249	8
7810230042 7810230043	7810230038 781023003 <del>9</del>	78/10/06 78/10/10	50-271	P	7810240150 7810240151	7810240148 7810240146	78/10/12 78/10/20	50-10 50-296	8
7810230044 7810230048	7810230039 7810230039	78/10/10 78/10/10	50-271 50-271	P	7810240154	7810240152	78/10/18	50-29	8
7810230052	7810230049	78/10/10	50-335	g.	7810240162	7810240160	78/10/17	50-302	В
7810230058	7810200258	78/10/11	90-369	g.	7810240165 7810240207	7810240 <b>15</b> 6 7810240₽04	78/10/19 78/09/13	50-29 50-390	6 6
7810230059 7810230061	7810230049 7810200258	78/10/10 78/10/11	50-335 50-369	g g	7810240208	7810240067	78/10/10 78/09/13	50-250 50-390	0
7810230064	7810200258	78/10/11	50-369	Œ	7810240210	7810240204			
7810230067	7810200258	78/10/11	50-369 50-335	G G	781024021 I 781024021 7	7810240067 7810240067	78/10/10 78/10/10	50-250 50-250	0
7810230068 7810230072	7810230049 7810230049	78/10/10 78/10/10	50-335	G	7810240221 7810240228	7810240216 7810240225	78/10/10 78/10/17	50-445 50-368	Q P
7810230092 7810230094	7810230090 7810230091	78/09/20 78/09/22	50-70 50-508	G G	7810240230	7810240225	78/10/17	50~348	P
		78/10/11	50-322	0	7810240236		78/09/15	50-498	0
7810230133 7810230146	7810230130 7810230143	78/10/11	50-324	8	7810250015 7810250031	7810250007 7810250027	78/09/07 78/10/05	50-445 50-482	Q Q
7810230150 7810230167	7810230149 7810230164	78/10/16 78/10/13	50-247 50-277	A R	7810250052	781025004B	78/09/11 78/10/24	50-311 50-285	0 P
7810230169	7810230166	78/10/13	50-335	8	7810250063				
7810230174	7810230171	78/10/16 78/10/13	50-338 50-321	R	7810250085 78102500 <del>9</del> 1	7810250082 7810250074	78/10/19 78/09/14	50-260 50-424	P G
781023017 <i>6</i> 7810230182	7810230175 7810230178	78/10/15	50-317	R	7810250093 7810250100		78/10/19 78/10/18	50-349 50-329	8
76102301B3 78102301B5	7810230177 7810230177	78/10/18 78/10/18	50-314 50-316	8	7810250104		78/10/18	50-272	R
7810230187	7810230184	78/10/13	50-280	R	7B10250110		78/10/17	50-213	8
7810230199	7810230185	78/10/18	50-333 50-366	8	791 <i>02</i> 50114 781 <i>0</i> 250117	7810250112 7810110154	78/10/19 78/10/03	50-349 50-315	8 8
7810230190 7810230195	7810230188 7810230193	78/10/13 78/10/11	50-324	8	7810250122 7810250135	7810250120	78/10/19 78/10/12	50-327 50-266	A .
7810230196	7810230192	78/10/17	50-329	ĸ		• ••	•	50-286	 a
7810230202	7810230198 7810230207	78/10/18	50-315 50-245	9 8	7810250138 7810250133	7810250134	78/10/12 78/10/12	20-589	Q.
7810230210 7810230213	7810230209	78/10/04	50-298	Q	7810250136 7810250140		78/10/12 78/09/14	50-286 50-280	0
7810230223 7810230224	7810230214 7810230218	78/10/10 78/10/11	50-413 50-338	0	781025014		78/10/19	50-34B	8
7810230227	7810230226	78/10/08	50-259	0	781025015		78/09/14	50-302	g g
7810230230	7810230226	78/10/06 78/10/11	50-259 50-338	œ œ	7810250190 7810250194		78/10/11 78/10/11	50-387 50-387	G .
7810230237 7810230241	7810230218 7810230218	78/10/11	50-338	ā	781025019 781025020	7810250196	78/10/11 78/10/10	50-387 50-369	Q Q
7810230249	7810230243	78/10/18	50-272	8	761025020		78/10/11	50-387	٥
7810230251 7810230253	7810230247 7810230230	78/10/09 78/10/13	50-305 50-251	8	781025020	7810250200	78/10/10	<b>90~349</b>	0
781 0230255	7610230252	78/10/18 78/10/16	50-272 50-373	8	781025021 781025022		78/10/13 78/09/19	50-275 50-331	A
7610230256 7610230260	7810230161 7810230254	78/10/16	50-338	8	781025022		78/10/05	50-413	a
7810230261	7910230259	78/10/12	50-219	A	781025022			50-331 50-219	0
7810230262	7810230257 7810230263	78/10/12 78/10/18	50-281 50-333	8 8	781025022 781025023		78/10/11	50-34B	٥
7810230273 7810230275	7810230271	78/10/05	50-313 50-346	Р 8	761025023 781025023			50~34B 50~34B	G G
			50-313	-	781025024	6 7810250238	78/10/11	50-348	0
7810230279 7810230281	7810230271	78/10/05	50-313	P	781025026	1 7810250258	78/09/12	50-354 50-354	0
7810230285 7810230291	7810230277	78/10/17 78/10/12	50-312 50-338		781025026 781026000	7 7810260004	78/10/13	50-250	a
7810230294			50-36B		781025001			50-250	a
7810230301			50~36B		76102600 76102600			50-220 50-220	9
7810230304 7810230304	7810230293	78/10/04	50-368	P	78102600	3 7B10260019	78/10/06	50-220 50-220	ā
7810230310 7810230339	7810230308	78/10/18			7810260© 7810260©			50-445	A
7810230345					781026006	4 7810260004	76/10/13	50-250	Q
781024000	7810240003	78/10/13	50-437	Α.	78102600 78102600	7 7810260067	78/09/15	50-261	G G
7810240011 7810240014	7810240009	78/10/17	50-440	A	78102500	3 781026000	78/10/13	20-320	ä
781024001			50~329	A	78102601	B 781026011	78/10/19	50-361	K

	PRINCIPAL	DATE	BUBJECT	•					_
ENCLOBURE	DOCUMENT	198060	CATEODR		ENCLOBURE	PRINCIPAL DOCUMENT	DATE	CATEGOR	۲Y
7810260128	7810260121	78/10/25	50-336	8	7810300269	7810300262	78/09/22	50-389	8
7810260129 7810260130	7810260121 7810260121	78/10/25 78/10/25	50-338 50-338	8 9	7810300277	2B10300395	78/09/22	50-3B9	В
7810260131	7B10260121	78/10/25	30-338	8	7810300280 7810300291	7810300275 7810300252	78/19/02 78/09/22	50-333 50-389	8
7810260132	7810260121	78/10/25	50-338	9	7810300292	7810300117	78/09/13	50-334	ā
7810260133 7810260135	7810260121 7810260121	78/10/25 78/10/25	50-338 50-338	8 8	7810300307	7810300302	78/10/06	50-554	0
7810260164	7810260121	79/10/25	50-338	8	7810300313 7810300330	7810300309 7810230069	78/10/05 78/09/27	50-267 50-468	8
7810260175	7810260169	78/08/30	50-341	0	7810300336	7810300332	78/10/10	50-488	e
7810260180	7810260179	79/09/18	50-155	0	7810300338	7810300334	78/10/23	20-501	G
7810260183 7810260184	7810240179 7810240149	78/09/18 78/08/30	50-155 50-341	Q Q	7810300343	7810300334	78/10/23	50-201	٥
7810260225	7810260219	78/10/16	50-275	A	7810300351 7810300354	7810300334 7810300334	78/10/23 78/10/23	50-201 50-201	o a
7810260228	7810260227	78/10/13 78/10/13	50-344 50-344	0	7810300358	7B10300334	78/10/23	50-201	G
7810260232	7810260227				7610300362	7810300334	78/10/23	90~201	٥
7810260243 7810270076	7810260227 7810270072	78/10/13 78/10/17	50-344 50-287	O P	7810300380	7810300377	78/10/17	50-369	q
7810270097	7810170094	78/10/23	50-219	Ř	7810300383 7810300385	7810300375 7810300377	78/07/22 78/10/77	50-315 50-369	0
7810270107	7810270104	78/09/15	50-163	A G	7810300387	7810300384	78/08/08	50-395	Q
7810270113	7810270103	77/12/27	50-13	3	7810310033	7810310029	78/09/21	50-182	Q
7810270162 7810270188	7810270157 7810270186	78/10/05 78/10/24	50-443 50-277	A P	7810310054	7810310048	78/09/21	50-2B0	Q
7810270189	7810270185	78/10/16	50-334	o	7810310064 7810310069	7810310060 7810310060	78/03/01 78/03/01	50-259 50-259	Q Q
7810270192		78/10/16	50-334	Q 8	7810310074	7810310060	78/03/01	50-259	0
7810270193		78/10/20	50-315		7810310082	7810310081	78/09/22	50-339	Q.
7810270194 7810270196	7810270185 7810270185	78/10/16 78/10/16	50-334 50-334	O O	7810310105 7810310116	7810310102 7810310115	78/10/20 78/09/23	50-317 50-338	8
7810270216	7810270214	78/10/25	50-206	O	7810310127	7810310113	78/10/20	50-241	g
7810270221 7810270223		78/09/12 78/10/25	50~327 50~280	Q P	7810310133 7810310134	7810310130	78/10/26 78/09/20	50-155 50-324	В 0
						7810310128			
7810270224 7810270231		78/10/16 78/10/17	50-261 50-249	8 8	7810310135 7810310141	7810310131 7810310136	78/10/26 78/10/23	50-349 50-302	9 8
7810270232	7810270228	78/10/24	50-267	9	7810310142	7810310139	78/10/24	50-324	g
7810270234 7810270240		78/10/17 78/10/20	50~237 50~317	9 B	7810310144 7810310150	7810310138 7810310146	78/09/19 78/10/13	50-261 50-321	@ 8
7810270246 7810270270		78/02/08 78/10/16	50~329 50~278	0 8	7810310153 7810310154	7810310143 7810310151	78/10/23 78/10/24	50-261 50-366	8 8
7810270272	7810270252	78/10/20	50~324	ä	7810310153	7810270309	78/10/20	A1C-02	8
7810270293 7810270296		78/10/24 78/10/16	50~267 50~255	8 P	7810310162 Ca10310187	7810310157 7810310158	78/10/20 78/10/24	50-321 50-293	8
	•								
7810270298 7810270293		78/09/12 78/10/16	50-311 50-255	Q P	7810310166 7810310168	7810310160 7810310029	78/10/25 78/09/21	50-321 50-182	8 0
7810270296	7810270287	78/10/19	50-237	8	7810310169	7810310164	78/10/23	50~302	8
7810270305 7810270314		78/10/17 78/10/20	50-249 50-316	<b>9</b> 8	7810310170 7810310171	7810310167 7810310165	78/10/25 78/10/23	50~344 50~321	8 8
•	•								
7810270345 7810270346		78/09/27 78/09/27	50-344 50-344	•	781031017 <b>9</b> 7810310181	7810210020 7810210175	78/10/23 78/10/25	50~498 50~366	M B
7810270354	7810270341	78/09/27	50-344	9	7810310182	7810310117	78/10/24	50-321	8
7810270358 7810270373		78/09/27 78/10/20	50-344 50-341	•	78103101 <b>86</b> 7810310189	7810310183 7810310183	78/10/25 78/10/27	50-259 50-443	B A
7810270374		78/09/20	50-301	a	7810310192	7810310184	78/10/20	50-289	8
7810270367		78/10/20	50-341	ŏ	7810310199	7810310170	78/1-/26	50-316	9
7810270386		78/09/21	50-315 50-363	0 0	7810310200 7810310201	7810310197 7810310194	78/10/20 78/10/25	50-317 50-346	9 8
7810270392 7810270398		78/09/1⊋ 78/09/⊉1	50-363	Ġ	7810310214	7810310205	78/10/20	30-346 44C-06	8
7810270404	7810270368	78/10/20	50-341	٥	7810310216	7810310209	78/10/20	50-31B	8
7810270410	7810270404	78/10/03	50-213	P	7810310219	7810310210	78/10/25	50-261	9
7810270412 7810270412		78/10/03 78/10/03	50-213 50-213	P P	7810310 <b>2</b> 22 7810310 <b>227</b>	7810310217 7810310220	78/10/25 78/10/27	50-324 50-331	9 8
781027042		78/10/03	20-513	P	7810310230	7810310225	78/10/27	50-267	8
7810300017	7 810200258	78/10/11	50-369	g	7810310236	7810310232	78/10/23	50-324	9
781030000	7810300018	78/09/07	50-206	0	7810310237	7810310233	78/10/06	50-261	P
781030005; 7810300065		78/10/16 78/10/16	50-338 50-338	0	7810310241 7810310242	7810310233 7810310238	78/10/06 78/10/27	50-261 50-338	P 8
7810300077		78/10/16	50-344	ö	7810310243	7810310240	78/10/13	50-244	P
7810300113	401000010A	78/10/21	50-341	a	7810310246	7810310233	78/10/06	50-261	P
7810300138	7810300124	78/10/23	50-447	A	7810310248	7810310244 7810310238	78/10/26 78/10/27	50-271 50-338	8
7810300153 7810300153		78/10/23 78/10/23	50-289 50-219	H P	7810310252 7810310260	7810310254	78/10/26	50-272	8
781030016		78/10/02	50-514	ò	7810310291	7810310273	78/10/16	30-568	A
7810300164	7810300164	78/09/27	50-267	8	7810310286	7810310273	78/10/18	50-569	A
781030016	7810300162	78/10/02	50-514	0	7810310288 7810310294	7810310284 7810310284	78/10/18 78/10/18	50-528 50-528	0
781030017: 781030017:		78/10/25 77/11/02	50-260 50-277	P	7810310301	7810310284	78/10/18	50-526	Q
781030017		78/10/12	50-298	8	7810310304	7810310299	78/10/17	50-247	P
781030018	7810300179	78/10/05	50-267	8	7810310305	7810310299	78/10/17	50-247	ρ
781030019	7810300189	78/09/27	50-267	9	7810310307 781031030B	7610310302 7810310284	78/10/10 78/10/18	50-349 50~528	Q.
781030019 781030023		78/10/25 78/09/12	50-263 50-278	8	7810310309	7810310303	78/09/27	30-346	8
781030026		78/09/22	50-389	٥	7810310312	7810310302	78/10/10	50-369	a

					ACCESSI	ON NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	CATES		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJE	
7810310318 7810310319 7810310330	7810310284 7810310302 7810310303	78/10/18 78/10/10	94E-06	G	7811020251 7811020251 781102025	7811020248	78/10/30 78/10/17	50~460 50~187	I P
7810310340 7810310342 781031034 <i>b</i>	7810310339	78/09/26 78/09/27	50-346 50-346	B	781102027 <b>4</b> 7811020275	7811020272 7811020270	78/10/27 78/10/12 78/10/17		P
7810310345	7810310357	78/10/23		8	7811020277 7811020298		78/10/12 78/10/12	50-59 50-59	Р
7811010010 7811010012	7811010007			â	7811020312 7811020302	7811020304	78/10/31	50-338	R
7811010013 7811010014	7811010008	78/10/26	50-329	Ä	7811020333	7811020328	78/10/19 78/10/20	50-344 50-549	0
7811010016 7811010022	7811010009	78/10/04	50-10	0	7811020343 7811020355	7811020325 7811020351	78/10/19 78/10/20	50-344 50-364	9
7811010002	7811010018	78/09/20		a	7811020360 7811020369	7811020351 7811020365	78/10/20 78/09/22	50~364	G
7811010029 7811010033			30-10	0 B	7811020375	781 1020349	78/10/25	50-458 50-254	F
7811010037 7811010041	7811010032 7811010036	78/09/21	80-361	a	7811020387 7811020388	7811020384 7811020385	78/10/25 78/10/18	50-49B 50-549	Qi H
7811010053	7811010050	78/09/14	50-244 50-359	9	7811020393 7811020395	7811020384 7811020392	78/10/25 78/10/11	50-498 50-409	Gi P
7811010055 7811010057			50-414 50-358	Α 0	7811020399 7811020408	78; 1020392	78/10/11	50-409	P
7811010058 7811010059	7811010052 7811010047	78/10/19	50-414	A	7811020440	7811020392 7811020119	78/10/11 78/10/25	50-409 50-160	P 0
7811010061	7811010052	78/09/19 78/10/19	50-373 50-414	Q A	7811020449 7811030016	7811020442 7811030013	78/09/29 78/10/13	50-445	0
7811010064 7811010068	7811010052 7811010052	78/10/19	50-414 50-414	A	7811030019	7811030013	78/10/13	50-366	P
7811010076 7811010089	7811010067	78/09/19	60-254	â	7811030002 7811030036	7811030013 7811030034	78/10/13 78/09/11	50-366 50-285	9
7811010093	7811010085 7811010085	78/10/10	50-277 50-277	0	7811030037 7811030040	7811030035	78/09/22	50~466	g
7811010095 7811010099	7811010085 7811010085	78/10/10	50-277	Q	7811030047	7811030035 7811030044	78/09/22 78/10/24	50-466 50-424	Q Q
7611010116	7811010113	78/10/26	50-277 50-317	8	7811030054 7811030078	7811030044 7811030057	78/10/24 78/10/23	50-424	g
7611010125 7611010131	7811010120 7811010141	78/10/31 78/11/01	50-395 50-295	K	7811030090	7811030076	78/10/21	50~438 50-319	Q P
7811010135	7811010127	78/09/15	50-443	Q	7811030084 7811030085	7811030057 7811030076	78/10/23 78/10/21	50-4 <i>36</i> 50-318	P
7811010191	7811010140 7811010186	78/10/19 78/09/21	50-349 50-338	6	7811030089 7811030089	7811030076 7811030057	79/10/21	50-318	P
7811010280 7811010309	7811010249 7811010306	78/09/13 78/09/15	50-259	q	7811030092	7811030057	78/10/23 78/10/23	50-438 50-438	Q Q
7811010368	7811010342	78/10/13	50-346 50-320	Q Q	7811030104 7811030117	7811030101 7811030112	78/10/23 78/10/27	50-390 50-317	8
7811010384 7811010388	7811010362 7811010362	78/10/24 78/10/24	50-275 50-275	9	7811030120 7811030124	7811030119	78/11/01	50-311	ж
7811010399 7811010393	7811010387 7811010390	78/09/29	50-524 50-277	A	7811030135	7811030119 7811030131	7B/11/01 7B/10/25	50-311 50-309	K B
7831010400	7811,010390	78/10/03	30-277	P	781103013 <del>9</del> 7811030140	7811030136 7811030137	78/10/31 78/09/29	50-155 50-309	9
7811010402 7811010402	7811010397 7811010390	78/09/21 78/10/03	50-324 50-277	Q P	7811030145	7811030143	78/10/24	50-237	B
7811010411	7811010407	78/09/21	50~250	-Qe	7811030152 7811030156	7811030149 7811030153	78/09/26 78/09/27	50-312 50-312	8
7811010418 7811010423	7811010414 7811010414	77/12/16 77/12/16	50-260 50-260	Q Q	781103015 <u>9</u> 781103016 <u>8</u>	7811030157 7811030003	78/10/27 78/10/24	50-346 50-250	8
7811010428 7811010435	7811010414 7811010432	77/12/16 78/10/17	50-280 50-387	9	7811030171	7811030003	78/10/24	50-250	a
7811020010	7811020003	78/10/24	50-582	E	7611030175 7611030178	7811030003 7811030003	78/10/24 78/10/24	50~250 50~250	Q
7811020047 7811020052	7611020041 7911020048	78/10/16 78/09/19	50-376 50-445	Q	781 103019 <u>1</u> 781 1030198	7611030184 7611030194	78/10/27 78/10/19	50-249 50-346	9 9
7811020055 7811020059	781102004B 7811020053	78/09/19 78/10/16	50-445 50-205	Q	781103020B	7811030205	78/10/17	60-331	P
7611020071	7811020066	78/10/13	50-205	P	7811030210 7811030215	7811030205 7811030205	78/10/17	166-06	P
7811020081 7811020086	7811020066 7811020066	78/10/13 78/10/13	50-271 50-271	P	7811030228 7811030231	7811030224 7811030224	78/10/17 78/10/12 78/10/23	50-331 50-113 50-335	P Q
7811020087 7811020093	7811020084 7811020084	78/10/03	50-312	P	7811030232	7811030224	78/10/12	50-113	ρ
7611020076	7811020091	78/10/03 78/10/27	50-312 50-313	P P	7811030235 7811030249	7811030226	78/10/23	50-335	g
7811020098 7811020111	7811020084 7811020106	78/10/03 78/09/25	50-312 50-315	g.	7811030245 7811030245	7811030244 7811030257 7811030263	78/10/24 78/10/18 78/10/16	50-445 50-438 50-327	0 8 8
7811020146	7811020140	78/10/12	50-2	P	7811060009	7811060007	78/09/29		
7811020150 7811020168	7811020140 7811020146	78/10/12 78/09/27	50-2 50-341	P	7811060015	7811060013	78/10/13	20-5 20-588	P
7811020175 7811020176	7811020170 7811020169	78/10/13	50-271	Q	7811060019 7811060038	7811060013 7811060036	78/10/13 78/10/23	50-338 50-338	e a
7811020178	7811020169	78/10/11 78/10/10	50-466 50-823	9	7811060044	7811030040	78/10/24	50~582	å
7811020178 7811020179	7811020060	78/10/10	50-223	Q	7811060053 7811060055	7811060051 7811060051	78/09/12 78/09/12	50-298 50-298	Q (1)
7611020181	7811020170 7811020169	78/10/19 78/10/11	50-271 50-466	9	7811060065 7811060069	7811040045	78/10/20	50-341	A
7811020182	7811020060	78/10/10	20-553	à	7811060070	7811060063 7811060068	78/10/30 78/10/20	50-390 50-3 <u>22</u>	8 E
7811020193 7811020186	7811020170 7811020060	78/10/13 78/10/10	50-271	9	7811040074	7811060073	78/10/29	50-116	8
7811020188	7811020170	78/10/13	50-223 50-271	9	7911060093 7911060096	7811060093 7811060090	78/10/23 78/10/17	50-556	4
7811020218 7811020234	7811020212 7811020231	78/10/20 78/10/27	50-155 50-439	K	7811040100	7811040083	78/10/23	50-390 30-556	B
			100	••	7811060101	7811060098	78/09/26	20-392	Q

ACCE6810					ACCERSI	RBBMUN NO			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJEC		ENCLOSURS	PRINCIPAL DOCUMENT	DATE	GUBJEC	
7811040105 7811040104 7811040107 7811040125 7811040128	7811040098 7811040083 7811040103 7811040124 7811040124	78/09/26 78/10/23 78/10/27 78/10/16 78/10/16	50-382 50-356 50-213 50-277 50-277	0 0 8 P	7811070256 7811070257 7811070258 7811070270 7811070270	7811070262 7811070264 7811070266 7811070269 7811070273	78/11/01 78/11/01 78/11/02 78/10/30 78/11/01	50-272 50-346 50-272 50-397 50-346	8 8 8 6
7811040130 7811040138 7811040140 7811040148 7811040149	7811040124 7811040131 7811040135 7811040144 7811040145	78/10/16 78/10/30 78/10/30 78/10/27 78/10/13	50-277 50-321 50-321 50-250 50-368	P 8 8	7811070291 7811070294 7811070307 7811070308 7811070311	7811070277 7811070268 7811070302 7811070305 7811070302	78/10/19 78/10/31 78/10/24 78/10/03 78/10/24	50-327 50-245 50-213 50-445 50-213	A P Q P
7811060151 7811060152 7811060153 7811060156 7811060158	7811040145 7811040142 7811040150 7811040145 7811040154	78/10/13 78/10/27 78/10/27 78/10/13 78/10/27	50-368 50-250 50-366 50-368 50-313	8 8 8	7611070313 7811070314 7811070323 7811070323 7811070335	7811070302 7811070309 7811070309 7811070310 7811070331	78/10/24 78/10/23 78/10/23 78/11/01 78/10/24	50-213 50-250 50-250 50-333 50-70	Р 0 0 8 Р
7811060160 7811060161 7811060162 7811060163 7811060180	7811060145 7811060155 7811060159 7811060157 7811060175	78/10/13 78/10/31 78/10/30 78/10/27 78/10/13	50-348 50-318 50-249 50-251 50-313	8 8	7811070377 7811070378 7811080008 7811080018 7811080024	7811070373 7811070373 7811080005 7811080013 7811080013	78/10/17 78/10/17 78/10/30 78/10/24 78/10/24	50-412 50-412 50-275 50-157 50-157	8 A P P
7811060183 7811060189 7811060204 7811060213 7811060213	7811060175 7811060175 7811060200 7811060211 7811060210	78/10/13 78/10/13 78/10/31 78/11/01 78/11/01	50-313 50-313 50-285 50-281 50-286	8 8 8	7811080000 7831080003 7811080004 7811080047 7811080096	7811080026 7811080026 7811080036 7811080039	78/10/30 78/10/30 78/10/10 78/10/23 78/10/20	50-584 50-584 50-284 50-356 50-70	A A P A P
7811040217 7811040237 7811040238 7811040239 7811040240	7811060211 7811060233 7811060224 7811060224 7811060233	78/11/01 78/11/01 78/10/20 78/10/20 78/11/01	50-281 50-338 50-3 50-3 50-338	8 9	7811080070 7811080074 7811080074 7811080080 7811080080	7811080066 7811080066 7811080067 7811080077 7811080082	78/10/04 78/10/04 78/10/23 78/10/02 78/10/27	50-295 50-295 50-466 50-254 50-286	0 H G
7811040242 7811040244 7811040245 7811040247 7811070004	7811060233 7811060224 7811060233 7811060224 7811070001	78/11/01 78/10/20 78/11/01 78/10/20 78/10/20	50-338 50-3 50-338 50-3 50-471	8	7611080089 7811080079 7811080079 7611080076 7611080097	7811080059 7811080082 7811080091 7811080082	78/10/18 78/10/27 78/10/27 78/09/20 78/10/27	50-344 50-286 50-286 50-317 50-206	0 0 0
7811070055 7811070057 7811070060 7811070063 7811070064	7811070013 7811070013 7811070013 7811070013 7811070059	78/10/23 78/10/23 78/10/23 78/10/23 78/10/30	50-269 50-269 50-269 50-269 50-568	PPPA	7811080078 7611080104 7811080111 7811080112 7811080127	7811080059 7811080101 7811080110 7811080106 7811080123	78/10/18 78/10/02 78/11/02 78/10/23 78/11/03	50-344 50-315 50-296 50-298 50-286	0 P 0 P
7811070068 7811070071 7811070139 7811070140 7811070143	7811070013 7811070013 7811070136 7811070138 7811070138	78/10/93 78/10/93 78/11/01 78/10/31 78/10/31	50-269 50-269 50-302 50-443 50-443	P B 1	7811080129 7811080134 7811080141 7811080144 7811080150	7811080123 7811080133 7811080137 7811080143 7811080148	78/11/03 78/11/03 78/11/01 78/11/02 78/11/01	50-286 50-390 50-270 50-336 50-251	P K 8 8
7811070145 7811070147 7811070148 7811070150 7811070151	7811070138 7811070133 7811070138 7811070138 7811070146	78/10/31 78/06/20 78/10/31 78/10/31 78/11/03	50-443 50-397 50-443 50-443 50-338	1 Q 3 1 P	7811080151 7811080154 7811080156 7811080157 7811080158	7811080147 7811080147 7811080152 7811080147 7811080147	78/10/27 78/10/27 78/11/02 78/10/27 78/10/27	50-395 50-395 50~293 50-395 50-395	9 9 9
7811070153 7811070156 7811070161 7811070163 7811070164	7811070138 7811070138 7811070138 7811070157 7811070133	78/10/31 78/10/31 78/10/31 78/11/03 78/06/20	50-443 50-443 50-443 50-247 50-397	1 1 P Q	7811060161 7811080166 7811080167 7811080177 7811080184	7811080155 7811080163 7811080164 7811080172 7811080183	78/11/02 78/09/27 78/10/30 78/09/20 78/11/02	50-336 50-395 50-318 50-333 50-286	B G A G P
7811070166 7811070169 7811070171 7811070179 7811070181	7811070138 7811070138 7811070138 7811070133 7811070178	78/10/31 78/10/31 78/10/31 78/06/20 78/11/02	50-443 50-443 50-443 50-397 50-272	1 0 1	7811080199 7811080191 7811080192 7811080194 7811080198	7811080175 7811080187 7811080175 7811080175 7811080174	78/10/16 78/09/27 78/10/16 78/10/16 78/09/27	50-363 50-327 50-363 50-363 50-327	0 0 0 0
7811070188 7811070198 7811070204 7811070208 7811070218	7811070184 7811070193 7811070183 7811070204 7811070210	79/11/01 78/10/31 78/11/03 78/11/01 78/11/02	50~346 50~344 50~255 50~302 50~255	8 8 8	7911080200 7811080211 7811080213 7811080215 7811080217	7811080175 7811080205 7811080205 7811080205 7811080208	78/10/16 78/10/27 78/10/27 78/10/27 78/11/01	50-343 50-349 50-349 50-349 50-335	0 0 0 8
7811070224 7811070230 7811070233 7811070235 7811070237	7811070217 7811070221 7811070226 7811070226 7811070228	78/11/02 78/11/01 78/11/02 78/11/01 78/11/02	50~155 50~247 50~338 50~302 50~339	8 8	7811090220 7611080224 7611080238 7611080242 7811080245	7811080205 7811080229 7811080229 7811080229 7811080235	78/10/27 78/10/20 78/10/20 78/10/20 78/09/23	50-369 50-219 50-219 50-219 50-271	0 0
7811070238 7811070240 7811070241 7811070248 7811070249	7811070234 7811070236 7811070228 7811070244 7811070245	78/11/02 78/09/08 78/11/02 78/11/01 78/09/22	50~267 50~327 50~338 50~333 50~518	R 8 8	7811080246 7811080246 7811080254 7811080256 7811080240	7811080229 7811080244 7811080251 7811080253 7811080253	78/10/20 78/09/19 78/10/27 78/10/19 78/10/19	50-219 50-219 50-219 50-219	0 0 0
7811070252 7811070256 7811070259 7811070260 7811070261	7811070246 7811070253 7811070247 7811070254 7811070258	78/11/03 78/10/31 78/11/01 78/10/24 78/11/03	50~510 50~286 50~282 50~445 50~336	A P B G 8	7811080264 7811080268 7611080279 7811080272 7811080274	7811080253 7811080253 7811080263 7811080270 7811080231	78/10/19 78/10/19 78/09/27 78/09/19 78/10/27	30-219 50-219 50-241 50-311 50-438	9

#### PRINCIPAL DOCUMENTS

ACCESSION					ACCESSION				
ENCLOSURE	PRINCIPAL EDCUMENT	DATE [SSUED	SUBJECT CATEOUR	<b>Y</b>	ENCL OSURE	PRINCIPAL DOCUMENT	DATE 189UED	SUBJECT CATEGORY	<u>,                                     </u>
7811080296 7811080298 7811080300 7811080302 7811080310	7811080250 7811080251 7811080250 7811080251 7811080305	78/10/27 78/10/27 78/10/27 78/10/27 78/10/13	50-369 50-438 50-369 50-438 50-368	0 0 0 0	7811100021 7811100023 7811100026 781110003	7811100017 7811100017 7811100017 7811100017 7811100056	78/11/01 78/11/01 78/11/01 78/11/01 78/10/20	20-305 20-305 20-305	0 0 0 8
7811080314 7811080353 7811090003 7811090006 7811090007	7811080250 7811080243 7811090001 7811090004 7811090004	78/10/27 78/10/30 78/10/03 78/09/20 78/09/20	50-369 50-389 50-367 50-341 50-341	0 M Q Q	78:1100076 78:11100083 78:11100084 78:11100094 78:11100097	7811100075 7811100082 7811100082 7811100092 7811100095	78/10/04 78/10/31 78/10/31 78/10/04 78/09/27	50-213 50-250 50-250 50-213 50-443	G G G
7811090013 7811090017 7811090018 7811090021 7811090024	7811090009 7811090016 7811090015 7811090013 7811090013	78/11/01 78/09/25 78/10/25 78/10/25 78/10/25	50-324 50-247 50-250 50-250 50-250	0 Р Р	7811100102 7811100109 2811100110 7811100115 7811100121	7811100099 7811100105 7811100103 7811100114	78/09/26 78/10/19 78/10/26 78/10/25 78/10/27	50-311 50-10 50-269 50-269 50-344	9 0 0
7811090030 7811090032 7811090034 7811090038 7811090040	7811090025 7811090025 7811090025 7811090025 7811090037	78/10/26 78/10/26 78/10/26 78/10/26 78/10/03	50-317 50-317 50-317 50-317 50-2	0 0 0	781 11 00124 781 11 00126 781 11 00128 781 11 00129 781 11 00130	7811100103 7811100114 7811100114 7811100120 7811100103	78/10/26 78/10/27 78/10/27 78/10/20 78/10/26	50~269 50~344 50~344 50~286 50~269	0
7811090041 7811090044 7811090054 7811090058 7811090071	7811090037 7811090043 7811090048 7811090053 7811090039	78/10/03 78/10/31 78/11/08 78/09/21 78/10/20	50-2 50-87 50-320 50-277 50-155	0 6 K 0 P	781 1 00133 781 1 1 00135 781 1 1 00145 781 1 1 00148 781 1 1 00158	7811100114 7811100120 7811100120 7811100142 7811100120	78/10/27 78/10/20 78/10/20 78/10/25 78/10/20	50~344 50~286 50~286 50~311 50~286	0 0 0
7811090079 7811090088 7811090119 7811090124 781109D126	7811070039 7811070039 7811070116 7811070113 7811070125	78/10/20 78/10/20 78/10/27 78/10/30 78/10/19	50-155 50-155 50-237 50-10 50-249	P & 8 8	7811100164 7811100165 7811100168 7811100172 7811100181	7811100157 7811100120 7811100104 7811100120 7811100120	78/10/02 78/10/20 78/10/21 78/10/20 78/10/20	50-211 50-286 50-321 50-286 50-286	0 0 0
7811090130 7811090133 7811090134 7811090135 7811090136	7811090129 7811090132 7811090132 7811090132 7811090132	78/10/27 78/11/03 78/11/03 78/11/03 78/11/03	50-237 50-423 50-423 50-423 50-423	8 8	7811130005 7811130007 7811130010 7811130013 7811130014	7811130004 7811130003 7811130004 7811130006 7811130009	78/10/02 78/08/24 78/10/02 78/10/31 78/09/29	50-331 50-250 50-331 50-259 50-332	0 0 0 0
7811090141 7811090142 7811090149 7811090150 7811090152	7811090137 7811090138 7811090143 7811090147 7811090146	78/10/24 78/10/27 78/11/03 78/10/27 78/11/01	50-277 50-237 50-329 50-443 50-277	8 8 8 8	7811130018 7811130022 7811130047 7811130073 7811130077	7811130006 7811130006 7811130006 7811130069 7811130069	78/10/31 78/10/31 78/10/31 78/10/25 78/10/25	50-259 50-259 50-259 50-387 50-387	0 0 6 8
7811090153 7811090156 7811090158 7811090159 7811090165	7811090151 7811090143 7811090151 7811090143 7811090155	78/11/01 78/11/03 78/11/01 78/11/03 78/11/02	50-316 50-329 50-316 50-329 50-220	8 4 8	781113000 7811130003 7811130119 7811130119 7811130120	7811130075 7811130075 7811130075 7811130115 7811130113	78/10/26 78/10/26 78/10/02 78/10/03 78/10/03	50-250 50-250 50-327 50-272 50-438	P G G
7811090168 7811090172 7811090174 7811090179 7811090185	7811070161 7811070167 7811070171 7811070178 7811070182	78/11/02 78/11/03 78/11/01 78/11/03 78/10/04	50-293 50-341 50-320 50-346 50-315	8 8	7811130151 7811130170 7811130175 7811130192 7811130209	7811130135 7811130075 7811130075 7811130169 7811130206	78/09/27 78/10/26 78/10/26 78/10/31 78/11/06	50-387 50-250 50-250 50-329 50-409	Q P P Q R
7811090187 7811090189 7811090191 7811090192 7811090194	7811090183 7811090182 7811090184 7811090183 7811090183	78/11/02 78/10/04 78/11/01 78/11/02 78/11/02	50-348 50-315 50-261 50-348 50-348	9 9 8 8	7811130214 7811130220 7811130228 7811130229 7811130230	7811130211 7811130218 7811130226 7811130226 7811130146	78/11/02 78/11/04 78/10/30 78/10/30 78/11/03	50-318 50-334 50-348 50-348 50-346	8 9 9 9
7811090197 7811090200 7811090204 7811090205 7811090206	7811090194 7811090183 7811090198 7811090203 7811090135	78/11/02 78/11/02 78/10/26 78/10/26 78/11/02	50-325 50-348 50-259 50-155 50-220	8 8 9 8	7811130231 7811130238 7811130239 7811130240 7811130241	7811130227 7811130237 7811130237 7811130237 7811130237	78/09/28 78/11/08 78/11/09 78/11/08 78/11/08	50-344 50-280 50-280 50-280 50-280	9
7811090210 7811090215 7811090217 7811090219 7811090223	7811090177 7811090177 7811090177 7811090177 7811090203	78/11/06 78/11/06 78/11/06 78/11/06 78/10/26	50-280 50-280 50-280 50-280 50-155	8 8 8	7811130249 7811130261 7811130252 7811130258 7811130275	7811130247 7811130256 7811130256 7811130256 7811130271	78/11/07 78/11/06 78/11/06 78/11/06 78/10/04	50-564 50-321 50-321 50-321 50-334	A 0 0 0
7811070226 7811070229 7811070234 7811070235 7811070238	7811070203 7811070203 7811070203 7811070232 7811070232	78/10/26 78/10/26 78/10/26 78/10/26 78/10/26	50-155 50-155 50-155 50-395 50-395	8 8 9	7811130285 7811130286 7811130278 7811130301 7811130327	7811130290 7811130256 7811130289 7811130299 7811130313	78/10/05 78/11/06 78/11/07 78/11/02 78/11/03	50-334 50-321 50-373 50-333 50-313	0 D P 0
7811070240 7811070246 7811070269 7811070273 7811070278	7811070235 7811070242 7811070265 7811070271 7811070274	78/11/06 78/10/18 78/10/02 78/11/02 78/11/01	50-281 50-335 50-332 50-220 50-220	8 8 8 8	7811130302 7811130303 7811130307 7811130304 7811130304	781113033 <sup>r</sup> 7811130059	78/10/24 78/10/24 78/08/17 78/09/21 78/11/03	50-582 50-284 50-10 50-329 50-580	A P G H
7811090279 7811090290 7811090303 7811100012 7811100013	7811070275 7611070284 7611070278 7611100008 7811100010	78/09/26 78/09/21 78/10/03 78/09/27 78/09/01	50-390 50-320 50-255 50-293 50-219	0 0	7811130350 7811130357 7811130378 7811130378 7811130381	7811130354 7811130354 7811130374	78/09/21 78/10/25 78/10/25 78/10/30 78/10/30	50-327 50-369 50-369 50-369 50-369	9

					ACCEBAIC	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	CATEOD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 16SUED	SUBJEC	
7811130391 7811130393 7811130412 7811130419 7811140033	7811220184 7811130384 7811130409 7811130410 7811140030	78/11/15 78/09/28 78/10/05 78/10/06 78/10/16	50-220 50-364 50-302 50-338 50-250	P 0 0	7811140246 7811140247 7811140247 7811140249 7811140277	7811140258 7811140264 7811140268 7811140271 7811140271	78/10/27 78/10/12 78/10/06 78/11/02 78/11/02	50-410 50-373 50-341 50-311 50-311	
7811140036 7811140049 7811140043 7811140034 7811140057	7811140030 7811140030 7811140037 7811140048 7811140053	78/10/16 78/10/16 78/10/04 78/10/10 78/10/31	50-250 50-250 50-311 50-329 50-205	PGG	7811140278 7811140280 7811150041 7811150043 7811150045	7811140271 7811140271 7811150038 7811150038 7811150038	78/11/02 78/11/02 78/11/01 78/11/01 78/11/01	50-311 50-311 50-220 50-220 50-220	0 0 0
7811140063 7811140106 7811140108 7811140113	7811140053 7811140053 7811140104 7811140102 7811140110	79/10/31 78/10/31 78/11/01 78/10/30 78/11/08	50-205 50-205 50-286 50-502 50-336	Р Р А Я	7811130049 7811130052 7811130062 7811130065 7811130067	7811150038 7811150053 7811150058 7811150058 7811150058	79/11/01 78/10/12 78/11/07 78/11/07 79/11/07	50-220 50-344 50-395 50-395 50-395	0 0 0
7811140117 7811140118 7811140122 7811140123 7811140127	7811140115 7811140116 7811140120 7811140121 7811140125	78/11/09 78/11/08 78/11/10 78/11/10 78/11/10	50-282 50-305 50-29 50-333 50-271	R R R R	7811130095 7811130095 7811150099 7811150100 7811150102	7811150086 7811150092 7811150091 7811150092 7811150092	78/10/13 78/11/03 78/11/09 78/11/03 78/11/03	50-331 50-309 50-309 50-309 50-309	0 0 P 0
7811140131 7811140133 7811140136 7811140140 7811140141	7811140124 7811140124 7811140135 7811140137 7811140139	78/11/08 78/11/08 78/11/08 78/11/09 78/11/06	50-266 50-266 50-346 50-259 50-344	P R R	7811150103 7811150109 7811150119 7811150129 7811150130	7811150092 7811150107 7811150116 7811150128 7811150127	78/11/03 78/10/30 78/11/06 78/11/07 78/10/23	50-309 50-329 50-171 30-260 50-528	Q A B C
7811140144 7811140145 7811140148 7811140150 7811140151	7811140142 7811140126 7811140147 7811140146 7811140146	78/11/09 78/11/09 78/11/08 78/11/10 78/11/10	50-277 50-275 50-255 50-155 50-155	R K R B	7811150131 7811150134 7811150149 7811150149 7811150173	7811150126 7811150135 7811150146 7811150154 7811150167	78/11/06 78/11/03 78/11/10 78/10/30 78/11/06	50-580 50-556 50-133 50-220 50-266	9 R P F
7811140161 7811140162 7811140163 7811140166 7811140169	7811140107 7811140156 7811140160 7811140112 7811140119	78/11/08 78/11/02 78/10/27 78/11/10 78/11/08	50-285 50-321 50-237 50-309 50-10	R S S R	7811150175 7811150176 7811150182 7811150188 7811150190	7811150171 7811150137 7811150171 7811150184 7811150184	78/11/05 78/11/07 78/11/06 78/11/03 78/11/03	50-247 50-327 50-247 50-220 50-220	P P G
7811140170 7811140173 7811140178 7811140181 7811140188	7811140164 7811140171 7811140174 7811140177 7811140183	78/11/02 78/10/30 78/11/08 78/11/06 78/11/10	50-293 50-206 50-308 50-318	8 R 8	7611150192 7611150194 7611150194 7611150199 7611150249	7811150184 7811150184 7811150137 7811150137 7811150265	78/11/03 78/11/03 78/11/07 78/11/07 78/11/02	50-220 50-220 50-327 50-327 58-317	G G A A
7811140189 7811140191 7811140195 7811140199 7811140204	7811140185 7811140187 7811140186 7811140193 7811140198	78/10/11 78/11/05 78/11/08 78/11/01 78/11/03	50-315 50-245 50-296 50-257 50-366	8 8	7811130272 7811130274 7811130274 7811160046 7811160063	7811150265 7811150265 7811150265 7811160045 7811160061	78/11/02 78/11/02 78/11/02 78/10/29 78/11/08	50-317 50-317 50-317 50-466 50-368	0 0
7811140208 7811140206 7811140211 7811140212 7811140213	7811140202 7811140201 7811140209 7811140207 7811140203	78/11/06 78/11/08 78/11/02 78/11/07 78/11/02	50-336 50-296 50-366 50-293 50-237	9 9 9 9	7811160054 7811160059 7811160072 7811160073 7811160078	7811160062 7811160066 7811160067 7811160074 7811160076	78/11/09 78/11/08 78/11/06 78/11/09 78/11/07	50-313 50-321 50-438 50-272 50-312	P R B R
7811140218 7811140220 7811140221 7811140226 7811140227	7811140210 7811140215 7811140217 7811140210 7811140222	78/11/09 78/11/02 78/11/08 78/11/09 78/11/01	50-316 50-237 50-259 50-316 50-249	9 8 8	7811160082 7811160080 7811160070 7811160072 7811160073	7811160080 7811160084 7811160085 7811160088 7811160089	78/11/05 78/11/09 78/11/02 78/11/09 78/11/07	50-206 50-277 50-348 50-325 50-245	A R R 8
7811140228 7811140232 7811140233 7811140234 7811140236	7811140223 7811140210 7811140225 7811140229 7811140230	78/11/09 78/11/08 78/11/07 78/11/02 78/11/06	50-255 50-316 50-348 50-322 50-312	8 8 9 9	7811160094 7811160101 7811160103 7811160104 7811160110	7811160091 7811160100 7811160102 7811160099 7811160106	78/11/10 78/11/06 78/11/13 78/11/08 78/11/08	50-324 50-344 50-271 50-296 50-366	R R S R
7811140237 7811140239 7811140242 7811140243 7811140244	7811140225 7811140229 7811140225 7811140229 7811140240	78/11/07 78/11/02 78/11/07 78/11/02 78/11/08	50-348 50-322 50-348 50-322 50-259	8 0 8	781116011 7811160114 7811160115 7611160117 7811160120	7811140109 7811140113 7811160112 7811160116 7811160119	78/11/11 78/11/03 78/11/09 78/11/13 78/11/09	50-334 50-298 50-237 50-263 50-261	R R B R
7811140246 7811140248 7811140249 7811140250 7811140251	7811140225 7811140238 7811140227 7811140247 7811140225	78/11/07 78/11/10 78/11/02 78/11/09 78/11/07	50-348 50-333 50-322 50-286 60-348	8 8 8	7811160125 7811160120 7811160120 7811160140 7811160141	7811160122 7811160128 7811160132 7811160136 7811160137	78/11/02 78/11/13 78/11/09 78/11/06 78/11/06	50-237 50-271 50-325 50-302 50-325	8 8 8
7811140253 7811140253 7811140253 7811140254 7811140255	7811140090 7811140090 7811140090 7811140243 7811140252	78/10/04 78/10/04 78/10/04 78/10/27 78/11/03	50-518 50-518 50-518 50-366 50-3	9	7811160142 7811160144 7811160159 7811160150 7811160152	7811160139 7811160138 7811160158 7811160157 7811160181	78/11/10 78/11/07 78/11/01 78/11/08 78/10/16	50-250 50-325 50-556 50-440 50-482	P 8 9 8
7811140254 7811140259 7811140261 7811140262 7811140265	7811140252 7811140252 7811140258 7811140252 7811140258	78/11/03 78/11/03 78/10/27 78/11/03 78/10/27	50-3 50-3 50-410 50-3 50-410	Q A Q A	7811160186 7811160186 7811170086 7811170090 7811170109	7811160181 7811160181 7811170085 7811170087 7811170107	78/10/16 78/10/16 78/11/02 78/10/31 78/11/14	50-482 50-482 50-382 60-466 50-338	g g g R

ACCESSION NUMBER ACCESSION NUMBER

ACCESSION						N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE LEBUED	SUBJECT CATEODR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	CATEGOR	
7811170114	7811170111	78/10/06	50-128	ā	761120016B	7811200006	78/10/27	50-437	A
7811170115	7811170104	78/11/13	50-245	R	7811200170	7811200004	78/10/27	50-437	Ą
7811170119 7811170131	7811170111 7811170130	78/10/06 78/11/09	50-128 50-277	Q R	7811200172 7811200174	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
7811170142	7811170141	78/11/03	50-344	P	7811200177	7811200006	78/10/27	50-437	A
7811170143	7811170141	78/11/03	50-344	P	7811200180	7811200176	78/11/06	50~313	8
7811170171 7811170174	7811170165 7811170168	78/11/10 78/10/17	50-318 50-556	B	7811200183 7811200186	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
7811170178	7811170172	78/11/13	50-334	8	7811200187	7811200184	78/11/15	50-302	R
7811170184	7811170182	78/11/14	50-338	8	7811200188	7811200182	78/10/11	50-518	Q
7811170185 7811170187	7811170183 7811170179	78/11/14 78/11/13	50-280 50-318	8	7811200190 7811200191	7811200185 7811200189	78/11/17 78/11/03	50-387 50-368	K S
7811170189	7811170182	78/11/14	50~33B	8	781 1200192	7811200004	78/10/27	50-437	Ä
7811170192 7811170213	7811170188	78/11/14 78/11/14	50-280	R	781 t 200 196	7811200006	78/10/27	50-437	A
	7811170209		50-325		7811200178	7811200194	78/11/14	50-280	
7811170234 7811170238	7811170221 7811170232	78/11/13 78/11/08	50-334 50-324	9	7811200202 7811200203	7811200006 7811200201	78/10/27 78/11/14	50-437 50-272	8
7811170240	7811170232	78/11/08	50-324	0	7811200205	7811200006	78/10/27	50~437	A
7811170242 7811170245	7811170232 7811170232	78/11/09 78/11/09	50~324 50~324	0	7811200207 7811200208	7811200204 7811200006	78/11/15 78/10/27	50-219 50-437	A
7811170249 7811170259	7811170247 7811170256	78/11/03 78/11/01	50~482 50-282	Q P	7811200210 7811200211	7811200127 7811200006	70/11/08 78/10/27	50-280 50-437	G A
7811170252	7811170260	78/10/03	50-358	Q	7811200212	7811200209	78/11/15	50-346	8
7811170264 7811170265	7811170260 7811170256	78/10/03 78/11/01	50-358 50-282	0 P	7811200213 7811200214	7811200006 7811200127	78/10/27 78/11/08	50~437 50~280	ė.
7811170268 7811170293	7811170256 7811170289	78/11/01 78/11/02	50-282 50-14B	P Q	7811200215 7811200217	7811200006 7811200216	78/10/27 78/10/06	50-437 50-498	â
781 1 1 70298	7911170294	78/11/10	50-329	C	7811200218	7811200216	78/10/05	50-49B	Q
7811170299 7811170319	781117029 <b>5</b> 7811170316	78/10/06 78/10/16	50-311 50-6	9	78:1200220 78:1200221	7811200006 7811200219	78/10/27 78/10/10	50-437 50-201	A
7811200013	7811200006	78/10/27	50-437	A	7811200224			50-437	
7811200013	7811200006	78/10/27	50-437	Ä	7811200227	7811200006 7811200006	78/10/27 78/10/27	50-437	A
7811200019 7811200024	7811200006 7811200021	78/10/27 78/10/13	50-437 · 50-327	A	7811200236	7811200006	78/10/27	50-437	A
7811200026	7B11200021	78/10/27	50-437	Ā	7811200238 7811200239	7811200006 7811200235	78/10/27	50-437 50-437	A
7811200032	7811200006	78/10/27	50-437	A	78:1200242	7811200006	78/10/27	50~437	<b>A</b>
7811200034	7811200029	78/10/11	50-324	a	7811200243	7811200006	78/10/27	50-437	Ä
7811200037 7811200043	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811200246 7811200248	7811200004 7811200004	78/10/27 78/10/27	50-437 50-437	A
7811200049	7811200006	78/10/27	50-437	Ä	7911200253	7811200006	78/10/27	50-437	Ä
7811200053	7811200006	78/10/27	50-437	A	7611200258	7B11200006	78/10/27	50-437	
7811200058 7811200063	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811200259	7811200173	78/11/17	50-424	٨
7811200067	7811200006	78/10/27	50-437	Ã	7911200241 7811200243	781120000 <i>6</i> 781120000 <i>6</i>	78/10/27 78/10/27	50-437 50-437	Â
7811200069	7811200006	78/10/27	50-437	A	7811200267	7811200006	78/10/27	50-437	A
7811200075	7811200004	78/10/27	50-437	A	7811200270	7811200006	78/10/27	50-437	A
7811200076 7811200078	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811200272 7811200276	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
7811200080	7811200080	78/05/15	50-346	P	7811200 <b>2</b> 79	7811200006	78/10/17	50-437	Ä
7811200082	7811200004	78/10/27	50-437	A	7811200285	7811200006	78/10/27	50-437	A
7811200083 7811200086	7811200004 7811200004	78/10/27 78/10/27	50-437 50-437	A	7611200298	7811200264	78/11/07	50-395	•
7811200089	7811200004	78/10/27	50~437	Ä	7911200291 7811200294	7811200006 7811200264	78/10/27 78/11/07	50-437 50 <b>-</b> 395	ô
7811200092 7811200093	7811200087 7811200006	78/10/03 78/10/27	50-346 50-437	R	7811200295 7811200298	7811200006	78/10/27	50-437	A
						7811200006	78/10/27	50-437	۸
7811200095 7811200096	7811200087 7811200006	78/10/03 78/10/27	50-346 50-437	R	7811200302 7811200310	7811200006 · 7811200006	78/10/27 78/10/27	50~437 50~437	A
7811200078	7811200087	78/10/03	50-346	R	7811200313	7811200006	79/10/27	50-437	Ã
7811200100 7811200102	78112000B7 7811200006	78/10/03 7 <del>8</del> /10/27	50-346 50-437	R	7811200327 7811200330	7811200006 7811200325	78/10/27 78/10/18	50-437 50- <i>298</i>	A Q
7811200105	7811200006	79/10/27	50-437						
7811200106	7811200087	78/10/03	50-346	A	7811200301 7811200339	7811200006 7811200006	78/10/27 78/10/27	50~437 50~437	<b>A</b>
7811200109 7811200110	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	78:1200343	7811200004	78/10/27	50-437	A
7811200114	7811200006	78/10/27	50-437	A	7811200348 7811200352	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
7811200130	7811200006	78/10/27	50-437	٨	7811200356	7811200350	78/11/17	50-313	P
7811200133	7811200127	78/11/08	50~280	q	78:1200359	7811200004	78/10/27	50-437	A
7811200134 7811200136	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7611200365 7811200369	7811200006	78/10/27	50-437 80-437	A
7811200138	7811200006	78/10/27	50-437	Ä	7811200367	7811200006 7811200006	78/10/27 78/10/27	50-437	A
7811200140	7811200127	78/11/08	50-280	Q	7811200380	7811200006	78/10/27	50-437	A
7811200142 7811200147	7811200006 7811200006	78/10/27 78/10/27	50-437	Ą	7811200384	7811200366	78/11/09	50-275	A
7811200149	7811200008	78/11/01	50-437 50-368	B	7811200386 7811200390	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
7811200151	7811200004	78/10/27	50-437	A	7811200392	7811200366	78/11/09	50-275	Ä
7811200153	7811200004	78/10/27	50-437	Ą	7811200395	7811200006	78/10/27	50-437	A
7811200156 7811200157	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811200403 7811200408	7811200006	78/10/27	50~437	A
7811200162	7811200006	78/10/27	50-437	A	7811200419	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A
781 1200164	7911200160	78/11/15	50-219	P	7811200424	7811200006	78/10/27	50-437	A

7811200432 7811200433	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811210384 7811210383		78/11/15		
7811200434	781 1200006	79/10/27	50-437	A	7811210391 7811210392	7811210363	78/04/04 78/11/14 78/11/13	50-213 50-315 50-10	
7811200436	7811200006 7811200006	78/10/27 78/10/27	50-437 50-437	A	7811210394	7811210390	78/11/13	<b>50</b> 70.	
7811200437	7811200006	78/10/27	50-437	A	7811210404	7811210398	78/11/09	50-33 t 50-3&6	R
7811200438 7811200439	7811200006 7811200006	78/10/27	50-437	A	7811210409 7811210422		78/11/16	50-317	8
7811200440	7811200006	78/10/27 78/10/27	50-437	A	7811210436		78/11/17 79/10/16	50-333 50-266	8
7811200441	7811200006	78/10/27	50-437 50-437	A	7811210436		78/11/14	50-316	R
7811200442 7811210013	7811200006	78/10/27	50-437	Ä	7811210476 7811210497		78/11/06	50-556	Ĥ
7811210024	7811210005 7811210018	78/10/19 78/10/19	50-456	0	7811210501	7811210480 7811210480	78/10/04 78/10/04	50-313 50-313	٥
77114		70710711	50-331	٥	7811220003	7811220002	78/11/09	50-313	9
7811210027 7811210044	7811210022 7811210039	78/10/18 78/11/01	50-454	q	7811220003	7911220002	78/11/09	E0-225	
7811210086	7811210055	78/11/01	50-466 50-70	ů	7811220028	7811220026	78/11/14	50-335 50-321	9
7811210088 7811210106	7811210083	78/10/10	50-339	ŏ	7811220033 7811220059	7811220031 7811220054	78/11/09	50-254	R
721.210100	7811210103	78/10/03	50-440	٥	7811220060	7811220039	78/11/13 78/11/07	50-321 50-549	O T
7811210112	7811210103	78/10/03	50-440	0	7811220062	7811220058			
7811210115 7811210121	7811210114 7811210114	78/09/14 78/09/14	50-313 50-313	0	7811220064	7811220054	78/11/07 78/11/13	50-549 50-321	T O
7811210125	7811210114	78/09/14	50-313	0	7811220065	781122005B	78/11/07	30-549	Ť
7811210128	7811210114	78/09/14	50-313	ā	7811220068 7811220070	7911220059 781122005B	78/11/07 78/11/07	30-349 30-349	Ĺ
7811210169	7811210164	78/11/13	50-275	F					T
7811210173	7811210170	78/10/06	50-356	j	7811220077 7811220078	7811220038	78/11/07 78/11/15	50-549	Ţ
7811210179 7811210181	7811210176 7811210177	78/11/15 78/11/13	50~348 50~237	R	7811220081	7811220076	78/11/15	50-3 50-3	J
7811210183	7811210178	78/10/24	50-496	S Á	7811220082 7811220084	7811220058	78/11/07	30-349	7
781 121 0184	7811210184	20				7811220038	78/11/07	50-549	۲
7811210192	7811210187	78/11/15 78/11/13	50-289 50-368	R R	7811220098 7811220091	781122005B	78/11/07	50~549	Ť
7811210205	7811210200	78/11/06	20-387	P	7811220071	7811220087 7811220058	78/11/15 78/11/07	50-260 50-349	Q T
7811210209 7811210213	7811210200 7811210200	78/11/06 78/11/08	50-286	P	7811220093	7811220087	78/11/15	50-240	å
			30-266	P	7811220095	7811220087	78/11/15	50-260	q
7811210216 7811210220	7811210214 7811210214	78/10/12 78/10/12	50-331	0	7811220095	7811220039	78/11/07	50-549	T
7811210226	7811210217	78/11/13	50-331 50-424	Q A	7911220099 7911220118	7811220087	78/11/15	50-260	0
7811210241	7811210239	78/11/14	50-219	R	7811220123	7611220113 7811220113	78/11/09 78/11/09	50-34B 50-34B	P
7811210243	7811210238	78/11/14	50-366	8	7811220125	7811220113	78/11/09	50-34B	P
7811210253	7811210246	78/11/07	50-366	8	7811220140	7811220138	78/10/30	50-263	ρ
7911210245 7811210246	7811210260 7811210257	78/11/14 78/11/14	50-315 50-281	P 8	7811220143	7811220138	78/10/30	50-263	P
7911210269	7811210243	78/11/01	50-293	R	7811220144 7811220148	7611220138 7811220145	78/10/30 78/11/03	50-263 50-338	P
7811210275	7811210268		50-336	8	7811220152	7811220149	78/11/06	30-366	0
7811210278	7011210271	78/11/15	50-315	8	7811220169	7811220168	78/11/14	50-361	٨
7811210293 7811210294	7811210281	78/11/13	50-220	8	7811220178	7811220176	78/11/17	50-329	8
7811210287	7811210282 7811210281	78/11/14 78/11/15	50-213 50-220	e e	7911220190 7911220192	7811220177 7811220181	78/09/22 78/11/20	50-325	P
7811210289	7811210242	78/11/09	50-338	q	7811220187	7811220183	78/11/15	50-275 50-324	A S
7811210291	7811210280	78/11/16	50-245	8	7811220188	7811220185	78/11/13	50-269	8
7811210292	7811210281	78/11/15	20-550	8	7811220191	7811220186	78/11/15	50-220	P
7811210294 7811210299	7811210290 7811210293	78/11/14 78/11/20	50-33B 50-341	8 K	7811220192 7811220193	7811220189	78/11/17	20-589	8
7811210303	7811210302	78/11/08	50-220	R	7811220197	7811220184 7811220195	78/11/15 78/11/17	50-220 50-397	P 9
7811210304	7811210301	78/10/27	50-237	8	7811220199	7811200181	70/11/12		_
7811210310	7811210305	78/11/13	50-327	Ā	7811220202	781122019A 7811220200	78/11/17 78/11/08	50-305 50-309	8
7811210311	7811210309	78/09/25	20-213	В	7911220203 7811220217	7811220201	78/11/08	50-250	8
7811210318 7811210318	7811210313 7811210113	78/11/17 78/11/14	50-338 50-275	B	7811220252	7611220213 7611220251	78/11/01 78/10/27	50-309 50-220	8 P
				_	7811220256				
7811210324 7811210325	7811210321 7811210317	78/11/18 78/11/13	50-219 50-29	8	7811220257	7611220254 7811220263	78/10/16 78/10/17	50-261 50-275	Q Q
7811210335	7811210330	78/11/16	80-255	8	7811220282	7811220280	78/11/09	50-395	õ
7811210336 7811210337	7811210332 7811210330	78/11/15 78/11/16	50-320 50-255	8	7811220284 7811240007	7811220280 7811240001	78/11/09 78/11/13	50-395 50-335	0
7811210339 7811210344	7811210333 7811210340	78/11/01 78/11/15	50-249 50-3	8 R	7811240009 7811240011	7811240001 7811240001	78/11/13 78/11/13	50-335 50-335	0
7811210345	7811210341	78/11/14	50-293	8	7811240013	7611240001	78/11/13	50-335	ă
7811210346	7811210342	78/11/13	50-321	8	7811240027 7811240032	7811240025 7811240029	78/11/09 78/11/13	50-250 50-363	G H
7811210352	7811210347	78/11/13	50-346	8		7811240024	/8/11/13	30-203	п.
7811210357	7811210347	78/11/13	50-346	8	7811240033 7811240048	7811240025	78/11/09	50-250 50-29	٩
7811210358 7811210359	7811210355 7811210347	78/11/13 78/11/13	50-34B 50-346	8 8	7811240050	7811240044 7811240046	78/10/10 78/11/15	50-27	9
7811210362	7811210347	78/11/13	50-346	8	7811240052	7811240046	78/11/15	50-338	ō
7811210366	7811210361	78/11/15	50-321	В	7811240055	7811240046	78/11/15	50-338	a
7811210370	7811210351	78/11/09	50-366	8	7811240057	7811240046	78/11/15	50-338	0
7811210371	7811210349	78/11/08 78/11/13	50-283 50-346	8	7811240065 7811240068	7811240041 7811240041	78/11/13 78/11/13		a a
7811210374 7811210375	7811210347 7811210372	78/11/13	50-346	8	7811240072	7811240067	78/11/17	50-440	Œ
7811210379		78/11/14	50-346	8	7811240074	7B11240071	78/11/14	50-302	G.

ACCESSION NUMBER

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

WCCERRIDA										
ENCLOSURE	PRINCIPAL DCCUMENT	B1A0 DBUEBI	EUBJECT CATEGOR			ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEGOR	Y 
7811240077 7811240079 7811240081 7811240074 7811240096	7811240071 7811240071 7811240071 7811240091 7811240091	78/11/14 78/11/14 78/11/14 78/11/15 78/11/15	50-302 50-302 50-302 50-70	0000		7911270146 7811270149 7811270150 7811270151 7811270156	7811270138 7811270138 7811270148 7811270147 7811270154	78/11/20 78/11/20 78/06/30 78/11/21 78/11/21	50-368 50-368 50-331 50-329 50-267	8 8 8 A P
7811240103 7811240116 7811240126 7811240126 7811240129	7811240102 7811240114 7811240124 7811240125 7811240127	78/11/21 78/11/22 78/10/25 78/11/16 78/10/13	50-220 50-498 50-263 50-384 50-295	0 0 8 8		7811270159 7811270168 7811270178 7811270181 7811270199	7811270157 7811270165 7811270177 7811270177 7811270174	78/11/20 78/11/17 78/10/18 78/10/18 78/10/10	50-369 50-369 50-482 50-482 50-522	K 0 0
7811240134 7811240136 7811240137 7811240139	7811240131 7811240130 7811240132 7811240035 7811240141	78/10/13 78/10/12 78/11/20 78/11/05 78/11/20	50-301 50-301 50-272 50-304 50-311	99994		7811270205 7811270209 7811270246 7811270250 7811270253	7811270201 7811270201 7811270243 7811270243 7811270243	78/10/11 78/10/11 78/11/09 78/11/09 78/11/09	50-382 50-333 50-333 50-333	0 0 P P
7811240147 7811240147 7811240156 7811240158 7811240161 7811240161	7811240154 7811240153 7811240153 7811240157 7811240171	78/10/19 78/11/03 78/10/23 78/11/13 78/11/01	50~304 50~265 50~266 50~322 50~315	8 8 0 8		7811280007 7811280008 7811280012 7811280032 7811280054	7811280004 7811280005 7811280006 7811210018 7811280050	78/11/08 78/11/13 78/11/13 78/10/19 78/10/16	50-206 50-321 50-321 50-331 50-556	P G G G
7811240173 7811240174 7811240177 7811240178 7811240181	7811240171 7811240171 7811240175 7811240176 7811240179	78/11/01 78/11/01 78/10/19 78/11/14 78/10/27	50~315 50~315 50~254 50~304 50~254	8 8 8		7811280060 7811280062 7811280082 7811280083 7811280084	7811280058 7811280058 7811280080 7811280080 7811280080	78/10/12 78/10/12 78/11/14 78/11/14 78/11/14	50-285 50-28 50-29 50-29 50-29	0 0 P P
7811240189 7811240193 7811240194 7811240198 7811240201	7811240187 7811240192 7811240195 7811240197 7811240200	78/11/17 78/10/26 78/10/23 78/10/13 78/10/13	50-245 50-265 50-304 50-295 50-295	8 8 8 8	•	7811280104 7611280159 7811280172 7811280174 7811280178	7811280101 7811280157 7811280170 7811280170 7811280170	78/11/16 78/11/20 78/11/08 78/11/08 78/11/08	50+373 50-458 50-250 50-250 50-250	A I P P F
7611240204 7811240206 7811240208 7811240211 7811240213	7811240203 7811240205 7811240207 7811240210 7811240212	78/10/30 78/11/03 78/11/03 78/10/17 78/10/13	50-265 50-295 50-295 50-237 50-295	8 8 8 8		7811280191 7811280196 7811280199 7811280202 7811280203	7811280187 7811280193 7811280194 7811280198 7811280201	78/11/21 78/11/16 78/11/17 78/11/22 78/11/24	50-259 50-219 50-249 50-346 50-260	8 8 8
7611240217 7811240220 7811240223 7811240224 7811240228	7811240215 7811240218 7811240221 7811240222 7811240222	78/11/15 78/10/13 78/10/13 78/10/20 78/11/17	50-317 50-304 50-295 50-265 50-267	* 8 8 8		7811280206 7811280207 7811280211 7811280220 7811280224	7811280204 7811260205 7811280208 7811280217 7811280222	78/11/20 78/11/22 78/11/16 78/11/20 78/11/20	50-331 50-259 50-366 50-366 50-366	8 8 8 8
7811240229 7811240234 7811240235 7811240240 7811240241	7811240227 7811240232 7811240231 7811240237 7811240237	78/10/27 78/11/17 78/10/06 78/10/25 78/11/01	50-295 50-267 50-135 50-254 50-265	8 8		7811280230 7811280278 7811280239 7811280242 7811280244	7811280227 7811280234 7811280234 7811270235 7811280234	78/11/20 78/11/21 78/11/22 78/11/20 78/11/22	50-278 50-280 50-263 50-321 50-263	8 8 8
7811270012 7811270014 7811270019 7811270020 7811270021	7811270011 7811270011 7811270018 7811270018 7811270018	78/10/16 78/10/16 78/11/08 78/11/08 78/11/08	50-338 50-338 50-315 50-315 50-315	0 0 P P		7811280249 7811280253 7811280254 7811280256 7811280253	7811280234 7811280234 7811270248 7811280234 7811280260	78/11/22 78/11/22 78/11/22 78/11/22 78/11/27	50-263 50-263 50-352 50-263 50-247	8 8 8
7811270023 7811270040 7811270043 7811270046 7811270050	7811270018 7811270039 7811270041 7811270044 7811270048	78/11/08 78/10/12 78/11/01 78/10/16 78/11/08	50-315 50-445 50-298 50-361 50-483	P Q E Q		7811280269 7811280270 7811280271 7811280272 7811280276	7811280264 7811280260 7811280268 7811280267 7811280275	78/11/27 78/11/17 78/11/20 78/11/22 78/11/21	50-373 50-247 50-302 50-348 50-272	C 8 2 8 7
7811270054 7811270058 7811270061 7811270063 7811270065	7811270052 7811270056 7811270059 7811270059 7811270059	78/11/07 78/10/24 78/11/13 78/11/13 78/11/13	50-489 50-312 50-348 50-348 50-348	A 0 P P		7811280281 7811280289 7811280290 7811280292 7811280293	7811280277 7811280285 7811270284 7811280286 7811280288	78/11/21 78/11/22 78/11/20 78/11/20 78/11/20	50-206 50-267 50-29 50-281 50-366	8 8 8
7911270073 7811270077 7811270078 7811270080 7811270081	7811270071 7811270040 7811270071 7811270049 7811270071	78/11/07 78/11/22 78/11/09 78/11/03 78/11/09	50-10 50-495 50-10 50-315 50-10	6 6 6		7811280298 7811280300 7811280302 7811280305 7811280307	7811280294 7811280295 7811280297 7811280299 7811280303	78/11/21 78/11/21 78/11/22 78/11/22 78/11/20	50-296 50-336 50-549 50-305 50-302	8 8
7811270089 7811270093 7811270096 7811270097 7811270099	7811270088 7811270088 7811270088 7811270088 7811270094	78/10/20 78/10/20 78/10/20 78/10/20 78/11/21	50-312 50-312 50-312 50-155	9 9 9 P		7811280309 7811280310 7811280313 7811280317 7811280318	7811280301 7811280299 7811280304 7811280315 7811280312	78/11/13 78/11/22 78/11/22 78/11/24 78/11/22	50-249 50-305 50-272 50-344 50-267	8 8 8 8
7811270103 7811270106 7811270107 7811270110 7811270113	7811270100 7811270100 7811270102 7811270100 7811270111	78/11/06 78/11/06 78/10/19 78/11/06 78/10/16	50-243 50-243 50-344 50-263 50-344	PPGPG		7811280320 7811280321 7811280323 7811280325 7811280326	7811280316 7811280316 7811270314 7811280322 7811280322	78/11/22 78/11/22 78/11/22 78/11/20 78/11/20	50-338 50-339 50-27 50-338 50-339	8 8 8
7811270126 7811270129 7811270134 7811270142	7811270121 7811270123 7811270130	78/10/19 78/11/13 78/11/17 78/11/20	50-70 50-298 50-271 50-368	0 0 P		7811280327 7811280330 7811280332 7811280335 7811280336	7811280324 7811280322 7811280328 7811280333 7811280333	78/11/22 78/11/20 78/11/20 78/11/22 78/11/22	50-344 50-338 50-29 50-293 50-348	9 8 8

AC CE6910					ABASSA		
	PRINCIPAL	DATE	SUBJEC	Ŧ	ACCESSION NUMBER		
ENCLOSURE	DOCUMENT	IBSUED	CATEGO	RY	PRINCIPAL DATE ENCLOSURE DOCUMENT 155UED	SUBJEC	
7811260342 7811280348	7811280336	78/11/20	50-348	8	***************************************	CATEGO	RY 
7811280390	7811280336	78/11/20 78/11/06	50-348 50 <i>-26</i> 9	S	781130024B 7811300241 78/11/03 7811300250 7811300241 78/11/03	50-334	0
7011280398	7811200378	78/11/06	50-269	ô	7811300254 7811300251 78/10/26	50-334 50-440	0
7011200434	7811280425	78/11/09	50-400	A	7811300260 7811300297 78/10/25 7811300264 7811300261 78/10/25	50-358 50-10	0
7811280458 7811280493	7811280454	70/11/06	90-412	8	7011700000		
7811260474	7811280491 7811280491	78/09/29 78/09/29	50-331 50-331	P	7811300298 7811300295 78/10/10	50-1 <i>0</i> 50-272	0
7811290005 7811290006	7011270000	78/11/14	50-572	A	7811300306 7811300303 78/10/10	50-322	9
	7811290003	78/11/14	50-572	A	7811300318 7811300314 78/09/29 7811300339 7811300336 78/10/18	50-255 50-390	9
7811290046 7811290099	7811290044 7811290095	78/11/03 78/11/11	50-514	0	7811300340 7811300337 78/10/19	50-247	
7811290104	7811270075	7B/11/11	50-219 50-219	P P	7811300342 7811300341 78/10/24	50-213	Q.
7811270106 7811270166	7811290095 7811290152	78/11/11 78/11/06	50-219	P	7811300347 7811300345 78/10/17 7811300350 7811300349 78/10/27	50-412 30-255	0
			30-280	Р	7811300352 7811300344 78/11/13	56-592	й
781129016B 7811290172	7811290152 7811290152	78/11/06 78/11/06	50~260 50~280	P	7811300354 7811300349 78/10/27	50-255	o.
7811290175	7811290152	78/11/06	50-280	p	7811300362 7811300361 78/09/13	50-184	œ
7811290203 7811290235	7811290198 7811290229	78/11/25 78/11/16	50-29 50-335	9 8	7811300377 7811300366 78/10/18	50-184 50-20	a a
7011000001					7811300380 7811300366 78/10/18	90-50	0
7811290251 7811290252	7811290247 7811290248	78/11/27 78/11/24	50~315 50~390	K	7811300392 7811300370 78/11/16	50-490	0
7811290267 7811290292	7811290264	78/11/24	90-317	8	7811300387 7811300383 78/10/13 7811300401 7811300398 78/09/29	50-410 50-263	0
7811270304	7811290291 7811290297	78/11/13 78/10/26	50-245 50-70	R	7811300402 7811300397 78/10/23	50-373	ā
7811290315	70.1700210					50-277	0
781 <b>1 2</b> 9031 B	7811290310 7811290317	78/11/02 78/11/08	50-112 50-309	P P	7812010014 7812010010 78/11/21 7812010015 7812010010 78/11/21	50-275	A
7811290319 7811290322	7811290317 7811290320	78/11/08	50-309	P	7812010015 7812010008 78/11/15	50-275 50-277	Q
7811270323	7811270320	78/11/14 78/10/19	50-389 50-566	G G	7812010019 7812010010 78/11/21 7812010023 7812010008 78/11/13	50-275 50-277	G
7811290325	7811270320	78/11/14	50-389	^			
7811290326	7011290324	78/10/25	50-320	0	7812010031 7812010008 78/11/15 7812010035 7812010034 78/10/20	50-277 50-333	9
7811290331 7811290332	7811290327 7811290328	78/10/25 78/11/17	50-346 50-336	0	7812010040 7812010038 78/10/18	50-566	Q
7811290335	7811290320	70/11/17	50-336	Ď.	7812010041 7812010037 78/10/20 7812010042 7812010039 78/11/21	50-220 50-47 t	9
7811290336	7811290333	78/10/25	50-266	a	7812010044 7812010039 78/11/21	50-471	e
7811290308 7811290339	7811270328	70/11/17	50-336	Q	7812010046 7812010039 78/11/21	50-471	0
7811270341	7811290328 7811290337	70/11/17 78/11/14	50-336 50-443	0 8	7812010050 7812010039 78/11/21 7812010057 7812010039 78/11/21	50-471 50-471	Ĉ
7811290344	7811270337	79/11/14	50-443	8	7812010059 7812010039 78/11/21	50-471	ŏ
7811270359	7811290346	78/11/03	50-400	0	7812010062 7812010047 78/10/23	50-286	o.
7811290366 7811290389	7811270346 7811270387	78/11/03 78/10/13	50-400 50-272	0	7812010070 7812010065 78/09/29 7812010076 7812010033 78/11/09	50-305 50-286	9
7011290397	7811290393	70/10/23	50-123	ò	7812010081 7812010033 78/11/09	50-2B6	ā
7811300004	7811300003	70/11/17	50-335	0	7812010085 7812010033 78/11/09	50-286	Q
7011300010	7811300003	78/11/17	50-335	g	7812010089 7812010033 78/11/09	50-286	0
7811300011 7811300013	7811300007 7811300003	78/11/17 78/11/17	50-329 50-335	A O	7812010092 7812010033 78/11/09 7812010093 7812010090 78/11/17	50-286 50-309	0
7811300019	7811300007	78/11/17	50-329	À	7812010096 7812010033 78/11/09 7812010097 7812010090 78/11/17	50-286 50-309	0
7911300020	7811300017	78/11/16	50-445	Q			
7811300023 7811300055	7811300007	78/11/17	50-329	A	7812010099 7812010090 78/11/17 7812010103 7812010090 78/11/17	50-309 50-309	0
7811300044	7911300063 7911300059	78/11/24 78/11/13	50-133 50-237	O P	7812010104 7812010100 78/11/15	50-250	0
7811300067 7811 <i>300070</i>	7811300058 7811300058	78/11/13 78/11/13	50-237 50-237	P	7812010109 7812010100 78/11/15 7812010111 7812010108 78/10/18	50-250 50-29	0
						50-250	G
7811300073 7811300077	7911300058 7911300058	78/11/13 78/11/13	50-237 50-237	P	7812010126 7812010124 78/10/27	50-255	à
7011300085	7811300058	78/11/13	50-237	₽	7812010128 7812010125 78/10/16 7812010129 7812010124 78/10/27	50-250 50-255	0
781 1300102 781 1300109	7811300100 7811300105	78/10/30 78/11/17	50-338 50-445	A Q	7812010131 7812010130 78/11/20	50-219	ō
7811300117	7811300114	78/11/20	50-255	g	7812010132 7812010130 78/11/20	50-219	Q.
7811300117	7811300114	78/11/20	50-155	ā	7812010134 7812010130 78/11/20	50-219 50-219	0
781 1300 141 781 1300 167	7811300135 7811300165	78/10/26 78/11/02	50-155 50-400	0	7812010136	50-244	ē
7811300170	7811300165	78/11/02	50-400	ä	7812010168 7812010162 78/11/14	50-369	A
7811300174	7811300172	78/11/22	50-270	8	7812010182 7812010173 78/10/20	50-160	G
7811300161	7811300177	78/11/22	50-314	8	7812010213 7812010207 78/11/27 7812010216 7812010214 78/11/27	50-346 50-309	g S
7811300165 7811300166	7811300177 7811300177	78/11/22 78/11/22	416-06 416-06	8	7812010229 7812010223 78/11/30	50-416 50-285	K S
7811300190	7811300184	78/11/17	50-335	8	7812010240 7812010238 78/11/25		
7811300193	7811300177	78/11/22	50-316	8	7812010245 7812010244 78/11/27 , 7812010247 7812010246 78/11/24	50-302 50-302	8 6
7811300199 7811300205	7811300176	78/11/17 78/11/22	50-317 50-591	8 K	7812010249 7812010248 78/11/15	50-447	A
7811300213	7811300203 7811300209	78/11/20	50-361	Q	7812010252 7812010251 78/11/27 7812010254 7812010253 78/11/27	50-329 50-348	ж В
7811300218	7811300215	78/11/14	50-433	J	,	50-338	Я
7811300220	7811300217	78/11/22	50-277	g Q	7812010265 7812010264 78/11/29 7812010268 7812010266 78/10/26	50-327	S
7811300221 7811300223	7811300228 7811300211	78/09/29 78/11/24	50-358 50-318	8	7812010274 7812010272 78/10/20 7812010275 7812010275 78/10/23	50-245 50-219	0
7811200243	7811300241	78/11/03 78/11/03	50-334 50-334	٥	7812010278 7812010277 78/10/10	50-29	Ğ
7811300246	7811300241	/0/11/03	40 Hay	•			

ACCE ES ION					ACCE®10	N NUMBER			
ENCLOGURE	PHINCIPAL TOSTUTENT	DATE (SSUED	CATEGOR	Y	ENCLOBURE	PRINCIPAL DOCUMENT	DATE 18SVEO	SUBJECT	
7812010202 7812010205 7812010205 7812010206 7812010208	7812010280 7812010284 7812010291 7812010291 7812010291	78/10/18 78/10/23 78/11/05 78/11/06 78/11/06	50-320 50-409 50-317 50-317	0 0 0	7812050016 7812050017 7812050018 7812050019 7812050020	7812050012 7812050003 7812050008 7812050012 7812050012	78/11/18 78/11/16 78/11/24 78/11/18 78/11/18	50-259 50-259 50-248 50-259 50-259	P G P
7812010303 7812010305 7812010308 7812010347 7812010389	7812010291 7812010331 7812010336 7817010344 7812010344	78/11/06 78/11/22 78/10/20 78/11/14 78/11/14	50-317 50-368 50-320 50-312 50-312	0 0 F F	7812050022 7812050023 7812050025 7812050026 7812050027	7812050003 7812050003 7812050021 7812050003 7812050011	78/11/16 78/11/16 78/11/20 78/11/16 78/10/30	50-259 50-259 50-269 50-259 50-10	P 0 P 0
7612010362 7612010374 7612010377 7612010360 7612010361	7812010344 7812010370 7812010370 7812010370 7812010370	78/11/14 78/11/13 78/11/13 78/11/13 78/11/13	50-313 50-313 50-313 50-313	5 5 5 6	7812050029 7812050030 7812050031 7812050044 7812050091	7812050021 7812050021 7812050021 7812050043 7812050047	78/11/20 78/11/20 78/11/20 78/11/27 78/11/09	50~269 50~269 50~269 50~213 50~295	0 0 0
7812040012 7612040017 7812040019 7812040020 7812040026	7812040007 7812040007 7812040014 7812040007 7812040021	78/11/17 78/11/17 78/11/20 78/11/17 78/10/25	50~20& 50~20& 50~55& 50~20& 50~452	P T P	7812030037 7812030058 7812030067 7812030070 7812030070	7812050053 7812050055 7812050063 7812050063 7812050063	78/10/27 78/11/09 78/11/24 78/11/24 78/11/24	50~259 50~556 50~302 50~302 50~302	9 9 9
7812040031 7812040038 7812040046 7812040055 7812040059	7812040028 7812040033 7812040033 7812040049 7812040049	78/11/20 78/10/31 78/10/31 78/11/21 78/11/21	50-344 50-254 50-254 50-390 50-390	9 9 9 9	7812050074 7812050074 7812050097 7812050117 7812050125	7812050063 7812050092 7812050092 7812050111 7812050111	78/11/24 78/11/17 78/11/17 78/11/21 78/11/21	50-302 50-329 50-329 50-327 50-327	Q A Q Q
7812040062 7612040060 7812040074 7812040079 7812040084	7812040049 7812040049 7812040071 7812040071 7812040072	78/11/21 78/11/21 78/11/16 78/11/16 78/11/15	50-390 50-390 50-148 50-148 50-397	0 9 P 0	7812050133 7812050133 7812050140 7812050145 7812050145	7812050131 7812050135 7812050111 7812050144 7812050111	78/11/24 78/10/13 78/11/21 78/11/21 78/11/21	50-335 50-298 50-327 50-327	8 0
7812040127 7812040137 7812040144 7812040159 7812040163	7812040122 7812040133 7812040141 7812040156 7812040160	78/11/16 78/11/07 78/11/09 78/11/28 78/10/26	50-498 50-549 50-305 50-333 50-546	0 9 9	7612050150 7812050161 7812050162 7812050164 7812050165	7812050111 7812050153 7812050157 7812050160 7812050158	78/11/21 78/11/28 78/11/28 78/11/28 78/10/23	50-327 50-336 50-346 50-213 50-327	9 8 8 0
7812040170 7812040174 7812040175 7812040176 7812040178	7812040167 7812040172 7812040167 7812040173 7812040172	78/11/13 78/06/12 78/11/13 78/11/27 78/06/12	50-395 50-255 50-395 50-293 50-255	0 0 8 0	7812050170 7812050172 7812050175 7812030179 7812030181	7812050166 7812050169 7812050167 7812050173 7812050176	78/10/28 78/10/25 78/11/30 78/11/30 78/11/27	50-298 50-295 50-285 50-281	8 0 8 8
7812040181 7812040189 7812040195 7812040197 7812040204	7612040180 7612040187 7812040191 7812040192 7812040201	78/10/18 78/11/24 78/11/17 78/10/20 78/11/30	50-395 50-250 50-237 50-327 50-454	8 8 8	7812050140 7812050142 7812050148 7812050201 7812050201	7812050199	78/12/04 78/11/29 78/11/27 78/11/27 78/12/04	50-367 50-293 50-335 50-296 50-446	8 8 8
7812040207 7812040210 7812040211 7812040213 7812040214	7812040201 7812040208 7812040209 7812040209 7812040218	78/11/30 78/11/30 78/11/29 78/11/29 78/11/30	50-454 50-454 50-338 50-338 50-456	8 6 8	7812050206 7812050209 7812050211 7812050214 7812050218	7812050208 7812050208 7812050208	78/11/28 78/11/30 78/11/30 78/11/30 78/11/28	50-346 50-280 50-280 50-280 50-346	8 8 8
7812040215 7812040217 7812040219 7812040222 7812040225	7812040209 7812040209 7812040216 7812040221 7812040224	78/11/29 78/11/29 78/11/27 78/11/20 78/11/16	50-038 50-338 50-409 50-251 50-272	9 8 8 F	7812050221 7812050225 7812050225 7812050241 7812050242	7812050223 7812050236 7812050236	78/11/30 78/11/30 78/10/19 78/10/19 78/11/16	50-447 50-338 50-456 50-456 50-250	A B Q Q
7812040227 7812040233 7812040239 7812040241 7812040249	7812040226 7812040230 7812040237 7812040237 7812040243	78/10/27 78/11/29 78/11/29 78/11/29 78/11/17	50-390 50-280 50-155 50-155 50-89	8 2 8 9	7812030246 7812030251 7812030251 7812030252 7812050268	7812050240 7812050243 7812050245	78/11/16 78/11/16 78/11/30 78/11/09 78/11/09	50-250 50-250 30-259 30-305 50-390	9 9 9 8
7812040281 7812040288 7812040302 7812040324 7812040325	7812040277 7812040285 7812040301 7812040321 7812040322	78/07/22 78/11/09 78/11/27 78/11/15 78/10/23	50-413 50-305 50-466 50-275 50-260	9999	7812050270 7812050280 7812050280 7812050285 7812050285	7812050276 7812050283 7812050281	78/11/03 78/11/30 78/11/24 78/11/07 78/11/24	30-327 50-537 50-437 30-556 30-437	8 4 9
7812040327 7612040328 7612040330 7812040332 7812040334	7812040321	78/11/15 78/11/22 78/11/15 78/11/22 78/11/15	50-275 50-269 50-275 50-269 50-275	00000	7812050270 7812080275 7812080275 7812030275 7812030275	7812030283 7812030284 7812030283	78/11/07 78/11/24 78/11/07 78/11/24 78/11/07	50-97 50-437 50-97 50-437 50-97	Q Q A Q
7812040335 7812040338 7812040339 7812050002 7812050005	7612040321 7812040325 7612050001	78/11/R2 78/11/15 78/11/R2 78/10/27 78/10/27	30-269 30-273 50-269 50-13 50-13	9	7812030301 7812030304 7812030304 7812030307 7812030343	7812050286 7812050286 7812050303	78/11/24 78/11/07 78/11/07 78/10/24 78/11/16	50-437 50-97 50-97 60-327 50-333	G G O P
7812050009 7812050010 7812050013 7812050014 7812050015	7B12050004	78/11/16 78/11/24 77/12/13 78/11/24 78/11/24	50~259 50~348 50~3 50~348 50~348	0 0	78120 5034 78120 5034 78120 5034 78120 5034 78120 5037	7819050336 7819050350 7819050350	78/11/16 78/11/16 78/11/08 78/11/08 78/11/13	50-333 50-333 50-349 50-349 50-341	P T T

# CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

PRINCIPAL DATE SUBJECT ENCLOSURE DOCUMENT ISSUED CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	CATEGO	т
				CALEGU	RY
7812060009 7812060003 78/11/16 50-321 P 7812060013 7812060003 78/11/16 50-321 P	7812070063 7812070065	7812070056 7812070059	78/11/15	50-275	E 0
7812060021 7812060015 78/11/28 50-239 0 7812060026 7812060015 78/11/28 50-239 0 7812060028 7812060025 78/11/29 50-395 0	7812070067 7812070069 7812070071	7812070036 7812070059 7812070059	78/11/15 78/11/29 78/11/28	30-275 50-261 30-261	ě
7812060029 7812060025 78/11/29 50-395 0 781206000 7812060015 78/11/28 50-259 0	7812070075 7812070076	7812070059 7812070074	78/11/28 78/10/30	30-263 50-263	0
7812060032 7812060035 78/11/29 50-395 0 7812060033 7812060015 78/11/28 50-259 0 7812060035 7812060025 78/11/29 50-395 0	7812070097 7812070108 7812070113	7812070082 7812070105 7812070110	78/11/20 78/11/03 78/11/21	50-321 50-456 50-322	0 8
7612060048 7612060044 76/11/21 50-265 9 7812060052 7612060049 76/11/29 50-298 0	7912070116 7812070148	7812070111	78/11/30	30-445	к
7812060047 7812060064 78/11/03 50-027 0 7812060070 7812060064 78/11/03 50-027 0 7812060074 7812060065 78/11/30 50-027 0	7812070142 7812070142 7812070168 7812070178	7812070082 7812070103 7812070165 7812070174	78/11/20 78/11/30 78/11/30 78/12/03	50-321 50-556 50-325 60-333	0 L 8
7812060077 7812060072 78/11/03 50-409 Q 7812060112 7812060108 78/10/30 50-483 Q	7812070181 7812070182	7812070175 7812070180	78/11/30 78/12/03	50-324 50-3	8 P
7812060119 7812060003 78/11/16 50-321 P 7812060128 7812060124 78/10/27 50-305 Q 7812060129 7812060121 78/11/08 50-327 S	7812070188 7812070190 7812070195	7812070187 7812070189 7812070193	78/11/28 78/12/04 78/12/04	50-400 50-338 50-338	8
7812060142 7812060134 78/11/22 50~338 9 7812060137 7812060135 78/11/29 50~437 A 7812060172 7818060126 78/11/13 50~329 9	7812070199 7812070201	7812070196 7812070198	78/11/29 78/11/30	50~346 50~346	8
7812060172 7812060126 78/11/13 50-329 0 7812060177 7812060171 78/11/28 50-320 8 7812060178 7812060174 78/10/31 50-266 0	7812070204 7812070204 7812070213	7812070202 7812070203 7812070210	78/11/21 78/12/04 78/11/29	50-284 50-320 50-277	P 8
7812060185 7812060180 78/11/24 50-20 Q 7812060194 7812060180 78/11/24 50-20 Q 7812060203 7812060180 78/11/24 50-20 Q	7812070217 7812070220	7812070214 7812070218	78/11/28 78/12/01	30-325 50-219	8
7812060211 7812060207 78/11/27 50-368 Q 7812060219 7812060180 78/11/24 50-20 Q	7812070222 7812070233 7812070231	7812070221 7812070223 7812070228	78/12/01 78/12/01 78/11/20	50-263 50-440 50-344	Р 8 0
7812040220 78120402214 78/10/30 50-338 H 7812040228 7812040224 78/10/23 50-338 0	7812070237 7812070242	7812070227 7812070227	78/11/20 78/11/20	50-275 50-275	T T
7812060230 7812060225 78/10/31 50-254 0 7612060234 7812060231 78/10/31 50-295 0 7612060236 7812060231 78/10/31 50-295 Q	7812070246 7812070259 7812070288	7812070238 7812070250 7812070284	78/10/27 78/11/17 78/11/16	50-361 50-370 80-219	0 8 0
7812060244 7812060242 78/11/25 50-317 G 7812060262 7812060258 78/10/23 50-280 G 7812060272 7812060260 78/11/24 50-269 P	7812070290 7812070291	7812070284 7812070284	78/11/16 78/11/16	50-219 50-219	0
7812060274 7812060248 78710/31 50-327 0 7812060282 7812060276 78/11/29 50-285 0	7812070295 7812070296 7812070309	7812070284 7812070283 7812070301	78/11/L6 78/11/08 78/10/30	50-219 50-206 50-261	G G
7812060286 7812060275 78/10/13 50-184 0 7812060291 7812060287 78/10/31 50-327 0	7812070312 7812070315	7B12070301 7B12070313	78/10/30 78/11/03	145-06 945-06	G O
7812060293 7812060288 78/11/01 80-261 0 7812060300 7812060286 78/10/13 50-184 Q 7812060302 7812060290 78/11/28 50-466 A	7812070319 7812070320 7812080010	7812070317 7812070317 7812080006	78/11/28 78/11/28 78/11/03	20-580 20-586 20-586	0 0
7812060304 7812060298 78/10/27 80-244 Q 7812060307 7812060299 78/10/20 80-854 Q	7812080015 7812080023	7812080007 78120800013	76/12/01 78/11/18	465-05 840-05	Q
7812060308 7812060286 78/10/13 50-184 0 7812060316 7812060286 78/10/13 50-184 0 7812060319 7812060311 78/11/20 50-148 0	7812080025 7812080029 7812080043	7812080013 7812080013 7812080034	78/11/18 78/11/18 78/12/01	50-34B 50-34B 50-272	P
7812060326	7812080052 7812080052	7812080046 7812080046	78/11/02 78/11/02	50-518 50-518	0
7812060331 7812060327 78/11/24 50-369 F 7812060332 7812060324 78/10/13 50-148 0	7812080067 7812080068 7812080070	7612060055 7612060061 7812080061	78/11/09 78/19/01 78/19/01	30-358 80-316 80-316	8
7812060333 7812060330 78/11/21 80-269 6 7812060336 7812060334 78/11/01 80-338 0	. 7812080003	7812080080	78/11/02	50-334	G B
7812060336 7812060334 78/11/01 50-938 0 7812060339 7812060338 78/10/20 50-445 0 7812060340 7812060337 78/06/27 50-831 0 7812060341 7812060335 78/10/25 50-445 0	7812080087 7812080089 7812080103	7812080075 7812080086 7812080101	78/12/01 78/12/04 78/12/04	50-315 50-316 50-260	8
7812060342 7812060338 78/10/20 50-445 0 7812060345 7812060343 78/11/27 50-321 0	7812080111	7812080109 7812080109	78/19/05 78/19/05	50-277 50-277	R
7812060346 7812060344 78/10/25 50-271 0 7812060349 7812060348 78/10/31 50-285 0 7812060350 7812060343 78/11/27 50-321 0	7812080115 7812080118 7812080120	7812080113 7812080117 7812080119	78/11/06 78/11/30 78/12/06	50-272 50-245 50-316	8
7812060361 7812060348 78/10/31 50-285 Q 7812060365 7812060353 78/10/25 50-311 Q	7812080122	7812080117 7812080126	78/12/06	50-316	8
7812060357 7812060356 78/11/22 50-389 0 7812060358 7812060352 78/11/03 50-454 0	7818080130 7818080136 7818080138	7812080127 7812080134 7812080135	78/12/01 78/11/20 78/12/06	50-325 50-272 50-304	R
7812060362 7812060356 78/11/22 50-389 Q 7812060367 7812060365 78/10/27 50-333 Q	78:2080140 78:2080142	7812080137 7812080135	78/11/R9 78/12/06	50-409	P
7812060361 7812060376 78/11/30 50-361 A 7812060361 7812060388 78/10/24 50-315 0 7812070002 7812070001 78/11/20 50-128 0	7812080145 7812080147	7812080144 7812080144	78/11/03 78/11/03	50-334 60-334	0
7812070022 7812070019 78/11/28 50-364 G 7812070023 7812070016 78/10/27 50-518 G	7812080170	7912080048 7912080168	78/11/17 78/11/22	50-344 50-333	P
7818070024 7812070019 78/11/28 50-364 G 7812070026 7812070019 78/11/28 50-364 G 7812070030 7812070019 78/11/28 50-364 G	7812080173 7812080176 7812080190	7812080168 7812080168 7812080188	78/11/22 78/11/22 78/12/01	50-333 50-333 50-305	P P
7812070045 7812070041 78/10/31 50-105 0 7812070054 7812070052 78/11/28 50-373 A	7812080193 7812080205	7812080188 7812080202	78/12/01 78/11/21	50-305 50-546	P A

ACCESS10N	NUMBER				IO1E93DDA	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE	CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 168UED	BUBJECT CATEGOR	
7812080211 7812080219 7812080221 7812080238 7812110033	7812080210 7812080215 7812080213 7812080237 7812110031	78/11/28 78/10/30 78/11/02 78/10/31 78/11/29	50-302 50-13 50-518 50-326 50-566	U 0 8 0 A	7912120067 7912120067 7912120094 7812120097 7812120103	7812120080 7812120095 7812120091 7812120095 7812120102	78/12/06 78/12/08 78/12/08 78/12/07 78/12/07	50-244 50-264 50-253 50-220	PRRSR
7812110036 7812110042 7812110057 7812110069 7812110072	7812110031 7812110031 7812110034 7812110068 7812110070	78/11/29 78/11/29 76/11/22 78/12/01 78/11/30	50-566 50-566 50-498 50-522 50-437	A A 0 0 0	7812120110 7812120111 7812120112 7812120113 7812120113	7812120093 7812120104 7812120109 7812120108 7812120093	78/11/30 78/12/07 78/12/05 78/12/06 78/11/30	50-518 50-329 50-155 50-334 50-518	A A R B A
7812110074 7812110077 7812110116 7812110125 7812110127	7812110070 7812110093 7812110133 7812110122 7812110124	78/11/30 79/11/22 78/12/04 78/12/04 78/11/17	50-437 50-219 50-447 50-255 50-295	9 A R 8	7812120121 7812120124 7812120125 7812120127 7812120127	7812120115 7812120093 7812120119 7812120123 7812120093	78/12/05 78/11/30 78/12/06 78/12/07 78/11/30	50-295 50-518 50-250 50-219 50-518	8 A F 8 A
7612110132 7812110138 7812110139 7812110140 7812110143	7812110128 7812110134 7812110135 7812110136 7812110135	78/12/06 78/12/04 78/11/24 78/12/08 78/11/24	50-334 50-348 50-29 50-263 50-29	R B P R	7812120129 7812120132 7812120134 7812120136 7812120137	7812120116 7812120126 7812120130 7812120133 7812120131	78/12/07 78/12/06 78/11/30 78/12/05 78/11/30	50-336 50-409 50-249 50-219 50-313	9 R S 9 0
7812110145 7812110147 7812110154 7812110158 7812110159	7812110135 7812110144 7812110151 7812110156 7812110157	78/11/24 78/11/17 78/11/20 78/12/04 78/11/17	50-29 50-295 50-295 50-409 50-295	8 8 8	7812120139 7812120141 7812120142 7812120146 7812120146	7812120093 7812120135 7812120138 7812120140 7812120143	78/11/30 78/12/05 78/12/07 78/12/07 78/12/06	50-51B 50-293 50-313 50-346 50-334	8 8 8
7812110163 7812110164 7812110167 7812110172 7812110173	7812110161 7812110160 7812110165 7812110169 7812110170	78/11/17 78/11/22 78/11/30 78/12/04 78/12/04	50-295 50-295 50-409 50-344 50-312	8 8 8 8	7812120152 7812120153 7812120157 7812120173 7812120177	7812120074 7812120149 7812120162 7812120165 7812120174	78/12/07 78/12/05 78/12/07 78/12/06 78/12/07	50-470 50-344 50-315 50-346 50-260	K R 8 9 8
7812110174 7812110177 7812110178 7812110180 7812110182	7912110171 7812110169 7812110176 7812110175 7812110179	78/12/06 78/12/04 78/11/21 78/11/20 78/11/22	50-155 50-344 50-254 50-295 50-295	8 8	7812120181 7812120186 7812120206 78121202231	7812120172 7812120178 7812120200 7812120216 7812120225	78/12/07 78/12/07 78/12/05 78/11/09 78/11/06	50-346 50-316 50-395 50-331 50-305	8 R G
7812110183 7812110192 7812110196 7812110208 7812110210	7812110181 7812110191 7812110193 7812110204 7812110206	78/11/15 78/12/07 78/12/07 78/12/06 78/12/06	50-254 50-336 50-336 50-338 50-255	8 8	7812120235 7812120237 7812120239 7812120238 7812120248	7812120232 7812120232 7812120236 7812120241 7812120241	78/10/17 78/10/17 78/12/04 78/10/17 78/10/17	50-250 50-250 50-250 50-363 50-363	0 0 0
7812110225 7812110230 7812110235 7812110235 7812110240	7812110222 7812110220 7812110232 7812110237 7812110237	79/11/02 79/11/14 78/11/01 78/10/24 79/10/24	50-280 50-382 50-334 50-361 50-361	0 0 0	7812130004 7812130005 7812130008 7812130007 7812130044	7812130001 7812130001 7812130002 7812130035 7812130038	78/11/01 78/11/01 78/12/05 78/11/09 78/11/16	50-327 50-327 50-133 50-315 50-566	0000
7812110251 7612110268 7612110271 7812110273 7812110274	7812110245 7812110254 7812110254 7812110264 7812110272	78/11/03 78/11/30 78/11/30 78/11/30 78/10/17	50-324 50-482 50-482 50-482 50-277	G A A A	7812130049 7812130069 7812130072 7812130084	7812130035 7812130061 7812130070 7812130071 7812130080	78/11/09 78/11/21 78/11/24 78/10/16 78/11/21	50-315 50-549 50-471 50-352 50-502	99999
7812110276 7812110277 7812110279 7812110282 7812110297	7812110264 7812110272 7812110264 7812110264 7812110295	78/11/30 78/10/17 78/11/30 78/11/30 78/11/02	50~482 50~277 50~482 50~482 50~336	A A O	7812130087 7812130092 7812130098 7812130102 7812130103	7812130080 7812130071 7813130071 7812130071 7812130071	78/11/21 78/10/16 78/10/16 78/10/16 78/10/16	50-352 50-352 50-352 50-352	00000
7812110301 7812110305 7812110309 7812110310 7812110313	7812110275 7812110303 7812110307 7812110303 7812110307	78/11/02 78/10/27 78/11/30 78/10/27 78/11/30	50-334 50-245 50-364 50-245 50-364	0 0 0	7812130106 7812130112 7812130134 7812130140 7812130141	7812130096 7812130071 7812130129 7812130136 7812130135	78/11/25 78/10/16 78/11/09 78/12/08 78/12/06	50-344 50-352 50-331 50-331 50-267	8 40 6
7812110316 7812110320 7812110322 7812110323 7812110329	7812110314 7812110319 7812110319 7812110319 7812110326	78/11/23 78/11/22 78/11/22 78/11/22 78/11/30	50-245 50-333 50-333 50-333 50-219	9 9 9	7812130149 7812130160 7812130177 7812130171 7812130172	7812130136 7812130158 7812130163 7812130168 7812130169	78/12/08 78/12/04 78/12/04 78/12/06 78/12/07	50-331 50-298 50-267 50-286 50-267	P R R G
7812120017 7812120018 7812120020 7812120024 7812120026	7812120014 7812120014 7812120014 7812120022 7812120022	78/11/30 78/11/30 78/11/30 78/10/17 78/10/17	50-424 50-424 50-424 50-322 50-322	0	7812130174 7812130179 7812130181 7812130183 7812130186	7812130170 7812130176 7812130178 7812130176 7812130184	78/12/07 78/12/07 78/12/08 78/12/07 78/12/08	50-318 50-267 50-265 50-267 50-10	8 R B R
7812120030 7812120032 7812120033 7812120034 7812120035	7812120027 7812120027 7812120029 7812120027 7812120027	78/12/04 78/12/04 78/11/27 78/12/04 78/12/04	50-445 50-445 50-395 50-445 50-445	A G A	7812130187 7812130192 7812130194 7812130197 7812130200	7812130193 7812130190 7812130189 7812130193 7812130149	78/12/07 78/12/06 78/12/07 78/12/04 78/11/22	50-318 50-267 50-317 50-320 50-263	8 8 9 9
7812120036 7812120041 7812120042 7812120044 7812120045	7812120027 7812120038 7812120038 7812120038 7812120029	78/12/04 78/12/04 78/12/04 78/12/04 78/11/27	50-445 50-580 50-580 50-580 50-395	А Н Н 0	7812130202 7812130207 7812130209 7812130210 7812130251	7812130191 7812130177 7812130206 7812130177 781213024)	78/12/04 78/12/08 78/11/09 78/12/08 78/12/07	50-341 50-361 50-315 50-361 50-261	0 4 0 4 0

# PRINCIPAL DOCUMENTS ACCESSION NUMBER PRINCIPAL ACCESSION NUMBER

ACCE8300A					ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGOR	
7812130286 7812130289 7812130295 7812130296 7812130298	7812130281 7812130287 7812130287 7812130294 7812130287	78/12/01 78/12/04 78/12/04 78/12/07 78/12/04	50-155 50-491 50-491 50-324 50-491	P 0 0	7812140275 7612140277 7612140279 7612140279 7812140283	7812140273 7812140195 7812140273 7812140273 7812140273	78/12/07 78/12/01 78/12/07 78/12/07 78/12/07	30-275 30-335 50-275 50-275 50-275	0000
7812130300 7812130304 7812130310 7812130311 7812130314	7812130294 7812130294 7812130294 7812130306 7812130301	78/12/07 78/12/07 78/12/07 78/12/05 78/11/17	50-324 50-324 50-324 50-269 50-275	0 0 0 0	781214026 7812140202 7812140202 7812140308 7812140311	7812140286 7812140297 7812140292 7812140292 7812140299	78/11/29 78/11/29 78/11/30 78/11/30 78/12/07	30-327 50-70 50-206 50-206 50-206	8 H P P
7612130317 7612130319 7612130321 7612130324 7812130327	7812130306 7812130316 7812130309 7812130316 7812130309	78/12/05 78/11/15 78/12/07 78/11/15 78/12/07	50-269 50-344 50-313 50-344 50-313	0 0 0 0	7812140318 7812140331 7812140339 781214038 7812150004	7812140316 7812140325 7812140316 7812140359 7812150001	78/11/27 78/11/16 78/11/27 78/11/13 78/11/16	50-245 50-437 50-245 50-266 50-275	P H P H O
7812130332 7812130336 7812130338 7812130342 7812130345	7812130309 7812130309 7812130329 7812130331 7812130334	70/12/07 78/12/07 78/11/09 78/12/01 78/11/24	50-313 50-313 50-295 50-187 50-219	0 0 0 P	7812150040 7812150063 781215007 781215002 7812150026	7912150030 7912150057 7812150072 7912150072 7912150072	78/11/07 78/11/07 78/12/04 78/12/04 78/12/04	50-327 50-261 50-245 50-245 50-245	О О Р Р
7812130346 7812130347 7812130350 7812130351 7812130353	7812130331 7812130331 7812130331 7812130334 7812130334	78/12/01 78/12/01 78/12/01 78/11/24 78/11/24	50-187 50-187 50-187 50-219 50-219	0 0 P P	7812150114 7812150117 7812150117 7812150195 7812150199	7812150107 7812150107 7812150107 7812150180 7812150192	78/12/05 78/12/05 78/12/05 78/11/03 78/11/06	50-285 50-285 50-285 30-206 50-390	P P G G
7812130368 7812130373 7812130376 7812130380 7812130385	7812130363 7812130363 7812130363 7812130363 7812130363	78/12/05 78/12/05 78/12/05 78/12/05 78/12/05	50-344 50-344 50-344 50-344	P P P P	78121 20234 78121 30240 78121 30241 78121 30244 78121 30263	7812150232 7812150214 7812150237 7812150242 7812150261	78/12/11 78/11/01 78/12/11 78/12/11 78/12/12	50-305 50-245 50-266 50-272 50-255	8 8 8
7812130387 7812130390 7812140012 7812140014 7812140016	7812130363 7812130389 7812140010 7812140013 7812140010	78/12/05 78/12/06 78/10/31 78/12/01 78/10/31	50-344 50-275 50-263 50-368 50-263	P G	78121 50265 78121 50269 78121 50272 78121 50273 78121 50274	7812150264 7812150259 7812150270 7812150259 7812150267	78/12/11 78/11/15 78/12/09 78/11/15 78/12/09	50-445 50-443 50-237 50-443 50-333	C 0 8 0 R
7812140017 7812140020 7612140027 7812140028 7812140030	7812140013 7812140013 7812140024 7812140021 7812140024	78/12/01 78/12/01 78/12/01 78/10/27 78/12/01	50-368 50-368 50-245 50-329 50-245	ը 6 6	70121 50293 78121 50288 78121 50292 78121 50294 78121 50298	7812150259 7812150286 7812150290 7812150287 7812150296	78/11/15 78/12/11 78/12/11 78/12/07 78/12/08	50-449 50-29 50-271 50-321 50-346	Q R R R R
7812140034 7812140038 7812140039 7812140042 7812140046	7812140024 7812140033 7812140037 7812140040 7812140041	78/12/01 78/11/28 78/11/14 78/11/27 78/12/05	\$0-245 \$0-213 \$0-312 \$0-29 \$0-269	P Q P	78121 50308 78121 5031 78121 5032 78121 5034 78121 50347	7812130301 7812130310 7812130330 7812130343 7812130334	78/12/11 78/12/08 78/12/11 78/12/01 78/12/07	50-336 50-133 50-324 50-400 50-366	R R R Q R
7812140048 7812140055 7812140059 7812140066 7812140069	7812140041 7812140053 7812140053 7812140063 7812140065	78/12/05 78/12/05 78/12/05 78/11/08 78/10/27	50-269 50-269 50-269 50-331 50-97	0 0 0 P	7812130351 7612150357 7812180037 7812180047 7812180049	7812150348 7812150355 7812180027 7812180045 7812180045	78/12/11 78/12/11 78/11/30 78/11/22 78/11/22	50-261 50-309 50-275 50-289 50-289	RROPP
7812140072 7812140085 7812140098 7812140114 7812140118	7812140070 7812140081 7812140095 7812140108 7812140117	78/10/31 78/12/01 78/11/28 78/12/06 78/12/05	50-70 50-10 50-20 50-400 50-348	9 0 p 0 q	7612160051 7812160055 7812160054 7812160075 7812160079	7812180045 7812180057 7612180060 7812180072 7812180076	78/11/22 78/11/03 78/11/29 78/11/27 78/11/28	50-289 50-3 50-13 50-285 50-182	P P P
7812140119 7812140122 7812140126 7812140129 7812140131	7812140117 7812140117 7812140123 7812140123 7812140125	78/12/05 78/12/05 78/12/12 78/12/12 78/12/12	50-349 50-348 8 <i>0-280</i> 50-280 50-280	9 9	7612180081 7812180082 7812180082 7812180086 7812180105	7812180072 7812180078 7812180072 7812180076 7812180104	78/11/27 78/11/03 78/11/27 78/11/28 78/11/30	50-285 50-20 50-285 50-182 50-277	P P P
7812140139 7812140140 7812140147 7812140152 7812140154	7812140130 7812140137 7812140141 7812140146 7812140149	78/11/08 78/12/09 78/11/13 78/12/08 78/12/08	50-329 50-346 50-266 50-251 50-220	0 8 0 P 8	7812180107 7812180108 7812180112 7812180141 7812180149	7812180104 7812180104 7812180104 7812180138 7812180145	78/11/30 78/11/30 78/11/30 78/12/11 78/12/08	50-277 50-277 50-277 50-250 50-249	9 P 0 0
7812140156 7812140157 7812140160 7812140161 7812140164	7812140151 7812140153 7812140158 7812140159 7812140155	78/11/07 78/12/06 78/11/11 78/12/12 78/12/07	50-280 50-232 50-304 50-368	88 67	7812180151 7812180155 7812180157 7812180161 7812180167	7812180142 7812180150 7812180154 7812180153 7812180162	78/12/13 78/12/11 78/12/12 78/11/29 78/12/01	50-213 50-302 50-277 50-363 50-366	8 8 8
7812140165 7812140169 7812140181 7812140229 7812140224	7812140163 7812140167 7812140177 7812140224 7812140224	78/11/11 78/12/11 78/12/12 78/12/12 78/12/12	50-261 50-272 50-443 50-281 50-281	8 9 8	7812180169 7812180170 7812180172 7812180174 7812180177	7812180163 7812180164 7812180168 7812180173 7812180174	78/12/08 78/11/20 78/12/09 78/07/24 78/12/08	50-321 50-321 50-293 50-271 50-10	8 8 8 8
7812140246 7812140257 7812140263 7812140265 7812140270	7812140244 7812140255 7812140252 7812140195 7812140195	78/11/14 78/12/01 78/12/07 78/12/01 78/12/01	50-445 50-406 50-366 50-335 50-335	М 9 9 9	7812180178 7812180189 7812180184 7812180186 7812180184	7812180175 7812180177 7812180180 7812180182 7812180190	78/12/07 78/12/10 78/12/08 78/11/22 78/07/25	50-249 50-366 50-334 50-366 50-271	8 9 8

ENCLOSURE	PRINCIPAL BDCUMENT	DATE 189UED	EU9JECT CATEGOR	4	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	CATEOUR	
7812160195	7812180188	78/12/05	50-270	8	7812200109	7812200105	78/11/17	50-263	0
7812180177 7812180202	7812180193 7812180198	78/07/24 78/12/07	50-271	8 8	7812200133 7812200158	78122001 <b>33</b> 7812200136	78/12/13 78/12/08	50-382 50-13	A
7812160205	7812180201	78/11/29	50-366	8	7812200161	7812200156	78/12/0B	50-13	ā
7812190208	7812180204	78/12/13	50-219	8	7812200165	7812200163	78/12/15	50-348	В
7812180212	7812180207	78/12/12	50-316 50-271	8	7612200174 7812200177	7812200173 7812200175	78/12/14 78/11/01	50-315 50-458	R
7812180216 7812180217	7812180213 7812180214	78/07/24 78/12/11	50-246	8	7812200179	7812200175	78/12/11	50-302	R
7812180218	7812180210	78/19/12	50-10 50-271	J S	7812200181 7812200182	761220017B 7612200160	78/12/11 78/12/14	50-302 50-219	8 R
7812180222	7812180219	76/12/13							
7812180≈25 2812180≈8	7812180220 7812180223	78/12/08 78/12/08	50-366 50-237	8	7812200185 781220018 <i>5</i>	7812200183 7812200184	78/12/01 78/12/15	50-293 50-445	R A
3815180575	7812180226	78/12/06	50-595	F	7812200195	7812200193	78/12/13	50-247	8
7812180234 7812180239	7812180231 7812180236	78/11/22 78/11/30	50-366 50-295	B	7812200197 7812200199	7812200196 7812200198	78/12/12 78/12/13	50-312 50-324	R B
					7812200201	7812200200			
7812180240 7612180241	7812180235 7812180237	78/11/30 78/08/10	50-275 50-271	8	7812200201	7812200200	78/12/13 78/12/14	50-324 50-316	8 R
7812100242	7812180236	78/11/30	50-295 50-295	P	7812200207 7812200208	7812200204 781220020&	78/12/13 78/12/13	50-280 50-247	8 8
7812180244 7812180245	7812180234 7812180243	78/11/30 78/08/23	50-267	R	7812200210	7812200209	78/12/14	50-247	8
7812180302	7812180292	78/12/10	50-338	٥	7812200215	7812200211	78/12/15	50-263	8
7812180311	7812190309	78/11/09	50-302	0	7812200217	7812200213	78/12/13	50-309	8
7812180316 7812180317	7812180313 7812180312	78/12/07 78/11/09	50-335 50-302	0	7812200218 7812200223	7812200214 7812200220	78/12/18 78/12/14	50-35B 50-309	K P
7612180323	7812180321	78/12/11	50-267	P	7812200229	7812200225	78/12/14	50-368	8
7812180325	7812100320	78/11/09	50-259	0	7812200231	7812200227	78/12/12	50-285	8
7812180331	3815180358	78/11/03	50-267	0	7812200239 7812200240	7812200234	78/12/14	50-338 50-219	8
7812180334 7812180306	7812180333	78/12/08 78/12/08	30-400 50-400	g G	7812200241	7812200236 7812200235	78/12/14 78/11/28	50-254	R
7812180338	7812180333	78/12/08	50-400	G	7812200245	7812200242	78/12/15	50-362	C
7812180340	7812180335	78/11/14	50-024	g	7812200246	7912200244	78/11/30	50-259	ĸ
7812180342 7812180343	7 <i>81218</i> 0339 7812180333	78/12/11 78/12/09	50-399 50-400	M	7612200247 7612200250	7812200243 7812200248	78/12/13 78/12/15	50-537 50-382	A K
7812180345	7812100335	70/11/16	50-324	q	7812200251	7912200243	78/12/13	50-537	A
7812180350	7812180348	78/10/30	90-548	Q	7812200254	7812200252	78/12/13	50-309	8
7812180351	7812180346	78/12/08	50-348	9	781 2200255	7812200253	78/12/12	50-338	R
7812180353 7812180356	7812180349 7812180348	78/11/08 78/10/30	50~416 50~298	Q Q	7812200287 7812200262	7812200253 7812200260	78/12/12 78/12/01	50-338 50-280	R
7812180358	7812180352	78/12/11	50-290	Qi P	7812200272 7812200273	7812200244 7812200270	78/12/08 78/12/11	50-285 50-302	9
7812180380	7812180376	78/11/30	50-265						
7812190389 7812180390	7812180386 7812180376	78/11/30 78/11/30	50-160 50-285	E	7812200274 7812200276	7812200271 7812200116	78/12/08 78/11/29	50-298 50-219	8 P
7812180401	7812180401	78/03/21	50-70	P	781220027B	7812200275	78/12/11	50-320	8
7812180424 7812190020	7812180421 7812190001	78/12/01 78/12/14	50-59 50-70	9	7812200280 7812200287	7812200116 7812200283	78/11/29 78/12/14	50-219 50-263	P 8
				Q	78:2200289	7812200288	78/11/20	50-395	.1
7812170059 7812170061	7812190053 7812190053	78/10/31 78/10/31	50-313 50-313	Q.	7812200293	7812200292	78/11/17	50-358	ă
7812190073	7812190071	78/12/08	50-528 50-587	B	7812200300 7812200302	7812200299 7812200299	78/11/15 78/11/15	50-255 50-255	G G
7812190074 7812190107	7812170072 7812170105	78/12/12 78/12/14	50-219	В	7812200307	7812200296	78/12/15	50-280	0
7812190111	7812190110	78/12/11	50-296	Θ	7812200308	7812200306	78/11/17	50-374	Q
7812190116	7812190115	78/12/13	50~346	8	7812200315	7812200312	78/12/07	50-488 50-488	0
7012190122 7812190123	7812190119 7812190118	78/12/13 78/12/14	50~296 50~261	2	7812200318 7812200349	7612200312 7812200348	78/12/07 78/11/24	50-482	8
7812190124	7812190120	78/12/12	30-361	ĸ	7812210005	7812210003	70/11/17	50~358	Q
7812190129	7812190117	78/10/27	50~483	o	7812210029	7812210027	78/12/07	50-498	Q
7812190130 7812190131	7812190127 7812190121	78/12/11 78/12/08	30~269 30~247	8	7812210039 7812210043	7812210035 7812210041	79/12/07 78/11/21	50-413 50-358	Q.
7812190134	7812190132	78/12/15	90~320	R	7812210048	7812210035	78/12/07 78/11/14	50-413 50-282	Q.
7812190139	7812190137	78/12/14	50~331	R	7812210049	7812210046			
7812190142 7812190149	7812190089	78/12/08	50-445 50-280	g	7812210050 7812210052	7812210047 7812210047	78/12/08 78/12/08	50-244 50-244	P
7812190132	7812190148 7812190151	78/12/15 78/12/07	30-280 84C-00	P R	7812210054	7812210046	78/11/14	50-282	0
7812190155 7812190155	7812190117 7812190153	78/10/27 78/12/08	50~493 50~287	8	7812210055 7812210056	7812210047 7812210053	78/12/08 78/11/24	50-244 50-245	P Q
								50-413	a
7812190159 7812190160	7812190157 7812190158	78/12/06 78/11/17	50-204 50-329	R	7812210061 7812210064	7812210059 7812210059	78/12/11 78/12/11	50-413	G
7812190162	7812190161	78/12/02	50-259	A	7812210070	7812210066	78/11/17 78/12/11	50-245 50-250	P G
7812190170 7812190172	7812190166 7812190171	78/12/13 78/11/29	50-289 30-344	R	7812210071 7812210074	7812210068 7812210066	78/11/17	50-245	P
7812190180	7812190174		50-3	P	7812210075	7812210069	78/11/17	50-546	Q
7812190185	7812190184	78/12/54 78/12/03	50-454	A	7812210076	7812210068	78/12/11	50-230	Q
7812190188 7812190193	7812190184 7812190187	78/12/05 78/11/08	50-454 50-267	A	7812210077 7812210078	7812210066 7812210081	78/11/17	50-245 50-361	P
7812190197	7 B12190194	78/11/17	50-133	ă	7812210102	7812210100	78/12/15	50-324	P
7812190238	7812190235	79/12/06	50-250	a	7812210104	7812210100	78/12/13	50-324	P
7812190243	7812190235	78/12/06	50-250	G	7812210107 7812210109	7812210100 7812210100	78/12/15 78/12/15	50-324 50-324	P
7812200057 7812200075	7812200034 7812200091	78/11/30 78/11/09	20~288 20~229	a a	7812210113	781221010B	78/11/13	20-580	G.
7812200099	7812200091	78/11/09	50-282	Q	7812210114	7812210110	78/12/13	50-328	8

ACCESS10	NUMBER				ACCESSII	N NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOS		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	BUBJECT CATEGOR	
7812210119 7812210131 7812210147 7812210149	7612210110 7612210120 7612210143 7612210138	78/12/15 78/11/17 78/11/08 78/12/06	50-328 50-264 50-460 50-335	8000	7812260092 7812260129 7812260134 7812260134 7812260134	7812260087 7812260126 7812260131 7812260131	78/11/30 78/12/18 78/12/21	50-443 50-322 50-327	0 A K K
7812210153 7812210154 7812210155	7812210143 7812210138 7812210152	78/11/09 78/12/05 78/11/09	50-460 50-335 50-324	0 0	7812260156 7812260170 7812260172	7812260154 7812260166 7812260169	78/12/18 78/11/07 78/12/15 78/12/14	50-322 50-321 50-458 50-266	P A F
7812210160 7812210161 7812210162 7812210166	7812210157 7812210143 7812210159 7812210143	79/12/15 79/11/08 78/10/24 78/11/08	50-269 50-460 50-368 50-460	R 0 0	7612280174 7612280194 7612280203 7812280204	7812260168 7812260191 7812260200	78/12/14 78/12/15 78/12/20	50-496 50-289 50-285	A 8 P
7612210169 7612210175 7612210179 7612210183	7812210159 7812210167 7812210178 7812210167	78/10/24 78/12/15 78/11/13 78/12/15	50-36B 50-500 50-445 50-500	O A O	7812260209 7812260216 7812260219 7812260223	7812260202 7812260207 7812260214 7812260213 7812260218	78/12/22 78/12/20 78/12/14 78/12/14 78/12/18	50-341 50-282 50-334 50-245 50-273	К В Р 8 К
7812210184 7812210185 7812210192 7812210193 7812210200	7812210180 7812210181 7812210187 7812210189 7812210193	78/11/17 78/12/14 78/12/14 78/12/15 78/12/06	50-298 50-325 50-325 50-237 50-275	8 8	7812260237 7812260248 7812260258 7812260261 7812260287	7012260222 7012260244 7012260256 7012260259 7012260288	78/12/20 78/12/14 78/12/19 78/12/13 78/12/08	50-306 50-318 50-263 50-320 50-245	8 8 8 8
7812210204 7812210209 7812210210 7812210211 7812210211	7812210201 7812210197 7812210206 7812210207 7812210202	70/12/13 78/11/30 78/12/14 78/12/14 78/12/14	50-213 50-275 50-272 50-3 50-349	R A F R	7812260295 7812260205 7812260205 7812260206 781226026	7812260288 7812260288 7812260298 7812260280 7812260323	78/12/08 78/12/08 78/11/28 78/12/08 78/12/13	50-245 50-245 50-329 50-245 50-263	P C P P
7812210213 7812210219 7812210220 7812210221 7812210222	7612210203 7612210214 7612210214 7612210217 7612210218	78/12/01 78/12/06 78/12/11 78/12/08 78/12/14	50~295 50~295 50~313 50~304 50~325	8 9 8	7812270009 7812270020 7812270023 7812270033 7812270040	7812270003 7812270017 7812270018 7812270030 7812270030	78/12/15 78/11/09 78/12/04 78/11/30 78/11/30	50-220 50-313 50-263 50-320 50-320	P G H O
7812210225 7812210226 7812210228 7812210232 7812210235	7012210223 7812210224 7812210227 7812210230 7812210229	78/12/01 78/12/11 78/12/07 78/12/18 78/11/28	50-275 50-368 50-275 50-255 50-275	A 0 8 A	7612270051 7612270056 7612270056 7612270057 7612270066	7812270047 7812270030 7812270030 7812270047 7812270062	78/11/21 78/11/30 78/11/30 78/11/21 78/11/20	50-209 50-320 50-320 50-289 50-346	0 0 0
7812210239 7812210245 7812210252 7812210260 7812210263	7812210234 7812210242 7812210244 7812210259 7812210261	78/12/11 79/11/30 78/11/30 78/12/01 78/12/15	50-295 50-249 50-249 50-397 50-361	8 8 9	7812270070 7812270076 7812270076 7812270078 7812270151	7812270062 7812270073 7812270073 7812270074 7812270034	78/11/20 78/12/12 78/12/12 78/11/29 78/11/09	50-346 50-485 50-485 50-409 50-341	90000
7812210265 7812210267 7812210301 7812210308 7812210312	7812210261 7812210281 7812210295 7812210295 7812210295	70/12/15 70/12/13 70/12/06 78/12/06 70/12/06	50-361 50-276 50-29 50-29 50-29	8 Q P P	7812270153 7812270158 7812270158 7812270166 7812270181	7812270149 7812270034 7812270157 7812270163 7812270178	78/11/13 78/11/09 78/12/06 78/12/20 78/12/20	50-334 50-341 50-502 50-407 50-315	G C K P
7812210324 7812210337 7812210344 7812210345 7812210346	7812210319 7812210333 7812210333 7812210319 7812210333	78/12/08 78/12/08 78/12/08 78/12/08 78/12/08	50-400 50-302 50-302 50-400 50-302	@ @ @	7812270197 7812270197 7812270206 7812270214 7812270217	7612270193 7612270196 7612270201 7812270211 7612270213	78/12/18 78/12/15 78/12/20 78/12/18 78/12/22	30-104 30-206 30-247 30-369 30-283	P B ♠ B
7612210350 7612210363 7612210376 7812210380 7812210388	7812210333 7812210355 7812210370 7812210370 7812210370	78/12/08 70/11/08 78/11/15 78/11/15 78/11/15	50-202 50-259 50-206 50-206	0 0 0	7812270224 7812270225 7812270235 7812270238 7812270243	7812270219 7812270220 7812270232 7812270235 7812270239	78/12/22 78/12/20 78/12/21 78/12/20 78/12/19	50-285 50-315 50-263 50-338 50-362	8 8 8
7812210399 7812210401 7812210511 7812220029 7812220031	7812210370 7812210396 7812210506 7812220027 7812220027	78/11/15 78/12/06 78/12/15 78/11/30 78/11/30	50-206 50-482 50-247 50-305 50-305	8 9	7812270245 7612270249 7812270250 7812270251 7812270253	7812270241 7812270247 7812270242 7812270246 7812270252	78/12/21 78/12/19 78/12/20 78/12/21 78/12/20	50-263 50-313 50-333 50-263 50-316	9 8 8
7812220040 7812220064 7812220069 7812220075 7812220077	7812220037 7812220063 7812220062 7812220074 7812220076	78/12/04 78/12/14 78/12/11 78/12/14 78/12/15	50-358 50-277 50-267 50-155 50-317	A R F 8 R	7812270250 7812270252 7812270253 7812270254 7812270258	7812270252 7812270258 7812270257 7812270252 7812270252	78/12/20 78/12/22 78/12/19 78/12/20 78/12/20	50-316 50-285 50-261 50-316 50-316	8 8 8 8
7812220080 7812220084 7812220086 7812220098 7812220100	7812220079 7812220081 7812220083 7812220093 7812220099	78/12/18 78/12/15 78/12/18 78/12/18 78/12/18	50-59 50-302 50-272 50-286 50-333	F 8 8 8	7812270269 7812270271 7812270272 7812270273 7812270273		78/12/19 78/12/19 78/12/20 78/12/20 78/12/18	50-259 50-237 50-316 50-366 50-335	8 8
7812220105 7812220107 7812220118 781226008 7812260019	7812220102 7812220104 7812220113 7812240003 7812240014	78/12/15 78/12/14 78/12/21 78/12/15 78/12/15	50-302 50-255 50-244 50-387 50-247	8 9 9	7612270277 7612270281 7612270282 7612270283 7812270283	7812270278	78/12/20 78/12/20 78/12/20 78/12/22 78/12/14	30-316 50-281 50-316 50-348 50-321	8 8 8 8
7812260023 7812260037 7812260057 7812260064 7812260067	7812260014 7812260014 7812260044 7812260062 7812260063	78/12/15 78/12/15 78/12/09 78/12/13 78/11/28	50-247 50-247 50-259 50-269 50-329	P P O P O	7612270286 7612270286 7612270287 7612270293 7612270293	7812270284 7812270289 7812270291	78/12/20 78/12/14 78/12/19 78/12/21 78/12/20	50-316 50-249 50-225 50-302 50-280	8 8

7812280291 7812280294 7812280306 7812280310 7812280315 7812280315 7812280319 7812280314 7812280314 7812280304 7812280304	7612260284 7812280284 7812280202 7612280302 7612280307 7812280307 7812280307 7612280323 7612280323 7612280323 7812280323	78/12/14 78/12/15 78/12/14 78/12/13 78/11/03 78/12/15 78/12/15 78/12/15 78/11/09 78/12/07 78/12/07 78/12/07 78/12/07	50-321 50-321 50-323 50-375 50-375 50-375 50-345 50-318 50-327 50-327 50-327	a a a a a a a a a a a a a a a a a a a	7812290245 7812290247 7812290230 7812290230 7812290230 7812290237 7812290271 7812290270 7812290270 7812290270	7812270241 7812270241 7812270254 7812270254 7812270264 7812270266 7812270266 7812270266 7812270266 7812270266	78/12/11 78/11/15 78/12/04 78/12/07 78/12/07 78/12/07 78/12/09 78/12/09 78/11/03	50-461 50-485 50-322 50-576 50-556 50-596 50-596 50-295	9 8 8
7812280361 7812280264 7812280267 781228027 7812280280 7812280288 7812280290	7812280238 7812280238 7812280238 7812280274 7812280271	78/12/18 78/12/18 78/12/18 78/12/18 78/12/08 78/12/15	50-269 50-269 50-269 50-267 50-237	е р н о	7812290227 7812290228 7812290238 7812290238 7812290243 7812290243	7812290216 7812290225 7812290216 7812290234 7812290241 7812290239	78/12/22 78/12/22 78/12/22 78/11/16 78/12/11 78/11/28 78/12/20	50-334 50-285 50-334 50-387 50-461 50-267 50-498	8 8 0 G A
7812280229 7812280234 7812280239 7812280244 7812280245 7812280247	7812280224 7812280231 7812280237 7812280237 7812280241 7812280238	78/11/21 78/11/30 78/11/13 78/11/13 78/11/17 78/11/17	50-456 50-219 50-367 50-361 50-269	9 9 9 9 9	7812270218 7812270219 7812270220 7812270223 7812270224 7812270224	7812290209 7812290213 7812290211 7812290216 7812290221 7812290222	78/12/22 78/12/22 78/11/15 78/12/22 78/12/21 78/12/19	50-287 50-219 50-334 50-334 50-260 50-334	8 9 8 8
7812280152 7812280200 7812280204 7812280215 7812280224	7812280151 7812280197 7812280197 7812280210 7812280223	78/12/21 78/12/20 78/12/20 78/12/08 78/11/28	50-466 50-477 50-477 50-311 50-361	6 0 0	7812290207 7812290208 7812290212 7812290214 7812290215	7812290202 7812290200 7812290205 7812290209 7812290210	78/12/26 78/12/22 78/12/22 78/12/22 78/12/21	50-255 50-245 50-245 50-287	8 8 8
7812280100 7812280100 7812280130 7812280135 7812280142	7812280055 7812280079 7812280128 7812280133 7812280137	78/12/21 78/12/21 78/12/20 78/12/21 78/12/18	50-424 50-447 50-344 50-369 50-336	а в к к Q	7812290152 7812290164 7812290173 7812290185 7812290201	7812290145 7812290160 7812290169 7812290182 7812290197	78/12/07 78/12/07 78/12/20 78/12/22 78/12/07	50-424 50-245 50-215 50-298	8 R P 8
7812280026 7812280040 7812280069 7812280070 7812280073	7812280019 7812280019 7812280056 7812280056 7812280066	78/12/07 78/12/07 78/12/15 78/12/15 78/12/15	50-250 50-250 50-424 50-424 50-424	P 0 0	7812290125 7812290128 7812290141 7812290143 7812290151	7812290114 7812290114 7812290136 7812290138 7812290148	78/12/20 78/12/20 78/12/27 78/12/27 78/12/19	50-327 50-327 50-480 50-384 50-508	0 0 4 4 4
7812280012 7812280015 7812280016 7812280018	7612280009 7812280011 7812280011 7812280011	78/11/13 78/12/12 78/12/12 78/12/12	50-272 50-305 50-305 50-305	G P P P	7812270111 7812270112 7812270115 7812270117 7812270122	7812290109 7812290096 7812290113 7812290114 7812290114	78/12/18 78/12/26 78/12/20 78/12/20	50-553 50-302 50-361 50-327 50-327	0 0 0 0
7812270436 7812270449 7812270449 7812270455 7812270478	7812270432 7812270432 7812270446 7812270450 7812270453 7812270469	78/12/14 78/11/22 78/11/13 78/11/22 78/11/13 78/12/06	50-247 50-243 50-220 50-133 50-333 50-322	9 9 9 9	7812290097 7812290101 7812290102 7812290105 7812290107	7812290089 7812290095 7812290095 7812290100 7812290108	78/11/30 78/12/18 78/12/22 78/12/05 78/12/18 78/11/14	50-219 50-302 50-275 50-502 50-302	8 9 5 9 9 9
7812270391 7812270391 7812270409 7812270415 7812270423	7812270387 7812270387 7812270401 7812270401 7812270417	78/11/15 78/11/27 78/12/14 78/12/14 78/11/13	50-390 50-508 50-73 50-73 50-272	0 P P	7812290066 7812290067 7812290070 7812290078 7812290088	7812290055 7812290055 7812290055 7812290076 7812290062	78/11/22 78/12/15 78/12/15 78/11/13 78/11/17	50-339 50-438 50-438 50-201 50-280	9009
7812270359 7812270364 7812270368 7812270372 7812270382	7812270357 7812270357 7812270357 7812270357 7812270377	78/12/15 78/12/15 78/12/15 78/12/15 78/11/28	50-369 50-369 50-369 50-369 50-397	0 0 0	7812290052 7812290053 7812290068 7812290061 7812290064	7812290049 7812290051 7812290055 7812290057 7812290055	78/12/15 78/11/09 78/12/15 78/12/07 78/12/15	50-220 50-271 50-438 50-336 50-438	0 0 0
7812270329 7812270331 7812270333 7812270339	7812270325 7812270326 7812270332 7812270337	78/12/18 78/12/20 78/12/22 78/11/13	50-366 50-366 50-285 50-407	8 8 9	7812290044 7812290045 7812290046 7812290048	7812290042 7812290038 7812290038 7812290038	78/11/15 78/12/15 78/12/15 78/12/15	50-311 50-390 50-390 50-390	0 0 0
7812270317 7812270318 7812270321 7812270323 7812270324	7812270314 7812270315 7812270319 7812270316 7812270320	78/12/20 78/12/18 78/12/20 78/12/21 78/12/20	50-366 50-321 50-366 50-219 50-280	S S S S	7812290020 7812290025 7812290032 7812290034 7812290043	7812290017 7812290017 7812290022 7812290028 7812290038	78/11/24 78/11/24 78/11/24 78/11/13 78/12/15	50-255 50-255 50-266 50-317 50-390	9 9 9
7812270309 7812270310 7812270311 7812270312 7812270313	7812270306 7812270299 7812270308 7812270307 7812270306	78/12/21 78/12/19 78/12/20 78/12/15 78/12/21	50-348 50-348 50-348 50-251 50-348	8 8 8	7812280358 7812290008 7812290010 7812290011 7812290014	7812280355 7812270007 7812270007 7812270009 7812270009	78/11/22- 78/12/19 78/12/19 78/11/24 78/11/24	50-344 50-62 50-62 50-305 50-305	9 9 0
7812270301 7812270302 7812270303 7812270304	7812270297 7812270300 7812270298 7812270299	78/12/13 78/12/12 78/12/21 78/12/19	50-331 50-237 50-324 50-369	8 8	7812280344 781228034B 7812280354 7812280356	7812280328 7812280328 7812280351 7812280351	78/12/19 78/12/19 78/12/11 78/12/11	50-250 50-466 50-466	9.00



#### **APPENDIX**

### DEFINITIONS OF DOCKET 50 CATEGORIES

# A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of Item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filled in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

#### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

# D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

#### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

tion are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.

of items 1 and 2.

applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

# O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testlmony by ACRS members or presented by individuals at ACRS
  proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.
- Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE
- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

#### CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- · 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

Title List of Documents Made Publicly Available  7. AUTHOR(S)  5. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS Hinchade Zip Code1  Division of Technical Information and Document Control  Office of Administration  U.S. Nuclear Regulatory Commission  Washington, DC 20555  8. PERIOD COVERED  Same  1. PERIOD COVERED  Special Edition  6. SUPPLEMENTARY NOTES	Special Edition	
Title List of Documents Made Publicly Available  AUTHOR(S)  PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Division of Technical Information and Document Control Office of Administration  U.S. Nuclear Regulatory Commission  Washington, DC 20555  2. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  1. TYPE OF REPORT  Special Edition  3. TYPE OF REPORT  Special Edition  3. ABSTRACT (2000 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 mm has not appeared in previous editions of the Title List.		on
Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555  2. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  3. TYPE OF REPORT Special Edition 5. SUPPLEMENTARY NOTES 6. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 m. has not appeared in previous editions of the Title List.	RECIPIENT'S ACCES	SICN NO.
U.S. Nuclear Regulatory Commission Washington, DC 20555  12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  13. TYPE OF REPORT  Special Edition  16. SUPPLEMENTARY NOTES  16. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 me has not appeared in previous editions of the Title List.	. DATE REPORT COM	
Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555  12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  13. TYPE OF REPORT Special Edition 16. SUPPLEMENTARY NOTES  16. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 me has not appeared in previous editions of the Title List.	MONTH	YEAR
Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, DC 20555  12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  13. TYPE OF REPORT Special Edition 16. SUPPLEMENTARY NOTES  16. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 me has not appeared in previous editions of the Title List.	August DATE REPORT ISSU	1981
U.S. Nuclear Regulatory Commission Washington, DC 20555  2. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  Same  Special Edition  5. SUPPLEMENTARY NOTES  6. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 me has not appeared in previous editions of the Title List.	September	YEAR 1981
2. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)  Same  1. Same  1. Special Edition  5. SUPPLEMENTARY NOTES  6. ABSTRACT (200 words or less)  This document contains a description of information recetthe U.S. NRC. This special edition contains Docket 50 makes not appeared in previous editions of the Title List.	. (Leave blank)	
Same  3. TYPE OF REPORT  Special Edition  5. SUPPLEMENTARY NOTES  1. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 makes not appeared in previous editions of the Title List.	. (Leave blank)	
Special Edition  5. SUPPLEMENTARY NOTES  6. ABSTRACT (200 words or less)  This document contains a description of information recethe U.S. NRC. This special edition contains Docket 50 me has not appeared in previous editions of the Title List.	0. PROJECT/TASK/WO	PRK UNIT NO
Special Edition  16. SUPPLEMENTARY NOTES  16. ABSTRACT (200 words or less)  This document contains a description of information rece the U.S. NRC. This special edition contains Docket 50 mm has not appeared in previous editions of the Title List.	1. CONTRACT NO.	
This document contains a description of information rece the U.S. NRC. This special edition contains Docket 50 m has not appeared in previous editions of the Title List.	(Inclusive dates)	
This document contains a description of information rece the U.S. NRC. This special edition contains Docket 50 m has not appeared in previous editions of the Title List.	4. (Leave Olank)	
•	aterial from l The document	1978 that

17. KEY WORDS AND DOCUMENT ANALYSIS

17a. DESCRIPTORS